



March 26, 2019

ISD# 834
1875 Greely Street South
Stillwater, MN 55082
Attn: Mr. Tony Willger

RE: **Radon Sampling**
Site: **Stillwater Area High School**

Field Environmental Consulting, Inc. (FIELD ENVIRONMENTAL) appreciates the opportunity to provide results for radon monitoring conducted at Stillwater Area High School.

Radon levels are measured in picocuries per liter or pCi/L. The Environmental Protection Agency (EPA) and the Minnesota Department of Health (MDH) action level for indoor radon is 4.0 pCi/L.

Radon monitoring was conducted using AccuStar® PicoCan 275 short-term open face charcoal canisters (registered device #AC-6048).

In February 2019, one hundred and thirty-two (132) detectors were analyzed for radon concentration. All samples were below the action level of 4.0 pCi/L. No additional action necessary.

PREPARED and REVIEWED BY:

Field Environmental Consulting, Inc.

Amy Weinzierl (CSP #27824)
EHS Manager / Licensed Radon Measurement Professional (RMEA-00111)
amy@fieldconsultinginc.com
952-746-5880

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082

Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3219661	3945241	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Gym Back Wall	0.6
3219662	3945242	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Gym Drinking Fountain	1.8
3219663	3945243	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Gymnastics Wall by Light	1.4
3219664	3945244	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Boys Locker Office File Cab	0.8
3219665	3945245	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room G116 Girls Locker Office Hutch	< 0.4
3219666	3945246	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room G113 Top of Cabinet	0.7
3219667	3945247	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room G115 Cabinet Right of Door	< 0.4
3219668	3945248	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room G117 Top of Ice Machine	0.7
3219669	3945249	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Mens PE Locker Office Hutch	< 0.4
3219670	3945250	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Womens PE Locker Office Shelf	< 0.4
3219671	3944881	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Main Gym Above Control Box	1.0

Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3219672	3944882	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Main Gym by Rear Door West	1.2
3219673	3944883	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Wrestling Gym Whiteboard	< 0.4
3219674	3944884	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Cafeteria Top of Fire Alarm	< 0.4
3219675	3944885	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Cafeteria Top of Fire Alarm	< 0.4
3219676	3944886	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room Kitchen Office 1st Level Hutch	< 0.4
3219677	3944887	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E116 Cabinet/Hutch	0.5
3219678	3944888	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E118 Hutch	1.1
3219679	3944889	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E120 Cabinet Right	0.7
3219680	3944890	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E122 Above Whiteboard	1.1
3219681	3945301	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E124 Hutch Right	< 0.4
3219682	3945302	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E126 Whiteboard	0.7


Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3219683	3945303	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room ALC Hutch	0.8
3219684	3945304	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E121 Shelf to Right	0.8
3219685	3945305	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E119 Cabinet to Right	< 0.4
3219686	3945306	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E117 Cabinet to Left	0.6
3219687	3945307	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E128 Shelf	0.4
3219688	3945308	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E123 Reception Shelf	0.6
3219689	3945309	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E111 Shelf	1.1
3219690	3945310	02/18/2019 1:00 pm	02/21/2019 2:00 pm	First Floor Room E115 Shelf by Door	0.9
3219691	3945201	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E114 Shelf by Desk	0.6
3219692	3945202	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E114 Shelf by Desk Duplicate	1.1
3219693	3945203	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E112 Top of Shelf	0.4

Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3219694	3945204	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E110 Hutch Left	0.6
3219695	3945205	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E108 Shelf to Left	0.6
3219696	3945206	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E105 Cabinet to Right	0.7
3219697	3945207	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E106 Back of Room Shelf	0.9
3219698	3945208	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E104 Whiteboard Sill	< 0.4
3219699	3945209	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E102 Shelf Behind Desk	0.8
3219700	3945210	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E130 Shelf Behind Radio	< 0.4
3219701	3945251	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E132 Shelf to Left	0.6
3219702	3945252	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E133 Hutch	0.6
3219703	3945253	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E135 Top of Shelf	0.5
3219704	3945254	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E134 Shelf by Phone	0.9


Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3219705	3945255	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room E136 Whiteboard Ledge	0.6
3219706	3945256	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room D132 Shelf Left	< 0.4
3219707	3945257	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room D134 Shelf	0.9
3219708	3945258	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room D129 Shelf Right	0.4
3219709	3945259	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room D130 Shelf Left	0.9
3219710	3945260	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room D125 Top of Fridge	< 0.4
3219711	3945261	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room D126 Cabinet Left	0.6
3219712	3945262	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room D123 Top Lockers	< 0.4
3219713	3945263	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room D123 Top Lockers Duplicate	< 0.4
3219714	3945264	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First floor Room D124 Cabinet Right	< 0.4
3219715	3945265	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room D122 Shelf	0.5


Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082

Log Number	Device Number	Test Exposure Duration:	Area Tested	Result pCi/L
3219716	3945266	02/18/2019 2:00 pm 02/21/2019 2:00 pm	First Floor Room D103 Reception Hutch	0.6
3219717	3945267	02/18/2019 2:00 pm 02/21/2019 2:00 pm	First Floor Room D102 Shelf Left	< 0.4
3219718	3945268	02/18/2019 2:00 pm 02/21/2019 2:00 pm	First Floor Room D106 Smartboard	< 0.4
3219719	3945269	02/18/2019 2:00 pm 02/21/2019 2:00 pm	First Floor Room D108 Smartboard	0.5
3219720	3945270	02/18/2019 2:00 pm 02/21/2019 2:00 pm	First Floor Room D109 Smartboard	0.9
3219721	3944871	02/18/2019 2:00 pm 02/21/2019 2:00 pm	First Floor Room D112 Smartboard	0.8
3219722	3944872	02/18/2019 2:00 pm 02/21/2019 2:00 pm	First Floor Room D114 TV Stand	0.9
3219723	3944873	02/18/2019 2:00 pm 02/21/2019 2:00 pm	First Floor Room Gray Pony Behind Computer	< 0.4
3219724	3944874	02/18/2019 2:00 pm 02/21/2019 2:00 pm	First Floor Room C123 File Cabinet	1.1
3219725	3944875	02/18/2019 2:00 pm 02/21/2019 2:00 pm	First Floor Room C124 By Phone	< 0.4
3219726	3944876	02/18/2019 2:00 pm 02/21/2019 2:00 pm	First Floor Room C121 Cabinet Right	0.5

Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3219727	3944877	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room C122 Cabinet Top	0.9
3219728	3944878	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room C120 Goggle Storage	< 0.4
3219729	3944879	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room C112 By Phone	1.1
3219730	3944880	02/18/2019 2:00 pm	02/21/2019 2:00 pm	First Floor Room C111 Cabinet	0.5
3219731	3945381	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room C114 Goggle Storage	< 0.4
3219732	3945382	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room C115 Phone	1.1
3219733	3945383	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room C118 Shelf Cabinet	1.0
3219734	3945384	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room C103 Top Cabinet	0.4
3219735	3945385	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room C103 Top Cabinet Duplicate	0.6
3219736	3945386	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room Black Pony Center Main Desk	0.8
3219737	3945387	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room C102 Top of Cabinet	0.9

Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3219738	3945388	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room C105 Phone	0.9
3219739	3945389	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room C104 Cabinet Left	0.6
3219740	3945390	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room C109 Phone	0.6
3219741	3945231	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room C110 Phone	0.7
3219742	3945232	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room B117 Top of Cabinet Left	0.6
3219743	3945233	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room B124 Cabinet with Mice	0.7
3219744	3945234	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room B115 Top of Hutch	0.7
3219745	3945235	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room B118 TV Stand	< 0.4
3219746	3945236	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room B120 File Cabinet	0.5
3219747	3945237	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room B122 Gray Cabinet	1.2
3219748	3945238	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room B116 Behind Desk	0.5


Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3219749	3945239	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room B113 Shelf Above Sink	1.0
3219750	3945240	02/18/2019 3:00 pm	02/21/2019 3:00 pm	First Floor Room B114 Cabinet Above Sink	< 0.4
3219751	3945372	02/18/2019 4:00 pm	02/21/2019 3:00 pm	First Floor Room A108 Hutch	< 0.4
3219752	3945321	02/18/2019 4:00 pm	02/21/2019 3:00 pm	First Floor Room A106 Shelf Right	0.4
3219753	3945195	02/18/2019 4:00 pm	02/21/2019 3:00 pm	First Floor Room A104 Hutch	< 0.4
3219754	3945196	02/18/2019 4:00 pm	02/21/2019 3:00 pm	First Floor Room A107 Top of Cabinet	0.7
3219755	3945197	02/18/2019 4:00 pm	02/21/2019 3:00 pm	First Floor Room B110 Cabinet Left	0.7
3219756	3945198	02/18/2019 4:00 pm	02/21/2019 3:00 pm	First Floor Room B110 Cabinet Left Duplicate	0.5
3219757	3945199	02/18/2019 4:00 pm	02/21/2019 3:00 pm	First Floor Room Auditorium Ledge	< 0.4
3219758	3945200	02/18/2019 4:00 pm	02/21/2019 3:00 pm	First Floor Room B108 Shelf by Flag	< 0.4
3219759	3945323	02/18/2019 4:00 pm	02/21/2019 3:00 pm	First Floor Room Main Office Behind Computer	0.7


Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Shawn Price, Director of Laboratory Operations, AccuStar Labs

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3219760	3945324	02/18/2019 4:00 pm	02/21/2019 3:00 pm	First Floor Room Principal Shelf	0.8
3219761	3945325	02/18/2019 4:00 pm	02/21/2019 3:00 pm	First Floor Room White Pony Center Computer	< 0.4
3219762	3945326	02/18/2019 4:00 pm	02/21/2019 3:00 pm	Floor Second Room D220 Paper Shelf	0.7
3219763	3945327	02/18/2019 4:00 pm	02/21/2019 3:00 pm	Floor Second Room D220 Paper Shelf Duplicate	< 0.4
3219764	3945328	02/18/2019 4:00 pm	02/21/2019 3:00 pm	Floor Second Room E204 Shelf Globe	< 0.4
3219765	3945329	02/18/2019 4:00 pm	02/21/2019 3:00 pm	Floor Second Room E204 Shelf Globe Duplicate	< 0.4
3219766	3945330	02/18/2019 4:00 pm	02/21/2019 3:00 pm	Floor Second Room E210 Shelf above Mailbox	< 0.4
3219767	3945431	02/18/2019 4:00 pm	02/21/2019 3:00 pm	Floor Second Room E224 Shelf	0.4
3219768	3945432	02/18/2019 4:00 pm	02/21/2019 3:00 pm	Floor Second Room E217 Shelf by Door	< 0.4
3219769	3945433	02/18/2019 4:00 pm	02/21/2019 3:00 pm	Floor Second Room Media Center Phone	0.5
3219770	3945434	02/18/2019 4:00 pm	02/21/2019 3:00 pm	Floor Second Room C216 Shelf by Desk	< 0.4


Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3219771	3945435	02/18/2019 5:00 pm	02/21/2019 3:00 pm	Floor Second Room C219 File Cabinet	< 0.4
3219772	3945436	02/18/2019 5:00 pm	02/21/2019 3:00 pm	Floor Second C204 Whiteboard Ledge	< 0.4
3219773	3945291	02/18/2019 5:00 pm	02/21/2019 3:00 pm	Floor Second C204 Whiteboard Ledge Duplicate	0.6
3219774	3945371	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room Secretary Office Cabinet	< 0.4
3219775	3945373	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room Office Behind Computer	0.9
3219776	3945192	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room E101 Shelf	< 0.4
3219777	3945292	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room E101 Shelf Duplicate	< 0.4
3219778	3945193	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room WPC Counselor Hutch	0.6
3219779	3945294	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room WPC Officer Shelf Right	0.6
3219780	3945375	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor GPC D138D Cabinet	< 0.4
3219781	3945322	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor GPC D138D Cabinet Duplicate	0.5


Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:

The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NRPP 105011 AL
NRSB ARL0007

EPA Method #402-R-92-004
Charcoal Canister
NRPP Device Code 6048
NRSB Device Code 10317

Laboratory Report for:

Property Tested: Project # 19036

Field Environmental Consulting, Inc.
8612 Eagle Creek Parkway
Savage MN 55378

Stillwater Area High School
5701 Stillwater Blvd N
Oak Park Heights MN 55082


Log Number	Device Number	Test Exposure	Duration:	Area Tested	Result pCi/L
3219782	3945295	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room GPC Asst. Principal Cabinet	< 0.4
3219783	3945296	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room GPC Pycologist Cabinet	< 0.4
3219784	3945297	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room GPC D138E Cabinet	1.7
3219785	3945298	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room BPC Asst Principal Shelf	< 0.4
3219786	3945299	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room BPC Counselor Left Shelf	< 0.4
3219787	3945300	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room BPC Counselor Right Hutch	< 0.4
3219788	3945377	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room Cutodial Office Phone	< 0.4
3219789	3945437	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room Main Office Field Blank	0.4
3219790	3945440	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room Main Office Field Blank	< 0.4
3219791	3945439	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room Main Office Field Blank	< 0.4
3219792	3945438	02/18/2019 5:00 pm	02/21/2019 3:00 pm	First Floor Room Main Office Field Blank	< 0.4


Comment: A copy of this report was emailed to mailbox@fieldconsulting.com.

Test Performed By: Nicole Fields Certification Number: RMEA-00146

Distributed by: Field Environmental Consulting, Inc.

Date Received: 02/26/2019 Date Logged: 02/26/2019 Date Analyzed: 02/27/2019 Date Reported: 03/01/2019

Report Reviewed By: 

Report Approved By: 

Disclaimer:


The uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Analytical results relate to the samples AS RECEIVED BY THE LABORATORY. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

Stillwater Area High School
 First Floor
 Short-Term Radon Monitoring
 Project #19036

Short-Term Radon (February 2019)

- ◆ Radon < 4 pCi/L
- ◆ Radon ≥ 4 pCi/L
- D Duplicate Detector
- FB Field Blank Detector



Stillwater Area High School
 Second Floor
 Short-Term Radon Monitoring
 Project #19036

Short-Term Radon (February 2019)

◆	Radon < 4 pCi/L
◆	Radon ≥ 4 pCi/L
D	Duplicate Detector
FB	Field Blank Detector

