

Everson Elementary School Progress Photos

Date: November 23, 2020



These drone aerial photos were taken on November 19 and they show 75% of the concrete footings poured with more forming underway.



Another view showing where the Everson 10 classroom addition is located in relation to the school and where the hallway will connect.



A close up view on November 19.



The final section of concrete footings has now been poured.



Form removal is underway.



Concrete stem wall forming has now started.