

Nooksack Elementary School Progress Photos

Date: November 23, 2020



These drone aerial photos were taken November 19 and show the main walls all framed up.



A closer look showing the 6 classrooms & shear walls. Bathroom walls still to be framed.



This photo taken from the southwest.



Trusses went up on Nov 23. This image captures the first half of trusses placed on the west side.



A gravel walk path was installed today to provide students with clean access around the construction area to the playground.



One more view showing the west side.