

Sumas Elementary School Progress Photos

Date: November 23, 2020



This drone aerial photo was taken on 11-19-2020 showing a large dump truck dropping gravel.



Grading & compaction on the east side of the pad is underway.



The east pad now has approx. 4 feet of pre-load gravel placed and compacted.



Pre-load and building pad perimeter grading on the east end.



A close up view of fine tuning.



Gravel continues to be brought in, graded and compacted.