

8612 Eagle Creek Parkway, Savage, MN 55378
Tel: (952) 746-5880 ◆ Fax: (952) 746-5882
Mailbox@FieldConsultingInc.com
www.FieldConsultingInc.com

Independent School District #191 200 Burnsville Pkwy Burnsville, MN 55337 Attn: Mr. Glenn Simon

RE: Lead in Drinking Water Sampling

SITE: Nicollet Middle School

DATE: January 2019

Dear Glenn Simon,

Field Environmental Consulting, Inc. (FIELD ENVIRONMENTAL) appreciates the opportunity to provide results for lead in drinking water sampling conducted at Nicollet Middle School.

Initial sampling ("first draw") was completed on Wednesday, October 31, 2018 $^+$. Nine (9) out of the forty-seven (47) initial first draw samples collected at Nicollet Middle School were above the recommended limit of 20 ppb (or μ g/L). Provided with results, ISD #191 removed two (2) taps from service located in the kitchen and cleaned aerators for five (5) of the nine (9) taps. Furthermore, ISD #191 decided to identify science department prep sinks with labels that state "water not for consumption."

After aerator cleaning was completed for the five (5) identified outlets, ISD #191 re-sampled these faucets on Thursday, November 29, 2018. Results at four (4) taps were below the recommended action level; however, one (1) tap located in workroom 120 remained above the recommended limit. After receiving this result, initial and thirty (30) second flush sampling was used to re-sample this tap on December 14, 2018. After results were reviewed, the initial sample was above the recommended action limit of 20 ppb. The flush sample was below the action limit. Therefore, ISD #191 labeled the faucet in workroom 120 "water not for consumption."

Analysis was conducted by Pace Analytical Services, Inc. of Minneapolis, Minnesota using EPA Method 200.8 ICPMS for determination of trace elements in drinking water.

PREPARED and REVIEWED BY:

Field Environmental Consulting, Inc.

Amy Weinzierl (CSP #27824)

Amy Weingel

Environmental Health and Safety Manager

amy @fieldconsultinginc.com

952-746-5880

*sampling was performed by ISD #191 Health & Safety Supervisor

LEAD IN THE WATER TESTING BUILDING: Nicollet ML 1 DATE 10/31/2018

TYPE OF FAUCET WC - water cooler DF - drinking fountain S - Sink K - Kettle BF - Bottle Filler HW - Hot Water Dispenser

Lead < = 20 ppb, Lead > 20 ppb (Action Level), ND= None Detected

	LABEL	BUILDING	ROOM/LOCATION	TYPE OF FAUCET	LEAD RESULT (ppb or µg/L)			
1	01	NM	Kitchen Southeast wall (sprayer)	S	6.0			
2	02	NM	Kitchen Southeast wall	S	1.6			
3	03	NM	Kitchen Southwest wall Left	К	823			
	Kettle Removed							
4	04	NM	Kitchen Southwest wall Right	К	522			
	Kettle Removed							
5	05	NM	Kitchen Southwest wall	HW	3.2			
6	06	NO SAMPLE COLLECTED						
7	07	NO SAMPLE COLLECTED						
8	08	NM	Custodian Break Room	S	1.9			
9	09	NM	408	S	2.1			
10	10	NM	WC outside room west side of Gym	WC	ND			
11	11	NM	404	S	329			
	11- Resample 11/29/2018							
12	12	NM	In hallway area music dept.	WC	4.0			
13	13	NM	Main Office work room	S	1.8			
14	14	NM	Nurse's Office	S	ND			
15	15	NM	WC outside room 202	WC	1.7			
16	16	NM	232	S	7.7			
17	17	NM	WC outside room 214	WC	0.78			
18	18	NM	Media Production room	S	7.9			
19	19	NM	WC outside room 224	WC	1.4			

BUILDING: Nicollet LL 1

DATE 10/31/2018

TYPE OF FAUCET WC - water cooler DF - drinking fountain S - Sink K - Kettle BF - Bottle Filler

Lead < = 20 ppb, Lead > 20 ppb (Action Level), ND= None Detected

	LABEL	BUILDING	ROOM/LOCATION	TYPE OF FAUCET	LEAD RESULT (ppb or µg/L)	
1	20	NM	100	S	23.8	
20-Resample 11/29/2018						
2	21	NM	100	S	1.9	
3	22	NM	102	S	3.0	
4	23	NM	102	S	0.88	
5	24	NM	Special Ed Office across from room 102	S	7.3	
6	25	NM	WC outside room #102	WC	2.1	
7	26	NM	Drinking fountain in the weight room	WC	7.7	
8	27	NM	106	S	3.1	
9	28	NM	106	S	13.7	
10	29	NM	108	S	3.9	
11	30	NM	108	S	18.5	
12	31	NM	Special Ed room 121	S	7.7	
13	32	NM	WC outside room #116	WC	1.6	
14	33	NM	Work room 120	S	<mark>78.5</mark>	
		33-Resa	ample 11/29/2018		52.2	
	33-Initial Resample/30 Second Flush Sample 12/14/18					
		Labeled	l "Non Potable Water - Do Not Drink"			
15	34		NO SAMPLE COLLECTED			
16	35	NM	124	S	<mark>48.0</mark>	
35-Resample 11/29/2018						
17	36	NM	WC outside room #124	WC	ND	
18	37	NM	Special Ed room 117	S	20.3	
37-Resample 11/29/2018						
19	38	NM	West side of the room Left	S	1.1	
20	39	NM	West side of the room Center	S	2.5	
21	40	NM	West side of the room Right	S	1.4	
22	41	NM	East side of the room Left	S	1.1	
23	42	NM	East side of the room Center	S	1.2	
24	43	NM	East side of the room Right	S	1.7	

LEAD IN THE WATER TESTING

BUILDING: Nicollet 3rd level


DATE 10/31/2018

TYPE OF FAUCET WC - water cooler DF - drinking fountain S - Sink K - Kettle BF - Bottle Filler HW - Hot Water Dispenser


Lead < = 20 ppb, Lead > 20 ppb (Action Level), ND= None Detected

	LABEL	BUILDING	ROOM/LOCATION	TYPE OF FAUCET	LEAD RESULT (ppb or µg/L)			
1	44	NM	WC outside room 304	WC	2.6			
2	45	NM	Science Prep Area (ctr round) Left	S	18.1			
	Labeled "Non Potable Water - Do Not Drink"							
3	46	NM	Science Prep Area (ctr round) Center	S	26.1			
Labeled "Non Potable Water - Do Not Drink"								
4	47	NM	Science Prep Area (ctr round) Right	S	29.0			
	Labeled "Non Potable Water - Do Not Drink"							
5	48	NM	WC outside room 316	WC	2.2			
6	49	NM	320	S	8.6			
7	50	NM	WC outside room 324	WC	3.2			

Nicollet Middle School



Nicollet Middle School



Nicollet Middle School

