

Nooksack Elementary School Progress Photos

Date: January 21, 2021



Waterproofing membrane is installed and masonry work continues on the south side.



A view down the interior hallway showing door frames installed, plumbing and electrical work.



Ductwork is proceeding overhead in the classrooms.



Electrical conduits are being installed throughout the new classroom addition.



The new gym center beam has been installed and walls for the storage & mechanical room are ready.



The large air handler/heater has arrived and will be installed in a 2nd floor mechanical room.