

# Northern High School

## 2018-2019 Testing Results

Laboratory Name	School Name	Laboratory Reporting Date	Floor #	School Outlet ID/Floor Plan ID	Sample Tap/Outlet Type (code)	Sample Tap/Outlet Description/Location	Sample Type (Code)	Date Water Last Used	Time Water Last Used	Date Sample Collected	Time Sample Collected	Analysis Date	Lead Sample Result (ppb)	≥ 20.5 ppb AL?
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	1	DF	Fountain outside of main office	FD	5/21/2018	6:45:00 PM	5/22/2018	5:31:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	2	DF	Fountain in cafeteria	FD	5/21/2018	6:45:00 PM	5/22/2018	5:42:00 AM	5/22/2018	2.9	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	3	DF	Fountain outside of finance office	FD	5/21/2018	6:45:00 PM	5/22/2018	5:44:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	4	DF	Fountain between 206 and 301	FD	5/21/2018	6:45:00 PM	5/22/2018	5:46:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	5	DF	Fountain between 305 and 400	FD	5/21/2018	6:45:00 PM	5/22/2018	5:47:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	6	DF	Fountain outside of 500	FD	5/21/2018	6:45:00 PM	5/22/2018	5:49:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	7	DF	Fountain between 508 and 601	FD	5/21/2018	6:45:00 PM	5/22/2018	5:53:00 AM	5/22/2018	<1.0	No

Water Testing Laboratory of MD	Northern High School	7/7/2018	1	8	DF	Fountain between 607 and 701	FD	5/21/2018	6:45:00 PM	5/22/2018	5:52:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	9	TL	Faucet in main office preparation room	FD	5/21/2018	6:45:00 PM	5/22/2018	5:33:00 AM	5/22/2018	1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	10	NO	Faucet in nurse room	FD	5/21/2018	6:45:00 PM	5/22/2018	5:34:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	11	NO	Faucet in nurse office	FD	5/21/2018	6:45:00 PM	5/22/2018	5:35:00 AM	5/22/2018	2.3	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	12	TL	Faucet in attendance office	FD	5/21/2018	6:45:00 PM	5/22/2018	5:36:00 AM	5/22/2018	4.3	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	13	TL	Faucet in media center media specialist	FD	5/21/2018	6:45:00 PM	5/22/2018	5:45:00 AM	5/22/2018	3.1	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	14	CR	Far left facet in 301	FD	5/21/2018	6:45:00 PM	5/22/2018	5:40:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	17	CR	Middle faucet in 301	FD	5/21/2018	6:45:00 PM	5/22/2018	5:41:00 AM	5/22/2018	3.6	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	18	CR	Far right faucet in 301	FD	5/21/2018	6:45:00 PM	5/22/2018	5:42:00 AM	5/22/2018	3.7	No
Water Testing	Northern High School	7/7/2018	1	19	CR	Back faucet in the center of 301	FD	5/21/2018	6:45:00 PM	5/22/2018	5:42:00 AM	5/22/2018	4.1	No

Laboratory of MD														
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	20	CR	Front faucet in the center of 301	FD	5/21/2018	6:45:00 PM	5/22/2018	5:42:00 AM	5/22/2018	5.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	21	CR	Faucet in cafeteria	FD	5/21/2018	6:45:00 PM	5/22/2018	5:40:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	22	CR	Faucet in lounge	FD	5/21/2018	6:45:00 PM	5/22/2018	5:40:00 AM	5/22/2018	1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	23	KS	Left solo faucet in kitchen	FD	5/21/2018	6:45:00 PM	5/22/2018	5:30:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	24	KS	Left double faucet in kitchen	FD	5/21/2018	6:45:00 PM	5/22/2018	5:31:00 AM	5/22/2018	1.6	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	25	KS	Right double faucet in kitchen	FD	5/21/2018	6:45:00 PM	5/22/2018	5:31:00 AM	5/22/2018	1.1	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	26	KS	Solo faucet on prep table	FD	5/21/2018	6:45:00 PM	5/22/2018	5:32:00 AM	5/22/2018	1.8	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	27	KS	Left cooking kettle faucet	FD	5/21/2018	6:45:00 PM	5/22/2018	5:32:00 AM	5/22/2018	3.1	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	28	KS	Right cooking kettle faucet	FD	5/21/2018	6:45:00 PM	5/22/2018	5:32:00 AM	5/22/2018	5.6	No

Water Testing Laboratory of MD	Northern High School	7/7/2018	1	29	CR	Faucet in the little room between 805 and 803	FD	5/21/2018	6:45:00 PM	5/22/2018	5:51:00 AM	5/22/2018	2.8	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	30	CR	Front faucet in 801	FD	5/21/2018	6:45:00 PM	5/22/2018	5:49:00 AM	5/22/2018	1.8	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	31	CR	Back faucet in 801	FD	5/21/2018	6:45:00 PM	5/22/2018	5:49:00 AM	5/22/2018	1.8	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	32	CR	Faucet in 803	FD	5/21/2018	6:45:00 PM	5/22/2018	5:50:00 AM	5/22/2018	4.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	33	DF	Left fountain outside of gym	FD	5/21/2018	6:45:00 PM	5/22/2018	6:01:00 AM	5/22/2018	2.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	34	DF	Right fountain outside of gym	FD	5/21/2018	6:45:00 PM	5/22/2018	6:01:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	35	DF	Fountain in team room	FD	5/21/2018	6:45:00 PM	5/22/2018	6:01:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	36	DF	Fountain in boys locker room	FD	5/21/2018	6:45:00 PM	5/22/2018	6:01:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	37	DF	Fountain in girls locker room	FD	5/21/2018	6:45:00 PM	5/22/2018	6:05:00 AM	5/22/2018	<1.0	No
Water Testing	Northern High School	7/7/2018	1	38	CR	Back faucet in 900	FD	5/21/2018	6:45:00 PM	5/22/2018	5:55:00 AM	5/22/2018	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	39	CR	Front faucet in 900	FD	5/21/2018	6:45:00 PM	5/22/2018	5:55:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	40	DF	Left fountain outside auditorium	FD	5/21/2018	6:45:00 PM	5/22/2018	5:58:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	41	DF	Right fountain outside auditorium	FD	5/21/2018	6:45:00 PM	5/22/2018	5:57:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	42	IM	Ice machine in kitchen	FD	5/21/2018	6:45:00 PM	5/22/2018	5:29:00 AM	5/22/2018	<1.0	No
Water Testing Laboratory of MD	Northern High School	7/7/2018	1	43	KS	Sprayer to fill steam room	FD	5/23/2018	6:45:00 PM	5/24/2018	6:22:00 AM	5/28/2018	<1.0	No