

Northern Middle School

2017-2018 Testing Results

Laboratory Name	School Name	Laboratory Reporting Date	Floor #	School Outlet ID/Floor Plan ID	Sample Tap/Outlet Type (code)	Sample Tap/Outlet Description/Location	Sample Type (Code)	Date Water Last Used	Time Water Last Used	Date Sample Collected	Time Sample Collected	Analysis Date	Lead Sample Result (ppb)	≥ 20.5 ppb AL?
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	1	DF	Left fountain outside of 2	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	2	DF	Right fountain outside of 2	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	3	DF	Left fountain outside of 7B	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	4	DF	Middle fountain outside of 7B	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	5	DF	Right fountain outside of 7B	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	6	DF	Left fountain outside of cafeteria	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	7	DF	Right fountain outside of cafeteria	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No

Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	8	DF	Fountain in cafeteria	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	9	DF	Left fountain outside of 15, 16, 17, 18	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	10	DF	Right fountain outside of 15, 16, 17, 18	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	11	DF	Left fountain outside of 26A	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	12	DF	Middle fountain outside of 26A	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	13	DF	Right fountain outside 26A	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	14	NO	Faucet in nurse room	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.6	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	15	CR	Faucet in records room	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.8	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	16	CR	Faucet between 1&3	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	17.6	No
Water Testing	Northern Middle School	7/7/2018	1	17	CR	Left faucet in 3	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	2.6	No

Laboratory of MD														
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	18	CR	Right faucet in 3	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.3	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	19	CR	Left faucet in 4	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	4.8	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	20	CR	Right faucet in 4	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	2.6	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	21	HE	Station 1 faucet in 5	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.6	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	22	HE	Station 2 faucet in 5	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	2.5	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	23	HE	Station 3 faucet in 5	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.6	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	24	HE	Station 4 faucet in 5	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	2.1	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	25	HE	Station 5 faucet in 5	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.5	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	26	HE	Station 6 faucet in 5	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	2.1	No

Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	27	CR	Faucet in 7B	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	6.9	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	28	CR	Faucet in labA. 11A	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	12.8	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	29	CR	Faucet in 29	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	2.1	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	30	CR	Faucet outside of BSW office	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.9	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	31	KS	Left faucet in dishwasher room	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	5.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	32	KS	Middle faucet in dishwasher room	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.4	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	33	KS	Right faucet in dishwasher room	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	34	KS	Faucet on prep table in middle of kitchen	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.7	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	35	KS	Solo Faucet w/ double sink in kitchen	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	2.2	No
Water Testing	Northern Middle School	7/7/2018	1	36	CR	Faucet in 22a	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.4	No

Laboratory of MD														
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	37	CR	Faucet in 23 by teachers desk	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	38	CR	Faucet in middle island	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.8	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	39	CR	Faucet in 26A	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	1.0	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	40	CR	Faucet in darkroom in media room	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	20.5	Yes
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	41	CR	Faucet in media center work room	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	2.9	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	42	CR	Faucet in 17A	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	2.7	No
Water Testing Laboratory of MD	Northern Middle School	7/7/2018	1	43	IM	Ice machine in kitchen	FD	5/23/2018	8:00:00 PM	3/21/2019	6:45:00 PM	5/28/2018	<1.0	No