

Huntingtown High School

2018-2019 Testing Results

Laboratory Name	School Name	Laboratory Reporting Date	Floor #	School Outlet ID/Floor Plan ID	Sample Tap/Outlet Type (code)	Sample Tap/Outlet Description/Location	Sample Type (Code)	Date Water Last Used	Time Water Last Used	Date Sample Collected	Time Sample Collected	Analysis Date	Lead Sample Result (ppb)	≥ 20.5 ppb AL?
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	1	DF	Fountain outside of main office	FD	4/3/2019	8:00:00 PM	4/4/2019	5:00:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	2	DF	fountain outside of B101	FD	4/3/2019	8:00:00 PM	4/4/2019	5:02:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	3	DF	Bottle filler outside Auditorium	FD	4/3/2019	8:00:00 PM	4/4/2019	5:08:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	4	DF	Fountain outside auditorium	FD	4/3/2019	8:00:00 PM	4/4/2019	5:08:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	5	DF	right fountain outside gym	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	6	DF	left fountain outside gym	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	7	DF	left fountain outside locker rooms	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	<1.0	No
Water Testing	Huntingtown High	4/20/2019	1	8	DF	right fountain outside locker rooms	FD	4/3/2019	8:00:00 PM	4/4/2019	5:17:00 AM	4/8/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	9	DF	Fountain outside of E111	FD	4/3/2019	8:00:00 PM	4/4/2019	5:21:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	10	DF	Fountain outside F114	FD	4/3/2019	8:00:00 PM	4/4/2019	5:20:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	11	DF	Fountain across F105	FD	4/3/2019	8:00:00 PM	4/4/2019	5:17:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	12	DF	left fountain across A112	FD	4/3/2019	8:00:00 PM	4/4/2019	4:54:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	13	DF	right fountain across A112	FD	4/3/2019	8:00:00 PM	4/4/2019	4:54:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	14	DF	fountain across H212	FD	4/3/2019	8:00:00 PM	4/4/2019	4:50:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	15	DF	fountain across H202	FD	4/3/2019	8:00:00 PM	4/4/2019	4:51:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	16	DF	fountain across I202	FD	4/3/2019	8:00:00 PM	4/4/2019	4:53:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	17	DF	fountain across J204	FD	4/3/2019	8:00:00 PM	4/4/2019	4:45:00 AM	4/8/2019	<1.0	No

Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	18	DF	fountain across K209	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	19	DF	fountain by K201	FD	4/3/2019	8:00:00 PM	4/4/2019	4:48:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	3	20	DF	fountain by L305	FD	4/3/2019	8:00:00 PM	4/4/2019	4:49:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	3	21	DF	left fountain outside M317	FD	4/3/2019	8:00:00 PM	4/4/2019	4:40:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	3	22	DF	right fountain outside M317	FD	4/3/2019	8:00:00 PM	4/4/2019	4:55:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	23	DF	Fountain in F115	FD	4/3/2019	8:00:00 PM	4/4/2019	5:19:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	24	CR	front faucet in C113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:04:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	25	CR	back faucet in C113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:04:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	26	CR	front faucet in C112	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	<1.0	No
Water Testing	Huntingtown High	4/20/2019	1	27	CR	back faucet in C112	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	28	KS	faucet in gym concession stand	FD	4/3/2019	8:00:00 PM	4/4/2019	5:12:00 AM	4/8/2019	1.4	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	29	IM	ice machine in gym concession stand	FD	4/3/2019	8:00:00 PM	4/4/2019	5:12:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	30	CR	faucet in F115	FD	4/3/2019	8:00:00 PM	4/4/2019	5:19:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	31	HE	right faucet in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:04:00 AM	4/8/2019	1.4	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	32	HE	right faucet in right cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:05:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	33	HE	left faucet in right cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:05:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	34	HE	right faucet in middle cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	35	HE	left faucet middle cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	1.6	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	36	HE	right faucet left cube F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:07:00 AM	4/8/2019	<1.0	No

Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	37	HE	left faucet left cube F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:07:00 AM	4/8/2019	1.7	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	38	HE	teacher's faucet F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:07:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	39	HE	right faucet in right cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:09:00 AM	4/8/2019	2.5	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	40	HE	left faucet in right cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:09:00 AM	4/8/2019	2.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	41	HE	right faucet in left cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	7.9	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	42	HE	left faucet in left cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	1.3	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	43	KS	left faucet 3 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:38:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	44	KS	right faucet 3 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:39:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	45	KS	sprayer	FD	4/3/2019	8:00:00 PM	4/4/2019	4:39:00 AM	4/8/2019	<1.0	No
Water Testing	Huntingtown High	4/20/2019	1	46	KS	faucet 2 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:40:00 AM	4/8/2019	1.4	No

Laboratory of MD														
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	47	KS	sprayer on 2 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:40:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	48	IM	ice machine	FD	4/3/2019	8:00:00 PM	4/4/2019	4:41:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	49	KS	faucet on kitchen kettle	FD	4/3/2019	8:00:00 PM	4/4/2019	4:43:00 AM	4/8/2019	4.8	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	50	KS	sprayer for kettle	FD	4/3/2019	8:00:00 PM	4/4/2019	4:44:00 AM	4/8/2019	1.1	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	51	TL	faucet in lounge	FD	4/3/2019	8:00:00 PM	4/4/2019	4:52:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	53	NO	faucet in health room	FD	4/3/2019	8:00:00 PM	4/4/2019	4:56:00 AM	4/8/2019	6.7	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	54	IM	ice machine	FD	4/3/2019	8:00:00 PM	4/4/2019	4:58:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	55	CR	faucet A109A	FD	4/3/2019	8:00:00 PM	4/4/2019	5:02:00 AM	4/8/2019	1.1	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	56	CR	faucet A109B	FD	4/3/2019	8:00:00 PM	4/4/2019	5:02:00 AM	4/8/2019	1.7	No

Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	57	DF	fountain in media center	FD	4/3/2019	8:00:00 PM	4/4/2019	5:00:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	58	KS	faucet 2 compartment sink in field house	FD	4/3/2019	8:00:00 PM	4/4/2019	5:46:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	59	IM	ice machine in field house	FD	4/3/2019	8:00:00 PM	4/4/2019	5:46:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	60	CR	faucet in gym training room	FD	4/3/2019	8:00:00 PM	4/4/2019	5:19:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	61	KS	sprayer in kitchen dish room	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	62	IM	ice machine in K-208	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	63	CR	faucet in K-208	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	2.1	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	1	DF	Fountain outside of main office	FD	4/3/2019	8:00:00 PM	4/4/2019	5:00:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	2	DF	fountain outside of B101	FD	4/3/2019	8:00:00 PM	4/4/2019	5:02:00 AM	4/8/2019	<1.0	No
Water Testing	Huntingtown High	4/20/2019	1	3	DF	Bottle filler outside Auditorium	FD	4/3/2019	8:00:00 PM	4/4/2019	5:08:00 AM	4/8/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	4	DF	Fountain outside auditorium	FD	4/3/2019	8:00:00 PM	4/4/2019	5:08:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	5	DF	right fountain outside gym	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	6	DF	left fountain outside gym	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	7	DF	left fountain outside locker rooms	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	8	DF	right fountain outside locker rooms	FD	4/3/2019	8:00:00 PM	4/4/2019	5:17:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	9	DF	Fountain outside of E111	FD	4/3/2019	8:00:00 PM	4/4/2019	5:21:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	10	DF	Fountain outside F114	FD	4/3/2019	8:00:00 PM	4/4/2019	5:20:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	11	DF	Fountain across F105	FD	4/3/2019	8:00:00 PM	4/4/2019	5:17:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	12	DF	left fountain across A112	FD	4/3/2019	8:00:00 PM	4/4/2019	4:54:00 AM	4/8/2019	<1.0	No

Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	13	DF	right fountain across A112	FD	4/3/2019	8:00:00 PM	4/4/2019	4:54:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	14	DF	fountain across H212	FD	4/3/2019	8:00:00 PM	4/4/2019	4:50:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	15	DF	fountain across H202	FD	4/3/2019	8:00:00 PM	4/4/2019	4:51:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	16	DF	fountain across I202	FD	4/3/2019	8:00:00 PM	4/4/2019	4:53:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	17	DF	fountain across J204	FD	4/3/2019	8:00:00 PM	4/4/2019	4:45:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	18	DF	fountain across K209	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	19	DF	fountain by K201	FD	4/3/2019	8:00:00 PM	4/4/2019	4:48:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	3	20	DF	fountain by L305	FD	4/3/2019	8:00:00 PM	4/4/2019	4:49:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	3	21	DF	left fountain outside M317	FD	4/3/2019	8:00:00 PM	4/4/2019	4:40:00 AM	4/8/2019	<1.0	No
Water Testing	Huntingtown High	4/20/2019	3	22	DF	right fountain outside M317	FD	4/3/2019	8:00:00 PM	4/4/2019	4:55:00 AM	4/8/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	23	DF	Fountain in F115	FD	4/3/2019	8:00:00 PM	4/4/2019	5:19:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	24	CR	front faucet in C113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:04:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	25	CR	back faucet in C113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:04:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	26	CR	front faucet in C112	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	27	CR	back faucet in C112	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	28	KS	faucet in gym concession stand	FD	4/3/2019	8:00:00 PM	4/4/2019	5:12:00 AM	4/8/2019	1.4	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	29	IM	ice machine in gym concession stand	FD	4/3/2019	8:00:00 PM	4/4/2019	5:12:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	30	CR	faucet in F115	FD	4/3/2019	8:00:00 PM	4/4/2019	5:19:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	31	HE	right faucet in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:04:00 AM	4/8/2019	1.4	No

Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	32	HE	right faucet in right cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:05:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	33	HE	left faucet in right cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:05:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	34	HE	right faucet in middle cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	35	HE	left faucet middle cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	1.6	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	36	HE	right faucet left cube F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:07:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	37	HE	left faucet left cube F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:07:00 AM	4/8/2019	1.7	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	38	HE	teacher's faucet F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:07:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	39	HE	right faucet in right cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:09:00 AM	4/8/2019	2.5	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	40	HE	left faucet in right cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:09:00 AM	4/8/2019	2.0	No
Water Testing	Huntingtown High	4/20/2019	1	41	HE	right faucet in left cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	7.9	No

Laboratory of MD														
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	42	HE	left faucet in left cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	1.3	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	43	KS	left faucet 3 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:38:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	44	KS	right faucet 3 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:39:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	45	KS	sprayer	FD	4/3/2019	8:00:00 PM	4/4/2019	4:39:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	46	KS	faucet 2 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:40:00 AM	4/8/2019	1.4	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	47	KS	sprayer on 2 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:40:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	48	IM	ice machine	FD	4/3/2019	8:00:00 PM	4/4/2019	4:41:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	49	KS	faucet on kitchen kettle	FD	4/3/2019	8:00:00 PM	4/4/2019	4:43:00 AM	4/8/2019	4.8	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	50	KS	sprayer for kettle	FD	4/3/2019	8:00:00 PM	4/4/2019	4:44:00 AM	4/8/2019	1.1	No

Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	51	TL	faucet in lounge	FD	4/3/2019	8:00:00 PM	4/4/2019	4:52:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	53	NO	faucet in health room	FD	4/3/2019	8:00:00 PM	4/4/2019	4:56:00 AM	4/8/2019	6.7	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	54	IM	ice machine	FD	4/3/2019	8:00:00 PM	4/4/2019	4:58:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	55	CR	faucet A109A	FD	4/3/2019	8:00:00 PM	4/4/2019	5:02:00 AM	4/8/2019	1.1	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	56	CR	faucet A109B	FD	4/3/2019	8:00:00 PM	4/4/2019	5:02:00 AM	4/8/2019	1.7	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	57	DF	fountain in media center	FD	4/3/2019	8:00:00 PM	4/4/2019	5:00:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	58	KS	faucet 2 compartment sink in field house	FD	4/3/2019	8:00:00 PM	4/4/2019	5:46:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	59	IM	ice machine in field house	FD	4/3/2019	8:00:00 PM	4/4/2019	5:46:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	60	CR	faucet in gym training room	FD	4/3/2019	8:00:00 PM	4/4/2019	5:19:00 AM	4/8/2019	<1.0	No
Water Testing	Huntingtown High	4/20/2019	1	61	KS	sprayer in kitchen dish room	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	62	IM	ice machine in K-208	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	63	CR	faucet in K-208	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	2.1	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	1	DF	Fountain outside of main office	FD	4/3/2019	8:00:00 PM	4/4/2019	5:00:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	2	DF	fountain outside of B101	FD	4/3/2019	8:00:00 PM	4/4/2019	5:02:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	3	DF	Bottle filler outside Auditorium	FD	4/3/2019	8:00:00 PM	4/4/2019	5:08:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	4	DF	Fountain outside auditorium	FD	4/3/2019	8:00:00 PM	4/4/2019	5:08:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	5	DF	right fountain outside gym	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	6	DF	left fountain outside gym	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	7	DF	left fountain outside locker rooms	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	<1.0	No

Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	8	DF	right fountain outside locker rooms	FD	4/3/2019	8:00:00 PM	4/4/2019	5:17:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	9	DF	Fountain outside of E111	FD	4/3/2019	8:00:00 PM	4/4/2019	5:21:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	10	DF	Fountain outside F114	FD	4/3/2019	8:00:00 PM	4/4/2019	5:20:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	11	DF	Fountain across F105	FD	4/3/2019	8:00:00 PM	4/4/2019	5:17:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	12	DF	left fountain across A112	FD	4/3/2019	8:00:00 PM	4/4/2019	4:54:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	13	DF	right fountain across A112	FD	4/3/2019	8:00:00 PM	4/4/2019	4:54:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	14	DF	fountain across H212	FD	4/3/2019	8:00:00 PM	4/4/2019	4:50:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	15	DF	fountain across H202	FD	4/3/2019	8:00:00 PM	4/4/2019	4:51:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	16	DF	fountain across I202	FD	4/3/2019	8:00:00 PM	4/4/2019	4:53:00 AM	4/8/2019	<1.0	No
Water Testing	Huntingtown High	4/20/2019	2	17	DF	fountain across J204	FD	4/3/2019	8:00:00 PM	4/4/2019	4:45:00 AM	4/8/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	18	DF	fountain across K209	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	19	DF	fountain by K201	FD	4/3/2019	8:00:00 PM	4/4/2019	4:48:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	3	20	DF	fountain by L305	FD	4/3/2019	8:00:00 PM	4/4/2019	4:49:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	3	21	DF	left fountain outside M317	FD	4/3/2019	8:00:00 PM	4/4/2019	4:40:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	3	22	DF	right fountain outside M317	FD	4/3/2019	8:00:00 PM	4/4/2019	4:55:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	23	DF	Fountain in F115	FD	4/3/2019	8:00:00 PM	4/4/2019	5:19:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	24	CR	front faucet in C113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:04:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	25	CR	back faucet in C113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:04:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	26	CR	front faucet in C112	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	<1.0	No

Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	27	CR	back faucet in C112	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	28	KS	faucet in gym concession stand	FD	4/3/2019	8:00:00 PM	4/4/2019	5:12:00 AM	4/8/2019	1.4	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	29	IM	ice machine in gym concession stand	FD	4/3/2019	8:00:00 PM	4/4/2019	5:12:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	30	CR	faucet in F115	FD	4/3/2019	8:00:00 PM	4/4/2019	5:19:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	31	HE	right faucet in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:04:00 AM	4/8/2019	1.4	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	32	HE	right faucet in right cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:05:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	33	HE	left faucet in right cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:05:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	34	HE	right faucet in middle cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	35	HE	left faucet middle cube in F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:06:00 AM	4/8/2019	1.6	No
Water Testing	Huntingtown High	4/20/2019	1	36	HE	right faucet left cube F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:07:00 AM	4/8/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	37	HE	left faucet left cube F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:07:00 AM	4/8/2019	1.7	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	38	HE	teacher's faucet F113	FD	4/3/2019	8:00:00 PM	4/4/2019	5:07:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	39	HE	right faucet in right cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:09:00 AM	4/8/2019	2.5	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	40	HE	left faucet in right cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:09:00 AM	4/8/2019	2.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	41	HE	right faucet in left cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	7.9	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	42	HE	left faucet in left cube of F113 extension	FD	4/3/2019	8:00:00 PM	4/4/2019	5:10:00 AM	4/8/2019	1.3	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	43	KS	left faucet 3 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:38:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	44	KS	right faucet 3 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:39:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	45	KS	sprayer	FD	4/3/2019	8:00:00 PM	4/4/2019	4:39:00 AM	4/8/2019	<1.0	No

Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	46	KS	faucet 2 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:40:00 AM	4/8/2019	1.4	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	47	KS	sprayer on 2 compartment sink	FD	4/3/2019	8:00:00 PM	4/4/2019	4:40:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	48	IM	ice machine	FD	4/3/2019	8:00:00 PM	4/4/2019	4:41:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	49	KS	faucet on kitchen kettle	FD	4/3/2019	8:00:00 PM	4/4/2019	4:43:00 AM	4/8/2019	4.8	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	50	KS	sprayer for kettle	FD	4/3/2019	8:00:00 PM	4/4/2019	4:44:00 AM	4/8/2019	1.1	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	51	TL	faucet in lounge	FD	4/3/2019	8:00:00 PM	4/4/2019	4:52:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	53	NO	faucet in health room	FD	4/3/2019	8:00:00 PM	4/4/2019	4:56:00 AM	4/8/2019	6.7	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	54	IM	ice machine	FD	4/3/2019	8:00:00 PM	4/4/2019	4:58:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	55	CR	faucet A109A	FD	4/3/2019	8:00:00 PM	4/4/2019	5:02:00 AM	4/8/2019	1.1	No
Water Testing	Huntingtown High	4/20/2019	1	56	CR	faucet A109B	FD	4/3/2019	8:00:00 PM	4/4/2019	5:02:00 AM	4/8/2019	1.7	No

Laboratory of MD														
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	57	DF	fountain in media center	FD	4/3/2019	8:00:00 PM	4/4/2019	5:00:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	58	KS	faucet 2 compartment sink in field house	FD	4/3/2019	8:00:00 PM	4/4/2019	5:46:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	59	IM	ice machine in field house	FD	4/3/2019	8:00:00 PM	4/4/2019	5:46:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	60	CR	faucet in gym training room	FD	4/3/2019	8:00:00 PM	4/4/2019	5:19:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	1	61	KS	sprayer in kitchen dish room	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	62	IM	ice machine in K-208	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	<1.0	No
Water Testing Laboratory of MD	Huntingtown High	4/20/2019	2	63	CR	faucet in K-208	FD	4/3/2019	8:00:00 PM	4/4/2019	4:47:00 AM	4/8/2019	2.1	No