

## 1.2 Executive Summary of Sampling and Analysis:

### Total Number of Samples Collected by Building Classified by First Draw & Confirmatory Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples at or Below Action Level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples at or Below Action Level of 15 ppb	Number of Samples Above Action Level of 15 ppb
Primary School	11/5/2020	144	137	7	N/A	N/A

\*\* Confirmatory samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

### Listing of Outlets Requiring Remediation

#### Locations of Outlets Analyzed above the NYS Action Level of 15 parts per billion based upon Analysis of First Draw Samples:

Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb	Retest Results
172.3-8	Kitchen Drum Fill	Sink	16.9	9.0
172.3-10	Kitchen Lav	Sink	17.0	1.4
172.3-29	Room 134	Bubbler	62.9	7.4
172.3-32	Room 132	Bubbler	84.8	13.7
172.3-41	Room 123	Bubbler	35.4	9.1
172.3-104	Room 148	Bubbler	21.8	1.1
172.3-160	Room 201	Sink	22.3	4.1