



**Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road SE, Tumwater WA 98501**

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please note: The school has implemented flushing program to help reduce overall children's exposure to lead in drinking water.

School Name: Foster High School

School Code: 2848

School District Name: Tukwila

Address: 4242 S 144th St, Tukwila WA 98168

County: King

Number of Samples Collected: 23

Date Collected: 10/29/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
1.	15348	First Draw	Tap	Room 313, far back wall	<1	11/07/2018	6:09 AM, No Aerator, Left Sink
2.	15349	First Draw	Tap	Room 313, far back wall	1	11/07/2018	Right Sink
3.	15350	First Draw	Tap	Room 313	1	11/07/2018	Near interior entrance, left sink
4.	15351	First Draw	Tap	Room 313	1	11/07/2018	Right Sink nearest interior entrance
5.	15352	First Draw	Tap	Kitchen	3	11/07/2018	Food Prep Area
6.	15353	First Draw	Tap	Kitchen, across from dishwasher	1	11/07/2018	Tap Dripping, also used for food prep
7.	15354	First Draw		Kitchen, across from dishwasher	<1	11/07/2018	Also used for food prep
8.	15355	First Draw	Bubbler	Cafeteria	1	11/07/2018	
9.	15356	First Draw	Bubbler	Room 315	<1	11/07/2018	
10.	15357	First Draw	Tap	Room 315	3	11/07/2018	
11.	15359	First Draw	Bubbler	Outside of Room 318	<1	11/07/2018	
12.	15360	First Draw	Bubbler	Room 317	5	11/07/2018	Poor Flow
13.	15361	First Draw	Tap	Room 317	1	11/07/2018	
14.	15362	First Draw	Bubbler	Gym	<1	11/07/2018	Near Men's Room
15.	15364	First Draw	Bubbler	Gym	<1	11/07/2018	Across from Women's Room

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
16.	15365	First Draw	Bubbler	Outside Restrooms Building 100	<1	11/07/2018	
17.	15366	First Draw	Tap	Room 105	3	11/07/2018	No Aerator, Left Sink
18.	15367	First Draw	Tap	Room 105, Right Sink	2	11/07/2018	Tap Drips, No Aerator
19.	15368	First Draw	Tap	Room 100g	4	11/07/2018	Nurses Room
20.	15369	First Draw	Bubbler	Near 2nd floor Restrooms	<1	11/07/2018	
21.	15370	First Draw	Tap	Room 204	7	11/07/2018	Left Side
22.	15371	First Draw	Tap	Room 204	9	11/07/2018	No Aerator, Right Side Sink
23.	15372	Blank			<1	11/07/2018	06295