

School Radon Testing Reporting Form

According to Minnesota Statute 123B.571 subd. 3, a school district that has tested its school buildings for the presence of radon shall report the results of its tests to the Department of Health. Please use this form to submit information about the most recent round or cycle of testing conducted for each building.

Instructions

- 1. Complete one form for each building tested. In this case, a building is defined as an occupied facility with a unique address. This includes administrative buildings.
- 2. Include this form, raw data (e.g. laboratory report) and a building map.
- 3. Submit this form when all work is completed for a round of testing. This includes reporting to the school board, and follow-up testing and post-mitigation testing, if applicable.
- 4. Email information to health.indoorair@state.mn.us.

Contact Information

Name: Wendy German	
	Douglas Rd S. Cottage brove, MN 55016
Phone: 651-425-6277	Email: Wgerman @ Sowashco.org

Initial Radon Testing Information

School Building Name: Pullman Ele	mentary
School District & District Number: South Wa	shington County Schools - District
Building Address: 1260 Selby Ave, St	Paul Park, MN 55071
Test Kit Manufacturer: Air Chek	Device Name: Prothet
Date of Kit Retrieval (DD/MM/YY): 28/02/20	Length of Test (days): 3
How many rooms were tested? 39	
Does the test period include weekends?	es 💢 No
Does the test period include school breaks or h	nolidays? 🗆 Yes 🖎 No

SCHOOL RADON TESTING REPORTING FORM

Were all frequently-occupied ground contact	rooms tested? ¹	es 💢 No
If no, did you attempt to test all freque test kits were placed in all these rooms		ntact rooms, meaning
How many rooms had results ≥ 4 pCi/L?: D		
Were the results reported at a school board m	neeting? 💢 Yes 🗆 N	No
Follow up Tosting Mitigation 9	2 Post Mitigation	Tosting
Follow-up Testing, Mitigation, 8	x Post-Willigation	resung
f one or more rooms tested ≥ 4 pCi/L, please a	nswer the questions belo	ow:
How many rooms had follow-up testing?:		
Number of rooms with follow-up results	≥ 4 pCi/L:	< 4 pCi/L:
Of the rooms that had test results ≥ 4 pCi/L, h	ow many rooms were:	
mitigated by HVAC balancing or operational ch	nanges? :	
mitigated by installation of active soil depress	urization:	
addressed through other corrective measures	?²:	
What was the cost of the installation and/or H	IVAC service work, to mit	tigate radon?\$
What is the known or anticipated annual oper	ating cost of mitigation (estimate)? \$
After radon mitigation, how many rooms were	e retested?:	

Post mitigation results (# of rooms)

≥ 4 pCi/L:

< 4 pCi/L:

¹ This includes classrooms, offices, break rooms, laboratories, cafeterias, libraries, auditoriums, gymnasiums, etc. It includes rooms on grade and rooms above unoccupied spaces that are in contact with the ground, such as rooms above storage rooms, crawl spaces, tunnels, and boiler rooms. If only a sample or portion of rooms were tested, then respond with 'no'.

² 'Other corrective measures' could include moving staff out of a room and making a room unoccupied or trying to seal radon entry points.

Radon test result report for: SOWASHCO PULLMAN

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
9393868	100	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393869	101	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393870	102	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393871	103	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393872	104	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393873	105	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393875	106	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393808	107	2020-02-24 @ 12:00 pm	2020-02-27 @ 11:00 am	0.9 ± 0.4	2020-03-03
9393874	108	2020-02-24 @ 12:00 pm	2020-02-27 @ 11:00 am	< 0.3	2020-03-03
9393803	109	2020-02-24 @ 12:00 pm	2020-02-27 @ 11:00 am	< 0.3	2020-03-03
9393881	11	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393876	110	2020-02-24 @ 12:00 pm	2020-02-27 @ 11:00 am	< 0.3	2020-03-03
9393810	111	2020-02-24 @ 12:00 pm	2020-02-27 @ 11:00 am	< 0.3	2020-03-03
9393804	112	2020-02-24 @ 12:00 pm	2020-02-27 @ 11:00 am	< 0.3	2020-03-03
9393865	113	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393864	114	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393863	115	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393862	116	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393861	117	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393860	118	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393889	119	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393888	120	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393887	121	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393886	122	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393885	123	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393884	124	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393813	18	2020-02-24 @ 12:00 pm	2020-02-27 @ 11:00 am	< 0.3	2020-03-03
9393812	. 19	2020-02-24 @ 12:00 pm	2020-02-27 @ 11:00 am	< 0.3	2020-03-03
9393814	20	2020-02-24 @ 12:00 pm	2020-02-27 @ 11:00 am	0.8 ± 0.4	2020-03-03
9393818	BAND 24	2020-02-24 @ 1:00 pm	2020-02-27 @ 11:00 am	< 0.3	2020-03-03
9393817	CAFETERIA	2020-02-24 @ 1:00 pm	2020-02-27 @ 11:00 am	< 0.3	2020-03-03
9393880	COUNSELOFS	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393816		2020-02-24 @ 12:00 pm	2020-02-27 @ 11:00 am	0.6 ± 0.4	2020-03-03
9393890	KA	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393859		2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393867		2020-02-24 @ 12:00 pm	2020-02-27 @ 11:00 am	< 0.3	2020-03-03
9393866	MEDIA CENTER	2020-02-24 @ 12:00 pm	2020-02-27 @ 10:00 am	< 0.3	2020-03-03

Radon test result report for: SOWASHCO PULLMAN

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
9393879	NURSES	2020-02-24 @ 12:0	00 pm 2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393877	OFFICE	2020-02-24 @ 12:0	00 pm 2020-02-27 @ 10:00 am	0.7 ± 0.4	2020-03-03
9393878	PRINCIPALS	2020-02-24 @ 12:0	00 pm 2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393883	RAEDING	2020-02-24 @ 12:0	00 pm 2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393882	RESOIRCE ROOM	2020-02-24 @ 12:0	00 pm 2020-02-27 @ 10:00 am	< 0.3	2020-03-03
9393811	STAFF	2020-02-24 @ 12:0	00 pm 2020-02-27 @ 11:00 am	< 0.3	2020-03-03

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498