

School Radon Testing Reporting Form

According to Minnesota Statute 123B.571 subd. 3, a school district that has tested its school buildings for the presence of radon shall report the results of its tests to the Department of Health. Please use this form to submit information about the most recent round or cycle of testing conducted for each building.

Instructions

- 1. Complete one form for each building tested. In this case, a building is defined as an occupied facility with a unique address. This includes administrative buildings.
- 2. Include this form, raw data (e.g. laboratory report) and a building map.
- 3. Submit this form when all work is completed for a round of testing. This includes reporting to the school board, and follow-up testing and post-mitigation testing, if applicable.
- 4. Email information to health.indoorair@state.mn.us.

Contact Information

Name: Wendy German	
Mailing Address: 7362 East Point	Douglas Rd S. Cottage brove, MN 55016
Phone: 651-425-6277	Email: Wgerman @ sowashco. org
Initial Radon Testing Inform	

School Building Name: Royal Daks E	Tementary
School District & District Number: South Was	hington County Schools-District 833
Building Address: 7335 Steepleview R	d, Woodbury, MN 55125
Building Address: 7335 Steepleview R. Test Kit Manufacturer: Air Chek	Device Name: Pro Chek
Date of Kit Retrieval (DD/MM/YY): 28/02/20	
How many rooms were tested? 44	
Does the test period include weekends?	es 💢 No
Does the test period include school breaks or h	olidays? □ Yes □ No

SCHOOL RADON TESTING REPORTING FORM

Were all frequently-occupied ground contact	rooms tested? ¹ \text{\text{\$\sigma}}	∕es ĽYNo
If no, did you attempt to test all freque test kits were placed in all these room		ontact rooms, meaning
How many rooms had results ≥ 4 pCi/L?: <i>O</i>		,
Were the results reported at a school board n	neeting? Yes 🗆	No
Follow-up Testing, Mitigation, & If one or more rooms tested ≥ 4 pCi/L, please a		
How many rooms had follow-up testing?:		
Number of rooms with follow-up results	≥ 4 pCi/L:	< 4 pCi/L:
Of the rooms that had test results ≥ 4 pCi/L, h	now many rooms were:	
mitigated by HVAC balancing or operational c mitigated by installation of active soil depress addressed through other corrective measures	surization:	
What was the cost of the installation and/or F		
After radon mitigation, how many rooms were	e retested?:	

≥ 4 pCi/L:

< 4 pCi/L:

Post mitigation results (# of rooms)

¹ This includes classrooms, offices, break rooms, laboratories, cafeterias, libraries, auditoriums, gymnasiums, etc. It includes rooms on grade and rooms above unoccupied spaces that are in contact with the ground, such as rooms above storage rooms, crawl spaces, tunnels, and boiler rooms. If only a sample or portion of rooms were tested, then respond with 'no'.

² 'Other corrective measures' could include moving staff out of a room and making a room unoccupied or trying to seal radon entry points.

Radon test result report for: SOWASHCO ROYAL OAKS

Kit#	Room Id	Started	Ended	pCi/L	Analyze
9393528	100	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	1.4 ± 0.4	2020-03-03
9393503	101	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.1 ± 0.4	2020-03-03
9393530	102	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	0.8 ± 0.4	2020-03-03
9393501	103	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.6 ± 0.5	2020-03-03
9393542	104	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	0.8 ± 0.4	2020-03-03
9393540	105	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.3 ± 0.4	2020-03-03
9393541	106	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	1.5 ± 0.5	2020-03-03
9393539	107	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	1.2 ± 0.5	2020-03-0
9393531	108	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	1.2 ± 0.4	2020-03-0
9393536	109	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	1.3 ± 0.4	2020-03-0
9393532	110	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	1.7 ± 0.4	2020-03-0
9393535	111	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	1.1 ± 0.4	2020-03-0
9393533	112	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	1.8 ± 0.5	2020-03-0
9393534	113	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	1.1 ± 0.4	2020-03-0
9393504	200	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.3 ± 0.4	2020-03-0
9393518	201	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.1 ± 0.4	2020-03-0
9393505	202	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	0.9 ± 0.4	2020-03-0
9393517	203	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.5 ± 0.4	2020-03-0
9393506	204	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	0.9 ± 0.4	2020-03-0
9393891	205	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.0 ± 0.4	2020-03-0
9393507	206	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.2 ± 0.4	2020-03-0
9393514	207	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	0.9 ± 0.4	2020-03-0
9393508	208	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	0.9 ± 0.4	2020-03-0
9393900	209	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.1 ± 0.4	2020-03-0
9393511	210	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.3 ± 0.4	2020-03-0
9393516	211	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.0 ± 0.4	2020-03-0
9393512	212	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	0.8 ± 0.4	2020-03-0
9393515	213	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	0.9 ± 0.4	2020-03-0
9393509	214	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.0 ± 0.4	2020-03-0
9393513	215	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	0.9 ± 0.4	2020-03-0
9393510	216	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	0.6 ± 0.4	2020-03-0
9393894	CAFETERIA	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	0.8 ± 0.4	2020-03-0
9393537	COUNSELOR	2020-02-24 @ 1:00 pm	2020-02-27 @ 11:00 am	1.0 ± 0.5	2020-03-0
9393502	MEDIA	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.0 ± 0.4	2020-03-0
9393522	NURSES	2020-02-24 @ 1:00 pm	2020-02-27 @ 11:00 am	< 0.3	2020-03-0
9393521	OFFICE	2020-02-24 @ 1:00 pm	2020-02-27 @ 11:00 am	1.1 ± 0.4	2020-03-0
9393892	OFFICE SALAZAR	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.1 ± 0.5	2020-03-0

** LABORATORY ANALYSIS REPORT **

March 5, 2020

Radon test result report for: SOWASHCO ROYAL OAKS

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
9393526	PRINCIPAL	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	0.9 ± 0.4	2020-03-03
9393529	REEOURCE2	2020-02-24 @ 1:00 pm	2020-02-27 @ 12:00 pm	0.6 ± 0.4	2020-03-03
9393527	RESOURCE	2020-02-24 @ 1:00 pm	2020-02-27 @ 11:00 am	0.7 ± 0.4	2020-03-03
9393519	STAFF	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	1.4 ± 0.4	2020-03-03
9393520	STAFF OFFICED BY GYM	2020-02-24 @ 2:00 pm	2020-02-27 @ 12:00 pm	0.8 ± 0.4	2020-03-03
9393538	ZEN DEN	2020-02-24 @ 1:00 pm	2020-02-27 @ 11:00 am	0.6 ± 0.4	2020-03-03

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498