

# **School Radon Testing Reporting Form**

According to Minnesota Statute 123B.571 subd. 3, a school district that has tested its school buildings for the presence of radon shall report the results of its tests to the Department of Health. Please use this form to submit information about the most recent round or cycle of testing conducted for each building.

#### Instructions

- 1. Complete one form for each building tested. In this case, a building is defined as an occupied facility with a unique address. This includes administrative buildings.
- 2. Include this form, raw data (e.g. laboratory report) and a building map.
- 3. Submit this form when all work is completed for a round of testing. This includes reporting to the school board, and follow-up testing and post-mitigation testing, if applicable.
- 4. Email information to health.indoorair@state.mn.us.

### **Contact Information**

Name: Wendy German	
Mailing Address: 7362 East Point	t Douglas Rd, Cottage Grove, MN 55016
Phone: 651-425-6277	Email: wgerman@sowashco.org

## **Initial Radon Testing Information**

School Building Name: Bailey Elementary				
School District & District Number: South Washington County Schools - District 833				
Building Address: 4125 Woodlane Drive, Woodbury, MN 55129				
Test Kit Manufacturer: AirChek	Device Name: ProChek			
Date of Kit Retrieval (DD/MM/YY): 11/3/21	Length of Test (days): 3			
How many rooms were tested? 53				
Does the test period include weekends? Yes No				
Does the test period include school breaks or holidays?  Yes No				

#### SCHOOL RADON TESTING REPORTING FORM

Were all frequently-occupied ground contact	rooms tested? <sup>1</sup>	es 🗸 No
If no, did you attempt to test all freque test kits were placed in all these room		ontact rooms, meaning
How many rooms had results $\geq$ 4 pCi/L?: 0		
Were the results reported at a school board n	meeting? Yes 1	No
Follow-up Testing, Mitigation, 8	& Post-Mitigation	n Testing
f one or more rooms tested $\geq$ 4 pCi/L, please a	_	_
	4	
How many rooms had follow-up testing?:		
Number of rooms with follow-up results	≥ 4 pCi/L:	< 4 pCi/L:
Of the rooms that had test results ≥ 4 pCi/L, I	how many rooms were:	
mitigated by HVAC balancing or operational c	changes? :	
mitigated by installation of active soil depress	surization?:	
addressed through other corrective measures	s? <sup>2</sup> :	
What was the cost of the installation and/or h	HVAC service work, to mi	tigate radon? \$
What is the known or anticipated annual ope	rating cost of mitigation (	(estimate)?\$
After radon mitigation, how many rooms wer	re retested?:	

≥ 4 pCi/L:

< 4 pCi/L:

Post mitigation results (# of rooms)

<sup>&</sup>lt;sup>1</sup> This includes classrooms, offices, break rooms, laboratories, cafeterias, libraries, auditoriums, gymnasiums, etc. It includes rooms on grade and rooms above unoccupied spaces that are in contact with the ground, such as rooms above storage rooms, crawl spaces, tunnels, and boiler rooms. If only a sample or portion of rooms were tested, then respond with 'no'.

<sup>&</sup>lt;sup>2</sup> 'Other corrective measures' could include moving staff out of a room and making a room unoccupied or trying to seal radon entry points.

Radon test result report for: SWC 833 BAILEY

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
9594058	100	2021-03-08 @ 10:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594041	101	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594040	102	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594044	115	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594045	116	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594046	117	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594047	118	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594048	119	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$1.1 \pm 0.3$	2021-03-15
9594049	120	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594057	121	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$0.7 \pm 0.4$	2021-03-15
9594056	122	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$0.9 \pm 0.3$	2021-03-15
9594055	123	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594054	124	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594053	125	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594052	126	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594033	127	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$0.9 \pm 0.3$	2021-03-15
9594034	128	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$1.9 \pm 0.4$	2021-03-15
9594035	129	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$0.9 \pm 0.3$	2021-03-15
9594036	130	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$0.6 \pm 0.3$	2021-03-15
9594037	131	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$1.0 \pm 0.4$	2021-03-15
9594038	132	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$1.7 \pm 0.4$	2021-03-15
9594030	133	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$0.9 \pm 0.3$	2021-03-15
9594029	134	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$1.2 \pm 0.3$	2021-03-15
9594028	135	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	$1.0 \pm 0.3$	2021-03-15
9594027	136	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594026	137	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	$0.5 \pm 0.3$	2021-03-15
9594025	138	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594022	139	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	$0.6 \pm 0.3$	2021-03-15
9594023	140	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	$1.1 \pm 0.4$	2021-03-15
9594031	155	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594050	156	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594032	157	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$0.6 \pm 0.3$	2021-03-15
9594051	158	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	< 0.3	2021-03-15
9594005	159 PRINCIPAL	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594006	159 PRINCIPAL 2	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594007	162 ASST PRINCIPAL	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594008	162 ASST PRINCIPAL 2	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15

March 16, 2021

Radon test result report for: SWC 833 BAILEY

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
9594014	181	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594015	183	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594016	184	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	$0.7 \pm 0.4$	2021-03-15
9594017	185	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594018	186	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594019	187	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594020	188	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594021	189	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594042	201	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$0.7 \pm 0.3$	2021-03-15
9594043	202	2021-03-08 @ 9:00 am	2021-03-11 @ 9:00 am	$0.8 \pm 0.4$	2021-03-15
9594024	<b>COMMONS</b>	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	$0.7 \pm 0.3$	2021-03-15
9594013	GYM A	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	$0.9 \pm 0.3$	2021-03-15
9594012	GYM B	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	$0.8 \pm 0.3$	2021-03-15
9594011	GYM C/CAF	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	$0.9 \pm 0.3$	2021-03-15
9594039	MEDIA CENTER	2021-03-08 @ 9:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594003	NURSE 1	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15
9594004	NURSE 2	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	$0.6 \pm 0.4$	2021-03-15
9594001	OFFICE	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	$0.6 \pm 0.3$	2021-03-15
9594002	OFFICE 2	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	$0.6 \pm 0.3$	2021-03-15
9594009	STAFF	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	$0.7 \pm 0.3$	2021-03-15
9594010	STAFF 2	2021-03-08 @ 8:00 am	2021-03-11 @ 8:00 am	< 0.3	2021-03-15

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498