

Lead in Water Testing Results  
South Washington County Schools  
Armstrong Elementary

On December 29<sup>th</sup>, 2018 Armstrong Elementary School's drinking water was tested for concentration of lead.

**The following water sources tested less than 20 parts-per-billion.**

**No action was taken at this time.**

<b>LOCATION</b>	<b>SOURCE</b>	<b>RESULTS (in ug/L)</b>
Nurse's Office	SINK	2.0
Staff Lounge	SINK	2.5
Cafeteria	FOUNTAIN	0
Cafeteria	BOTTLE FILLER	0
Gym (north)	FOUNTAIN	5.6
Gym (south)	FOUNTAIN	13.6
Kitchen (1)	SINK	5.5
Kitchen (2)	SPRAYER	5.4
Room R1	SINK	2.4
Room R1	FOUNTAIN	2.6
Room R2	SINK	13.5
Room R2	FOUNTAIN	7.6
Room R3	SINK	8.6
Room R3	FOUNTAIN	5.6
Room R4	SINK	1.7
Room R4	FOUNTAIN	6.0

Room R5	SINK	10.9
Room R5	FOUNTAIN	10.9
Room R6	SINK	7.7
Room R6	FOUNTAIN	4.1
Room G1	FOUNTAIN	12.1
Hallway (outside G1)	FOUNTAIN	.40
Room G2	SINK	3.1
Room G2	FOUNTAIN	3.9
Room G3	SINK	3.7
Room G3	FOUNTAIN	1.6
Room G4	SINK	2.1
Room G4	FOUNTAIN	1.6
Room G5	SINK	11.1
Room G5	FOUNTAIN	12.0
Room G6	SINK	3.6
Room G6	FOUNTAIN	2.8
Room Y1	SINK	8.3
Room Y1	FOUNTAIN	7.1
Room Y2	SINK	4.4
Room Y2	FOUNTAIN	3.3
Room Y3	SINK	3.7
Room Y3	FOUNTAIN	1.0
Room Y4	SINK	6.2
Room Y4	FOUNTAIN	1.3
Room Y5	SINK	6.5

Room Y5	FOUNTAIN	5.7
Room Y6	SINK	7.1
Room Y6	FOUNTAIN	5.1
Room Y7	SINK	6.1
Room Y7	FOUNTAIN	1.3
Room Y8	SINK	5.3
Room Y8	FOUNTAIN	1.5
Room B1	SINK	4.8
Room B1	FOUNTAIN	4.9
Hallway (outside B1)	FOUNTAIN	0
Hallway (outside B1)	BOTTLE FILLER	0
Room B3	SINK	2.6
Room B3	FOUNTAIN	2.7
Room B4	SINK	3.9
Room B4	FOUNTAIN	2.1
Room B5	SINK	2.8
Room B5	FOUNTAIN	1.7
Room B6	SINK	9.3
Room B6	FOUNTAIN	7.8
Room B7	SINK	6.5
Room B7	FOUNTAIN	4.4
Room KA	SINK	5.5
Room KA	FOUNTAIN	1.5
Room KB	SINK	10.9
Room KB	FOUNTAIN	3.0

**The following water sources tested with results of the concentration to be over 20 parts-per-billion. The fixtures of these water sources were replaced, and a re-test was administered. Results of the initial test and retest are below. No water sources re-tested over 20 parts-per-billion and no further action will be taken at this time.**

<b>LOCATION</b>	<b>SOURCE</b>	<b>INITIAL RESULTS (in ug/L)</b>	<b>RE-TEST RESULTS</b>
Room G1	SINK	77.6	6.8
Room B2	SINK	20.0	7.7
Room B2	SINK	23.7	3.4
Kitchen (3)	SINK	49.1	8.4
Kitchen (4)	SINK	53.8	1.1