Water Testing Results - Pleasant Hill School District Action Level is 15 parts per billion (ppb)			
Fixture Location / Description	**Fixture ID #**	**Test Date**	**Test Results (ppb)**
PHES Classroom #17 Sink *RESTEST*	20810100-033CF	6/17/2021	ND
PHES Classroom #16 Sink *RETEST*	20810100-050CF	6/17/2021	ND
PHHS -HS Girl's Restroom South Sink North Faucet	20810200-008BF	6/17/2021	7.89
PHHS -HS Girl's Restroom North Sink South Faucet	20810200-010BF	6/17/2021	2.65
PHHS -HS Boy's Restroom North Sink South Faucet	20810200-012BF	6/17/2021	5.31
PHHS -HS Boy's Restroom South Sink North Faucet	20810200-013BF	6/17/2021	13.8
PHHS -MS Vestibule #101 Upper Drinking Fountain	20810200-015DW	6/17/2021	ND
PHHS -MS Vestibule #101 Lower Drinking Fountain	20810200-016DW	6/17/2021	ND
PHHS -HS Vestibule #102 Upper Drinking Fountain	20810200-017DW	6/17/2021	ND
PHHS -HS Vestibule #102 Lower Drinking Fountain	20810200-018DW	6/17/2021	ND
PHHS -MS Boy's Restroom North Sink South Faucet	20810200-039BF	6/17/2021	5.84
PHHS -MS Boy's Restroom South Sink North Faucet	20810200-040BF	6/17/2021	3.93
PHHS -MS Girl's Restroom North Sink South Faucet	20810200-043BF	6/17/2021	5.04
PHHS -MS Girl's Restroom South Sink North Faucet	20810200-044BF	6/17/2021	4.78
PHHS Main Gym Canteen Food Prep Sink	20810201-001KF	6/17/2021	2.09
PHHS Main Gym Commons Drinking Fountain	20810201-002DW	6/17/2021	ND
PHHS Main Gym Boy's Locker Room Restroom West Sink	20810201-004BF	6/17/2021	2.39
PHHS Main Gym Boy's Locker Room Restroom Center Sink	20810201-005BF	6/17/2021	ND
PHHS Main Gym Boy's Locker Room Restroom East Sink	20810201-006BF	6/17/2021	ND
PHHS Main Gym Boy's Locker Room Drinking Fountain	20810201-007DW	6/17/2021	ND
PHHS Main Gym Girl's Team Room Restroom Sink	20810201-008BF	6/17/2021	3.37
PHHS Main Gym Girl's Team Room Drinking Fountain	20810201-009DW	6/17/2021	29.2
PHHS Main Gym Girl's Locker Room Restroom South Sink	20810201-010BF	6/17/2021	ND
PHHS Main Gym Girl's Locker Room Restroom Center Sink	20810201-011BF	6/17/2021	ND
PHHS Main Gym Girl's Locker Room Restroom North Sink	20810201-012BF	6/17/2021	2.2
ND = Not Dectected - Lead level is below the set detection limits of 2 ppb			

Action Level is 15 parts per billion (ppb)			
Fixture Location / Description	**Fixture ID #**	**Test Date**	**Test Results (ppb)**
PHHS Main Gym Girl's Locker Room Drinking Fountain	20810201-013DW	6/17/2021	ND
PHHS Main Gym Girl's Locker Room Coach's Restroom Sink	20810201-014BF	6/17/2021	ND
PHHS Main Gym Girl's Restroom North Sink	20810201-015BF	6/17/2021	ND
PHHS Main Gym Girl's Restroom South Sink	20810201-016BF	6/17/2021	ND
PHHS Main Gym Boy's Restroom North Sink	20810201-017BF	6/17/2021	ND
PHHS Main Gym Boy's Restroom South Sink	20810201-018BF	6/17/2021	ND
PHHS Main Gym Weight Room Drinking Fountain	20810201-019DW	6/17/2021	2.96
PHHS Main Gym Girl's Locker Room Water Bottle Filler	20810201-021WB	6/17/2021	ND
PHHS Main Gym Boy's Locker Room Water Bottle Filler	20810201-022WB	6/17/2021	ND
PHHS Main Gym Boy's Locker Room Coach's Restroom Sink	20810201-053SF	6/17/2021	ND
PHHS Main Gym Athletic Trainer Office Sink	20810201-054SF	6/17/2021	ND
PHHS Forestry Building Restroom Sink	20810208-002BF	6/17/2021	10.7
PHHS Billy Shack Boy's Restroom East Sink	20810210-002BF	6/17/2021	19.1
PHHS Billy Shack Boy's Restroom West Sink	20810210-003BF	6/17/2021	32.1
PHHS Billy Shack Girl's Restroom East Sink	20810210-004BF	6/17/2021	15.4
PHHS Billy Shack Girl's West Sink	20810210-005BF	6/17/2021	9.92
PHHS Billy Shack Ice Machine	20810210-006IM	6/17/2021	ND
PHHS Baseball Snack Shack Varsity Field Drinking Fountain	20810213-001DW	6/17/2021	ND
PHHS Baseball Snack Shack Ice Machine	20810213-002IM	6/17/2021	ND
ND = Not Dectected - Lead level is below the set detection limits of 2 ppb			