Water Testing Results - Pleasant Hill School District Action Level is 15 parts per billion (ppb)			
Fixture Location / Description	**Fixture ID #**	**Test Date**	**Test Results (ppb)**
PHHS Classroom S2 South Sink East Faucet	20810200-026CF	6/9/2021	ND
PHHS Classroom S2 South Sink West Faucet	20810200-027CF	6/9/2021	ND
PHHS Classroom S2 North Sink East Faucet	20810200-028CF	6/9/2021	ND
PHHS Classroom S2 North Sink West Faucet	20810200-029CF	6/9/2021	ND
PHHS Classroom S2 Center Sink	20810200-030CF	6/9/2021	ND
PHHS Staff Women's Restroom East Sink	20810200-031BF	6/9/2021	ND
PHHS Staff Women's Restroom West Sink	20810200-032BF	6/9/2021	ND
PHHS Prep Room #127 Sink	20810200-033OT	6/9/2021	ND
PHHS Classroom S4 East Sink	20810200-034CF	6/9/2021	ND
PHHS Classroom S4 West Sink	20810200-035CF	6/9/2021	ND
PHHS Classroom S5 East Sink	20810200-036CF	6/9/2021	ND
PHHS Classroom S5 West Sink	20810200-037CF	6/9/2021	ND
PHHS -MS Boy's Restroom North Sink North Faucet	20810200-038BF	6/9/2021	2.99
PHHS -MS Boy's Restroom South Sink South Faucet	20810200-041BF	6/9/2021	ND
PHHS -MS Girl's Restroom North Sink North Faucet	20810200-042BF	6/9/2021	ND
PHHS -MS Vestibule #101 Water Bottle Filler	20810200-056WB	6/9/2021	ND
PHHS -MS Girl's Restroom South Sink South Faucet	20810200-058BF	6/9/2021	ND
ND = Not Dectected - Lead level is below the set detection limits of 2 ppb			