

Water Testing Results - Pleasant Hill School District
Action Level is 15 parts per billion (ppb)

Fixture Location / Description	Fixture ID #	Test Date	Test Results (ppb)
PHHS Prep Room #123 Sink	20810200-001OT	6/8/2021	ND
PHHS Classroom S3 South Sink East Faucet	20810200-002CF	6/8/2021	ND
PHHS Classroom S3 South Sink West Faucet	20810200-003CF	6/8/2021	ND
PHHS Classroom S3 North Sink East Faucet	20810200-004CF	6/8/2021	ND
PHHS Classroom S3 North Sink West Faucet	20810200-005CF	6/8/2021	ND
PHHS Classrom S3 Center Sink	20810200-006CF	6/8/2021	ND
PHHS Girls Restroom South Sink South Faucet	20810200-007BF	6/8/2021	2.37
PHHS Girls Restroom North Sink North Faucet	20810200-009BF	6/8/2021	ND
PHHS Boys Restroom North Sink North Faucet	20810200-011BF	6/8/2021	ND
PHHS Boys Restroom South Sink South Faucet	20810200-014BF	6/8/2021	2.18
PHHS Staff Men's Restroom East Sink	20810200-019BF	6/8/2021	ND
PHHS Staff Men's Restroom West Sink	20810200-020BF	6/8/2021	ND
PHHS Classroom S1 South Sink East Faucet	20810200-021CF	6/8/2021	ND
PHHS Classroom S1 South Sink West Faucet	20810200-022CF	6/8/2021	ND
PHHS Classroom S1 North Sink East Faucet	20810200-023CF	6/8/2021	ND
PHHS Classroom S1 North Sink West Faucet	20810200-024CF	6/8/2021	ND
PHHS Classroom S1 Center Sink	20810200-025CF	6/8/2021	ND
PHHS Vestibule #102 Water Bottle Filler	20810200-057WB	6/8/2021	ND

ND = Not Detected - Lead level is below the set detection limits of 2 ppb