Water Testing Results - Pleasant Hill School District Action Level is 15 parts per billion (ppb)			
Fixture Location / Description	**Fixture ID #**	**Test Date**	**Test Results (ppb)**
PHES Nurse Room Sink	20810100-025NS	6/5/2021	ND
PHES Nurse Restroom Sink	20810100-026BF	6/5/2021	ND
PHES 2nd Floor Staff Restroom West Sink	20810100-027BF	6/5/2021	ND
PHES 2nd Floor Staff Restroom East Sink	20810100-028BF	6/5/2021	ND
PHES 3rd Floor Staff Restroom Sink	20810100-030BF	6/5/2021	ND
PHES Copy Room Sink	20810100-031SF	6/5/2021	3.15
PHES K-1 Commons Sink	20810100-032OT	6/5/2021	3.25
PHES Classroom #14 Sink	20810100-034CF	6/5/2021	3.19
PHES Classroom #12 Sink	20810100-035CF	6/5/2021	ND
PHES Classroom #13 Sink	20810100-036CF	6/5/2021	ND
PHES Classroom #15 Sink	20810100-037CF	6/5/2021	ND
PHES 5th Grade Commons Sink	20810100-038OT	6/5/2021	ND
PHES Classroom #4 Sink	20810100-042CF	6/5/2021	6.26
PHES 1st Grade Commons Sink	20810100-048OT	6/5/2021	2.48
PHES Classroom #18 Sink	20810100-051CF	6/5/2021	2.26
PHES Classroom #19 Sink	20810100-052CF	6/5/2021	ND
PHES 3rd Grade Commons Sink	20810100-053OT	6/5/2021	ND
PHES Classroom #20 Sink	20810100-081CF	6/5/2021	ND
PHES Classroom #21 Sink	20810100-082CF	6/5/2021	ND
ND = Not Dectected - Lead level is below the set detection limits of 2 ppb			