

Water Sampling Results

Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above

ND: Non-detect (below detection limit) | PPB: Parts per Billion

School Name Silver Creek ES

Sample Type	Sample ID	Sample Description	Lead Result in PPB	Action Taken	Back in Service Date	Sample Count
Initial Sample	030317.199A.A104SK.01	Sink, room A104	0.63	-	-	1
	030317.199A.A106SK.01	Sink, room A106	ND	-	-	1
	030317.199A.A110DF.01	Drinking fountain, room A110	ND	-	-	1
	030317.199A.A113DF.01	Drinking fountain, room A113, attached to sink	5.2	-	-	1
	030317.199A.A113SK.01	Sink, room A113	1.5	-	-	1
	030317.199A.A116SK.01	Sink, room A116	ND	-	-	1
	030317.199A.A117ADF.01	Drinking fountain, corridor A117A	ND	-	-	1
	030317.199A.A120DF.01	Drinking fountain, room A120, attached to sink	ND	-	-	1
	030317.199A.A120SK.01	Sink, room A120	1	-	-	1
	030317.199A.A126DF.01	Drinking fountain, room A120, attached to sink	ND	-	-	1
	030317.199A.A126SK.01	Sink, room A120	3	-	-	1
	030317.199A.A128DF.01	Drinking fountain, room A128, attached to sink	ND	-	-	1
	030317.199A.A128SK.01	Sink, room A128	0.82	-	-	1
	030317.199A.A129DF.01	Drinking fountain, room A129, attached to sink	ND	-	-	1
	030317.199A.A129SK.01	Sink, room A129	ND	-	-	1
	030317.199A.A133DF.01	Drinking fountain, corridor A133	ND	-	-	1
	030317.199A.A134DF.01	Drinking fountain, room A134, attached to sink	ND	-	-	1
	030317.199A.A134SK.01	Sink, room A134	0.78	-	-	1
	030317.199A.A135DF.01	Drinking fountain, room A135, attached to sink	ND	-	-	1
	030317.199A.A135SK.01	Sink, room A135	0.62	-	-	1
	030317.199A.A136DF.01	Drinking fountain, room A136, attached to sink	ND	-	-	1
	030317.199A.A136SK.01	Sink, room A136	0.51	-	-	1
	030317.199A.A138DF.01	Drinking fountain, room A138, attached to sink	ND	-	-	1
	030317.199A.A138SK.01	Sink, room A138	ND	-	-	1
	030317.199A.A139DF.01	Drinking fountain, room A139, attached to sink	ND	-	-	1
	030317.199A.A139SK.01	Sink, room A139	ND	-	-	1
	030317.199A.B100SK.01	Sink, room B100, middle of room, north side of wall	7.4	-	-	1
	030317.199A.B100SK.02	Sink, room B100, middle of room, south side of wall	0.5	-	-	1
	030317.199A.B100SK.03	Sink, room B100, middle of room, south end, west wall	1.1	-	-	1
	030317.199A.B100SK.04	Sink, room B100, middle of room, south wall of kitchen	19	Taken offline	-	1
	030317.199A.B114DF.01	Drinking fountain, room B114, attached to sink	ND	-	-	1
	030317.199A.B114SK.01	Sink, room B114, SE corner	ND	-	-	1
	030317.199A.B114SK.02	Sink, room B114, west wall, right side sink	0.54	-	-	1
	030317.199A.B114SK.03	Sink, room B114, west wall, left side sink	ND	-	-	1
	030317.199A.C100DF.01	Drinking fountain, room C100, attached to sink	ND	-	-	1
	030317.199A.C100SK.01	Sink, room C100	ND	-	-	1
	030317.199A.C102DF.01	Drinking fountain, room C102, attached to sink	ND	-	-	1
	030317.199A.C102SK.01	Sink, room C102	0.74	-	-	1
	030317.199A.C103DF.01	Drinking fountain, room C103, attached to sink	ND	-	-	1
	030317.199A.C103SK.01	Sink, room C103	0.59	-	-	1
	030317.199A.C104DF.01	Sink, corridor C104	ND	-	-	1
	030317.199A.C108DF.01	Drinking fountain, room C108, attached to sink	ND	-	-	1
	030317.199A.C108SK.01	Sink, room C108	0.79	-	-	1
	030317.199A.C109DF.01	Drinking fountain, room C109, attached to sink	ND	-	-	1
	030317.199A.C109SK.01	Sink, room C109	ND	-	-	1
030317.199A.C110DF.01	Drinking fountain, room C110, attached to sink	ND	-	-	1	
030317.199A.C110SK.01	Sink, room C110	ND	-	-	1	
030317.199A.C112DF.01	Drinking fountain, room C112, attached to sink	ND	-	-	1	
030317.199A.C112SK.01	Sink, room C112	ND	-	-	1	
030317.199A.C113DF.01	Drinking fountain, room C113, attached to sink	ND	-	-	1	
030317.199A.C113SK.01	Sink, room C113	ND	-	-	1	
030317.199A.D100DF.01	Drinking fountain, room D100, attached to sink	ND	-	-	1	
030317.199A.D100SK.01	Sink, room D100	ND	-	-	1	
030317.199A.D102DF.01	Drinking fountain, room D102, attached to sink	ND	-	-	1	

Water Sampling Results

Report Legend:

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above

ND: Non-detect (below detection limit) | PPB: Parts per Billion

School Name Silver Creek ES

Sample Type	Sample ID	Sample Description	Lead Result in PPB	Action Taken	Back in Service Date	Sample Count
	030317.199A.D102SK.01	Sink, room D102	ND	-	-	1
	030317.199A.D103DF.01	Drinking fountain, room D103, attached to sink	ND	-	-	1
	030317.199A.D103SK.01	Sink, room D103	ND	-	-	1
	030317.199A.D104DF.01	Sink, corridor D104	ND	-	-	1
	030317.199A.D108DF.01	Drinking fountain, room D108, attached to sink	ND	-	-	1
	030317.199A.D108SK.01	Sink, room D108	ND	-	-	1
	030317.199A.D109DF.01	Drinking fountain, room D109, attached to sink	ND	-	-	1
	030317.199A.D109SK.01	Sink, room D109	ND	-	-	1
	030317.199A.D110DF.01	Drinking fountain, room D110, attached to sink	ND	-	-	1
	030317.199A.D110SK.01	Sink, room D110	ND	-	-	1
	030317.199A.D112DF.01	Drinking fountain, room D112, attached to sink	ND	-	-	1
	030317.199A.D112SK.01	Sink, room D112	0.78	-	-	1
	030317.199A.D120DF.01	Drinking fountain, room D120, attached to sink	0.62	-	-	1
	030317.199A.D120SK.01	Sink, room D120	ND	-	-	1
	030317.199A.D125SK.01	Sink, room D125	ND	-	-	1
	030317.199A.D128SK.01	Sink, room D128	ND	-	-	1
	030317.199A.D131SK.01	Sink, room D131	ND	-	-	1
	030317.199A.D142DF.01	Drinking fountain, room D142, attached to SK.01	ND	-	-	1
	030317.199A.D142DF.02	Drinking fountain, room D142, attached to SK.02	ND	-	-	1
	030317.199A.D142SK.01	Sink, room D142, south wall, west side	0.89	-	-	1
	030317.199A.D142SK.02	Sink, room D142, south wall, east side	0.67	-	-	1
	030317.199A.D144DF.01	Drinking fountain, room D144, attached to SK.01	0.92	-	-	1
	030317.199A.D144DF.02	Drinking fountain, room D144, attached to SK.02	ND	-	-	1
	030317.199A.D144SK.01	Sink, room D144, south wall, east side	0.59	-	-	1
	030317.199A.D144SK.02	Sink, room D144, south wall, west side	0.57	-	-	1
Initial Sample Total						79

Resultados de las Muestras de Agua

Guía en español para leer los resultados de las pruebas de las muestras de agua en su escuela

Por favor, consulte esta guía para entender mejor los resultados en español de las pruebas de las muestras de agua en su escuela:

Report Legend: Leyenda del Reporte

- Sample ID: Lab Generated Unique ID = ID de la Muestra: ID única creada por el laboratorio
- Yellow: 15-19.9PPB | Orange: 20 PPB and Above = Amarillo: 15-19.9 ppb | Anaranjado: 20 ppb y más
- PPB: partes por mil millones
- ND: No detectable (por debajo del límite detectable)

Sample Description: ID de la Muestra

- Drinking fountain = Fuente de agua
- Sink = Lavabo
- Room ## = salón ##
- Middle of room = a mitad del salón
- North wall = pared del norte
- NE corner = esquina al noreste
- SE corner = esquina al sureste
- NW corner = esquina al noroeste
- SW corner = esquina al suroeste
- Next to SK.## = al lado del SK.## (SK=lavabo/fregadero)
- Hallway = pasillo
- Main hallway = pasillo principal
- Long main hallway = Pasillo principal largo
- Short main hallway = Pasillo principal corto

Lead Result in PPB = Resultados de plomo en PPB

La Agencia de Protección Ambiental (EPA, por sus siglas en inglés) mide la cantidad de plomo en el agua en "partes por mil millones" o "ppb (por sus siglas en inglés)." Una parte por mil millones equivale a una gota de agua en 55,000 galones. Al igual que otros distritos escolares en Colorado que voluntariamente están conduciendo estas pruebas, Adams 12 Five Star Schools está siguiendo las normas de EPA para eliminar y remediar cualquier accesorio de plomería que tenga niveles de plomo de 15 ppb o más.

Action = Acción

Taken offline = Desconectado/a