

## Water Sampling Results

**Report Legend:**

Sample ID: Lab Generated Unique ID | Yellow: 15-19.9PPB | Orange: 20 PPB and Above

ND: Non-detect (below detection limit) | PPB: Parts per Billion

**School Name** Century MS

Sample Type	Sample ID	Sample Description	Lead Result in PPB	Action Taken	Back in Service Date	Sample Count
Initial Sample	031717.270A.A101DF.01	Drinking fountain, room A101, east wall, left side DF	ND	-	-	1
	031717.270A.A101DF.02	Drinking fountain, room A101, east wall, middle DF	ND	-	-	1
	031717.270A.A101DF.03	Drinking fountain, room A101, east wall, right side DF	ND	-	-	1
	031717.270A.A102DF.01	Drinking fountain, north wall, right side DF	ND	-	-	1
	031717.270A.A102DF.02	Drinking fountain, north wall, left side DF	ND	-	-	1
	031717.270A.AD104SK.01	Sink, room AD104	0.68	-	-	1
	031717.270A.AD112SK.01	Sink, room AD112	5.6	-	-	1
	031717.270A.AD114DF.01	Drinking fountain, room AD114, attached to sink	ND	-	-	1
	031717.270A.AD114SK.01	Sink, room AD114	0.62	-	-	1
	031717.270A.B100DF.01	Drinking fountain, room B100	ND	-	-	1
	031717.270A.B100SK.01	Sink, room B100	6.1	-	-	1
	031717.270A.B101DF.01	Drinking fountain, room B101	ND	-	-	1
	031717.270A.B101SK.01	Sink, room B101	1.1	-	-	1
	031717.270A.C100ASK.01	Sink, room C100A	4	-	-	1
	031717.270A.C100CSK.01	Sink, room C100C, north side	2	-	-	1
	031717.270A.C100CSK.02	Sink, room C100C, east side of middle island	7.8	-	-	1
	031717.270A.C100CSK.03	Sink, room C100C, south end, west side of middle island	1.2	-	-	1
	031717.270A.C100CSK.04	Sink, room C100C, east wall, right side	0.72	-	-	1
	031717.270A.C100CSK.05	Sink, room C100C, east wall, left side	ND	-	-	1
	031717.270A.C101DF.01	Drinking fountain, corridor C101, south end, west wall, bot	ND	-	-	1
	031717.270A.C101DF.02	Drinking fountain, corridor C101, south end, west wall, high	ND	-	-	1
	031717.270A.C101DF.03	Drinking fountain, corridor C101, south end, west wall, low	ND	-	-	1
	031717.270A.C103SK.01	Sink, room C103	0.67	-	-	1
	031717.270A.C104ESK.01	Sink, room C104E	1.1	-	-	1
	031717.270A.C107DF.01	Drinking fountain, hallway C107, south end, west wall	ND	-	-	1
	031717.270A.C107DF.02	Drinking fountain, room C107	ND	-	-	1
	031717.270A.C201DF.01	Drinking fountain, room C201	ND	-	-	1
	031717.270A.C210DF.01	Drinking fountain, room C210	ND	-	-	1
	031717.270A.D104SK.01	Sink, room D104, north wall, left side SK	0.53	-	-	1
	031717.270A.D104SK.02	Sink, room D104, north wall, right side SK	0.86	-	-	1
	031717.270A.D104SK.03	Sink, room D104, east wall, left side SK	1.5	-	-	1
	031717.270A.D104SK.04	Sink, room D104, east wall, right side SK	3.9	-	-	1
	031717.270A.D104SK.05	Sink, room D104, south wall, left side SK	13	-	-	1
	031717.270A.D104SK.06	Sink, room D104, south wall, middle SK	1.1	-	-	1
	031717.270A.D104SK.07	Sink, room D104, south wall, right side SK	1.6	-	-	1
	031717.270A.D106SK.01	Sink, room D106	1.1	-	-	1
	031717.270A.D109SK.01	Sink, room D109	ND	-	-	1
	031717.270A.D205SK.01	Sink, room D205	1.4	-	-	1
	031717.270A.D208SK.01	Sink, room D208	1.3	-	-	1
	031717.270A.E100SK.01	Sink, room E100, north wall (south wall SK not working)	1.2	-	-	1
031717.270A.F102SK.01	Sink, room F102	2.4	-	-	1	
031717.270A.F105SK.01	Sink, room F105	1	-	-	1	
031717.270A.F108SK.01	Sink, room F108	2.5	-	-	1	
031717.270A.F202SK.01	Sink, room F202	2.1	-	-	1	
031717.270A.F205SK.01	Sink, room F205	2	-	-	1	
031717.270A.F208SK.01	Sink, room F208	2.4	-	-	1	
031717.270A.G100SK.01	Sink, room G100	ND	-	-	1	
031717.270A.G101SK.01	Sink, room G101	0.51	-	-	1	
031717.270A.IP105DF.01	Drinking fountain, room IP105	ND	-	-	1	
031717.270A.IP125DF.01	Drinking fountain, room IP125	ND	-	-	1	
031717.270A.IP207DF.01	Drinking fountain, room IP207	ND	-	-	1	
031717.270A.IP226DF.01	Drinking fountain, room IP226	ND	-	-	1	
031717.270A.PE107DF.01	Drinking fountain, room PE107	ND	-	-	1	
031717.270A.PE108SK.01	Sink, room PE108	0.96	-	-	1	
031717.270A.PE115SK.01	Sink, room PE115	1.8	-	-	1	
031717.270A.PE117DF.01	Drinking fountain, room PE117	ND	-	-	1	
031717.270A.S104SK.01	Sink, room S104, cafeteria stage sink	660	Taken offline	-	1	
<b>Initial Sample Total</b>						<b>57</b>
Re-test Sample - 1	072117.270A.S104SK.01	Sink, room S104, cafeteria stage sink	13	Back in service	8/3/2017	1
<b>Re-test Sample - 1 Total</b>						<b>1</b>