

To: All Bidders
From: Ryan Fealey, Director of Finance
Date: May 22, 2020
Re: RFP 20-07 Fire Alarm, Building PA System, and Clock System

ADDENDUM 1

VENDOR QUESTIONS & ANSWERS FOR RFP 20-07

1. Are you able to provide previous test reports for Fire Alarm System, PA system and Clock System?
Yes, see below in page 2.
2. Who is the incumbent(s)? How many years have they been your current provider?
TPC for fire alarm, FPT for fire sprinkler.
3. How many vendors will be selected for this contract? (Is your intent to consolidate all services)?
One vendor for each RFP. However, one vendor can be awarded both contracts as well.
4. What is the current contract value for Fire Alarm, Sprinkler, and Kitchen Hoods?
Fire Alarm inspections - \$49,876.00; Fire sprinkler quarterly inspection – \$21,172; Kitchen hood test & inspections – \$10,035.73.
5. Are you able to provide historical data on annual spending for service and repair work?
N/A
6. How many bids will you be receiving and from whom?
This is a public bid.
7. Does this Bid require our company to quote all 3-Different Systems or can we just bid the Fire Alarm Systems? How do we get an Inventory List of the Schools and the type of systems that are installed in the schools? Would an Inventory list tell us how many smoke detectors are installed as well as duct smoke detectors?
We prefer all 3 systems to be bid by same contractor. Inventory in page 2 below. **Please note that Westover school is under construction and we not have a report for it at the time being**

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Davenport Ridge
School
1300 Newfield Avenue
Stamford, CT 06904

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Feb 18, 2020



Building: Stamford BOE-Davenport Ridge School
Contact: Davor Lucaj
Title: Facilities Trades Manager

Company: TPC Associates, Inc.
Contact: Dave Majewski
Title: Inspector

Executive Summary





Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Davenport Ridge School	Contact: Davor Lucaj	
Address: 1300 Newfield Avenue	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06904	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Dave Majewski	
Address: 261 Pepe's Farm Road	Phone: 203-666-9587	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: dave.majewski@tpcsystems.com	
System Control Unit		
Manufacturer: Notifier	Inspection Date: 02/18/2020	IDC Style:
Model Number:	Install Date: 02/25/2013	SLC Style:
Software Version:	Version Date: 02/25/2013	NAC Style:
Location: 1st Corridor By Main Office	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.67%	0	0%	0	0%	0	0%
Control	5	3.33%	5	100.00%	4	80.00%	1	20.00%
Initiating	144	96.00%	144	100.00%	144	100.00%	0	0%
Totals	150	100%	149	99.33%	148	99.33%	1	0.67%
Certification								
Company: TPC Associates, Inc.				Building: Stamford BOE-Davenport Ridge School				
Inspector: Dave Majewski				Contact: Davor Lucaj				
								
Signed: Feb 18, 2020 8:30:32 AM				Signed: Feb 18, 2020 8:30:42 AM				

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-Davenport Ridge School			Control Panel: 1 - Notifier	
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
 ScanID	 Location	 Problem	Address	 Reference
<i>Control</i>				
Battery				
09396232	1st Corridor By Main Office Below FACP	Failed Test	1	NFPA 72 Table 10.4.2.2.5(a-e)

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-Davenport Ridge School			Control Panel: 1 - Notifier		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
Control					
Battery					
09396232	1st Corridor By Main Office Below FACP	Replace	UB12550	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Davenport Ridge School		Control Panel: 1 - Notifier		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Annunciator	1st Custodian Office	Tested	8:16:49 AM	02/18/2020
Battery	1st Corridor By Main Office FACP	Tested	7:36:26 AM	02/18/2020
Battery	1st Pump Room	Tested	8:07:03 AM	02/18/2020
Control Panel	1st Corridor By Main Office	Tested	7:36:12 AM	02/18/2020
Initiating				
Duct Detector	1st Corridor By Custodian 2 RTU-3	Visually Checked	10:30:49 AM	02/18/2020
Duct Detector	1st Corridor By P.E. Office RTU-11	Visually Checked	10:30:57 AM	02/18/2020
Duct Detector	1st Corridor By Professional Room RTU-8	Visually Checked	10:31:01 AM	02/18/2020
Duct Detector	1st Corridor By Room 31 RTU-1	Visually Checked	10:30:53 AM	02/18/2020
Duct Detector	1st Corridor By Custodial 2 RTU-9	Visually Checked	10:30:40 AM	02/18/2020
Duct Detector	1st Corridor By Custodian 6 RTU 7	Visually Checked	10:30:17 AM	02/18/2020
Duct Detector	1st Corridor By Main Office	Visually Checked	10:30:36 AM	02/18/2020
Duct Detector	1st Corridor Ramp By Room 9 RTU-4	Visually Checked	10:30:44 AM	02/18/2020
Duct Detector	1st Kindergarten Wing Corridor RTU-5	Visually Checked	10:30:29 AM	02/18/2020
Duct Detector	1st Room 38 Art, Music, Drama Storage 8 RTU-6	Visually Checked	10:31:06 AM	02/18/2020
Heat Detector	1st Kitchen	Tested	8:21:37 AM	02/18/2020
Pull Station	1st Corridor By Cafeteria	Visually Checked	8:02:07 AM	02/18/2020
Pull Station	1st Corridor By Library Media Center Storage	Visually Checked	8:19:24 AM	02/18/2020
Pull Station	1st Corridor By P.E. Office	Visually Checked	8:17:44 AM	02/18/2020
Pull Station	1st Corridor By Custodian 2	Visually Checked	7:44:46 AM	02/18/2020
Pull Station	1st Corridor By Room 28	Visually Checked	7:50:53 AM	02/18/2020
Pull Station	1st Corridor Exit By Pump Room	Visually Checked	8:00:59 AM	02/18/2020
Pull Station	1st Corridor Exit By Storage 2	Visually Checked	7:48:42 AM	02/18/2020
Pull Station	1st Kindergarten Wing Exit	Visually Checked	7:42:05 AM	02/18/2020
Pull Station	1st Kindergarten Wing Exit Corridor By Room 1	Visually Checked	7:42:37 AM	02/18/2020
Pull Station	1st Kitchen	Visually Checked	7:59:47 AM	02/18/2020
Pull Station	1st Outside Courtyard	Visually Checked	7:52:50 AM	02/18/2020
Pull Station	1st Room 38 Art, Music, Drama Storage 8	Visually Checked	8:20:07 AM	02/18/2020
Pull Station	1st Room 38 Art, Music, Drama	Visually Checked	7:54:45 AM	02/18/2020
Pull Station	1st Room 38 Art, Music, Drama	Visually Checked	7:55:59 AM	02/18/2020
Pull Station	1st Cafeteria	Visually Checked	7:57:18 AM	02/18/2020
Pull Station	1st Cafeteria	Visually Checked	7:57:36 AM	02/18/2020
Pull Station	1st Gym	Visually Checked	7:53:37 AM	02/18/2020
Smoke Detector	1st Main Office Corridor By Room S.S.3	Visually Checked	7:43:45 AM	02/18/2020
Smoke Detector	1st Main Office Kitchen Across Conference Room	Visually Checked	7:43:17 AM	02/18/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Main Office Conference Room	Visually Checked	7:43:23 AM	02/18/2020
Smoke Detector	1st Main Office Room S.S.1	Visually Checked	7:44:01 AM	02/18/2020
Smoke Detector	1st Main Office Room S.S.2	Visually Checked	7:43:54 AM	02/18/2020
Smoke Detector	1st Main Office Room S.S.3	Visually Checked	7:43:48 AM	02/18/2020
Smoke Detector	1st Main Office Room S.S.4	Visually Checked	7:43:38 AM	02/18/2020
Smoke Detector	1st Main Office Room S.S.5	Visually Checked	7:43:28 AM	02/18/2020
Smoke Detector	1st Closet By Storage 12	Visually Checked	7:58:21 AM	02/18/2020
Smoke Detector	1st Corridor By Reading Center	Visually Checked	8:17:57 AM	02/18/2020
Smoke Detector	1st Corridor By Reading Center	Visually Checked	8:18:09 AM	02/18/2020
Smoke Detector	1st Corridor Ramp By P.E. Office	Visually Checked	8:17:52 AM	02/18/2020
Smoke Detector	1st Corridor By Custodian 2	Visually Checked	7:49:04 AM	02/18/2020
Smoke Detector	1st Corridor By Room 13	Visually Checked	7:46:40 AM	02/18/2020
Smoke Detector	1st Corridor By Room 17	Visually Checked	7:46:55 AM	02/18/2020
Smoke Detector	1st Corridor By Room 9	Visually Checked	7:46:17 AM	02/18/2020
Smoke Detector	1st Corridor By Storage 3	Visually Checked	7:47:39 AM	02/18/2020
Smoke Detector	1st Corridor By Cafeteria	Visually Checked	8:20:11 AM	02/18/2020
Smoke Detector	1st Corridor By Cafeteria	Visually Checked	8:20:15 AM	02/18/2020
Smoke Detector	1st Corridor By Custodian 6	Visually Checked	7:56:20 AM	02/18/2020
Smoke Detector	1st Corridor By Custodian 7	Visually Checked	7:56:48 AM	02/18/2020
Smoke Detector	1st Corridor By Library Media Center Storage	Visually Checked	8:19:20 AM	02/18/2020
Smoke Detector	1st Corridor By P.E. Office	Visually Checked	7:52:33 AM	02/18/2020
Smoke Detector	1st Corridor By P.E. Office	Visually Checked	8:17:40 AM	02/18/2020
Smoke Detector	1st Corridor By Preparation Room	Visually Checked	7:56:38 AM	02/18/2020
Smoke Detector	1st Corridor By Professional Room	Visually Checked	8:19:44 AM	02/18/2020
Smoke Detector	1st Corridor By Pump Room	Visually Checked	8:21:22 AM	02/18/2020
Smoke Detector	1st Corridor By Pump Room	Visually Checked	8:21:33 AM	02/18/2020
Smoke Detector	1st Corridor By Room 31	Visually Checked	7:51:31 AM	02/18/2020
Smoke Detector	1st Corridor By Room 31	Visually Checked	7:52:16 AM	02/18/2020
Smoke Detector	1st Corridor By Room 35	Visually Checked	7:52:24 AM	02/18/2020
Smoke Detector	1st Corridor By Storage 12	Visually Checked	7:58:14 AM	02/18/2020
Smoke Detector	1st Corridor By Storage 13	Visually Checked	8:20:59 AM	02/18/2020
Smoke Detector	1st Corridor By Storage 5	Visually Checked	7:51:04 AM	02/18/2020
Smoke Detector	1st Corridor By Utility Room	Visually Checked	8:21:12 AM	02/18/2020
Smoke Detector	1st Corridor By Custodian 5	Visually Checked	7:50:30 AM	02/18/2020
Smoke Detector	1st Corridor By Custodian2	Visually Checked	7:44:43 AM	02/18/2020
Smoke Detector	1st Corridor By Custodian2	Visually Checked	7:45:00 AM	02/18/2020
Smoke Detector	1st Corridor By Main Office	Visually Checked	7:42:40 AM	02/18/2020
Smoke Detector	1st Corridor By Main Office	Visually Checked	7:44:09 AM	02/18/2020
Smoke Detector	1st Corridor By Room 23	Visually Checked	7:49:35 AM	02/18/2020
Smoke Detector	1st Corridor By Room 25	Visually Checked	7:50:17 AM	02/18/2020
Smoke Detector	1st Corridor By Room 28	Visually Checked	7:50:51 AM	02/18/2020
Smoke Detector	1st Corridor By Storage 2	Visually Checked	7:48:30 AM	02/18/2020
Smoke Detector	1st Corridor By Storage 2	Visually Checked	7:48:39 AM	02/18/2020
Smoke Detector	1st Corridor Ramp By Room 9	Visually Checked	7:46:06 AM	02/18/2020
Smoke Detector	1st Corridor The Red Pit	Visually Checked	7:49:53 AM	02/18/2020
Smoke Detector	1st Corridor The Red Pit	Visually Checked	7:50:05 AM	02/18/2020
Smoke Detector	1st Custodial 2	Visually Checked	8:17:14 AM	02/18/2020
Smoke Detector	1st Custodian 3	Visually Checked	7:49:08 AM	02/18/2020
Smoke Detector	1st Custodian 4	Visually Checked	7:50:22 AM	02/18/2020
Smoke Detector	1st Custodian 5	Visually Checked	8:17:18 AM	02/18/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Custodian Office	Visually Checked	8:00:37 AM	02/18/2020
Smoke Detector	1st Custodian Office	Visually Checked	8:00:43 AM	02/18/2020
Smoke Detector	1st Custodian Office	Visually Checked	8:00:47 AM	02/18/2020
Smoke Detector	1st Electrical Room In Custodian 5	Visually Checked	8:17:22 AM	02/18/2020
Smoke Detector	1st Kindergarten Wing Corridor	Visually Checked	7:40:28 AM	02/18/2020
Smoke Detector	1st Kindergarten Wing Corridor	Visually Checked	8:16:53 AM	02/18/2020
Smoke Detector	1st Kindergarten Wing Corridor By Room 1	Visually Checked	7:40:03 AM	02/18/2020
Smoke Detector	1st Kindergarten Wing Custodian 1 Closet	Visually Checked	7:40:12 AM	02/18/2020
Smoke Detector	1st Kindergarten Wing Exit	Visually Checked	7:41:58 AM	02/18/2020
Smoke Detector	1st Kindergarten Wing Storage Closet Across Custodian 1 Closet	Visually Checked	7:40:23 AM	02/18/2020
Smoke Detector	1st Kitchen Office	Visually Checked	8:21:41 AM	02/18/2020
Smoke Detector	1st Library Media Center Media Center Office	Visually Checked	8:19:35 AM	02/18/2020
Smoke Detector	1st Library Media Center Media Center Storage	Visually Checked	8:19:40 AM	02/18/2020
Smoke Detector	1st Library Media Center	Visually Checked	8:18:14 AM	02/18/2020
Smoke Detector	1st Library Media Center	Visually Checked	8:18:18 AM	02/18/2020
Smoke Detector	1st Library Media Center	Visually Checked	8:18:26 AM	02/18/2020
Smoke Detector	1st Library Media Center	Visually Checked	8:18:30 AM	02/18/2020
Smoke Detector	1st Library Media Center	Visually Checked	8:18:34 AM	02/18/2020
Smoke Detector	1st Library Media Center	Visually Checked	8:18:39 AM	02/18/2020
Smoke Detector	1st Main Electrical Room By Custodian Office	Visually Checked	8:16:35 AM	02/18/2020
Smoke Detector	1st Main Office	Visually Checked	7:42:49 AM	02/18/2020
Smoke Detector	1st Main Office Corridor By Conference Room	Visually Checked	7:43:14 AM	02/18/2020
Smoke Detector	1st Main Office Principal's Office	Visually Checked	7:43:02 AM	02/18/2020
Smoke Detector	1st Media Center By Custodial 2	Visually Checked	8:17:01 AM	02/18/2020
Smoke Detector	1st Media Center By Custodial 2	Visually Checked	8:17:06 AM	02/18/2020
Smoke Detector	1st Media Center By Custodial 2	Visually Checked	8:17:10 AM	02/18/2020
Smoke Detector	1st Office By Storage 2	Visually Checked	7:48:20 AM	02/18/2020
Smoke Detector	1st Room 38 Art, Music, Drama Storage	Visually Checked	7:54:01 AM	02/18/2020
Smoke Detector	1st Room 38 Art, Music, Drama Storage 10	Visually Checked	7:55:39 AM	02/18/2020
Smoke Detector	1st Room 38 Art, Music, Drama Storage 9	Visually Checked	7:54:57 AM	02/18/2020
Smoke Detector	1st Room 38 Art, Music, Drama	Visually Checked	7:56:02 AM	02/18/2020
Smoke Detector	1st Room 38 Art, Music, Drama	Visually Checked	7:56:05 AM	02/18/2020
Smoke Detector	1st Room 38 Art, Music, Drama	Visually Checked	7:56:07 AM	02/18/2020
Smoke Detector	1st Room 38 By Cafeteria	Visually Checked	8:02:02 AM	02/18/2020
Smoke Detector	1st Staff Lounge By Cafeteria	Visually Checked	8:01:40 AM	02/18/2020
Smoke Detector	1st Storage 4	Visually Checked	8:17:26 AM	02/18/2020
Smoke Detector	1st Womens Locker Room Behind Kitchen	Visually Checked	7:59:50 AM	02/18/2020
Smoke Detector	1st Womens Locker Room Toilet Behind Kitchen	Visually Checked	7:59:53 AM	02/18/2020
Smoke Detector	1st Cafeteria	Visually Checked	8:20:19 AM	02/18/2020
Smoke Detector	1st Cafeteria	Visually Checked	8:20:23 AM	02/18/2020
Smoke Detector	1st Cafeteria	Visually Checked	8:20:26 AM	02/18/2020
Smoke Detector	1st Cafeteria	Visually Checked	8:20:30 AM	02/18/2020
Smoke Detector	1st Cafeteria	Visually Checked	8:20:34 AM	02/18/2020
Smoke Detector	1st Cafeteria	Visually Checked	8:20:38 AM	02/18/2020
Smoke Detector	1st Cafeteria	Visually Checked	8:20:46 AM	02/18/2020
Smoke Detector	1st Cafeteria	Visually Checked	8:20:51 AM	02/18/2020
Smoke Detector	1st Custodian 6	Visually Checked	8:20:02 AM	02/18/2020
Smoke Detector	1st Custodian 8	Visually Checked	8:21:08 AM	02/18/2020
Smoke Detector	1st Gym Storage 6	Visually Checked	8:17:48 AM	02/18/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Library Media Center Computer Room	Visually Checked	8:19:27 AM	02/18/2020
Smoke Detector	1st Library Media Center Office	Visually Checked	8:16:39 AM	02/18/2020
Smoke Detector	1st Library Media Center Primary Room	Visually Checked	8:19:31 AM	02/18/2020
Smoke Detector	1st P.E. Office	Visually Checked	7:53:09 AM	02/18/2020
Smoke Detector	1st Preparation Room	Visually Checked	8:19:53 AM	02/18/2020
Smoke Detector	1st Preparation Room	Visually Checked	8:19:57 AM	02/18/2020
Smoke Detector	1st Pump Room	Visually Checked	8:00:19 AM	02/18/2020
Smoke Detector	1st Reading Center	Visually Checked	8:18:01 AM	02/18/2020
Smoke Detector	1st Reading Center	Visually Checked	8:18:05 AM	02/18/2020
Smoke Detector	1st Storage 12	Visually Checked	8:20:55 AM	02/18/2020
Smoke Detector	1st Storage 13	Visually Checked	8:21:04 AM	02/18/2020
Smoke Detector	1st Storage 14	Visually Checked	7:59:27 AM	02/18/2020
Smoke Detector	1st Storage 5	Visually Checked	8:21:46 AM	02/18/2020
Smoke Detector	1st Storage 7	Visually Checked	8:03:42 AM	02/18/2020
Smoke Detector	1st Utility Room	Visually Checked	8:21:16 AM	02/18/2020
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	1st Corridor By Main Office Below FACP	Tested	8:16:28 AM	02/18/2020

Service Summary

Generated by: BuildingReports.com






Building: Stamford BOE-Davenport Ridge School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	1
Total		1
<i>Passed</i>		
Annunciator	Tested	1
Battery	Tested	2
Control Panel	Tested	1
Duct Detector	Visually Checked	10
Heat Detector	Tested	1
Pull Station	Visually Checked	17
Smoke Detector	Visually Checked	116
Total		148
Grand Total		149

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Davenport Ridge School							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		 dB	 dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
Whole Facility				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Davenport Ridge School				Control Panel: 1 - Notifier			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	1st Corridor By Main Office FACP	7	12	12.47V	7.6ah		
Photoelectric	1st Pump Room	26A	12V	13.18V	23ah		
Failed/Other							
Battery							
Sealed Lead Acid	1st Corridor By Main Office Below FACP	55	12	13.44V	29Ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Davenport Ridge School				Control Panel: 1 - Notifier	
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		0.67%	1
Control Panel		Control		0.67%	1
Battery		Control		2.00%	3
Smoke Detector		Initiating		77.33%	116
Pull Station		Initiating		11.33%	17
Annunciator		Control		0.67%	1
Heat Detector		Initiating		0.67%	1
Duct Detector		Initiating		6.67%	10
Type	Qty	Model #	Description		Install Date
In Service - 2 Years to 3 Years					
Ultra Tech					
Battery	1	UT 1270	Sealed Lead Acid		12/08/2017
Universal					
Battery	1	UB12550	Sealed Lead Acid		12/08/2017
Power-Sonic					
Battery	1	PS12260	Photoelectric		10/31/2017
In Service - 5 Years to 10 Years					
Notifier					
Annunciator	1		LCD Display		02/25/2013
Control Panel	1				02/25/2013
Duct Detector	1	FSP-851			02/25/2013
Duct Detector	9	FSP-851	Photoelectric		02/25/2013
Heat Detector	1	FSP-851	Fixed Temperature		02/25/2013
Pull Station	1	FGB-10	Dual Action		02/25/2013
Pull Station	4	NBG-10	Dual Action		02/25/2013
Pull Station	12	NGB-10	Dual Action		02/25/2013
Smoke Detector	11	FSP-851	Photoelectric		02/25/2013
	6				

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Davenport Ridge School

Control Panel: 1 - Notifier

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
0001	Smoke Detector	1st Kindergarten Wing Corridor By Room 1	Photoelectric	21097659
0001	Pull Station	1st Kindergarten Wing Exit	Dual Action	21097652
0002	Smoke Detector	1st Kindergarten Wing Storage Closet Across Custodian 1 Closet	Photoelectric	21097658
0003	Smoke Detector	1st Kindergarten Wing Corridor	Photoelectric	21097656
0006	Smoke Detector	1st Kindergarten Wing Corridor	Photoelectric	21097654
0007	Smoke Detector	1st Kindergarten Wing Exit	Photoelectric	21097653
0008	Pull Station	1st Corridor By Custodian 2	Dual Action	21097676
0009	Pull Station	1st Corridor Exit By Storage 2	Dual Action	21097690
0009	Smoke Detector	1st Kindergarten Wing Custodian 1 Closet	Photoelectric	21097657
0010	Smoke Detector	1st Corridor By Main Office	Photoelectric	21097661
0010	Pull Station	1st Kindergarten Wing Exit Corridor By Room 1	Dual Action	21097660
0011	Pull Station	1st Corridor By Library Media Center Storage	Dual Action	21097738
0011	Smoke Detector	1st Corridor By Main Office	Photoelectric	21097673
0013	Smoke Detector	1st Corridor By Custodian2	Photoelectric	21097677
0015	Smoke Detector	1st Corridor By Storage 2	Photoelectric	21097691
0017	Smoke Detector	1st Corridor By Room 23	Photoelectric	21097697
0018	Smoke Detector	1st Main Office	Photoelectric	21097662
0019	Pull Station	1st Corridor Exit By Pump Room	Dual Action	21097793
0019	Smoke Detector	1st Main Office Principal's Office	Photoelectric	21097663
0020	Pull Station	1st Corridor By Cafeteria	Dual Action	21097765
0020	Smoke Detector	1st Main Office Conference Room	Photoelectric	21097666
0021	Smoke Detector	1st Main Office Corridor By Conference Room	Photoelectric	21097664
0022	Smoke Detector	1st Main Office Kitchen Across Conference Room	Photoelectric	21097665
0023	Pull Station	1st Outside Courtyard	Dual Action	09396228
0023	Smoke Detector	1st Main Office Room S.S.5	Photoelectric	21097667
0024	Smoke Detector	1st Main Office Room S.S.4	Photoelectric	21097668
0025	Smoke Detector	1st Main Office Room S.S.3	Photoelectric	21097669
0026	Smoke Detector	1st Main Office Room S.S.2	Photoelectric	21097670
0027	Smoke Detector	1st Main Office Corridor By Room S.S.3	Photoelectric	21097672
0028	Smoke Detector	1st Main Office Room S.S.1	Photoelectric	21097671
0029	Smoke Detector	1st Corridor By Custodian2	Photoelectric	21097675
0030	Smoke Detector	1st Media Center By Custodial 2	Photoelectric	21097680
0031	Pull Station	1st Cafeteria	Dual Action	21097778
0031	Smoke Detector	1st Media Center By Custodial 2	Photoelectric	21097679

0032	Pull Station	1st Cafeteria	Dual Action	21097769
0032	Smoke Detector	1st Media Center By Custodial 2	Photoelectric	21097678
0033	Smoke Detector	1st Corridor By Library Media Center Storage	Photoelectric	21097737
0033	Pull Station	1st Room 38 Art, Music, Drama	Dual Action	21097754
0034	Smoke Detector	1st Library Media Center	Photoelectric	21097736
0034	Pull Station	1st Room 38 Art, Music, Drama Storage 8	Dual Action	21097760
0035	Smoke Detector	1st Library Media Center	Photoelectric	21097735
0035	Pull Station	1st Room 38 Art, Music, Drama	Dual Action	21097759
0036	Pull Station	1st Gym	Dual Action	21097724
0036	Smoke Detector	1st Library Media Center	Photoelectric	21097733
0037	Smoke Detector	1st Library Media Center	Photoelectric	21097732
0038	Smoke Detector	1st Library Media Center	Photoelectric	21097731
0039	Smoke Detector	1st Library Media Center	Photoelectric	21097730
0040	Smoke Detector	1st Reading Center	Photoelectric	21097728
0041	Smoke Detector	1st Reading Center	Photoelectric	21097727
0041	Pull Station	1st Corridor By P.E. Office	Dual Action	21097721
0042	Smoke Detector	1st Library Media Center Computer Room	Photoelectric	21097739
0042	Pull Station	1st Corridor By Room 28	Dual Action	21097708
0043	Smoke Detector	1st Library Media Center Primary Room	Photoelectric	21097740
0044	Smoke Detector	1st Library Media Center Office	Photoelectric	09396225
0045	Smoke Detector	1st Library Media Center Media Center Storage	Photoelectric	21097742
0046	Smoke Detector	1st Custodial 2	Photoelectric	21097682
0047	Smoke Detector	1st Corridor Ramp By Room 9	Photoelectric	21097683
0049	Smoke Detector	1st Corridor By Room 9	Photoelectric	21097685
0050	Smoke Detector	1st Corridor By Room 13	Photoelectric	21097686
0051	Smoke Detector	1st Corridor By Room 17	Photoelectric	21097687
0052	Smoke Detector	1st Corridor By Storage 3	Photoelectric	21097688
0053	Smoke Detector	1st Corridor By Storage 2	Photoelectric	21097692
0054	Smoke Detector	1st Office By Storage 2	Photoelectric	21097693
0055	Smoke Detector	1st Custodian 3	Photoelectric	21097696
0056	Smoke Detector	1st Corridor By Custodian 2	Photoelectric	21097694
0058	Smoke Detector	1st Corridor The Red Pit	Photoelectric	21097701
0060	Smoke Detector	1st Corridor The Red Pit	Photoelectric	21097700
0062	Battery	1st Pump Room	Photoelectric	23585747
0062	Smoke Detector	1st Pump Room	Photoelectric	21097791
0063	Smoke Detector	1st Corridor By Pump Room	Photoelectric	21097792
0064	Smoke Detector	1st Main Electrical Room By Custodian Office	Photoelectric	04592573
0065	Smoke Detector	1st Custodian Office	Photoelectric	21097794
0066	Smoke Detector	1st Custodian Office	Photoelectric	21097795
0067	Smoke Detector	1st Corridor By Pump Room	Photoelectric	21097790
0068	Smoke Detector	1st Custodian Office	Photoelectric	21097796
0069	Smoke Detector	1st Womens Locker Room Toilet Behind Kitchen	Photoelectric	21097789
0070	Smoke Detector	1st Womens Locker Room Behind Kitchen	Photoelectric	21097788
0071	Smoke Detector	1st Corridor By Utility Room	Photoelectric	21097786
0072	Smoke Detector	1st Utility Room	Photoelectric	21097787
0073	Smoke Detector	1st Custodian 8	Photoelectric	21097784

0074	Smoke Detector	1st Storage 13	Photoelectric	21097783
0075	Smoke Detector	1st Corridor By Storage 13	Photoelectric	21097782
0076	Smoke Detector	1st Storage 14	Photoelectric	21097785
0077	Smoke Detector	1st Storage 12	Photoelectric	21097781
0078	Smoke Detector	1st Corridor By Storage 12	Photoelectric	21097779
0079	Smoke Detector	1st Closet By Storage 12	Photoelectric	21097780
0080	Smoke Detector	1st Staff Lounge By Cafeteria	Photoelectric	21097767
0081	Smoke Detector	1st Corridor By Cafeteria	Photoelectric	21097768
0082	Smoke Detector	1st Corridor By Cafeteria	Photoelectric	21097764
0083	Smoke Detector	1st Corridor By Custodian 7	Photoelectric	21097763
0084	Smoke Detector	1st Room 38 By Cafeteria	Photoelectric	21097766
0085	Smoke Detector	1st Preparation Room	Photoelectric	21097748
0086	Smoke Detector	1st Preparation Room	Photoelectric	21097749
0087	Smoke Detector	1st Corridor By Preparation Room	Photoelectric	21097762
0088	Smoke Detector	1st Corridor By Reading Center	Photoelectric	21097726
0089	Smoke Detector	1st Corridor By P.E. Office	Photoelectric	21097718
0090	Smoke Detector	1st Corridor By Room 25	Photoelectric	21097702
0091	Smoke Detector	1st Custodian 4	Photoelectric	21097703
0092	Smoke Detector	1st Corridor By Custodian 5	Photoelectric	21097706
0093	Smoke Detector	1st Custodian 5	Photoelectric	21097704
0094	Smoke Detector	1st Electrical Room In Custodian 5	Photoelectric	21097705
0095	Smoke Detector	1st Corridor By Storage 5	Photoelectric	21097710
0096	Smoke Detector	1st Kitchen Office	Photoelectric	21097800
0097	Smoke Detector	1st Cafeteria	Photoelectric	21097770
0098	Smoke Detector	1st Cafeteria	Photoelectric	21097771
0099	Smoke Detector	1st Cafeteria	Photoelectric	21097772
0102	Smoke Detector	1st Room 38 Art, Music, Drama	Photoelectric	21097758
0103	Smoke Detector	1st Cafeteria	Photoelectric	21097777
0104	Smoke Detector	1st Cafeteria	Photoelectric	21097775
0105	Smoke Detector	1st Cafeteria	Photoelectric	21097774
0106	Smoke Detector	1st Cafeteria	Photoelectric	21097773
0107	Smoke Detector	1st Cafeteria	Photoelectric	21097776
0109	Smoke Detector	1st Room 38 Art, Music, Drama Storage	Photoelectric	21097752
0110	Smoke Detector	1st Room 38 Art, Music, Drama	Photoelectric	21097756
0111	Smoke Detector	1st Room 38 Art, Music, Drama Storage 10	Photoelectric	21097753
0112	Smoke Detector	1st Room 38 Art, Music, Drama	Photoelectric	21097757
0114	Smoke Detector	1st Corridor By Custodian 6	Photoelectric	21097750
0116	Smoke Detector	1st Custodian 6	Photoelectric	21097751
0118	Smoke Detector	1st Corridor By Professional Room	Photoelectric	21097744
0119	Smoke Detector	1st Storage 7	Photoelectric	21097743
0120	Smoke Detector	1st Corridor By Reading Center	Photoelectric	21097729
0121	Smoke Detector	1st Gym Storage 6	Photoelectric	21097723
0122	Smoke Detector	1st Corridor Ramp By P.E. Office	Photoelectric	21097725
0124	Smoke Detector	1st P.E. Office	Photoelectric	21097722
0125	Smoke Detector	1st Corridor By P.E. Office	Photoelectric	21097720
0126	Smoke Detector	1st Corridor By Room 35	Photoelectric	21097717
0127	Smoke Detector	1st Corridor By Room 31	Photoelectric	21097716
0128	Smoke Detector	1st Corridor By Room 31	Photoelectric	21097712
0131	Smoke Detector	1st Storage 4	Photoelectric	21097709
0132	Smoke Detector	1st Corridor By Room 28	Photoelectric	21097707

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Hart School
61 Adams Road
Stamford, CT 06904

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Mar 27, 2020

Building: Stamford BOE-Hart School
Contact: Davor Lucaj
Title: Facilities Trades Manager



Company: TPC Associates, Inc.
Contact: Landon Gendreau
Title: Inspector

Executive Summary

Generated by: BuildingReports.com





Building Information		
Building: Stamford BOE-Hart School	Contact: Davor Lucaj	
Address: 61 Adams Road	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06904	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Landon Gendreau	
Address: 261 Pepe's Farm Road	Phone: 2038781321	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: landon.gendreau@tpcsystems.com	
System Control Unit		
Manufacturer: EST	Inspection Date: 03/26/2020	IDC Style:
Model Number: EST-3	Install Date: 08/08/2014	SLC Style:
Software Version:	Version Date: 01/16/2014	NAC Style:
Location: Ground Telephone Room 051	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.40%	0	0%	0	0%	0	0%
Control	3	1.20%	3	100.00%	2	66.67%	1	33.33%
Initiating	246	98.40%	246	100.00%	246	100.00%	0	0%
Totals	250	100%	249	99.60%	248	99.60%	1	0.40%

Certification	
<p>Company: TPC Associates, Inc.</p> <p>Inspector: Landon Gendreau</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px 0;">  </div> <p>Signed: Mar 26, 2020 1:58:14 PM</p>	<p>Building: Stamford BOE-Hart School</p> <p>Contact: Davor Lucaj</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px 0;">  </div> <p>Signed: Mar 26, 2020 1:58:55 PM</p>

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-Hart School			Control Panel: 1 - EST EST-3	
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
 ScanID	 Location	 Problem	Address	 Reference
<i>Control</i>				
Battery				
04061205	Ground Battery Cab 4	Special Note	1-1 0000	NFPA 72 10.2.1.2

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-Hart School			Control Panel: 1 - EST EST-3		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
Control					
Battery					
04061205	Ground Battery Cab 4	Replace	UB12500	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

Notes & Recommendations

Generated by: BuildingReports.com

Building: Stamford BOE-Hart School			Control Panel: 1 - EST		EST-3
<i>The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.</i>					
ScanID	Note	Device Type	Location		Comment
Control					
04061205	1	Battery	Ground Battery Cab 4		Special Note
Replace with matching sets of 12v 45 ah batteries					

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Hart School		Control Panel: 1 - EST EST-3		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Battery	Ground Battery Cab 3	Tested	12:27:06 PM	03/26/2020
Control Panel	Ground Telephone Room 051	Tested	12:23:00 PM	03/26/2020
Initiating				
Duct Detector	1st Auditorium Center EF15	Visually Checked	1:32:18 PM	03/26/2020
Duct Detector	1st Auditorium Front Center AC3 Supply	Visually Checked	1:32:13 PM	03/26/2020
Duct Detector	1st Auditorium Front Right Stage AC3 Supply	Visually Checked	1:32:08 PM	03/26/2020
Duct Detector	1st Auditorium Front Right Stage Thru Right Brass Grate AC3 Return	Visually Checked	1:32:29 PM	03/26/2020
Duct Detector	1st Cafe/Gym Corridor AC6 Return	Visually Checked	1:39:22 PM	03/26/2020
Duct Detector	1st Cafe/Gym Corridor AC6 Supply	Visually Checked	1:37:52 PM	03/26/2020
Duct Detector	1st Gym AC4 Return	Visually Checked	1:37:32 PM	03/26/2020
Duct Detector	1st Gym AC4 Supply	Visually Checked	1:37:25 PM	03/26/2020
Duct Detector	1st Gym AC5 Return	Visually Checked	1:36:42 PM	03/26/2020
Duct Detector	1st Gym AC5 Supply	Visually Checked	1:37:21 PM	03/26/2020
Duct Detector	1st Gym EF12	Visually Checked	1:37:44 PM	03/26/2020
Duct Detector	1st Gym EF13	Visually Checked	1:37:40 PM	03/26/2020
Duct Detector	1st Kitchen EF11	Visually Checked	1:36:51 PM	03/26/2020
Duct Detector	1st Kitchen Make Up Air Unit	Visually Checked	1:36:33 PM	03/26/2020
Duct Detector	1st Stage Corridor By Room 171 EX14	Visually Checked	1:45:22 PM	03/26/2020
Duct Detector	1st Stage EX16	Visually Checked	1:38:32 PM	03/26/2020
Duct Detector	2nd – Corridor By Room 214 AC1 Return (6'–10'–12' Ladder)	Visually Checked	12:07:08 PM	03/26/2020
Duct Detector	2nd – Corridor By Room 214 AC2 Return (8'–10'–12' Ladder)	Visually Checked	12:07:01 PM	03/26/2020
Duct Detector	2nd – Corridor By Room 214 AC2 Supply (8'–10'–12' Ladder)	Visually Checked	12:07:04 PM	03/26/2020
Duct Detector	2nd – Corridor By Stair 1 EF1 (6'–10'–12' Ladder)	Visually Checked	12:07:19 PM	03/26/2020
Duct Detector	2nd – Corridor By Stair 1 EF6 (6'–10'–12' Ladder)	Visually Checked	12:07:15 PM	03/26/2020
Duct Detector	2nd – Corridor By Stair 2 AC1 Supply (6'–10'–12' Ladder)	Visually Checked	12:07:11 PM	03/26/2020
Duct Detector	2nd – Corridor By Stair 2 EF7 (6'–10'–12' Ladder)	Visually Checked	12:07:22 PM	03/26/2020
Duct Detector	2nd – Room 216 EF2 (6'–10'–12' Ladder)	Visually Checked	12:07:26 PM	03/26/2020
Duct Detector	2nd – Room 232 EF10 (6'–10'–12' Ladder)	Visually Checked	12:07:50 PM	03/26/2020
Duct Detector	2nd – Room 232 EF8 (6'–10'–12' Ladder)	Visually Checked	12:07:43 PM	03/26/2020
Duct Detector	2nd – Room 232 EF9 (6'–10'–12' Ladder)	Visually Checked	12:07:46 PM	03/26/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Duct Detector	2nd Above Ceiling By Elevator on Top of Unit EF3	Visually Checked	12:06:48 PM	03/26/2020
Duct Detector	2nd Above Ceiling By Elevator on Top of Unit EF4	Visually Checked	12:06:51 PM	03/26/2020
Duct Detector	2nd Boyroom EF5 (10'-12' Ladder)	Visually Checked	12:06:58 PM	03/26/2020
Heat Detector	1st Kitchen	Visually Checked	1:35:25 PM	03/26/2020
Heat Detector	1st Kitchen	Visually Checked	1:35:38 PM	03/26/2020
Heat Detector	1st Room 147 Kiln	Visually Checked	1:04:09 PM	03/26/2020
Heat Detector	Ground Boiler Room 027	Visually Checked	1:19:04 PM	03/26/2020
Initiating Device	1st Auditorium Center EF15	Visually Checked	1:31:58 PM	03/26/2020
Initiating Device	1st Auditorium Center EF16	Visually Checked	1:36:23 PM	03/26/2020
Initiating Device	1st Auditorium Front Center AC3 Supply	Visually Checked	1:31:48 PM	03/26/2020
Initiating Device	1st Auditorium Front Right Stage AC3 Return	Visually Checked	1:32:02 PM	03/26/2020
Initiating Device	1st Auditorium Front Right Stage AC3 Supply	Visually Checked	1:31:52 PM	03/26/2020
Initiating Device	1st Cafe/Gym Corridor AC4 Return	Visually Checked	1:41:50 PM	03/26/2020
Initiating Device	1st Cafe/Gym Corridor AC4 Supply	Visually Checked	1:42:06 PM	03/26/2020
Initiating Device	1st Cafe/Gym Corridor AC5 Return	Visually Checked	1:41:24 PM	03/26/2020
Initiating Device	1st Cafe/Gym Corridor AC5 Supply	Visually Checked	1:42:19 PM	03/26/2020
Initiating Device	1st Cafe/Gym Corridor AC6 Return	Visually Checked	1:44:36 PM	03/26/2020
Initiating Device	1st Cafe/Gym Corridor AC6 Supply	Tested	1:34:08 PM	03/26/2020
Initiating Device	1st Cafe/Gym Corridor EF12	Visually Checked	1:41:10 PM	03/26/2020
Initiating Device	1st Cafe/Gym Corridor EF13	Visually Checked	1:40:50 PM	03/26/2020
Initiating Device	1st Kitchen EF11	Visually Checked	1:36:27 PM	03/26/2020
Initiating Device	1st Kitchen Make Up Air Unit	Visually Checked	1:36:36 PM	03/26/2020
Initiating Device	1st Stage Corridor By Room 171 EX14	Visually Checked	1:44:57 PM	03/26/2020
Initiating Device	2nd – Corridor By Room 214 AC1 Return (6'-10'-12' Ladder)	Visually Checked	12:05:22 PM	03/26/2020
Initiating Device	2nd – Corridor By Room 214 AC2 Supply (8'-10'-12' Ladder)	Visually Checked	12:05:26 PM	03/26/2020
Initiating Device	2nd – Corridor By Stair 1 EF6 (6'-10'-12' Ladder)	Visually Checked	12:05:12 PM	03/26/2020
Initiating Device	2nd – Corridor By Stair 2 AC1 Supply (6'-10'-12' Ladder)	Visually Checked	12:05:19 PM	03/26/2020
Initiating Device	2nd – Corridor By Stair 2 EF7 (6'-10'-12' Ladder)	Visually Checked	12:05:15 PM	03/26/2020
Initiating Device	2nd – Room 216 EF2 (6'-10'-12' Ladder)	Visually Checked	12:05:32 PM	03/26/2020
Initiating Device	2nd – Room 232 EF10 (6'-10'-12' Ladder)	Visually Checked	12:07:39 PM	03/26/2020
Initiating Device	2nd – Room 232 EF8 (6'-10'-12' Ladder)	Visually Checked	12:07:32 PM	03/26/2020
Initiating Device	2nd – Room 232 EF9 (6'-10'-12' Ladder)	Visually Checked	12:07:35 PM	03/26/2020
Initiating Device	2nd Above Ceiling By Elevator on Top of Unit EF3	Visually Checked	12:05:39 PM	03/26/2020
Initiating Device	2nd Above Ceiling By Elevator on Top of Unit EF4	Visually Checked	12:05:36 PM	03/26/2020
Initiating Device	2nd Boyroom EF5	Visually Checked	12:06:54 PM	03/26/2020
Initiating Device	2nd Corridor By Room 214 AC2 Return (8'-10'-12' Ladder)	Visually Checked	12:05:29 PM	03/26/2020
Initiating Device	2nd Corridor By Stair 1 EF1 (6'-10'-12' Ladder)	Visually Checked	12:05:08 PM	03/26/2020
Pull Station	1st Auditorium Stage	Visually Checked	1:38:49 PM	03/26/2020
Pull Station	1st By Stair 1	Visually Checked	12:41:30 PM	03/26/2020
Pull Station	1st Cafe/Gym Entrance	Visually Checked	1:43:48 PM	03/26/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	1st Gym	Visually Checked	1:34:46 PM	03/26/2020
Pull Station	1st Kitchen Exit	Visually Checked	1:36:13 PM	03/26/2020
Pull Station	1st Main Entrance By Office	Visually Checked	12:46:43 PM	03/26/2020
Pull Station	1st Stage Corridor Exit	Visually Checked	1:33:04 PM	03/26/2020
Pull Station	1st Stair 4	Visually Checked	1:08:54 PM	03/26/2020
Pull Station	1st Stair 2	Visually Checked	12:50:52 PM	03/26/2020
Pull Station	2nd By Stair 3	Visually Checked	12:04:09 PM	03/26/2020
Pull Station	2nd Stair 4	Visually Checked	12:00:50 PM	03/26/2020
Pull Station	2nd Stair 1	Visually Checked	12:05:01 PM	03/26/2020
Pull Station	2nd Stair 2	Visually Checked	12:04:45 PM	03/26/2020
Pull Station	Ground By Stair 2	Visually Checked	1:24:18 PM	03/26/2020
Pull Station	Ground Room 012	Visually Checked	1:29:20 PM	03/26/2020
Pull Station	Ground Room 014	Visually Checked	1:30:18 PM	03/26/2020
Pull Station	Ground Room 037	Visually Checked	1:29:44 PM	03/26/2020
Pull Station	Ground Room 29	Visually Checked	1:30:09 PM	03/26/2020
Pull Station	Ground Stair 2 Exit	Visually Checked	1:24:56 PM	03/26/2020
Pull Station	Ground Stair 3	Visually Checked	1:21:08 PM	03/26/2020
Pull Station	Ground Stair 3 Exit	Visually Checked	1:20:29 PM	03/26/2020
Pull Station	Ground Stair 4 By Room 029	Visually Checked	1:17:39 PM	03/26/2020
Pull Station	Ground Stair 4 Exit	Visually Checked	1:12:50 PM	03/26/2020
Pull Station	Ground Room 007	Visually Checked	1:30:22 PM	03/26/2020
Pull Station	Ground Room 009	Visually Checked	1:24:12 PM	03/26/2020
Pull Station	Ground Stair 1	Visually Checked	1:24:02 PM	03/26/2020
Pull Station	Ground Stair 1 Exit	Visually Checked	1:24:06 PM	03/26/2020
Smoke Detector	1st By Elevator Lobby – Cafe/Gym	Tested/Cleaned	1:38:22 PM	03/26/2020
Smoke Detector	1st By Stair 3 Landing to Cafe/Gym	Tested/Cleaned	1:39:02 PM	03/26/2020
Smoke Detector	1st Auditorium Front Left	Visually Checked	1:31:38 PM	03/26/2020
Smoke Detector	1st Auditorium Front Right	Visually Checked	1:31:34 PM	03/26/2020
Smoke Detector	1st Auditorium Rear Left	Visually Checked	1:31:30 PM	03/26/2020
Smoke Detector	1st Auditorium Rear Right	Visually Checked	1:31:42 PM	03/26/2020
Smoke Detector	1st By Restroom	Visually Checked	1:45:51 PM	03/26/2020
Smoke Detector	1st By Room 126	Visually Checked	12:53:07 PM	03/26/2020
Smoke Detector	1st By Room 138	Visually Checked	1:46:13 PM	03/26/2020
Smoke Detector	1st By Room 139	Visually Checked	1:46:24 PM	03/26/2020
Smoke Detector	1st By Room 144	Visually Checked	1:06:13 PM	03/26/2020
Smoke Detector	1st By Room 148	Visually Checked	1:02:12 PM	03/26/2020
Smoke Detector	1st By Room 151	Visually Checked	1:45:56 PM	03/26/2020
Smoke Detector	1st By Stair 1	Visually Checked	1:44:03 PM	03/26/2020
Smoke Detector	1st By Stair 2	Visually Checked	12:45:50 PM	03/26/2020
Smoke Detector	1st By Stair 3	Visually Checked	1:42:39 PM	03/26/2020
Smoke Detector	1st By Boys Room 162	Tested/Cleaned	1:40:09 PM	03/26/2020
Smoke Detector	1st Cafe/Gym Corridor Near Gym Storage 157	Tested/Cleaned	1:33:50 PM	03/26/2020
Smoke Detector	1st Cafe/Gym Corridor Near Gym Storage 157	Visually Checked	1:42:33 PM	03/26/2020
Smoke Detector	1st Cafe/Gym Entrance	Visually Checked	1:43:53 PM	03/26/2020
Smoke Detector	1st Cafe/Gym Smk 1	Visually Checked	1:35:46 PM	03/26/2020
Smoke Detector	1st Cafe/Gym Smk 2	Visually Checked	1:37:36 PM	03/26/2020
Smoke Detector	1st Cafe/Gym Smk 3	Visually Checked	1:35:51 PM	03/26/2020
Smoke Detector	1st Cafe/Gym Smk 4	Visually Checked	1:36:07 PM	03/26/2020
Smoke Detector	1st Cafe/Gym Smk 5	Visually Checked	1:35:57 PM	03/26/2020
Smoke Detector	1st Cafe/Gym Smk 6	Visually Checked	1:36:01 PM	03/26/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Cafe/Gym Storage 170	Visually Checked	1:43:43 PM	03/26/2020
Smoke Detector	1st Corridor Room 144	Visually Checked	1:10:59 PM	03/26/2020
Smoke Detector	1st Corridor By Gym Office 159	Tested/Cleaned	1:39:50 PM	03/26/2020
Smoke Detector	1st Data 177 in Room 120	Visually Checked	12:51:33 PM	03/26/2020
Smoke Detector	1st Electrical Room 154 in Room 110	Visually Checked	12:44:13 PM	03/26/2020
Smoke Detector	1st Kitchen Office	Visually Checked	1:35:31 PM	03/26/2020
Smoke Detector	1st Kitchen Storage	Visually Checked	1:36:47 PM	03/26/2020
Smoke Detector	1st Main Entrance	Visually Checked	12:47:13 PM	03/26/2020
Smoke Detector	1st Main Entrance By Office	Tested/Cleaned	12:46:24 PM	03/26/2020
Smoke Detector	1st Main Office 116	Visually Checked	12:47:44 PM	03/26/2020
Smoke Detector	1st Main Office 116	Visually Checked	12:48:07 PM	03/26/2020
Smoke Detector	1st Main Office 116/ Kitchen 118	Visually Checked	1:44:13 PM	03/26/2020
Smoke Detector	1st Room 110	Visually Checked	12:45:02 PM	03/26/2020
Smoke Detector	1st Room 112 Assistant Principal	Visually Checked	1:36:17 PM	03/26/2020
Smoke Detector	1st Room 140	Visually Checked	1:10:11 PM	03/26/2020
Smoke Detector	1st Room 148	Visually Checked	1:46:02 PM	03/26/2020
Smoke Detector	1st Room 150 Left Storage	Visually Checked	1:46:31 PM	03/26/2020
Smoke Detector	1st Room 150 Right Storage	Visually Checked	1:37:04 PM	03/26/2020
Smoke Detector	1st Room 150	Visually Checked	1:12:22 PM	03/26/2020
Smoke Detector	1st Stage Corridor By Room 171	Visually Checked	1:33:38 PM	03/26/2020
Smoke Detector	1st Stage Corridor Exit	Visually Checked	1:32:56 PM	03/26/2020
Smoke Detector	1st Stage Left	Visually Checked	1:38:40 PM	03/26/2020
Smoke Detector	1st Stage Right	Visually Checked	1:38:36 PM	03/26/2020
Smoke Detector	1st Stair 4	Visually Checked	1:09:09 PM	03/26/2020
Smoke Detector	1st Storage 176 in Room 110	Visually Checked	12:44:40 PM	03/26/2020
Smoke Detector	1st Custodian 133	Visually Checked	1:37:14 PM	03/26/2020
Smoke Detector	1st Custodian 161	Visually Checked	1:42:55 PM	03/26/2020
Smoke Detector	1st Electrical 134	Visually Checked	1:37:10 PM	03/26/2020
Smoke Detector	1st Gym Office 159	Visually Checked	1:42:50 PM	03/26/2020
Smoke Detector	1st Gym Storage 157	Visually Checked	1:42:45 PM	03/26/2020
Smoke Detector	1st Room 111	Visually Checked	12:45:34 PM	03/26/2020
Smoke Detector	1st Room 119 Principal	Visually Checked	12:48:46 PM	03/26/2020
Smoke Detector	1st Room 120 Storage	Visually Checked	12:52:02 PM	03/26/2020
Smoke Detector	1st Room 120	Visually Checked	12:52:27 PM	03/26/2020
Smoke Detector	1st Room 121	Visually Checked	12:53:33 PM	03/26/2020
Smoke Detector	1st Room 122	Visually Checked	12:54:18 PM	03/26/2020
Smoke Detector	1st Room 123	Visually Checked	12:54:34 PM	03/26/2020
Smoke Detector	1st Room 124	Visually Checked	12:54:56 PM	03/26/2020
Smoke Detector	1st Room 125	Visually Checked	12:53:57 PM	03/26/2020
Smoke Detector	1st Room 126A	Visually Checked	12:49:32 PM	03/26/2020
Smoke Detector	1st Room 126B	Visually Checked	12:49:11 PM	03/26/2020
Smoke Detector	1st Room 128	Visually Checked	12:56:25 PM	03/26/2020
Smoke Detector	1st Room 129 Nurse	Visually Checked	12:56:58 PM	03/26/2020
Smoke Detector	1st Room 130 Nurse Cot Room	Visually Checked	12:58:13 PM	03/26/2020
Smoke Detector	1st Room 142 Smoke A	Visually Checked	1:07:21 PM	03/26/2020
Smoke Detector	1st Room 142 Smoke B	Visually Checked	1:07:03 PM	03/26/2020
Smoke Detector	1st Room 143	Visually Checked	1:46:07 PM	03/26/2020
Smoke Detector	1st Room 144	Visually Checked	1:11:33 PM	03/26/2020
Smoke Detector	1st Room 146 Smoke A	Visually Checked	1:03:11 PM	03/26/2020
Smoke Detector	1st Room 146 Smoke B	Visually Checked	1:02:46 PM	03/26/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Room 147	Visually Checked	1:04:46 PM	03/26/2020
Smoke Detector	1st Room 166	Visually Checked	1:03:44 PM	03/26/2020
Smoke Detector	1st Room 171 Teachers Room	Visually Checked	1:43:33 PM	03/26/2020
Smoke Detector	1st Room 172 By Stage	Visually Checked	1:43:38 PM	03/26/2020
Smoke Detector	1st Room 178 Nurse Exam	Visually Checked	12:57:24 PM	03/26/2020
Smoke Detector	1st Stair 1	Visually Checked	1:44:08 PM	03/26/2020
Smoke Detector	1st Stair 2	Visually Checked	12:46:10 PM	03/26/2020
Smoke Detector	1st Stair 3	Visually Checked	1:05:28 PM	03/26/2020
Smoke Detector	2nd By Restroom	Visually Checked	12:04:33 PM	03/26/2020
Smoke Detector	2nd By Stair 3	Visually Checked	12:04:05 PM	03/26/2020
Smoke Detector	2nd By Stair 4	Visually Checked	12:00:59 PM	03/26/2020
Smoke Detector	2nd Corridor By Room 228	Visually Checked	12:01:12 PM	03/26/2020
Smoke Detector	2nd Corridor By Stair 1	Visually Checked	12:04:57 PM	03/26/2020
Smoke Detector	2nd Corridor By Stair 2	Visually Checked	12:04:41 PM	03/26/2020
Smoke Detector	2nd Corridor By Room 214	Visually Checked	12:04:37 PM	03/26/2020
Smoke Detector	2nd Custodian 220	Visually Checked	12:06:37 PM	03/26/2020
Smoke Detector	2nd Ed Storage 235	Visually Checked	12:04:20 PM	03/26/2020
Smoke Detector	2nd Electrical Room 219	Visually Checked	12:06:34 PM	03/26/2020
Smoke Detector	2nd PTO Room 210	Visually Checked	12:06:22 PM	03/26/2020
Smoke Detector	2nd Room 207	Visually Checked	12:04:52 PM	03/26/2020
Smoke Detector	2nd Room 211	Visually Checked	12:06:26 PM	03/26/2020
Smoke Detector	2nd Room 239 Cross Thru to Room 238	Visually Checked	12:04:01 PM	03/26/2020
Smoke Detector	2nd Room 239	Visually Checked	12:06:44 PM	03/26/2020
Smoke Detector	2nd Room 240	Visually Checked	12:03:34 PM	03/26/2020
Smoke Detector	2nd Stair 3	Visually Checked	12:04:15 PM	03/26/2020
Smoke Detector	2nd Stair 4	Visually Checked	12:00:43 PM	03/26/2020
Smoke Detector	2nd Stair 4	Visually Checked	12:05:05 PM	03/26/2020
Smoke Detector	2nd Data Closet in Room 211	Visually Checked	12:06:30 PM	03/26/2020
Smoke Detector	2nd Electrical Closet in Room 207	Visually Checked	12:05:50 PM	03/26/2020
Smoke Detector	2nd Room 226	Visually Checked	12:06:41 PM	03/26/2020
Smoke Detector	2nd Room 228	Visually Checked	12:04:25 PM	03/26/2020
Smoke Detector	2nd Stair 2	Visually Checked	12:04:49 PM	03/26/2020
Smoke Detector	Ground By Custodian Storage 036	Visually Checked	1:23:13 PM	03/26/2020
Smoke Detector	Ground By Electrical Room	Visually Checked	1:29:37 PM	03/26/2020
Smoke Detector	Ground By Restroom	Visually Checked	1:29:28 PM	03/26/2020
Smoke Detector	Ground By Stair 4	Visually Checked	1:29:57 PM	03/26/2020
Smoke Detector	Ground By Stair 1	Visually Checked	1:24:51 PM	03/26/2020
Smoke Detector	Ground By Room 012	Visually Checked	1:29:08 PM	03/26/2020
Smoke Detector	Ground By Stair 2	Visually Checked	1:25:00 PM	03/26/2020
Smoke Detector	Ground Corridor By Data Room 020	Visually Checked	12:38:03 PM	03/26/2020
Smoke Detector	Ground Corridor to Water Service 039	Visually Checked	1:30:38 PM	03/26/2020
Smoke Detector	Ground Custodian Office 035	Visually Checked	1:21:37 PM	03/26/2020
Smoke Detector	Ground Custodian Storage 036	Visually Checked	1:22:48 PM	03/26/2020
Smoke Detector	Ground Data Room 020	Visually Checked	12:37:26 PM	03/26/2020
Smoke Detector	Ground ED Storage Rm 26	Visually Checked	12:35:34 PM	03/26/2020
Smoke Detector	Ground Elevator Lobby	Visually Checked	1:29:53 PM	03/26/2020
Smoke Detector	Ground Room 007 Storage	Visually Checked	1:30:26 PM	03/26/2020
Smoke Detector	Ground Room 012 Storage	Visually Checked	1:29:24 PM	03/26/2020
Smoke Detector	Ground Room 014	Visually Checked	1:30:13 PM	03/26/2020
Smoke Detector	Ground Room 025	Visually Checked	1:14:30 PM	03/26/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Ground Room 029	Visually Checked	1:30:04 PM	03/26/2020
Smoke Detector	Ground Room 037 Storage	Visually Checked	1:29:49 PM	03/26/2020
Smoke Detector	Ground Room 040	Visually Checked	1:15:45 PM	03/26/2020
Smoke Detector	Ground Room 040	Visually Checked	1:16:09 PM	03/26/2020
Smoke Detector	Ground Room 17	Visually Checked	1:29:40 PM	03/26/2020
Smoke Detector	Ground Stair 2	Visually Checked	1:25:10 PM	03/26/2020
Smoke Detector	Ground Stair 2 Exit	Visually Checked	1:25:06 PM	03/26/2020
Smoke Detector	Ground Stair 3	Visually Checked	1:20:08 PM	03/26/2020
Smoke Detector	Ground Stair 3 Exit	Visually Checked	1:20:45 PM	03/26/2020
Smoke Detector	Ground Stair 3 Landing to Cafe/Gym	Visually Checked	1:30:00 PM	03/26/2020
Smoke Detector	Ground Stair 4	Visually Checked	1:13:44 PM	03/26/2020
Smoke Detector	Ground Telephone Rm 51	Visually Checked	12:32:34 PM	03/26/2020
Smoke Detector	Ground Water Service 039	Visually Checked	1:30:34 PM	03/26/2020
Smoke Detector	Ground Computer Room 016	Visually Checked	1:26:09 PM	03/26/2020
Smoke Detector	Ground Computer Room 016	Visually Checked	1:26:15 PM	03/26/2020
Smoke Detector	Ground Electrical Room 021	Visually Checked	12:36:54 PM	03/26/2020
Smoke Detector	Ground Media Room 004 Smk 1	Visually Checked	1:25:42 PM	03/26/2020
Smoke Detector	Ground Media Room 004 Smk 3	Visually Checked	1:26:33 PM	03/26/2020
Smoke Detector	Ground Media Room 004 Smk 4	Visually Checked	1:25:48 PM	03/26/2020
Smoke Detector	Ground Media Room 004 Smk 4	Visually Checked	1:26:37 PM	03/26/2020
Smoke Detector	Ground Media Room 004 Smk 5	Visually Checked	1:26:21 PM	03/26/2020
Smoke Detector	Ground Media Room 004 Left Storage	Visually Checked	1:27:55 PM	03/26/2020
Smoke Detector	Ground Media Room 004 Right Storage	Visually Checked	1:28:01 PM	03/26/2020
Smoke Detector	Ground Media Room 004/Office 005	Visually Checked	1:26:28 PM	03/26/2020
Smoke Detector	Ground Media Room 004/Workroom 006	Visually Checked	1:27:48 PM	03/26/2020
Smoke Detector	Ground Room 002 Multipurpose	Visually Checked	1:29:12 PM	03/26/2020
Smoke Detector	Ground Room 009 Storage	Visually Checked	1:30:30 PM	03/26/2020
Smoke Detector	Ground Room 127 Teachers Work Room	Visually Checked	12:55:59 PM	03/26/2020
Smoke Detector	Ground Stair 1	Visually Checked	1:24:32 PM	03/26/2020
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	Ground Battery Cab 4	Tested	9:38:00 AM	03/27/2020

Service Summary

Generated by: BuildingReports.com




Building: Stamford BOE-Hart School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	1
Total		1
<i>Passed</i>		
Battery	Tested	1
Control Panel	Tested	1
Duct Detector	Visually Checked	30
Heat Detector	Visually Checked	4
Initiating Device	Tested	1
Initiating Device	Visually Checked	29
Pull Station	Visually Checked	27
Smoke Detector	Tested/Cleaned	6
Smoke Detector	Visually Checked	149
Total		248
Grand Total		249

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Hart School							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		◀ dB	◀ dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
WHOLE FACILITY				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Hart School				Control Panel: 1 - EST EST-3			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	Ground Battery Cab 3	40Ah	12V	13.29V	65ah		
Failed/Other							
Battery							
Sealed Lead Acid	Ground Battery Cab 4	50AH	12V	13.29V	30ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Hart School				Control Panel: 1 - EST EST-3	
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		0.40%	1
Smoke Detector		Initiating		62.00%	155
Pull Station		Initiating		10.80%	27
Initiating Device		Initiating		12.00%	30
Duct Detector		Initiating		12.00%	30
Control Panel		Control		0.40%	1
Battery		Control		0.80%	2
Heat Detector		Initiating		1.60%	4
Type	Qty	Model #	Description		Install Date
In Service - 1 Year to 2 Years					
Universal					
Battery	1	UB12500	Sealed Lead Acid		02/01/2019
In Service - 2 Years to 3 Years					
Universal					
Battery	1	UB12500	Sealed Lead Acid		02/01/2018
In Service - 5 Years to 10 Years					
EST					
Control Panel	1	EST-3			08/08/2014
Duct Detector	1	SIGA-PS			07/30/2012
Duct Detector	29	SIGA-PS	Photoelectric	07/30/2012	
Heat Detector	2	283B	Fixed Temperature	07/30/2012	
Heat Detector	2	SIGA-HFS	Fixed Temperature	07/30/2012	
Initiating Device	30	SIGA-DTS	Supporting Field Device	07/30/2012	
Pull Station	1	SIGA-270	Dual Action	07/30/2012	
Pull Station	26	SIGA-278	Dual Action	07/30/2012	
Smoke Detector	1	SIGA-278	Photoelectric	07/30/2012	
Smoke Detector	1	SIGA-PD	Photoelectric	07/30/2012	
Smoke Detector	15	SIGA-PS	Photoelectric	07/30/2012	
	3				

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Hart School			Control Panel: 1 - EST EST-3	
<i>The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.</i>				
Address	Device Type	Location	Type	ScanID
Zone/Circuit: 1				
0000	Battery	Ground Battery Cab 3	Sealed Lead Acid	04061203
0000	Battery	Ground Battery Cab 4	Sealed Lead Acid	04061205
Zone/Circuit: 04				
0001	Smoke Detector	2nd Stair 4	Photoelectric	04061123
0002	Smoke Detector	2nd Room 240	Photoelectric	04061124
0003	Smoke Detector	2nd Room 239 Cross Thru to Room 238	Photoelectric	04061125
0005	Smoke Detector	2nd By Stair 4	Photoelectric	04061127
0006	Duct Detector	2nd Above Ceiling By Elevator on Top of Unit EF3	Photoelectric	20666967
0007	Smoke Detector	2nd Room 226	Photoelectric	04061276
0008	Smoke Detector	2nd Room 228	Photoelectric	04061133
0009	Duct Detector	2nd – Room 232 EF8 (6'-10'-12' Ladder)	Photoelectric	20666982
0010	Duct Detector	2nd – Corridor By Stair 2 AC1 Supply (6'-10'-12' Ladder)	Photoelectric	20666974
0011	Duct Detector	2nd Boyroom EF5 (10'-12' Ladder)	Photoelectric	20666970
0012	Duct Detector	2nd – Room 232 EF10 (6'-10'-12' Ladder)	Photoelectric	20666984
0013	Smoke Detector	2nd Electrical Closet in Room 207	Photoelectric	04061270
0014	Duct Detector	2nd – Room 216 EF2 (6'-10'-12' Ladder)	Photoelectric	20666978
0015	Duct Detector	2nd – Corridor By Room 214 AC2 Return (8'-10'-12' Ladder)	Photoelectric	20666971
0016	Smoke Detector	2nd Ed Storage 235	Photoelectric	04061131
0017	Smoke Detector	2nd Corridor By Room 228	Photoelectric	04061132
0018	Smoke Detector	2nd By Stair 3	Photoelectric	04061128
0019	Duct Detector	2nd – Corridor By Stair 2 EF7 (6'-10'-12' Ladder)		20666977
0020	Duct Detector	2nd – Corridor By Room 214 AC1 Return (6'-10'-12' Ladder)	Photoelectric	20666973
0021	Duct Detector	2nd Above Ceiling By Elevator on Top of Unit EF4	Photoelectric	20666968
0022	Smoke Detector	2nd Corridor By Room 214	Photoelectric	04061135
0023	Smoke Detector	2nd By Restroom	Photoelectric	04061134
0024	Duct Detector	2nd – Corridor By Room 214 AC2 Supply (8'-10'-12' Ladder)	Photoelectric	20666972
0025	Duct Detector	2nd – Corridor By Stair 1 EF1 (6'-10'-12' Ladder)	Photoelectric	20666976
0026	Smoke Detector	2nd Stair 2	Photoelectric	04061138
0027	Smoke Detector	2nd Data Closet in Room 211	Photoelectric	04061273

0028	Smoke Detector	2nd Corridor By Stair 2	Photoelectric	04061136
0029	Smoke Detector	2nd Room 211	Photoelectric	04061272
0030	Duct Detector	2nd – Room 232 EF9 (6'-10'-12' Ladder)	Photoelectric	20666983
0031	Smoke Detector	2nd Stair 4	Photoelectric	04061142
0032	Smoke Detector	2nd Corridor By Stair 1	Photoelectric	04061140
0033	Duct Detector	2nd – Corridor By Stair 1 EF6 (6'-10'-12' Ladder)	Photoelectric	20666975
0036	Smoke Detector	2nd Room 207	Photoelectric	04061139
0037	Smoke Detector	2nd PTO Room 210	Photoelectric	04061271
0038	Smoke Detector	2nd Room 239	Photoelectric	20666915
0039	Smoke Detector	2nd Custodian 220	Photoelectric	04061275
0040	Smoke Detector	2nd Stair 3	Photoelectric	04061130
0041	Smoke Detector	1st By Elevator Lobby – Cafe/Gym	Photoelectric	04061225
0042	Smoke Detector	1st Room 147	Photoelectric	04061277
0043	Smoke Detector	1st Room 120	Photoelectric	04061093
0044	Smoke Detector	1st Custodian 161	Photoelectric	04061230
0045	Smoke Detector	1st Stair 4	Photoelectric	04061121
0046	Smoke Detector	1st Main Office 116	Photoelectric	04061083
0048	Smoke Detector	1st Room 126B	Photoelectric	04061080
0049	Smoke Detector	1st Room 110	Photoelectric	04061090
0050	Smoke Detector	1st By Room 138	Photoelectric	04061280
0051	Smoke Detector	1st Main Entrance By Office	Photoelectric	04061077
0052	Smoke Detector	1st Room 166	Photoelectric	04061278
0053	Smoke Detector	1st Room 120 Storage	Photoelectric	04061094
0054	Smoke Detector	1st Room 129 Nurse	Photoelectric	04061099
0055	Smoke Detector	1st By Stair 1	Photoelectric	04061089
0056	Smoke Detector	1st Electrical 134	Photoelectric	04061283
0057	Smoke Detector	1st Room 126A	Photoelectric	04061081
0058	Smoke Detector	1st Stair 2	Photoelectric	04061086
0059	Heat Detector	1st Room 147 Kiln	Fixed Temperature	04061279
0060	Smoke Detector	1st Stair 1	Photoelectric	04061087
0061	Smoke Detector	1st By Restroom	Photoelectric	04061105
0062	Smoke Detector	1st Main Office 116	Photoelectric	04061078
0063	Smoke Detector	1st Room 119 Principal	Photoelectric	04061079
0064	Smoke Detector	1st By Room 144	Photoelectric	04061115
0065	Smoke Detector	1st By Room 148	Photoelectric	04061107
0066	Smoke Detector	1st Stair 3	Photoelectric	04061112
0067	Smoke Detector	1st Room 123	Photoelectric	04061222
0068	Smoke Detector	1st Room 140	Photoelectric	04061120
0069	Smoke Detector	1st Electrical Room 154 in Room 110	Photoelectric	04061218
0070	Smoke Detector	1st Room 122	Photoelectric	04061221
0071.	Smoke Detector	1st Room 125	Photoelectric	04061220
0072	Smoke Detector	1st By Stair 3	Photoelectric	04061111
0073	Smoke Detector	1st Room 112 Assistant Principal	Photoelectric	04062103
0074	Smoke Detector	1st Room 143	Photoelectric	04061117
0075	Smoke Detector	1st Room 150	Photoelectric	04061122
0076	Smoke Detector	1st Main Entrance	Photoelectric	04061076
0077	Smoke Detector	1st Room 178 Nurse Exam	Photoelectric	04061101
0078	Smoke Detector	1st Room 130 Nurse Cot Room	Photoelectric	04061104
0079	Smoke Detector	1st By Room 139	Photoelectric	04061281
0080	Smoke Detector	1st Room 146 Smoke A	Photoelectric	04061109
0081	Smoke Detector	1st Room 146 Smoke B	Photoelectric	04061108

0082	Smoke Detector	1st Corridor Room 144	Photoelectric	04061118
0083	Smoke Detector	1st Main Office 116/ Kitchen 118	Photoelectric	04061082
0084	Smoke Detector	1st Room 111	Photoelectric	04061092
0085	Smoke Detector	1st Room 150 Right Storage	Photoelectric	20666925
0086	Smoke Detector	1st Room 150 Left Storage	Photoelectric	20666924
0087	Smoke Detector	1st By Room 151	Photoelectric	04061106
0088	Smoke Detector	1st Room 144	Photoelectric	04061119
0089	Smoke Detector	1st Room 142 Smoke A	Photoelectric	04061113
0090	Smoke Detector	1st Room 128	Photoelectric	04061098
0091	Smoke Detector	1st Storage 176 in Room 110	Photoelectric	04061091
0092	Smoke Detector	1st Room 148	Photoelectric	04061110
0093	Smoke Detector	1st Data 177 in Room 120	Photoelectric	04061095
0094	Smoke Detector	1st Custodian 133	Photoelectric	04061282
0095	Smoke Detector	1st Room 121	Photoelectric	04061219
0096	Smoke Detector	1st By Stair 2	Photoelectric	04061084
0097	Smoke Detector	1st Room 142 Smoke B	Photoelectric	04061114
0098	Smoke Detector	1st By Room 126	Photoelectric	04061096
0099	Smoke Detector	1st Gym Office 159	Photoelectric	04061229
0126	Pull Station	2nd Stair 4	Dual Action	04061126
0127	Pull Station	2nd By Stair 3	Dual Action	04061129
0128	Initiating Device	2nd – Room 232 EF8 (6'-10'-12' Ladder)	Supporting Field Device	20666979
0129	Initiating Device	2nd – Room 232 EF10 (6'-10'-12' Ladder)	Supporting Field Device	20666981
0130	Initiating Device	2nd Above Ceiling By Elevator on Top of Unit EF3	Supporting Field Device	04061152
0131	Initiating Device	2nd – Room 232 EF9 (6'-10'-12' Ladder)	Supporting Field Device	20666980
0132	Initiating Device	2nd Corridor By Room 214 AC2 Return (8'-10'-12' Ladder)	Supporting Field Device	04061149
0133	Initiating Device	2nd Above Ceiling By Elevator on Top of Unit EF4	Supporting Field Device	04061151
0143	Initiating Device	2nd – Room 216 EF2 (6'-10'-12' Ladder)	Supporting Field Device	04061150
0144	Initiating Device	2nd – Corridor By Stair 2 AC1 Supply (6'-10'-12' Ladder)	Supporting Field Device	04061146
0145	Initiating Device	2nd – Corridor By Room 214 AC1 Return (6'-10'-12' Ladder)	Supporting Field Device	04061147
0146	Initiating Device	2nd Corridor By Stair 1 EF1 (6'-10'-12' Ladder)	Supporting Field Device	04061143
0147	Initiating Device	2nd – Corridor By Stair 2 EF7 (6'-10'-12' Ladder)	Supporting Field Device	04061145
0148	Initiating Device	2nd – Corridor By Stair 1 EF6 (6'-10'-12' Ladder)	Supporting Field Device	04061144
0149	Initiating Device	2nd Boyroom EF5	Supporting Field Device	20666969
0150	Initiating Device	2nd – Corridor By Room 214 AC2 Supply (8'-10'-12' Ladder)	Supporting Field Device	04061148
0159	Pull Station	2nd Stair 1	Dual Action	04061141
0160	Pull Station	2nd Stair 2	Dual Action	04061137
0164	Pull Station	1st By Stair 1	Dual Action	04061088
0165	Pull Station	1st Stair 4	Dual Action	04061116
0166	Pull Station	1st Main Entrance By Office	Dual Action	04061075

0167	Pull Station	1st Stair 2	Dual Action	04061085
Zone/Circuit: 05				
0001	Smoke Detector	Ground Electrical Room 021	Photoelectric	04061179
0002	Smoke Detector	Ground ED Storage Rm 26	Photoelectric	04061180
0003	Smoke Detector	Ground Telephone Rm 51	Photoelectric	04061181
0004	Smoke Detector	Ground By Electrical Room	Photoelectric	04061176
0005	Smoke Detector	Ground Water Service 039	Photoelectric	20666913
0006	Smoke Detector	Ground Corridor to Water Service 039	Photoelectric	20666914
0007	Smoke Detector	Ground By Custodian Storage 036	Photoelectric	04061185
0008	Smoke Detector	Ground Custodian Storage 036	Photoelectric	04061186
0009	Smoke Detector	Ground Custodian Office 035	Photoelectric	04061187
0010	Smoke Detector	Ground Stair 3	Photoelectric	04061188
0011	Smoke Detector	Ground Elevator Lobby	Photoelectric	04061192
0012	Smoke Detector	Ground By Stair 4	Photoelectric	04061193
0013	Smoke Detector	Ground Stair 4	Photoelectric	04061195
0014	Smoke Detector	Ground Room 040	Photoelectric	04061196
0015	Smoke Detector	Ground Room 040	Photoelectric	04061197
0016	Smoke Detector	Ground Stair 3 Exit	Photoelectric	04061191
0017	Smoke Detector	Ground By Restroom	Photoelectric	04061175
0018	Smoke Detector	Ground Computer Room 016	Photoelectric	04061164
0019	Smoke Detector	Ground Computer Room 016	Photoelectric	04061165
0020	Smoke Detector	Ground Room 127 Teachers Work Room	Photoelectric	04061097
0021	Smoke Detector	Ground Room 014	Photoelectric	04061211
0022	Smoke Detector	Ground Media Room 004 Smk 3	Photoelectric	04061170
0023	Smoke Detector	Ground Media Room 004 Smk 4	Photoelectric	04061171
0024	Smoke Detector	Ground Media Room 004 Smk 5	Photoelectric	04061168
0025	Smoke Detector	Ground Media Room 004 Smk 4	Photoelectric	04061167
0026	Smoke Detector	Ground Media Room 004 Smk 1	Photoelectric	04061166
0027	Smoke Detector	Ground By Stair 2	Photoelectric	04061158
0028	Smoke Detector	Ground Media Room 004/Office 005	Photoelectric	04061169
0029	Smoke Detector	Ground Media Room 004/Workroom 006	Photoelectric	04061213
0030	Smoke Detector	Ground Stair 2	Photoelectric	04061162
0031	Smoke Detector	Ground Stair 2 Exit	Photoelectric	04061161
0032	Smoke Detector	Ground Room 009 Storage	Photoelectric	04062104
0033	Smoke Detector	1st Room 124	Photoelectric	04061223
0034	Smoke Detector	Ground Room 002 Multipurpose	Photoelectric	04061172
0035	Smoke Detector	Ground Room 007 Storage	Photoelectric	04061217
0036	Smoke Detector	Ground Room 029	Photoelectric	04061209
0037	Smoke Detector	Ground Room 025	Photoelectric	04061208
0038	Smoke Detector	Ground Media Room 004 Right Storage	Photoelectric	04061215
0039	Smoke Detector	Ground Media Room 004 Left Storage	Photoelectric	04061214
0040	Smoke Detector	Ground Room 17	Photoelectric	04061182
0041	Smoke Detector	Ground Data Room 020	Photoelectric	04061178
0042	Smoke Detector	Ground Corridor By Data Room 020	Photoelectric	04061177
0043	Smoke Detector	Ground By Room 012	Photoelectric	04061163
0044	Smoke Detector	Ground Stair 1	Photoelectric	04061154
0045	Smoke Detector	Ground By Stair 1	Photoelectric	04061157
0046	Smoke Detector	1st Auditorium Front Left	Photoelectric	04061251
0047	Smoke Detector	1st Cafe/Gym Entrance	Photoelectric	04061235
0048	Smoke Detector	1st Cafe/Gym Smk 4	Photoelectric	20666954
0049	Smoke Detector	1st Cafe/Gym Smk 2	Photoelectric	20666953
0050	Smoke Detector	1st Cafe/Gym Smk 6	Photoelectric	20666955
0051	Smoke Detector	1st Cafe/Gym Smk 5	Photoelectric	20666956

0052	Smoke Detector	1st Cafe/Gym Smk 1	Photoelectric	20666958
0053	Smoke Detector	1st Cafe/Gym Smk 3	Photoelectric	20666957
0054	Smoke Detector	1st Gym Storage 157	Photoelectric	04061227
0055	Smoke Detector	1st Stage Corridor By Room 171	Photoelectric	04061239
0056	Smoke Detector	1st Kitchen Office	Photoelectric	20666959
0057	Smoke Detector	Ground Room 012 Storage	Photoelectric	04061174
0058	Smoke Detector	Ground Room 037 Storage	Photoelectric	04061184
0059	Duct Detector	1st Gym AC4 Supply	Photoelectric	20666990
0060	Duct Detector	1st Gym AC5 Return	Photoelectric	20666988
0061	Duct Detector	1st Gym AC5 Supply	Photoelectric	20666989
0062	Smoke Detector	1st Room 171 Teachers Room	Photoelectric	04061238
0063	Smoke Detector	1st Cafe/Gym Corridor Near Gym Storage 157	Photoelectric	04061234
0064	Smoke Detector	1st Cafe/Gym Storage 170	Photoelectric	04061237
0065	Smoke Detector	1st Room 172 By Stage	Photoelectric	04061241
0066	Smoke Detector	1st Stage Corridor Exit	Photoelectric	04061240
0067	Duct Detector	1st Stage Corridor By Room 171 EX14	Photoelectric	04061267
0068	Duct Detector	1st Gym AC4 Return	Photoelectric	20666991
0069	Duct Detector	1st Cafe/Gym Corridor AC6 Supply	Photoelectric	04061266
0070	Duct Detector	1st Gym EF12	Photoelectric	20666993
0071	Duct Detector	1st Auditorium Front Right Stage AC3 Supply	Photoelectric	04061262
0072	Duct Detector	1st Auditorium Front Right Stage Thru Right Brass Grate AC3 Return	Photoelectric	56181714
0073	Smoke Detector	1st Stage Left	Photoelectric	04061259
0074	Duct Detector	1st Gym EF13	Photoelectric	20666992
0075	Smoke Detector	1st Stage Right	Photoelectric	04061258
0076	Duct Detector	1st Stage EX16	Photoelectric	04061261
0077	Smoke Detector	1st Cafe/Gym Corridor Near Gym Storage 157	Photoelectric	04061226
0078	Duct Detector	1st Kitchen EF11	Photoelectric	20666963
0079	Smoke Detector	1st By Stair 3 Landing to Cafe/Gym	Photoelectric	04061224
0080	Duct Detector	1st Auditorium Center EF15	Photoelectric	04061264
0081	Duct Detector	1st Cafe/Gym Corridor AC6 Return	Photoelectric	04061265
0082	Duct Detector	1st Auditorium Front Center AC3 Supply	Photoelectric	04061263
0083	Smoke Detector	1st Corridor By Gym Office 159	Photoelectric	04061228
0084	Smoke Detector	1st Auditorium Front Right	Photoelectric	04061252
0085	Duct Detector	1st Kitchen Make Up Air Unit	Photoelectric	20666965
0086	Smoke Detector	1st By Boys Room 162	Photoelectric	04061231
0088	Smoke Detector	2nd Electrical Room 219	Photoelectric	04061274
0089	Smoke Detector	Ground Stair 3 Landing to Cafe/Gym	Photoelectric	04061207
0090	Smoke Detector	1st Auditorium Rear Right	Photoelectric	04061253
0093	Smoke Detector	1st Auditorium Rear Left	Photoelectric	04061250
0093	Smoke Detector	1st Kitchen Storage	Photoelectric	20666966
0094	Heat Detector	1st Kitchen	Fixed Temperature	20666960
0095	Heat Detector	1st Kitchen	Fixed Temperature	20666961
0126	Pull Station	Ground Room 29	Dual Action	04061210
0127	Pull Station	Ground Stair 1 Exit	Dual Action	04061153
0128	Pull Station	Ground Stair 4 By Room 029	Dual Action	04061194
0129	Pull Station	Ground Stair 3	Dual Action	04061189
0130	Pull Station	Ground Stair 3 Exit	Dual Action	04061190
0131	Pull Station	Ground Room 012	Dual Action	04061173
0132	Pull Station	Ground Room 037	Dual Action	04061183

0133	Pull Station	Ground Stair 4 Exit	Dual Action	04061198
0134	Pull Station	Ground Room 014	Dual Action	04061212
0135	Pull Station	Ground Stair 2 Exit	Dual Action	04061160
0136	Pull Station	Ground Room 009	Dual Action	04061156
0137	Pull Station	Ground Room 007	Dual Action	04061216
0138	Pull Station	Ground By Stair 2	Dual Action	04061159
0139	Pull Station	1st Stage Corridor Exit	Dual Action	04061242
0140	Pull Station	1st Gym	Dual Action	56181713
0141	Pull Station	1st Cafe/Gym Entrance	Dual Action	04061236
0142	Initiating Device	1st Cafe/Gym Corridor AC4 Return	Supporting Field Device	04061245
0143	Initiating Device	1st Cafe/Gym Corridor AC5 Return	Supporting Field Device	04061247
0144	Initiating Device	1st Cafe/Gym Corridor EF12	Supporting Field Device	04061248
0145	Initiating Device	1st Stage Corridor By Room 171 EX14	Supporting Field Device	04061243
0146	Initiating Device	1st Cafe/Gym Corridor EF13	Supporting Field Device	04061249
0147	Initiating Device	1st Cafe/Gym Corridor AC5 Supply	Supporting Field Device	04061246
0148	Initiating Device	1st Cafe/Gym Corridor AC4 Supply	Supporting Field Device	04061244
0149	Initiating Device	1st Auditorium Center EF16	Supporting Field Device	20666952
0150	Pull Station	Ground Stair 1	Dual Action	04061155
0182	Initiating Device	1st Kitchen EF11	Supporting Field Device	20666962
0183	Initiating Device	1st Cafe/Gym Corridor AC6 Supply	Supporting Field Device	04061232
0184	Initiating Device	1st Cafe/Gym Corridor AC6 Return	Supporting Field Device	04061233
0185	Initiating Device	1st Kitchen Make Up Air Unit	Supporting Field Device	20666964
0186	Initiating Device	1st Auditorium Front Right Stage AC3 Return	Supporting Field Device	04061257
0187	Initiating Device	1st Auditorium Center EF15	Supporting Field Device	04061254
0188	Initiating Device	1st Auditorium Front Center AC3 Supply	Supporting Field Device	04061255
0189	Initiating Device	1st Auditorium Front Right Stage AC3 Supply	Supporting Field Device	04061256
0191	Pull Station	1st Kitchen Exit	Dual Action	04062102
0204	Pull Station	1st Auditorium Stage	Dual Action	04061260
0221	Heat Detector	Ground Boiler Room 027	Fixed Temperature	20666912

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Toquam School
123 Ridgewood Avenue
Stamford, CT 06902

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Feb 14, 2020

Building: Stamford BOE-Toquam School
Contact: Davor Lucaj
Title: Facilities Trades Manager



Company: TPC Associates, Inc.
Contact: Dave Majewski
Title: Inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Toquam School	Contact: Davor Lucaj	
Address: 123 Ridgewood Avenue	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06902	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Dave Majewski	
Address: 261 Pepe's Farm Road	Phone: 203-666-9587	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: dave.majewski@tpcsystems.com	
System Control Unit		
Manufacturer: EST	Inspection Date: 02/14/2020	IDC Style:
Model Number: LSS4/12	Install Date: 08/02/2012	SLC Style:
Software Version:	Version Date: 08/02/2012	NAC Style:
Location: Basement Electrical/ Panel Room	Current Protection: Breaker	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type: Digital Communicator	Mfg: Notifire	Model #: 911A
Test Time/Date: 2/14/20 9:53:41 AM	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.98%	0	0%	0	0%	0	0%
Control	4	3.92%	4	100.00%	3	75.00%	1	25.00%
Initiating	97	95.10%	97	100.00%	97	100.00%	0	0%
Totals	102	100%	101	99.02%	100	99.01%	1	0.99%

Certification	
<p>Company: TPC Associates, Inc.</p> <p>Inspector: Dave Majewski</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px 0;">  </div> <p>Signed: Feb 14, 2020 11:15:06 AM</p>	<p>Building: Stamford BOE-Toquam School</p> <p>Contact: Davor Lucaj</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px 0;">  </div> <p>Signed: Feb 14, 2020 11:29:34 AM</p>

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-Toquam School			Control Panel: 1 - EST LSS4/12	
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
🔧 ScanID	📍 Location	🔑 Problem	Address	📖 Reference
<i>Control</i>				
Battery				
04062259	Basement Electrical/ Panel Room (Dialer)	Failed Test	1	NFPA 72 Table 10.4.2.2.5(a-e)

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-Toquam School			Control Panel: 1 - EST LSS4/12		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
Control					
Battery					
04062259	Basement Electrical/ Panel Room (Dialer)	Replace	UB1250	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

Notes & Recommendations

Generated by: BuildingReports.com

Building: Stamford BOE-Toquam School			Control Panel: 1 - EST LSS4/12	
<i>The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.</i>				
ScanID	Note	Device Type	Location	Comment
<i>Control</i>				
04062259	1	Battery	Basement Electrical/ Panel Room (Dialer)	Failed Test
low amps				
2/14/2020				

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Toquam School		Control Panel: 1 - EST LSS4/12		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
<i>Passed</i>				
Control				
Battery	Basement Electrical/ Panel Room	Tested	9:55:01 AM	02/14/2020
Communicator	Basement Electrical/ Panel Room (Dialer)	Tested	9:53:41 AM	02/14/2020
Control Panel	Basement Electrical/ Panel Room	Tested	9:53:16 AM	02/14/2020
Initiating				
Duct Detector	1st Mechanical Room By Mirror Box (Local Devices)	Visually Checked	11:12:12 AM	02/14/2020
Duct Detector	2nd Room 19 (Local Devices)	Visually Checked	11:14:45 AM	02/14/2020
Duct Detector	2nd Room 37 (Local Devices)	Visually Checked	10:22:36 AM	02/14/2020
Heat Detector	Basement Electrical/ Panel Room	Tested	9:53:40 AM	02/14/2020
Heat Detector	Basement Boiler Room	Tested	9:53:32 AM	02/14/2020
Heat Detector	Basement Boiler Room	Tested	9:53:35 AM	02/14/2020
Heat Detector	Basement Boiler Room	Tested	9:53:36 AM	02/14/2020
Heat Detector	Basement Boiler Room	Tested	9:53:37 AM	02/14/2020
Heat Detector	Basement Boiler Room	Tested	9:53:39 AM	02/14/2020
Heat Detector	Basement Custodian Office By Air Handler	Visually Checked	10:15:54 AM	02/14/2020
Heat Detector	Basement Custodian Office By Desk	Visually Checked	10:15:59 AM	02/14/2020
Heat Detector	Basement Kitchen by Freezer	Visually Checked	10:13:27 AM	02/14/2020
Heat Detector	Basement Kitchen	Tested	10:10:15 AM	02/14/2020
Heat Detector	1st By Room 46	Visually Checked	11:04:27 AM	02/14/2020
Heat Detector	1st By Room 50	Visually Checked	10:58:45 AM	02/14/2020
Heat Detector	1st Mechanical Room	Visually Checked	11:02:09 AM	02/14/2020
Heat Detector	1st Storage By Exit	Visually Checked	11:01:37 AM	02/14/2020
Heat Detector	2nd Room 36A	Visually Checked	11:14:41 AM	02/14/2020
Heat Detector	2nd Kiln Room 13	Visually Checked	10:36:20 AM	02/14/2020
Heat Detector	2nd Storage By Elevator	Visually Checked	10:24:30 AM	02/14/2020
Pull Station	Basement Boiler Room	Visually Checked	10:16:09 AM	02/14/2020
Pull Station	Basement Gym Corridor By Cafe	Visually Checked	10:05:52 AM	02/14/2020
Pull Station	Basement Gym Rear By Exit	Visually Checked	10:07:16 AM	02/14/2020
Pull Station	Basement Cafe By Water Fountain	Visually Checked	10:13:59 AM	02/14/2020
Pull Station	1st Corridor By Media Center By Exit to Courtyard	Visually Checked	11:08:27 AM	02/14/2020
Pull Station	1st By Elevators Smoke 13	Visually Checked	11:10:02 AM	02/14/2020
Pull Station	1st Exit to Courtyard	Visually Checked	10:53:32 AM	02/14/2020
Pull Station	1st Media Center Left Side	Visually Checked	11:12:00 AM	02/14/2020
Pull Station	1st Media Center Right Side	Visually Checked	11:11:42 AM	02/14/2020
Pull Station	2nd Top of Stair Corridor By Elevator	Visually Checked	10:25:49 AM	02/14/2020
Pull Station	2nd Top of Stairs By Room MOD1	Visually Checked	10:18:23 AM	02/14/2020
Pull Station	2nd By Main Office	Visually Checked	10:31:29 AM	02/14/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	2nd By Room 18	Visually Checked	11:14:49 AM	02/14/2020
Pull Station	2nd Portables By Room P-1	Visually Checked	10:37:51 AM	02/14/2020
Pull Station	2nd Portables By Room P-5	Visually Checked	10:43:24 AM	02/14/2020
Pull Station	2nd Portables Room P-1	Visually Checked	11:12:55 AM	02/14/2020
Pull Station	2nd Portables Room P-2	Visually Checked	10:39:36 AM	02/14/2020
Pull Station	2nd Portables Room P-3	Visually Checked	11:14:27 AM	02/14/2020
Pull Station	2nd Portables Room P-4	Visually Checked	10:42:27 AM	02/14/2020
Pull Station	2nd Portables Room P-5	Visually Checked	10:44:01 AM	02/14/2020
Smoke Detector	Basement By Elevator Smoke 80	Visually Checked	10:04:35 AM	02/14/2020
Smoke Detector	Basement Cafe/ Bandroom Storage Smoke 8	Visually Checked	10:15:50 AM	02/14/2020
Smoke Detector	Basement Gym Corridor By Cafe Smoke 59	Visually Checked	10:06:05 AM	02/14/2020
Smoke Detector	Basement Gym Center	Visually Checked	10:16:03 AM	02/14/2020
Smoke Detector	Basement Gym Left	Visually Checked	10:08:24 AM	02/14/2020
Smoke Detector	Basement Gym Right	Visually Checked	10:08:14 AM	02/14/2020
Smoke Detector	Basement Cafe Left	Visually Checked	10:08:56 AM	02/14/2020
Smoke Detector	Basement Cafe Right	Visually Checked	10:09:04 AM	02/14/2020
Smoke Detector	Basement Cafe Stage	Visually Checked	10:09:06 AM	02/14/2020
Smoke Detector	1st By Exit/Storage	Visually Checked	11:00:28 AM	02/14/2020
Smoke Detector	1st By Room 46 Smoke 21	Visually Checked	10:55:14 AM	02/14/2020
Smoke Detector	1st By Room 50 Smoke 23	Visually Checked	10:58:32 AM	02/14/2020
Smoke Detector	1st Corridor By Media Center Smoke 18	Visually Checked	11:11:56 AM	02/14/2020
Smoke Detector	1st Corridor By Media Center Smoke 19	Visually Checked	11:06:53 AM	02/14/2020
Smoke Detector	1st Corridor By Media Center Smoke 20	Visually Checked	11:07:23 AM	02/14/2020
Smoke Detector	1st Mechanical Room By Mirror Box Smoke 20A	Visually Checked	11:12:04 AM	02/14/2020
Smoke Detector	1st By Elevators Smoke 13	Visually Checked	11:09:41 AM	02/14/2020
Smoke Detector	1st By Media Center Smoke 14	Visually Checked	11:11:36 AM	02/14/2020
Smoke Detector	1st Mechanical Room Smoke 25A	Visually Checked	11:02:28 AM	02/14/2020
Smoke Detector	1st Media Center Center Smoke 16	Visually Checked	11:12:23 AM	02/14/2020
Smoke Detector	1st Media Center Left Side Smoke 17	Visually Checked	11:11:52 AM	02/14/2020
Smoke Detector	1st Media Center Right Side Smoke 15	Visually Checked	11:11:46 AM	02/14/2020
Smoke Detector	1st Room By Room 50 Smoke 24	Visually Checked	11:12:16 AM	02/14/2020
Smoke Detector	1st Room With The Double-Double Doors By Room 46 Smoke 22	Visually Checked	11:12:19 AM	02/14/2020
Smoke Detector	2nd By Office	Visually Checked	10:29:08 AM	02/14/2020
Smoke Detector	2nd By Room 1 Smoke 31	Visually Checked	10:26:36 AM	02/14/2020
Smoke Detector	2nd By Room 5 Smoke 30	Visually Checked	10:27:37 AM	02/14/2020
Smoke Detector	2nd Corridor By Fire Door Smoke 34	Visually Checked	10:23:33 AM	02/14/2020
Smoke Detector	2nd Corridor By Room 31 Smoke 35	Visually Checked	10:20:49 AM	02/14/2020
Smoke Detector	2nd Corridor By Room MOD1 Smoke 36	Visually Checked	10:19:00 AM	02/14/2020
Smoke Detector	2nd Custodial Closet By Room 16 Smoke 42	Visually Checked	11:12:40 AM	02/14/2020
Smoke Detector	2nd Custodian By Room MOD2 Smoke 38	Visually Checked	11:12:52 AM	02/14/2020
Smoke Detector	2nd Custodian Closet By Elevator Smoke 33	Visually Checked	10:25:28 AM	02/14/2020
Smoke Detector	2nd Top of Stair Smoke 32	Visually Checked	10:26:13 AM	02/14/2020
Smoke Detector	2nd Top of Stairs By Room MOD1 Smoke 37	Visually Checked	10:17:55 AM	02/14/2020
Smoke Detector	2nd By Room 10 Smoke 45	Visually Checked	10:32:34 AM	02/14/2020
Smoke Detector	2nd By Room 14 Smoke 44	Visually Checked	10:33:09 AM	02/14/2020
Smoke Detector	2nd By Room 19A Smoke 43	Visually Checked	10:34:59 AM	02/14/2020
Smoke Detector	2nd By Room 21 Smoke 41	Visually Checked	10:46:02 AM	02/14/2020
Smoke Detector	2nd By Room 24 Smoke 40	Visually Checked	11:12:44 AM	02/14/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd By Room MOD 2 Smoke 39	Visually Checked	11:12:48 AM	02/14/2020
Smoke Detector	2nd Office Smoke 27	Visually Checked	10:29:59 AM	02/14/2020
Smoke Detector	2nd Office Storage Smoke 28	Visually Checked	11:12:33 AM	02/14/2020
Smoke Detector	2nd Portables Smoke 48	Visually Checked	10:37:09 AM	02/14/2020
Smoke Detector	2nd Portables Smoke 51	Visually Checked	10:40:09 AM	02/14/2020
Smoke Detector	2nd Portables Smoke 52	Visually Checked	10:40:26 AM	02/14/2020
Smoke Detector	2nd Portables Smoke 53	Visually Checked	10:43:08 AM	02/14/2020
Smoke Detector	2nd Portables Room P-1 Smoke 49	Visually Checked	11:14:06 AM	02/14/2020
Smoke Detector	2nd Portables Room P-2 Smoke 50	Visually Checked	10:38:49 AM	02/14/2020
Smoke Detector	2nd Portables Room P-3 Smoke 54	Visually Checked	11:14:11 AM	02/14/2020
Smoke Detector	2nd Portables Room P-4 Smoke 55	Visually Checked	10:41:48 AM	02/14/2020
Smoke Detector	2nd Portables Room P-5	Visually Checked	10:43:42 AM	02/14/2020
Smoke Detector	2nd Ramp To Portables Smoke 46	Visually Checked	10:36:49 AM	02/14/2020
Smoke Detector	2nd Ramp To Portables Smoke 47	Visually Checked	10:37:03 AM	02/14/2020
Smoke Detector	2nd Room 20 Storage	Visually Checked	11:14:33 AM	02/14/2020
Smoke Detector	2nd Room 21 Smoke 57	Visually Checked	11:14:37 AM	02/14/2020
Smoke Detector	2nd Top of Stair By Main Office	Visually Checked	10:31:45 AM	02/14/2020
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	Basement Electrical/ Panel Room (Dialer)	Tested	9:59:21 AM	02/14/2020

Service Summary

Generated by: BuildingReports.com






Building: Stamford BOE-Toquam School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	1
Total		1
<i>Passed</i>		
Battery	Tested	1
Communicator	Tested	1
Control Panel	Tested	1
Duct Detector	Visually Checked	3
Heat Detector	Tested	7
Heat Detector	Visually Checked	10
Pull Station	Visually Checked	20
Smoke Detector	Visually Checked	57
Total		100
Grand Total		101

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Toquam School							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		 dB	 dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
					<input type="checkbox"/>	0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Toquam School				Control Panel: 1 - EST LSS4/12			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	Basement Electrical/ Panel Room	8	12	12.84v	7.4ah040		
Failed/Other							
Battery							
Sealed Lead Acid	Basement Electrical/ Panel Room (Dialer)	5	12	12.29V	2.4ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Toquam School				Control Panel: 1 - EST LSS4/12	
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		0.98%	1
Control Panel		Control		0.98%	1
Heat Detector		Initiating		16.67%	17
Communicator		Control		0.98%	1
Battery		Control		1.96%	2
Smoke Detector		Initiating		55.88%	57
Pull Station		Initiating		19.61%	20
Duct Detector		Initiating		2.94%	3
Type	Qty	Model #	Description		Install Date
In Service - 3 Years to 5 Years					
Universal					
Battery	1	UB1250	Sealed Lead Acid		01/26/2017
Battery	1	UB1280	Sealed Lead Acid		04/27/2016
In Service - 5 Years to 10 Years					
AP&C					
Duct Detector	3	RW-UNI-N	Photoelectric		08/02/2012
Edwards					
Heat Detector	11	283B	Fixed Temperature		08/02/2012
Pull Station	8	SPO-270	Single Action		08/02/2012
Smoke Detector	3	6250B	Ionization		08/02/2012
Smoke Detector	3	EC30U	Photoelectric		08/02/2012
ESL					
Heat Detector	4	BELL	Fixed Temperature		08/02/2012
Smoke Detector	8	2251	Ionization		08/02/2012
Smoke Detector	25	612U	Ionization		08/02/2012
Smoke Detector	6	623B	Photoelectric		08/02/2012
Smoke Detector	1	683B	Ionization		08/02/2012
EST					
Control Panel	1	LSS4/12			08/02/2012
Faraday					
Heat Detector	2	8300	Fixed Temperature		08/02/2012
Fenwal					
Smoke Detector	2	PSD 7125	Photoelectric		08/02/2012
Fire-Lite					

Pull Station	6		Dual Action	08/02/2012
Notifire				
Communicator	1	911A	Digital Communicator	08/02/2012
Standard				
Pull Station	6	700	Single Action	08/02/2012
System Sensor				
Smoke Detector	1	2451		08/02/2012
Smoke Detector	8	2451	Photoelectric	08/02/2012

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Newfield School
345 Pepper Ridge Road
Stamford, CT 06901

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Feb 18, 2020



Building: Stamford BOE-Newfield School
Contact: Davor Lucaj
Title: Facilities Trades Manager

Company: TPC Associates, Inc.
Contact: Dave Majewski
Title: Inspector

Executive Summary





Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Newfield School	Contact: Davor Lucaj	
Address: 345 Pepper Ridge Road	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06901	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Dave Majewski	
Address: 261 Pepe's Farm Road	Phone: 203-666-9587	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: dave.majewski@tpcsystems.com	
System Control Unit		
Manufacturer: EST	Inspection Date: 02/18/2020	IDC Style:
Model Number: 3X-SFS1R	Install Date: 08/23/2012	SLC Style:
Software Version:	Version Date: 08/23/2012	NAC Style:
Location: 1st Main Office	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.83%	0	0%	0	0%	0	0%
Control	5	4.17%	5	100.00%	4	80.00%	1	20.00%
Initiating	114	95.00%	114	100.00%	114	100.00%	0	0%
Totals	120	100%	119	99.17%	118	99.16%	1	0.84%
Certification								
Company: TPC Associates, Inc.				Building: Stamford BOE-Newfield School				
Inspector: Dave Majewski				Contact: Davor Lucaj				
								
Signed: Feb 18, 2020 9:57:57 AM				Signed: Feb 18, 2020 10:05:29 AM				

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-Newfield School			Control Panel: 1 - EST 3X-SFS1R	
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
 ScanID	 Location	 Problem	Address	 Reference
<i>Control</i>				
Battery				
44890370	1st FA Communicator	Failed Test	1	NFPA72 Table 14.4.3.2 (9a)(1)

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-Newfield School			Control Panel: 1 - EST 3X-SFS1R		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
Control					
Battery					
44890370	1st FA Communicator	Replace	UB1250	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Newfield School		Control Panel: 1 - EST 3X-SFS1R		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
<i>Passed</i>				
Control				
Battery	1st Bottom battery cabinet	Tested	9:30:48 AM	02/18/2020
Battery	1st NAC BOOSTER 2 Lower	Tested	9:20:12 AM	02/18/2020
Battery	1st NAC BOOSTER TRIP 1 Lower	Tested	9:22:35 AM	02/18/2020
Control Panel	1st Main Office	Tested	9:17:37 AM	02/18/2020
Initiating				
Beam Detector	1st Media Center	Visually Checked	9:52:54 AM	02/18/2020
CO Detector	Basement Boiler Room Above Stairs	Visually Checked	9:46:31 AM	02/18/2020
CO Detector	1st kitchen entrance	Visually Checked	9:52:18 AM	02/18/2020
Duct Detector	1st Northwest by P.E. Office DD1 (Local)	Visually Checked	9:07:56 AM	02/18/2020
Duct Detector	1st Northwest by Room 310 DD2	Visually Checked	8:57:26 AM	02/18/2020
Duct Detector	1st Northwest by Room 312 DD3	Visually Checked	8:57:00 AM	02/18/2020
Duct Detector	1st South by Room 210B DD4	Visually Checked	9:52:43 AM	02/18/2020
Duct Detector	1st South by Room 210B DD5	Visually Checked	9:52:46 AM	02/18/2020
Heat Detector	Basement Boiler	Visually Checked	9:46:41 AM	02/18/2020
Heat Detector	Basement Boiler	Visually Checked	9:46:46 AM	02/18/2020
Heat Detector	Basement Storage	Visually Checked	9:46:59 AM	02/18/2020
Heat Detector	Basement Boiler Room Above Stairs	Visually Checked	9:45:44 AM	02/18/2020
Heat Detector	Basement Boiler Room Left Side Back	Visually Checked	9:47:04 AM	02/18/2020
Heat Detector	Basement Boiler Room Left Side Front	Visually Checked	9:45:42 AM	02/18/2020
Heat Detector	Basement Boiler Room Middle Back	Visually Checked	9:45:38 AM	02/18/2020
Heat Detector	Basement Boiler Room Middle Front	Visually Checked	9:45:41 AM	02/18/2020
Heat Detector	Basement Boiler Room Right side Back	Visually Checked	9:47:09 AM	02/18/2020
Heat Detector	Basement Boiler Room Right side Front	Visually Checked	9:45:39 AM	02/18/2020
Heat Detector	1st North Storage by Room 302	Visually Checked	9:47:13 AM	02/18/2020
Heat Detector	1st Northwest Gym	Visually Checked	9:47:18 AM	02/18/2020
Heat Detector	1st Northwest Gym	Visually Checked	9:47:21 AM	02/18/2020
Heat Detector	1st Northwest Gym	Visually Checked	9:47:26 AM	02/18/2020
Heat Detector	1st Northwest Gym	Visually Checked	9:47:30 AM	02/18/2020
Heat Detector	1st Northwest Gym	Visually Checked	9:47:41 AM	02/18/2020
Heat Detector	1st Northwest Gym	Visually Checked	9:47:46 AM	02/18/2020
Heat Detector	1st Northwest Kitchen	Visually Checked	9:52:34 AM	02/18/2020
Heat Detector	1st Northwest Kitchen	Visually Checked	9:52:38 AM	02/18/2020
Heat Detector	1st Southwest Stage	Visually Checked	9:47:37 AM	02/18/2020
Pull Station	1st by exit end of 300 wing	Visually Checked	9:50:40 AM	02/18/2020
Pull Station	1st exit by lobby side	Visually Checked	9:50:36 AM	02/18/2020
Pull Station	1st exit from custodian area	Visually Checked	9:50:48 AM	02/18/2020
Pull Station	1st Exit in front of room 201	Visually Checked	9:48:07 AM	02/18/2020
Pull Station	1st exit room 403	Visually Checked	9:51:10 AM	02/18/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	1st Stage left upper	Visually Checked	9:49:25 AM	02/18/2020
Pull Station	1st west media center exit Pull	Visually Checked	9:50:02 AM	02/18/2020
Pull Station	1st by door to custodian dock	Visually Checked	9:50:44 AM	02/18/2020
Pull Station	1st by exit end of 200 wing	Visually Checked	9:48:33 AM	02/18/2020
Pull Station	1st exit by kitchen side	Visually Checked	9:50:32 AM	02/18/2020
Pull Station	1st exit by l/h side	Visually Checked	9:50:57 AM	02/18/2020
Pull Station	1st exit by r/h side	Visually Checked	9:50:52 AM	02/18/2020
Pull Station	1st exit by room 406	Visually Checked	9:51:35 AM	02/18/2020
Pull Station	1st exit room 401	Visually Checked	9:51:00 AM	02/18/2020
Pull Station	1st exit room 402	Visually Checked	9:51:05 AM	02/18/2020
Pull Station	1st exit room 404	Visually Checked	9:51:18 AM	02/18/2020
Pull Station	1st main lobby entrance	Visually Checked	9:50:17 AM	02/18/2020
Pull Station	1st Pull east media center exit	Visually Checked	9:49:58 AM	02/18/2020
Pull Station	1st stage left lower	Visually Checked	9:49:20 AM	02/18/2020
Smoke Detector	Basement by exit	Visually Checked	9:46:52 AM	02/18/2020
Smoke Detector	1st sd hall by courtyard rm 202	Visually Checked	9:48:25 AM	02/18/2020
Smoke Detector	1st 300 hall by staff lounge	Visually Checked	8:59:48 AM	02/18/2020
Smoke Detector	1st area between 100-400	Visually Checked	9:02:34 AM	02/18/2020
Smoke Detector	1st Auditorium stage left	Visually Checked	9:34:44 AM	02/18/2020
Smoke Detector	1st by door to custodian dock	Visually Checked	9:02:13 AM	02/18/2020
Smoke Detector	1st by room 306	Visually Checked	8:58:14 AM	02/18/2020
Smoke Detector	1st by Room 310	Visually Checked	8:57:14 AM	02/18/2020
Smoke Detector	1st by room 314	Visually Checked	8:56:19 AM	02/18/2020
Smoke Detector	1st by room 316	Visually Checked	8:54:46 AM	02/18/2020
Smoke Detector	1st by room 318	Visually Checked	8:54:33 AM	02/18/2020
Smoke Detector	1st by room 404	Visually Checked	9:05:22 AM	02/18/2020
Smoke Detector	1st by Room 405	Visually Checked	9:05:29 AM	02/18/2020
Smoke Detector	1st corridor by room 201	Visually Checked	9:48:11 AM	02/18/2020
Smoke Detector	1st Hall by room 104	Visually Checked	9:50:21 AM	02/18/2020
Smoke Detector	1st hall by room 106	Visually Checked	9:50:28 AM	02/18/2020
Smoke Detector	1st hallway by 202	Visually Checked	9:48:21 AM	02/18/2020
Smoke Detector	1st hallway by p.e office	Visually Checked	9:08:20 AM	02/18/2020
Smoke Detector	1st hallway by room 202 & 201	Visually Checked	9:48:17 AM	02/18/2020
Smoke Detector	1st Main office room	Visually Checked	9:47:55 AM	02/18/2020
Smoke Detector	1st nurses office by main office	Visually Checked	9:48:03 AM	02/18/2020
Smoke Detector	1st p office	Visually Checked	9:52:10 AM	02/18/2020
Smoke Detector	1st room 401	Visually Checked	9:03:05 AM	02/18/2020
Smoke Detector	1st room 401	Visually Checked	9:03:11 AM	02/18/2020
Smoke Detector	1st room 402	Visually Checked	9:03:32 AM	02/18/2020
Smoke Detector	1st sd 2 media centerlibrary	Visually Checked	9:49:41 AM	02/18/2020
Smoke Detector	1st sd 2 media office	Visually Checked	9:49:37 AM	02/18/2020
Smoke Detector	1st sd 3 media centerlibrary	Visually Checked	9:49:54 AM	02/18/2020
Smoke Detector	1st sd hall by Room 208	Visually Checked	9:48:56 AM	02/18/2020
Smoke Detector	1st sd hall by courtyard leading to room 202	Visually Checked	9:48:29 AM	02/18/2020
Smoke Detector	1st sd hall by main storage	Visually Checked	9:49:12 AM	02/18/2020
Smoke Detector	1st sd hall by room 200	Visually Checked	9:49:00 AM	02/18/2020
Smoke Detector	1st sd hall by room 204	Visually Checked	9:49:04 AM	02/18/2020
Smoke Detector	1st sd hallway by main office entrance	Visually Checked	9:49:29 AM	02/18/2020
Smoke Detector	1st sd hallway by room 212b	Visually Checked	9:48:51 AM	02/18/2020
Smoke Detector	1st Sd main office front area	Visually Checked	9:47:59 AM	02/18/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st start of 300 wing	Visually Checked	9:01:10 AM	02/18/2020
Smoke Detector	1st Storage Room Across from 302	Visually Checked	9:47:51 AM	02/18/2020
Smoke Detector	1st 300 hall by girls bathroom	Visually Checked	8:58:34 AM	02/18/2020
Smoke Detector	1st Auditorium stage right	Visually Checked	9:34:47 AM	02/18/2020
Smoke Detector	1st Auditorium stage middle	Visually Checked	9:34:46 AM	02/18/2020
Smoke Detector	1st by room 308	Visually Checked	8:57:57 AM	02/18/2020
Smoke Detector	1st by room 312	Visually Checked	8:56:45 AM	02/18/2020
Smoke Detector	1st by room 401	Visually Checked	9:04:41 AM	02/18/2020
Smoke Detector	1st by room 406	Visually Checked	9:06:16 AM	02/18/2020
Smoke Detector	1st front main lobby doors	Visually Checked	9:50:13 AM	02/18/2020
Smoke Detector	1st hall by room 321	Visually Checked	8:54:12 AM	02/18/2020
Smoke Detector	1st hall by room 105	Visually Checked	9:50:24 AM	02/18/2020
Smoke Detector	1st main lobby in front of media center	Visually Checked	9:50:09 AM	02/18/2020
Smoke Detector	1st media center computer room	Visually Checked	9:51:55 AM	02/18/2020
Smoke Detector	1st media center instruction 504	Visually Checked	9:50:05 AM	02/18/2020
Smoke Detector	1st media center office	Visually Checked	9:52:05 AM	02/18/2020
Smoke Detector	1st room 402	Visually Checked	9:03:39 AM	02/18/2020
Smoke Detector	1st room 403	Visually Checked	9:04:12 AM	02/18/2020
Smoke Detector	1st room 403	Visually Checked	9:04:18 AM	02/18/2020
Smoke Detector	1st room 404	Visually Checked	9:51:14 AM	02/18/2020
Smoke Detector	1st room 404	Visually Checked	9:51:23 AM	02/18/2020
Smoke Detector	1st room 405	Visually Checked	9:05:45 AM	02/18/2020
Smoke Detector	1st room 406	Visually Checked	9:06:28 AM	02/18/2020
Smoke Detector	1st sd 1 media centerlibrary	Visually Checked	9:49:46 AM	02/18/2020
Smoke Detector	1st sd 4 media centerlibrary	Visually Checked	9:49:50 AM	02/18/2020
Smoke Detector	1st sd hall by main & nurses office	Visually Checked	9:49:16 AM	02/18/2020
Smoke Detector	1st sd hall by room 216	Visually Checked	9:48:37 AM	02/18/2020
Smoke Detector	1st sd hall by storage	Visually Checked	9:49:08 AM	02/18/2020
Smoke Detector	1st sd hallway by main office confrence room	Visually Checked	9:49:33 AM	02/18/2020
Smoke Detector	1st sd hallway by room 212	Visually Checked	9:48:46 AM	02/18/2020
Smoke Detector	1st sd hallway by room 214	Visually Checked	9:48:41 AM	02/18/2020
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	1st FA Communicator	Tested	9:19:39 AM	02/18/2020

Service Summary

Generated by: BuildingReports.com




Building: Stamford BOE-Newfield School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	1
Total		1
<i>Passed</i>		
Battery	Tested	3
Beam Detector	Visually Checked	1
CO Detector	Visually Checked	2
Control Panel	Tested	1
Duct Detector	Visually Checked	5
Heat Detector	Visually Checked	20
Pull Station	Visually Checked	19
Smoke Detector	Visually Checked	67
Total		118
Grand Total		119

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Newfield School							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		◀ dB	◀ dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
Whole Facility				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Newfield School				Control Panel: 1 - EST 3X-SFS1R			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	1st Bottom battery cabinet	51Ah	12V	13.35V	45Ah04		
					06		
Sealed Lead Acid	1st NAC BOOSTER 2 Lower	8Ah	12V	12.66V	11Ah		
Sealed Lead Acid	1st NAC BOOSTER TRIP 1 Lower	7Ah	12V	12.47V	6V		
Failed/Other							
Battery							
Sealed Lead Acid	1st FA Communicator	5Ah	12V	12.22V	2.5Ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Newfield School	Control Panel: 1 - EST 3X-SFS1R
--	---------------------------------

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type	Category	% of Inventory	Quantity
Sound Test	Sound Test	0.83%	1
Smoke Detector	Initiating	55.83%	67
Duct Detector	Initiating	4.17%	5
Control Panel	Control	0.83%	1
Battery	Control	3.33%	4
Heat Detector	Initiating	16.67%	20
CO Detector	Initiating	1.67%	2
Pull Station	Initiating	15.83%	19
Beam Detector	Initiating	0.83%	1

Type	Qty	Model #	Description	Install Date
<i>In Service - 90 Days - 1 Year</i>				
LEOCH				
Battery	1	DJW12-7.2	Sealed Lead Acid	08/20/2019
PEAK				
Battery	1	PK12V40	Sealed Lead Acid	08/20/2019
<i>In Service - 2 Years to 3 Years</i>				
Universal				
Battery	1	UB1250	Sealed Lead Acid	12/07/2017
<i>In Service - 5 Years to 10 Years</i>				
Yuasa				
Battery	1	NP7-12	Sealed Lead Acid	11/20/2014
Edwards				
Beam Detector	1			08/23/2012
Heat Detector	11	283B	Fixed Temperature	08/23/2012
Smoke Detector	3	SIGA2-PS	Photoelectric	08/23/2012
EST				
CO Detector	2	SIGA2-COS		08/23/2012
Control Panel	1	3X-SFS1R		08/23/2012
Duct Detector	5	SIGA-SD	Photoelectric	08/23/2012
Heat Detector	2	SIGA2-H/S	Fixed Temperature	08/23/2012
Heat Detector	7	SIGA2-PD		08/23/2012
Pull Station	1	278	Dual Action	08/23/2012
Pull Station	1	SPO-270	Dual Action	08/23/2012
Pull Station	2	SPO-270	Single Action	08/23/2012
Pull Station	13	SPO-278	Dual Action	08/23/2012

Pull Station	2	SPO-278	Single Action	08/23/2012
Smoke Detector	64	SIGA2-PS	Photoelectric	08/23/2012

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Newfield School			Control Panel: 1 - EST 3X-SFS1R	
<i>The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.</i>				
Address	Device Type	Location	Type	ScanID
Zone/Circuit: 00				
	Control Panel	1st Main Office		44890297
Zone/Circuit: 02				
0000	Heat Detector	1st Southwest Stage	Fixed Temperature	20667129
0080	CO Detector	1st kitchen entrance		44890396
Zone/Circuit: 03				
0000	Heat Detector	Basement Boiler	Fixed Temperature	04061016
0000	Heat Detector	Basement Boiler	Fixed Temperature	44890361
0000	Heat Detector	Basement Storage	Fixed Temperature	44890363
0000	Heat Detector	1st North Storage by Room 302	Fixed Temperature	20667116
0005	Smoke Detector	1st by door to custodian dock	Photoelectric	44890358
0006	Smoke Detector	1st area between 100-400	Photoelectric	44890364
0007	Smoke Detector	1st by room 401	Photoelectric	44890371
0008	Smoke Detector	1st by room 404	Photoelectric	44890384
0009	Smoke Detector	1st by Room 405	Photoelectric	44890386
0010	Smoke Detector	1st by room 406	Photoelectric	44890387
0016	Smoke Detector	1st hall by room 321	Photoelectric	44890347
0017	Smoke Detector	1st by room 318	Photoelectric	44890348
0018	Smoke Detector	1st by room 316	Photoelectric	44890349
0019	Smoke Detector	1st by room 314	Photoelectric	44890350
0020	Smoke Detector	1st by room 312	Photoelectric	44890351
0021	Smoke Detector	1st by Room 310	Photoelectric	44890352
0022	Smoke Detector	1st by room 308	Photoelectric	44890353
0023	Smoke Detector	1st by room 306	Photoelectric	44890354
0024	Smoke Detector	1st 300 hall by girls bathroom	Photoelectric	44890355
0025	Smoke Detector	1st Storage Room Across from 302	Photoelectric	3915833589
0026	Smoke Detector	1st 300 hall by staff lounge	Photoelectric	44890356
0027	Smoke Detector	1st start of 300 wing	Photoelectric	44890357
0028	Smoke Detector	1st hallway by p.e office	Photoelectric	44890345
0029	Smoke Detector	1st hall by room 106	Photoelectric	44890342
0030	Smoke Detector	1st hall by room 105	Photoelectric	44890341
0031	Smoke Detector	1st Hall by room 104	Photoelectric	44890340
0032	Smoke Detector	1st media center computer room	Photoelectric	44890390
0033	Smoke Detector	1st media center office	Photoelectric	44890391
0034	Smoke Detector	1st sd 2 media office	Photoelectric	44890329
0035	Smoke Detector	1st sd 1 media centerlibrary	Photoelectric	44890331
0036	Smoke Detector	1st sd 2 media centerlibrary	Photoelectric	44890330
0037	Smoke Detector	1st sd 3 media centerlibrary	Photoelectric	44890333
0038	Smoke Detector	1st media center instruction 504	Photoelectric	44890336
0039	Smoke Detector	1st sd 4 media centerlibrary	Photoelectric	44890332

0040	Smoke Detector	1st main lobby in front of media center	Photoelectric	44890337
0041	Smoke Detector	1st front main lobby doors	Photoelectric	44890338
0042	Smoke Detector	1st p office	Photoelectric	44890392
0043	Smoke Detector	1st Main office room	Photoelectric	44890299
0044	Smoke Detector	1st sd hallway by main office confrence room	Photoelectric	44890328
0045	Smoke Detector	1st Sd main office front area	Photoelectric	44890304
0046	Smoke Detector	1st sd hallway by main office entrance	Photoelectric	44890327
0047	Smoke Detector	1st nurses office by main office	Photoelectric	44890305
0048	Smoke Detector	1st sd hall by main & nurses office	Photoelectric	44890324
0049	Smoke Detector	1st sd hall by main storage	Photoelectric	44890323
0050	Smoke Detector	1st Auditorium stage right	Photoelectric	04060976
0051	Smoke Detector	1st Audotorium stage middle	Photoelectric	04060975
0052	Smoke Detector	1st sd hall by room 216	Photoelectric	44890315
0053	Smoke Detector	1st sd hallway by room 214	Photoelectric	44890316
0054	Smoke Detector	1st sd hallway by room 212	Photoelectric	44890317
0055	Smoke Detector	1st sd hallway by room 212b	Photoelectric	44890318
0056	Smoke Detector	1st sd hall by Room 208	Photoelectric	44890319
0057	Smoke Detector	1st sd hall by room 200	Photoelectric	44890320
0058	Smoke Detector	1st sd hall by room 204	Photoelectric	44890321
0059	Smoke Detector	1st sd hall by storage	Photoelectric	44890322
0060	Smoke Detector	1st sd hall by courtyard leading to room 202	Photoelectric	44890311
0061	Smoke Detector	1st sd hall by courtyard rm 202	Photoelectric	44890310
0062	Smoke Detector	1st hallway by 202	Photoelectric	44890309
0063	Smoke Detector	1st hallway by room 202 & 201	Photoelectric	44890308
0064	Smoke Detector	1st corridoor by room 201	Photoelectric	44890307
0065	Smoke Detector	1st room 405	Photoelectric	44890385
0066	Smoke Detector	1st room 406	Photoelectric	44890389
0067	Smoke Detector	1st room 404	Photoelectric	44890381
0068	Smoke Detector	1st room 404	Photoelectric	44890383
0069	Smoke Detector	1st room 403	Photoelectric	44890380
0070	Smoke Detector	1st room 403	Photoelectric	44890378
0071	Smoke Detector	1st room 402	Photoelectric	44890375
0072	Smoke Detector	1st room 402	Photoelectric	44890376
0073	Smoke Detector	1st room 401	Photoelectric	44890373
0074	Smoke Detector	1st room 401	Photoelectric	44890372
0085	Smoke Detector	1st Auditorium stage left	Photoelectric	04060974
0086	CO Detector	Basement Boiler Room Above Stairs		55052769
0089	Smoke Detector	Basement by exit	Photoelectric	44890362
0091	Heat Detector	Basement Boiler Room Right side Back		55052775
0092	Heat Detector	Basement Boiler Room Right side Front		55052776
0093	Heat Detector	Basement Boiler Room Middle Back		55052774
0094	Heat Detector	Basement Boiler Room Middle Front		55052772
0097	Heat Detector	Basement Boiler Room Above Stairs		55052770
0105	Heat Detector	Basement Boiler Room Left Side Front		55052771
0106	Heat Detector	Basement Boiler Room Left Side Back		55052773
0128	Pull Station	1st west media center exit Pull	Dual Action	44890335
0129	Pull Station	1st by exit end of 200 wing	Dual Action	44890312
0130	Pull Station	1st main lobby entrance	Dual Action	44890339
0131	Pull Station	1st stage left lower	Single Action	44890325
0132	Pull Station	1st Stage left upper	Dual Action	44890326
0133	Pull Station	1st Exit in front of room 201	Dual Action	44890306

0134	Pull Station	1st Pull east media center exit	Dual Action	44890334
0137	Pull Station	1st exit by kitchen side	Dual Action	44890343
0138	Pull Station	1st exit by lobby side	Dual Action	44890344
0140	Pull Station	1st by door to custodian dock	Single Action	44890359
0141	Pull Station	1st by exit end of 300 wing	Dual Action	44890346
0142	Pull Station	1st exit by r/h side	Dual Action	44890365
0143	Pull Station	1st exit room 401	Dual Action	44890374
0144	Pull Station	1st exit room 402	Single Action	44890377
0145	Pull Station	1st exit room 403	Dual Action	44890379
0146	Pull Station	1st exit room 404	Dual Action	44890382
0147	Pull Station	1st exit by l/h side	Dual Action	44890366
0148	Pull Station	1st exit by room 406	Dual Action	44890388
0149	Pull Station	1st exit from custodian area	Single Action	44890360
Zone/Circuit: 04				
0000	Heat Detector	1st Northwest Gym	Fixed Temperature	20667130
0000	Heat Detector	1st Northwest Gym	Fixed Temperature	20667131
0000	Heat Detector	1st Northwest Gym	Fixed Temperature	20667120
0000	Heat Detector	1st Northwest Gym	Fixed Temperature	20667121
0000	Heat Detector	1st Northwest Gym	Fixed Temperature	20667122
0000	Heat Detector	1st Northwest Gym	Fixed Temperature	20667123
0000	Heat Detector	1st Northwest Kitchen	Fixed Temperature	44890397
0000	Heat Detector	1st Northwest Kitchen	Fixed Temperature	44890398
0000	Duct Detector	1st Northwest by P.E. Office DD1 (Local)	Photoelectric	44890395
Zone/Circuit: 05				
0000	Beam Detector	1st Media Center		44890401
Zone/Circuit: 08				
0000	Duct Detector	1st South by Room 210B DD4	Photoelectric	44890399
0000	Duct Detector	1st South by Room 210B DD5	Photoelectric	44890400
Zone/Circuit: 18				
0000	Duct Detector	1st Northwest by Room 310 DD2	Photoelectric	44890394
0000	Duct Detector	1st Northwest by Room 312 DD3	Photoelectric	44890393

Fire Alarm and Life Safety System Inspection Certificate

For

Northeast Elementary Annex
82 Scofieldtown Road
Stamford, CT 06904

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Apr 7, 2020

Building: Northeast Elementary Annex
Contact: Davor Lucaj
Title: Facilities Trades Manager


Company: TPC Associates, Inc.
Contact: Dave Majewski
Title: Inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Northeast Elementary Annex	Contact: Davor Lucaj	
Address: 82 Scofieldtown Road	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06904	Mobile: 347-675-6021	
Country: null	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Dave Majewski	
Address: 261 Pepe's Farm Road	Phone: 203-666-9587	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: null	Email: dave.majewski@tpcsystems.com	
System Control Unit		
Manufacturer:	Inspection Date: 04/07/2020	IDC Style:
Model Number:	Install Date: 03/24/2014	SLC Style:
Software Version:	Version Date: 03/25/2014	NAC Style:
Location: By rear door	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type: Digital Communicator	Mfg: Fire Watch	Model #: 411UDAC
Test Time/Date: 4/7/20 9:09:42 AM	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	4	25.00%	4	100.00%	4	100.00%	0	0%
Initiating	12	75.00%	12	100.00%	12	100.00%	0	0%
Totals	16	100%	16	100.00%	16	100.00%	0	0%

Certification	
<p>Company: TPC Associates, Inc.</p> <p>Inspector: Dave Majewski</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px 0;">  </div> <p>Signed: Apr 7, 2020 9:12:36 AM</p>	<p>Building: Northeast Elementary Annex</p> <p>Contact: Davor Lucaj</p> <p>Signed:</p>

Inspection & Testing

Generated by: BuildingReports.com

Building: Northeast Elementary Annex		Control Panel: 1 -		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Battery	By electrical panels	Tested	9:11:17 AM	04/07/2020
Battery	FACP	Tested	9:11:55 AM	04/07/2020
Communicator	By electrical panels	Visually Checked	9:09:42 AM	04/07/2020
Control Panel	By rear door	Tested	9:09:47 AM	04/07/2020
Initiating				
Heat Detector	Area above bathroom	Visually Checked	9:10:00 AM	04/07/2020
Heat Detector	Area by panel	Visually Checked	9:12:15 AM	04/07/2020
Heat Detector	Front room	Visually Checked	9:10:46 AM	04/07/2020
Heat Detector	Front room	Visually Checked	9:10:53 AM	04/07/2020
Heat Detector	Garage front	Visually Checked	9:12:02 AM	04/07/2020
Heat Detector	Garage rear	Visually Checked	9:12:06 AM	04/07/2020
Heat Detector	Office	Visually Checked	9:12:10 AM	04/07/2020
Heat Detector	Storage between restrooms	Visually Checked	9:10:10 AM	04/07/2020
Pull Station	By rear exit by FACP	Visually Checked	9:09:52 AM	04/07/2020
Pull Station	Front door	Visually Checked	9:11:59 AM	04/07/2020
Smoke Detector	Area by panel	Visually Checked	9:09:55 AM	04/07/2020
Smoke Detector	Front room	Visually Checked	9:10:05 AM	04/07/2020

Service Summary

Generated by: BuildingReports.com

Building: Northeast Elementary Annex

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Passed</i>		
Battery	Tested	2
Communicator	Visually Checked	1
Control Panel	Tested	1
Heat Detector	Visually Checked	8
Pull Station	Visually Checked	2
Smoke Detector	Visually Checked	2
Total		16
Grand Total		16

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Northeast Elementary Annex				Control Panel: 1 -			
<i>The Battery & Power Supply Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Battery							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Sealed Lead Acid	By electrical panels	8	12	12.65V	7.3Ah		
Sealed Lead Acid	FACP	8	12	12.85V	6.5Ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Northeast Elementary Annex				Control Panel: 1 -
<p><i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Device or Type		Category	% of Inventory	Quantity
Communicator		Control	6.25%	1
Control Panel		Control	6.25%	1
Pull Station		Initiating	12.50%	2
Smoke Detector		Initiating	12.50%	2
Heat Detector		Initiating	50.00%	8
Battery		Control	12.50%	2
Type	Qty	Model #	Description	Install Date
<i>In Service - 5 Years to 10 Years</i>				
Control Panel	1			03/24/2014
EST				
Heat Detector	8	283b-PL		03/24/2014
Smoke Detector	1	2251	Ionization	03/24/2014
Smoke Detector	1	EC30U	Ionization	03/24/2014
Fire Watch				
Communicator	1	411UDAC	Digital Communicator	03/24/2014
Gamewell				
Pull Station	2	M46-3	Single Action	03/24/2014
Universal				
Battery	2	UB1280	Sealed Lead Acid	03/24/2014

Zone Address Report

Generated by: BuildingReports.com

Building: Northeast Elementary Annex			Control Panel: 1 -	
<i>The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.</i>				
Address	Device Type	Location	Type	ScanID
Zone/Circuit: 0				
	Battery	By electrical panels	Sealed Lead Acid	16323610
	Communicator	By electrical panels	Digital Communicator	16323600
	Battery	FACP	Sealed Lead Acid	16323611
Zone/Circuit: 1				
	Heat Detector	Area above bathroom		16323605
	Heat Detector	Area by panel		51385736
	Smoke Detector	Area by panel	Ionization	16323603
	Heat Detector	Front room		16323608
	Heat Detector	Front room		16323609
	Smoke Detector	Front room	Ionization	16323606
	Heat Detector	Garage front		16323613
	Heat Detector	Garage rear		16323614
	Heat Detector	Office		16323615
	Heat Detector	Storage between restrooms		16323607
Zone/Circuit: 2				
	Pull Station	By rear exit by FACP	Single Action	16323602
	Pull Station	Front door	Single Action	16323612

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Northeast
Elementary
82 Scofieldtown Road
Stamford, CT 06904

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Apr 7, 2020



Building: Stamford BOE-Northeast Elementary
Contact: Davor Lucaj
Title: Facilities Trades Manager

Company: TPC Associates, Inc.
Contact: Dave Majewski
Title: Inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Northeast Elementary	Contact: Davor Lucaj	
Address: 82 Scofieldtown Road	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06904	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Dave Majewski	
Address: 261 Pepe's Farm Road	Phone: 203-666-9587	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: dave.majewski@tpcsystems.com	
System Control Unit		
Manufacturer: Silent Knight	Inspection Date: 04/07/2020	IDC Style:
Model Number: ECS-RCU2000	Install Date: 11/17/2017	SLC Style:
Software Version:	Version Date: 08/07/2012	NAC Style:
Location: Ground left gym	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.68%	0	0%	0	0%	0	0%
Control	8	5.44%	8	100.00%	8	100.00%	0	0%
Initiating	138	93.88%	138	100.00%	138	100.00%	0	0%
Totals	147	100%	146	99.32%	146	100.00%	0	0%
Certification								
Company: TPC Associates, Inc.				Building: Stamford BOE-Northeast Elementary				
Inspector: Dave Majewski				Contact: Davor Lucaj				
								
Signed: Apr 7, 2020 9:09:19 AM				Signed: Apr 7, 2020 9:09:02 AM				

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Northeast Elementary		Control Panel: 1 - Silent Knight ECS-RCU2000		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Annunciator	1st main entrance	Visually Checked	7:49:00 AM	04/07/2020
Annunciator	1st Main Office	Visually Checked	8:20:32 AM	04/07/2020
Annunciator	Ground custodian office	Visually Checked	8:25:53 AM	04/07/2020
Battery	Ground main fire panel	Tested	8:41:20 AM	04/07/2020
Battery	Ground main fire panel	Tested	8:46:37 AM	04/07/2020
Control Panel	Ground left gym	Visually Checked	7:59:40 AM	04/07/2020
Control Panel	Ground right gym	Visually Checked	7:59:54 AM	04/07/2020
Initiating				
Duct Detector	1st Computer Lab Media	Visually Checked	8:20:20 AM	04/07/2020
Duct Detector	1st Corridor AHU 1 By 137	Visually Checked	8:20:05 AM	04/07/2020
Duct Detector	1st Corridor AHU 1 By 137	Visually Checked	8:20:09 AM	04/07/2020
Duct Detector	1st Main Office AHU 1	Visually Checked	8:20:23 AM	04/07/2020
Duct Detector	1st Main Office Closet	Visually Checked	8:19:29 AM	04/07/2020
Duct Detector	1st Main Office Closet	Visually Checked	8:19:33 AM	04/07/2020
Duct Detector	1st Main Office Closet	Visually Checked	8:20:26 AM	04/07/2020
Duct Detector	1st Mechanical AHU 2	Visually Checked	8:19:44 AM	04/07/2020
Duct Detector	1st Mechanical AHU 2	Visually Checked	8:19:50 AM	04/07/2020
Duct Detector	1st Teachers Work Rm Media	Visually Checked	8:20:16 AM	04/07/2020
Heat Detector	1st Mechanical	Visually Checked	8:20:13 AM	04/07/2020
Heat Detector	1st Portable Boys Bathroom	Visually Checked	8:19:40 AM	04/07/2020
Heat Detector	1st Portable Girls Bathroom	Visually Checked	8:19:37 AM	04/07/2020
Heat Detector	Ground boiler room	Visually Checked	8:01:08 AM	04/07/2020
Heat Detector	Ground boiler room	Visually Checked	8:25:38 AM	04/07/2020
Heat Detector	Ground boiler room	Visually Checked	8:25:41 AM	04/07/2020
Heat Detector	Ground boiler room	Visually Checked	8:25:44 AM	04/07/2020
Heat Detector	Ground boiler room	Visually Checked	8:25:48 AM	04/07/2020
Heat Detector	Ground garage	Visually Checked	8:25:04 AM	04/07/2020
Heat Detector	Ground kiln room	Visually Checked	8:24:20 AM	04/07/2020
Pull Station	1st Auditorium Entrance	Visually Checked	8:23:58 AM	04/07/2020
Pull Station	1st by 131	Visually Checked	8:20:57 AM	04/07/2020
Pull Station	1st by library exit	Visually Checked	8:22:07 AM	04/07/2020
Pull Station	1st Corridor by .computer lab	Visually Checked	8:22:04 AM	04/07/2020
Pull Station	1st Corridor by 106	Visually Checked	8:21:57 AM	04/07/2020
Pull Station	1st Corridor by 108	Visually Checked	8:21:39 AM	04/07/2020
Pull Station	1st Corridor by 125	Visually Checked	8:20:44 AM	04/07/2020
Pull Station	1st Corridor by 136	Visually Checked	8:20:54 AM	04/07/2020
Pull Station	1st Corridor by 1st grade 115	Visually Checked	8:22:36 AM	04/07/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	1st Corridor by art 102	Visually Checked	8:21:53 AM	04/07/2020
Pull Station	1st Corridor by k1 special education	Visually Checked	8:22:46 AM	04/07/2020
Pull Station	1st Corridor by media center	Visually Checked	8:22:00 AM	04/07/2020
Pull Station	1st Corridor by men's toilet	Visually Checked	8:23:33 AM	04/07/2020
Pull Station	1st Corridor by music room 166	Visually Checked	8:23:39 AM	04/07/2020
Pull Station	1st Corridor by stair 2	Visually Checked	8:20:39 AM	04/07/2020
Pull Station	1st Corridor by stair s1	Visually Checked	8:23:46 AM	04/07/2020
Pull Station	1st Corridor mech room	Visually Checked	8:20:36 AM	04/07/2020
Pull Station	1st Corridor to special education/music wing	Visually Checked	8:22:50 AM	04/07/2020
Pull Station	1st front stage left	Visually Checked	8:21:14 AM	04/07/2020
Pull Station	1st front stage right	Visually Checked	8:21:17 AM	04/07/2020
Pull Station	1st main entrance	Visually Checked	8:21:07 AM	04/07/2020
Pull Station	1st main entrance by auditorium	Visually Checked	8:21:04 AM	04/07/2020
Pull Station	1st rear stage left exit	Visually Checked	8:21:25 AM	04/07/2020
Pull Station	1st rear stage right exit	Visually Checked	8:21:20 AM	04/07/2020
Pull Station	1st special education 164	Visually Checked	8:23:03 AM	04/07/2020
Pull Station	1st special education 165	Visually Checked	8:22:57 AM	04/07/2020
Pull Station	1st Across From Cafe	Visually Checked	8:20:01 AM	04/07/2020
Pull Station	Ground Boiler Room 203	Visually Checked	8:26:45 AM	04/07/2020
Pull Station	Ground Corridor by 5th grade 225	Visually Checked	8:26:26 AM	04/07/2020
Pull Station	Ground Corridor by 5th grade 228	Visually Checked	8:25:58 AM	04/07/2020
Pull Station	Ground Corridor by stair s2	Visually Checked	8:26:30 AM	04/07/2020
Pull Station	Ground gym entrance	Visually Checked	8:25:19 AM	04/07/2020
Pull Station	Ground gym entrance	Visually Checked	8:25:22 AM	04/07/2020
Pull Station	Ground gym rear exit left	Visually Checked	8:25:26 AM	04/07/2020
Pull Station	Ground gym rear exit right	Visually Checked	8:25:31 AM	04/07/2020
Pull Station	Ground gym side exit eft	Visually Checked	8:25:12 AM	04/07/2020
Pull Station	Ground gym side exit right	Visually Checked	8:25:15 AM	04/07/2020
Pull Station	Ground Near dry storage	Visually Checked	8:26:34 AM	04/07/2020
Pull Station	Ground Stair S1	Visually Checked	8:26:53 AM	04/07/2020
Smoke Detector	1st .nurses office	Visually Checked	8:21:46 AM	04/07/2020
Smoke Detector	1st .nurses office	Visually Checked	8:22:19 AM	04/07/2020
Smoke Detector	1st by 137	Visually Checked	7:45:58 AM	04/07/2020
Smoke Detector	1st by 138	Visually Checked	7:46:17 AM	04/07/2020
Smoke Detector	1st by girls restroom	Visually Checked	7:42:45 AM	04/07/2020
Smoke Detector	1st by nurses office	Visually Checked	8:22:22 AM	04/07/2020
Smoke Detector	1st by room 121	Visually Checked	7:52:23 AM	04/07/2020
Smoke Detector	1st by room 124	Visually Checked	7:52:07 AM	04/07/2020
Smoke Detector	1st by room 129	Visually Checked	7:49:56 AM	04/07/2020
Smoke Detector	1st by room IUB	Visually Checked	7:51:40 AM	04/07/2020
Smoke Detector	1st by stage right entrance	Visually Checked	7:43:13 AM	04/07/2020
Smoke Detector	1st by stair 3	Visually Checked	7:51:12 AM	04/07/2020
Smoke Detector	1st Corridor By Mechanical	Visually Checked	8:19:54 AM	04/07/2020
Smoke Detector	1st corridor by 105	Visually Checked	8:22:15 AM	04/07/2020
Smoke Detector	1st corridor by 106	Visually Checked	8:22:12 AM	04/07/2020
Smoke Detector	1st corridor by 107	Visually Checked	8:21:42 AM	04/07/2020
Smoke Detector	1st corridor by 109	Visually Checked	8:21:35 AM	04/07/2020
Smoke Detector	1st corridor by 110	Visually Checked	8:21:32 AM	04/07/2020
Smoke Detector	1st corridor by 135	Visually Checked	7:48:00 AM	04/07/2020
Smoke Detector	1st corridor by 1st grade 115	Visually Checked	8:22:33 AM	04/07/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Corridor by 1st grade 115	Visually Checked	8:22:40 AM	04/07/2020
Smoke Detector	1st corridor by front office	Visually Checked	7:48:41 AM	04/07/2020
Smoke Detector	1st corridor by front office	Visually Checked	7:49:30 AM	04/07/2020
Smoke Detector	1st Corridor by men's toilet	Visually Checked	8:23:23 AM	04/07/2020
Smoke Detector	1st Corridor by music room 165	Visually Checked	8:23:14 AM	04/07/2020
Smoke Detector	1st Corridor by music room 166	Visually Checked	8:23:43 AM	04/07/2020
Smoke Detector	1st corridor by nurses office	Visually Checked	8:21:49 AM	04/07/2020
Smoke Detector	1st corridor by reading 119	Visually Checked	8:22:26 AM	04/07/2020
Smoke Detector	1st Corridor by special education 111	Visually Checked	8:22:43 AM	04/07/2020
Smoke Detector	1st corridor by special education 163	Visually Checked	8:22:53 AM	04/07/2020
Smoke Detector	1st Corridor by special education 164	Visually Checked	8:23:26 AM	04/07/2020
Smoke Detector	1st corridor by stage right exit	Visually Checked	7:47:40 AM	04/07/2020
Smoke Detector	1st Corridor by stair s1	Visually Checked	7:46:35 AM	04/07/2020
Smoke Detector	1st corridor by teachers lounge	Visually Checked	7:48:13 AM	04/07/2020
Smoke Detector	1st corridor to special education/music wing	Visually Checked	8:07:38 AM	04/07/2020
Smoke Detector	1st corridor to special education/music wing	Visually Checked	8:07:51 AM	04/07/2020
Smoke Detector	1st corridor to special education/music wing	Visually Checked	8:08:00 AM	04/07/2020
Smoke Detector	1st in stage storage	Visually Checked	7:47:06 AM	04/07/2020
Smoke Detector	1st Main corridor center	Visually Checked	8:23:06 AM	04/07/2020
Smoke Detector	1st main office closet	Visually Checked	8:22:29 AM	04/07/2020
Smoke Detector	1st mech room left	Visually Checked	8:05:17 AM	04/07/2020
Smoke Detector	1st mech room right	Visually Checked	8:05:14 AM	04/07/2020
Smoke Detector	1st Men's toilet	Visually Checked	8:23:36 AM	04/07/2020
Smoke Detector	1st mid stage left	Visually Checked	8:23:50 AM	04/07/2020
Smoke Detector	1st mid stage right	Visually Checked	8:23:54 AM	04/07/2020
Smoke Detector	1st music room 165	Visually Checked	8:21:28 AM	04/07/2020
Smoke Detector	1st Music Room 166	Visually Checked	8:23:19 AM	04/07/2020
Smoke Detector	1st room 131	Visually Checked	8:21:00 AM	04/07/2020
Smoke Detector	1st room IUB	Visually Checked	8:20:50 AM	04/07/2020
Smoke Detector	1st special education 163	Visually Checked	8:23:00 AM	04/07/2020
Smoke Detector	1st special education 163	Visually Checked	8:23:30 AM	04/07/2020
Smoke Detector	1st teachers lounge	Visually Checked	8:21:10 AM	04/07/2020
Smoke Detector	1st top of stair 2	Visually Checked	7:52:39 AM	04/07/2020
Smoke Detector	1st top of stair 3	Visually Checked	7:50:20 AM	04/07/2020
Smoke Detector	1st Women's toilet	Visually Checked	8:23:10 AM	04/07/2020
Smoke Detector	Ground Corridor by 5th grade 224	Visually Checked	7:54:15 AM	04/07/2020
Smoke Detector	Ground Corridor by 5th grade 225	Visually Checked	7:54:33 AM	04/07/2020
Smoke Detector	Ground Corridor by custodian 210	Visually Checked	8:26:37 AM	04/07/2020
Smoke Detector	Ground Corridor by special education 232	Visually Checked	7:54:58 AM	04/07/2020
Smoke Detector	Ground Corridor by stair s1	Visually Checked	8:00:52 AM	04/07/2020
Smoke Detector	Ground Corridor by stair s2	Visually Checked	7:53:27 AM	04/07/2020
Smoke Detector	Ground Corridor by storage 206	Visually Checked	8:26:49 AM	04/07/2020
Smoke Detector	Ground Corridor by toilets	Visually Checked	7:56:22 AM	04/07/2020
Smoke Detector	Ground Custodian Office	Visually Checked	8:26:02 AM	04/07/2020
Smoke Detector	Ground gym storage	Visually Checked	8:25:34 AM	04/07/2020
Smoke Detector	Ground left gym front left device	Visually Checked	8:24:48 AM	04/07/2020
Smoke Detector	Ground left gym front right device	Visually Checked	8:24:52 AM	04/07/2020
Smoke Detector	Ground left gym rear left device	Visually Checked	8:24:41 AM	04/07/2020
Smoke Detector	Ground left gym rear right device	Visually Checked	8:24:45 AM	04/07/2020
Smoke Detector	Ground paper storage	Visually Checked	8:24:56 AM	04/07/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Ground paper storage	Visually Checked	8:24:59 AM	04/07/2020
Smoke Detector	Ground right gym front left device	Visually Checked	8:24:30 AM	04/07/2020
Smoke Detector	Ground right gym front right device	Visually Checked	8:24:25 AM	04/07/2020
Smoke Detector	Ground right gym rear left device	Visually Checked	8:24:34 AM	04/07/2020
Smoke Detector	Ground right gym rear right device	Visually Checked	8:24:37 AM	04/07/2020
Smoke Detector	Ground sprinkler storage	Visually Checked	8:25:08 AM	04/07/2020
Smoke Detector	Ground Storage 1	Visually Checked	8:26:06 AM	04/07/2020
Smoke Detector	Ground Storage 1	Visually Checked	8:26:20 AM	04/07/2020
Smoke Detector	Ground Table Storage	Visually Checked	8:26:41 AM	04/07/2020

Building: Stamford BOE-Northeast Elementary		Control Panel: 2 - Silent Knight IFP-2000ECS		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
<i>Passed</i>				
Control				
Control Panel	Ground panel room	Tested	8:50:22 AM	04/07/2020

Service Summary

Generated by: BuildingReports.com




Building: Stamford BOE-Northeast Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Passed</i>		
Annunciator	Visually Checked	3
Battery	Tested	2
Control Panel	Tested	1
Control Panel	Visually Checked	2
Duct Detector	Visually Checked	10
Heat Detector	Visually Checked	10
Pull Station	Visually Checked	39
Smoke Detector	Visually Checked	79
Total		146
Grand Total		146

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Northeast Elementary							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		◀ dB	◀ dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
Whole Building				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Northeast Elementary				Control Panel: 1 - Silent Knight ECS-RCU2000			
<i>The Battery & Power Supply Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Battery							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Sealed Lead Acid	Ground main fire panel	18	12	13.21V	23Ah		
Sealed Lead Acid	Ground main fire panel	18	12	13.18V	26Ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Northeast Elementary	Control Panel: 1 - Silent Knight ECS-RCU2000
--	---

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type	Category	% of Inventory	Quantity
Sound Test	Sound Test	0.68%	1
Smoke Detector	Initiating	53.74%	79
Annunciator	Control	2.04%	3
Control Panel	Control	2.04%	3
Heat Detector	Initiating	6.80%	10
Duct Detector	Initiating	6.80%	10
Pull Station	Initiating	26.53%	39
Battery	Control	1.36%	2

Type	Qty	Model #	Description	Install Date
<i>In Service - 2 Years to 3 Years</i>				
Power-Sonic				
Battery	2	PS-12180 NB	Sealed Lead Acid	11/17/2017
Silent Knight				
Control Panel	2	ECS-RCU2000		11/17/2017
<i>In Service - 5 Years to 10 Years</i>				
EST				
Smoke Detector	1	2551F	Photoelectric	08/08/2012
Duct Detector	10	2551F	Photoelectric	08/07/2012
Heat Detector	1	283B	Fixed Temperature	08/07/2012
Heat Detector	1	5251F	Fixed Temperature	08/07/2012
Heat Detector	1	5251FB	Fixed Temperature	08/07/2012
Pull Station	1	SIGA-270	Single Action	08/07/2012
Silent Knight				
Annunciator	3	RA2000	LCD Display	08/07/2012
Heat Detector	7	IDP-ROR	Rate-of-Rise	08/07/2012
Pull Station	38	IDP-PULL	Single Action	08/07/2012
Smoke Detector	78	IFP-Photo	Photoelectric	08/07/2012

Building: Stamford BOE-Northeast Elementary	Control Panel: 2 - Silent Knight IFP-2000ECS
--	---

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Type	Qty	Model #	Description	Install Date
------	-----	---------	-------------	--------------

	y			
<i>In Service - 2 Years to 3 Years</i>				
Silent Knight				
Control Panel	1	IFP-2000ECS		11/17/2017

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Northeast Elementary Control Panel: 1 - Silent Knight
ECS-RCU2000

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 97				
1	Pull Station	Ground Stair S1	Single Action	47370802
1	Smoke Detector	Ground Storage 1	Photoelectric	47370780
1	Smoke Detector	Ground left gym front left device	Photoelectric	47370663
1	Smoke Detector	Ground left gym front right device	Photoelectric	47370664
1	Smoke Detector	Ground left gym rear left device	Photoelectric	47370662
1	Smoke Detector	Ground left gym rear right device	Photoelectric	47370661
1	Smoke Detector	Ground right gym front left device	Photoelectric	47370658
1	Smoke Detector	Ground right gym front right device	Photoelectric	47370657
1	Smoke Detector	Ground right gym rear left device	Photoelectric	47370659
1	Smoke Detector	Ground right gym rear right device	Photoelectric	47370660
2	Pull Station	Ground Boiler Room 203	Single Action	47370796
2	Smoke Detector	Ground Storage 1	Photoelectric	47370786
2	Heat Detector	Ground kiln room	Rate-of-Rise	20666644
03	Pull Station	Ground gym rear exit left	Single Action	47370675
3	Smoke Detector	Ground Corridor by storage 206	Photoelectric	47370797
03	Heat Detector	Ground garage	Rate-of-Rise	47370669
04	Pull Station	Ground gym rear exit right	Single Action	47370676
04	Smoke Detector	Ground gym storage	Photoelectric	47370677
04	Smoke Detector	Ground sprinkler storage	Photoelectric	47370670
05	Pull Station	Ground gym entrance	Single Action	47370674
5	Smoke Detector	Ground Corridor by stair s1	Photoelectric	47370801
06	Pull Station	Ground gym entrance	Single Action	47370673
06	Heat Detector	Ground boiler room	Rate-of-Rise	47370678
06	Heat Detector	Ground boiler room	Rate-of-Rise	47370682
07	Pull Station	Ground gym side exit eft	Single Action	47370671
07	Heat Detector	Ground boiler room	Rate-of-Rise	47370679
07	Heat Detector	Ground boiler room	Rate-of-Rise	47370681
08	Pull Station	Ground gym side exit right	Single Action	47370672
08	Heat Detector	Ground boiler room	Rate-of-Rise	47370680
08	Smoke Detector	Ground paper storage	Photoelectric	47370666
9	Pull Station	Ground Corridor by stair s2	Single Action	47370792
09	Smoke Detector	Ground paper storage	Photoelectric	47370667
10	Pull Station	Ground Corridor by 5th grade 225	Single Action	47370791
11	Pull Station	Ground Corridor by 5th grade 228	Single Action	47370778
11	Smoke Detector	Ground Custodian Office	Photoelectric	47370779
12	Pull Station	1st Auditorium Entrance	Single Action	51385735
12	Pull Station	1st Corridor by music room 166	Single Action	47370773
13	Pull Station	1st Corridor by men's toilet	Single Action	47370771
14	Pull Station	1st special education 164	Single Action	47370763

15	Pull Station	1st special education 165	Single Action	47370761
16	Pull Station	1st Corridor to special education/music wing	Single Action	47370755
17	Pull Station	1st Corridor by k1 special education	Single Action	47370754
18	Pull Station	1st Corridor by 1st grade 115	Single Action	47370751
20	Pull Station	1st front stage left	Single Action	47370715
20	Smoke Detector	Ground Table Storage	Photoelectric	47370795
21	Pull Station	1st rear stage left exit	Single Action	47370721
21	Smoke Detector	Ground Corridor by custodian 210	Photoelectric	47370794
22	Pull Station	1st Corridor by stair s1	Single Action	47370775
23	Pull Station	1st rear stage right exit	Single Action	47370718
24	Pull Station	1st front stage right	Single Action	47370716
27	Pull Station	1st Corridor mech room	Single Action	47370690
27	Smoke Detector	Ground Corridor by stair s2	Photoelectric	47370787
28	Pull Station	1st Corridor by stair 2	Single Action	47370694
28	Smoke Detector	Ground Corridor by 5th grade 224	Photoelectric	47370788
29	Pull Station	1st Corridor by 125	Single Action	47370699
29	Smoke Detector	Ground Corridor by 5th grade 225	Photoelectric	47370789
30	Pull Station	1st Corridor by 136	Single Action	47370702
31	Pull Station	1st by 131	Single Action	47370705
31	Smoke Detector	Ground Corridor by special education 232	Photoelectric	47370790
32	Pull Station	1st main entrance by auditorium	Single Action	47370708
32	Smoke Detector	Ground Corridor by toilets	Photoelectric	47370777
34	Pull Station	1st main entrance	Single Action	47370709
36	Pull Station	1st Corridor by art 102	Single Action	47370730
37	Pull Station	1st Corridor by 108	Single Action	47370726
38	Pull Station	1st Corridor by 106	Single Action	47370731
39	Pull Station	1st Corridor by media center	Single Action	47370732
40	Smoke Detector	1st Music Room 166	Photoelectric	47370767
41	Pull Station	1st by library exit	Single Action	47370734
41	Smoke Detector	1st Corridor by music room 166	Photoelectric	47370774
42	Smoke Detector	1st Corridor by music room 165	Photoelectric	47370766
43	Pull Station	1st Corridor by .computer lab	Single Action	47370733
43	Smoke Detector	1st music room 165	Photoelectric	47370723
44	Smoke Detector	1st Corridor by men's toilet	Photoelectric	47370768
44	Pull Station	Ground Near dry storage	Single Action	47370793
45	Smoke Detector	1st Men's toilet	Photoelectric	47370772
46	Smoke Detector	1st Women's toilet	Photoelectric	47370765
47	Smoke Detector	1st Main corridor center	Photoelectric	47370764
48	Smoke Detector	1st Corridor by special education 164	Photoelectric	47370770
49	Smoke Detector	1st special education 163	Photoelectric	47370769
50	Smoke Detector	1st special education 163	Photoelectric	47370762
51	Smoke Detector	1st corridor by special education 163	Photoelectric	47370760
52	Smoke Detector	1st corridor to special education/music wing	Photoelectric	47370759
53	Smoke Detector	1st corridor to special education/music wing	Photoelectric	47370757
54	Smoke Detector	1st corridor to special education/music wing	Photoelectric	47370756
55	Smoke Detector	1st Corridor by special education 111	Photoelectric	47370753
56	Smoke Detector	1st corridor by 110	Photoelectric	47370724
57	Smoke Detector	1st Corridor by 1st grade 115	Photoelectric	47370752

58	Smoke Detector	1st corridor by 1st grade 115	Photoelectric	47370750
59	Smoke Detector	1st corridor by reading 119	Photoelectric	47370749
60	Smoke Detector	1st in stage storage	Photoelectric	47370722
60	Smoke Detector	1st mid stage left	Photoelectric	51385733
60	Smoke Detector	1st mid stage right	Photoelectric	51385734
61	Smoke Detector	1st corridor by 135	Photoelectric	47370713
62	Smoke Detector	1st teachers lounge	Photoelectric	47370712
63	Smoke Detector	1st corridor by teachers lounge	Photoelectric	47370711
66	Smoke Detector	1st corridor by stage right exit	Photoelectric	47370717
67	Smoke Detector	1st Corridor by stair s1	Photoelectric	47370776
68	Smoke Detector	1st by 138	Photoelectric	47370687
69	Smoke Detector	1st by 137	Photoelectric	47370688
72	Smoke Detector	1st by stage right entrance	Photoelectric	47370689
75	Smoke Detector	1st mech room right	Photoelectric	47370691
76	Smoke Detector	1st mech room left	Photoelectric	47370692
79	Smoke Detector	1st by girls restroom	Photoelectric	47370693
80	Smoke Detector	1st by room 121	Photoelectric	47370696
81	Smoke Detector	1st top of stair 2	Photoelectric	47370695
82	Smoke Detector	1st by room 124	Photoelectric	47370697
83	Smoke Detector	1st by room IUB	Photoelectric	47370698
84	Smoke Detector	1st room IUB	Photoelectric	47370700
85	Smoke Detector	1st by stair 3	Photoelectric	47370701
86	Smoke Detector	1st top of stair 3	Photoelectric	47370703
87	Smoke Detector	1st by room 129	Photoelectric	47370704
88	Smoke Detector	1st corridor by front office	Photoelectric	47370707
89	Smoke Detector	1st room 131	Photoelectric	47370706
92	Smoke Detector	1st by nurses office	Photoelectric	47370739
93	Smoke Detector	1st .nurses office	Photoelectric	47370738
94	Smoke Detector	1st .nurses office	Photoelectric	47370728
95	Smoke Detector	1st corridor by nurses office	Photoelectric	47370729
96	Smoke Detector	1st corridor by 105	Photoelectric	47370737
97	Smoke Detector	1st corridor by 109	Photoelectric	47370725
98	Smoke Detector	1st corridor by 107	Photoelectric	47370727
99	Smoke Detector	1st corridor by 106	Photoelectric	47370736
102	Smoke Detector	1st corridor by front office	Photoelectric	47370710
103	Smoke Detector	1st main office closet	Photoelectric	47370740
128	Smoke Detector	1st Corridor By Mechanical	Photoelectric	04060916
132	Duct Detector	1st Corridor AHU 1 By 137	Photoelectric	04060947
133	Duct Detector	1st Corridor AHU 1 By 137	Photoelectric	04060946
134	Duct Detector	1st Mechanical AHU 2	Photoelectric	04060913
135	Duct Detector	1st Mechanical AHU 2	Photoelectric	04060912
206	Pull Station	1st Across From Cafe	Single Action	04060935
218	Heat Detector	1st Mechanical	Fixed Temperature	20666627
306	Duct Detector	1st Main Office Closet	Photoelectric	20666643
325	Duct Detector	1st Main Office AHU 1	Photoelectric	20666642
334	Duct Detector	1st Main Office Closet	Photoelectric	04060866
335	Duct Detector	1st Main Office Closet	Photoelectric	04060867
346	Heat Detector	1st Portable Boys Bathroom	Fixed Temperature	04060894
347	Heat Detector	1st Portable Girls Bathroom	Fixed Temperature	04060888
383	Duct Detector	1st Teachers Work Rm Media	Photoelectric	20666639
385	Duct Detector	1st Computer Lab Media	Photoelectric	20666640

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Strawberry Hill
School
200 Strawberry Hill Avenue
Stamford, CT 06902

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date

-

Building: Stamford BOE-Strawberry Hill School
Contact: Davor Lucaj
Title: Facility Contact

Company: TPC Associates, Inc.
Contact: Jordan Feher
Title: Fire alarm inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Strawberry Hill School		Contact: Davor Lucaj
Address: 200 Strawberry Hill Avenue		Phone: 203-977-6668
Address:		Fax:
City/State/Zip: Stamford, CT 06902		Mobile: 347-675-6021
Country: United States of America		Email:
Inspection Performed By		
Company: TPC Associates, Inc.		Inspector: Jordan Feher
Address: 261 Pepe's Farm Road		Phone: (203)878-1321
Address:		Fax:
City/State/Zip: Milford, Connecticut 06460		Mobile:
Country: United States of America		Email: jordan.feher@tpcsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date:	IDC Style:
Model Number: 5820XL	Install Date: 09/30/2017	SLC Style:
Software Version:	Version Date: 09/30/2017	NAC Style:
Location: 1st Main Office F.A.C.P	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.52%	0	0%	0	0%	0	0%
Control	2	1.03%	0	0%	0	0%	0	0%
Initiating	191	98.45%	0	0%	0	0%	0	0%
Totals	194	100%	0	0%	0	0%	0	0%
Certification								
Company: TPC Associates, Inc.				Building: Stamford BOE–Strawberry Hill School				
Inspector: Jordan Feher				Contact: Davor Lucaj				
Signed:				Signed:				

Notes & Recommendations

Generated by: BuildingReports.com

Building: Stamford BOE-Strawberry Hill School

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

General Note

under construction, no devices or fire cable. 4/8/20 -JF

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Strawberry Hill School		Control Panel: 1 - Silent Knight 5820XL		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
<i>Untested</i>				
Control				
Control Panel	1st Main Office F.A.C.P			

**Building: Stamford BOE-Strawberry Hill
School**

Control Panel: 2

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
Untested				
Control				
Battery	1st Main Office Below Panel			
Initiating				
Heat Detector	1st 114A Center Smoke			
Heat Detector	1st 114A Left Smoke			
Heat Detector	1st 114A Right Smoke			
Pull Station	1st Stair A Exit			
Pull Station	1st Stair A Upper Exit			
Pull Station	3rd Stair A			
Pull Station	3rd Stair C			
Pull Station	4th Stair A			
Pull Station	4th Stair C			
Smoke Detector	1st Electrical Room 105C			
Smoke Detector	1st Closet South 117			
Smoke Detector	1st Hall			
Smoke Detector	1st Hall			
Smoke Detector	1st Hall South			
Smoke Detector	1st Principal Office 103			
Smoke Detector	1st Reception			
Smoke Detector	1st Room 102			
Smoke Detector	1st Room 116 Men/Women's Toilet			
Smoke Detector	1st Staff Room			
Smoke Detector	1st Stair A			
Smoke Detector	1st Stair B			
Smoke Detector	3rd Bathroom By 307			
Smoke Detector	3rd Girl's Bathroom			
Smoke Detector	3rd Hall North By Stair C			
Smoke Detector	3rd Hall By 303			
Smoke Detector	3rd Hall By Room 301			
Smoke Detector	3rd Hall By Room 309			
Smoke Detector	3rd Hall By Room 310			
Smoke Detector	3rd Hall South By Stair A			
Smoke Detector	3rd Men's & Women's Bathroom			
Smoke Detector	3rd Room 301			
Smoke Detector	3rd Room 302			
Smoke Detector	3rd Room 303			
Smoke Detector	3rd Room 305 Men's Toilet			
Smoke Detector	3rd Room 306			
Smoke Detector	3rd Room 307			
Smoke Detector	3rd Room 309			
Smoke Detector	3rd Room 310			
Smoke Detector	3rd Room 322 Closet			
Smoke Detector	3rd Stair A			

Device Type	Location	Service	Time	Date
<i>Untested</i>				
Smoke Detector	3rd Stair A 3 & 4			
Smoke Detector	3rd Stair B			
Smoke Detector	3rd Stair B 2 & 3			
Smoke Detector	3rd Stair C			
Smoke Detector	4th Boy's Bathroom			
Smoke Detector	4th Girl's Bathroom			
Smoke Detector	4th Hall By Room 402			
Smoke Detector	4th Hall By Room 403			
Smoke Detector	4th Hall By Room 404			
Smoke Detector	4th Hall North By Room 405			
Smoke Detector	4th Hall South By Stair A			
Smoke Detector	4th Room 401			
Smoke Detector	4th Room 402			
Smoke Detector	4th Room 403			
Smoke Detector	4th Room 404			
Smoke Detector	4th Room 405			
Smoke Detector	4th Room 406			
Smoke Detector	4th Room 407			
Smoke Detector	4th Room 422 Closet			
Smoke Detector	4th Stair A			
Smoke Detector	4th Stair B			
Smoke Detector	4th Stair B 3 & 4			
Smoke Detector	4th Stair C			
Smoke Detector	4th Stair C 3 & 4			
Smoke Detector	4th Women's Bathroom			
Smoke Detector	Attic Dead End			
Smoke Detector	Attic Stair B			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			
Smoke Detector	Attic			

**Building: Stamford BOE-Strawberry Hill
School**

Control Panel: 33

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
Untested				
Initiating				
Pull Station	1st Hall North			
Pull Station	1st Hall North By Room 138			
Pull Station	1st Kindergarten Hall East Entrance			
Pull Station	1st Kindergarten Hall West Entrance			
Pull Station	1st Room 136 Kindergarten A Right By Exit			
Pull Station	1st Stair B Exit			
Pull Station	1st Stair D			
Pull Station	1st Stair D Kindergarten Hall			
Pull Station	1st Stair D North			
Pull Station	2nd Entrance			
Pull Station	2nd Stair A By Room 201			
Pull Station	2nd Stair C			
Pull Station	2nd Stair D Auditorium/Gym Exit By Stage			
Pull Station	2nd Stair D Gym/Cafe Exit			
Smoke Detector	1st Boy's Bathroom			
Smoke Detector	1st Conference room			
Smoke Detector	1st Girl's Bathroom			
Smoke Detector	1st Hall			
Smoke Detector	1st Hall North			
Smoke Detector	1st Kindergarten Hall			
Smoke Detector	1st Kindergarten Hall			
Smoke Detector	1st Kindergarten Hall			
Smoke Detector	1st Kindergarten Hall			
Smoke Detector	1st Kindergarten Hall By Room 133			
Smoke Detector	1st Kindergarten Hall Boy's Bathroom			
Smoke Detector	1st Kindergarten Hall By Bathrooms			
Smoke Detector	1st Kindergarten Hall Girl's Bathroom			
Smoke Detector	1st Room 106 in 107, Nurse Closet			
Smoke Detector	1st Room 107 Nurse			
Smoke Detector	1st Room 108 Literacy			
Smoke Detector	1st Room 112 PT/OT			
Smoke Detector	1st Room 112 PT/OT			
Smoke Detector	1st Room 112A in Room 112 PT/OT			
Smoke Detector	1st Room 113 Special Ed			
Smoke Detector	1st Room 127 Kindergarten A Left			
Smoke Detector	1st Room 133 Kindergarten Left			
Smoke Detector	1st Room 133 Kindergarten Right			
Smoke Detector	1st Room 134 Kindergarten Left			
Smoke Detector	1st Room 134 Kindergarten Right			
Smoke Detector	1st Room 135 Kindergarten A Left			
Smoke Detector	1st Room 135 Kindergarten A Right			
Smoke Detector	1st Room 136 Kindergarten A Left			

[illegible]

Device Type	Location	Service	Time	Date
<i>Untested</i>				
Smoke Detector	2nd Room 222 Closet			
Smoke Detector	2nd Room 223 ALT Toilet Gym			
Smoke Detector	2nd Room 224			
Smoke Detector	2nd Room 231			
Smoke Detector	2nd Room 239 Gym Platform			
Smoke Detector	2nd Room 239 Gym Platform			
Smoke Detector	2nd Room 239 Gym Platform			
Smoke Detector	2nd Room 239 Gym Platform			
Smoke Detector	2nd Room 239 Gym Platform			
Smoke Detector	2nd Room 239 Gym Platform			
Smoke Detector	2nd Room 239 Gym Platform			
Smoke Detector	2nd Room 239 Gym Platform			
Smoke Detector	2nd Room 249 Machine Room			
Smoke Detector	2nd Stair A			
Smoke Detector	2nd Stair B			
Smoke Detector	2nd Stair D At Gym Doors			
Smoke Detector	2nd Stair D At Gym Doors			

Service Summary

Generated by: BuildingReports.com




Building: Stamford BOE-Strawberry Hill School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Untested</i>		
Battery		1
Control Panel		1
Heat Detector		3
Pull Station		20
Smoke Detector		168
Total		193
Grand Total		193

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Strawberry Hill School							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		◀ dB	◀ dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
Whole Facility				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Strawberry Hill School				Control Panel: 2			
<i>The Battery & Power Supply Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Battery							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Untested							
Sealed Lead Acid	1st Main Office Below Panel	55AH	12V				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Strawberry Hill School	Control Panel: 1 - Silent Knight 5820XL
---	---

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type	Category	% of Inventory	Quantity
Smoke Detector	Initiating	86.60%	168
Heat Detector	Initiating	1.55%	3
Pull Station	Initiating	10.31%	20
Control Panel	Control	0.52%	1
Battery	Control	0.52%	1
Sound Test	Sound Test	0.52%	1

Type	Qty	Model #	Description	Install Date
------	-----	---------	-------------	--------------

In Service - 2 Years to 3 Years

Silent Knight

Control Panel	1	5820XL		09/30/2017
---------------	---	--------	--	------------

Building: Stamford BOE-Strawberry Hill School	Control Panel: 2
---	------------------

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Type	Qty	Model #	Description	Install Date
------	-----	---------	-------------	--------------

In Service - 2 Years to 3 Years

Silent Knight

Heat Detector	3			09/30/2017
Pull Station	6	PS-DA	Single Action	09/30/2017
Smoke Detector	73		Photoelectric	09/30/2017

In Service - 3 Years to 5 Years

Power-Sonic

Battery	1	PS-12550 U	Sealed Lead Acid	06/15/2016
---------	---	------------	------------------	------------

Building: Stamford BOE-Strawberry Hill School	Control Panel: 33
---	-------------------

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Type	Qty	Model #	Description	Install Date
------	-----	---------	-------------	--------------

	y			
<i>In Service - 2 Years to 3 Years</i>				
Silent Knight				
Pull Station	1		Single Action	09/30/2017
Pull Station	13	PS-DA	Single Action	09/30/2017
Smoke Detector	95		Photoelectric	09/30/2017

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Strawberry Hill School			Control Panel: 1 - Silent Knight 5820XL	
<i>The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.</i>				
Address	Device Type	Location	Type	ScanID
00	Control Panel	1st Main Office F.A.C.P		47371076

**Building: Stamford BOE-Strawberry Hill
School**

Control Panel: 2

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
00	Battery	1st Main Office Below Panel	Sealed Lead Acid	47371077
01	Smoke Detector	3rd Room 302	Photoelectric	47371026
02	Smoke Detector	3rd Room 301	Photoelectric	47370114
03	Smoke Detector	3rd Hall South By Stair A	Photoelectric	47371029
04	Smoke Detector	3rd Stair A	Photoelectric	47371033
05	Smoke Detector	3rd Hall By Room 301	Photoelectric	47371027
06	Smoke Detector	3rd Hall By Room 310	Photoelectric	47371025
07	Smoke Detector	3rd Room 322 Closet	Photoelectric	47371031
08	Smoke Detector	3rd Girl's Bathroom	Photoelectric	47371032
09	Smoke Detector	3rd Room 310	Photoelectric	47371024
10	Smoke Detector	3rd Stair B 2 & 3	Photoelectric	47371023
11	Smoke Detector	3rd Stair B	Photoelectric	47371022
12	Smoke Detector	3rd Hall By 303	Photoelectric	47371019
13	Smoke Detector	3rd Hall By Room 309	Photoelectric	47371016
14	Smoke Detector	3rd Room 309	Photoelectric	47371017
15	Smoke Detector	3rd Bathroom By 307	Photoelectric	47371014
16	Smoke Detector	3rd Men's & Women's Bathroom	Photoelectric	47371015
17	Smoke Detector	3rd Hall North By Stair C	Photoelectric	47371012
18	Smoke Detector	3rd Stair C	Photoelectric	47371010
19	Smoke Detector	3rd Room 307	Photoelectric	47371013
20	Smoke Detector	3rd Room 306	Photoelectric	47371018
21	Smoke Detector	3rd Room 305 Men's Toilet	Photoelectric	47371020
23	Smoke Detector	3rd Room 303	Photoelectric	47371021
24	Smoke Detector	4th Room 403	Photoelectric	47371045
25	Smoke Detector	4th Room 402	Photoelectric	47371041
26	Smoke Detector	4th Room 401	Photoelectric	47371038
27	Smoke Detector	3rd Stair A 3 & 4	Photoelectric	47371034
28	Smoke Detector	4th Stair A	Photoelectric	47371035
29	Smoke Detector	4th Hall South By Stair A	Photoelectric	47371037
30	Smoke Detector	4th Hall By Room 402	Photoelectric	47371042
31	Smoke Detector	4th Room 422 Closet	Photoelectric	47371040
32	Smoke Detector	4th Boy's Bathroom	Photoelectric	47371039
33	Smoke Detector	4th Room 407	Photoelectric	47371043
34	Smoke Detector	4th Hall By Room 403	Photoelectric	47371044
35	Smoke Detector	4th Hall By Room 404	Photoelectric	47371049
36	Smoke Detector	4th Room 404	Photoelectric	47371048
37	Smoke Detector	4th Room 405	Photoelectric	47371055
38	Smoke Detector	4th Hall North By Room 405	Photoelectric	47371053
40	Smoke Detector	4th Women's Bathroom	Photoelectric	47371051
41	Smoke Detector	4th Girl's Bathroom	Photoelectric	47371052
42	Smoke Detector	4th Room 406	Photoelectric	47371050
43	Smoke Detector	4th Stair B	Photoelectric	47371046
44	Smoke Detector	4th Stair B 3 & 4	Photoelectric	47371047
45	Smoke Detector	Attic Stair B	Photoelectric	47371058
46	Smoke Detector	Attic	Photoelectric	47371059
47	Smoke Detector	Attic	Photoelectric	47371060

48	Smoke Detector	Attic	Photoelectric	47371061
49	Smoke Detector	Attic	Photoelectric	47371066
50	Smoke Detector	Attic	Photoelectric	47371067
51	Smoke Detector	Attic	Photoelectric	47371074
52	Smoke Detector	Attic	Photoelectric	47371073
53	Smoke Detector	Attic	Photoelectric	47371072
54	Smoke Detector	Attic	Photoelectric	47371070
55	Smoke Detector	Attic	Photoelectric	47371071
56	Smoke Detector	Attic	Photoelectric	47371069
57	Smoke Detector	Attic	Photoelectric	47371068
58	Smoke Detector	Attic	Photoelectric	47371065
59	Smoke Detector	Attic	Photoelectric	47371064
60	Smoke Detector	Attic	Photoelectric	47371063
61	Smoke Detector	Attic Dead End	Photoelectric	47371062
62	Smoke Detector	4th Stair C	Photoelectric	47371056
63	Smoke Detector	1st Electrical Room 105C	Photoelectric	47371075
64	Smoke Detector	1st Reception	Photoelectric	47370885
65	Smoke Detector	1st Principal Office 103	Photoelectric	47370887
66	Smoke Detector	1st Room 102	Photoelectric	47370892
67	Smoke Detector	1st Staff Room	Photoelectric	47370888
68	Smoke Detector	1st Hall	Photoelectric	47370891
69	Smoke Detector	1st Hall South	Photoelectric	47370889
70	Smoke Detector	1st Stair A	Photoelectric	47370982
72	Smoke Detector	1st Room 116 Men/Women's Toilet	Photoelectric	47370979
73	Smoke Detector	1st Closet South 117	Photoelectric	47370890
74	Heat Detector	1st 114A Left Smoke		47370893
75	Smoke Detector	1st Stair B	Photoelectric	47370897
76	Smoke Detector	1st Hall	Photoelectric	47370896
77	Heat Detector	1st 114A Center Smoke		47370894
78	Heat Detector	1st 114A Right Smoke		47370895
79	Smoke Detector	4th Stair C 3 & 4	Photoelectric	47371057
101	Pull Station	3rd Stair A	Single Action	47371030
102	Pull Station	3rd Stair C	Single Action	47371011
103	Pull Station	4th Stair A	Single Action	47371036
104	Pull Station	4th Stair C	Single Action	47371054
111	Pull Station	1st Stair A Upper Exit	Single Action	47370981
112	Pull Station	1st Stair A Exit	Single Action	47370980

**Building: Stamford BOE-Strawberry Hill
School**

Control Panel: 33

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
01	Smoke Detector	2nd Hall South By Stair A	Photoelectric	47370986
02	Smoke Detector	2nd Stair A	Photoelectric	47370984
03	Smoke Detector	1st Stair A 1 & 2	Photoelectric	47370983
04	Smoke Detector	2nd Room 201 1st Grade C	Photoelectric	47370987
05	Smoke Detector	2nd Room 202	Photoelectric	47370993
06	Smoke Detector	2nd Hall By Room 202	Photoelectric	47370991
07	Smoke Detector	2nd Hall By Room 204A	Photoelectric	47370999
08	Smoke Detector	2nd Entrance Lobby	Photoelectric	47370998
09	Smoke Detector	2nd Entrance	Photoelectric	47370997
10	Smoke Detector	1st Kindergarten Hall By Room 133	Photoelectric	47370937
11	Smoke Detector	1st Stair D	Photoelectric	47370938
12	Smoke Detector	1st Stair E	Photoelectric	47370939
13	Smoke Detector	1st Stair B Mech Room	Photoelectric	47370898
14	Smoke Detector	1st Stair B Mech Room	Photoelectric	47370899
17	Smoke Detector	1st Room 113 Special Ed	Photoelectric	47370900
18	Smoke Detector	1st Room 112 PT/OT	Photoelectric	47370903
19	Smoke Detector	1st Room 112 PT/OT	Photoelectric	47370904
20	Smoke Detector	1st Room 112A in Room 112 PT/OT	Photoelectric	47370905
21	Smoke Detector	1st Boy's Bathroom	Photoelectric	47370908
22	Smoke Detector	1st Girl's Bathroom	Photoelectric	47370907
23	Smoke Detector	1st Hall	Photoelectric	47370906
24	Smoke Detector	1st Room 106 in 107, Nurse Closet	Photoelectric	47370902
25	Smoke Detector	1st Conference room	Photoelectric	47370886
26	Smoke Detector	1st Room 107 Nurse	Photoelectric	47370901
27	Smoke Detector	1st Room 108 Literacy	Photoelectric	47370911
28	Smoke Detector	1st Hall North	Photoelectric	47370909
29	Smoke Detector	1st Stair C	Photoelectric	47370912
30	Smoke Detector	1st Stair C Closet	Photoelectric	47370913
31	Smoke Detector	1st Kindergarten Hall	Photoelectric	47370914
32	Smoke Detector	1st Kindergarten Hall	Photoelectric	47370918
33	Smoke Detector	1st Kindergarten Hall	Photoelectric	47370920
34	Smoke Detector	1st Kindergarten Hall	Photoelectric	47370928
35	Smoke Detector	1st Room 138 Kindergarten Hall	Photoelectric	47370919
36	Smoke Detector	1st Kindergarten Hall By Bathrooms	Photoelectric	47370931
37	Smoke Detector	1st Room 242 Closet Kindergarten Hall	Photoelectric	47370936
38	Smoke Detector	1st Kindergarten Hall Girl's Bathroom	Photoelectric	47370930
39	Smoke Detector	1st Kindergarten Hall Boy's Bathroom	Photoelectric	47370929
40	Smoke Detector	1st Stair D Lower Landing Closet	Photoelectric	47370945
41	Smoke Detector	1st Stair D Lower Landing Room 120 Staff Toilet	Photoelectric	47370943
42	Smoke Detector	1st Stair D Lower Landing	Photoelectric	47370942
43	Smoke Detector	2nd Stair D At Gym Doors	Photoelectric	47370946
44	Smoke Detector	2nd Stair D At Gym Doors	Photoelectric	47370947
46	Smoke Detector	1st Room 133 Kindergarten Left	Photoelectric	47370934
47	Smoke Detector	1st Room 133 Kindergarten Right	Photoelectric	47370935
48	Smoke Detector	1st Room 134 Kindergarten Right	Photoelectric	47370933

49	Smoke Detector	1st Room 134 Kindergarten Left	Photoelectric	47370932
50	Smoke Detector	1st Room 135 Kindergarten A Left	Photoelectric	47370927
51	Smoke Detector	1st Room 135 Kindergarten A Right	Photoelectric	47370926
52	Smoke Detector	1st Room 136 Kindergarten A Right By Exit	Photoelectric	47370924
53	Smoke Detector	1st Room 136 Kindergarten A Left	Photoelectric	47370923
54	Smoke Detector	1st Room 137 Kindergarten A Right	Photoelectric	47370921
55	Smoke Detector	1st Room 127 Kindergarten A Left	Photoelectric	47370922
56	Smoke Detector	2nd Room 249 Machine Room	Photoelectric	47370977
57	Smoke Detector	2nd Room 239 Gym Platform	Photoelectric	47370976
58	Smoke Detector	2nd Room 239 Gym Platform	Photoelectric	47370951
59	Smoke Detector	2nd Room 239 Gym Platform	Photoelectric	47370950
60	Smoke Detector	2nd Room 239 Gym Platform	Photoelectric	47370949
61	Smoke Detector	2nd Room 239 Gym Platform	Photoelectric	47370948
62	Smoke Detector	2nd Room 224	Photoelectric	47370978
63	Smoke Detector	2nd Room 239 Gym Platform	Photoelectric	47370975
64	Smoke Detector	2nd Room 239 Gym Platform	Photoelectric	47370974
65	Smoke Detector	2nd Room 239 Gym Platform	Photoelectric	47370952
66	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370957
67	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370958
68	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370965
69	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370966
70	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370967
71	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370964
72	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370959
73	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370956
74	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370955
75	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370960
76	Smoke Detector	2nd Room 223 ALT Toilet Gym	Photoelectric	47370973
77	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370963
78	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370968
79	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370969
80	Smoke Detector	2nd Room 231	Photoelectric	47370953
81	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370962
82	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370961
83	Smoke Detector	2nd Room 215 Auditorium/Gym	Photoelectric	47370954
84	Smoke Detector	2nd Stair C 2 & 3	Photoelectric	47371009
85	Smoke Detector	1st Stair C 1 & 2	Photoelectric	47371008
86	Smoke Detector	2nd Hall By Stair C	Photoelectric	47371005
87	Smoke Detector	2nd Room 205	Photoelectric	47371006
88	Smoke Detector	2nd Room 204A	Photoelectric	47371000
89	Smoke Detector	2nd Hall By Room 208	Photoelectric	47371002
90	Smoke Detector	2nd Room 206 Women's Toilet	Photoelectric	47371003
91	Smoke Detector	2nd Girl's Bathroom By Room 205	Photoelectric	47371004
92	Smoke Detector	2nd Room 208	Photoelectric	47371001
94	Smoke Detector	1st Stair B 1 & 2	Photoelectric	47370995
95	Smoke Detector	2nd Stair B	Photoelectric	47370994
96	Smoke Detector	2nd Room 209	Photoelectric	47370992
97	Smoke Detector	2nd Boy's Bathroom	Photoelectric	47370988
98	Smoke Detector	2nd Room 222 Closet	Photoelectric	47370989
99	Smoke Detector	2nd Hall By Room 222	Photoelectric	47370990
100	Pull Station	1st Room 136 Kindergarten A Right By Exit	Single Action	47370925

106	Pull Station	1st Hall North	Single Action	47370910
107	Pull Station	1st Kindergarten Hall East Entrance	Single Action	47370915
108	Pull Station	1st Kindergarten Hall West Entrance	Single Action	47370916
109	Pull Station	1st Hall North By Room 138	Single Action	47370917
110	Pull Station	1st Stair D Kindergarten Hall	Single Action	47370944
111	Pull Station	1st Stair D	Single Action	47370941
112	Pull Station	1st Stair D North	Single Action	47370940
115	Pull Station	2nd Stair D Gym/Cafe Exit	Single Action	47370971
116	Pull Station	2nd Stair D Auditorium/Gym Exit By Stage	Single Action	47370972
118	Pull Station	2nd Stair C	Single Action	47371007
119	Pull Station	1st Stair B Exit	Single Action	47370970
120	Pull Station	2nd Stair A By Room 201	Single Action	47370985
121	Pull Station	2nd Entrance	Single Action	47370996

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Rogers School
202 Blachley Rd
Stamford, CT 06902

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Mar 25, 2020

Building: Stamford BOE-Rogers School
Contact: Davor Lucaj
Title: Facilities Trades Manager



Company: TPC Associates, Inc.
Contact: Jordan Feher
Title: Fire alarm inspector

Executive Summary

Generated by: BuildingReports.com





Building Information		
Building: Stamford BOE-Rogers School		Contact: Davor Lucaj
Address: 202 Blachley Rd		Phone: 203-977-6668
Address:		Fax:
City/State/Zip: Stamford, CT 06902		Mobile: 347-675-6021
Country: United States of America		Email: dlucaj@stamfordct.gov
Inspection Performed By		
Company: TPC Associates, Inc.		Inspector: Jordan Feher
Address: 261 Pepe's Farm Road		Phone: (203)878-1321
Address:		Fax:
City/State/Zip: Milford, Connecticut 06460		Mobile:
Country: United States of America		Email: jordan.feher@tpcsystems.com
System Control Unit		
Manufacturer: EST	Inspection Date: 03/25/2020	IDC Style:
Model Number: EST-2	Install Date: 08/07/2012	SLC Style:
Software Version:	Version Date: 08/07/2012	NAC Style:
Location: 1st reception office	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type: Digital Communicator	Mfg: EST	Model #: 411UD
Test Time/Date: 3/25/20 1:05:27 PM	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	1.02%	0	0%	0	0%	0	0%
Control	23	23.47%	23	100.00%	22	95.65%	1	4.35%
Initiating	74	75.51%	74	100.00%	74	100.00%	0	0%
Totals	98	100%	97	98.98%	96	98.97%	1	1.03%

Certification	
<p>Company: TPC Associates, Inc.</p> <p>Inspector: Jordan Feher</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px 0;">  </div> <p>Signed: Mar 25, 2020 2:50:35 PM</p>	<p>Building: Stamford BOE-Rogers School</p> <p>Contact: Davor Lucaj</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px 0;">  </div> <p>Signed: Mar 25, 2020 2:51:49 PM</p>

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-Rogers School		Control Panel: 1 - EST EST-2		
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
 ScanID	 Location	 Problem	Address	 Reference
<i>Control</i>				
Battery				
48218873	1st Data Room 122 (Booster #3)	Failed Test	1	NFPA 72 Table 10.4.2.2.5(a-e)

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-Rogers School			Control Panel: 1 - EST EST-2		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
Control					
Battery					
48218873	1st Data Room 122 (Booster #3)	Replace	WB1280	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Rogers School		Control Panel: 1 - EST EST-2		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Annunciator	1st Main Entrance Lobby	Tested	2:21:06 PM	03/25/2020
Battery	1st Data Room 122 (Booster #2)	Tested	2:01:44 PM	03/25/2020
Battery	1st Data Room 122 (Booster #2)	Tested	2:04:07 PM	03/25/2020
Battery	1st Data Room 122 (Booster #4)	Tested	1:54:44 PM	03/25/2020
Battery	1st Main office/reception Booster below FACP	Tested	1:06:01 PM	03/25/2020
Battery	1st Main office/reception inside FACP	Tested	1:07:45 PM	03/25/2020
Battery	1st Office Storage (Booster #1)	Tested	1:25:59 PM	03/25/2020
Battery	1st Office Storage (Booster #2)	Tested	1:26:49 PM	03/25/2020
Battery	1st Office Storage (Booster #3)	Tested	1:27:03 PM	03/25/2020
Battery	1st Office Storage (Booster #4)	Tested	1:27:27 PM	03/25/2020
Battery	2nd Room 218 (Center Booster)	Tested	1:32:42 PM	03/25/2020
Battery	2nd Room 218 (Left Booster)	Tested	1:33:32 PM	03/25/2020
Battery	2nd Room 218 (Right Booster)	Tested	1:31:37 PM	03/25/2020
Communicator	1st Main office Main panel EST2 Office	Tested	1:05:27 PM	03/25/2020
Control Panel	1st reception office	Tested	1:05:22 PM	03/25/2020
Power Supply	1st Office Storage (Booster #1)	Visually Checked	2:48:16 PM	03/25/2020
Power Supply	1st Office Storage (Booster #2)	Visually Checked	2:48:10 PM	03/25/2020
Power Supply	1st Office Storage (Booster #3)	Visually Checked	2:47:57 PM	03/25/2020
Power Supply	1st Office Storage (Booster #3)	Visually Checked	2:48:04 PM	03/25/2020
Power Supply	2nd Room 218 (Center Booster)	Visually Checked	2:47:44 PM	03/25/2020
Power Supply	2nd Room 218 (Left Booster)	Visually Checked	2:47:37 PM	03/25/2020
Power Supply	2nd Room 218 (Right Booster)	Visually Checked	2:47:51 PM	03/25/2020
Initiating				
Duct Detector	Basement AHU 1 Fan room Return	Visually Checked	2:49:14 PM	03/25/2020
Duct Detector	Basement AHU 1 Fan room Supply	Visually Checked	2:48:59 PM	03/25/2020
Duct Detector	Basement AHU 1 Fan room Outside air	Visually Checked	2:49:07 PM	03/25/2020
Duct Detector	Basement AHU 2 Fan room Return	Visually Checked	2:48:43 PM	03/25/2020
Duct Detector	Basement AHU 2 Fan room Return	Visually Checked	2:48:55 PM	03/25/2020
Duct Detector	Basement AHU 2 Fan room Supply	Visually Checked	2:48:49 PM	03/25/2020
Duct Detector	Penthouse AHU 1 Fan room Return	Visually Checked	2:49:22 PM	03/25/2020
Duct Detector	Penthouse AHU 3 Fan room Return above reception/office	Visually Checked	2:49:58 PM	03/25/2020
Duct Detector	Penthouse AHU 3 Fan room Supply above reception/office	Visually Checked	2:49:51 PM	03/25/2020
Duct Detector	Penthouse AHU 4 Fan room Return above reception/office	Visually Checked	2:50:24 PM	03/25/2020
Duct Detector	Penthouse AHU 4 Fan room Supply above reception/office	Visually Checked	2:50:05 PM	03/25/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Duct Detector	Penthouse AHU 5 Fan room Return above reception/office	Visually Checked	2:50:18 PM	03/25/2020
Duct Detector	Penthouse AHU 5 Fan room Supply above reception/office	Visually Checked	2:50:11 PM	03/25/2020
Duct Detector	Penthouse AHU 6 Fan room Return above reception/office	Visually Checked	2:49:37 PM	03/25/2020
Duct Detector	Penthouse AHU 6 Fan room Supply above reception/office	Visually Checked	2:49:44 PM	03/25/2020
Duct Detector	Penthouse AHU 7 Fan room Return above reception/office	Visually Checked	2:49:30 PM	03/25/2020
Heat Detector	1st Elevator machine room	Visually Checked	2:40:34 PM	03/25/2020
Pull Station	Basement by stair 3 Fan room	Visually Checked	2:39:42 PM	03/25/2020
Pull Station	Basement rear by double door exit	Visually Checked	2:39:38 PM	03/25/2020
Pull Station	1st Corr C108 By loading dock exit	Visually Checked	2:40:30 PM	03/25/2020
Pull Station	1st East Corridor by entrance /stair 1	Visually Checked	2:40:59 PM	03/25/2020
Pull Station	1st East Corridor C104 by 115 by basement stair	Visually Checked	2:41:03 PM	03/25/2020
Pull Station	1st in stair 1	Visually Checked	2:41:21 PM	03/25/2020
Pull Station	1st North by stair 8	Visually Checked	2:41:47 PM	03/25/2020
Pull Station	1st North Corridor C106 across from rm 125	Visually Checked	2:40:46 PM	03/25/2020
Pull Station	1st North Entrance vestibule lobby	Visually Checked	2:39:53 PM	03/25/2020
Pull Station	1st Northeast auditorium	Visually Checked	2:41:39 PM	03/25/2020
Pull Station	1st Northeast Gym	Visually Checked	2:39:59 PM	03/25/2020
Pull Station	1st Northwest Cafeteria 142	Visually Checked	2:40:25 PM	03/25/2020
Pull Station	1st Northwest Gym	Visually Checked	2:40:09 PM	03/25/2020
Pull Station	1st South Corridor C1075 outside library	Visually Checked	2:40:42 PM	03/25/2020
Pull Station	1st South Entrance vestibule lobby	Visually Checked	2:39:56 PM	03/25/2020
Pull Station	1st Southeast auditorium	Visually Checked	2:41:44 PM	03/25/2020
Pull Station	1st Southeast Cafeteria 142	Visually Checked	2:40:21 PM	03/25/2020
Pull Station	1st Southeast Corridor outside Gym	Visually Checked	2:40:17 PM	03/25/2020
Pull Station	1st Southeast Gym	Visually Checked	2:40:06 PM	03/25/2020
Pull Station	1st Southwest auditorium	Visually Checked	2:41:35 PM	03/25/2020
Pull Station	1st Southwest Bottom of ramp auditorium	Visually Checked	2:41:31 PM	03/25/2020
Pull Station	1st Southwest Gym	Visually Checked	2:40:13 PM	03/25/2020
Pull Station	1st Southwest Stair 6 by stair 6	Visually Checked	2:41:17 PM	03/25/2020
Pull Station	1st West Corridor C104 by 117	Visually Checked	2:41:07 PM	03/25/2020
Pull Station	1st Corridor by 155/162	Visually Checked	2:41:25 PM	03/25/2020
Pull Station	1st Exit Stair 5	Visually Checked	2:41:10 PM	03/25/2020
Pull Station	1st Hallway to stair 5	Visually Checked	2:41:14 PM	03/25/2020
Pull Station	1st Media center exit	Visually Checked	2:40:50 PM	03/25/2020
Pull Station	1st Stairwell to Basement	Visually Checked	2:40:55 PM	03/25/2020
Pull Station	2nd by stair 5 Corridor C208	Visually Checked	2:41:55 PM	03/25/2020
Pull Station	2nd Southwest Corridor by stair 6	Visually Checked	2:41:51 PM	03/25/2020
Pull Station	2nd Corridor By Stair 1	Visually Checked	2:41:59 PM	03/25/2020
Pull Station	3rd Top stair 8	Visually Checked	2:42:03 PM	03/25/2020
Smoke Detector	1st East Corridor C101 by stair 1	Visually Checked	2:45:47 PM	03/25/2020
Smoke Detector	1st Elevator lobby recall	Visually Checked	2:44:54 PM	03/25/2020
Smoke Detector	1st Elevator machine room	Visually Checked	2:44:47 PM	03/25/2020
Smoke Detector	1st in stair 1	Visually Checked	2:47:09 PM	03/25/2020
Smoke Detector	1st North Corridor outside rm 125 Entrance	Visually Checked	2:45:09 PM	03/25/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st South Corridor to left of elevator	Visually Checked	2:45:02 PM	03/25/2020
Smoke Detector	1st West Reception 159	Visually Checked	2:44:38 PM	03/25/2020
Smoke Detector	1st Corridor C105 outside stair 5	Visually Checked	2:45:54 PM	03/25/2020
Smoke Detector	1st Corridor outside stair 8	Visually Checked	2:47:23 PM	03/25/2020
Smoke Detector	1st in Stair 5	Visually Checked	2:46:04 PM	03/25/2020
Smoke Detector	1st in stair 8	Visually Checked	2:47:17 PM	03/25/2020
Smoke Detector	1st Main Entrance Vestibule Lobby	Visually Checked	2:43:48 PM	03/25/2020
Smoke Detector	2nd By Stair 5 Corridor C208	Visually Checked	2:46:42 PM	03/25/2020
Smoke Detector	2nd in stair 1 by rm 201	Visually Checked	2:47:01 PM	03/25/2020
Smoke Detector	2nd In Stair 5	Visually Checked	2:46:49 PM	03/25/2020
Smoke Detector	2nd outside stair 1 by rm 201	Visually Checked	2:46:55 PM	03/25/2020
Smoke Detector	2nd Southwest Corridor By Room 229	Visually Checked	2:46:33 PM	03/25/2020
Smoke Detector	2nd Southwest In stair 6	Visually Checked	2:46:26 PM	03/25/2020
Smoke Detector	2nd Corridor by stair 7	Visually Checked	2:45:27 PM	03/25/2020
Smoke Detector	2nd Corridor center before elevator lobby	Visually Checked	2:46:10 PM	03/25/2020
Smoke Detector	2nd Corridor north before elevator lobby	Visually Checked	2:45:17 PM	03/25/2020
Smoke Detector	2nd Elevator lobby recall	Visually Checked	2:45:33 PM	03/25/2020
Smoke Detector	2nd W Corridor south before elevator lobby	Visually Checked	2:46:18 PM	03/25/2020
Smoke Detector	3rd Elevator lobby recall	Visually Checked	2:45:41 PM	03/25/2020
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	1st Data Room 122 (Booster #3)	Tested	2:01:24 PM	03/25/2020

Service Summary

Generated by: BuildingReports.com

Building: Stamford BOE-Rogers School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	1
Total		1
<i>Passed</i>		
Annunciator	Tested	1
Battery	Tested	12
Communicator	Tested	1
Control Panel	Tested	1
Duct Detector	Visually Checked	16
Heat Detector	Visually Checked	1
Power Supply	Visually Checked	7
Pull Station	Visually Checked	33
Smoke Detector	Visually Checked	24
Total		96
Grand Total		97






Auxiliary Functions Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Rogers School			Control Panel: 1 - EST EST-2	
<i>The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.</i>				
Type	Location	Comment	ScanID	Simulated
Passed				
Heat Detector				
Shunt Trip	1st Elevator machine room	Passed	17013063	
Smoke Detector				
Elevator Recall	1st Elevator lobby recall	Passed	17013065	
Elevator Recall	1st Elevator machine room	Passed	17013064	
Elevator Recall	2nd Elevator lobby recall	Passed	17013073	
Elevator Recall	3rd Elevator lobby recall	Passed	17013074	

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Rogers School								
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>								
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test		
		 dB	 dB	Voice	STI			
<i>Untested</i>								
Sound Test Points								
Whole Facility				<input type="checkbox"/>		0001		

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Rogers School				Control Panel: 1 - EST EST-2			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	1st Data Room 122 (Booster #2)	7ah	12v	12.53v	5.4ah		
Sealed Lead Acid	1st Data Room 122 (Booster #2)	8ah	12v	12.50v	5.4ah		
Sealed Lead Acid	1st Data Room 122 (Booster #4)	7ah	12v	12.57v	10ah		
Sealed Lead Acid	1st Main office/reception Booster below FACP	26	12	13.26v	22ah		
Sealed Lead Acid	1st Main office/reception inside FACP	12	12	12.87v	11ah		
Sealed Lead Acid	1st Office Storage (Booster #1)	8	12	12.69v	7.8ah		
Sealed Lead Acid	1st Office Storage (Booster #2)	8	12	12.50v	5ah		
Sealed Lead Acid	1st Office Storage (Booster #3)	8	12	12.50v	7ah23028		
Sealed Lead Acid	1st Office Storage (Booster #4)	7	12	12.51v	7.8ah		
Sealed Lead Acid	2nd Room 218 (Center Booster)	8	12	12.68v	7.8ah		
Sealed Lead Acid	2nd Room 218 (Left Booster)	8	12	12.63v	7.8ah		
Sealed Lead Acid	2nd Room 218 (Right Booster)	8	12	12.68v	7.8ah		
Failed/Other							
Battery							
Sealed Lead Acid	1st Data Room 122 (Booster #3)	8ah	12v	12.34v	2.4ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Rogers School	Control Panel: 1 - EST EST-2
--------------------------------------	------------------------------

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type	Category	% of Inventory	Quantity
Sound Test	Sound Test	1.02%	1
Control Panel	Control	1.02%	1
Communicator	Control	1.02%	1
Battery	Control	13.27%	13
Annunciator	Control	1.02%	1
Pull Station	Initiating	33.67%	33
Heat Detector	Initiating	1.02%	1
Smoke Detector	Initiating	24.49%	24
Power Supply	Control	7.14%	7
Duct Detector	Initiating	16.33%	16

Type	Qty	Model #	Description	Install Date
<i>In Service - 90 Days - 1 Year</i>				
Power-Sonic				
Battery	1	PS-12260 NB	Sealed Lead Acid	08/20/2019
<i>In Service - 2 Years to 3 Years</i>				
Universal				
Battery	4	UB1280	Sealed Lead Acid	11/15/2017
Power-Sonic				
Battery	1	PS-1270 F1	Sealed Lead Acid	05/15/2017
<i>In Service - 5 Years to 10 Years</i>				
Universal				
Battery	1	UB1280	Sealed Lead Acid	02/07/2014
Bright Way Group				
Battery	1	BW1280	Sealed Lead Acid	09/05/2012
EST				
Battery	1	BPS10	Sealed Lead Acid	09/05/2012
Power Supply	4	BPS10		09/05/2012
Ultra Tech				
Battery	1	iso9001	Sealed Lead Acid	09/05/2012
Universal				
Battery	1	UB1280	Sealed Lead Acid	09/05/2012
Weida				
Battery	1	WB1280	Sealed Lead Acid	09/05/2012

EST				
Annunciator	1	EST	LCD Display	08/07/2012
Control Panel	1	EST-2		08/07/2012
Duct Detector	16	SIGA-SD	Photoelectric	08/07/2012
Heat Detector	1	SIGA-HFS	Fixed Temperature	08/07/2012
Power Supply	3	BPS6		08/07/2012
Pull Station	33	SIGA-278	Dual Action	08/07/2012
Smoke Detector	24	SIGA-PS	Photoelectric	08/07/2012
Genesis				
Battery	1	NP12-12T	Sealed Lead Acid	08/07/2012
<i>In Service - 10 Years to 15 Years</i>				
EST				
Communicator	1	411UD	Digital Communicator	12/13/2008

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Rogers School

Control Panel: 1 - EST EST-2

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
0003	Battery	1st Main office/reception Booster below FACP	Sealed Lead Acid	17013131
0101	Smoke Detector	1st in stair 8	Photoelectric	17013118
0102	Smoke Detector	1st Corridor outside stair 8	Photoelectric	17013133
0103	Smoke Detector	1st West Reception 159	Photoelectric	17013054
0104	Smoke Detector	1st Main Entrance Vestibule Lobby	Photoelectric	17013053
0105	Smoke Detector	1st South Corridor to left of elevator	Photoelectric	17013066
0106	Smoke Detector	1st North Corridor outside rm 125 Entrance	Photoelectric	17013069
0107	Smoke Detector	1st Corridor C105 outside stair 5	Photoelectric	17013088
0108	Smoke Detector	1st in Stair 5	Photoelectric	17013089
0109	Smoke Detector	1st East Corridor C101 by stair 1	Photoelectric	17013084
0110	Smoke Detector	1st in stair 1	Photoelectric	17013111
0111	Smoke Detector	1st Elevator lobby recall	Photoelectric	17013065
0204	Pull Station	1st North by stair 8	Dual Action	17013117
0205	Pull Station	1st Northeast auditorium	Dual Action	17013115
0206	Pull Station	1st Southeast auditorium	Dual Action	17013116
0207	Pull Station	1st Southwest auditorium	Dual Action	17013114
0208	Pull Station	1st Southwest Bottom of ramp auditorium	Dual Action	17013113
0210	Pull Station	1st Corridor by 155/162	Dual Action	17013112
0211	Pull Station	1st North Entrance vestibule lobby	Dual Action	17013051
0213	Pull Station	1st South Entrance vestibule lobby	Dual Action	17013052
0214	Pull Station	1st Northeast Gym	Dual Action	17013055
0215	Pull Station	1st Northwest Gym	Dual Action	17013057
0216	Pull Station	1st Southwest Gym	Dual Action	17013058
0217	Pull Station	1st Southeast Gym	Dual Action	17013056
0218	Pull Station	1st Southeast Corridor outside Gym	Dual Action	17013059
0219	Pull Station	1st Northwest Cafeteria 142	Dual Action	17013061
0220	Pull Station	1st Southeast Cafeteria 142	Dual Action	17013060
0221	Pull Station	1st Corr C108 By loading dock exit	Dual Action	17013062
0227	Pull Station	3rd Top stair 8	Dual Action	17013134
0229	Pull Station	1st South Corridor C1075 outside library	Dual Action	17013067
0230	Pull Station	1st Media center exit	Dual Action	17013070
0231	Pull Station	1st North Corridor C106 across from rm 125	Dual Action	17013068
0232	Pull Station	1st Southwest Stair 6 by stair 6	Dual Action	17013095
0233	Pull Station	1st Exit Stair 5	Dual Action	17013090
0235	Pull Station	1st Hallway to stair 5	Dual Action	17013091
0236	Pull Station	1st West Corridor C104 by 117	Dual Action	17013087
0237	Pull Station	1st East Corridor by entrance /stair 1	Dual Action	17013085
0238	Pull Station	1st Stairwell to Basement	Dual Action	17013083

0241	Pull Station	1st in stair 1	Dual Action	17013110
0242	Battery	1st Main office/reception inside FACP	Sealed Lead Acid	17013136
0273	Battery	1st Office Storage (Booster #1)	Sealed Lead Acid	23028752
0273	Power Supply	1st Office Storage (Booster #1)		23028753
0273	Battery	1st Office Storage (Booster #2)	Sealed Lead Acid	23028750
0273	Power Supply	1st Office Storage (Booster #2)		23028751
0273	Battery	1st Office Storage (Booster #3)	Sealed Lead Acid	23028748
0273	Power Supply	1st Office Storage (Booster #3)		23028747
0273	Power Supply	1st Office Storage (Booster #3)		23028749
0273	Battery	1st Office Storage (Booster #4)	Sealed Lead Acid	23028746
0273	Power Supply	2nd Room 218 (Center Booster)		17013100
0273	Battery	2nd Room 218 (Left Booster)	Sealed Lead Acid	17013098
0273	Power Supply	2nd Room 218 (Left Booster)		17013099
0273	Power Supply	2nd Room 218 (Right Booster)		17013102
0274	Battery	2nd Room 218 (Center Booster)	Sealed Lead Acid	17013101
0275	Battery	2nd Room 218 (Right Booster)	Sealed Lead Acid	17013103
0278	Pull Station	1st East Corridor C104 by 115 by basement stair	Dual Action	17013086
0301	Duct Detector	Basement AHU 2 Fan room Supply	Photoelectric	17013077
0302	Duct Detector	Basement AHU 2 Fan room Return	Photoelectric	17013076
0303	Duct Detector	Basement AHU 2 Fan room Return	Photoelectric	17013078
0305	Duct Detector	Basement AHU 1 Fan room Supply	Photoelectric	17013079
0306	Duct Detector	Basement AHU 1 Fan room Return	Photoelectric	17013081
0307	Duct Detector	Penthouse AHU 1 Fan room Return	Photoelectric	17013121
0308	Smoke Detector	2nd in stair 1 by rm 201	Photoelectric	17013109
0309	Smoke Detector	2nd outside stair 1 by rm 201	Photoelectric	17013108
0310	Smoke Detector	2nd Elevator lobby recall	Photoelectric	17013073
0311	Smoke Detector	2nd Corridor by stair 7	Photoelectric	17013072
0312	Smoke Detector	2nd Southwest Corridor By Room 229	Photoelectric	17013097
0313	Smoke Detector	2nd W Corridor south before elevator lobby	Photoelectric	17013093
0314	Smoke Detector	2nd Corridor center before elevator lobby	Photoelectric	17013092
0315	Smoke Detector	2nd Corridor north before elevator lobby	Photoelectric	17013071
0316	Smoke Detector	2nd By Stair 5 Corridor C208	Photoelectric	17013105
0317	Smoke Detector	2nd In Stair 5	Photoelectric	17013106
0318	Duct Detector	Basement AHU 1 Fan room Outside air	Photoelectric	17013080
0319	Duct Detector	Penthouse AHU 7 Fan room Return above reception/office	Photoelectric	17013122
0320	Duct Detector	Penthouse AHU 6 Fan room Supply above reception/office	Photoelectric	17013124
0321	Duct Detector	Penthouse AHU 6 Fan room Return above reception/office	Photoelectric	17013123
0322	Duct Detector	Penthouse AHU 3 Fan room Supply above reception/office	Photoelectric	17013125
0323	Duct Detector	Penthouse AHU 3 Fan room Return above reception/office	Photoelectric	17013126
0324	Duct Detector	Penthouse AHU 4 Fan room Supply above reception/office	Photoelectric	17013127
0325	Duct Detector	Penthouse AHU 4 Fan room Return above reception/office	Photoelectric	17013130
0326	Duct Detector	Penthouse AHU 5 Fan room Supply above reception/office	Photoelectric	17013128

0327	Duct Detector	Penthouse AHU 5 Fan room Return above reception/office	Photoelectric	17013129
0328	Smoke Detector	2nd Southwest In stair 6	Photoelectric	17013096
0329	Smoke Detector	3rd Elevator lobby recall	Photoelectric	17013074
0403	Pull Station	Basement rear by double door exit	Dual Action	17013075
0442	Pull Station	Basement by stair 3 Fan room	Dual Action	17013082
0444	Pull Station	2nd Corridor By Stair 1	Dual Action	21098543
0448	Pull Station	2nd Southwest Corridor by stair 6	Dual Action	17013094
0450	Pull Station	2nd by stair 5 Corridor C208	Dual Action	17013104

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Roxbury School
751 Westhill Road
Stamford, CT 06902

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Feb 18, 2020

Building: Stamford BOE-Roxbury School
Contact: Davor Lucaj
Title: Facilities Trades Manager



Company: TPC Associates, Inc.
Contact: Dave Majewski
Title: Inspector

Executive Summary

Generated by: BuildingReports.com





Building Information		
Building: Stamford BOE-Roxbury School	Contact: Davor Lucaj	
Address: 751 Westhill Road	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06902	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Dave Majewski	
Address: 261 Pepe's Farm Road	Phone: 203-666-9587	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: dave.majewski@tpcsystems.com	
System Control Unit		
Manufacturer: EST	Inspection Date: 02/18/2020	IDC Style:
Model Number: iO64	Install Date: 01/23/2009	SLC Style:
Software Version:	Version Date: 08/22/2012	NAC Style:
Location: 1st Office – Panel	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type: Digital Communicator	Mfg: Notifier	Model #: Noti Fire 911A
Test Time/Date: 2/18/20 11:12:28 AM	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.70%	0	0%	0	0%	0	0%
Control	6	4.20%	6	100.00%	5	83.33%	1	16.67%
Initiating	135	94.41%	135	100.00%	135	100.00%	0	0%
Supervisory	1	0.70%	1	100.00%	1	100.00%	0	0%
Totals	143	100%	142	99.30%	141	99.30%	1	0.70%

Certification	
<p>Company: TPC Associates, Inc.</p> <p>Inspector: Dave Majewski</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px 0;">  </div> <p>Signed: Feb 18, 2020 11:51:57 AM</p>	<p>Building: Stamford BOE-Roxbury School</p> <p>Contact: Davor Lucaj</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px 0;">  </div> <p>Signed: Feb 18, 2020 11:59:08 AM</p>

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-Roxbury School		Control Panel: 1 - EST iO64		
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
 ScanID	 Location	 Problem	Address	 Reference
<i>Control</i>				
Battery				
23028996	1st Office – Panel	Failed Test	1-01 074	NFPA 72 Table 10.4.2.2.5(a-e)

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-Roxbury School			Control Panel: 1 - EST iO64		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
Control					
Battery					
23028996	1st Office – Panel	Replace	UB1280	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Roxbury School		Control Panel: 1 - EST iO64		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
<i>Passed</i>				
Control				
Annunciator	1st Main Entrance Lobby	Tested	11:04:17 AM	02/18/2020
Battery	1st Office In Booster Panel	Tested	11:13:00 AM	02/18/2020
Communicator	1st Office – Panel	Tested	11:12:28 AM	02/18/2020
Control Panel	1st Office – Panel	Tested	11:10:29 AM	02/18/2020
Power Supply	1st Office	Tested	11:10:30 AM	02/18/2020
Initiating				
Beam Detector	1st Media Center	Tested	11:51:44 AM	02/18/2020
Duct Detector	1st Hallway A By Room 207	Visually Checked	11:50:43 AM	02/18/2020
Duct Detector	1st Hallway A By Room 209	Visually Checked	11:47:15 AM	02/18/2020
Duct Detector	1st Hallway D By Room 408	Visually Checked	11:00:16 AM	02/18/2020
Duct Detector	1st Hallway D By Room 410	Visually Checked	11:00:40 AM	02/18/2020
Duct Detector	1st North Wing By 501	Visually Checked	10:55:23 AM	02/18/2020
Duct Detector	1st North Wing By 502	Visually Checked	10:49:42 AM	02/18/2020
Duct Detector	1st North Wing By 505	Visually Checked	10:50:20 AM	02/18/2020
Duct Detector	1st North Wing By 505	Visually Checked	10:50:32 AM	02/18/2020
Heat Detector	Basement Boiler Room thru Maintainance Dock	Visually Checked	11:48:47 AM	02/18/2020
Heat Detector	1st Hallway C Boiler Room	Visually Checked	11:51:52 AM	02/18/2020
Heat Detector	1st Hallway C Gym/Cafe Kitchen	Visually Checked	11:49:49 AM	02/18/2020
Heat Detector	1st Hallway C Gym/Cafe Kitchen	Visually Checked	11:49:54 AM	02/18/2020
Heat Detector	1st Hallway C Teachers room	Visually Checked	11:50:06 AM	02/18/2020
Heat Detector	1st Hallway C Teachers room by Copier	Visually Checked	11:50:02 AM	02/18/2020
Heat Detector	1st Stage	Visually Checked	11:51:35 AM	02/18/2020
Heat Detector	1st Stage	Visually Checked	11:51:40 AM	02/18/2020
Pull Station	1st Boiler Room Exit	Visually Checked	11:51:48 AM	02/18/2020
Pull Station	1st Gymnasium	Visually Checked	11:21:22 AM	02/18/2020
Pull Station	1st Hallway A By Room 217	Visually Checked	11:45:49 AM	02/18/2020
Pull Station	1st Hallway B Auditorium	Visually Checked	11:17:38 AM	02/18/2020
Pull Station	1st Hallway B Auditorium Stage	Visually Checked	11:18:25 AM	02/18/2020
Pull Station	1st Hallway B By 101	Visually Checked	11:21:39 AM	02/18/2020
Pull Station	1st Hallway B Main Lobby	Visually Checked	11:04:43 AM	02/18/2020
Pull Station	1st Hallway C Gym/Cafe	Visually Checked	11:49:40 AM	02/18/2020
Pull Station	1st Hallway D By Room 414	Visually Checked	11:01:18 AM	02/18/2020
Pull Station	1st Kitchen Exit	Visually Checked	11:49:59 AM	02/18/2020
Pull Station	1st Media Center Rear Left	Visually Checked	11:06:50 AM	02/18/2020
Pull Station	1st Media Center Rear Right	Visually Checked	11:08:03 AM	02/18/2020
Pull Station	1st Mod Room 105	Visually Checked	11:49:07 AM	02/18/2020
Pull Station	1st Mod Room 106	Visually Checked	11:49:15 AM	02/18/2020
Pull Station	1st Mod Room 107	Visually Checked	11:29:01 AM	02/18/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	1st Mod Room 108	Visually Checked	11:31:07 AM	02/18/2020
Pull Station	1st Mod	Visually Checked	11:24:27 AM	02/18/2020
Pull Station	1st Mod By Room 103	Visually Checked	11:26:31 AM	02/18/2020
Pull Station	1st Mod Entrance by 104	Visually Checked	11:24:53 AM	02/18/2020
Pull Station	1st Mod Entrance by 104	Visually Checked	11:25:30 AM	02/18/2020
Pull Station	1st Mod Exit by Room 108	Visually Checked	11:31:50 AM	02/18/2020
Pull Station	1st North Port	Visually Checked	11:50:14 AM	02/18/2020
Pull Station	1st North Port Room 510	Visually Checked	11:50:18 AM	02/18/2020
Pull Station	1st North Port Room 511	Visually Checked	11:50:23 AM	02/18/2020
Pull Station	1st North Port By Music	Visually Checked	11:50:27 AM	02/18/2020
Pull Station	1st North Port Music	Visually Checked	11:50:31 AM	02/18/2020
Pull Station	1st North Wing By 502	Visually Checked	11:50:10 AM	02/18/2020
Pull Station	1st North Wing By 506	Visually Checked	10:53:44 AM	02/18/2020
Smoke Detector	Basement Boiler Room thru Maintainance Dock	Visually Checked	11:48:43 AM	02/18/2020
Smoke Detector	1st Auditorium	Visually Checked	11:19:50 AM	02/18/2020
Smoke Detector	1st Auditorium	Visually Checked	11:19:53 AM	02/18/2020
Smoke Detector	1st Auditorium	Visually Checked	11:19:56 AM	02/18/2020
Smoke Detector	1st Auditorium	Visually Checked	11:19:57 AM	02/18/2020
Smoke Detector	1st Hallway A By Room 201	Visually Checked	11:48:11 AM	02/18/2020
Smoke Detector	1st Hallway A By Room 201	Visually Checked	11:48:20 AM	02/18/2020
Smoke Detector	1st Hallway A By Room 205A	Visually Checked	11:47:54 AM	02/18/2020
Smoke Detector	1st Hallway A By Room 207	Visually Checked	11:47:26 AM	02/18/2020
Smoke Detector	1st Hallway A By Room 209	Visually Checked	11:47:12 AM	02/18/2020
Smoke Detector	1st Hallway A By Room 211	Visually Checked	11:47:00 AM	02/18/2020
Smoke Detector	1st Hallway A By Room 215	Visually Checked	11:46:13 AM	02/18/2020
Smoke Detector	1st Hallway A By Room 215	Visually Checked	11:46:33 AM	02/18/2020
Smoke Detector	1st Hallway A By Room 217	Visually Checked	11:45:59 AM	02/18/2020
Smoke Detector	1st Hallway B By 101	Visually Checked	11:22:32 AM	02/18/2020
Smoke Detector	1st Hallway B By Health Suite	Visually Checked	11:16:20 AM	02/18/2020
Smoke Detector	1st Hallway B By Main Lobby	Visually Checked	11:04:37 AM	02/18/2020
Smoke Detector	1st Hallway B By Main Lobby	Visually Checked	11:05:01 AM	02/18/2020
Smoke Detector	1st Hallway B By Main Office	Visually Checked	11:09:19 AM	02/18/2020
Smoke Detector	1st Hallway B By Main Office	Visually Checked	11:09:36 AM	02/18/2020
Smoke Detector	1st Hallway B By Room 102	Visually Checked	11:23:43 AM	02/18/2020
Smoke Detector	1st Hallway B By Room 102	Visually Checked	11:23:59 AM	02/18/2020
Smoke Detector	1st Hallway B By Storage 2	Visually Checked	11:23:00 AM	02/18/2020
Smoke Detector	1st Hallway B By Storage 2	Visually Checked	11:33:31 AM	02/18/2020
Smoke Detector	1st Hallway B By Storage 2	Visually Checked	11:48:55 AM	02/18/2020
Smoke Detector	1st Hallway B By Storage 4	Visually Checked	11:20:41 AM	02/18/2020
Smoke Detector	1st Hallway B By Storage 5	Visually Checked	11:20:22 AM	02/18/2020
Smoke Detector	1st Hallway B Near 101	Visually Checked	11:22:51 AM	02/18/2020
Smoke Detector	1st Hallway C Gym/Cafe Smk 1	Visually Checked	11:51:12 AM	02/18/2020
Smoke Detector	1st Hallway C Gym/Cafe Smk 2	Visually Checked	11:51:16 AM	02/18/2020
Smoke Detector	1st Hallway C Gym/Cafe Smk 3	Visually Checked	11:51:19 AM	02/18/2020
Smoke Detector	1st Hallway C Gym/Cafe Smk 4	Visually Checked	11:51:23 AM	02/18/2020
Smoke Detector	1st Hallway C Gym/Cafe Smk 5	Visually Checked	11:51:27 AM	02/18/2020
Smoke Detector	1st Hallway C Gym/Cafe Smk 6	Visually Checked	11:51:31 AM	02/18/2020
Smoke Detector	1st Hallway C By Maintenance Dock	Visually Checked	10:57:20 AM	02/18/2020
Smoke Detector	1st Hallway C By Room 301	Visually Checked	11:03:57 AM	02/18/2020
Smoke Detector	1st Hallway C By Room 302	Visually Checked	11:03:43 AM	02/18/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Hallway C By Room 305	Visually Checked	11:03:28 AM	02/18/2020
Smoke Detector	1st Hallway C By Room 306	Visually Checked	11:03:07 AM	02/18/2020
Smoke Detector	1st Hallway C By Room 400	Visually Checked	10:57:51 AM	02/18/2020
Smoke Detector	1st Hallway C By Room 400	Visually Checked	10:58:47 AM	02/18/2020
Smoke Detector	1st Hallway D By Room 402	Visually Checked	11:50:35 AM	02/18/2020
Smoke Detector	1st Hallway D By Room 404	Visually Checked	11:50:39 AM	02/18/2020
Smoke Detector	1st Hallway D By Room 406A	Visually Checked	11:00:00 AM	02/18/2020
Smoke Detector	1st Hallway D By Room 410	Visually Checked	11:00:33 AM	02/18/2020
Smoke Detector	1st Hallway D By Room 412	Visually Checked	11:00:49 AM	02/18/2020
Smoke Detector	1st Hallway D By Room 412	Visually Checked	11:01:04 AM	02/18/2020
Smoke Detector	1st Hallway D By Room 414	Visually Checked	11:01:16 AM	02/18/2020
Smoke Detector	1st Heath Suite	Visually Checked	11:48:51 AM	02/18/2020
Smoke Detector	1st Main Office	Visually Checked	11:09:59 AM	02/18/2020
Smoke Detector	1st Media Center Front Left	Visually Checked	11:50:52 AM	02/18/2020
Smoke Detector	1st Media Center Front Right	Visually Checked	11:50:56 AM	02/18/2020
Smoke Detector	1st Media Center Rear Left	Visually Checked	11:07:16 AM	02/18/2020
Smoke Detector	1st Media Center Rear Right	Visually Checked	11:07:47 AM	02/18/2020
Smoke Detector	1st Media Center Room 601	Visually Checked	11:50:47 AM	02/18/2020
Smoke Detector	1st Media Center Room 602	Visually Checked	11:51:08 AM	02/18/2020
Smoke Detector	1st Media Center Room 603	Visually Checked	11:51:00 AM	02/18/2020
Smoke Detector	1st Media Center Room 603	Visually Checked	11:51:04 AM	02/18/2020
Smoke Detector	1st Mod Electrical Room	Visually Checked	11:49:00 AM	02/18/2020
Smoke Detector	1st Mod Room 103	Visually Checked	11:26:41 AM	02/18/2020
Smoke Detector	1st Mod Room 105	Visually Checked	11:27:26 AM	02/18/2020
Smoke Detector	1st Mod Room 106	Visually Checked	11:49:11 AM	02/18/2020
Smoke Detector	1st Mod Room 107	Visually Checked	11:49:19 AM	02/18/2020
Smoke Detector	1st Mod Room 108	Visually Checked	11:30:56 AM	02/18/2020
Smoke Detector	1st Mod Room 108	Visually Checked	11:49:23 AM	02/18/2020
Smoke Detector	1st Mod	Visually Checked	11:24:08 AM	02/18/2020
Smoke Detector	1st Mod	Visually Checked	11:24:38 AM	02/18/2020
Smoke Detector	1st Mod By Electrical Room	Visually Checked	11:26:11 AM	02/18/2020
Smoke Detector	1st Mod By Room 105	Visually Checked	11:26:55 AM	02/18/2020
Smoke Detector	1st Mod By Room 108	Visually Checked	11:49:28 AM	02/18/2020
Smoke Detector	1st Mod Exit by Room 108	Visually Checked	11:31:46 AM	02/18/2020
Smoke Detector	1st Mod rm 104 Long	Visually Checked	11:25:20 AM	02/18/2020
Smoke Detector	1st Mod rm 104 Long	Visually Checked	11:49:03 AM	02/18/2020
Smoke Detector	1st North Port	Visually Checked	10:50:57 AM	02/18/2020
Smoke Detector	1st North Port By Music	Visually Checked	10:51:26 AM	02/18/2020
Smoke Detector	1st North Port By Room 510	Visually Checked	10:51:05 AM	02/18/2020
Smoke Detector	1st North Port By Room 510	Visually Checked	10:51:13 AM	02/18/2020
Smoke Detector	1st North Port Music	Visually Checked	10:51:36 AM	02/18/2020
Smoke Detector	1st North Port Room 510	Visually Checked	10:53:06 AM	02/18/2020
Smoke Detector	1st North Port Room 511	Visually Checked	10:52:42 AM	02/18/2020
Smoke Detector	1st North Wing By 501	Visually Checked	10:55:13 AM	02/18/2020
Smoke Detector	1st North Wing By 501	Visually Checked	10:56:29 AM	02/18/2020
Smoke Detector	1st North Wing By 502	Visually Checked	10:49:12 AM	02/18/2020
Smoke Detector	1st North Wing By 502	Visually Checked	10:49:32 AM	02/18/2020
Smoke Detector	1st North Wing By 502	Visually Checked	10:54:59 AM	02/18/2020
Smoke Detector	1st North Wing By 505	Visually Checked	10:49:56 AM	02/18/2020
Smoke Detector	1st North Wing By 505	Visually Checked	10:50:10 AM	02/18/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st North Wing By 506	Visually Checked	10:50:47 AM	02/18/2020
Smoke Detector	1st Office Conference Room	Visually Checked	11:49:32 AM	02/18/2020
Smoke Detector	1st Office Principal	Visually Checked	11:49:36 AM	02/18/2020
Supervisory				
End Of Line	1st Mod Room 107	Tested	11:28:51 AM	02/18/2020
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	1st Office – Panel	Tested	11:12:26 AM	02/18/2020




Service Summary

Generated by: BuildingReports.com

Building: Stamford BOE-Roxbury School		
The Service Summary section provides an overview of the services performed in this report.		
Device Type	Service	Quantity
Failed/Other		
Battery	Tested	1
Total		1
Passed		
Annunciator	Tested	1
Battery	Tested	1
Beam Detector	Tested	1
Communicator	Tested	1
Control Panel	Tested	1
Duct Detector	Visually Checked	8
End Of Line	Tested	1
Heat Detector	Visually Checked	8
Power Supply	Tested	1
Pull Station	Visually Checked	28
Smoke Detector	Visually Checked	90
Total		141
Grand Total		142

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Roxbury School						
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>						
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test
		◀ dB	◀ dB	Voice	STI	
<i>Untested</i>						
Sound Test Points						
Whole Facility				<input type="checkbox"/>		0001

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Roxbury School				Control Panel: 1 - EST iO64			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<i>Passed</i>							
Battery							
Sealed Lead Acid	1st Office In Booster Panel	8	12	12.62V	7.4Ah		
<i>Failed/Other</i>							
Battery							
Sealed Lead Acid	1st Office – Panel	8	12	12.78V	4.8Ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Roxbury School				Control Panel: 1 - EST iO64	
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		0.70%	1
Smoke Detector		Initiating		62.94%	90
Duct Detector		Initiating		5.59%	8
Pull Station		Initiating		19.58%	28
Annunciator		Control		0.70%	1
Control Panel		Control		0.70%	1
Power Supply		Control		0.70%	1
Battery		Control		1.40%	2
Communicator		Control		0.70%	1
End Of Line		Supervisory		0.70%	1
Heat Detector		Initiating		5.59%	8
Beam Detector		Initiating		0.70%	1
Type	Qty	Model #	Description		Install Date
In Service - 5 Years to 10 Years					
Edwards					
Annunciator	1		LCD Display		08/22/2012
Beam Detector	1				08/22/2012
End Of Line	1	6250B			08/22/2012
Heat Detector	8	283B	Fixed Temperature		08/22/2012
Pull Station	1	SPO-270	Dual Action		08/22/2012
Pull Station	5	SPO-270	Single Action		08/22/2012
Pull Station	14	SPO-278	Dual Action		08/22/2012
Smoke Detector	85	6250B	Ionization		08/22/2012
Smoke Detector	4	EC30-U	Ionization		08/22/2012
Fire-Lite					
Duct Detector	6	TC805C1018	Ionization		08/22/2012
Pull Station	7	BG10	Dual Action		08/22/2012
Fire-lite					
Pull Station	1	BG10	Single Action		08/22/2012
Honeywell					
Duct Detector	2	TC805C1018	Ionization		08/22/2012
System Sensor					
Smoke Detector	1	2WB	Ionization		08/22/2012
In Service - 10 Years to 15 Years					
EST					
Control Panel	1	iO64	Sealed Lead Acid		01/23/2009

Power Supply	1	BPS10		01/23/2009
Notifier				
Communicator	1	Noti Fire 911A	Digital Communicator	01/23/2009
Universal				
Battery	2	UB1280	Sealed Lead Acid	01/23/2009

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Roxbury School

Control Panel: 1 - EST iO64

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 01				
001	Smoke Detector	1st Hallway A By Room 201	Ionization	04060511
001	Smoke Detector	1st Hallway A By Room 201	Ionization	04060512
001	Smoke Detector	1st Hallway A By Room 205A	Ionization	04060513
001	Duct Detector	1st Hallway A By Room 207	Ionization	04060582
001	Smoke Detector	1st Hallway A By Room 207	Ionization	04060514
001	Duct Detector	1st Hallway A By Room 209	Ionization	04060583
001	Smoke Detector	1st Hallway A By Room 209	Ionization	04060515
001	Smoke Detector	1st Hallway A By Room 211	Ionization	23029185
001	Smoke Detector	1st Hallway A By Room 215	Ionization	04060517
001	Smoke Detector	1st Hallway A By Room 215	Ionization	04060518
001	Pull Station	1st Hallway A By Room 217	Dual Action	23029184
001	Smoke Detector	1st Hallway A By Room 217	Ionization	04060519
003	Smoke Detector	1st Auditorium	Ionization	51386289
003	Smoke Detector	1st Auditorium	Ionization	51386295
003	Smoke Detector	1st Auditorium	Ionization	51386297
003	Smoke Detector	1st Auditorium	Ionization	51386298
003	Pull Station	1st Gymnasium	Dual Action	04060510
003	Pull Station	1st Hallway B Auditorium	Dual Action	04062225
003	Pull Station	1st Hallway B Auditorium Stage	Dual Action	04060521
003	Pull Station	1st Hallway B By 101	Dual Action	04060509
003	Smoke Detector	1st Hallway B By 101	Ionization	20669864
003	Smoke Detector	1st Hallway B By Health Suite	Ionization	04060474
003	Smoke Detector	1st Hallway B By Main Lobby	Ionization	04060529
003	Smoke Detector	1st Hallway B By Main Lobby	Ionization	04060531
003	Smoke Detector	1st Hallway B By Main Office	Ionization	04060525
003	Smoke Detector	1st Hallway B By Main Office	Ionization	04060528
003	Smoke Detector	1st Hallway B By Room 102	Ionization	04060479
003	Smoke Detector	1st Hallway B By Room 102	Ionization	04060480
003	Smoke Detector	1st Hallway B By Storage 2	Ionization	04060506
003	Smoke Detector	1st Hallway B By Storage 2	Ionization	04060477
003	Smoke Detector	1st Hallway B By Storage 2	Ionization	20669861
003	Smoke Detector	1st Hallway B By Storage 4	Ionization	04060476
003	Smoke Detector	1st Hallway B By Storage 5	Ionization	04060475
003	Pull Station	1st Hallway B Main Lobby	Dual Action	04060530
003	Smoke Detector	1st Hallway B Near 101	Ionization	04060507
003	Smoke Detector	1st Main Office	Ionization	04060472
003	Smoke Detector	1st Office Conference Room	Ionization	04060526
003	Smoke Detector	1st Office Principal	Ionization	04060527
003	Heat Detector	1st Stage	Fixed Temperature	20667109
003	Heat Detector	1st Stage	Fixed Temperature	20667110

005	Smoke Detector	1st Hallway D By Room 402	Ionization	04060572
005	Smoke Detector	1st Hallway D By Room 404	Ionization	04060573
005	Smoke Detector	1st Hallway D By Room 406A	Ionization	04060574
005	Duct Detector	1st Hallway D By Room 408	Ionization	04060581
005	Duct Detector	1st Hallway D By Room 410	Ionization	04060580
005	Smoke Detector	1st Hallway D By Room 410	Ionization	04060575
005	Smoke Detector	1st Hallway D By Room 412	Ionization	04060576
005	Smoke Detector	1st Hallway D By Room 412	Ionization	04060577
005	Pull Station	1st Hallway D By Room 414	Dual Action	04060579
005	Smoke Detector	1st Hallway D By Room 414	Ionization	04060578
007	Pull Station	1st Boiler Room Exit	Dual Action	23029182
007	Heat Detector	1st Hallway C Boiler Room	Fixed Temperature	23029183
007	Pull Station	1st Hallway C Gym/Cafe	Dual Action	04060535
007	Heat Detector	1st Hallway C Gym/Cafe Kitchen	Fixed Temperature	04060536
007	Heat Detector	1st Hallway C Gym/Cafe Kitchen	Fixed Temperature	04060537
007	Smoke Detector	1st Hallway C Gym/Cafe Smk 1	Ionization	16320752
007	Smoke Detector	1st Hallway C Gym/Cafe Smk 2	Ionization	16320753
007	Smoke Detector	1st Hallway C Gym/Cafe Smk 3	Ionization	16320754
007	Smoke Detector	1st Hallway C Gym/Cafe Smk 4	Ionization	16320755
007	Smoke Detector	1st Hallway C Gym/Cafe Smk 5	Ionization	16320756
007	Smoke Detector	1st Hallway C Gym/Cafe Smk 6	Ionization	16320757
007	Smoke Detector	1st Hallway C By Maintenance Dock	Ionization	04060540
007	Smoke Detector	1st Hallway C By Room 301	Ionization	04060532
007	Smoke Detector	1st Hallway C By Room 302	Ionization	04060533
007	Smoke Detector	1st Hallway C By Room 305	Ionization	04060534
007	Smoke Detector	1st Hallway C By Room 306	Ionization	04060539
007	Smoke Detector	1st Hallway C By Room 400	Ionization	04060570
007	Smoke Detector	1st Hallway C By Room 400	Ionization	04060571
007	Heat Detector	1st Hallway C Teachers room	Fixed Temperature	04060542
007	Heat Detector	1st Hallway C Teachers room by Copier	Fixed Temperature	04060541
007	Pull Station	1st Kitchen Exit	Dual Action	04060538
009	Smoke Detector	1st Media Center Front Left	Ionization	04060587
009	Smoke Detector	1st Media Center Front Right	Ionization	04060590
009	Pull Station	1st Media Center Rear Left	Dual Action	04060593
009	Smoke Detector	1st Media Center Rear Left	Ionization	04060588
009	Pull Station	1st Media Center Rear Right	Dual Action	04060592
009	Smoke Detector	1st Media Center Rear Right	Ionization	04060589
009	Smoke Detector	1st Media Center Room 601	Ionization	04060586
009	Smoke Detector	1st Media Center Room 602	Ionization	04060595
009	Smoke Detector	1st Media Center Room 603	Ionization	04060591
009	Smoke Detector	1st Media Center Room 603	Ionization	04060594
011	Heat Detector	Basement Boiler Room thru Maintainance Dock	Fixed Temperature	23029187
011	Smoke Detector	Basement Boiler Room thru Maintainance Dock	Ionization	04060584
013	Smoke Detector	1st Heath Suite	Ionization	04060473
013	Duct Detector	1st North Wing By 501	Ionization	04060566
013	Smoke Detector	1st North Wing By 501	Ionization	04060543
013	Smoke Detector	1st North Wing By 501	Ionization	04060546
013	Duct Detector	1st North Wing By 502	Ionization	04060567
013	Pull Station	1st North Wing By 502	Dual Action	04060549
013	Smoke Detector	1st North Wing By 502	Ionization	04060547
013	Smoke Detector	1st North Wing By 502	Ionization	04060548

013	Smoke Detector	1st North Wing By 502	Ionization	04060550
013	Duct Detector	1st North Wing By 505	Ionization	04060568
013	Duct Detector	1st North Wing By 505	Ionization	04060569
013	Smoke Detector	1st North Wing By 505	Ionization	04060551
013	Smoke Detector	1st North Wing By 505	Ionization	04060552
013	Pull Station	1st North Wing By 506	Dual Action	04062226
013	Smoke Detector	1st North Wing By 506	Ionization	04060553
015	Beam Detector	1st Media Center		20667115
026	Pull Station	1st Mod	Dual Action	04060482
026	Smoke Detector	1st Mod	Ionization	04060481
026	Smoke Detector	1st Mod	Ionization	04060483
026	Smoke Detector	1st Mod Electrical Room	Ionization	04060484
026	Smoke Detector	1st Mod Room 103	Ionization	51386296
026	Pull Station	1st Mod Room 105	Single Action	04060494
026	Smoke Detector	1st Mod Room 105	Ionization	04060493
026	Pull Station	1st Mod Room 106	Dual Action	04060496
026	Smoke Detector	1st Mod Room 106	Ionization	04060495
026	End Of Line	1st Mod Room 107		04060497
026	Pull Station	1st Mod Room 107	Dual Action	04060498
026	Smoke Detector	1st Mod Room 107	Ionization	04060499
026	Pull Station	1st Mod Room 108	Dual Action	04060502
026	Smoke Detector	1st Mod Room 108	Ionization	04060500
026	Smoke Detector	1st Mod Room 108	Ionization	04060501
026	Smoke Detector	1st Mod By Electrical Room	Ionization	23029186
026	Pull Station	1st Mod By Room 103	Dual Action	04060491
026	Smoke Detector	1st Mod By Room 105	Ionization	04060492
026	Smoke Detector	1st Mod By Room 108	Ionization	04060503
026	Pull Station	1st Mod Entrance by 104	Dual Action	04060486
026	Pull Station	1st Mod Entrance by 104	Dual Action	04060488
026	Pull Station	1st Mod Exit by Room 108	Dual Action	04060505
026	Smoke Detector	1st Mod Exit by Room 108	Ionization	04060504
026	Smoke Detector	1st Mod rm 104 Long	Ionization	04060485
026	Smoke Detector	1st Mod rm 104 Long	Ionization	04060487
032	Pull Station	1st North Port	Single Action	04060555
032	Smoke Detector	1st North Port	Ionization	04060554
032	Pull Station	1st North Port Room 510	Single Action	04060558
032	Pull Station	1st North Port Room 511	Single Action	04060561
032	Pull Station	1st North Port By Music	Single Action	04060563
032	Smoke Detector	1st North Port By Music	Ionization	04060562
032	Smoke Detector	1st North Port By Room 510	Ionization	04060556
032	Smoke Detector	1st North Port By Room 510	Ionization	04060559
032	Pull Station	1st North Port Music	Single Action	04060565
032	Smoke Detector	1st North Port Music	Ionization	04060564
032	Smoke Detector	1st North Port Room 510	Ionization	04060557
032	Smoke Detector	1st North Port Room 511	Ionization	04060560
074	Battery	1st Office – Panel	Sealed Lead Acid	23028996

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE Springdale EST
1127 Hope Street
Stamford, ct 000000

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Mar 25, 2020

Building: Stamford BOE Springdale EST
Contact: Davor Lucaj
Title: Facilities Trades Manager



Company: TPC Associates, Inc.
Contact: Luis De La Cruz
Title: Fire alarm inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE Springdale EST	Contact: Davor Lucaj	
Address: 1127 Hope Street	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, ct 000000	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Luis De La Cruz	
Address: 261 Pepe's Farm Road	Phone: (203)878-1321	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: Luis.delacruz@tpcsystems.com	
System Control Unit		
Manufacturer: EST	Inspection Date: 03/25/2020	IDC Style:
Model Number: 3X	Install Date: 07/11/2014	SLC Style:
Software Version:	Version Date: 07/11/2004	NAC Style:
Location: 1st Fire Panel Room	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type: Digital Communicator	Mfg: Notifier	Model #: 911A
Test Time/Date: 3/25/20 11:02:08 AM	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.64%	0	0%	0	0%	0	0%
Control	8	5.13%	8	100.00%	8	100.00%	0	0%
Initiating	147	94.23%	147	100.00%	147	100.00%	0	0%
Totals	156	100%	155	99.36%	155	100.00%	0	0%

Certification	
<p>Company: TPC Associates, Inc.</p> <p>Inspector: Luis De La Cruz</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px auto;">  </div> <p>Signed: Mar 25, 2020 11:30:10 AM</p>	<p>Building: Stamford BOE Springdale EST</p> <p>Contact: Davor Lucaj</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px auto;">  </div> <p>Signed: Mar 25, 2020 11:32:44 AM</p>

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE Springdale EST		Control Panel: 1 - EST 3X		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Annunciator	1st MAIN ENTRANCE	Visually Checked	10:21:10 AM	03/25/2020
Battery	1st Fire Panel Room	Tested	10:52:33 AM	03/25/2020
Battery	1st Fire Panel Room	Tested	10:55:06 AM	03/25/2020
Battery	1st Fire Panel Room(Communicator)	Tested	10:59:18 AM	03/25/2020
Battery	1st BOILER ROOM STORAGE AREA	Tested	11:10:37 AM	03/25/2020
Battery	3rd FLR NORTH STORAGE ROOM	Tested	10:27:52 AM	03/25/2020
Communicator	1st Fire Panel Room	Visually Checked	11:02:08 AM	03/25/2020
Control Panel	1st Fire Panel Room	Visually Checked	10:56:49 AM	03/25/2020
Initiating				
Duct Detector	2nd DUCTSMOKE RETURN MEDIA CENTER	Visually Checked	11:12:15 AM	03/25/2020
Duct Detector	2nd DUCTSMOKE SUPPLY MEDIA CENTER	Visually Checked	11:12:19 AM	03/25/2020
Duct Detector	3rd DUCTSMOKE RTU RETURN WEST WING NORTH	Visually Checked	10:30:39 AM	03/25/2020
Duct Detector	3rd DUCTSMOKE RTU RETURN WEST WING NORTH	Visually Checked	10:30:53 AM	03/25/2020
Duct Detector	3rd DUCTSMOKE RTU RETURN WEST WING SOUTH	Visually Checked	10:32:02 AM	03/25/2020
Duct Detector	3rd DUCTSMOKE RTU RETURN WEST WING SOUTH	Visually Checked	10:32:11 AM	03/25/2020
Duct Detector	3rd DUCTSMOKE RTU SUPPLY WEST WING NORTH	Visually Checked	10:30:43 AM	03/25/2020
Duct Detector	3rd DUCTSMOKE RTU SUPPLY WEST WING NORTH	Visually Checked	10:30:49 AM	03/25/2020
Duct Detector	3rd DUCTSMOKE RTU SUPPLY WEST WING SOUTH	Visually Checked	10:32:05 AM	03/25/2020
Duct Detector	3rd DUCTSMOKE RTU SUPPLY WEST WING SOUTH	Visually Checked	10:32:14 AM	03/25/2020
Duct Detector	Roof DUCTSMOKE RTU-1 RET AUDITORIUM	Visually Checked	11:20:30 AM	03/25/2020
Duct Detector	Roof DUCTSMOKE RTU-2 RET AUDITORIUM	Visually Checked	11:12:11 AM	03/25/2020
Duct Detector	DUCTSMOKE RTU-1 SUP AUDITORIUM	Visually Checked	10:52:01 AM	03/25/2020
Duct Detector	DUCTSMOKE RTU-2 SUP AUDITORIUM	Visually Checked	10:52:00 AM	03/25/2020
Heat Detector	1st HEAT BOILER ROOM BY EXTERIOR STAIR	Visually Checked	11:12:24 AM	03/25/2020
Heat Detector	1st HEAT BOILER ROOM BY INTERIOR STAIR	Visually Checked	11:12:33 AM	03/25/2020
Heat Detector	1st HEAT BOILER ROOM STORAGE AREA	Visually Checked	11:10:31 AM	03/25/2020
Heat Detector	1st HEAT GRND FLR EAST CUSTODIANS CLOSET	Visually Checked	11:19:33 AM	03/25/2020
Heat Detector	1st HEAT GRND FLR EAST GYM CLOSET	Visually Checked	11:12:46 AM	03/25/2020
Heat Detector	1st HEAT GRND FLR EAST GYM OFFICE	Visually Checked	11:12:55 AM	03/25/2020
Heat Detector	2nd HEAT 2ND FL CENTER CUSTODIAN CLOSET	Visually Checked	10:34:28 AM	03/25/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	Penthouse ATTIC HEAT DETECTORS	Visually Checked	11:12:59 AM	03/25/2020
Heat Detector	Ground HEAT ELEVATOR MACHINE ROOM	Visually Checked	11:12:42 AM	03/25/2020
Pull Station	1st PULL 1ST FL WEST AT SOUTH STAIR	Visually Checked	11:13:46 AM	03/25/2020
Pull Station	1st PULL AUDITORIUM BACKSTAGE RIGHT	Visually Checked	11:15:46 AM	03/25/2020
Pull Station	1st PULL AUDITORIUM EXIT STAGE LEFT	Visually Checked	11:15:55 AM	03/25/2020
Pull Station	1st PULL AUDITORIUM REAR LEFT	Visually Checked	11:14:20 AM	03/25/2020
Pull Station	1st PULL AUDITORIUM REAR RIGHT	Visually Checked	11:14:16 AM	03/25/2020
Pull Station	1st PULL AUDITORIUM RIGHT FRONT	Visually Checked	11:14:13 AM	03/25/2020
Pull Station	1st PULL BY NURSES OFF AT NORTH STAIR	Visually Checked	11:13:55 AM	03/25/2020
Pull Station	1st PULL GRND FLR EAST BY BATHROOMS	Visually Checked	11:16:08 AM	03/25/2020
Pull Station	1st PULL GRND FLR EAST EAST EXIT	Visually Checked	11:16:03 AM	03/25/2020
Pull Station	1st PULL REAR ENTRANCE TO MAIN OFFICE	Visually Checked	11:14:00 AM	03/25/2020
Pull Station	1st PULLSTATION BOILER ROOM	Visually Checked	11:16:12 AM	03/25/2020
Pull Station	1st PULLSTATION ENTRANCE BY GYM	Visually Checked	11:13:10 AM	03/25/2020
Pull Station	1st PULLSTATION GYM	Visually Checked	11:13:26 AM	03/25/2020
Pull Station	1st PULLSTATION GYM	Visually Checked	11:13:29 AM	03/25/2020
Pull Station	1st PULLSTATION KITCHEN	Visually Checked	11:15:21 AM	03/25/2020
Pull Station	1st PULLSTATION MAIN ENTRANCE	Visually Checked	11:14:08 AM	03/25/2020
Pull Station	1st PULLSTATION MAIN OFFICE	Visually Checked	11:14:04 AM	03/25/2020
Pull Station	1st PULLSTATION SIDE ENTRANCE	Visually Checked	11:13:50 AM	03/25/2020
Pull Station	2nd PULL 2ND FL CENTER AT EAST STAIR	Visually Checked	11:13:42 AM	03/25/2020
Pull Station	2nd PULL 2ND FL WEST AT NORTH STAIR	Visually Checked	11:13:37 AM	03/25/2020
Pull Station	2nd PULL 2ND FL WEST AT SOUTH STAIR	Visually Checked	11:15:31 AM	03/25/2020
Pull Station	3rd PULL 3RD FL NORTH AT NORTH STAIR	Visually Checked	11:14:24 AM	03/25/2020
Pull Station	3rd PULL 3RD FL WEST AT SOUTH STAIR	Visually Checked	11:14:40 AM	03/25/2020
Pull Station	Ground PULL MEDIA CENTER	Visually Checked	11:13:33 AM	03/25/2020
Pull Station	Ground PULLSTATION MEDIA CENTER	Visually Checked	11:13:21 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FL CUSTODIANS ROOM	Visually Checked	11:05:05 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FL MAIN ELECTRICAL RM	Visually Checked	10:50:44 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FL STORAGE/SPRINKLER	Visually Checked	10:50:08 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FL WEST AT SOUTH STAIR	Visually Checked	11:04:48 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FL WEST BY ART ROOM	Visually Checked	10:48:16 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FL WEST LARGE STORAGE RM	Visually Checked	10:47:41 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FL WEST LARGE STORAGE RM	Visually Checked	10:47:42 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FL WEST OVER RAMP	Visually Checked	10:47:53 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FL WEST STORAGE @ SPEECH RM	Visually Checked	11:18:05 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FL WEST STORAGE RM BY ART	Visually Checked	10:49:25 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FLR BACK ENTRY BY OFF.	Visually Checked	11:08:30 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FLR BY MAIN OFFICE	Visually Checked	11:18:00 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FLR BY NURSES OFFICE	Visually Checked	10:46:43 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FLR ELEVATOR LOBBY	Visually Checked	11:17:51 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FLR LOBBY OUTSIDE MAIN OFFICE	Visually Checked	10:22:45 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FLR MAIN ENTRANCE	Visually Checked	10:21:24 AM	03/25/2020
Smoke Detector	1st SMOKE 1ST FLR MAIN OFFICE STORAGE	Visually Checked	11:20:20 AM	03/25/2020
Smoke Detector	1st SMOKE ART RESOURCE ROOM	Visually Checked	11:06:17 AM	03/25/2020
Smoke Detector	1st SMOKE AUDITORIUM BACKSTAGE LEFT	Visually Checked	10:52:02 AM	03/25/2020
Smoke Detector	1st SMOKE AUDITORIUM BACKSTAGE RIGHT	Visually Checked	10:52:03 AM	03/25/2020
Smoke Detector	1st SMOKE AUDITORIUM CENTER LEFT	Visually Checked	11:17:47 AM	03/25/2020
Smoke Detector	1st SMOKE AUDITORIUM CENTER RIGHT	Visually Checked	10:52:05 AM	03/25/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st SMOKE AUDITORIUM FRONT LEFT	Visually Checked	10:52:04 AM	03/25/2020
Smoke Detector	1st SMOKE AUDITORIUM FRONT RIGHT	Visually Checked	10:52:04 AM	03/25/2020
Smoke Detector	1st SMOKE AUDITORIUM REAR LEFT	Visually Checked	10:52:08 AM	03/25/2020
Smoke Detector	1st SMOKE AUDITORIUM REAR RIGHT	Visually Checked	11:18:15 AM	03/25/2020
Smoke Detector	1st SMOKE CORRIDOR BY CUSTODIANS OFFICE	Visually Checked	10:51:43 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #1	Visually Checked	11:29:48 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #10	Visually Checked	11:19:48 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #2	Visually Checked	11:28:51 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #3	Visually Checked	11:24:56 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #4	Visually Checked	11:22:43 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #5	Visually Checked	11:29:20 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #6	Visually Checked	11:18:50 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #7	Visually Checked	11:23:27 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #8	Visually Checked	11:19:23 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #9	Visually Checked	11:21:30 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CORRIDOR	Visually Checked	11:18:44 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CORRIDOR	Visually Checked	11:19:59 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CORRIDOR	Visually Checked	11:21:51 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CORRIDOR	Visually Checked	11:22:24 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST CORRIDOR	Visually Checked	11:23:15 AM	03/25/2020
Smoke Detector	1st SMOKE GRND FLR EAST NEAR EAST EXIT	Visually Checked	11:29:31 AM	03/25/2020
Smoke Detector	1st SMOKE GYM FRONT LEFT	Visually Checked	10:51:58 AM	03/25/2020
Smoke Detector	1st SMOKE GYM FRONT RIGHT	Visually Checked	10:51:59 AM	03/25/2020
Smoke Detector	1st SMOKE GYM REAR LEFT	Visually Checked	10:51:56 AM	03/25/2020
Smoke Detector	1st SMOKE GYM REAR RIGHT	Visually Checked	10:51:57 AM	03/25/2020
Smoke Detector	1st SMOKE HALL BETWEEN AUDITORIUM & MEDIA	Visually Checked	11:09:06 AM	03/25/2020
Smoke Detector	1st SMOKE HALL OUTSIDE AUDITORIUM	Visually Checked	11:09:23 AM	03/25/2020
Smoke Detector	1st SMOKE MEDIA CENTER THERAPIST ROOM	Visually Checked	11:18:24 AM	03/25/2020
Smoke Detector	1st SMOKE NEAR STAGE ENTRANCE	Visually Checked	11:09:38 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER AT FIRE DOOR BY 111	Visually Checked	10:36:00 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 111	Visually Checked	10:37:52 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 112	Visually Checked	10:36:41 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 113	Visually Checked	10:39:08 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 114	Visually Checked	10:38:39 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 115	Visually Checked	10:39:53 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 116	Visually Checked	10:40:56 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 117	Visually Checked	10:42:09 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 118	Visually Checked	10:42:37 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER CORRIDOR BY BOYS RM	Visually Checked	10:34:42 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER ELEVATOR LOBBY	Visually Checked	10:34:47 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER IN EAST STAIR	Visually Checked	11:16:41 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER STORAGE IN RM 112	Visually Checked	10:36:20 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FL CENTER UTILITY ROOM	Visually Checked	10:34:34 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FLR CENTER AT FIRE DOOR	Visually Checked	11:20:17 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FLR WEST AT NORTH STAIR	Visually Checked	10:34:13 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FLR WEST AT SOUTH STAIR	Visually Checked	10:33:22 AM	03/25/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd SMOKE 2ND FLR WEST BY ROOM 104A	Visually Checked	10:33:59 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FLR WEST BY ROOM 106	Visually Checked	10:33:33 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FLR WEST BY ROOM 109/110	Visually Checked	10:33:48 AM	03/25/2020
Smoke Detector	2nd SMOKE 2ND FLR WEST STORAGE ROOM	Visually Checked	11:20:09 AM	03/25/2020
Smoke Detector	3rd SMOKE 3RD FLR NORTH BY ROOM 204	Visually Checked	10:31:10 AM	03/25/2020
Smoke Detector	3rd SMOKE 3RD FLR NORTH BY ROOM 205/206	Visually Checked	10:31:32 AM	03/25/2020
Smoke Detector	3rd SMOKE 3RD FLR NORTH CUSTODIAN CLOSET	Visually Checked	11:20:12 AM	03/25/2020
Smoke Detector	3rd SMOKE 3RD FLR NORTH ELEVATOR LOBBY	Visually Checked	10:29:49 AM	03/25/2020
Smoke Detector	3rd SMOKE 3RD FLR NORTH IN NORTH STAIR	Visually Checked	11:18:11 AM	03/25/2020
Smoke Detector	3rd SMOKE 3RD FLR NORTH IN SMALL HALL	Visually Checked	10:29:57 AM	03/25/2020
Smoke Detector	3rd SMOKE 3RD FLR NORTH NEAR NORTH STAIR	Visually Checked	10:30:27 AM	03/25/2020
Smoke Detector	3rd SMOKE 3RD FLR NORTH NEAR SOUTH STAIR	Visually Checked	10:31:43 AM	03/25/2020
Smoke Detector	3rd SMOKE 3RD FLR NORTH SOUTH STAIR	Visually Checked	10:33:03 AM	03/25/2020
Smoke Detector	3rd SMOKE 3RD FLR NORTH STORAGE ROOM	Visually Checked	10:27:26 AM	03/25/2020
Smoke Detector	Ground SMOKE ELEVATOR MACHINE ROOM	Visually Checked	11:17:33 AM	03/25/2020
Smoke Detector	Ground SMOKE GND FL OUTSIDE MEDIA CTR DOUBLE DR	Visually Checked	11:16:21 AM	03/25/2020
Smoke Detector	Ground SMOKE GRND FLR EAST BY DOUBLE DR IN GYM	Visually Checked	11:16:33 AM	03/25/2020
Smoke Detector	Ground SMOKE GRND FLR EAST GYM DOOR TO LOBBY	Visually Checked	11:16:27 AM	03/25/2020
Smoke Detector	Ground SMOKE GROUND FLR UPPER HALL TO MEDIA	Visually Checked	11:17:55 AM	03/25/2020
Smoke Detector	Ground SMOKE IN ELEC ROOM IN MEDIA CENTER	Visually Checked	11:18:20 AM	03/25/2020
Smoke Detector	Ground SMOKE IN STORAGE RM BEHIND ELEVATOR RM	Visually Checked	11:20:04 AM	03/25/2020
Smoke Detector	Ground SMOKE MEDIA CENTER AID/VOLUNTEER AREA	Visually Checked	11:16:49 AM	03/25/2020
Smoke Detector	Ground SMOKE MEDIA CENTER BY MECH ROOM	Visually Checked	11:17:38 AM	03/25/2020
Smoke Detector	Ground SMOKE MEDIA CENTER BY MEDIA LAB	Visually Checked	11:17:26 AM	03/25/2020
Smoke Detector	Ground SMOKE MEDIA CENTER BY STAIRS	Visually Checked	10:52:11 AM	03/25/2020
Smoke Detector	Ground SMOKE MEDIA CENTER ELEVATOR LOBBY	Visually Checked	11:17:30 AM	03/25/2020
Smoke Detector	Ground SMOKE MEDIA CENTER IN MEDIA LAB	Visually Checked	11:16:59 AM	03/25/2020
Smoke Detector	Ground SMOKE MEDIA CENTER OFFICE	Visually Checked	11:16:53 AM	03/25/2020
Smoke Detector	Ground SMOKE MEDIA CENTER OVER LAB AREA	Visually Checked	10:52:12 AM	03/25/2020
Smoke Detector	Ground SMOKE MEDIA CENTER OVER READING AREA	Visually Checked	10:52:10 AM	03/25/2020
Smoke Detector	Ground SMOKE MEDIA CENTER OVER READING AREA	Visually Checked	10:52:12 AM	03/25/2020

Service Summary

Generated by: BuildingReports.com

Building: Stamford BOE Springdale EST

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Passed</i>		
Annunciator	Visually Checked	1
Battery	Tested	5
Communicator	Visually Checked	1
Control Panel	Visually Checked	1
Duct Detector	Visually Checked	14
Heat Detector	Visually Checked	9
Pull Station	Visually Checked	25
Smoke Detector	Visually Checked	99
Total		155
Grand Total		155






Auxiliary Functions Testing

Generated by: BuildingReports.com

Building: Stamford BOE Springdale EST			Control Panel: 1 - EST 3X	
<i>The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.</i>				
Type	Location	Comment	ScanID	Simulated
<i>Passed</i>				
Heat Detector				
Shunt Trip	Ground HEAT ELEVATOR MACHINE ROOM	Passed	23585768	
Smoke Detector				
Elevator Recall	1st SMOKE 1ST FLR ELEVATOR LOBBY	Passed	23586903	
Elevator Recall	Ground SMOKE ELEVATOR MACHINE ROOM	Passed	23585769	
Elevator Recall	Ground SMOKE MEDIA CENTER ELEVATOR LOBBY	Passed	23585770	

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE Springdale EST							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		 dB	 dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
whole facility				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE Springdale EST				Control Panel: 1 - EST 3X			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	1st Fire Panel Room	5	12	12.66V	6.5Ah		
Sealed Lead Acid	1st Fire Panel Room	26	12	13.34V	14Ah		
Sealed Lead Acid	1st Fire Panel Room(Communicator)	5	12	12.84V	7Ah		
Sealed Lead Acid	1st BOILER ROOM STORAGE AREA	8	12	12.82V	8Ah		
Sealed Lead Acid	3rd FLR NORTH STORAGE ROOM	7	12	12.91V	11Ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE Springdale EST				Control Panel: 1 - EST 3X	
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		0.64%	1
Annunciator		Control		0.64%	1
Smoke Detector		Initiating		63.46%	99
Battery		Control		3.21%	5
Duct Detector		Initiating		8.97%	14
Heat Detector		Initiating		5.77%	9
Control Panel		Control		0.64%	1
Communicator		Control		0.64%	1
Pull Station		Initiating		16.03%	25
Type	Qty	Model #	Description		Install Date
In Service - 90 Days - 1 Year					
EST					
Smoke Detector	1	SIGA2-PS			07/23/2019
In Service - 2 Years to 3 Years					
Power-Sonic					
Battery	1	PS-1270 F1	Sealed Lead Acid		08/29/2017
In Service - 5 Years to 10 Years					
EST					
Annunciator	1	EST3	LCD Display		07/11/2014
Control Panel	1	3X			07/11/2014
Duct Detector	14	SIGA-SD	Photoelectric		07/11/2014
Heat Detector	1	283B	Fixed Temperature		07/11/2014
Heat Detector	8	SIGA2-HFS	Fixed Temperature		07/11/2014
Pull Station	1	278	Dual Action		07/11/2014
Pull Station	24	SIGA-278	Dual Action		07/11/2014
Smoke Detector	1	PS	Photoelectric		07/11/2014
Smoke Detector	97	SIGA2-PS	Photoelectric		07/11/2014
Leoch					
Battery	1	DJW12-26	Sealed Lead Acid		07/11/2014
LEOCH					
Battery	1	DJW12-7.2	Sealed Lead Acid		07/11/2014
Notifier					
Communicator	1	911A	Digital Communicator		07/11/2014
Universal					

Battery	2	UB1250	Sealed Lead Acid	07/11/2014
---------	---	--------	------------------	------------

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE Springdale EST

Control Panel: 1 - EST 3X

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 03				
0001	Smoke Detector	1st SMOKE HALL OUTSIDE AUDITORIUM	Photoelectric	23585753
0002	Smoke Detector	1st SMOKE HALL BETWEEN AUDITORIUM & MEDIA	Photoelectric	23585752
0003	Smoke Detector	1st SMOKE NEAR STAGE ENTRANCE	Photoelectric	23585754
0004	Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #1	Photoelectric	23587208
0005	Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #2	Photoelectric	23587211
0006	Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #3	Photoelectric	23587216
0007	Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #4	Photoelectric	23587217
0008	Heat Detector	1st HEAT GRND FLR EAST GYM OFFICE	Fixed Temperature	23587236
0009	Heat Detector	1st HEAT GRND FLR EAST GYM CLOSET	Fixed Temperature	23587223
0010	Heat Detector	1st HEAT GRND FLR EAST CUSTODIANS CLOSET	Fixed Temperature	23587224
0011	Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #10	Photoelectric	23587222
0012	Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #9	Photoelectric	23587221
0013	Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #8	Photoelectric	23587218
0014	Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #7	Photoelectric	23587215
0015	Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #6	Photoelectric	23587212
0016	Smoke Detector	1st SMOKE GRND FLR EAST CLASSROOM #5	Photoelectric	23587210
0017	Smoke Detector	1st SMOKE GRND FLR EAST NEAR EAST EXIT	Photoelectric	23587209
0018	Smoke Detector	1st SMOKE GRND FLR EAST CORRIDOR	Photoelectric	23587213
0019	Smoke Detector	1st SMOKE GRND FLR EAST CORRIDOR	Photoelectric	23587214
0020	Smoke Detector	1st SMOKE GRND FLR EAST CORRIDOR	Photoelectric	23587219
0021	Smoke Detector	1st SMOKE GRND FLR EAST CORRIDOR	Photoelectric	23587220
0022	Smoke Detector	1st SMOKE GRND FLR EAST CORRIDOR	Photoelectric	23587225
0023	Smoke Detector	Ground SMOKE GRND FLR EAST BY DOUBLE DR IN GYM	Photoelectric	23585759
0024	Smoke Detector	Ground SMOKE GRND FLR EAST GYM DOOR TO LOBBY	Photoelectric	23585758
0025	Smoke Detector	Ground SMOKE GROUND FLR UPPER	Photoelectric	23586898

		HALL TO MEDIA		
0026	Smoke Detector	1st SMOKE 1ST FLR ELEVATOR LOBBY	Photoelectric	23586903
0027	Smoke Detector	1st SMOKE 1ST FLR BY MAIN OFFICE	Photoelectric	23586893
0028	Smoke Detector	1st SMOKE 1ST FLR MAIN OFFICE	Photoelectric	51385742
		STORAGE		
0029	Smoke Detector	1st SMOKE 1ST FLR LOBBY OUTSIDE	Photoelectric	23586902
		MAIN OFFICE		
0030	Heat Detector	1st HEAT BOILER ROOM STORAGE AREA	Fixed Temperature	23587227
0031	Heat Detector	1st HEAT BOILER ROOM BY INTERIOR	Fixed Temperature	20666948
		STAIR		
0032	Heat Detector	1st HEAT BOILER ROOM BY EXTERIOR	Fixed Temperature	20666947
		STAIR		
0033	Smoke Detector	1st SMOKE 1ST FLR BACK ENTRY BY OFF.	Photoelectric	23586894
0034	Smoke Detector	1st SMOKE 1ST FLR BY NURSES OFFICE	Photoelectric	23586891
0035	Smoke Detector	1st SMOKE AUDITORIUM BACKSTAGE	Photoelectric	23586912
		LEFT		
0036	Smoke Detector	1st SMOKE AUDITORIUM BACKSTAGE	Photoelectric	23586911
		RIGHT		
0037	Smoke Detector	1st SMOKE AUDITORIUM FRONT LEFT	Photoelectric	23586908
0038	Smoke Detector	1st SMOKE AUDITORIUM FRONT RIGHT	Photoelectric	23586909
0039	Smoke Detector	1st SMOKE AUDITORIUM CENTER LEFT	Photoelectric	23586910
0040	Smoke Detector	1st SMOKE AUDITORIUM CENTER RIGHT	Photoelectric	23586907
0041	Smoke Detector	1st SMOKE AUDITORIUM REAR LEFT	Photoelectric	23587001
0042	Smoke Detector	1st SMOKE AUDITORIUM REAR RIGHT	Photoelectric	23587000
0043	Smoke Detector	Ground SMOKE IN STORAGE RM BEHIND	Photoelectric	23587232
		ELEVATOR RM		
0044	Smoke Detector	Ground SMOKE IN ELEC ROOM IN MEDIA	Photoelectric	23587002
		CENTER		
0045	Smoke Detector	Ground SMOKE ELEVATOR MACHINE	Photoelectric	23585769
		ROOM		
0046	Heat Detector	Ground HEAT ELEVATOR MACHINE	Fixed Temperature	23585768
		ROOM		
0047	Smoke Detector	2nd SMOKE 2ND FLR WEST AT NORTH	Photoelectric	23585783
		STAIR		
0048	Smoke Detector	2nd SMOKE 2ND FLR WEST BY ROOM	Photoelectric	23585782
		104A		
0049	Smoke Detector	2nd SMOKE 2ND FLR WEST BY ROOM	Photoelectric	23585781
		109/110		
0050	Smoke Detector	2nd SMOKE 2ND FLR WEST STORAGE	Photoelectric	23587234
		ROOM		
0051	Smoke Detector	2nd SMOKE 2ND FLR WEST BY ROOM 106	Photoelectric	23585780
0052	Smoke Detector	2nd SMOKE 2ND FLR WEST AT SOUTH	Photoelectric	23585779
		STAIR		
0053	Smoke Detector	2nd SMOKE 2ND FLR CENTER AT FIRE	Photoelectric	51385741
		DOOR		
0054	Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM	Photoelectric	23585797
		118		
0055	Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM	Photoelectric	23586932
		117		
0056	Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM	Photoelectric	23585799
		116		
0057	Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM	Photoelectric	23585798
		115		

0058	Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 114	Photoelectric	23585793
0059	Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 113	Photoelectric	23585792
0060	Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 112	Photoelectric	23585790
0061	Smoke Detector	2nd SMOKE 2ND FL CENTER CLASSROOM 111	Photoelectric	23585788
0062	Smoke Detector	2nd SMOKE 2ND FL CENTER CORRIDOR BY BOYS RM	Photoelectric	23585785
0064	Smoke Detector	2nd SMOKE 2ND FL CENTER STORAGE IN RM 112	Photoelectric	23585791
0065	Smoke Detector	2nd SMOKE 2ND FL CENTER AT FIRE DOOR BY 111	Photoelectric	23585789
0066	Smoke Detector	2nd SMOKE 2ND FL CENTER UTILITY ROOM	Photoelectric	23585786
0067	Smoke Detector	2nd SMOKE 2ND FL CENTER IN EAST STAIR	Photoelectric	23585794
0068	Heat Detector	2nd HEAT 2ND FL CENTER CUSTODIAN CLOSET	Fixed Temperature	23587233
0069	Duct Detector	2nd DUCTSMOKE RETURN MEDIA CENTER	Photoelectric	51385739
0070	Duct Detector	2nd DUCTSMOKE SUPPLY MEDIA CENTER	Photoelectric	51385740
0071	Duct Detector	Roof DUCTSMOKE RTU-1 RET AUDITORIUM	Photoelectric	23587230
0072	Duct Detector	DUCTSMOKE RTU-1 SUP AUDITORIUM	Photoelectric	23586944
0073	Duct Detector	Roof DUCTSMOKE RTU-2 RET AUDITORIUM	Photoelectric	23587229
0074	Duct Detector	DUCTSMOKE RTU-2 SUP AUDITORIUM	Photoelectric	23587239
0075	Smoke Detector	3rd SMOKE 3RD FLR NORTH IN NORTH STAIR	Photoelectric	23586924
0076	Smoke Detector	3rd SMOKE 3RD FLR NORTH ELEVATOR LOBBY	Photoelectric	23586921
0077	Smoke Detector	3rd SMOKE 3RD FLR NORTH IN SMALL HALL	Photoelectric	23586922
0078	Smoke Detector	3rd SMOKE 3RD FLR NORTH NEAR NORTH STAIR	Photoelectric	23586926
0079	Smoke Detector	3rd SMOKE 3RD FLR NORTH BY ROOM 204	Photoelectric	23586927
0080	Smoke Detector	3rd SMOKE 3RD FLR NORTH BY ROOM 205/206	Photoelectric	23586928
0081	Smoke Detector	3rd SMOKE 3RD FLR NORTH NEAR SOUTH STAIR	Photoelectric	23586929
0082	Smoke Detector	3rd SMOKE 3RD FLR NORTH SOUTH STAIR	Photoelectric	23586931
0083	Smoke Detector	3rd SMOKE 3RD FLR NORTH CUSTODIAN CLOSET	Photoelectric	51385737
0084	Smoke Detector	3rd SMOKE 3RD FLR NORTH STORAGE ROOM	Photoelectric	23586923
0085	Smoke Detector	Ground SMOKE GND FL OUTSIDE MEDIA CTR DOUBLE DR	Photoelectric	23585756
0086	Smoke Detector	Ground SMOKE MEDIA CENTER OVER READING AREA	Photoelectric	23585775

0087	Smoke Detector	Ground SMOKE MEDIA CENTER BY STAIRS	Photoelectric	23585776
0088	Smoke Detector	Ground SMOKE MEDIA CENTER OVER READING AREA	Photoelectric	23585777
0089	Smoke Detector	Ground SMOKE MEDIA CENTER OVER LAB AREA	Photoelectric	23585778
0090	Smoke Detector	1st SMOKE MEDIA CENTER THERAPIST ROOM	Photoelectric	23587003
0091	Smoke Detector	Ground SMOKE MEDIA CENTER BY MECH ROOM	Photoelectric	23585767
0092	Smoke Detector	Ground SMOKE MEDIA CENTER BY MEDIA LAB	Photoelectric	23585771
0093	Smoke Detector	Ground SMOKE MEDIA CENTER IN MEDIA LAB	Photoelectric	23585772
0094	Smoke Detector	Ground SMOKE MEDIA CENTER OFFICE	Photoelectric	23585773
0095	Smoke Detector	Ground SMOKE MEDIA CENTER AID/VOLUNTEER AREA	Photoelectric	23585774
0096	Smoke Detector	Ground SMOKE MEDIA CENTER ELEVATOR LOBBY	Photoelectric	23585770
0097	Smoke Detector	1st SMOKE GYM FRONT LEFT	Photoelectric	23585764
0098	Smoke Detector	1st SMOKE GYM FRONT RIGHT	Photoelectric	23585765
0099	Smoke Detector	1st SMOKE GYM REAR LEFT	Photoelectric	23585762
0100	Smoke Detector	1st SMOKE GYM REAR RIGHT	Photoelectric	23585763
0101	Smoke Detector	1st SMOKE 1ST FL WEST AT SOUTH STAIR	Photoelectric	23586878
0102	Smoke Detector	1st SMOKE CORRIDOR BY CUSTODIANS OFFICE	Photoelectric	23586880
0103	Smoke Detector	1st SMOKE ART RESOURCE ROOM	Photoelectric	23586881
0104	Smoke Detector	1st SMOKE 1ST FL WEST BY ART ROOM	Photoelectric	23586885
0105	Smoke Detector	1st SMOKE 1ST FL WEST STORAGE RM BY ART	Photoelectric	23586884
0106	Smoke Detector	1st SMOKE 1ST FL WEST STORAGE @ SPEECH RM	Photoelectric	23586886
0107	Smoke Detector	1st SMOKE 1ST FL WEST OVER RAMP	Photoelectric	23586888
0108	Smoke Detector	1st SMOKE 1ST FL WEST LARGE STORAGE RM	Photoelectric	23586890
0109	Smoke Detector	1st SMOKE 1ST FL WEST LARGE STORAGE RM	Photoelectric	23586889
0110	Smoke Detector	1st SMOKE 1ST FL CUSTODIANS ROOM	Photoelectric	23586877
0111	Smoke Detector	1st SMOKE 1ST FL STORAGE/SPRINKLER	Photoelectric	23586883
0112	Smoke Detector	1st SMOKE 1ST FL MAIN ELECTRICAL RM	Photoelectric	23587231
0113	Duct Detector	3rd DUCTSMOKE RTU SUPPLY WEST WING NORTH	Photoelectric	23586920
0114	Duct Detector	3rd DUCTSMOKE RTU RETURN WEST WING NORTH	Photoelectric	23586919
0115	Duct Detector	3rd DUCTSMOKE RTU RETURN WEST WING NORTH	Photoelectric	23586917
0116	Duct Detector	3rd DUCTSMOKE RTU SUPPLY WEST WING NORTH	Photoelectric	23586918
0117	Duct Detector	3rd DUCTSMOKE RTU RETURN WEST WING SOUTH	Photoelectric	23586915
0118	Duct Detector	3rd DUCTSMOKE RTU SUPPLY WEST WING SOUTH	Photoelectric	23586916
0119	Duct Detector	3rd DUCTSMOKE RTU RETURN WEST WING SOUTH	Photoelectric	23586913

0120	Duct Detector	3rd DUCTSMOKE RTU SUPPLY WEST WING SOUTH	Photoelectric	23586914
0121	Smoke Detector	1st SMOKE 1ST FLR MAIN ENTRANCE	Photoelectric	23586899
0131	Pull Station	Ground PULLSTATION MEDIA CENTER	Dual Action	23585757
0132	Pull Station	1st PULLSTATION ENTRANCE BY GYM	Dual Action	23585755
0133	Pull Station	1st PULL BY NURSES OFF AT NORTH STAIR	Dual Action	23586892
0134	Pull Station	1st PULL GRND FLR EAST EAST EXIT	Dual Action	23587207
0135	Pull Station	1st PULL GRND FLR EAST BY BATHROOMS	Dual Action	23587226
0136	Pull Station	1st PULL REAR ENTRANCE TO MAIN OFFICE	Dual Action	23586895
0137	Pull Station	1st PULLSTATION MAIN OFFICE	Dual Action	23586896
0138	Pull Station	1st PULLSTATION BOILER ROOM	Dual Action	23587228
0139	Pull Station	1st PULL AUDITORIUM BACKSTAGE RIGHT	Dual Action	23587006
0140	Pull Station	1st PULL AUDITORIUM EXIT STAGE LEFT	Dual Action	23587007
0141	Pull Station	1st PULL AUDITORIUM RIGHT FRONT	Dual Action	23586904
0142	Pull Station	1st PULL AUDITORIUM REAR LEFT	Dual Action	23586906
0143	Pull Station	1st PULL AUDITORIUM REAR RIGHT	Dual Action	23586905
0149	Pull Station	2nd PULL 2ND FL WEST AT NORTH STAIR	Dual Action	23585784
0150	Pull Station	2nd PULL 2ND FL WEST AT SOUTH STAIR	Dual Action	23587005
0151	Pull Station	2nd PULL 2ND FL CENTER AT EAST STAIR	Dual Action	23585796
0154	Pull Station	3rd PULL 3RD FL NORTH AT NORTH STAIR	Dual Action	23586925
0155	Pull Station	3rd PULL 3RD FL WEST AT SOUTH STAIR	Dual Action	23586930
0156	Pull Station	Ground PULL MEDIA CENTER	Dual Action	23585766
0157	Pull Station	1st PULLSTATION KITCHEN	Dual Action	23587004
0158	Pull Station	1st PULLSTATION GYM	Dual Action	23585760
0159	Pull Station	1st PULL 1ST FL WEST AT SOUTH STAIR	Dual Action	23586879
0160	Heat Detector	Penthouse ATTIC HEAT DETECTORS	Fixed Temperature	4826612850
0167	Pull Station	1st PULLSTATION SIDE ENTRANCE	Dual Action	23586882
0168	Pull Station	1st PULLSTATION MAIN ENTRANCE	Dual Action	23586900
0169	Pull Station	1st PULLSTATION GYM	Dual Action	23585761

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Julia Stark School
398 Glenbrook Road
Stamford, CT 06902

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Apr 8, 2020

Building: Stamford BOE-Julia Stark School
Contact: Davor Lucaj
Title: Facilities Trades Manager



Company: TPC Associates, Inc.
Contact: Landon Gendreau
Title: Inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Julia Stark School	Contact: Davor Lucaj	
Address: 398 Glenbrook Road	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06902	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Landon Gendreau	
Address: 261 Pepe's Farm Road	Phone: 2038781321	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: landon.gendreau@tpcsystems.com	
System Control Unit		
Manufacturer: Edwards	Inspection Date: 04/08/2020	IDC Style:
Model Number: iO 1000	Install Date: 07/22/2012	SLC Style:
Software Version:	Version Date: 08/08/2012	NAC Style:
Location: Basement Electrical/Panel Room Main Panel	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.52%	0	0%	0	0%	0	0%
Control	6	3.09%	6	100.00%	6	100.00%	0	0%
Initiating	187	96.39%	187	100.00%	187	100.00%	0	0%
Totals	194	100%	193	99.48%	193	100.00%	0	0%

Certification	
<p>Company: TPC Associates, Inc.</p> <p>Inspector: Landon Gendreau</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px 0;">  </div> <p>Signed: Apr 8, 2020 9:24:52 AM</p>	<p>Building: Stamford BOE-Julia Stark School</p> <p>Contact: Davor Lucaj</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px 0;">  </div> <p>Signed: Apr 8, 2020 9:23:51 AM</p>

Notes & Recommendations

Generated by: BuildingReports.com

Building: Stamford BOE-Julia Stark School				
<i>The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.</i>				
General Note				
upon activation of alarm all fire doors operated accordingly				
Building: Stamford BOE-Julia Stark School Control Panel: 1 - Edwards iO 1000				
ScanID	Note	Device Type	Location	Comment
Control				
56180434	2	Battery	Basement Electrical/Panel Room Top Booster	Passed
*REPLACED BY TPC 8-20-19				

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Julia Stark School		Control Panel: 1 - Edwards iO 1000		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
<i>Passed</i>				
Control				
Battery	Basement Electrical/Panel Room Bottom Booster	Tested	9:05:20 AM	04/08/2020
Battery	Basement Electrical/Panel Room Center Booster	Tested	9:06:47 AM	04/08/2020
Battery	Basement Electrical/Panel Room Dialer	Tested	9:12:57 AM	04/08/2020
Battery	Basement Electrical/Panel Room Main Panel	Tested	9:12:37 AM	04/08/2020
Battery	Basement Electrical/Panel Room Top Booster	Tested	9:08:11 AM	04/08/2020
Control Panel	Basement Electrical/Panel Room Main Panel	Visually Checked	9:11:03 AM	04/08/2020
Initiating				
Duct Detector	1st Faculty Dining AC 1 Return	Visually Checked	8:55:58 AM	04/08/2020
Duct Detector	1st Faculty Dining AC 1 Supply	Visually Checked	8:55:35 AM	04/08/2020
Duct Detector	1st Gym (Need Lift)	Visually Checked	8:33:03 AM	04/08/2020
Duct Detector	1st Gym (Need Lift)	Visually Checked	8:33:10 AM	04/08/2020
Duct Detector	1st Gym (Need Lift)	Visually Checked	8:33:16 AM	04/08/2020
Duct Detector	2nd By Room 209 Return	Visually Checked	8:01:18 AM	04/08/2020
Duct Detector	2nd By Room 209 Supply	Visually Checked	8:01:34 AM	04/08/2020
Duct Detector	2nd AC 2 Girls bathroom by ramp	Visually Checked	8:23:32 AM	04/08/2020
Duct Detector	2nd AC 2 Return By Room 241	Visually Checked	8:16:21 AM	04/08/2020
Duct Detector	2nd AC 2 Supply By Room 244	Visually Checked	8:15:48 AM	04/08/2020
Duct Detector	2nd By Room 245 AC 5 Return	Visually Checked	8:15:00 AM	04/08/2020
Duct Detector	2nd By Room 245 AC 5 Supply	Visually Checked	8:14:44 AM	04/08/2020
Duct Detector	2nd By Room 246 EF 3	Visually Checked	8:22:56 AM	04/08/2020
Duct Detector	2nd By Room 254 AC 6 Supply	Visually Checked	8:12:53 AM	04/08/2020
Duct Detector	2nd By Room 254 AC6 Return	Visually Checked	8:13:26 AM	04/08/2020
Duct Detector	2nd By Room 254 EF-4	Visually Checked	8:13:10 AM	04/08/2020
Duct Detector	2nd EF 16 By Room 244	Visually Checked	8:15:55 AM	04/08/2020
Duct Detector	2nd Room 212 Storage EF-1	Visually Checked	7:58:43 AM	04/08/2020
Duct Detector	Penthouse AC 4 Return	Visually Checked	7:41:29 AM	04/08/2020
Duct Detector	Penthouse AC 4 Supply	Visually Checked	7:41:12 AM	04/08/2020
Duct Detector	Penthouse EF 11	Visually Checked	7:43:21 AM	04/08/2020
Duct Detector	Penthouse EF-1 Return	Visually Checked	7:44:42 AM	04/08/2020
Heat Detector	Basement Above Boiler	Visually Checked	9:18:54 AM	04/08/2020
Heat Detector	Basement Above Boiler Tank	Visually Checked	9:16:11 AM	04/08/2020
Heat Detector	Basement Above Boiler Tank	Visually Checked	9:19:52 AM	04/08/2020
Heat Detector	1st Kitchen	Visually Checked	8:36:37 AM	04/08/2020
Heat Detector	1st Kitchen	Visually Checked	8:36:52 AM	04/08/2020
Pull Station	Basement Exit	Visually Checked	9:19:37 AM	04/08/2020
Pull Station	Basement Office Space	Visually Checked	9:01:48 AM	04/08/2020
Pull Station	1st By Faculty Dining	Visually Checked	8:56:37 AM	04/08/2020
Pull Station	1st Exit By Room 105	Visually Checked	8:26:08 AM	04/08/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	1st Stair Exit By Room 105	Visually Checked	8:25:44 AM	04/08/2020
Pull Station	1st Stair Exit By Room 105	Visually Checked	8:25:53 AM	04/08/2020
Pull Station	1st Auditorium Exit	Visually Checked	8:41:35 AM	04/08/2020
Pull Station	1st Auditorium Side Exit	Visually Checked	9:00:55 AM	04/08/2020
Pull Station	1st By Media Center	Visually Checked	8:31:44 AM	04/08/2020
Pull Station	1st By Room 101	Visually Checked	8:29:16 AM	04/08/2020
Pull Station	1st By Room 119	Visually Checked	8:24:52 AM	04/08/2020
Pull Station	1st Cafe Exit	Visually Checked	8:56:50 AM	04/08/2020
Pull Station	1st Cafe Exit	Visually Checked	8:58:53 AM	04/08/2020
Pull Station	1st Cafe Serving Area	Visually Checked	8:35:52 AM	04/08/2020
Pull Station	1st Corridor By Auditorium	Visually Checked	8:38:04 AM	04/08/2020
Pull Station	1st Corridor By Room 143 /Stage	Visually Checked	8:50:04 AM	04/08/2020
Pull Station	1st Corridor to New Section	Visually Checked	8:27:58 AM	04/08/2020
Pull Station	1st Elevator Lobby	Visually Checked	8:51:09 AM	04/08/2020
Pull Station	1st Main Lobby	Visually Checked	8:59:14 AM	04/08/2020
Pull Station	1st Main Lobby By Principals Office	Visually Checked	8:58:01 AM	04/08/2020
Pull Station	2nd By Room 201	Visually Checked	8:02:29 AM	04/08/2020
Pull Station	2nd Area of Refuge by Room 201	Visually Checked	8:03:02 AM	04/08/2020
Pull Station	2nd By Room 204	Visually Checked	8:05:35 AM	04/08/2020
Pull Station	2nd By Room 220	Visually Checked	7:48:38 AM	04/08/2020
Pull Station	2nd By Room 224	Visually Checked	8:22:19 AM	04/08/2020
Pull Station	2nd By Room 230	Visually Checked	8:18:51 AM	04/08/2020
Pull Station	2nd By Room 244	Visually Checked	8:15:35 AM	04/08/2020
Pull Station	2nd By Room 249	Visually Checked	8:07:49 AM	04/08/2020
Pull Station	2nd Elevator Lobby	Visually Checked	8:11:43 AM	04/08/2020
Pull Station	2nd Top of Stairs by Room 255	Visually Checked	8:22:45 AM	04/08/2020
Pull Station	Penthouse Entrance/ Exit (Unit Shut Down)	Visually Checked	7:40:51 AM	04/08/2020
Smoke Detector	Basement Corridor	Visually Checked	9:19:10 AM	04/08/2020
Smoke Detector	Basement Electrical/Panel Room	Visually Checked	9:04:26 AM	04/08/2020
Smoke Detector	Basement Electrical/Panel Room	Visually Checked	9:06:39 AM	04/08/2020
Smoke Detector	Basement Fire Pump rm	Visually Checked	9:03:20 AM	04/08/2020
Smoke Detector	Basement Gas Room	Visually Checked	9:17:26 AM	04/08/2020
Smoke Detector	Basement Office Space	Visually Checked	9:00:25 AM	04/08/2020
Smoke Detector	Basement Storage	Visually Checked	9:02:38 AM	04/08/2020
Smoke Detector	1st By Janitors Closet	Visually Checked	8:28:20 AM	04/08/2020
Smoke Detector	1st Exit By Room 105	Visually Checked	8:26:27 AM	04/08/2020
Smoke Detector	1st Stairs By Elevator Lobby	Visually Checked	9:01:19 AM	04/08/2020
Smoke Detector	1st Stairs By Elevator Lobby	Visually Checked	9:01:31 AM	04/08/2020
Smoke Detector	1st Storage By Room 167	Visually Checked	9:01:07 AM	04/08/2020
Smoke Detector	1st Auditorium	Visually Checked	8:41:08 AM	04/08/2020
Smoke Detector	1st Auditorium	Visually Checked	8:41:56 AM	04/08/2020
Smoke Detector	1st Auditorium	Visually Checked	8:42:03 AM	04/08/2020
Smoke Detector	1st Auditorium	Visually Checked	8:42:09 AM	04/08/2020
Smoke Detector	1st Auditorium	Visually Checked	8:42:15 AM	04/08/2020
Smoke Detector	1st Auditorium	Visually Checked	8:42:20 AM	04/08/2020
Smoke Detector	1st Auditorium	Visually Checked	8:42:26 AM	04/08/2020
Smoke Detector	1st Auditorium Side Exit	Visually Checked	9:00:50 AM	04/08/2020
Smoke Detector	1st By Elevator Lobby	Visually Checked	8:51:02 AM	04/08/2020
Smoke Detector	1st By Faculty Dining	Visually Checked	8:54:59 AM	04/08/2020
Smoke Detector	1st By Media Center	Visually Checked	8:31:33 AM	04/08/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st By Media Center	Visually Checked	8:32:01 AM	04/08/2020
Smoke Detector	1st By Room 101	Visually Checked	8:29:03 AM	04/08/2020
Smoke Detector	1st By Room 103	Visually Checked	8:28:37 AM	04/08/2020
Smoke Detector	1st By Room 117	Visually Checked	8:25:26 AM	04/08/2020
Smoke Detector	1st By Room 119	Visually Checked	8:25:10 AM	04/08/2020
Smoke Detector	1st By Room 121	Visually Checked	8:24:41 AM	04/08/2020
Smoke Detector	1st By Room 133 Heath Services	Visually Checked	8:54:30 AM	04/08/2020
Smoke Detector	1st By Room 143/Stage	Tested/Cleaned	8:44:58 AM	04/08/2020
Smoke Detector	1st By Room 157	Visually Checked	8:50:19 AM	04/08/2020
Smoke Detector	1st By Room 157	Visually Checked	8:50:33 AM	04/08/2020
Smoke Detector	1st By Room 167	Visually Checked	8:50:49 AM	04/08/2020
Smoke Detector	1st Cafe Serving Area	Visually Checked	8:35:46 AM	04/08/2020
Smoke Detector	1st Corridor By Room 101	Visually Checked	8:29:42 AM	04/08/2020
Smoke Detector	1st Corridor Between Media Center And Gym	Visually Checked	8:32:22 AM	04/08/2020
Smoke Detector	1st Corridor Between Media Center And Gym	Tested/Cleaned	8:45:21 AM	04/08/2020
Smoke Detector	1st Corridor Between Media Center And Gym	Visually Checked	8:45:36 AM	04/08/2020
Smoke Detector	1st Corridor By Auditorium	Visually Checked	8:58:26 AM	04/08/2020
Smoke Detector	1st Corridor By Room 143	Visually Checked	8:40:01 AM	04/08/2020
Smoke Detector	1st Corridor to New Section	Visually Checked	8:27:27 AM	04/08/2020
Smoke Detector	1st Corridor to New Section	Visually Checked	8:27:45 AM	04/08/2020
Smoke Detector	1st Faculty Dining	Visually Checked	8:55:16 AM	04/08/2020
Smoke Detector	1st Janitors Closet	Visually Checked	8:59:01 AM	04/08/2020
Smoke Detector	1st Kitchen Storage	Visually Checked	8:58:19 AM	04/08/2020
Smoke Detector	1st Main Lobby	Visually Checked	8:53:24 AM	04/08/2020
Smoke Detector	1st Main Lobby by Conference Room	Visually Checked	8:31:13 AM	04/08/2020
Smoke Detector	1st Main Lobby by Principals Office	Visually Checked	8:24:18 AM	04/08/2020
Smoke Detector	1st Main Lobby by Storage	Visually Checked	8:58:10 AM	04/08/2020
Smoke Detector	1st Media Center Computer Lab	Visually Checked	8:46:26 AM	04/08/2020
Smoke Detector	1st Media Center Computer Lab	Visually Checked	8:46:46 AM	04/08/2020
Smoke Detector	1st Media Center Kitchennet	Visually Checked	8:48:47 AM	04/08/2020
Smoke Detector	1st Media Center	Visually Checked	8:46:07 AM	04/08/2020
Smoke Detector	1st Media Center	Visually Checked	8:47:08 AM	04/08/2020
Smoke Detector	1st Media Center	Visually Checked	8:47:23 AM	04/08/2020
Smoke Detector	1st Media Center	Visually Checked	8:47:37 AM	04/08/2020
Smoke Detector	1st Media Center	Visually Checked	8:47:52 AM	04/08/2020
Smoke Detector	1st Media Center	Visually Checked	8:49:07 AM	04/08/2020
Smoke Detector	1st Media Center Side Room	Visually Checked	8:48:15 AM	04/08/2020
Smoke Detector	1st Media Center Side Room	Visually Checked	8:51:59 AM	04/08/2020
Smoke Detector	1st Outside Custodians Office	Visually Checked	8:35:07 AM	04/08/2020
Smoke Detector	1st Outside Custodians Office	Visually Checked	8:37:56 AM	04/08/2020
Smoke Detector	1st Room 143	Visually Checked	9:00:05 AM	04/08/2020
Smoke Detector	1st Stage Left	Visually Checked	8:58:42 AM	04/08/2020
Smoke Detector	1st Stage Right	Visually Checked	8:58:34 AM	04/08/2020
Smoke Detector	1st Storage	Visually Checked	8:39:22 AM	04/08/2020
Smoke Detector	1st Storage	Visually Checked	8:39:39 AM	04/08/2020
Smoke Detector	1st Storage by Room 157	Visually Checked	9:01:01 AM	04/08/2020
Smoke Detector	1st Storage Closet – IGA	Visually Checked	9:00:43 AM	04/08/2020
Smoke Detector	1st Storage Closet by Principals Office	Visually Checked	9:00:37 AM	04/08/2020
Smoke Detector	1st Storage/Locker Area	Visually Checked	8:38:29 AM	04/08/2020
Smoke Detector	1st Storage/Locker Area	Visually Checked	8:38:44 AM	04/08/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Storeroom By Room 101	Visually Checked	9:00:17 AM	04/08/2020
Smoke Detector	2nd Adult Restroom By Room 201	Visually Checked	8:22:38 AM	04/08/2020
Smoke Detector	2nd By Room 209	Visually Checked	8:00:12 AM	04/08/2020
Smoke Detector	2nd By Room 253	Visually Checked	8:11:30 AM	04/08/2020
Smoke Detector	2nd Janitors Closet By Room 201	Visually Checked	8:22:31 AM	04/08/2020
Smoke Detector	2nd Janitors Closet By Room 252	Visually Checked	8:09:42 AM	04/08/2020
Smoke Detector	2nd Storage By Room 230	Visually Checked	8:22:04 AM	04/08/2020
Smoke Detector	2nd Top of Stair By Room 220	Visually Checked	8:22:10 AM	04/08/2020
Smoke Detector	2nd Top of Stairs By Room 249	Visually Checked	8:08:17 AM	04/08/2020
Smoke Detector	2nd Area of Refuge by Room 201	Visually Checked	8:03:16 AM	04/08/2020
Smoke Detector	2nd By Room 201	Visually Checked	8:02:46 AM	04/08/2020
Smoke Detector	2nd By Room 202	Visually Checked	8:04:25 AM	04/08/2020
Smoke Detector	2nd By Room 203	Visually Checked	8:04:48 AM	04/08/2020
Smoke Detector	2nd By Room 204	Visually Checked	8:05:14 AM	04/08/2020
Smoke Detector	2nd By Room 206	Visually Checked	8:06:18 AM	04/08/2020
Smoke Detector	2nd By Room 211	Visually Checked	7:52:03 AM	04/08/2020
Smoke Detector	2nd By Room 219	Visually Checked	7:48:03 AM	04/08/2020
Smoke Detector	2nd By Room 220	Visually Checked	7:48:18 AM	04/08/2020
Smoke Detector	2nd By Room 222	Visually Checked	7:47:44 AM	04/08/2020
Smoke Detector	2nd By Room 224	Visually Checked	7:47:27 AM	04/08/2020
Smoke Detector	2nd By Room 228	Visually Checked	8:19:11 AM	04/08/2020
Smoke Detector	2nd By Room 230	Visually Checked	8:18:34 AM	04/08/2020
Smoke Detector	2nd By Room 234	Visually Checked	8:18:05 AM	04/08/2020
Smoke Detector	2nd By Room 241	Visually Checked	8:16:13 AM	04/08/2020
Smoke Detector	2nd By Room 241	Visually Checked	8:17:23 AM	04/08/2020
Smoke Detector	2nd By Room 244	Visually Checked	8:15:25 AM	04/08/2020
Smoke Detector	2nd By Room 246 By Firedoors	Visually Checked	8:15:15 AM	04/08/2020
Smoke Detector	2nd By Room 246	Visually Checked	8:14:23 AM	04/08/2020
Smoke Detector	2nd By Room 249	Visually Checked	8:08:32 AM	04/08/2020
Smoke Detector	2nd By Room 250	Visually Checked	8:09:06 AM	04/08/2020
Smoke Detector	2nd By Room 253	Visually Checked	8:10:52 AM	04/08/2020
Smoke Detector	2nd Corridor By Room 220	Visually Checked	7:50:08 AM	04/08/2020
Smoke Detector	2nd Corridor By Room 206	Visually Checked	8:06:49 AM	04/08/2020
Smoke Detector	2nd Corridor By Room 206 By Firedoors	Visually Checked	8:07:35 AM	04/08/2020
Smoke Detector	2nd Corridor to New Section	Visually Checked	7:50:32 AM	04/08/2020
Smoke Detector	2nd Room 209 Storage	Visually Checked	8:00:48 AM	04/08/2020
Smoke Detector	2nd Room 210 Storage	Visually Checked	7:57:30 AM	04/08/2020
Smoke Detector	2nd Room 211 Storage	Visually Checked	7:56:17 AM	04/08/2020
Smoke Detector	2nd Room 212 Storage	Visually Checked	7:59:31 AM	04/08/2020
Smoke Detector	2nd Room 212 Storage/Kiln	Visually Checked	7:58:57 AM	04/08/2020
Smoke Detector	2nd Room 238	Visually Checked	8:23:08 AM	04/08/2020
Smoke Detector	2nd Room 238	Visually Checked	8:23:22 AM	04/08/2020
Smoke Detector	2nd Room 238 Storage	Visually Checked	8:23:15 AM	04/08/2020
Smoke Detector	2nd Room 256 Storage	Visually Checked	8:23:01 AM	04/08/2020
Smoke Detector	2nd Stair Landing	Visually Checked	8:21:57 AM	04/08/2020
Smoke Detector	2nd Stairs by Room 201	Visually Checked	8:03:35 AM	04/08/2020
Smoke Detector	2nd Storage by Room 253	Visually Checked	8:22:50 AM	04/08/2020
Smoke Detector	2nd Top of Stairs by Room 255	Visually Checked	8:12:15 AM	04/08/2020
Smoke Detector	2nd By Janitors Closet	Tested/Cleaned	7:51:13 AM	04/08/2020
Smoke Detector	2nd Janitors Closet	Visually Checked	8:22:25 AM	04/08/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Penthouse Above Door Smoke 4	Visually Checked	7:44:25 AM	04/08/2020
Smoke Detector	Penthouse Center Smoke 3	Visually Checked	7:44:35 AM	04/08/2020
Smoke Detector	Penthouse Left Side Smoke 5	Visually Checked	7:44:01 AM	04/08/2020
Smoke Detector	Penthouse Right Side Smoke 1	Visually Checked	7:44:22 AM	04/08/2020
Smoke Detector	Penthouse Right Side Smoke 2	Visually Checked	7:43:53 AM	04/08/2020
Smoke Detector	Penthouse Top of Stair	Visually Checked	7:45:33 AM	04/08/2020

Service Summary

Generated by: BuildingReports.com

Building: Stamford BOE-Julia Stark School		
The Service Summary section provides an overview of the services performed in this report.		
Device Type	Service	Quantity
<i>Passed</i>		
Battery	Tested	5
Control Panel	Visually Checked	1
Duct Detector	Visually Checked	22
Heat Detector	Visually Checked	5
Pull Station	Visually Checked	31
Smoke Detector	Tested/Cleaned	3
Smoke Detector	Visually Checked	126
Total		193
Grand Total		193




Auxiliary Functions Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Julia Stark School		Control Panel: 1 - Edwards iO 1000		
<i>The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.</i>				
Type	Location	Comment	ScanID	Simulated
<i>Passed</i>				
Duct Detector				
Unit Shut Down	2nd AC 2 Girls bathroom by ramp	Passed	21097946	
Unit Shut Down	2nd AC 2 Return By Room 241	Passed	04062250	
Unit Shut Down	2nd AC 2 Supply By Room 244	Passed	04061878	
Unit Shut Down	2nd EF 16 By Room 244	Passed	04061879	
Unit Shut Down	2nd Room 212 Storage EF-1	Passed	04061834	
Unit Shut Down	Penthouse AC 4 Return	Passed	04061814	
Unit Shut Down	Penthouse AC 4 Supply	Passed	04061808	
Unit Shut Down	Penthouse EF 11	Passed	04061809	
Unit Shut Down	Penthouse EF-1 Return	Passed	20669264	

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Julia Stark School						
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>						
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test
		◀ dB	◀ dB	Voice	STI	
<i>Untested</i>						
Sound Test Points						
Whole Facility				<input type="checkbox"/>		0001

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Julia Stark School				Control Panel: 1 - Edwards iO 1000			
<i>The Battery & Power Supply Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Battery							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Sealed Lead Acid	Basement Electrical/Panel Room Bottom Booster	8	12	12.87V	7.2ah		
Sealed Lead Acid	Basement Electrical/Panel Room Center Booster	8	12	12.81V	7.8ah		
Sealed Lead Acid	Basement Electrical/Panel Room Dialer	5	12	12.44V	4.6ah		
Sealed Lead Acid	Basement Electrical/Panel Room Main Panel	18	12	13.41V	12ah		
Sealed Lead Acid	Basement Electrical/Panel Room Top Booster	7	12	12.78V	11ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Julia Stark School				Control Panel: 1 - Edwards iO 1000	
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		0.52%	1
Pull Station		Initiating		15.98%	31
Duct Detector		Initiating		11.34%	22
Smoke Detector		Initiating		66.49%	129
Heat Detector		Initiating		2.58%	5
Battery		Control		2.58%	5
Control Panel		Control		0.52%	1
Type	Qty	Model #	Description		Install Date
In Service - 90 Days - 1 Year					
Universal battery					
Battery	1	UB1250	Sealed Lead Acid		08/20/2019
In Service - 5 Years to 10 Years					
Universal					
Battery	1	UB1280	Sealed Lead Acid		01/16/2014
Edwards					
Duct Detector	19	6264B-001	Ionization		08/08/2012
Heat Detector	5	283B	Fixed Temperature		08/08/2012
Smoke Detector	12	6264B-001	Ionization		08/08/2012
	1				
EST					
Pull Station	11	SPO-270	Single Action		08/08/2012
Pull Station	20	SPO-278	Dual Action		08/08/2012
Smoke Detector	8	EC10-U	Ionization		08/08/2012
Edwards					
Control Panel	1	iO 1000			07/22/2012
Duct Detector	3	6264B-001	Ionization		07/22/2012
Power Patrol					
Battery	1	SEC1055	Sealed Lead Acid		07/20/2012
Universal Battery					
Battery	1	UB12180	Sealed Lead Acid		07/20/2012
Universal battery					
Battery	1	UB1280	Sealed Lead Acid		07/20/2012

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Julia Stark School Control Panel: 1 - Edwards iO 1000

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 01				
0142	Smoke Detector	Basement Storage	Ionization	04061960
0143	Smoke Detector	Basement Corridor	Ionization	04061961
0143	Smoke Detector	1st Kitchen Storage	Ionization	04061944
0145	Heat Detector	Basement Above Boiler Tank	Fixed Temperature	56180430
0146	Heat Detector	Basement Above Boiler Tank	Fixed Temperature	04061970
0148	Smoke Detector	Basement Office Space	Ionization	04061958
0149	Heat Detector	Basement Above Boiler	Fixed Temperature	20669265
0151	Smoke Detector	Basement Fire Pump rm	Ionization	04062228
0152	Smoke Detector	Basement Gas Room	Ionization	20667049
0153	Smoke Detector	Basement Electrical/Panel Room	Ionization	04061971
0154	Smoke Detector	Basement Electrical/Panel Room	Ionization	04061805
Zone/Circuit: 02				
0061	Smoke Detector	1st Exit By Room 105	Ionization	04062229
0062	Smoke Detector	1st By Room 117	Ionization	04061890
0063	Smoke Detector	1st By Room 119	Ionization	04061889
0065	Smoke Detector	1st By Room 121	Ionization	04061887
0066	Smoke Detector	1st Main Lobby by Principals Office	Ionization	04061901
0068	Smoke Detector	1st Storage Closet by Principals Office	Ionization	04062230
0069	Smoke Detector	1st Main Lobby by Conference Room	Ionization	04061903
0071	Smoke Detector	1st Main Lobby	Ionization	04061906
0072	Smoke Detector	1st By Room 133 Heath Services	Ionization	04061908
0073	Smoke Detector	1st By Faculty Dining	Ionization	04061909
0074	Smoke Detector	1st Faculty Dining	Ionization	04062233
0105	Smoke Detector	1st Storage Closet - IGA	Ionization	04062231
0106	Smoke Detector	1st Main Lobby by Storage	Ionization	04061904
0124	Smoke Detector	1st Corridor to New Section	Ionization	04061895
0125	Smoke Detector	1st Corridor to New Section	Ionization	04061894
0127	Smoke Detector	1st By Janitors Closet	Ionization	04061897
0128	Smoke Detector	1st Janitors Closet	Ionization	04061962
0129	Smoke Detector	1st By Room 103	Ionization	04061898
0130	Smoke Detector	1st By Room 101	Ionization	04061899
0131	Smoke Detector	1st Storeroom By Room 101	Ionization	04061963
0132	Smoke Detector	1st Corridor By Room 101	Ionization	04061964
Zone/Circuit: 03				
0077	Smoke Detector	1st Outside Custodians Office	Ionization	04061945
0078	Smoke Detector	1st Cafe Serving Area	Ionization	04061939
0080	Heat Detector	1st Kitchen	Fixed Temperature	04061941
0081	Heat Detector	1st Kitchen	Fixed Temperature	04061943
0082	Smoke Detector	1st Storage	Ionization	04061938

0083	Smoke Detector	1st Outside Custodians Office	Ionization	04061934
0084	Smoke Detector	1st Storage/Locker Area	Ionization	04061935
0085	Smoke Detector	1st Storage/Locker Area	Ionization	04061936
0086	Smoke Detector	1st Storage	Ionization	04061937
0088	Smoke Detector	1st Room 143	Ionization	04061927
0089	Smoke Detector	1st By Room 143/Stage	Ionization	04061930
0090	Smoke Detector	1st Corridor By Room 143	Ionization	04061931
0091	Smoke Detector	1st Corridor By Auditorium	Ionization	04061932
0101	Smoke Detector	1st Auditorium Side Exit	Ionization	04062237
0107	Smoke Detector	1st By Media Center	Ionization	04061911
0108	Smoke Detector	1st By Media Center	Ionization	04061913
0110	Smoke Detector	1st Corridor Between Media Center And Gym	Ionization	04061925
0111	Smoke Detector	1st Corridor Between Media Center And Gym	Ionization	04061926
0112	Smoke Detector	1st Corridor Between Media Center And Gym	Ionization	04061928
0114	Smoke Detector	1st By Room 157	Ionization	04062239
0115	Smoke Detector	1st By Room 157	Ionization	04062240
0116	Smoke Detector	1st Storage by Room 157	Ionization	04062242
0117	Smoke Detector	1st By Room 167	Ionization	04062241
0118	Smoke Detector	1st By Elevator Lobby	Ionization	04062245
0120	Smoke Detector	1st Stairs By Elevator Lobby	Ionization	04062247
0120	Smoke Detector	1st Stairs By Elevator Lobby	Ionization	04062249
0121	Smoke Detector	1st Storage By Room 167	Ionization	04062243
0155	Smoke Detector	1st Media Center	Ionization	04061920
0156	Smoke Detector	1st Media Center	Ionization	04061919
0157	Smoke Detector	1st Media Center	Ionization	04061918
0158	Smoke Detector	1st Media Center	Ionization	04061917
0159	Smoke Detector	1st Media Center	Ionization	04061916
0160	Smoke Detector	1st Media Center Side Room	Ionization	04061914
0160	Smoke Detector	1st Media Center Side Room	Ionization	04061915
0162	Smoke Detector	1st Media Center Kitchennet	Ionization	04061921
0163	Smoke Detector	1st Media Center	Ionization	04061922
0165	Smoke Detector	1st Media Center Computer Lab	Ionization	04061923
0166	Smoke Detector	1st Media Center Computer Lab	Ionization	04061924
	Smoke Detector	1st Stage Left	Ionization	04061954
	Smoke Detector	1st Stage Right	Ionization	04061953
Zone/Circuit: 04				
0002	Smoke Detector	2nd Top of Stair By Room 220	Ionization	04061823
0003	Smoke Detector	2nd By Room 220	Ionization	04061822
0004	Smoke Detector	2nd By Room 219	Ionization	04061821
0005	Smoke Detector	2nd By Room 222	Ionization	04061820
0007	Smoke Detector	2nd By Room 224	Ionization	04061818
0008	Smoke Detector	2nd By Room 228	Ionization	04061817
0010	Smoke Detector	2nd Stair Landing	Ionization	04061816
0011	Smoke Detector	2nd Storage By Room 230	Ionization	04061819
0012	Smoke Detector	2nd By Room 230	Ionization	04061886
0013	Smoke Detector	2nd By Room 234	Ionization	04061885
0014	Smoke Detector	2nd Room 238	Ionization	04061884
0015	Smoke Detector	2nd Room 238 Storage	Ionization	04061883
0016	Smoke Detector	2nd Room 238	Ionization	04061882
0017	Smoke Detector	2nd By Room 241	Ionization	04061881

0018	Smoke Detector	2nd By Room 241	Ionization	04061880
0020	Smoke Detector	2nd By Room 244	Ionization	04061876
0021	Smoke Detector	2nd By Room 246 By Firedoors	Ionization	04061875
0022	Smoke Detector	2nd By Room 246	Ionization	04061871
0033	Smoke Detector	2nd Corridor By Room 206 By Firedoors	Ionization	04061854
0034	Smoke Detector	2nd Corridor By Room 206	Ionization	04061853
0035	Smoke Detector	2nd By Room 206	Ionization	04061852
0037	Smoke Detector	2nd By Room 204	Ionization	04061850
0038	Smoke Detector	2nd By Room 203	Ionization	04061849
0039	Smoke Detector	2nd By Room 202	Ionization	04061848
0040	Smoke Detector	2nd Janitors Closet By Room 201	Ionization	04061841
0041	Smoke Detector	2nd Adult Restroom By Room 201	Ionization	04061842
0042	Smoke Detector	2nd By Room 201	Ionization	04061843
0044	Smoke Detector	2nd Area of Refuge by Room 201	Ionization	04061846
0046	Smoke Detector	2nd Stairs by Room 201	Ionization	04061847
0047	Smoke Detector	2nd By Room 209	Ionization	04061837
0048	Smoke Detector	2nd Room 209 Storage	Ionization	04061840
0049	Smoke Detector	2nd Room 212 Storage/Kiln	Ionization	04061833
0050	Smoke Detector	2nd Room 212 Storage	Ionization	04061835
0051	Smoke Detector	2nd Room 210 Storage	Ionization	04061836
0052	Smoke Detector	2nd By Room 211	Ionization	04061830
0053	Smoke Detector	2nd Room 211 Storage	Ionization	04061831
0054	Smoke Detector	2nd Janitors Closet	Ionization	04061832
0055	Smoke Detector	2nd By Janitors Closet	Ionization	04061829
0056	Smoke Detector	2nd Corridor to New Section	Ionization	04061828
0057	Smoke Detector	2nd Corridor By Room 220	Ionization	04061827
Zone/Circuit: 05				
0024	Smoke Detector	2nd By Room 249	Ionization	04061866
0025	Smoke Detector	2nd Top of Stairs By Room 249	Ionization	04061867
0026	Smoke Detector	2nd By Room 250	Ionization	04061865
0027	Smoke Detector	2nd Janitors Closet By Room 252	Ionization	04061864
0028	Smoke Detector	2nd By Room 253	Ionization	04061863
0029	Smoke Detector	2nd By Room 253	Ionization	04061858
0029A	Smoke Detector	2nd Storage by Room 253	Ionization	04061859
0029B	Smoke Detector	2nd Room 256 Storage	Ionization	04061873
0032	Smoke Detector	2nd Top of Stairs by Room 255	Ionization	04061855
Zone/Circuit: 07				
0000	Smoke Detector	Penthouse Above Door Smoke 4	Ionization	20667047
0000	Smoke Detector	Penthouse Center Smoke 3	Ionization	20667046
0000	Smoke Detector	Penthouse Left Side Smoke 5	Ionization	20667048
0000	Smoke Detector	Penthouse Right Side Smoke 1	Ionization	20667044
0000	Smoke Detector	Penthouse Right Side Smoke 2	Ionization	20667045
0133	Smoke Detector	Penthouse Top of Stair	Ionization	04061815
Zone/Circuit: 08				
0141	Pull Station	Basement Exit	Dual Action	04061968
0150	Pull Station	Basement Office Space	Dual Action	04061959
Zone/Circuit: 09				
0058	Pull Station	1st Stair Exit By Room 105	Dual Action	04061891
0058	Pull Station	1st Stair Exit By Room 105	Dual Action	04061892
0060	Pull Station	1st Exit By Room 105	Dual Action	04061893
0064	Pull Station	1st By Room 119	Dual Action	04061888

0067	Pull Station	1st Main Lobby By Principals Office	Single Action	04061902
0070	Pull Station	1st Main Lobby	Single Action	04061905
0075	Pull Station	1st By Faculty Dining	Single Action	04061910
0076	Pull Station	1st Cafe Exit	Single Action	04061956
0076	Pull Station	1st Cafe Exit	Single Action	04061957
0126	Pull Station	1st Corridor to New Section	Dual Action	04061896
0131	Pull Station	1st By Room 101	Single Action	04061900
Zone/Circuit: 10				
0079	Pull Station	1st Cafe Serving Area	Dual Action	04061940
0092	Pull Station	1st Corridor By Auditorium	Single Action	04061933
0102	Pull Station	1st Auditorium Side Exit	Single Action	04062238
0109	Pull Station	1st By Media Center	Dual Action	04061912
0113	Pull Station	1st Corridor By Room 143 /Stage	Single Action	04061929
0119	Pull Station	1st Elevator Lobby	Single Action	04062246
Zone/Circuit: 11				
0002	Pull Station	2nd By Room 220	Dual Action	04061824
0006	Pull Station	2nd By Room 224	Dual Action	04061825
0009	Pull Station	2nd By Room 230	Dual Action	04061826
0019	Pull Station	2nd By Room 244	Dual Action	04061877
0023	Pull Station	2nd By Room 249	Dual Action	04061870
0036	Pull Station	2nd By Room 204	Dual Action	04061851
0043	Pull Station	2nd By Room 201	Dual Action	04061844
0045	Pull Station	2nd Area of Refuge by Room 201	Dual Action	04061845
Zone/Circuit: 12				
0030	Pull Station	2nd Elevator Lobby	Dual Action	04061857
0031	Pull Station	2nd Top of Stairs by Room 255	Dual Action	04061856
Zone/Circuit: 13				
0134	Pull Station	Penthouse Entrance/ Exit (Unit Shut Down)	Dual Action	04061810
Zone/Circuit: 26				
0000	Duct Detector	1st Faculty Dining AC 1 Return	Ionization	04062235
0000	Duct Detector	1st Faculty Dining AC 1 Supply	Ionization	04062234
0000	Duct Detector	1st Gym (Need Lift)	Ionization	56180427
0000	Duct Detector	1st Gym (Need Lift)	Ionization	56180428
0000	Duct Detector	1st Gym (Need Lift)	Ionization	56180429
Zone/Circuit: 27				
0000	Duct Detector	Penthouse EF-1 Return	Ionization	20669264
Zone/Circuit: 28				
0000	Duct Detector	Penthouse AC 4 Return	Ionization	04061814
0000	Duct Detector	Penthouse AC 4 Supply	Ionization	04061808
Zone/Circuit: 29				
0000	Duct Detector	2nd By Room 209 Return	Ionization	04061839
0000	Duct Detector	2nd By Room 209 Supply	Ionization	04061838
Zone/Circuit: 31				
0000	Duct Detector	2nd By Room 246 EF 3	Ionization	04061869
Zone/Circuit: 32				
0000	Duct Detector	2nd By Room 245 AC 5 Return	Ionization	04061874

0000	Duct Detector	2nd By Room 245 AC 5 Supply	Ionization	04061872
Zone/Circuit: 33				
0000	Duct Detector	2nd AC 2 Girls bathroom by ramp	Ionization	21097946
0000	Duct Detector	2nd AC 2 Return By Room 241	Ionization	04062250
0000	Duct Detector	2nd AC 2 Supply By Room 244	Ionization	04061878
Zone/Circuit: 35				
0000	Duct Detector	2nd By Room 254 EF-4	Ionization	04061860
Zone/Circuit: 36				
0000	Duct Detector	2nd By Room 254 AC 6 Supply	Ionization	04061861
0000	Duct Detector	2nd By Room 254 AC6 Return	Ionization	04061862
Zone/Circuit: 42				
0000	Duct Detector	2nd Room 212 Storage EF-1	Ionization	04061834
Zone/Circuit: 45				
0000	Duct Detector	2nd EF 16 By Room 244	Ionization	04061879
Zone/Circuit: 46				
0093	Smoke Detector	1st Auditorium	Ionization	04061946
0093	Smoke Detector	1st Auditorium	Ionization	04061947
0094	Smoke Detector	1st Auditorium	Ionization	04061948
0095	Smoke Detector	1st Auditorium	Ionization	04061949
0096	Smoke Detector	1st Auditorium	Ionization	04061950
0097	Smoke Detector	1st Auditorium	Ionization	04061951
0098	Smoke Detector	1st Auditorium	Ionization	04061952
Zone/Circuit: 47				
0100	Pull Station	1st Auditorium Exit	Single Action	04062236
Zone/Circuit: 49				
0000	Duct Detector	Penthouse EF 11	Ionization	04061809

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-StillMeadow
School
800 Stillwater Road
Stamford, CT 06904

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Feb 18, 2020



Building: Stamford BOE-StillMeadow School
Contact: Davor Lucaj
Title: Facilities Trades Manager

Company: TPC Associates, Inc.
Contact: Dave Majewski
Title: Inspector

Executive Summary





Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-StillMeadow School		Contact: Davor Lucaj
Address: 800 Stillwater Road		Phone: 203-977-6668
Address:		Fax:
City/State/Zip: Stamford, CT 06904		Mobile: 347-675-6021
Country: United States of America		Email: dlucaj@stamfordct.gov
Inspection Performed By		
Company: TPC Associates, Inc.		Inspector: Dave Majewski
Address: 261 Pepe's Farm Road		Phone: 203-666-9587
Address:		Fax:
City/State/Zip: Milford, Connecticut 06460		Mobile:
Country: United States of America		Email: dave.majewski@tpcsystems.com
System Control Unit		
Manufacturer: EST	Inspection Date: 02/18/2020	IDC Style:
Model Number: io	Install Date: 08/17/2012	SLC Style:
Software Version:	Version Date: 08/17/2019	NAC Style:
Location: Lower Level Electrical Room	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type: Digital Communicator	Mfg: Noti Fire	Model #: 911A
Test Time/Date: 2/18/20 2:01:33 PM	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.66%	0	0%	0	0%	0	0%
Control	8	5.26%	8	100.00%	6	75.00%	2	25.00%
Initiating	143	94.08%	143	100.00%	143	100.00%	0	0%
Totals	152	100%	151	99.34%	149	98.68%	2	1.32%
Certification								
Company: TPC Associates, Inc.				Building: Stamford BOE-StillMeadow School				
Inspector: Dave Majewski				Contact: Davor Lucaj				
								
Signed: Feb 18, 2020 2:11:58 PM				Signed: Feb 18, 2020 2:20:42 PM				

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-StillMeadow School Control Panel: 1 - EST io				
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i></p>				
Device Type	Manufacturer	ModelNumber	Date	Qty
Items listed for Recall by Manufacturer				
No recalled items found during this inspection.				
 ScanID	 Location	 Problem	Address	 Reference
Control				
Battery				
04062254	Lower Level Electrical Room	Failed Test	1	NFPA 72 Table 10.4.2.2.5(a-e)
04061679	Lower Level #2 Electrical Room Left	Failed Test	1	NFPA 72 Table 10.4.2.2.5(a-e)

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-StillMeadow School			Control Panel: 1 - EST io		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
Control					
Battery					
04062254	Lower Level Electrical Room	Replace	UB1250	T/M	<input type="checkbox"/>
04061679	Lower Level #2 Electrical Room Left	Replace	UB1280	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-StillMeadow School		Control Panel: 1 - EST io		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Battery	Lower Level Electrical Room Below FACP	Tested	1:59:46 PM	02/18/2020
Battery	Lower Level #3 Electrical Room Right	Tested	1:57:56 PM	02/18/2020
Communicator	Lower Level Electrical Room	Tested	2:01:33 PM	02/18/2020
Control Panel	Lower Level Electrical Room	Tested	1:56:02 PM	02/18/2020
Power Supply	Lower Level Electrical Room Left	Tested	1:56:14 PM	02/18/2020
Power Supply	Lower Level Electrical Room Right	Tested	1:56:17 PM	02/18/2020
Initiating				
Duct Detector	Upper Level Corridor By Media Center By Media Center	Visually Checked	1:14:43 PM	02/18/2020
Duct Detector	Upper Level Corridor By rm 167	Visually Checked	1:17:53 PM	02/18/2020
Duct Detector	Upper Level Corridor By Main Office	Visually Checked	1:11:26 PM	02/18/2020
Duct Detector	Upper Level Corridor By Main Office AHU 2	Visually Checked	2:09:06 PM	02/18/2020
Duct Detector	Upper Level Corridor By Main Office AHU 2	Visually Checked	2:09:10 PM	02/18/2020
Duct Detector	Upper Level Corridor By Media Center Unit 3	Visually Checked	2:09:18 PM	02/18/2020
Duct Detector	Upper Level Corridor By rm 163	Visually Checked	2:09:24 PM	02/18/2020
Duct Detector	Upper Level Corridor By rm 166 AHU 4	Visually Checked	2:08:58 PM	02/18/2020
Duct Detector	Upper Level Corridor By Rm133	Visually Checked	1:33:07 PM	02/18/2020
Duct Detector	Upper Level Corridor By Rm188	Visually Checked	2:08:45 PM	02/18/2020
Duct Detector	Upper Level Corridor ByRm 167 Unit 4	Visually Checked	2:08:54 PM	02/18/2020
Duct Detector	Upper Level Corridor ByRm 188 Unit 5	Visually Checked	2:08:49 PM	02/18/2020
Duct Detector	Upper Level Entrance to Technology Center	Visually Checked	2:08:17 PM	02/18/2020
Duct Detector	Upper Level Mechanical room over Stage	Visually Checked	2:06:48 PM	02/18/2020
Duct Detector	Upper Level Media Center office	Visually Checked	2:10:08 PM	02/18/2020
Duct Detector	Upper Level Media Center by book shelf Wall Unit 1 above ceiling	Visually Checked	2:08:41 PM	02/18/2020
Duct Detector	Upper Level Media Center Work Rm Unit 7	Visually Checked	2:08:36 PM	02/18/2020
Heat Detector	Upper Level Corridor by Faculty Dinning Kitchen	Visually Checked	2:06:23 PM	02/18/2020
Heat Detector	Upper Level Kitchen	Visually Checked	1:41:36 PM	02/18/2020
Heat Detector	Upper Level Kitchen	Visually Checked	1:41:47 PM	02/18/2020
Initiating Device	Upper Level Corridor By Gym Unit 3	Visually Checked	2:11:41 PM	02/18/2020
Initiating Device	Upper Level Corridor By Gym Unit 6	Visually Checked	2:11:36 PM	02/18/2020
Initiating Device	Upper Level Corridor By Main Office Unit 2	Visually Checked	2:11:31 PM	02/18/2020
Initiating Device	Upper Level Corridor By Meda Center Unit 3	Visually Checked	2:10:44 PM	02/18/2020
Initiating Device	Upper Level Corridor By rm 163 Unit 3	Visually Checked	2:11:11 PM	02/18/2020
Initiating Device	Upper Level Corridor By rm 166 AHU 4	Visually Checked	2:10:35 PM	02/18/2020
Initiating Device	Upper Level Corridor By rm 167 AHU 4	Visually Checked	2:10:26 PM	02/18/2020
Initiating Device	Upper Level Corridor By rm 188 Unit 5	Visually Checked	2:11:25 PM	02/18/2020
Initiating Device	Upper Level Main Office Unit 2	Visually Checked	2:11:48 PM	02/18/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Initiating Device	Upper Level Media Center by book Shelf next Wall Unit 1	Visually Checked	2:11:07 PM	02/18/2020
Initiating Device	Upper Level Media Work rm Unit 7	Visually Checked	2:11:16 PM	02/18/2020
Pull Station	Lower Level Boiler Rm	Visually Checked	2:05:42 PM	02/18/2020
Pull Station	Lower Level Corridor by Art rm	Visually Checked	1:21:39 PM	02/18/2020
Pull Station	Lower Level Corridor by rm 41	Visually Checked	1:23:29 PM	02/18/2020
Pull Station	Lower Level Corridor by rm 46	Visually Checked	1:26:21 PM	02/18/2020
Pull Station	Upper Level Cafeteria	Visually Checked	1:41:03 PM	02/18/2020
Pull Station	Upper Level Cafeteria	Visually Checked	1:44:28 PM	02/18/2020
Pull Station	Upper Level Corridor By rm 168	Visually Checked	1:18:09 PM	02/18/2020
Pull Station	Upper Level Corridor by Faculty Dinning	Visually Checked	1:38:47 PM	02/18/2020
Pull Station	Upper Level Corridor By G Fire Door	Visually Checked	1:33:41 PM	02/18/2020
Pull Station	Upper Level Corridor By Gym	Visually Checked	2:06:27 PM	02/18/2020
Pull Station	Upper Level Corridor by Media Center	Visually Checked	1:13:34 PM	02/18/2020
Pull Station	Upper Level Corridor by Rm 156	Visually Checked	1:12:06 PM	02/18/2020
Pull Station	Upper Level Corridor by Room 162	Visually Checked	1:15:56 PM	02/18/2020
Pull Station	Upper Level Corridor by room 172	Visually Checked	1:19:31 PM	02/18/2020
Pull Station	Upper Level Corridor by Side Entrance	Visually Checked	1:12:45 PM	02/18/2020
Pull Station	Upper Level Corridor Rm 185	Visually Checked	2:05:58 PM	02/18/2020
Pull Station	Upper Level Gym	Visually Checked	1:10:48 PM	02/18/2020
Pull Station	Upper Level Gym	Visually Checked	2:06:32 PM	02/18/2020
Pull Station	Upper Level Gym By Exit C	Visually Checked	1:10:06 PM	02/18/2020
Pull Station	Upper Level Gym By Exit Door D	Visually Checked	2:06:36 PM	02/18/2020
Pull Station	Upper Level Kitchen	Visually Checked	1:42:15 PM	02/18/2020
Pull Station	Upper Level Main Entrance	Visually Checked	1:05:47 PM	02/18/2020
Pull Station	Upper Level Media Center Entrance	Visually Checked	2:07:19 PM	02/18/2020
Pull Station	Upper Level Media Center Entrance	Visually Checked	2:07:24 PM	02/18/2020
Pull Station	Upper Level Portable Classroom	Visually Checked	2:06:02 PM	02/18/2020
Pull Station	Upper Level Portable Classroom Main Entrance	Visually Checked	2:06:11 PM	02/18/2020
Pull Station	Upper Level Portable Classroom rear	Visually Checked	2:06:18 PM	02/18/2020
Pull Station	Upper Level Side Entrance	Visually Checked	1:39:08 PM	02/18/2020
Pull Station	Upper Level Technology Center Entrance	Visually Checked	2:07:50 PM	02/18/2020
Pull Station	Upper Level Technology Center Entrance	Visually Checked	2:07:54 PM	02/18/2020
Smoke Detector	Lower Level Custodian rm by Storage	Visually Checked	1:28:22 PM	02/18/2020
Smoke Detector	Lower Level Main Lobby	Visually Checked	2:04:54 PM	02/18/2020
Smoke Detector	Lower Level Stairwell lobby Entrance	Visually Checked	1:26:48 PM	02/18/2020
Smoke Detector	Lower Level Art rm	Visually Checked	2:05:11 PM	02/18/2020
Smoke Detector	Lower Level Corridor by Art rm	Visually Checked	1:21:52 PM	02/18/2020
Smoke Detector	Lower Level Corridor By Rm 41	Visually Checked	1:23:23 PM	02/18/2020
Smoke Detector	Lower Level Corridor By Rm 44	Visually Checked	1:24:02 PM	02/18/2020
Smoke Detector	Lower Level Corridor By Rm 45	Visually Checked	1:24:20 PM	02/18/2020
Smoke Detector	Lower Level Corridor Rm 37	Visually Checked	1:22:25 PM	02/18/2020
Smoke Detector	Lower Level Corridor Rm 40	Visually Checked	2:05:03 PM	02/18/2020
Smoke Detector	Lower Level Electrical Rm	Visually Checked	2:05:26 PM	02/18/2020
Smoke Detector	Lower Level Elevator Room by rm 38	Visually Checked	1:22:52 PM	02/18/2020
Smoke Detector	Lower Level Music rm Storage room by Art rm	Visually Checked	2:05:31 PM	02/18/2020
Smoke Detector	Lower Level Office by rm 45	Visually Checked	1:24:30 PM	02/18/2020
Smoke Detector	Lower Level Portable Classroom	Visually Checked	2:04:59 PM	02/18/2020
Smoke Detector	Lower Level Rm 37	Visually Checked	2:05:07 PM	02/18/2020
Smoke Detector	Lower Level Stairwell Lobby by Art Rm.	Visually Checked	1:21:15 PM	02/18/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Lower Level Storage room	Visually Checked	1:30:30 PM	02/18/2020
Smoke Detector	Lower Level Storage room	Visually Checked	2:05:16 PM	02/18/2020
Smoke Detector	Lower Level Storage room	Visually Checked	2:05:35 PM	02/18/2020
Smoke Detector	Upper Level Cafeteria	Visually Checked	2:06:52 PM	02/18/2020
Smoke Detector	Upper Level Cafeteria	Visually Checked	2:06:57 PM	02/18/2020
Smoke Detector	Upper Level Corridor by Gym	Visually Checked	1:45:27 PM	02/18/2020
Smoke Detector	Upper Level Corridor by Cafe	Visually Checked	1:40:16 PM	02/18/2020
Smoke Detector	Upper Level Corridor by Faculty Dinning	Visually Checked	1:39:00 PM	02/18/2020
Smoke Detector	Upper Level Corridor By General Office	Visually Checked	1:11:10 PM	02/18/2020
Smoke Detector	Upper Level Corridor by Gym	Visually Checked	1:50:03 PM	02/18/2020
Smoke Detector	Upper Level Corridor by Gym	Visually Checked	1:50:18 PM	02/18/2020
Smoke Detector	Upper Level Corridor by Main Office	Visually Checked	2:05:46 PM	02/18/2020
Smoke Detector	Upper Level Corridor by Media Center	Visually Checked	1:13:27 PM	02/18/2020
Smoke Detector	Upper Level Corridor by Portable	Visually Checked	1:39:26 PM	02/18/2020
Smoke Detector	Upper Level Corridor by rm 129	Visually Checked	1:34:42 PM	02/18/2020
Smoke Detector	Upper Level Corridor by rm 129	Visually Checked	1:34:58 PM	02/18/2020
Smoke Detector	Upper Level Corridor by Rm 158	Visually Checked	1:12:28 PM	02/18/2020
Smoke Detector	Upper Level Corridor by rm 166	Visually Checked	1:16:43 PM	02/18/2020
Smoke Detector	Upper Level Corridor by rm 167	Visually Checked	1:17:15 PM	02/18/2020
Smoke Detector	Upper Level Corridor by rm 169	Visually Checked	1:18:19 PM	02/18/2020
Smoke Detector	Upper Level Corridor by rm 174	Visually Checked	1:32:55 PM	02/18/2020
Smoke Detector	Upper Level Corridor by rm 175	Visually Checked	1:33:30 PM	02/18/2020
Smoke Detector	Upper Level Corridor by rm 177A	Visually Checked	1:34:10 PM	02/18/2020
Smoke Detector	Upper Level Corridor by rm 179	Visually Checked	1:36:49 PM	02/18/2020
Smoke Detector	Upper Level Corridor By rm 180	Visually Checked	1:37:22 PM	02/18/2020
Smoke Detector	Upper Level Corridor by rm 188	Visually Checked	1:37:59 PM	02/18/2020
Smoke Detector	Upper Level Corridor by Room 162	Visually Checked	1:13:55 PM	02/18/2020
Smoke Detector	Upper Level Corridor By Room 163	Visually Checked	1:16:18 PM	02/18/2020
Smoke Detector	Upper Level Corridor By Room 170	Visually Checked	1:18:51 PM	02/18/2020
Smoke Detector	Upper Level Corridor Storage	Visually Checked	2:10:00 PM	02/18/2020
Smoke Detector	Upper Level Corridor Storage by Gym	Visually Checked	2:09:56 PM	02/18/2020
Smoke Detector	Upper Level Gym Front Half	Visually Checked	1:45:52 PM	02/18/2020
Smoke Detector	Upper Level Gym Front Half	Visually Checked	1:45:53 PM	02/18/2020
Smoke Detector	Upper Level Gym Front Half	Visually Checked	2:09:40 PM	02/18/2020
Smoke Detector	Upper Level Gym Rear	Visually Checked	1:09:29 PM	02/18/2020
Smoke Detector	Upper Level Gym Rear	Visually Checked	1:09:30 PM	02/18/2020
Smoke Detector	Upper Level Gym Rear	Visually Checked	2:09:44 PM	02/18/2020
Smoke Detector	Upper Level Gym Rear	Visually Checked	2:09:48 PM	02/18/2020
Smoke Detector	Upper Level Gym Stage	Visually Checked	1:48:09 PM	02/18/2020
Smoke Detector	Upper Level Gym Stage	Visually Checked	1:48:11 PM	02/18/2020
Smoke Detector	Upper Level Gym Storage	Visually Checked	2:06:40 PM	02/18/2020
Smoke Detector	Upper Level Kitchen Storage	Visually Checked	2:07:02 PM	02/18/2020
Smoke Detector	Upper Level Kitchen Storage	Visually Checked	2:07:07 PM	02/18/2020
Smoke Detector	Upper Level Main Lobby	Visually Checked	1:09:03 PM	02/18/2020
Smoke Detector	Upper Level Main Office Storage	Visually Checked	2:09:52 PM	02/18/2020
Smoke Detector	Upper Level Mechanical rm. over Stage Right	Visually Checked	2:08:32 PM	02/18/2020
Smoke Detector	Upper Level Mechanical Rm.	Visually Checked	2:06:44 PM	02/18/2020
Smoke Detector	Upper Level Media Center	Visually Checked	2:07:11 PM	02/18/2020
Smoke Detector	Upper Level Media Center	Visually Checked	2:07:15 PM	02/18/2020
Smoke Detector	Upper Level Media Center	Visually Checked	2:07:29 PM	02/18/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Upper Level Media Center	Visually Checked	2:07:34 PM	02/18/2020
Smoke Detector	Upper Level Media Work Room	Visually Checked	2:08:05 PM	02/18/2020
Smoke Detector	Upper Level Portable Classroom	Visually Checked	2:09:02 PM	02/18/2020
Smoke Detector	Upper Level Portable Classroom Rear	Visually Checked	2:09:14 PM	02/18/2020
Smoke Detector	Upper Level Rm 134	Visually Checked	2:09:28 PM	02/18/2020
Smoke Detector	Upper Level Rm 131	Visually Checked	2:09:32 PM	02/18/2020
Smoke Detector	Upper Level Rm 160	Visually Checked	2:05:50 PM	02/18/2020
Smoke Detector	Upper Level Rm 161	Visually Checked	2:05:54 PM	02/18/2020
Smoke Detector	Upper Level Stairwell by rm 172	Visually Checked	1:20:20 PM	02/18/2020
Smoke Detector	Upper Level Stairwell by rm 173	Visually Checked	1:19:47 PM	02/18/2020
Smoke Detector	Upper Level Stairwell by room 164	Visually Checked	1:15:29 PM	02/18/2020
Smoke Detector	Upper Level Storage by rm 130	Visually Checked	1:35:17 PM	02/18/2020
Smoke Detector	Upper Level Storage by rm 130	Visually Checked	1:35:38 PM	02/18/2020
Smoke Detector	Upper Level Technology Center	Visually Checked	2:07:58 PM	02/18/2020
Smoke Detector	Upper Level Technology Center	Visually Checked	2:09:36 PM	02/18/2020
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	Lower Level Electrical Room	Tested	2:04:44 PM	02/18/2020
Battery	Lower Level #2 Electrical Room Left	Tested	1:57:49 PM	02/18/2020

Service Summary

Generated by: BuildingReports.com






Building: Stamford BOE-StillMeadow School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	2
Total		2
<i>Passed</i>		
Battery	Tested	2
Communicator	Tested	1
Control Panel	Tested	1
Duct Detector	Visually Checked	17
Heat Detector	Visually Checked	3
Initiating Device	Visually Checked	11
Power Supply	Tested	2
Pull Station	Visually Checked	30
Smoke Detector	Visually Checked	82
Total		149
Grand Total		151

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-StillMeadow School							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		 dB	 dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
Whole Facility				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-StillMeadow School				Control Panel: 1 - EST io			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<i>Passed</i>							
Battery							
Sealed Lead Acid	Lower Level Electrical Room Below FACP	7.6Ah	12	13.07V	7.4Ah		
Sealed Lead Acid	Lower Level #3 Electrical Room Right	8	12	12.82V	5.8Ah		
<i>Failed/Other</i>							
Battery							
Sealed Lead Acid	Lower Level Electrical Room	5	12	12.37V	2.3Ah		
Sealed Lead Acid	Lower Level #2 Electrical Room Left	8	12	12.57V	2.7Ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-StillMeadow School				Control Panel: 1 - EST io	
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		0.66%	1
Pull Station		Initiating		19.74%	30
Smoke Detector		Initiating		53.95%	82
Duct Detector		Initiating		11.18%	17
Heat Detector		Initiating		1.97%	3
Control Panel		Control		0.66%	1
Power Supply		Control		1.32%	2
Battery		Control		2.63%	4
Communicator		Control		0.66%	1
Initiating Device		Initiating		7.24%	11
Type	Qty	Model #	Description		Install Date
In Service - 1 Year to 2 Years					
Universal					
Battery	1	UB12500	Sealed Lead Acid		08/05/2018
In Service - 3 Years to 5 Years					
Universal					
Battery	1	UB1250	Sealed Lead Acid		02/21/2017
Battery	1	UB1280	Sealed Lead Acid		02/21/2017
In Service - 5 Years to 10 Years					
Universal					
Battery	1	UB1280	Sealed Lead Acid		09/01/2012
Edwards					
Duct Detector	1	6251B	Ionization		08/17/2012
Edwards GS					
Duct Detector	9	6251B	Ionization		08/17/2012
Smoke Detector	69	6251B	Ionization		08/17/2012
Smoke Detector	1	6251S	Ionization		08/17/2012
EST					
Control Panel	1	io			08/17/2012
Heat Detector	3	283B	Fixed Temperature		08/17/2012
Initiating Device	11	CAT 6262A-001	Supporting Field Device		08/17/2012
Pull Station	30	SIGA-270	Single Action		08/17/2012
GE Security					

Smoke Detector	1	EC304-U	Ionization	08/17/2012
Smoke Detector	11	EC30U-3	Ionization	08/17/2012
Noti Fire				
Communicator	1	911A	Digital Communicator	08/17/2012
System Sensor				
Duct Detector	7	DH100ACDCLP	Ionization	08/17/2012
<i>In Service - 10 Years to 15 Years</i>				
EST				
Power Supply	2	BPS-10A		08/31/2006

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-StillMeadow School Control Panel: 1 - EST io

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 1				
	Pull Station	Upper Level Cafeteria	Single Action	04061728
	Pull Station	Upper Level Cafeteria	Single Action	04061729
	Smoke Detector	Upper Level Cafeteria	Ionization	04061746
	Smoke Detector	Upper Level Cafeteria	Ionization	04061747
	Heat Detector	Upper Level Corridor by Faculty Dinning Kitchen	Fixed Temperature	04061727
	Heat Detector	Upper Level Kitchen	Fixed Temperature	04061748
	Heat Detector	Upper Level Kitchen	Fixed Temperature	04061749
	Pull Station	Upper Level Kitchen	Single Action	04061750
	Smoke Detector	Upper Level Kitchen Storage	Ionization	04061751
	Smoke Detector	Upper Level Kitchen Storage	Ionization	04061752
Zone/Circuit: 2				
	Initiating Device	Upper Level Corridor By Gym Unit 3	Supporting Field Device	20668376
	Smoke Detector	Upper Level Corridor Storage	Ionization	20668424
	Smoke Detector	Upper Level Corridor Storage by Gym	Ionization	20668423
	Pull Station	Upper Level Gym	Single Action	04061736
	Pull Station	Upper Level Gym	Single Action	04061737
	Pull Station	Upper Level Gym By Exit C	Single Action	04061739
	Pull Station	Upper Level Gym By Exit Door D	Single Action	04061738
	Smoke Detector	Upper Level Gym Front Half	Ionization	20668412
	Smoke Detector	Upper Level Gym Front Half	Ionization	20668414
	Smoke Detector	Upper Level Gym Front Half	Ionization	20668415
	Smoke Detector	Upper Level Gym Rear	Ionization	20668416
	Smoke Detector	Upper Level Gym Rear	Ionization	20668417
	Smoke Detector	Upper Level Gym Rear	Ionization	20668418
	Smoke Detector	Upper Level Gym Rear	Ionization	20668419
	Smoke Detector	Upper Level Gym Stage	Ionization	20668410
	Smoke Detector	Upper Level Gym Stage	Ionization	20668411
	Smoke Detector	Upper Level Gym Storage	Ionization	04061740
	Smoke Detector	Upper Level Mechanical rm. over Stage Right	Ionization	20668377
	Smoke Detector	Upper Level Mechanical Rm.	Ionization	04061744
Zone/Circuit: 3				
	Smoke Detector	Upper Level Corridor by Gym	Ionization	04061732
	Pull Station	Upper Level Corridor By G Fire Door	Single Action	04061705
	Pull Station	Upper Level Corridor By Gym	Single Action	04061731
	Smoke Detector	Upper Level Corridor By rm 180	Ionization	20668404
	Pull Station	Upper Level Corridor Rm 185	Single Action	04061714

Smoke Detector	Upper Level Corridor by Cafe	Ionization	04061725
Pull Station	Upper Level Corridor by Faculty Dinning	Single Action	04061726
Smoke Detector	Upper Level Corridor by rm 129	Ionization	04061710
Smoke Detector	Upper Level Corridor by rm 129	Ionization	04061711
Smoke Detector	Upper Level Corridor by rm 174	Ionization	04061703
Smoke Detector	Upper Level Corridor by rm 175	Ionization	04061704
Smoke Detector	Upper Level Corridor by rm 177A	Ionization	20668383
Smoke Detector	Upper Level Corridor by rm 179	Ionization	04061712
Smoke Detector	Upper Level Corridor by rm 188	Ionization	04061715
Zone/Circuit: 4			
Smoke Detector	Upper Level Corridor By General Office	Ionization	20668420
Smoke Detector	Upper Level Corridor by Gym	Ionization	04061733
Smoke Detector	Upper Level Corridor by Gym	Ionization	04061734
Smoke Detector	Upper Level Corridor by Main Office	Ionization	04061686
Pull Station	Upper Level Corridor by Media Center	Single Action	04061692
Smoke Detector	Upper Level Corridor by Media Center	Ionization	04061691
Pull Station	Upper Level Corridor by Rm 156	Single Action	04061687
Smoke Detector	Upper Level Corridor by Rm 158	Ionization	04061688
Smoke Detector	Upper Level Corridor by Room 162	Ionization	04061694
Pull Station	Upper Level Corridor by Side Entrance	Single Action	04061689
Pull Station	Upper Level Main Entrance	Single Action	04061684
Smoke Detector	Upper Level Main Lobby	Ionization	20668422
Smoke Detector	Upper Level Main Office Storage	Ionization	20668421
Smoke Detector	Upper Level Rm 160	Ionization	04061690
Smoke Detector	Upper Level Rm 161	Ionization	04061693
Zone/Circuit: 5			
Pull Station	Upper Level Corridor By rm 168	Single Action	04061700
Smoke Detector	Upper Level Corridor By Room 163	Ionization	04061695
Smoke Detector	Upper Level Corridor By Room 170	Ionization	20668408
Duct Detector	Upper Level Corridor By rm 163	Ionization	20668397
Duct Detector	Upper Level Corridor By rm 166 AHU 4	Ionization	20668386
Duct Detector	Upper Level Corridor ByRm 167 Unit 4	Ionization	20668385
Pull Station	Upper Level Corridor by Room 162	Single Action	04061696
Smoke Detector	Upper Level Corridor by rm 166	Ionization	04061697
Smoke Detector	Upper Level Corridor by rm 167	Ionization	04061699
Smoke Detector	Upper Level Corridor by rm 169	Ionization	04061701
Pull Station	Upper Level Corridor by room 172	Single Action	04061707
Smoke Detector	Upper Level Media Work Room	Ionization	04061788
Smoke Detector	Upper Level Rm 134	Ionization	20668403
Smoke Detector	Upper Level Rm 131	Ionization	20668407
Smoke Detector	Upper Level Stairwell by rm 172	Ionization	04061708
Smoke Detector	Upper Level Stairwell by rm 173	Ionization	04061706
Smoke Detector	Upper Level Stairwell by room 164	Ionization	04061698
Smoke Detector	Upper Level Storage by rm 130	Ionization	04061742
Smoke Detector	Upper Level Storage by rm 130	Ionization	04061743
Zone/Circuit: 6			
Initiating Device	Upper Level Corridor By Meda Center Unit 3	Supporting Field Device	04061775
Smoke Detector	Upper Level Media Center	Ionization	04061777
Smoke Detector	Upper Level Media Center	Ionization	04061778
Smoke Detector	Upper Level Media Center	Ionization	04061781
Smoke Detector	Upper Level Media Center	Ionization	04061782

Pull Station	Upper Level Media Center Entrance	Single Action	04061779
Pull Station	Upper Level Media Center Entrance	Single Action	04061780
Initiating Device	Upper Level Media Work rm Unit 7	Supporting Field Device	04061789
Smoke Detector	Upper Level Technology Center	Ionization	04061786
Smoke Detector	Upper Level Technology Center	Ionization	20668409
Pull Station	Upper Level Technology Center Entrance	Single Action	04061784
Pull Station	Upper Level Technology Center Entrance	Single Action	04061785
Zone/Circuit: 7			
Smoke Detector	Lower Level Custodian rm by Storage	Ionization	20668399
Smoke Detector	Lower Level Main Lobby	Ionization	20668402
Smoke Detector	Lower Level Stairwell lobby Entrance	Ionization	20668405
Smoke Detector	Lower Level Corridor By Rm 41	Ionization	04061759
Smoke Detector	Lower Level Corridor By Rm 44	Ionization	04061758
Smoke Detector	Lower Level Corridor By Rm 45	Ionization	04061757
Smoke Detector	Lower Level Corridor Rm 37	Ionization	04061766
Smoke Detector	Lower Level Corridor Rm 40	Ionization	04061764
Pull Station	Lower Level Corridor by Art rm	Single Action	04061768
Smoke Detector	Lower Level Corridor by Art rm	Ionization	04061767
Pull Station	Lower Level Corridor by rm 41	Single Action	04061760
Pull Station	Lower Level Corridor by rm 46	Single Action	04061755
Smoke Detector	Lower Level Elevator Room by rm 38	Ionization	04061763
Smoke Detector	Lower Level Office by rm 45	Ionization	04061756
Smoke Detector	Lower Level Rm 37	Ionization	04061765
Smoke Detector	Lower Level Stairwell Lobby by Art Rm.	Ionization	04061770
Smoke Detector	Lower Level Storage room	Ionization	04061762
Smoke Detector	Lower Level Storage room	Ionization	04061771
Smoke Detector	Lower Level Storage room	Ionization	20668400
Zone/Circuit: 8			
Smoke Detector	Lower Level Art rm	Ionization	04061769
Pull Station	Lower Level Boiler Rm	Single Action	20668428
Smoke Detector	Lower Level Electrical Rm	Ionization	04061794
Smoke Detector	Lower Level Music rm Storage room by Art rm	Ionization	20668398
Zone/Circuit: 9			
Smoke Detector	Lower Level Portable Classroom	Ionization	04061716
Smoke Detector	Upper Level Corridor by Faculty Dinning	Ionization	04061723
Smoke Detector	Upper Level Corridor by Portable	Ionization	20668427
Pull Station	Upper Level Portable Classroom	Single Action	04061717
Smoke Detector	Upper Level Portable Classroom	Ionization	20668387
Pull Station	Upper Level Portable Classroom Main Entrance	Single Action	04061719
Smoke Detector	Upper Level Portable Classroom Rear	Ionization	20668391
Pull Station	Upper Level Portable Classroom rear	Single Action	04061721
Pull Station	Upper Level Side Entrance	Single Action	04061724
Zone/Circuit: 14			
Initiating Device	Upper Level Corridor By rm 163 Unit 3	Supporting Field Device	04061776

Zone/Circuit: 17				
Duct Detector	Upper Level Entrance to Technology Center	Ionization		04062255
Initiating Device	Upper Level Media Center by book Shelf next Wall Unit 1	Supporting Field Device		04061783
Zone/Circuit: 18				
Duct Detector	Upper Level Corridor By Main Office	Ionization		04061792
Initiating Device	Upper Level Corridor By Main Office Unit 2	Supporting Field Device		04061793
Initiating Device	Upper Level Main Office Unit 2	Supporting Field Device		20668389
Zone/Circuit: 20				
Duct Detector	Upper Level Corridor By rm 167	Ionization		20669862
Duct Detector	Upper Level Corridor By Rm133	Ionization		20668384
Initiating Device	Upper Level Corridor By rm 166 AHU 4	Supporting Field Device		04061774
Initiating Device	Upper Level Corridor By rm 167 AHU 4	Supporting Field Device		04061773
Zone/Circuit: 21				
Duct Detector	Upper Level Corridor By Rm188	Ionization		20668381
Initiating Device	Upper Level Corridor By rm 188 Unit 5	Supporting Field Device		04061791
Zone/Circuit: 25				
Initiating Device	Upper Level Corridor By Gym Unit 6	Supporting Field Device		20668375

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Cloonan School
11 West North Street
Stamford, CT 06902

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Mar 26, 2020



Building: Stamford BOE-Cloonan School
Contact: Davor Lucaj
Title: Facilities Trades Manager

Company: TPC Associates, Inc.
Contact: Landon Gendreau
Title: Inspector

Executive Summary





Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Cloonan School		Contact: Davor Lucaj
Address: 11 West North Street		Phone: 203-977-6668
Address:		Fax:
City/State/Zip: Stamford, CT 06902		Mobile: 347-675-6021
Country: United States of America		Email: dlucaj@stamfordct.gov
Inspection Performed By		
Company: TPC Associates, Inc.		Inspector: Landon Gendreau
Address: 261 Pepe's Farm Road		Phone: 2038781321
Address:		Fax:
City/State/Zip: Milford, Connecticut 06460		Mobile:
Country: United States of America		Email: landon.gendreau@tpcsystems.com
System Control Unit		
Manufacturer: EST	Inspection Date: 03/26/2020	IDC Style:
Model Number: EST-3	Install Date: 07/25/2012	SLC Style:
Software Version:	Version Date: 07/25/2012	NAC Style:
Location: 1st Loading Dock	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type: Digital Communicator	Mfg: NotiFire	Model #: 911A
Test Time/Date: 3/26/20 10:01:09 AM	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.41%	0	0%	0	0%	0	0%
Control	12	4.88%	12	100.00%	7	58.33%	5	41.67%
Initiating	233	94.72%	233	100.00%	233	100.00%	0	0%
Totals	246	100%	245	99.59%	240	97.96%	5	2.04%
Certification								
Company: TPC Associates, Inc.				Building: Stamford BOE-Cloonan School				
Inspector: Landon Gendreau				Contact: Davor Lucaj				
								
Signed: Mar 26, 2020 11:15:19 AM				Signed: Mar 26, 2020 11:16:31 AM				

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-Cloonan School			Control Panel: 1 - EST EST-3		
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>					
Device Type		Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>					
No recalled items found during this inspection.					
 ScanID	 Location		 Problem	Address	 Reference
<i>Control</i>					
Battery					
16320785	1st Dialer Panel		Failed Test	1-05	NFPA 72 Table 10.4.2.2.5(a-e)
16320782	2nd Electrical By Stair 4 Left		Failed Test	1-05	NFPA 72 Table 10.4.2.2.5(a-e)
16320781	2nd Electrical By Stair 4 Right		Failed Test	1-05	NFPA 72 Table 10.4.2.2.5(a-e)
20666194	3rd Electrical By Stair 4 Booster 5 (left)		Failed Test	1-09 0001	NFPA 72 Table 10.4.2.2.5(a-e)
20666195	3rd Electrical By Stair 4 Booster 6 (right)		Failed Test	1-09 0001	NFPA 72 Table 10.4.2.2.5(a-e)

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-Cloonan School			Control Panel: 1 - EST EST-3		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
<i>Control</i>					
Battery					
16320785	1st Dialer Panel	Replace	NP4-12	T/M	<input type="checkbox"/>
16320782	2nd Electrical By Stair 4 Left	Replace	UT 1270	T/M	<input type="checkbox"/>
16320781	2nd Electrical By Stair 4 Right	Replace	UT 1270	T/M	<input type="checkbox"/>
20666194	3rd Electrical By Stair 4 Booster 5 (left)	Replace	UB1280	T/M	<input type="checkbox"/>
20666195	3rd Electrical By Stair 4 Booster 6 (right)	Replace	UB1280	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

Notes & Recommendations

Generated by: BuildingReports.com

Building: Stamford BOE-Cloonan School				
<p><i>The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.</i></p>				
General Note				
upon activation of fire alarm all fire doors operated accordingly				
Building: Stamford BOE-Cloonan School		Control Panel: 1 - EST EST-3		
ScanID	Note	Device Type	Location	Comment
Control				
16320798	2	Battery	1st Booster By Panel Left	Passed
Battery replaced by TPC service tech 11/14/17				
16320797	3	Battery	1st Booster By Panel Right	Passed
Battery replaced by TPC service tech 11/14/17				
16320785	4	Battery	1st Dialer Panel	Failed Test
Battery replaced by TPC service tech 11/14/17				
16320784	5	Battery	1st Lower Cab By Panel Left	Passed
Battery replaced by TPC service tech 11/14/17				
20666195	6	Battery	3rd Electrical By Stair 4 Booster 6 (right)	Failed Test
Battery replaced by TPC service tech 11/14/17				

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Cloonan School		Control Panel: 1 - EST EST-3		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Battery	1st Booster By Panel Left	Tested	11:36:27 AM	03/26/2020
Battery	1st Booster By Panel Right	Tested	11:36:21 AM	03/26/2020
Battery	1st Lower Cab By Panel Left	Tested	10:15:14 AM	03/26/2020
Battery	1st Lower Cab By Panel Right	Tested	11:36:37 AM	03/26/2020
Battery	1st Lower Cab By Panel	Tested	11:36:16 AM	03/26/2020
Communicator	1st Dialer Panel	Visually Checked	10:01:09 AM	03/26/2020
Control Panel	1st Loading Dock	Visually Checked	10:01:55 AM	03/26/2020
Initiating				
CO Detector	1st Boiler Room	Visually Checked	12:05:29 PM	03/26/2020
CO Detector	1st Generater Room	Visually Checked	12:05:54 PM	03/26/2020
Duct Detector	1st Cafe Return	Visually Checked	12:08:35 PM	03/26/2020
Duct Detector	1st Cafe Supply	Visually Checked	12:08:41 PM	03/26/2020
Duct Detector	1st Mechanical 111F Return	Visually Checked	12:09:21 PM	03/26/2020
Duct Detector	1st Mechanical 111F Return	Visually Checked	12:09:33 PM	03/26/2020
Duct Detector	1st Mechanical Room 113E Return	Visually Checked	12:08:48 PM	03/26/2020
Duct Detector	1st Mechanical Room 113E Supply	Visually Checked	12:08:56 PM	03/26/2020
Duct Detector	3rd Mechanical 343 Return	Visually Checked	11:45:32 AM	03/26/2020
Duct Detector	3rd Mechanical 343 Supply	Visually Checked	11:45:24 AM	03/26/2020
Duct Detector	Mezzanine Above Gym Storage Return	Visually Checked	11:45:11 AM	03/26/2020
Duct Detector	Mezzanine Above Gym Storage Return 16	Visually Checked	11:45:00 AM	03/26/2020
Duct Detector	Mezzanine Above Gym Storage Return 17	Visually Checked	2:16:28 PM	03/26/2020
Duct Detector	Mezzanine Above Gym Storage Supply	Visually Checked	11:45:16 AM	03/26/2020
Duct Detector	Mezzanine Above Gym Storage Supply 16	Visually Checked	11:45:06 AM	03/26/2020
Duct Detector	Mezzanine Above Gym Storage Supply 17	Visually Checked	2:16:22 PM	03/26/2020
Heat Detector	1st Boiler Room (7 Heats On One Mod.)	Visually Checked	12:05:45 PM	03/26/2020
Heat Detector	1st Generater Room	Visually Checked	12:07:04 PM	03/26/2020
Pull Station	1st By Stair 1	Visually Checked	12:06:49 PM	03/26/2020
Pull Station	1st By Stair 2 Exit	Visually Checked	12:06:31 PM	03/26/2020
Pull Station	1st By Stair 2	Visually Checked	12:06:41 PM	03/26/2020
Pull Station	1st By Stair 4	Visually Checked	12:07:54 PM	03/26/2020
Pull Station	1st Auditorium Stair 7 Exit	Visually Checked	9:35:41 AM	03/26/2020
Pull Station	1st Auditorium Stair 8	Visually Checked	9:35:46 AM	03/26/2020
Pull Station	1st Boiler Room Exit	Visually Checked	12:05:37 PM	03/26/2020
Pull Station	1st Boiler Room	Visually Checked	12:08:05 PM	03/26/2020
Pull Station	1st Boy Locker Room By Stair 5	Visually Checked	9:57:53 AM	03/26/2020
Pull Station	1st Boys Locker room exit by stair 5	Visually Checked	12:08:00 PM	03/26/2020
Pull Station	1st By Stair 3	Visually Checked	12:06:26 PM	03/26/2020
Pull Station	1st Cafe Exit	Visually Checked	12:05:11 PM	03/26/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	1st Cafe Exit By Frezzer	Visually Checked	12:05:17 PM	03/26/2020
Pull Station	1st Cafe	Visually Checked	12:07:09 PM	03/26/2020
Pull Station	1st Cafe	Visually Checked	12:07:15 PM	03/26/2020
Pull Station	1st Cafe	Visually Checked	12:07:40 PM	03/26/2020
Pull Station	1st Cafe	Visually Checked	12:07:46 PM	03/26/2020
Pull Station	1st Generater Room	Visually Checked	12:06:01 PM	03/26/2020
Pull Station	1st Girls Locker Exit by Stair 6	Visually Checked	9:57:37 AM	03/26/2020
Pull Station	1st Girls Locker Exit by Stair 6	Visually Checked	9:57:41 AM	03/26/2020
Pull Station	1st Loading Dock	Visually Checked	12:06:10 PM	03/26/2020
Pull Station	1st Music Wing By Room 131	Visually Checked	10:59:29 AM	03/26/2020
Pull Station	1st Music Wing By Stair 7	Visually Checked	10:12:23 AM	03/26/2020
Pull Station	1st Music Wing By Stair 8	Visually Checked	10:12:19 AM	03/26/2020
Pull Station	1st Music Wing Room 106	Visually Checked	10:12:14 AM	03/26/2020
Pull Station	1st Room 111	Visually Checked	10:11:11 AM	03/26/2020
Pull Station	1st Room 112	Visually Checked	12:07:27 PM	03/26/2020
Pull Station	1st Room 113	Visually Checked	12:07:33 PM	03/26/2020
Pull Station	1st Special Ed Room 110A	Visually Checked	12:06:36 PM	03/26/2020
Pull Station	1st Stair 1	Visually Checked	12:06:54 PM	03/26/2020
Pull Station	1st Stair 4	Visually Checked	12:06:15 PM	03/26/2020
Pull Station	1st Stair 3	Visually Checked	12:06:20 PM	03/26/2020
Pull Station	2nd By Stair 5 Entrance	Visually Checked	11:37:51 AM	03/26/2020
Pull Station	2nd Auditorium By Stair 7	Visually Checked	11:38:55 AM	03/26/2020
Pull Station	2nd Auditorium By Stair 8	Visually Checked	11:38:47 AM	03/26/2020
Pull Station	2nd Auditorium Main Entrance	Visually Checked	11:37:27 AM	03/26/2020
Pull Station	2nd Auditorium Main Entrance	Visually Checked	11:37:32 AM	03/26/2020
Pull Station	2nd Auditorium On Stage By Stair 7	Visually Checked	11:38:40 AM	03/26/2020
Pull Station	2nd Auditorium Stage	Visually Checked	11:38:34 AM	03/26/2020
Pull Station	2nd Auditorium Stair 8 Storage 225	Visually Checked	11:38:28 AM	03/26/2020
Pull Station	2nd By Stair 2	Visually Checked	11:38:22 AM	03/26/2020
Pull Station	2nd By Stair 3	Visually Checked	11:38:16 AM	03/26/2020
Pull Station	2nd Gym	Visually Checked	11:37:38 AM	03/26/2020
Pull Station	2nd Gym	Visually Checked	11:37:46 AM	03/26/2020
Pull Station	2nd Gym	Visually Checked	11:37:56 AM	03/26/2020
Pull Station	2nd Gym	Visually Checked	11:47:16 AM	03/26/2020
Pull Station	2nd Main Lobby By Stair 1	Visually Checked	11:39:09 AM	03/26/2020
Pull Station	2nd Main Lobby	Visually Checked	11:39:04 AM	03/26/2020
Pull Station	2nd By Stair 3	Visually Checked	11:39:17 AM	03/26/2020
Pull Station	3rd By Stair 2	Visually Checked	11:37:16 AM	03/26/2020
Pull Station	3rd By Stair 3	Visually Checked	11:37:00 AM	03/26/2020
Pull Station	3rd By Stair 4	Visually Checked	11:37:07 AM	03/26/2020
Pull Station	3rd By Stair 1	Visually Checked	11:37:22 AM	03/26/2020
Pull Station	3rd By Stair 5	Visually Checked	11:36:43 AM	03/26/2020
Smoke Detector	1st By Stair 2	Visually Checked	9:41:48 AM	03/26/2020
Smoke Detector	1st By Stair 4	Visually Checked	12:10:04 PM	03/26/2020
Smoke Detector	1st Corner By Stair 1	Visually Checked	10:41:58 AM	03/26/2020
Smoke Detector	1st Outside Library	Visually Checked	9:36:33 AM	03/26/2020
Smoke Detector	1st Outside Library	Visually Checked	9:36:46 AM	03/26/2020
Smoke Detector	1st Outside Library	Visually Checked	9:36:59 AM	03/26/2020
Smoke Detector	1st Outside Transformer Room	Visually Checked	9:41:26 AM	03/26/2020
Smoke Detector	1st Phone Room by stair 2	Visually Checked	9:42:48 AM	03/26/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Boy Exercise Room	Visually Checked	9:55:47 AM	03/26/2020
Smoke Detector	1st Boy Exercise Room	Visually Checked	9:55:49 AM	03/26/2020
Smoke Detector	1st Boys Exercise Rooms Storage S22	Visually Checked	9:55:50 AM	03/26/2020
Smoke Detector	1st By Stair 3	Visually Checked	9:52:20 AM	03/26/2020
Smoke Detector	1st By Boys Locker Room	Visually Checked	9:54:39 AM	03/26/2020
Smoke Detector	1st By Boys Locker Room	Visually Checked	9:54:52 AM	03/26/2020
Smoke Detector	1st By Boys Locker Room	Visually Checked	9:55:14 AM	03/26/2020
Smoke Detector	1st By Boys Room	Visually Checked	10:35:24 AM	03/26/2020
Smoke Detector	1st By Cafe	Visually Checked	9:54:04 AM	03/26/2020
Smoke Detector	1st By Cafe	Visually Checked	9:59:31 AM	03/26/2020
Smoke Detector	1st By Cafe	Visually Checked	10:57:18 AM	03/26/2020
Smoke Detector	1st By Girls Room	Visually Checked	11:04:57 AM	03/26/2020
Smoke Detector	1st By Room 111C School store	Visually Checked	9:43:10 AM	03/26/2020
Smoke Detector	1st Cafe Above Freezer	Visually Checked	12:08:29 PM	03/26/2020
Smoke Detector	1st Custodial Office	Visually Checked	10:05:45 AM	03/26/2020
Smoke Detector	1st Data Server Room	Visually Checked	11:10:52 AM	03/26/2020
Smoke Detector	1st Electrical Room	Visually Checked	11:12:40 AM	03/26/2020
Smoke Detector	1st Girls Exercise Room Storage S22	Visually Checked	9:56:02 AM	03/26/2020
Smoke Detector	1st Girls Exercise Room	Visually Checked	9:56:00 AM	03/26/2020
Smoke Detector	1st Girls Exercise Room	Visually Checked	9:56:01 AM	03/26/2020
Smoke Detector	1st Girls Locker Room	Visually Checked	9:56:32 AM	03/26/2020
Smoke Detector	1st Girls Locker Room	Visually Checked	9:56:51 AM	03/26/2020
Smoke Detector	1st Girls Locker Room	Visually Checked	9:58:20 AM	03/26/2020
Smoke Detector	1st Library (Center)	Visually Checked	9:37:47 AM	03/26/2020
Smoke Detector	1st Library (East)	Visually Checked	9:38:01 AM	03/26/2020
Smoke Detector	1st Library (Left)	Visually Checked	9:37:35 AM	03/26/2020
Smoke Detector	1st Library Reading Room	Visually Checked	12:08:21 PM	03/26/2020
Smoke Detector	1st Library Reading Room/ Mechanical	Visually Checked	11:04:18 AM	03/26/2020
Smoke Detector	1st Library Storage	Visually Checked	9:39:23 AM	03/26/2020
Smoke Detector	1st Library Workroom	Visually Checked	9:38:58 AM	03/26/2020
Smoke Detector	1st Loading Dock	Visually Checked	12:09:56 PM	03/26/2020
Smoke Detector	1st Loading Dock	Visually Checked	12:10:23 PM	03/26/2020
Smoke Detector	1st Mechanical	Visually Checked	12:09:26 PM	03/26/2020
Smoke Detector	1st Mechanical Room 113E	Visually Checked	12:09:03 PM	03/26/2020
Smoke Detector	1st Music Wing By Room 105 Storage A	Visually Checked	10:40:43 AM	03/26/2020
Smoke Detector	1st Music Wing By Room 105 Storage B	Visually Checked	10:38:29 AM	03/26/2020
Smoke Detector	1st Music Wing By Room 119	Visually Checked	10:59:19 AM	03/26/2020
Smoke Detector	1st Music Wing By Room 128 Storage	Visually Checked	10:39:34 AM	03/26/2020
Smoke Detector	1st Music Wing By Room 130	Visually Checked	10:36:18 AM	03/26/2020
Smoke Detector	1st Music Wing By Room 130	Visually Checked	10:37:14 AM	03/26/2020
Smoke Detector	1st Music Wing By Room 131	Visually Checked	10:36:06 AM	03/26/2020
Smoke Detector	1st Music Wing Storage 106A	Visually Checked	11:00:42 AM	03/26/2020
Smoke Detector	1st Music Wing Storage 106A	Visually Checked	12:10:40 PM	03/26/2020
Smoke Detector	1st Music Wing	Visually Checked	10:36:50 AM	03/26/2020
Smoke Detector	1st Music Wing	Visually Checked	10:36:57 AM	03/26/2020
Smoke Detector	1st Music Wing	Visually Checked	2:14:38 PM	03/26/2020
Smoke Detector	1st Outside Room 112	Visually Checked	9:43:32 AM	03/26/2020
Smoke Detector	1st Outside Room 112B	Visually Checked	9:44:14 AM	03/26/2020
Smoke Detector	1st Outside Room 112B	Visually Checked	9:51:34 AM	03/26/2020
Smoke Detector	1st Outside Room 114 By Stair 3	Visually Checked	9:52:35 AM	03/26/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Receiving Dock	Visually Checked	12:10:16 PM	03/26/2020
Smoke Detector	1st Room 114 Storage	Visually Checked	10:50:02 AM	03/26/2020
Smoke Detector	1st Stair 1	Visually Checked	9:35:03 AM	03/26/2020
Smoke Detector	1st Storage	Visually Checked	12:09:51 PM	03/26/2020
Smoke Detector	1st Storage in Boys Room	Visually Checked	10:57:04 AM	03/26/2020
Smoke Detector	1st Storage Room In Custodial Break Room	Visually Checked	12:10:09 PM	03/26/2020
Smoke Detector	1st Storage Room By Restrooms (Center)	Visually Checked	10:58:05 AM	03/26/2020
Smoke Detector	1st Storage Room By Restrooms (East)	Visually Checked	10:58:03 AM	03/26/2020
Smoke Detector	1st Storage Room By Restrooms (West)	Visually Checked	10:58:03 AM	03/26/2020
Smoke Detector	1st Switchgear Room	Visually Checked	12:09:44 PM	03/26/2020
Smoke Detector	2nd By Electrical Room	Visually Checked	12:03:07 PM	03/26/2020
Smoke Detector	2nd By Room 211	Visually Checked	11:51:17 AM	03/26/2020
Smoke Detector	2nd By Room 214	Visually Checked	11:53:33 AM	03/26/2020
Smoke Detector	2nd By Room 216	Visually Checked	12:04:05 PM	03/26/2020
Smoke Detector	2nd By Room 217	Visually Checked	12:03:58 PM	03/26/2020
Smoke Detector	2nd By Stair 3	Visually Checked	11:52:24 AM	03/26/2020
Smoke Detector	2nd Room 213 Storage	Visually Checked	2:28:09 PM	03/26/2020
Smoke Detector	2nd Room 215 Storage	Visually Checked	11:48:49 AM	03/26/2020
Smoke Detector	2nd 210 Back Electrical Closet	Visually Checked	11:51:08 AM	03/26/2020
Smoke Detector	2nd 210 Closet	Visually Checked	11:49:19 AM	03/26/2020
Smoke Detector	2nd 211 Storage	Visually Checked	11:49:09 AM	03/26/2020
Smoke Detector	2nd Auditorium Stair 7	Visually Checked	11:54:42 AM	03/26/2020
Smoke Detector	2nd Auditorium On Stage By Stair 7	Visually Checked	2:28:29 PM	03/26/2020
Smoke Detector	2nd Auditorium Stage	Visually Checked	11:55:30 AM	03/26/2020
Smoke Detector	2nd Auditorium Stair 7	Visually Checked	11:54:35 AM	03/26/2020
Smoke Detector	2nd Auditorium Stair 8 Storage 225	Visually Checked	11:55:07 AM	03/26/2020
Smoke Detector	2nd Auditorium Stair 8 Storage 225	Visually Checked	11:55:13 AM	03/26/2020
Smoke Detector	2nd Auditorium Stair 8	Visually Checked	11:54:50 AM	03/26/2020
Smoke Detector	2nd Auditorium Stair 8	Visually Checked	11:55:00 AM	03/26/2020
Smoke Detector	2nd By Boys Room	Visually Checked	11:54:21 AM	03/26/2020
Smoke Detector	2nd By Custodian Room 230	Visually Checked	2:28:19 PM	03/26/2020
Smoke Detector	2nd By Room 201	Visually Checked	11:53:52 AM	03/26/2020
Smoke Detector	2nd By Room 203	Visually Checked	11:54:01 AM	03/26/2020
Smoke Detector	2nd By Room 207	Visually Checked	11:54:12 AM	03/26/2020
Smoke Detector	2nd By Stair 2	Visually Checked	11:53:45 AM	03/26/2020
Smoke Detector	2nd By Stair 3	Visually Checked	11:54:28 AM	03/26/2020
Smoke Detector	2nd By Waiting Room	Visually Checked	12:02:53 PM	03/26/2020
Smoke Detector	2nd Corridor By Gym	Visually Checked	11:51:28 AM	03/26/2020
Smoke Detector	2nd Corridor By Gym	Visually Checked	11:51:49 AM	03/26/2020
Smoke Detector	2nd Corridor By Gyms Main Entrance	Visually Checked	11:52:01 AM	03/26/2020
Smoke Detector	2nd Corridor By Gyms Main Entrance	Visually Checked	11:52:15 AM	03/26/2020
Smoke Detector	2nd Data Room 201A	Visually Checked	11:51:00 AM	03/26/2020
Smoke Detector	2nd Electrical Room By Stair 4	Visually Checked	11:52:08 AM	03/26/2020
Smoke Detector	2nd Gym Electrical Room	Visually Checked	12:04:19 PM	03/26/2020
Smoke Detector	2nd Gym Storage	Visually Checked	12:04:39 PM	03/26/2020
Smoke Detector	2nd Gym Storage	Visually Checked	12:04:47 PM	03/26/2020
Smoke Detector	2nd Gym / Stair	Visually Checked	12:05:06 PM	03/26/2020
Smoke Detector	2nd Main Lobby By Office	Visually Checked	12:03:14 PM	03/26/2020
Smoke Detector	2nd Main Lobby By Stair 1	Visually Checked	12:03:28 PM	03/26/2020
Smoke Detector	2nd Main Lobby	Visually Checked	12:03:21 PM	03/26/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd Stair 5 Entrance	Visually Checked	12:02:46 PM	03/26/2020
Smoke Detector	2nd By Room 218	Visually Checked	12:02:04 PM	03/26/2020
Smoke Detector	2nd By Room 219	Visually Checked	12:01:57 PM	03/26/2020
Smoke Detector	2nd By Room 219 Storage	Visually Checked	11:50:44 AM	03/26/2020
Smoke Detector	2nd By Room 220	Visually Checked	12:01:48 PM	03/26/2020
Smoke Detector	2nd Main Office (Barcode on Strobe)	Visually Checked	12:03:44 PM	03/26/2020
Smoke Detector	2nd Office Kitchen/Copy Room	Visually Checked	12:03:35 PM	03/26/2020
Smoke Detector	2nd Office Storage	Visually Checked	12:03:50 PM	03/26/2020
Smoke Detector	2nd By Room 218	Visually Checked	12:02:34 PM	03/26/2020
Smoke Detector	2nd Room 218 Storage	Visually Checked	2:17:22 PM	03/26/2020
Smoke Detector	2nd Room 220 Storage	Visually Checked	11:50:49 AM	03/26/2020
Smoke Detector	3rd Between Room 303 And 304	Visually Checked	11:43:28 AM	03/26/2020
Smoke Detector	3rd Between Room 301 And 302	Visually Checked	2:15:05 PM	03/26/2020
Smoke Detector	3rd By Room 310	Visually Checked	11:40:45 AM	03/26/2020
Smoke Detector	3rd By Room 312	Visually Checked	11:40:54 AM	03/26/2020
Smoke Detector	3rd By Room 314	Visually Checked	2:14:54 PM	03/26/2020
Smoke Detector	3rd By Room 318	Visually Checked	11:41:58 AM	03/26/2020
Smoke Detector	3rd By Room 320	Visually Checked	11:42:08 AM	03/26/2020
Smoke Detector	3rd By Room 322	Visually Checked	11:41:16 AM	03/26/2020
Smoke Detector	3rd By Room 322	Visually Checked	11:42:19 AM	03/26/2020
Smoke Detector	3rd By Room 322	Visually Checked	11:42:27 AM	03/26/2020
Smoke Detector	3rd By Stair 3	Visually Checked	8:15:59 AM	03/26/2020
Smoke Detector	3rd By Stair 4	Visually Checked	11:42:47 AM	03/26/2020
Smoke Detector	3rd By Boys Room	Visually Checked	2:15:16 PM	03/26/2020
Smoke Detector	3rd By Copy Room	Visually Checked	11:39:47 AM	03/26/2020
Smoke Detector	3rd By Room 302	Visually Checked	11:43:38 AM	03/26/2020
Smoke Detector	3rd By Room 324 Storage	Visually Checked	11:40:17 AM	03/26/2020
Smoke Detector	3rd By Room 325 Storage	Visually Checked	11:39:56 AM	03/26/2020
Smoke Detector	3rd By Room 325	Visually Checked	11:40:25 AM	03/26/2020
Smoke Detector	3rd By Room 325	Visually Checked	11:40:36 AM	03/26/2020
Smoke Detector	3rd By Room 326 Storage	Visually Checked	11:39:27 AM	03/26/2020
Smoke Detector	3rd By Room 326	Visually Checked	11:40:05 AM	03/26/2020
Smoke Detector	3rd Copy Room	Visually Checked	11:36:50 AM	03/26/2020
Smoke Detector	3rd Corridor Between Stair 1 And 4 By Balcolny	Visually Checked	11:44:10 AM	03/26/2020
Smoke Detector	3rd Corridor Between Stair 1 And 4	Visually Checked	11:44:20 AM	03/26/2020
Smoke Detector	3rd Corridor Between Stair 1 And 4	Visually Checked	11:44:33 AM	03/26/2020
Smoke Detector	3rd Corridor By Stair 1	Visually Checked	11:44:04 AM	03/26/2020
Smoke Detector	3rd Electrical By Room 302	Visually Checked	2:17:16 PM	03/26/2020
Smoke Detector	3rd Electrical By Stair 4	Visually Checked	11:43:03 AM	03/26/2020
Smoke Detector	3rd Mechanical 343	Visually Checked	2:16:38 PM	03/26/2020
Smoke Detector	3rd Mechanical 343	Visually Checked	2:16:44 PM	03/26/2020
Smoke Detector	3rd Mechanical 343	Visually Checked	2:16:53 PM	03/26/2020
Smoke Detector	3rd Stair 1	Visually Checked	11:43:53 AM	03/26/2020
Smoke Detector	3rd Stair 5	Visually Checked	11:39:36 AM	03/26/2020
Smoke Detector	3rd By Room 304	Visually Checked	11:43:20 AM	03/26/2020
Smoke Detector	3rd By Stair 2	Visually Checked	11:43:11 AM	03/26/2020
Smoke Detector	3rd Stair 2	Visually Checked	11:42:55 AM	03/26/2020
Smoke Detector	3rd Stair 3	Visually Checked	11:41:35 AM	03/26/2020
Smoke Detector	3rd Stair 4	Visually Checked	11:42:38 AM	03/26/2020
Smoke Detector	Mezzanine Above Gym Storage	Visually Checked	11:48:16 AM	03/26/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Mezzanine Above Gym Storage	Visually Checked	11:48:21 AM	03/26/2020
Smoke Detector	Mezzanine Above Gym Storage	Visually Checked	11:48:26 AM	03/26/2020
Smoke Detector	Mezzanine Above Gym Storage	Visually Checked	2:17:00 PM	03/26/2020
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	1st Dialer Panel	Tested	10:01:43 AM	03/26/2020
Battery	2nd Electrical By Stair 4 Left	Tested	10:23:36 AM	03/26/2020
Battery	2nd Electrical By Stair 4 Right	Tested	10:22:16 AM	03/26/2020
Battery	3rd Electrical By Stair 4 Booster 5 (left)	Tested	10:26:56 AM	03/26/2020
Battery	3rd Electrical By Stair 4 Booster 6 (right)	Tested	10:28:22 AM	03/26/2020

Service Summary

Generated by: BuildingReports.com




Building: Stamford BOE-Cloonan School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	5
Total		5
<i>Passed</i>		
Battery	Tested	5
CO Detector	Visually Checked	2
Communicator	Visually Checked	1
Control Panel	Visually Checked	1
Duct Detector	Visually Checked	14
Heat Detector	Visually Checked	2
Pull Station	Visually Checked	54
Smoke Detector	Visually Checked	161
Total		240
Grand Total		245

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Cloonan School							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		◀ dB	◀ dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
Whole Facility				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Cloonan School				Control Panel: 1 - EST EST-3			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	1st Booster By Panel Left	8AH	12V	12.57V	6ah		
Sealed Lead Acid	1st Booster By Panel Right	8AH	12V	12.60V	7.2ah		
Sealed Lead Acid	1st Lower Cab By Panel Left	50AH	12V	13.31V	12ah		
Sealed Lead Acid	1st Lower Cab By Panel Right	50ah	12v	13.29V	30ah		
Sealed Lead Acid	1st Lower Cab By Panel	12AH	12V	12.76V	7.8ah		
Failed/Other							
Battery							
Sealed Lead Acid	1st Dialer Panel	5AH	12V	12.47V	2.3ah		
Sealed Lead Acid	2nd Electrical By Stair 4 Left	8AH	12V	12.59V	2.5ah		
Sealed Lead Acid	2nd Electrical By Stair 4 Right	8AH	12V	12.63V	2.3Ah		
Sealed Lead Acid	3rd Electrical By Stair 4 Booster 5 (left)	8AH	12V	12.57V	4.0ah		
Sealed Lead Acid	3rd Electrical By Stair 4 Booster 6 (right)	8AH	12V	12.63V	3.3ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Cloonan School				Control Panel: 1 - EST EST-3	
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		0.41%	1
Smoke Detector		Initiating		65.45%	161
Pull Station		Initiating		21.95%	54
Communicator		Control		0.41%	1
Battery		Control		4.07%	10
Control Panel		Control		0.41%	1
Duct Detector		Initiating		5.69%	14
CO Detector		Initiating		0.81%	2
Heat Detector		Initiating		0.81%	2
Type	Qty	Model #	Description		Install Date
In Service - 2 Years to 3 Years					
Ultra Tech					
Battery	2	UT 1270	Sealed Lead Acid		11/14/2017
Universal					
Battery	2	UB12500	Sealed Lead Acid		11/14/2017
Battery	4	UB1280	Sealed Lead Acid		11/14/2017
Yuasa					
Battery	1	NP4-12	Sealed Lead Acid		11/14/2017
In Service - 5 Years to 10 Years					
Embassy					
Battery	1	12CE12 T1	Sealed Lead Acid		07/25/2012
EST					
Control Panel	1	EST-3			07/25/2012
Duct Detector	14	SIGA-SD	Photoelectric		07/25/2012
Heat Detector	2	283B	Fixed Temperature		07/25/2012
Pull Station	54	SIGA-278	Dual Action		07/25/2012
Smoke Detector	16	SIGA-PS	Photoelectric		07/25/2012
	1				
Macurco					
CO Detector	2	CM-S1			07/25/2012
NotiFire					
Communicator	1	911A	Digital Communicator		07/25/2012

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Cloonan School			Control Panel: 1 - EST EST-3	
<i>The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.</i>				
Address	Device Type	Location	Type	ScanID
Zone/Circuit: 01				
0615	Battery	1st Lower Cab By Panel Left	Sealed Lead Acid	16320784
Zone/Circuit: 05				
0001	Smoke Detector	1st Music Wing	Photoelectric	20666509
0002	Smoke Detector	1st Music Wing By Room 119	Photoelectric	20666512
0003	Smoke Detector	1st Music Wing By Room 130	Photoelectric	20666516
0004	Smoke Detector	1st Music Wing Storage 106A	Photoelectric	20666506
0005	Smoke Detector	1st Music Wing By Room 131	Photoelectric	20666518
0007	Smoke Detector	1st Girls Exercise Room Storage S22	Photoelectric	20666526
0008	Smoke Detector	1st Boy Exercise Room	Photoelectric	20666532
0009	Smoke Detector	1st Boy Exercise Room	Photoelectric	20666533
0010	Smoke Detector	1st Boys Exercise Rooms Storage S22	Photoelectric	20666525
0011	Smoke Detector	1st Girls Exercise Room	Photoelectric	20666528
0012	Smoke Detector	1st Girls Exercise Room	Photoelectric	20666527
0013	Smoke Detector	1st Girls Locker Room	Photoelectric	20666531
0014	Smoke Detector	1st Girls Locker Room	Photoelectric	20666530
0015	Smoke Detector	1st Girls Locker Room	Photoelectric	20666529
0016	Smoke Detector	1st Storage Room By Restrooms (East)	Photoelectric	20666520
0017	Smoke Detector	1st Storage Room By Restrooms (West)	Photoelectric	20666521
0018	Smoke Detector	1st Electrical Room	Photoelectric	20666597
0018	Smoke Detector	1st Storage Room By Restrooms (Center)	Photoelectric	20666522
0019	Smoke Detector	1st By Boys Locker Room	Photoelectric	20666539
0020	Smoke Detector	1st Storage in Boys Room	Photoelectric	20666536
0021	Smoke Detector	1st By Boys Locker Room	Photoelectric	20666538
0022	Smoke Detector	1st By Boys Locker Room	Photoelectric	20666537
0025	Smoke Detector	1st Music Wing By Room 128 Storage	Photoelectric	20666515
0026	Smoke Detector	1st Music Wing	Photoelectric	20666510
0027	Smoke Detector	1st Music Wing	Photoelectric	20666511
0028	Smoke Detector	1st Music Wing By Room 130	Photoelectric	20666517
0029	Smoke Detector	1st Corner By Stair 1	Photoelectric	20666022
0030	Smoke Detector	1st Outside Library	Photoelectric	20666013
0031	Smoke Detector	1st Outside Library	Photoelectric	20666014
0032	Smoke Detector	1st Outside Library	Photoelectric	20666012
0033	Smoke Detector	1st Outside Transformer Room	Photoelectric	20666011
0034	Smoke Detector	1st Stair 1	Photoelectric	20666025
0035	Smoke Detector	1st Library Reading Room/ Mechanical	Photoelectric	20666021
0036	Smoke Detector	1st Library (East)	Photoelectric	20666019
0037	Smoke Detector	1st Library (Center)	Photoelectric	20666018
0038	Smoke Detector	1st Library (Left)	Photoelectric	20666017
0039	Smoke Detector	1st Library Storage	Photoelectric	20666015
0040	Smoke Detector	1st Library Workroom	Photoelectric	20666016

0041	Smoke Detector	1st By Boys Room	Photoelectric	20666540
0042	Smoke Detector	1st Phone Room by stair 2	Photoelectric	21097510
0043	Smoke Detector	1st By Stair 2	Photoelectric	20666010
0044	Smoke Detector	1st By Room 111C School store	Photoelectric	20666596
0045	Smoke Detector	1st Outside Room 112	Photoelectric	20666588
0046	Smoke Detector	1st Data Server Room	Photoelectric	20666593
0047	Smoke Detector	1st By Cafe	Photoelectric	20666543
0048	Smoke Detector	1st By Cafe	Photoelectric	20666544
0049	Smoke Detector	1st By Cafe	Photoelectric	20666542
0050	Smoke Detector	1st By Girls Room	Photoelectric	20666541
0051	Smoke Detector	1st Outside Room 112B	Photoelectric	20666587
0052	Smoke Detector	1st Outside Room 112B	Photoelectric	20666586
0053	Smoke Detector	1st By Stair 3	Photoelectric	20666581
0054	Smoke Detector	1st Outside Room 114 By Stair 3	Photoelectric	20666585
0054	Smoke Detector	1st Room 114 Storage	Photoelectric	20666584
0056	Smoke Detector	1st Custodial Office	Photoelectric	20666503
0057	Smoke Detector	1st Music Wing By Room 105 Storage A	Photoelectric	20666514
0058	Smoke Detector	1st Music Wing By Room 105 Storage B	Photoelectric	20666513
0059	Smoke Detector	1st Music Wing Storage 106A	Photoelectric	20666505
0060	Smoke Detector	1st Loading Dock	Photoelectric	20666502
0061	Smoke Detector	1st Receiving Dock	Photoelectric	20669857
0062	Smoke Detector	1st Storage Room In Custodial Break Room	Photoelectric	20666549
0063	Smoke Detector	1st By Stair 4	Photoelectric	20666557
0064	Smoke Detector	1st Loading Dock	Photoelectric	20666556
0064	Smoke Detector	1st Storage	Photoelectric	20666551
0065	Smoke Detector	1st Switchgear Room	Photoelectric	20666550
0066	Duct Detector	1st Mechanical 111F Return	Photoelectric	20666501
0067	Smoke Detector	1st Mechanical	Photoelectric	20666499
0068	Duct Detector	1st Mechanical 111F Return	Photoelectric	20666500
0069	Smoke Detector	1st Mechanical Room 113E	Photoelectric	20666591
0070	Duct Detector	1st Mechanical Room 113E Supply	Photoelectric	20666590
0071	Duct Detector	1st Mechanical Room 113E Return	Photoelectric	20666589
0080	Duct Detector	1st Cafe Supply	Photoelectric	20666576
0081	Duct Detector	1st Cafe Return	Photoelectric	20666575
0082	Smoke Detector	1st Cafe Above Freezer	Photoelectric	20669860
0083	Smoke Detector	1st Library Reading Room	Photoelectric	20666020
0138	Pull Station	1st Room 111	Dual Action	20666595
0139	Pull Station	1st Auditorium Stair 8	Dual Action	20666028
0140	Pull Station	1st Music Wing By Stair 8	Dual Action	20666507
0141	Pull Station	1st Music Wing Room 106	Dual Action	20666504
0142	Pull Station	1st Music Wing By Stair 7	Dual Action	20666508
0143	Pull Station	1st Auditorium Stair 7 Exit	Dual Action	20666026
0144	Pull Station	1st Music Wing By Room 131	Dual Action	20666519
0145	Pull Station	1st Girls Locker Exit by Stair 6	Dual Action	20666523
0146	Pull Station	1st Girls Locker Exit by Stair 6	Dual Action	20666524
0147	Pull Station	1st Boy Locker Room By Stair 5	Dual Action	20666535
0148	Pull Station	1st Boiler Room	Dual Action	20666548
0149	Pull Station	1st Boys Locker room exit by stair 5	Dual Action	20666534
0150	Pull Station	1st By Stair 4	Dual Action	20666558
0151	Pull Station	1st Cafe	Dual Action	20666578
0152	Pull Station	1st Cafe	Dual Action	20666579
0153	Pull Station	1st Room 113	Dual Action	20666592

0154	Pull Station	1st Room 112	Dual Action	20666594
0155	Pull Station	1st Cafe	Dual Action	20666580
0156	Pull Station	1st Cafe	Dual Action	20666577
0156	Heat Detector	1st Generator Room	Fixed Temperature	20666554
0157	Pull Station	1st Stair 1	Dual Action	20666024
0158	Pull Station	1st By Stair 1	Dual Action	20666023
0160	Pull Station	1st By Stair 2	Dual Action	20666009
0161	Pull Station	1st Special Ed Room 110A	Dual Action	20666598
0162	Pull Station	1st By Stair 2 Exit	Dual Action	20666599
0163	Pull Station	1st By Stair 3	Dual Action	20666582
0164	Pull Station	1st Stair 3	Dual Action	20666583
0165	Pull Station	1st Stair 4	Dual Action	20666559
0166	Pull Station	1st Loading Dock	Dual Action	20666555
0167	Pull Station	1st Generator Room	Dual Action	20666553
0171	CO Detector	1st Generator Room		20666552
0174	Heat Detector	1st Boiler Room (7 Heats On One Mod.)	Fixed Temperature	20666545
0176	Pull Station	1st Boiler Room Exit	Dual Action	20666547
0177	CO Detector	1st Boiler Room		20666546
0184	Pull Station	1st Cafe Exit By Frezzer	Dual Action	20666574
0185	Pull Station	1st Cafe Exit	Dual Action	20666573
0251	Smoke Detector	2nd Gym / Stair	Photoelectric	20666056
0252	Smoke Detector	2nd Gym Storage	Photoelectric	20666053
0253	Smoke Detector	2nd Gym Storage	Photoelectric	20666054
0254	Smoke Detector	2nd Gym Electrical Room	Photoelectric	20666055
0255	Smoke Detector	2nd By Room 216	Photoelectric	20666079
0256	Smoke Detector	2nd By Room 217	Photoelectric	20666077
0257	Smoke Detector	2nd Office Storage	Photoelectric	20666097
0258	Smoke Detector	2nd Main Office (Barcode on Strobe)	Photoelectric	20666098
0259	Smoke Detector	2nd Office Kitchen/Copy Room	Photoelectric	20666096
0260	Smoke Detector	2nd Main Lobby By Stair 1	Photoelectric	20666199
0261	Smoke Detector	2nd Main Lobby	Photoelectric	20666197
0262	Smoke Detector	2nd Main Lobby By Office	Photoelectric	20666099
0263	Smoke Detector	2nd By Electrical Room	Photoelectric	20666095
0264	Smoke Detector	2nd By Custodian Room 230	Photoelectric	20666094
0265	Smoke Detector	2nd By Waiting Room	Photoelectric	20666093
0266	Smoke Detector	2nd Stair 5 Entrance	Photoelectric	20666062
0267	Smoke Detector	2nd By Room 218	Photoelectric	20666069
0268	Smoke Detector	2nd By Room 218	Photoelectric	20666067
0269	Smoke Detector	2nd By Room 219	Photoelectric	20666066
0270	Smoke Detector	2nd By Room 220	Photoelectric	20666063
0271	Smoke Detector	2nd Auditorium Stage	Photoelectric	20666035
0272	Smoke Detector	2nd Auditorium On Stage By Stair 7	Photoelectric	20666037
0273	Smoke Detector	2nd Auditorium Stair 8 Storage 225	Photoelectric	20666030
0274	Smoke Detector	2nd Auditorium Stair 8 Storage 225	Photoelectric	20666031
0275	Smoke Detector	2nd Auditorium Stair 8	Photoelectric	20666032
0276	Smoke Detector	2nd Auditorium Stair 8	Photoelectric	20666033
0277	Smoke Detector	2nd Auditorium Stair 7	Photoelectric	20666036
0278	Smoke Detector	2nd Auditorium Stair 7	Photoelectric	20666027
0279	Smoke Detector	2nd By Stair 3	Photoelectric	20666085
0280	Smoke Detector	2nd By Boys Room	Photoelectric	20666086
0281	Smoke Detector	2nd By Room 207	Photoelectric	20666087
0282	Smoke Detector	2nd By Room 203	Photoelectric	20666088
0283	Smoke Detector	2nd By Room 201	Photoelectric	20666089

0284	Smoke Detector	2nd By Stair 2	Photoelectric	20666092
0285	Smoke Detector	2nd By Room 214	Photoelectric	20666080
0286	Smoke Detector	2nd By Stair 3	Photoelectric	20666076
0287	Smoke Detector	2nd Corridor By Gyms Main Entrance	Photoelectric	20666070
0288	Smoke Detector	2nd Electrical Room By Stair 4	Photoelectric	20666075
0289	Smoke Detector	2nd Corridor By Gyms Main Entrance	Photoelectric	20666071
0290	Smoke Detector	2nd Corridor By Gym	Photoelectric	20666073
0291	Smoke Detector	2nd Corridor By Gym	Photoelectric	20666072
0292	Smoke Detector	2nd By Room 211	Photoelectric	20666082
0293	Smoke Detector	2nd 210 Back Electrical Closet	Photoelectric	20669859
0294	Smoke Detector	2nd Data Room 201A	Photoelectric	20666090
0297	Smoke Detector	2nd Room 220 Storage	Photoelectric	3957977647
0298	Smoke Detector	2nd By Room 219 Storage	Photoelectric	20666065
0300	Smoke Detector	2nd 210 Closet	Photoelectric	20669858
0301	Smoke Detector	2nd 211 Storage	Photoelectric	20666083
0302	Smoke Detector	2nd Room 213 Storage	Photoelectric	20666081
0303	Smoke Detector	2nd Room 215 Storage	Photoelectric	20666078
0304	Smoke Detector	2nd Room 218 Storage	Photoelectric	20666068
0305	Smoke Detector	3rd Electrical By Room 302	Photoelectric	20666155
0321	Smoke Detector	Mezzanine Above Gym Storage	Photoelectric	20666043
0322	Smoke Detector	Mezzanine Above Gym Storage	Photoelectric	20666048
0323	Smoke Detector	Mezzanine Above Gym Storage	Photoelectric	20666047
0324	Smoke Detector	Mezzanine Above Gym Storage	Photoelectric	20666044
0325	Smoke Detector	3rd Mechanical 343	Photoelectric	20666191
0326	Smoke Detector	3rd Mechanical 343	Photoelectric	20666189
0327	Smoke Detector	3rd Mechanical 343	Photoelectric	20666190
0328	Duct Detector	3rd Mechanical 343 Return	Photoelectric	20666193
0328	Duct Detector	3rd Mechanical 343 Supply	Photoelectric	20666192
0330	Duct Detector	Mezzanine Above Gym Storage Supply	Photoelectric	20666045
0331	Duct Detector	Mezzanine Above Gym Storage Return	Photoelectric	20666046
0332	Duct Detector	Mezzanine Above Gym Storage Supply 16	Photoelectric	20666049
0333	Duct Detector	Mezzanine Above Gym Storage Return 16	Photoelectric	20666050
0334	Duct Detector	Mezzanine Above Gym Storage Return 17	Photoelectric	20666052
0335	Duct Detector	Mezzanine Above Gym Storage Supply 17	Photoelectric	20666051
0340	Smoke Detector	3rd By Boys Room	Photoelectric	20666185
0341	Smoke Detector	3rd Corridor Between Stair 1 And 4	Photoelectric	20666186
0342	Smoke Detector	3rd Corridor Between Stair 1 And 4	Photoelectric	20666187
0343	Smoke Detector	3rd Corridor Between Stair 1 And 4 By Balcolny	Photoelectric	20666188
0344	Smoke Detector	3rd Corridor By Stair 1	Photoelectric	20666152
0345	Smoke Detector	3rd Stair 1	Photoelectric	20666150
0346	Smoke Detector	3rd Between Room 301 And 302	Photoelectric	20666153
0347	Smoke Detector	3rd By Room 302	Photoelectric	20666154
0348	Smoke Detector	3rd Between Room 303 And 304	Photoelectric	20666156
0349	Smoke Detector	3rd By Room 304	Photoelectric	20666157
0350	Smoke Detector	3rd By Stair 2	Photoelectric	20666158
0351	Smoke Detector	3rd Stair 2	Photoelectric	20666159
0351	Smoke Detector	3rd Electrical By Stair 4	Photoelectric	20666173
0352	Smoke Detector	3rd By Stair 4	Photoelectric	20666172

0353	Smoke Detector	3rd Stair 4	Photoelectric	20666175
0354	Smoke Detector	3rd By Room 322	Photoelectric	20666171
0355	Smoke Detector	3rd By Room 322	Photoelectric	20666170
0356	Smoke Detector	3rd By Room 320	Photoelectric	20666169
0357	Smoke Detector	3rd By Room 318	Photoelectric	20666168
0358	Smoke Detector	3rd By Stair 3	Photoelectric	20666165
0359	Smoke Detector	3rd Stair 3	Photoelectric	20666166
0360	Smoke Detector	3rd By Room 322	Photoelectric	20666164
0361	Smoke Detector	3rd By Room 314	Photoelectric	20666163
0362	Smoke Detector	3rd By Room 312	Photoelectric	20666162
0363	Smoke Detector	3rd By Room 310	Photoelectric	20666161
0364	Smoke Detector	3rd By Room 325	Photoelectric	20666176
0365	Smoke Detector	3rd By Room 325	Photoelectric	20666177
0366	Smoke Detector	3rd By Room 324 Storage	Photoelectric	20666178
0367	Smoke Detector	3rd By Room 326	Photoelectric	20666180
0368	Smoke Detector	3rd By Room 325 Storage	Photoelectric	20666179
0369	Smoke Detector	3rd By Copy Room	Photoelectric	20666181
0370	Smoke Detector	3rd Stair 5	Photoelectric	20666182
0371	Smoke Detector	3rd By Room 326 Storage	Photoelectric	21098544
0376	Pull Station	2nd By Stair 3	Dual Action	51386276
0377	Pull Station	2nd Main Lobby By Stair 1	Dual Action	20666198
0378	Pull Station	2nd Main Lobby	Dual Action	20666196
0379	Pull Station	2nd Auditorium By Stair 7	Dual Action	20666039
0380	Pull Station	2nd Auditorium By Stair 8	Dual Action	20666040
0381	Pull Station	2nd Auditorium On Stage By Stair 7	Dual Action	20666038
0382	Pull Station	2nd Auditorium Stage	Dual Action	20666034
0383	Pull Station	2nd Auditorium Stair 8 Storage 225	Dual Action	20666029
0384	Pull Station	2nd By Stair 2	Dual Action	20666091
0385	Pull Station	2nd By Stair 3	Dual Action	20666084
0386	Pull Station	2nd Gym	Dual Action	20666059
0387	Pull Station	2nd Gym	Dual Action	20666060
0388	Pull Station	2nd By Stair 5 Entrance	Dual Action	20666061
0389	Pull Station	2nd Gym	Dual Action	20666058
0390	Pull Station	2nd Gym	Dual Action	20666057
0401	Pull Station	2nd Auditorium Main Entrance	Dual Action	20666041
0402	Pull Station	2nd Auditorium Main Entrance	Dual Action	20666042
0415	Pull Station	3rd By Stair 1	Dual Action	20666151
0416	Pull Station	3rd By Stair 2	Dual Action	20666160
0417	Pull Station	3rd By Stair 4	Dual Action	20666174
0418	Pull Station	3rd By Stair 3	Dual Action	20666167
0419	Pull Station	3rd By Stair 5	Dual Action	20666183
0419	Smoke Detector	3rd Copy Room	Photoelectric	20666184
	Battery	1st Dialer Panel	Sealed Lead Acid	16320785
	Communicator	1st Dialer Panel	Digital Communicator	16320786
	Control Panel	1st Loading Dock		16320787
	Battery	2nd Electrical By Stair 4 Left	Sealed Lead Acid	16320782
	Battery	2nd Electrical By Stair 4 Right	Sealed Lead Acid	16320781
Zone/Circuit: 08				
0615	Battery	1st Lower Cab By Panel Right	Sealed Lead Acid	16320799
Zone/Circuit: 09				
0001	Battery	1st Booster By Panel Left	Sealed Lead Acid	16320798
0001	Battery	1st Booster By Panel Right	Sealed Lead Acid	16320797

0001	Battery	3rd Electrical By Stair 4 Booster 5 (left)	Sealed Lead Acid	20666194
0001	Battery	3rd Electrical By Stair 4 Booster 6 (right)	Sealed Lead Acid	20666195
Zone/Circuit: 10				
0615	Battery	1st Lower Cab By Panel	Sealed Lead Acid	16320783

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Dolan School
51 Toms Road
Stamford, CT 06906

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Feb 14, 2020



Building: Stamford BOE-Dolan School
Contact: Davor Lucaj
Title: Facilities Trades Manager

Company: TPC Associates, Inc.
Contact: Dave Majewski
Title: Inspector

Executive Summary





Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Dolan School		Contact: Davor Lucaj
Address: 51 Toms Road		Phone: 203-977-6668
Address:		Fax:
City/State/Zip: Stamford, CT 06906		Mobile: 347-675-6021
Country: United States of America		Email: dlucaj@stamfordct.gov
Inspection Performed By		
Company: TPC Associates, Inc.		Inspector: Dave Majewski
Address: 261 Pepe's Farm Road		Phone: 203-666-9587
Address:		Fax:
City/State/Zip: Milford, Connecticut 06460		Mobile:
Country: United States of America		Email: dave.majewski@tpcsystems.com
System Control Unit		
Manufacturer: EST	Inspection Date: 02/14/2020	IDC Style:
Model Number: EST3X	Install Date: 07/05/2019	SLC Style:
Software Version:	Version Date: 07/05/2019	NAC Style:
Location: 2nd Lobby MAIN FACP	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg: Notifier	Model #: 911A
Test Time/Date: 2/14/20 8:32:29 AM	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.37%	0	0%	0	0%	0	0%
Control	6	2.20%	6	100.00%	5	83.33%	1	16.67%
Initiating	266	97.44%	266	100.00%	266	100.00%	0	0%
Totals	273	100%	272	99.63%	271	99.63%	1	0.37%
Certification								
Company: TPC Associates, Inc.				Building: Stamford BOE-Dolan School				
Inspector: Dave Majewski				Contact: Davor Lucaj				
								
Signed: Feb 14, 2020 9:43:07 AM				Signed: Feb 14, 2020 9:44:45 AM				

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-Dolan School			Control Panel: 1 - EST EST3X	
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
 ScanID	 Location	 Problem	Address	 Reference
<i>Control</i>				
Battery				
56181909	2nd Lobby Main FACP BATTERY above ceiling	Failed Test	1	NFPA 72 Table 10.4.2.2.5(a-e)

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-Dolan School			Control Panel: 1 - EST EST3X		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
Control					
Battery					
56181909	2nd Lobby Main FACP BATTERY above ceiling	Replace	UB1280	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

Notes & Recommendations

Generated by: BuildingReports.com

Building: Stamford BOE-Dolan School			Control Panel: 1 - EST EST3X	
<i>The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.</i>				
ScanID	Note	Device Type	Location	Comment
<i>Control</i>				
56181909	1	Battery	2nd Lobby Main FACP BATTERY above ceiling	Failed Test
Flat Battery				
2/14/2020				

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Dolan School		Control Panel: 1 - EST EST3X		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Battery	2nd Lobby Main FACP BATTERY	Tested	8:01:46 AM	02/14/2020
Battery	2nd Lobby Main FACP BATTERY above ceiling	Tested	7:45:11 AM	02/14/2020
Battery	2nd Lobby Main FACP BATTERY above ceiling	Tested	7:56:20 AM	02/14/2020
Communicator	2nd 2ND FLR MAIN OFFICE	Tested	8:32:29 AM	02/14/2020
Control Panel	2nd Lobby MAIN FACP	Visually Checked	7:38:55 AM	02/14/2020
Initiating				
Heat Detector	Basement BSMT BOILER RM HEATS 3 above ceiling by boiler room	Tested	9:22:43 AM	02/14/2020
Heat Detector	1st 1ST FLR EAST STORAGE CLOSET BY GYM HEAT	Visually Checked	9:42:27 AM	02/14/2020
Heat Detector	1st 1ST FLR WEST ELECTRICAL RM HEAT	Tested	9:29:42 AM	02/14/2020
Heat Detector	1st 1ST FLR WEST JANITORS CLOSET HEAT	Tested	9:18:18 AM	02/14/2020
Heat Detector	1st 1ST FLR WEST JANITORS CLOSET HEAT	Tested	9:32:01 AM	02/14/2020
Heat Detector	1st 1ST FLR WEST JANITORS CLOSET HEAT	Visually Checked	9:39:08 AM	02/14/2020
Heat Detector	1st 1ST FLR WEST KITCHEN AREA HEAT	Visually Checked	9:41:27 AM	02/14/2020
Heat Detector	1st 1ST FLR WEST KITCHEN AREA HEAT	Visually Checked	9:41:33 AM	02/14/2020
Heat Detector	1st 1ST FLR WEST KITCHEN STORE RM HEAT	Visually Checked	9:39:03 AM	02/14/2020
Heat Detector	1st 1ST FLR WEST MAINTENANCE SHOP HEAT	Visually Checked	9:39:44 AM	02/14/2020
Heat Detector	1st 1ST FLR WEST STOR CLST BY STAIR #2 HEAT	Tested	9:29:22 AM	02/14/2020
Heat Detector	1st BOYS GYM HEATS	Visually Checked	9:40:48 AM	02/14/2020
Heat Detector	1st GIRLS GYM HEAT	Visually Checked	9:42:01 AM	02/14/2020
Heat Detector	1st STAGE WEST STORAGE RM HEAT	Tested	9:35:21 AM	02/14/2020
Heat Detector	2nd 2ND FLR EAST CHASEWAY IN BOYS RM HEAT	Tested	8:11:07 AM	02/14/2020
Heat Detector	2nd 2ND FLR EAST JANITOR CLST @ BOYS RM HEAT	Tested	8:11:00 AM	02/14/2020
Heat Detector	2nd 2ND FLR WEST CHASEWAY IN BOYS RM HEAT	Tested	8:39:11 AM	02/14/2020
Heat Detector	2nd 2ND FLR WEST JANITORS CLOSET HEAT	Tested	8:39:19 AM	02/14/2020
Heat Detector	3rd 3RD FLR EAST CHASEWAY IN BOYS ROOM HEAT	Visually Checked	9:03:45 AM	02/14/2020
Heat Detector	3rd 3RD FLR WEST ALCOVE IN BOYS ROOM HEAT	Tested	8:54:04 AM	02/14/2020
Heat Detector	3rd 3RD FLR WEST CHASEWAY IN BOYS RM HEAT	Visually Checked	9:04:21 AM	02/14/2020
Heat Detector	3rd 3RD FLR WEST CLOSET IN BOYS ROOM HEAT	Visually Checked	9:04:08 AM	02/14/2020
Heat Detector	3rd 3RD FLR WEST ROOM 314 HEAT	Tested	8:53:21 AM	02/14/2020
Heat Detector	3rd 3RD FLR WEST ROOM 316 HEAT	Tested	8:52:45 AM	02/14/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	3rd 3RD FLR WEST ROOM 316 HEAT	Tested	8:52:47 AM	02/14/2020
Heat Detector	Penthouse East EAST PENTHOUSE HEAT	Visually Checked	8:49:12 AM	02/14/2020
Heat Detector	Penthouse West WEST PENTHOUSE HEAT	Tested	8:43:30 AM	02/14/2020
Heat Detector	Penthouse West WEST PENTHOUSE HEAT	Tested	8:43:45 AM	02/14/2020
Heat Detector	Penthouse West WEST PENTHOUSE HEAT	Tested	8:44:13 AM	02/14/2020
Pull Station	Basement BSMT BOILER RM HEATS & PULLS	Visually Checked	9:42:56 AM	02/14/2020
Pull Station	1st 1ST FLR EAST BOYS LOCKER RM PULL	Visually Checked	9:40:35 AM	02/14/2020
Pull Station	1st 1ST FLR EAST ROOM 100 EXIT PULL	Visually Checked	9:39:57 AM	02/14/2020
Pull Station	1st 1ST FLR EAST ROOM 105 PULL	Visually Checked	9:38:46 AM	02/14/2020
Pull Station	1st 1ST FLR EAST STAIR #4 PULL	Visually Checked	9:05:22 AM	02/14/2020
Pull Station	1st 1ST FLR WEST BY STAIR #2 PULL	Visually Checked	9:29:14 AM	02/14/2020
Pull Station	1st 1ST FLR WEST CAFETERIA PULL	Visually Checked	9:38:05 AM	02/14/2020
Pull Station	1st 1ST FLR WEST CAFETERIA PULL	Visually Checked	9:41:50 AM	02/14/2020
Pull Station	1st 1ST FLR WEST CORRIDOR BY STAIR 3 PULL	Visually Checked	9:19:24 AM	02/14/2020
Pull Station	1st 1ST FLR WEST IN STAIR #2 PULL	Visually Checked	9:29:58 AM	02/14/2020
Pull Station	1st 1ST FLR WEST KITCHEN AREA PULL	Visually Checked	9:38:12 AM	02/14/2020
Pull Station	1st 1ST FLR WEST STAIR #1 HALL SIDE PULL	Visually Checked	9:37:29 AM	02/14/2020
Pull Station	1st 1ST FLR WEST STAIR IN STAIR 3 PULL	Visually Checked	9:19:09 AM	02/14/2020
Pull Station	1st AUD EAST DOUBLE DOOR @ STAGE STAIRS PULL	Visually Checked	9:36:33 AM	02/14/2020
Pull Station	1st AUD WEST DOUBLE DOOR AT STAGE PULL	Visually Checked	9:33:26 AM	02/14/2020
Pull Station	1st AUDITORIUM EAST REAR DOUBLE DOOR PULL	Visually Checked	9:33:10 AM	02/14/2020
Pull Station	1st AUDITORIUM FRONT LOBBY PULL	Visually Checked	9:38:23 AM	02/14/2020
Pull Station	1st AUDITORIUM WEST REAR DOUBLE DOOR PULL	Visually Checked	9:34:41 AM	02/14/2020
Pull Station	1st Boys Gym Pull	Visually Checked	9:38:29 AM	02/14/2020
Pull Station	1st Elevator lobby	Visually Checked	9:22:05 AM	02/14/2020
Pull Station	1st Girls Gym Pull	Visually Checked	9:38:51 AM	02/14/2020
Pull Station	1st Girls Locker Room	Visually Checked	9:38:58 AM	02/14/2020
Pull Station	1st Gym Pull Vestibule by girls locker room	Visually Checked	9:13:45 AM	02/14/2020
Pull Station	1st Gym Pull Vestibule by girls locker room	Visually Checked	9:13:56 AM	02/14/2020
Pull Station	1st STAGE DOUBLE DOOR PULL	Visually Checked	9:36:06 AM	02/14/2020
Pull Station	2nd 2ND FL WEST CORRIDOR BY STAIR #1 PULL	Visually Checked	8:39:36 AM	02/14/2020
Pull Station	2nd 2ND FLR EAST CORRIDOR BY STAIR #4 PULL	Visually Checked	8:15:07 AM	02/14/2020
Pull Station	2nd 2ND FLR EAST CORRIDOR STAIR # 3 PULL	Visually Checked	8:08:38 AM	02/14/2020
Pull Station	2nd 2ND FLR MAIN LOBBY LEFT PULL STATION	Visually Checked	8:05:52 AM	02/14/2020
Pull Station	2nd 2ND FLR MAIN LOBBY RIGHT PULL STATION	Tested	7:39:11 AM	02/14/2020
Pull Station	3rd 3RD FLR EAST CORRIDOR BY STAIR # 3 PULL	Visually Checked	8:58:46 AM	02/14/2020
Pull Station	3rd 3RD FLR EAST CORRIDOR BY STAIR # 4 PULL	Visually Checked	9:03:05 AM	02/14/2020
Pull Station	3rd 3RD FLR WEST CORRIDOR BY STAIR # 1 PULL	Visually Checked	8:51:33 AM	02/14/2020
Pull Station	3rd 3RD FLR WEST CORRIDOR BY STAIR # 2 PULL	Visually Checked	8:55:51 AM	02/14/2020
Pull Station	Penthouse East EAST PENTHOUSE PULL STATION	Visually Checked	8:49:17 AM	02/14/2020
Pull Station	Penthouse West WEST PENTHOUSE PULL STATION	Visually Checked	8:49:22 AM	02/14/2020
Smoke Detector	Basement SMOKE DETECTOR BASEMENT ELEV MACHINE RM	Visually Checked	9:23:24 AM	02/14/2020
Smoke Detector	Basement SMOKE DETECTOR BASEMENT	Visually Checked	9:43:00 AM	02/14/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	ELEVATOR LOBBY 1st 1ST FL EAST GIRLS LOCKER RM BATHRM SMOKE	Visually Checked	9:15:24 AM	02/14/2020
Smoke Detector	1st 1ST FL EAST GIRLS LOCKER RM OFFICE SMOKE	Visually Checked	9:14:48 AM	02/14/2020
Smoke Detector	1st 1ST FL EAST GIRLS LOCKER RM SMOKE	Visually Checked	9:40:43 AM	02/14/2020
Smoke Detector	1st 1ST FL EAST GIRLS LOCKER RM STORAGE SMK	Visually Checked	9:39:19 AM	02/14/2020
Smoke Detector	1st 1ST FL EAST WOMENS BATHROOM SMOKE	Visually Checked	9:18:55 AM	02/14/2020
Smoke Detector	1st 1ST FLR E. HEALTH CTR CORR BY BATHRM SMK	Visually Checked	9:39:34 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST BOYS LOCKER RM BATHRM SMOKE	Visually Checked	9:06:58 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST BOYS LOCKER RM BATHRM SMOKE	Visually Checked	9:39:53 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST BOYS LOCKER RM OFFICE SMOKE	Visually Checked	9:12:06 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST BOYS LOCKER RM SMOKE	Visually Checked	9:07:07 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST CORR BY HEALTH CTR SMOKE	Visually Checked	9:40:19 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST CORRIDOR BY GYM SMOKE	Visually Checked	9:39:25 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST CORRIDOR BY GYM SMOKE	Visually Checked	9:40:24 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST CORRIDOR BY RM 104 SMOKE	Visually Checked	9:05:58 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST CORRIDOR BY RM 106 SMOKE	Visually Checked	9:06:38 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST HEALTH CTR BATHROOM SMOKE	Visually Checked	9:09:23 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST HEALTH CTR BATHROOM SMOKE	Visually Checked	9:42:23 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST HEALTH CTR CONF RM SMOKE	Visually Checked	9:09:10 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST HEALTH CTR DENTAL HYG. SMOK	Visually Checked	9:09:59 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST HEALTH CTR SOCIAL WORK SMK	Visually Checked	9:09:32 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST HEALTH CTR WAITING RM SMOKE	Visually Checked	9:09:04 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST NURSE PRACTITIONER SMOKE	Visually Checked	9:09:41 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST NURSES OFFICE SMOKE	Visually Checked	9:09:51 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 100 SMOKE	Visually Checked	9:42:19 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 101 SMOKE	Visually Checked	9:04:33 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 102 SMOKE	Visually Checked	9:04:40 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 102 SMOKE	Visually Checked	9:04:41 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 103 SMOKE	Visually Checked	9:04:23 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 104 SMOKE	Visually Checked	9:05:33 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 104 SMOKE	Visually Checked	9:05:34 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 105 SMOKE	Visually Checked	9:05:48 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 106 SMOKE	Visually Checked	9:42:06 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 107 SMOKE	Visually Checked	9:42:32 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 110A SMOKE	Visually Checked	9:42:44 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 110B SMOKE	Visually Checked	9:42:40 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST RM 110C SMOKE	Visually Checked	9:42:35 AM	02/14/2020
Smoke Detector	1st 1ST FLR EAST STAIR #4 SMOKE	Visually Checked	9:40:28 AM	02/14/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st 1ST FLR GYM CORR TO BOYS LOCKER RM SMOKE	Visually Checked	9:40:53 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST BOOK STORAGE RM SMOKE	Visually Checked	9:26:27 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST BOYS BATHROOM SMOKE	Visually Checked	9:18:27 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST BOYS BATHROOM SMOKE	Visually Checked	9:39:14 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST BY BOYS BATHROOM SMOKE	Visually Checked	9:40:14 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST BY GIRLS BATHROOM SMOKE	Visually Checked	9:39:38 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST BY RM 107 SMOKE	Visually Checked	9:21:10 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CAFETERIA SMOKE	Visually Checked	9:41:09 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CAFETERIA SMOKE	Visually Checked	9:41:16 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CAFETERIA SMOKE	Visually Checked	9:41:22 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CORR BY AUDITORIUM SMOKE	Visually Checked	9:32:52 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CORR BY SPRINKLER RM SMOKE	Visually Checked	9:27:47 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CORRIDOR BY BOILER RM SMOKE	Visually Checked	9:22:33 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CORRIDOR BY CAFETERIA SMOKE	Visually Checked	9:41:05 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CORRIDOR BY CUSTODIAN SMOKE	Visually Checked	9:30:38 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CORRIDOR BY ELECTRIC RM SMK	Visually Checked	9:29:06 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CORRIDOR BY RM 110 SMOKE	Visually Checked	9:32:36 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CORRIDOR BY STAIR #3 SMOKE	Visually Checked	9:19:07 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST CUSTODIANS OFFICE SMOKE	Visually Checked	9:30:43 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST GIRLS BATHROOM SMOKE	Visually Checked	9:39:49 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST GUIDANCE OFFICE A SMOKE	Visually Checked	9:20:25 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST GUIDANCE OFFICE B SMOKE	Visually Checked	9:20:35 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST GUIDANCE OFFICE C SMOKE	Visually Checked	9:20:42 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST GUIDANCE OFFICE D SMOKE	Visually Checked	9:39:29 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST GUIDANCE OFFICE SMOKE	Visually Checked	9:19:56 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST RM 109 SMOKE	Visually Checked	9:30:26 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST RM 109 SMOKE	Visually Checked	9:30:28 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST RM 110 SMOKE	Visually Checked	9:41:00 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST SPRINKLER RM SMOKE	Visually Checked	9:27:34 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST STAIR #1 SMOKE	Visually Checked	9:37:25 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST STAIR #2 SMOKE	Visually Checked	9:30:06 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST STAIR #3 SMOKE	Visually Checked	9:19:14 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST STRING RM SMOKE	Visually Checked	9:41:46 AM	02/14/2020
Smoke Detector	1st 1ST FLR WEST TEACHERS LOUNGE SMOKE	Visually Checked	9:41:40 AM	02/14/2020
Smoke Detector	1st SMOKE DETECTOR 1ST FLOOR ELEVATOR LOBBY	Visually Checked	9:21:52 AM	02/14/2020
Smoke Detector	1st STAGE LADDER SIDE SMOKE	Visually Checked	9:40:02 AM	02/14/2020
Smoke Detector	1st STAGE SCHOOL SIDE SMOKE	Visually Checked	9:40:08 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ALCOVE IN BOYS ROOM SMOKE	Visually Checked	8:10:31 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST BOYS ROOM SMOKE	Visually Checked	8:10:38 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST CONFERENCE ROOM SMOKE	Visually Checked	8:08:51 AM	02/14/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd 2ND FLR EAST CORR BY ELEV DOORS SMOKE	Visually Checked	8:08:01 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY GIRLS RM SMOKE	Visually Checked	8:09:37 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY ROOM 203 SMOKE	Visually Checked	8:14:51 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY ROOM 204 SMOKE	Visually Checked	8:11:24 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY ROOM 205 SMOKE	Visually Checked	8:13:41 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY ROOM 206 SMOKE	Visually Checked	8:10:11 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY ROOM 209 SMOKE	Visually Checked	8:08:20 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST GIRLS ROOM SMOKE	Visually Checked	8:50:45 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 200 SMOKE	Visually Checked	8:17:22 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 200-A SMOKE	Visually Checked	8:49:56 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 200-B SMOKE	Visually Checked	8:17:03 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 200-C SMOKE	Visually Checked	8:16:21 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 200-C SMOKE	Visually Checked	8:50:11 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 200-D SMOKE	Visually Checked	8:16:04 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 200-D SMOKE	Visually Checked	8:16:07 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 200-E SMOKE	Visually Checked	8:16:14 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 201 SMOKE	Visually Checked	8:16:28 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 202 BATHROOM SMOKE	Visually Checked	8:50:31 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 202 SMOKE	Visually Checked	8:15:14 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 203 SMOKE	Visually Checked	8:14:27 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 203 SMOKE	Visually Checked	8:50:16 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 204 SMOKE	Visually Checked	8:11:39 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 204-A SMOKE	Visually Checked	8:14:43 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 205 SMOKE	Visually Checked	8:13:59 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 205 SMOKE	Visually Checked	8:14:00 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 206 SMOKE	Visually Checked	8:09:48 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 207 SMOKE	Visually Checked	8:09:11 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 208 SMOKE	Visually Checked	8:09:21 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST ROOM 209 SMOKE	Visually Checked	8:07:39 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST STAIR #3 SMOKE	Visually Checked	8:08:27 AM	02/14/2020
Smoke Detector	2nd 2ND FLR EAST STAIR #4 SMOKE	Visually Checked	8:15:02 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN LOBBY SMOKE BY CORRIDOR	Visually Checked	8:50:06 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN LOBBY SMOKE BY ENTRANCE	Visually Checked	8:05:38 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN OFF ALCOVE BY PRINC SMOKE	Visually Checked	8:33:07 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN OFFICE BATHROOM SMOKE	Visually Checked	8:31:57 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN OFFICE COPY ROOM SMOKE	Visually Checked	8:31:50 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN OFFICE M02 SMOKE	Visually Checked	8:32:35 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN OFFICE M03 CLOSET SMOKE	Visually Checked	8:31:30 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN OFFICE M03 SMOKE	Visually Checked	8:31:10 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN OFFICE MAILBOX AREA SMOKE	Visually Checked	8:31:45 AM	02/14/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd 2ND FLR MAIN OFFICE MIDDLE SMOKE	Visually Checked	8:30:42 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN OFFICE PRINCIPAL BATH SMOKE	Visually Checked	8:33:15 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN OFFICE PRINCIPALS SMOKE	Visually Checked	8:49:45 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN OFFICE SUPPLY CLOSET SMOKE	Visually Checked	8:30:55 AM	02/14/2020
Smoke Detector	2nd 2ND FLR MAIN OFFICE VAULT SMOKE	Visually Checked	8:51:04 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST BOYS BATHROOM ALCOVE SMOKE	Visually Checked	8:38:31 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST BOYS BATHROOM SMOKE	Visually Checked	8:50:59 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST CLST BETWEEN 215 & 216 SMK	Visually Checked	8:40:36 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST CONFERENCE RM 211A SMOKE	Visually Checked	8:33:30 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST CORRIDOR BY RM 210 SMOKE	Visually Checked	8:50:25 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST CORRIDOR BY RM 212 SMOKE	Visually Checked	8:37:15 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST CORRIDOR BY RM 213 SMOKE	Visually Checked	8:38:13 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST CORRIDOR BY RM 214 SMOKE	Visually Checked	8:40:30 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST CORRIDOR BY STAIR #1 SMOKE	Visually Checked	8:39:30 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST GIRLS BATHROOM SMOKE	Visually Checked	8:50:53 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST RM 211 SMOKE	Visually Checked	8:36:59 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST RM 212 SMOKE	Visually Checked	8:37:29 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST RM 213 SMOKE	Visually Checked	8:37:47 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST RM 214 SMOKE	Visually Checked	8:40:25 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST RM 215 SMOKE	Visually Checked	8:40:07 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST RM 216 SMOKE	Visually Checked	8:40:44 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST RM 216 SMOKE	Visually Checked	8:40:46 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST RM 217 SMOKE	Visually Checked	8:41:12 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST RM 217 SMOKE	Visually Checked	8:41:14 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST ROOM 210 SMOKE	Visually Checked	8:35:41 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST STAIR #1 SMOKE	Visually Checked	8:39:49 AM	02/14/2020
Smoke Detector	2nd 2ND FLR WEST STAIR #2 SMOKE	Visually Checked	8:36:24 AM	02/14/2020
Smoke Detector	2nd SMOKE DETECTOR 2ND FLOOR ELEVATOR LOBBY	Visually Checked	8:08:07 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ALCOVE IN BOYS ROOM SMOKE	Visually Checked	9:01:32 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST BOYS BATH ROOM SMOKE	Visually Checked	9:01:35 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST CLOSET IN BOYS ROOM HEAT	Visually Checked	9:04:12 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST CORRIDOR BY ELEV DOOR SMOKE	Visually Checked	9:03:54 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST CORRIDOR BY RM 304 SMOKE	Visually Checked	9:00:13 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST CORRIDOR BY RM 307 SMOKE	Visually Checked	8:59:37 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST CORRIDOR BY RM 308	Visually Checked	8:58:13 AM	02/14/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	SMOKE 3rd 3RD FLR EAST CORRIDOR BY ROOM 302	Visually Checked	9:02:13 AM	02/14/2020
Smoke Detector	SMOKE 3rd 3RD FLR EAST CORRIDOR BY STAIR #4	Visually Checked	9:04:16 AM	02/14/2020
Smoke Detector	SMOKE 3rd 3RD FLR EAST CORRIDOR MEDIA CENTER	Visually Checked	8:57:47 AM	02/14/2020
Smoke Detector	SMOKE 3rd 3RD FLR EAST CORRIDOR ROOM 302	Visually Checked	9:02:44 AM	02/14/2020
Smoke Detector	SMOKE 3rd 3RD FLR EAST GIRLS BATHROOM SMOKE	Visually Checked	8:59:33 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST MEDIA CENTER SMOKE	Visually Checked	8:57:06 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST MEDIA CENTER SMOKE	Visually Checked	8:57:07 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST MEDIA CENTER SMOKE	Visually Checked	8:57:16 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST RM 305 SMOKE	Visually Checked	8:59:57 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST RM 306 SMOKE	Visually Checked	8:59:13 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST RM 307 SMOKE	Visually Checked	8:59:24 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 300 SMOKE	Visually Checked	9:02:59 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 300 SMOKE	Visually Checked	9:03:00 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 301 SMOKE	Visually Checked	9:02:37 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 301 SMOKE	Visually Checked	9:03:41 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 302 SMOKE	Visually Checked	9:02:28 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 303 SMOKE	Visually Checked	9:01:19 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 303 SMOKE	Visually Checked	9:01:20 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 303-304 CLOSET SMOKE	Visually Checked	9:01:01 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 303-304 CLOSET SMOKE	Visually Checked	9:03:49 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 304 SMOKE	Visually Checked	9:00:19 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 308 SMOKE	Visually Checked	9:04:00 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST ROOM 309 SMOKE	Visually Checked	8:57:37 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST STAIR #3 SMOKE	Visually Checked	8:58:52 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST STAIR #4 SMOKE	Visually Checked	9:03:10 AM	02/14/2020
Smoke Detector	3rd 3RD FLR EAST VICE PRINCIPALS SMOKE	Visually Checked	8:59:01 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST BOYS ROOM SMOKE	Visually Checked	8:54:08 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY BOYS RM SMOKE	Visually Checked	8:54:28 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY GIRLS RM SMOKE	Visually Checked	8:55:15 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY RM 311 SMOKE	Visually Checked	8:56:16 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY RM 313 SMOKE	Visually Checked	8:53:51 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY RM 316 SMOKE	Visually Checked	8:52:14 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY STAIR #1 SMOKE	Visually Checked	8:51:32 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST GIRLS RM SMOKE	Visually Checked	8:55:34 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST MEDIA CENTER OFFICE SMOKE	Visually Checked	8:56:33 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST ROOM 310 SMOKE	Visually Checked	8:56:21 AM	02/14/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	3rd 3RD FLR WEST ROOM 311 SMOKE	Visually Checked	8:55:22 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST ROOM 312 SMOKE	Visually Checked	8:55:10 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST ROOM 313 SMOKE	Visually Checked	8:54:19 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST ROOM 315 SMOKE	Visually Checked	9:04:04 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST ROOM 317 CLOSET SMOKE	Visually Checked	8:52:31 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST ROOM 317 SMOKE	Visually Checked	8:52:26 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST STAIR # 1 SMOKE	Visually Checked	8:42:09 AM	02/14/2020
Smoke Detector	3rd 3RD FLR WEST STAIR #2 SMOKE	Visually Checked	8:56:11 AM	02/14/2020
Smoke Detector	3rd SMOKE DETECTOR 3RD FLOOR ELEVATOR LOBBY	Visually Checked	8:58:31 AM	02/14/2020
Smoke Detector	4th SMOKE DETECTOR 4TH FLOOR ELEVATOR LOBBY	Visually Checked	8:49:38 AM	02/14/2020
Smoke Detector	Penthouse West WEST PENTHOUSE STAIR #1 SMOKE	Visually Checked	8:42:56 AM	02/14/2020
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	2nd Lobby Main FACP BATTERY above ceiling	Tested	7:53:48 AM	02/14/2020

Service Summary

Generated by: BuildingReports.com

Building: Stamford BOE-Dolan School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	1
Total		1
<i>Passed</i>		
Battery	Tested	3
Communicator	Tested	1
Control Panel	Visually Checked	1
Heat Detector	Tested	17
Heat Detector	Visually Checked	12
Pull Station	Tested	1
Pull Station	Visually Checked	35
Smoke Detector	Visually Checked	201
Total		271
Grand Total		272






Auxiliary Functions Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Dolan School			Control Panel: 1 - EST EST3X	
<i>The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.</i>				
Type	Location	Comment	ScanID	Simulated
<i>Passed</i>				
Smoke Detector				
pop hatch	1st STAGE LADDER SIDE SMOKE	Passed	56180437	
pop hatch	1st STAGE SCHOOL SIDE SMOKE	Passed	56180438	

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Dolan School							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		 dB	 dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
					<input type="checkbox"/>	0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Dolan School				Control Panel: 1 - EST EST3X			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<i>Passed</i>							
Battery							
Sealed Lead Acid	2nd Lobby Main FACP BATTERY	18ah	12v	12.93V	17Ah		
Sealed Lead Acid	2nd Lobby Main FACP BATTERY	8ah	12v	12.62V	6.8Ah		
	above ceiling						
Sealed Lead Acid	2nd Lobby Main FACP BATTERY	8ah	12v	12.63V	6.2AH		
	above ceiling						
<i>Failed/Other</i>							
Battery							
Sealed Lead Acid	2nd Lobby Main FACP BATTERY	8ah	12v	flat	flat		
	above ceiling						

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Dolan School				Control Panel: 1 - EST EST3X	
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		0.37%	1
Control Panel		Control		0.37%	1
Pull Station		Initiating		13.19%	36
Battery		Control		1.47%	4
Smoke Detector		Initiating		73.63%	201
Heat Detector		Initiating		10.62%	29
Communicator		Control		0.37%	1
Type	Qty	Model #	Description		Install Date
In Service - 90 Days - 1 Year					
EST					
Control Panel	1	EST3X			07/05/2019
Heat Detector	2	284B-PL	Fixed Temperature		07/05/2019
Heat Detector	1	CT1			07/05/2019
Heat Detector	26	HFS			07/05/2019
Pull Station	2	270			07/05/2019
Pull Station	34	278			07/05/2019
Smoke Detector	1	56180506			07/05/2019
Smoke Detector	20	PS			07/05/2019
	0				
Notifier					
Communicator	1	911A			07/05/2019
Universal					
Battery	1	UB1280	Sealed Lead Acid		07/05/2019
In Service - 2 Years to 3 Years					
UB12180					
Battery	1		Sealed Lead Acid		09/01/2017
Universal					
Battery	2	UB1280	Sealed Lead Acid		09/01/2017

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Dolan School			Control Panel: 1 - EST EST3X	
<i>The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.</i>				
Address	Device Type	Location	Type	ScanID
Zone/Circuit: 03				
0003	Smoke Detector	4th SMOKE DETECTOR 4TH FLOOR ELEVATOR LOBBY		3981403631
0004	Smoke Detector	Basement SMOKE DETECTOR BASEMENT ELEV MACHINE RM		56180522
0006	Smoke Detector	Basement SMOKE DETECTOR BASEMENT ELEVATOR LOBBY		56180521
0007	Smoke Detector	1st SMOKE DETECTOR 1ST FLOOR ELEVATOR LOBBY		56181903
0008	Smoke Detector	2nd SMOKE DETECTOR 2ND FLOOR ELEVATOR LOBBY		56181857
0009	Smoke Detector	3rd SMOKE DETECTOR 3RD FLOOR ELEVATOR LOBBY		56180505
0010	Heat Detector	2nd 2ND FLR WEST CHASEWAY IN BOYS RM HEAT		56181869
0011	Heat Detector	2nd 2ND FLR WEST JANITORS CLOSET HEAT		56181861
0012	Heat Detector	1st 1ST FLR WEST ELECTRICAL RM HEAT		20666677
0013	Heat Detector	1st 1ST FLR WEST STOR CLST BY STAIR #2 HEAT		20666676
0014	Heat Detector	1st 1ST FLR WEST MAINTENANCE SHOP HEAT		3943356005
0015	Heat Detector	1st 1ST FLR WEST KITCHEN AREA HEAT		56181788
0016	Heat Detector	1st 1ST FLR WEST KITCHEN STORE RM HEAT		20666687
0017	Heat Detector	1st 1ST FLR WEST JANITORS CLOSET HEAT		3682728231
0018	Heat Detector	1st 1ST FLR WEST JANITORS CLOSET HEAT		20666678
0019	Heat Detector	1st 1ST FLR WEST KITCHEN AREA HEAT		56181787
0020	Heat Detector	1st 1ST FLR WEST JANITORS CLOSET HEAT		56181902
0021	Heat Detector	1st STAGE WEST STORAGE RM HEAT		56180436
0022	Heat Detector	1st 1ST FLR EAST STORAGE CLOSET BY GYM HEAT		56181899
0023	Smoke Detector	2nd 2ND FLR WEST ROOM 210 SMOKE		56180469
0024	Smoke Detector	2nd 2ND FLR WEST CONFERENCE RM 211A SMOKE		56181870
0025	Smoke Detector	2nd 2ND FLR WEST CORRIDOR BY RM 210 SMOKE		56180470
0026	Smoke Detector	2nd 2ND FLR WEST STAIR #2 SMOKE		56180468

0027	Smoke Detector	2nd 2ND FLR WEST RM 211 SMOKE	56181858
0028	Smoke Detector	2nd 2ND FLR WEST RM 212 SMOKE	56180467
0029	Smoke Detector	2nd 2ND FLR WEST GIRLS BATHROOM SMOKE	56181859
0030	Smoke Detector	2nd 2ND FLR WEST RM 213 SMOKE	56180465
0031	Smoke Detector	2nd 2ND FLR WEST CORRIDOR BY RM 212 SMOKE	56180466
0032	Smoke Detector	2nd 2ND FLR WEST CORRIDOR BY RM 213 SMOKE	56180464
0033	Smoke Detector	2nd 2ND FLR WEST BOYS BATHROOM SMOKE	56181860
0034	Smoke Detector	2nd 2ND FLR WEST BOYS BATHROOM ALCOVE SMOKE	56180463
0035	Smoke Detector	2nd 2ND FLR WEST CORRIDOR BY STAIR #1 SMOKE	56180462
0036	Smoke Detector	2nd 2ND FLR WEST STAIR #1 SMOKE	56181862
0037	Smoke Detector	2nd 2ND FLR WEST CORRIDOR BY RM 214 SMOKE	56180460
0038	Smoke Detector	2nd 2ND FLR WEST RM 215 SMOKE	56181863
0039	Smoke Detector	2nd 2ND FLR WEST CLST BETWEEN 215 & 216 SMK	56181864
0040	Smoke Detector	2nd 2ND FLR WEST RM 214 SMOKE	56180461
0041	Smoke Detector	2nd 2ND FLR WEST RM 216 SMOKE	56181865
0042	Smoke Detector	2nd 2ND FLR WEST RM 216 SMOKE	56181866
0043	Smoke Detector	2nd 2ND FLR WEST RM 217 SMOKE	56181867
0044	Smoke Detector	2nd 2ND FLR WEST RM 217 SMOKE	56181868
0045	Smoke Detector	1st 1ST FLR GYM CORR TO BOYS LOCKER RM SMOKE	56180530
0046	Smoke Detector	1st 1ST FLR EAST BOYS LOCKER RM SMOKE	56180525
0047	Smoke Detector	1st 1ST FLR EAST BOYS LOCKER RM BATHRM SMOKE	3943356302
0047	Smoke Detector	1st 1ST FLR EAST BOYS LOCKER RM BATHRM SMOKE	56181794
0048	Smoke Detector	1st 1ST FLR EAST BOYS LOCKER RM OFFICE SMOKE	56180531
0049	Smoke Detector	1st 1ST FLR WEST SPRINKLER RM SMOKE	20666675
0050	Smoke Detector	1st 1ST FLR WEST BOOK STORAGE RM SMOKE	20666674
0051	Smoke Detector	1st 1ST FLR WEST GUIDANCE OFFICE SMOKE	56180444
0052	Smoke Detector	1st 1ST FLR WEST GUIDANCE OFFICE A SMOKE	56180440
0053	Smoke Detector	1st 1ST FLR WEST GUIDANCE OFFICE B SMOKE	56180442
0054	Smoke Detector	1st 1ST FLR WEST GUIDANCE OFFICE C SMOKE	56180441
0055	Smoke Detector	1st 1ST FLR WEST GUIDANCE OFFICE D SMOKE	3937323945
0056	Smoke Detector	1st 1ST FLR WEST RM 109 SMOKE	51385728
0057	Smoke Detector	1st 1ST FLR WEST RM 109 SMOKE	56180543
0058	Smoke Detector	1st 1ST FLR WEST CORR BY SPRINKLER RM SMOKE	56180540

0059	Smoke Detector	1st 1ST FLR WEST RM 110 SMOKE	56180548
0060	Smoke Detector	1st 1ST FLR WEST BOYS BATHROOM SMOKE	3937323846
0061	Smoke Detector	1st 1ST FLR WEST GIRLS BATHROOM SMOKE	3943356098
0062	Smoke Detector	1st 1ST FLR WEST CUSTODIANS OFFICE SMOKE	56180545
0063	Smoke Detector	1st 1ST FLR WEST STAIR #2 SMOKE	56180542
0064	Smoke Detector	1st 1ST FLR WEST CORR BY AUDITORIUM SMOKE	04060108
0065	Smoke Detector	1st 1ST FLR WEST STAIR #1 SMOKE	56180546
0066	Smoke Detector	1st 1ST FLR WEST CAFETERIA SMOKE	56181786
0067	Smoke Detector	1st 1ST FLR WEST CAFETERIA SMOKE	56181785
0068	Smoke Detector	1st 1ST FLR WEST CAFETERIA SMOKE	56181784
0069	Smoke Detector	1st 1ST FLR WEST STRING RM SMOKE	56181790
0070	Smoke Detector	1st 1ST FLR WEST TEACHERS LOUNGE SMOKE	56181789
0071	Smoke Detector	1st 1ST FLR WEST BY BOYS BATHROOM SMOKE	56180453
0072	Smoke Detector	1st 1ST FLR WEST BOYS BATHROOM SMOKE	56181900
0073	Smoke Detector	1st 1ST FLR WEST BY GIRLS BATHROOM SMOKE	3943355848
0074	Smoke Detector	1st 1ST FLR WEST CORRIDOR BY STAIR #3 SMOKE	56180535
0075	Smoke Detector	1st 1ST FLR WEST BY RM 107 SMOKE	56180538
0076	Smoke Detector	1st 1ST FLR WEST STAIR #3 SMOKE	56180534
0077	Smoke Detector	1st 1ST FLR WEST CORRIDOR BY BOILER RM SMOKE	56180539
0078	Smoke Detector	1st 1ST FLR WEST CORRIDOR BY ELECTRIC RM SMK	56180541
0079	Smoke Detector	1st 1ST FLR WEST CORRIDOR BY CUSTODIAN SMOKE	56180547
0080	Smoke Detector	1st 1ST FLR WEST CORRIDOR BY RM 110 SMOKE	56180550
0081	Smoke Detector	1st 1ST FLR WEST CORRIDOR BY CAFETERIA SMOKE	56180551
0082	Smoke Detector	1st 1ST FLR EAST CORRIDOR BY RM 106 SMOKE	56181888
0083	Smoke Detector	1st 1ST FLR EAST HEALTH CTR CONF RM SMOKE	56181890
0084	Smoke Detector	1st 1ST FLR EAST HEALTH CTR WAITING RM SMOKE	56181891
0085	Smoke Detector	1st 1ST FLR EAST HEALTH CTR SOCIAL WORK SMK	56181898
0086	Smoke Detector	1st 1ST FLR EAST CORR BY HEALTH CTR SMOKE	56180454
0087	Smoke Detector	1st 1ST FLR EAST NURSE PRACTITIONER SMOKE	56181897
0088	Smoke Detector	1st 1ST FLR EAST HEALTH CTR BATHROOM SMOKE	56181896
0089	Smoke Detector	1st 1ST FLR EAST NURSES OFFICE SMOKE	56181893
0090	Smoke Detector	1st 1ST FLR EAST HEALTH CTR	56181894

		BATHROOM SMOKE	
0091	Smoke Detector	1st 1ST FLR EAST HEALTH CTR DENTAL HYG. SMOK	56181895
0092	Smoke Detector	1st 1ST FLR EAST CORRIDOR BY GYM SMOKE	3943328972
0092	Smoke Detector	1st 1ST FLR EAST CORRIDOR BY GYM SMOKE	56180455
0093	Smoke Detector	1st 1ST FLR E. HEALTH CTR CORR BY BATHRM SMK	3943355749
0094	Smoke Detector	1st 1ST FLR EAST RM 100 SMOKE	56181883
0095	Smoke Detector	1st 1ST FLR EAST RM 103 SMOKE	56181884
0096	Smoke Detector	1st 1ST FLR EAST RM 101 SMOKE	56181882
0097	Smoke Detector	1st 1ST FLR EAST RM 102 SMOKE	56180458
0098	Smoke Detector	1st 1ST FLR EAST RM 102 SMOKE	56180459
0099	Smoke Detector	1st 1ST FLR EAST RM 104 SMOKE	56181885
0100	Smoke Detector	1st 1ST FLR EAST RM 105 SMOKE	56180457
0101	Smoke Detector	1st 1ST FLR EAST RM 104 SMOKE	56181886
0102	Smoke Detector	1st 1ST FLR EAST CORRIDOR BY RM 104 SMOKE	56181887
0103	Smoke Detector	1st 1ST FLR EAST RM 106 SMOKE	56181889
0104	Smoke Detector	1st 1ST FLR EAST STAIR #4 SMOKE	56180456
0105	Smoke Detector	1st STAGE LADDER SIDE SMOKE	56180437
0106	Smoke Detector	1st STAGE SCHOOL SIDE SMOKE	56180438
0107	Smoke Detector	1st 1ST FL EAST GIRLS LOCKER RM OFFICE SMOKE	56181793
0108	Smoke Detector	1st 1ST FL EAST GIRLS LOCKER RM SMOKE	56180528
0109	Smoke Detector	1st 1ST FL EAST GIRLS LOCKER RM BATHRM SMOKE	56180527
0110	Smoke Detector	1st 1ST FL EAST GIRLS LOCKER RM STORAGE SMK	3937323907
0111	Smoke Detector	1st 1ST FL EAST WOMENS BATHROOM SMOKE	56180532
0112	Smoke Detector	1st 1ST FLR EAST RM 107 SMOKE	56181904
0113	Smoke Detector	1st 1ST FLR EAST RM 110C SMOKE	56181905
0114	Smoke Detector	1st 1ST FLR EAST RM 110B SMOKE	56181906
0115	Smoke Detector	1st 1ST FLR EAST RM 110A SMOKE	56181907
0148	Pull Station	2nd 2ND FL WEST CORRIDOR BY STAIR #1 PULL	04060079
0149	Pull Station	1st 1ST FLR EAST BOYS LOCKER RM PULL	56180524
0150	Pull Station	Basement BSMT BOILER RM HEATS & PULLS	20666673
0150	Heat Detector	Basement BSMT BOILER RM HEATS 3 above ceiling by boiler room	56181795
0151	Heat Detector	1st GIRLS GYM HEAT	Fixed Temperature 56181792
0151	Pull Station	1st Girls Gym Pull	20666657
0151	Pull Station	1st Gym Pull Vestibule by girls locker room	20666658
0151	Pull Station	1st Gym Pull Vestibule by girls locker room	20666659
0152	Heat Detector	1st BOYS GYM HEATS	Fixed Temperature 56180529
0152	Pull Station	1st Boys Gym Pull	04060137
0153	Pull Station	1st 1ST FLR WEST KITCHEN AREA PULL	04060099

0154	Pull Station	1st 1ST FLR WEST IN STAIR #2 PULL	04060164
0156	Pull Station	1st 1ST FLR WEST BY STAIR #2 PULL	56180452
0157	Pull Station	1st 1ST FLR WEST STAIR #1 HALL SIDE PULL	04060086
0159	Pull Station	1st 1ST FLR WEST CAFETERIA PULL	56181791
0160	Pull Station	1st 1ST FLR WEST CAFETERIA PULL	04060094
0161	Pull Station	1st 1ST FLR WEST STAIR IN STAIR 3 PULL	56180536
0162	Pull Station	1st 1ST FLR WEST CORRIDOR BY STAIR 3 PULL	04060162
0163	Pull Station	1st STAGE DOUBLE DOOR PULL	56180445
0164	Pull Station	1st AUD EAST DOUBLE DOOR @ STAGE STAIRS PULL	56180446
0165	Pull Station	1st AUD WEST DOUBLE DOOR AT STAGE PULL	56180448
0166	Pull Station	1st AUDITORIUM WEST REAR DOUBLE DOOR PULL	56180447
0167	Pull Station	1st AUDITORIUM FRONT LOBBY PULL	04060106
0168	Pull Station	1st AUDITORIUM EAST REAR DOUBLE DOOR PULL	56180449
0169	Pull Station	1st 1ST FLR EAST ROOM 100 EXIT PULL	51385730
0170	Pull Station	1st 1ST FLR EAST ROOM 105 PULL	04060159
0171	Pull Station	1st 1ST FLR EAST STAIR #4 PULL	51385729
0251	Smoke Detector	2nd 2ND FLR MAIN LOBBY SMOKE BY CORRIDOR	3943392867
0252	Smoke Detector	2nd 2ND FLR MAIN LOBBY SMOKE BY ENTRANCE	56180473
0253	Smoke Detector	2nd 2ND FLR MAIN OFFICE SUPPLY CLOSET SMOKE	20666647
0254	Smoke Detector	2nd 2ND FLR MAIN OFFICE M03 SMOKE	56181873
0255	Smoke Detector	2nd 2ND FLR MAIN OFFICE M03 CLOSET SMOKE	56181874
0256	Smoke Detector	2nd 2ND FLR MAIN OFFICE MAILBOX AREA SMOKE	56181877
0257	Smoke Detector	2nd 2ND FLR MAIN OFFICE COPY ROOM SMOKE	56181875
0258	Smoke Detector	2nd 2ND FLR MAIN OFFICE BATHROOM SMOKE	56181876
0259	Smoke Detector	2nd 2ND FLR MAIN OFFICE MIDDLE SMOKE	56181872
0260	Smoke Detector	2nd 2ND FLR MAIN OFFICE VAULT SMOKE	56181881
0261	Smoke Detector	2nd 2ND FLR MAIN OFFICE M02 SMOKE	56181878
0262	Smoke Detector	2nd 2ND FLR MAIN OFFICE PRINCIPALS SMOKE	3937323709
0263	Smoke Detector	2nd 2ND FLR MAIN OFFICE PRINCIPAL BATH SMOKE	56181880
0264	Smoke Detector	2nd 2ND FLR MAIN OFF ALCOVE BY PRINC SMOKE	56181879
0265	Smoke Detector	2nd 2ND FLR EAST ROOM 209 SMOKE	56180475
0266	Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY ROOM 209 SMOKE	56180476
0267	Smoke Detector	2nd 2ND FLR EAST CORR BY ELEV DOORS SMOKE	56181856

0268	Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY ROOM 204 SMOKE	56180481
0269	Smoke Detector	2nd 2ND FLR EAST BOYS ROOM SMOKE	56181852
0270	Heat Detector	2nd 2ND FLR EAST CHASEWAY IN BOYS RM HEAT	56181851
0271	Smoke Detector	2nd 2ND FLR EAST ALCOVE IN BOYS ROOM SMOKE	56181849
0272	Heat Detector	2nd 2ND FLR EAST JANITOR CLST @ BOYS RM HEAT	56181850
0273	Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY ROOM 206 SMOKE	56180480
0274	Smoke Detector	2nd 2ND FLR EAST ROOM 207 SMOKE	56180486
0275	Smoke Detector	2nd 2ND FLR EAST ROOM 206 SMOKE	56180487
0276	Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY GIRLS RM SMOKE	56180479
0277	Smoke Detector	2nd 2ND FLR EAST GIRLS ROOM SMOKE	56181853
0278	Smoke Detector	2nd 2ND FLR EAST ROOM 208 SMOKE	56180478
0279	Smoke Detector	2nd 2ND FLR EAST CONFERENCE ROOM SMOKE	56181855
0280	Smoke Detector	2nd 2ND FLR EAST STAIR #3 SMOKE	56180477
0281	Smoke Detector	2nd 2ND FLR EAST ROOM 200-D SMOKE	56180507
0282	Smoke Detector	2nd 2ND FLR EAST ROOM 200-D SMOKE	51385726
0283	Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY ROOM 203 SMOKE	56180484
0284	Smoke Detector	2nd 2ND FLR EAST ROOM 202 SMOKE	56180485
0285	Smoke Detector	2nd 2ND FLR EAST ROOM 202 BATHROOM SMOKE	56181841
0286	Smoke Detector	2nd 2ND FLR EAST ROOM 203 SMOKE	3943393079
0287	Smoke Detector	2nd 2ND FLR EAST STAIR #4 SMOKE	56180491
0288	Smoke Detector	2nd 2ND FLR EAST ROOM 203 SMOKE	56181846
0289	Smoke Detector	2nd 2ND FLR EAST ROOM 204-A SMOKE	56180489
0290	Smoke Detector	2nd 2ND FLR EAST ROOM 205 SMOKE	56181847
0291	Smoke Detector	2nd 2ND FLR EAST ROOM 205 SMOKE	56181848
0292	Smoke Detector	2nd 2ND FLR EAST CORRIDOR BY ROOM 205 SMOKE	56180483
0293	Smoke Detector	2nd 2ND FLR EAST ROOM 204 SMOKE	56180488
0294	Smoke Detector	2nd 2ND FLR EAST ROOM 200 SMOKE	56181842
0295	Smoke Detector	2nd 2ND FLR EAST ROOM 200-C SMOKE	3943392959
0296	Smoke Detector	2nd 2ND FLR EAST ROOM 200-C SMOKE	56180503
0297	Smoke Detector	2nd 2ND FLR EAST ROOM 201 SMOKE	51385727
0298	Smoke Detector	2nd 2ND FLR EAST ROOM 200-E SMOKE	56180508
0299	Smoke Detector	2nd 2ND FLR EAST ROOM 200-B SMOKE	56181843
0300	Smoke Detector	2nd 2ND FLR EAST ROOM 200-A SMOKE	3943392591
0301	Smoke Detector	3rd 3RD FLR WEST BOYS ROOM SMOKE	56181808
0302	Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY RM 311 SMOKE	56181811
0303	Heat Detector	3rd 3RD FLR WEST ALCOVE IN BOYS ROOM HEAT	56181806
0304	Heat Detector	3rd 3RD FLR WEST CLOSET IN BOYS ROOM HEAT	56181807
0305	Heat Detector	3rd 3RD FLR WEST CHASEWAY IN BOYS RM HEAT	56181838
0306	Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY RM 316	56181800

		SMOKE	
0307	Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY STAIR #1 SMOKE	56181802
0308	Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY RM 313 SMOKE	56181805
0309	Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY BOYS RM SMOKE	56181809
0310	Smoke Detector	3rd 3RD FLR WEST CORRIDOR BY GIRLS RM SMOKE	56181810
0311	Smoke Detector	3rd 3RD FLR WEST GIRLS RM SMOKE	56181839
0312	Smoke Detector	3rd 3RD FLR WEST ROOM 311 SMOKE	56180512
0313	Smoke Detector	3rd 3RD FLR WEST MEDIA CENTER OFFICE SMOKE	56180511
0314	Smoke Detector	3rd 3RD FLR WEST ROOM 310 SMOKE	56180509
0315	Smoke Detector	3rd 3RD FLR WEST STAIR #2 SMOKE	56180495
0316	Smoke Detector	3rd 3RD FLR WEST ROOM 312 SMOKE	56180513
0317	Smoke Detector	3rd 3RD FLR WEST ROOM 313 SMOKE	56180514
0318	Heat Detector	3rd 3RD FLR WEST ROOM 314 HEAT	56180515
0319	Heat Detector	3rd 3RD FLR WEST ROOM 316 HEAT	56180516
0320	Heat Detector	3rd 3RD FLR WEST ROOM 316 HEAT	56180517
0321	Smoke Detector	3rd 3RD FLR WEST ROOM 317 CLOSET SMOKE	56181799
0322	Smoke Detector	3rd 3RD FLR WEST ROOM 317 SMOKE	56181798
0323	Smoke Detector	3rd 3RD FLR WEST ROOM 315 SMOKE	56181801
0324	Smoke Detector	3rd 3RD FLR WEST STAIR # 1 SMOKE	56181804
0325	Smoke Detector	3rd 3RD FLR EAST ROOM 309 SMOKE	56180506
0326	Smoke Detector	3rd 3RD FLR EAST MEDIA CENTER SMOKE	56181832
0327	Smoke Detector	3rd 3RD FLR EAST MEDIA CENTER SMOKE	56181833
0328	Smoke Detector	3rd 3RD FLR EAST MEDIA CENTER SMOKE	56180497
0329	Smoke Detector	3rd 3RD FLR EAST CORRIDOR MEDIA CENTER SMOKE	56181812
0330	Smoke Detector	3rd 3RD FLR EAST ROOM 302 SMOKE	56181835
0331	Smoke Detector	3rd 3RD FLR EAST ROOM 300 SMOKE	56181827
0332	Smoke Detector	3rd 3RD FLR EAST ROOM 300 SMOKE	56181826
0333	Smoke Detector	3rd 3RD FLR EAST ROOM 301 SMOKE	20666702
0334	Smoke Detector	3rd 3RD FLR EAST ROOM 301 SMOKE	56181837
0335	Smoke Detector	3rd 3RD FLR EAST BOYS BATH ROOM SMOKE	56181820
0336	Smoke Detector	3rd 3RD FLR EAST GIRLS BATHROOM SMOKE	56180500
0337	Smoke Detector	3rd 3RD FLR EAST ALCOVE IN BOYS ROOM SMOKE	56181819
0338	Smoke Detector	3rd 3RD FLR EAST CLOSET IN BOYS ROOM HEAT	56181818
0339	Heat Detector	3rd 3RD FLR EAST CHASEWAY IN BOYS ROOM HEAT	3682728552
0340	Smoke Detector	3rd 3RD FLR EAST ROOM 308 SMOKE	56180504
0341	Heat Detector	Penthouse East EAST PENTHOUSE HEAT	3682728620
0342	Smoke Detector	3rd 3RD FLR EAST CORRIDOR BY ROOM 302 SMOKE	56181821
0343	Smoke Detector	3rd 3RD FLR EAST ROOM 303 SMOKE	56181829
0344	Smoke Detector	3rd 3RD FLR EAST VICE PRINCIPALS SMOKE	56181834

0345	Smoke Detector	3rd 3RD FLR EAST ROOM 303 SMOKE	56181830
0346	Smoke Detector	3rd 3RD FLR EAST ROOM 303-304 CLOSET SMOKE	56180494
0347	Smoke Detector	3rd 3RD FLR EAST ROOM 303-304 CLOSET SMOKE	56180493
0348	Smoke Detector	3rd 3RD FLR EAST CORRIDOR ROOM 302 SMOKE	56181822
0349	Smoke Detector	3rd 3RD FLR EAST CORRIDOR BY STAIR #4 SMOKE	56181823
0350	Smoke Detector	3rd 3RD FLR EAST ROOM 304 SMOKE	56180499
0351	Smoke Detector	3rd 3RD FLR EAST STAIR #4 SMOKE	56180492
0352	Smoke Detector	Penthouse West WEST PENTHOUSE STAIR #1 SMOKE	56180520
0353	Heat Detector	Penthouse West WEST PENTHOUSE HEAT	56181796
0354	Heat Detector	Penthouse West WEST PENTHOUSE HEAT	56181797
0355	Heat Detector	Penthouse West WEST PENTHOUSE HEAT	56180518
0356	Smoke Detector	3rd 3RD FLR EAST CORRIDOR BY ELEV DOOR SMOKE	56180498
0357	Smoke Detector	3rd 3RD FLR EAST CORRIDOR BY RM 308 SMOKE	56181813
0358	Smoke Detector	3rd 3RD FLR EAST CORRIDOR BY RM 307 SMOKE	56181816
0359	Smoke Detector	3rd 3RD FLR EAST RM 306 SMOKE	56180502
0360	Smoke Detector	3rd 3RD FLR EAST RM 307 SMOKE	56180501
0361	Smoke Detector	3rd 3RD FLR EAST RM 305 SMOKE	56180496
0362	Smoke Detector	3rd 3RD FLR EAST STAIR #3 SMOKE	56181815
0363	Smoke Detector	3rd 3RD FLR EAST CORRIDOR BY RM 304 SMOKE	56181817
0376	Pull Station	2nd 2ND FLR MAIN LOBBY RIGHT PULL STATION	56180471
0377	Pull Station	2nd 2ND FLR MAIN LOBBY LEFT PULL STATION	56180472
0378	Pull Station	2nd 2ND FLR EAST CORRIDOR STAIR # 3 PULL	56181854
0379	Pull Station	2nd 2ND FLR EAST CORRIDOR BY STAIR #4 PULL	56180490
0380	Pull Station	3rd 3RD FLR WEST CORRIDOR BY STAIR # 2 PULL	56180510
0381	Pull Station	3rd 3RD FLR WEST CORRIDOR BY STAIR # 1 PULL	56181803
0382	Pull Station	3rd 3RD FLR EAST CORRIDOR BY STAIR # 3 PULL	56181814
0383	Pull Station	Penthouse East EAST PENTHOUSE PULL STATION	4895743059
0384	Pull Station	Penthouse West WEST PENTHOUSE PULL STATION	56180519
0385	Pull Station	3rd 3RD FLR EAST CORRIDOR BY STAIR # 4 PULL	56181824

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Turn of River
School
117 VINE ROAD
Stamford, CT 06904

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Mar 27, 2020

Building: Stamford BOE-Turn of River School
Contact: Davor Lucaj
Title: Facilities Trades Manager



Company: TPC Associates, Inc.
Contact: Jordan Feher
Title: Fire alarm inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Turn of River School		Contact: Davor Lucaj
Address: 117 VINE ROAD		Phone: 203-977-6668
Address:		Fax:
City/State/Zip: Stamford, CT 06904		Mobile: 347-675-6021
Country: United States of America		Email: dlucaj@stamfordct.gov
Inspection Performed By		
Company: TPC Associates, Inc.		Inspector: Jordan Feher
Address: 261 Pepe's Farm Road		Phone: (203)878-1321
Address:		Fax:
City/State/Zip: Milford, Connecticut 06460		Mobile:
Country: United States of America		Email: jordan.feher@tpcsystems.com
System Control Unit		
Manufacturer: Notifier	Inspection Date: 03/27/2020	IDC Style:
Model Number: NFS2-3030(E)	Install Date: 08/21/2015	SLC Style:
Software Version:	Version Date: 08/21/2015	NAC Style:
Location: 1st Main Office In FACP	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type: Digital Communicator	Mfg: Radionics	Model #: D2071A
Test Time/Date: 3/27/20 11:17:58 AM	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	1.22%	0	0%	0	0%	0	0%
Control	5	6.10%	5	100.00%	5	100.00%	0	0%
Initiating	76	92.68%	76	100.00%	76	100.00%	0	0%
Totals	82	100%	81	98.78%	81	100.00%	0	0%

Certification	
<p>Company: TPC Associates, Inc.</p> <p>Inspector: Jordan Feher</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px auto;">  </div> <p>Signed: Mar 27, 2020 11:03:12 AM</p>	<p>Building: Stamford BOE-Turn of River School</p> <p>Contact: Davor Lucaj</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px auto;">  </div> <p>Signed: Mar 27, 2020 11:10:23 AM</p>

Notes & Recommendations

Generated by: BuildingReports.com

Building: Stamford BOE-Turn of River School

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

General Note

upon arrival and departure the "choral room hall smoke" has been disabled with permission. tech will be here next week for repair or replacement. -JF 3/22

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Turn of River School		Control Panel: 1 - Notifier NFS2-3030(E)		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Annunciator	1st Main Entrance Vestibule	Visually Checked	11:17:53 AM	03/27/2020
Battery	1st Main Office In FACP	Tested	10:48:03 AM	03/27/2020
Battery	1st Main Office In FACP	Tested	10:54:37 AM	03/27/2020
Communicator	1st Main Office In FACP	Visually Checked	11:17:58 AM	03/27/2020
Control Panel	1st Main Office In FACP	Visually Checked	10:53:05 AM	03/27/2020
Initiating				
Duct Detector	2nd MEDIA CENTER	Visually Checked	11:18:08 AM	03/27/2020
Duct Detector	2nd MEDIA CENTER ABOVE CEILING	Visually Checked	11:18:12 AM	03/27/2020
Duct Detector	2nd MEDIA CENTER ABOVE CEILING	Visually Checked	11:18:16 AM	03/27/2020
Duct Detector	2nd MEDIA CENTER ABOVE CEILING	Visually Checked	11:18:20 AM	03/27/2020
Heat Detector	Basement Office In Room 82	Visually Checked	11:19:43 AM	03/27/2020
Pull Station	1st Loading Dock	Visually Checked	11:19:52 AM	03/27/2020
Pull Station	1st Main Entrance Vestibule	Visually Checked	11:19:48 AM	03/27/2020
Smoke Detector	Basement Bottom Of Stair 4	Visually Checked	11:23:45 AM	03/27/2020
Smoke Detector	Basement Corridor By Room 81	Visually Checked	11:23:49 AM	03/27/2020
Smoke Detector	Basement Corridor By Room 82	Visually Checked	11:23:52 AM	03/27/2020
Smoke Detector	1st Band Storage In Rear Of Auditorium	Visually Checked	11:19:56 AM	03/27/2020
Smoke Detector	1st Band Storage In Rear Of Auditorium	Visually Checked	11:20:03 AM	03/27/2020
Smoke Detector	1st Corridor By Boys Locker Room	Visually Checked	11:24:40 AM	03/27/2020
Smoke Detector	1st Corridor By Boys Room/Auditorium	Visually Checked	11:23:33 AM	03/27/2020
Smoke Detector	1st Corridor By Cafeteria	Visually Checked	11:23:03 AM	03/27/2020
Smoke Detector	1st Corridor By Cafeteria	Visually Checked	11:23:07 AM	03/27/2020
Smoke Detector	1st Corridor By Conference Room 3	Visually Checked	11:22:52 AM	03/27/2020
Smoke Detector	1st Corridor By Faculty Dining	Visually Checked	11:23:00 AM	03/27/2020
Smoke Detector	1st Corridor By Girls Locker Room	Visually Checked	11:24:20 AM	03/27/2020
Smoke Detector	1st Corridor By Gym	Visually Checked	11:24:23 AM	03/27/2020
Smoke Detector	1st Corridor By Gym	Visually Checked	11:24:28 AM	03/27/2020
Smoke Detector	1st Corridor By Gym	Visually Checked	11:24:33 AM	03/27/2020
Smoke Detector	1st Corridor By Gym	Visually Checked	11:24:36 AM	03/27/2020
Smoke Detector	1st Corridor By Restrooms/Stair 1	Visually Checked	11:25:29 AM	03/27/2020
Smoke Detector	1st Corridor By Room 100	Visually Checked	11:23:22 AM	03/27/2020
Smoke Detector	1st Corridor By Room 101/Stair 3	Visually Checked	11:22:39 AM	03/27/2020
Smoke Detector	1st Corridor By Room 102	Visually Checked	11:23:19 AM	03/27/2020
Smoke Detector	1st Corridor By Room 103	Visually Checked	11:22:30 AM	03/27/2020
Smoke Detector	1st Corridor By Room 104	Visually Checked	11:23:15 AM	03/27/2020
Smoke Detector	1st Corridor By Room 105	Visually Checked	11:22:14 AM	03/27/2020
Smoke Detector	1st Corridor By Room 106	Visually Checked	11:23:12 AM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Corridor By Room 109	Visually Checked	11:24:13 AM	03/27/2020
Smoke Detector	1st Corridor By Room 110	Visually Checked	11:25:26 AM	03/27/2020
Smoke Detector	1st Corridor By Room 111	Visually Checked	11:24:17 AM	03/27/2020
Smoke Detector	1st Corridor By Room 112	Visually Checked	11:25:23 AM	03/27/2020
Smoke Detector	1st Corridor By Room 114	Visually Checked	11:25:18 AM	03/27/2020
Smoke Detector	1st Corridor By Room 120	Visually Checked	11:25:14 AM	03/27/2020
Smoke Detector	1st Corridor By Room 96	Visually Checked	11:23:38 AM	03/27/2020
Smoke Detector	1st Corridor By Room 98	Visually Checked	11:23:26 AM	03/27/2020
Smoke Detector	1st Corridor By Room 98/Auditorium	Visually Checked	11:23:29 AM	03/27/2020
Smoke Detector	1st Corridor By Room 99/Faculty Womens Room	Visually Checked	11:22:44 AM	03/27/2020
Smoke Detector	1st Corridor Outside Of Auditorium	Visually Checked	11:23:56 AM	03/27/2020
Smoke Detector	1st Corridor Outside Of Auditorium	Visually Checked	11:24:01 AM	03/27/2020
Smoke Detector	1st Corridor Outside Of Auditorium	Visually Checked	11:24:06 AM	03/27/2020
Smoke Detector	1st Front Center Corridor By Main Office Supply Room	Visually Checked	11:22:56 AM	03/27/2020
Smoke Detector	1st Janitor Closet By Auditorium	Visually Checked	11:24:10 AM	03/27/2020
Smoke Detector	1st Main Entrance Vestibule	Visually Checked	11:21:52 AM	03/27/2020
Smoke Detector	1st Main Lobby Corridor By Main Office	Visually Checked	11:21:58 AM	03/27/2020
Smoke Detector	1st Main Office	Visually Checked	11:22:02 AM	03/27/2020
Smoke Detector	1st Top Of Stair 4 By Room 96	Visually Checked	11:23:42 AM	03/27/2020
Smoke Detector	1st Vestibule Between Rooms 107/109	Visually Checked	11:22:06 AM	03/27/2020
Smoke Detector	1st Vestibule By Room 107	Visually Checked	11:22:09 AM	03/27/2020
Smoke Detector	2nd Corridor By Library	Visually Checked	11:20:48 AM	03/27/2020
Smoke Detector	2nd Corridor By Restrooms/Stair 2	Visually Checked	11:21:08 AM	03/27/2020
Smoke Detector	2nd Corridor By Room 201/Stair 3	Visually Checked	11:20:34 AM	03/27/2020
Smoke Detector	2nd Corridor By Room 203	Visually Checked	11:20:42 AM	03/27/2020
Smoke Detector	2nd Corridor By Room 206	Visually Checked	11:21:20 AM	03/27/2020
Smoke Detector	2nd Corridor By Room 207	Visually Checked	11:20:55 AM	03/27/2020
Smoke Detector	2nd Corridor By Room 208	Visually Checked	11:21:25 AM	03/27/2020
Smoke Detector	2nd Corridor By Room 210	Visually Checked	11:21:32 AM	03/27/2020
Smoke Detector	2nd Corridor By Room 212	Visually Checked	11:21:38 AM	03/27/2020
Smoke Detector	2nd Corridor By Room 214/Stair 1	Visually Checked	11:21:45 AM	03/27/2020
Smoke Detector	2nd Corridor By Room 219/Stair 1	Visually Checked	11:21:42 AM	03/27/2020
Smoke Detector	2nd Corridor By Teachers Lounge Room 225	Visually Checked	11:21:02 AM	03/27/2020
Smoke Detector	2nd MEDIA CENTER ABOVE CEILING	Visually Checked	11:20:07 AM	03/27/2020
Smoke Detector	2nd Top Of Stair 1	Visually Checked	11:21:48 AM	03/27/2020
Smoke Detector	2nd Top Of Stair 2	Visually Checked	11:21:15 AM	03/27/2020
Smoke Detector	2nd Top Of Stair 3	Visually Checked	11:20:25 AM	03/27/2020
Smoke Detector	1st Portable Classroom 126	Visually Checked	11:25:11 AM	03/27/2020
Smoke Detector	1st Portable Classroom 128	Visually Checked	11:25:03 AM	03/27/2020
Smoke Detector	1st Portable Classroom 130	Visually Checked	11:25:07 AM	03/27/2020
Smoke Detector	1st Portable Classroom 132	Visually Checked	11:24:59 AM	03/27/2020
Smoke Detector	1st Portable Corridor By Rear Exit	Visually Checked	11:24:56 AM	03/27/2020
Smoke Detector	1st Portable Corridor By Restroom	Visually Checked	11:24:49 AM	03/27/2020
Smoke Detector	1st Portable Corridor By Room 130	Visually Checked	11:24:52 AM	03/27/2020
Smoke Detector	1st Portable Entrance	Visually Checked	11:24:45 AM	03/27/2020

Service Summary

Generated by: BuildingReports.com






Building: Stamford BOE-Turn of River School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Passed</i>		
Annunciator	Visually Checked	1
Battery	Tested	2
Communicator	Visually Checked	1
Control Panel	Visually Checked	1
Duct Detector	Visually Checked	4
Heat Detector	Visually Checked	1
Pull Station	Visually Checked	2
Smoke Detector	Visually Checked	69
Total		81
Grand Total		81

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Turn of River School							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		 dB	 dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
Whole Building				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Turn of River School				Control Panel: 1 - Notifier NFS2-3030(E)			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<i>Passed</i>							
Battery							
Sealed Lead Acid	1st Main Office In FACP	5	12	12.56v	5.8ah		
Sealed Lead Acid	1st Main Office In FACP	55	12	13.27	40ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Turn of River School			Control Panel: 1 - Notifier NFS2-3030(E)		
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		1.22%	1
Battery		Control		2.44%	2
Control Panel		Control		1.22%	1
Annunciator		Control		1.22%	1
Communicator		Control		1.22%	1
Duct Detector		Initiating		4.88%	4
Heat Detector		Initiating		1.22%	1
Pull Station		Initiating		2.44%	2
Smoke Detector		Initiating		84.15%	69
Type	Qty	Model #	Description		Install Date
In Service - 1 Year to 2 Years					
Universal					
Battery	1	UB1250	Sealed Lead Acid		09/21/2018
In Service - 3 Years to 5 Years					
Notifier					
Annunciator	1	NFS2-3030(E)	LCD Display		08/21/2015
Control Panel	1				08/21/2015
Duct Detector	4		FSP-851	Photoelectric	08/21/2015
Heat Detector	1		FST-851	Fixed Temperature	08/21/2015
Pull Station	2		NBG-12LX	Dual Action	08/21/2015
Smoke Detector	69		FSP-851	Photoelectric	08/21/2015
Power-Sonic					
Battery	1	PS-12550 U	Sealed Lead Acid		08/21/2015
Radionics					
Communicator	1	D2071A	Digital Communicator		08/21/2015

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Turn of River School

Control Panel: 1 - Notifier
NFS2-3030(E)

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 1				
1D00	Duct Detector	2nd MEDIA CENTER	Photoelectric	21123294
1D001	Smoke Detector	1st Corridor By Room 96	Photoelectric	21130683
1D002	Smoke Detector	1st Corridor By Boys Room/Auditorium	Photoelectric	21130682
1D003	Smoke Detector	1st Corridor By Room 98/Auditorium	Photoelectric	21130681
1D004	Smoke Detector	1st Top Of Stair 4 By Room 96	Photoelectric	21130684
1D005	Smoke Detector	1st Janitor Closet By Auditorium	Photoelectric	21130692
1D006	Smoke Detector	1st Band Storage In Rear Of Auditorium	Photoelectric	20667093
1D007	Smoke Detector	1st Band Storage In Rear Of Auditorium	Photoelectric	20667092
1D009	Smoke Detector	1st Corridor Outside Of Auditorium	Photoelectric	21130691
1D010	Smoke Detector	1st Corridor Outside Of Auditorium	Photoelectric	21130690
1D011	Smoke Detector	1st Corridor Outside Of Auditorium	Photoelectric	21130689
1D012	Smoke Detector	1st Corridor By Room 98	Photoelectric	21130680
1D013	Smoke Detector	1st Corridor By Room 100	Photoelectric	21130679
1D014	Smoke Detector	1st Corridor By Room 102	Photoelectric	21130678
1D015	Smoke Detector	1st Corridor By Room 104	Photoelectric	21130677
1D016	Smoke Detector	1st Corridor By Room 106	Photoelectric	21130676
1D019	Smoke Detector	1st Corridor By Cafeteria	Photoelectric	21130674
1D019	Pull Station	1st Main Entrance Vestibule	Dual Action	21130660
1D020	Smoke Detector	1st Corridor By Cafeteria	Photoelectric	21130673
1D022	Smoke Detector	1st Corridor By Faculty Dining	Photoelectric	21130672
1D023	Smoke Detector	1st Front Center Corridor By Main Office Supply Room	Photoelectric	21130671
1D024	Smoke Detector	1st Corridor By Conference Room 3	Photoelectric	21130670
1D025	Smoke Detector	1st Main Lobby Corridor By Main Office	Photoelectric	21130662
1D026	Smoke Detector	1st Main Entrance Vestibule	Photoelectric	21130659
1D027	Smoke Detector	1st Corridor By Room 99/Faculty Womens Room	Photoelectric	21130669
1D028	Smoke Detector	1st Corridor By Room 101/Stair 3	Photoelectric	21130668
1D029	Smoke Detector	1st Corridor By Room 103	Photoelectric	21130667
1D030	Smoke Detector	1st Corridor By Room 105	Photoelectric	21130666
1D031	Smoke Detector	1st Vestibule By Room 107	Photoelectric	21130665
1D032	Smoke Detector	1st Vestibule Between Rooms 107/109	Photoelectric	21130664
1D033	Smoke Detector	1st Corridor By Room 109	Photoelectric	21130693
1D034	Smoke Detector	1st Corridor By Room 111	Photoelectric	21130694
1D035	Smoke Detector	1st Corridor By Girls Locker Room	Photoelectric	21130695
1D036	Smoke Detector	1st Corridor By Gym	Photoelectric	21130696
1D037	Smoke Detector	1st Corridor By Gym	Photoelectric	21130697
1D038	Smoke Detector	1st Corridor By Gym	Photoelectric	21130698
1D039	Smoke Detector	1st Corridor By Gym	Photoelectric	21130699

1D040	Smoke Detector	1st Corridor By Boys Locker Room	Photoelectric	21130700
1D041	Smoke Detector	1st Corridor By Room 120	Photoelectric	21130709
1D042	Smoke Detector	1st Corridor By Room 114	Photoelectric	21130710
1D043	Smoke Detector	1st Corridor By Room 112	Photoelectric	21130711
1D044	Smoke Detector	1st Corridor By Room 110	Photoelectric	21130712
1D045	Smoke Detector	1st Corridor By Restrooms/Stair 1	Photoelectric	21130713
1D046	Smoke Detector	1st Main Office	Photoelectric	21130663
1D047	Smoke Detector	Basement Bottom Of Stair 4	Photoelectric	21130685
1D048	Smoke Detector	Basement Corridor By Room 82	Photoelectric	21130687
1D049	Smoke Detector	Basement Corridor By Room 81	Photoelectric	21130686
1D050	Heat Detector	Basement Office In Room 82	Fixed Temperature	21130688
1D051	Smoke Detector	1st Portable Entrance	Photoelectric	21130701
1D052	Smoke Detector	1st Portable Corridor By Restroom	Photoelectric	21130702
1D053	Smoke Detector	1st Portable Corridor By Room 130	Photoelectric	21130703
1D054	Smoke Detector	1st Portable Corridor By Rear Exit	Photoelectric	21130704
1D055	Smoke Detector	1st Portable Classroom 128	Photoelectric	21130706
1D056	Smoke Detector	1st Portable Classroom 126	Photoelectric	21130708
1D057	Smoke Detector	1st Portable Classroom 130	Photoelectric	21130707
1D058	Smoke Detector	1st Portable Classroom 132	Photoelectric	21130705
1D061	Smoke Detector	2nd Corridor By Teachers Lounge Room 225	Photoelectric	21130649
1D062	Smoke Detector	2nd Corridor By Room 207	Photoelectric	21130648
1D063	Smoke Detector	2nd Corridor By Library	Photoelectric	21130647
1D064	Smoke Detector	2nd Corridor By Room 203	Photoelectric	21130646
1D065	Smoke Detector	2nd Corridor By Room 201/Stair 3	Photoelectric	21130645
1D067	Smoke Detector	2nd Top Of Stair 3	Photoelectric	21130644
1D068	Duct Detector	2nd MEDIA CENTER ABOVE CEILING	Photoelectric	21123295
1D069	Duct Detector	2nd MEDIA CENTER ABOVE CEILING	Photoelectric	21123306
1D070	Smoke Detector	2nd MEDIA CENTER ABOVE CEILING	Photoelectric	21123305
1D071	Duct Detector	2nd MEDIA CENTER ABOVE CEILING	Photoelectric	21123296
1D072	Smoke Detector	2nd Top Of Stair 2	Photoelectric	21130651
1D073	Smoke Detector	2nd Corridor By Restrooms/Stair 2	Photoelectric	21130650
1D074	Smoke Detector	2nd Corridor By Room 214/Stair 1	Photoelectric	21130657
1D075	Smoke Detector	2nd Corridor By Room 219/Stair 1	Photoelectric	21130656
1D076	Smoke Detector	2nd Corridor By Room 212	Photoelectric	21130655
1D077	Smoke Detector	2nd Corridor By Room 210	Photoelectric	21130654
1D078	Smoke Detector	2nd Corridor By Room 208	Photoelectric	21130653
1D079	Smoke Detector	2nd Corridor By Room 206	Photoelectric	21130652
1D080	Smoke Detector	2nd Top Of Stair 1	Photoelectric	21130658
1M050	Pull Station	1st Loading Dock	Dual Action	21130675
	Annunciator	1st Main Entrance Vestibule	LCD Display	21130661

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Scofield School
641 Scofieldtown Road
Stamford, CT 06904

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Mar 25, 2020



Building: Stamford BOE-Scofield School
Contact: Davor Lucaj
Title: Facilities Trades Manager

Company: TPC Associates, Inc.
Contact: Luis De La Cruz
Title: Fire alarm inspector

Executive Summary





Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Scofield School	Contact: Davor Lucaj	
Address: 641 Scofieldtown Road	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06904	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Luis De La Cruz	
Address: 261 Pepe's Farm Road	Phone: (203)878-1321	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: Luis.delacruz@tpcsystems.com	
System Control Unit		
Manufacturer: EST	Inspection Date: 03/25/2020	IDC Style:
Model Number: EST-2	Install Date: 08/06/2012	SLC Style:
Software Version:	Version Date: 08/06/2012	NAC Style:
Location: 1st Office Copy Rm	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.44%	0	0%	0	0%	0	0%
Control	10	4.39%	10	100.00%	5	50.00%	5	50.00%
Auxiliary	1	0.44%	1	100.00%	1	100.00%	0	0%
Initiating	216	94.74%	216	100.00%	216	100.00%	0	0%
Totals	228	100%	227	99.56%	222	97.80%	5	2.20%
Certification								
Company: TPC Associates, Inc.				Building: Stamford BOE-Scofield School				
Inspector: Luis De La Cruz				Contact: Davor Lucaj				
								
Signed: Mar 25, 2020 9:22:00 AM				Signed: Mar 25, 2020 9:23:31 AM				

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-Scofield School			Control Panel: 1 - EST EST-2		
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>					
Device Type		Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>					
No recalled items found during this inspection.					
 ScanID	 Location		 Problem	Address	 Reference
<i>Control</i>					
Battery					
04061462	1st Office Copy Rm Top Left Set		Failed Test	1-0203	NFPA 72 Table 10.4.2.2.5(a-e)
04061465	1st Office Copy Rm Top Right Set		Failed Test	1-0205	NFPA 72 Table 10.4.2.2.5(a-e)
04062214	1st Storage Room 156A		Failed Test	1-0451	NFPA 72 Table 10.4.2.2.5(a-e)
04590169	2nd Electrical Room 221B By Elevator		Failed Test	1-0457	NFPA 72 Table 10.4.2.2.5(a-e)
04062207	2nd Electrical Room 245A		Failed Test	1-0458	NFPA 72 Table 10.4.2.2.5(a-e)

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-Scofield School			Control Panel: 1 - EST EST-2		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
<i>Control</i>					
Battery					
04061462	1st Office Copy Rm Top Left Set	Replace	UB1280	T/M	<input type="checkbox"/>
04061465	1st Office Copy Rm Top Right Set	Replace	UB1280	T/M	<input type="checkbox"/>
04062214	1st Storage Room 156A	Replace	12120-F2	T/M	<input type="checkbox"/>
04590169	2nd Electrical Room 221B By Elevator	Replace	UB1280	T/M	<input type="checkbox"/>
04062207	2nd Electrical Room 245A	Replace	UT 1270	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Scofield School		Control Panel: 1 - EST EST-2		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Auxiliary				
Damper Control	Parking Gym Fitness	Visually Checked	8:47:37 AM	03/25/2020
Control				
Annunciator	Basement Cafeteria Head Custodian B6	Visually Checked	9:01:29 AM	03/25/2020
Annunciator	1st Lobby Main Entrance	Visually Checked	8:31:06 AM	03/25/2020
Battery	1st Office Copy Rm (FACP)	Visually Checked	8:22:54 AM	03/25/2020
Battery	1st Office Copy Rm Bottom Set	Visually Checked	8:17:02 AM	03/25/2020
Control Panel	1st Office Copy Rm	Visually Checked	8:22:48 AM	03/25/2020
Initiating				
Duct Detector	Basement Cafeteria Mechanical AC7 Return	Visually Checked	8:59:56 AM	03/25/2020
Duct Detector	Basement Cafeteria Mechanical AC7 Supply	Visually Checked	8:54:54 AM	03/25/2020
Duct Detector	2nd Corridor Room 248 AC5A Supply	Visually Checked	7:54:09 AM	03/25/2020
Duct Detector	2nd Corridor Room 265 AC 6 Supply	Visually Checked	8:03:35 AM	03/25/2020
Duct Detector	2nd Corridor By Room 225 AC4A Return	Visually Checked	7:58:00 AM	03/25/2020
Duct Detector	2nd Corridor By Room 225 AC4A Supply	Visually Checked	7:58:01 AM	03/25/2020
Duct Detector	2nd Corridor By Room 234 AC4B Return	Visually Checked	7:56:57 AM	03/25/2020
Duct Detector	2nd Corridor By Room 234 AC4B Supply	Visually Checked	7:57:04 AM	03/25/2020
Duct Detector	2nd Corridor By Room 263 AC 1B Return	Visually Checked	8:05:34 AM	03/25/2020
Duct Detector	2nd Corridor By Room 263 AC 1B Supply	Visually Checked	8:03:51 AM	03/25/2020
Duct Detector	2nd Corridor By Room 265 AC1A Supply	Visually Checked	8:02:55 AM	03/25/2020
Duct Detector	2nd Corridor By Room 265 AC 1A Return	Visually Checked	8:03:23 AM	03/25/2020
Duct Detector	2nd Corridor By Room 206 AC 2A-Return	Visually Checked	8:00:58 AM	03/25/2020
Duct Detector	2nd Corridor By Room 206 AC 2A-Supply	Visually Checked	8:01:13 AM	03/25/2020
Duct Detector	2nd Corridor By Room 206 AC 3A-Return	Visually Checked	8:01:04 AM	03/25/2020
Duct Detector	2nd Corridor By Room 209 AC 3A-Supply	Visually Checked	8:55:06 AM	03/25/2020
Duct Detector	2nd Corridor By Room 219A Custodial Room AC 3B-Return	Visually Checked	7:58:54 AM	03/25/2020
Duct Detector	2nd Corridor By Room 219A Custodial Room AC 3B-Supply	Visually Checked	7:58:59 AM	03/25/2020
Duct Detector	2nd Corridor By Stair E AC5A Return	Visually Checked	7:54:27 AM	03/25/2020
Duct Detector	2nd Corridor by Womens Room AC5B Supply	Visually Checked	7:53:58 AM	03/25/2020
Duct Detector	2nd Room 248 AC5A Return	Visually Checked	7:54:20 AM	03/25/2020
Duct Detector	2nd Womens AC5B Return	Visually Checked	7:53:54 AM	03/25/2020
Duct Detector	2nd Room 222 AC2A Return	Visually Checked	7:58:17 AM	03/25/2020
Duct Detector	2nd Room 222 AC2A Supply	Visually Checked	7:58:16 AM	03/25/2020
Duct Detector	2nd Room 264 AC 6 Return	Visually Checked	8:55:01 AM	03/25/2020
Heat Detector	Basement Boiler Room B55	Visually Checked	8:55:43 AM	03/25/2020
Heat Detector	Basement Boiler Room B55	Visually Checked	8:55:46 AM	03/25/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	Basement Cafeteria Custodial Rm B22	Visually Checked	8:55:50 AM	03/25/2020
Heat Detector	Basement Cafeteria Kitchen	Visually Checked	8:55:53 AM	03/25/2020
Heat Detector	Basement Cafeteria Kitchen	Visually Checked	8:55:56 AM	03/25/2020
Heat Detector	Basement Cafeteria Mechanical B7	Visually Checked	9:00:12 AM	03/25/2020
Heat Detector	Basement Cafeteria Mechanical B8 Electical	Visually Checked	9:00:17 AM	03/25/2020
Heat Detector	Basement B15 Elevator Machine Rm	Visually Checked	8:56:04 AM	03/25/2020
Heat Detector	Basement b51 elevator machine room	Visually Checked	8:56:32 AM	03/25/2020
Heat Detector	1st 159c phys Ed office in girls locker room	Visually Checked	8:55:18 AM	03/25/2020
Heat Detector	1st Bathroom Rm 160C boys locker room	Visually Checked	8:55:32 AM	03/25/2020
Heat Detector	1st Boys Bathroom	Visually Checked	8:55:24 AM	03/25/2020
Heat Detector	1st Gym Bathroom in office 159c	Visually Checked	8:55:21 AM	03/25/2020
Heat Detector	1st Gym Fitness Girls Rm	Visually Checked	8:48:04 AM	03/25/2020
Heat Detector	1st P.E. Office Rm 160C	Visually Checked	8:55:28 AM	03/25/2020
Heat Detector	1st Room 146B	Visually Checked	8:56:29 AM	03/25/2020
Heat Detector	1st Room 161	Visually Checked	8:55:35 AM	03/25/2020
Heat Detector	1st Storage Room 156	Visually Checked	8:45:18 AM	03/25/2020
Heat Detector	1st Storage Room 156A	Visually Checked	9:19:01 AM	03/25/2020
Heat Detector	1st Storage Room 158	Visually Checked	8:55:39 AM	03/25/2020
Heat Detector	1st Boys Locker Rm 160	Visually Checked	8:47:43 AM	03/25/2020
Heat Detector	2nd Corridor 225B	Visually Checked	7:58:44 AM	03/25/2020
Heat Detector	2nd Room 247A	Visually Checked	8:56:00 AM	03/25/2020
Pull Station	Basement Boiler Room B55	Visually Checked	8:57:48 AM	03/25/2020
Pull Station	Basement Cafeteria by Stair E	Visually Checked	8:54:29 AM	03/25/2020
Pull Station	Basement Cafeteria by Stair F	Visually Checked	8:52:59 AM	03/25/2020
Pull Station	Basement Cafeteria by Stair G	Visually Checked	8:53:23 AM	03/25/2020
Pull Station	Basement Passage Way	Visually Checked	8:37:44 AM	03/25/2020
Pull Station	Basement Stair E	Visually Checked	8:54:37 AM	03/25/2020
Pull Station	Basement Stair G (below)	Visually Checked	8:53:33 AM	03/25/2020
Pull Station	Basement Stair A	Visually Checked	8:36:14 AM	03/25/2020
Pull Station	1st By Gym	Visually Checked	8:45:07 AM	03/25/2020
Pull Station	1st By Science Lab 120	Visually Checked	8:13:34 AM	03/25/2020
Pull Station	1st Gym	Visually Checked	8:43:35 AM	03/25/2020
Pull Station	1st Lobby Main Entrance	Visually Checked	8:31:12 AM	03/25/2020
Pull Station	1st Lobby Main Entrance	Visually Checked	8:31:17 AM	03/25/2020
Pull Station	1st Room 144	Visually Checked	8:57:45 AM	03/25/2020
Pull Station	1st Back Entrance	Visually Checked	8:11:28 AM	03/25/2020
Pull Station	1st Back Entrance	Visually Checked	8:11:46 AM	03/25/2020
Pull Station	1st Side Entrance By Storage 118	Visually Checked	8:13:48 AM	03/25/2020
Pull Station	1st Side Entrance Stair B	Visually Checked	8:57:37 AM	03/25/2020
Pull Station	1st Side Entrance Stair C	Visually Checked	8:12:03 AM	03/25/2020
Pull Station	1st Side Entrance Stair D	Visually Checked	8:12:21 AM	03/25/2020
Pull Station	1st Stair A	Visually Checked	8:29:53 AM	03/25/2020
Pull Station	1st Stair A	Visually Checked	8:30:03 AM	03/25/2020
Pull Station	1st By Rm 155 Maintance	Visually Checked	8:49:26 AM	03/25/2020
Pull Station	1st By Science Lab	Visually Checked	8:10:26 AM	03/25/2020
Pull Station	1st By Stair E	Visually Checked	8:09:12 AM	03/25/2020
Pull Station	1st By Stair G	Visually Checked	8:50:58 AM	03/25/2020
Pull Station	1st In Stair G	Visually Checked	8:08:34 AM	03/25/2020
Pull Station	2nd By Room 260	Visually Checked	8:06:34 AM	03/25/2020
Pull Station	2nd By Stair F	Visually Checked	8:57:29 AM	03/25/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	2nd By Stair G	Visually Checked	8:07:15 AM	03/25/2020
Pull Station	2nd Corridor By Room 265	Visually Checked	8:02:48 AM	03/25/2020
Pull Station	2nd Corridor By Room 225B	Visually Checked	7:58:36 AM	03/25/2020
Pull Station	2nd Corridor By Stair A	Visually Checked	8:01:39 AM	03/25/2020
Pull Station	2nd Corridor By Stair B	Visually Checked	7:59:04 AM	03/25/2020
Pull Station	2nd Corridor By Stair C	Visually Checked	7:56:46 AM	03/25/2020
Pull Station	2nd Corridor By Stair D	Visually Checked	7:56:51 AM	03/25/2020
Pull Station	2nd Corridor By Stair E	Visually Checked	8:57:26 AM	03/25/2020
Smoke Detector	Basement Elevator Lobby by Stair A	Visually Checked	8:36:31 AM	03/25/2020
Smoke Detector	Basement Lobby Elevator By B15 Elevator Machine	Visually Checked	9:00:46 AM	03/25/2020
Smoke Detector	Basement Room B57	Visually Checked	8:59:43 AM	03/25/2020
Smoke Detector	Basement Room B58	Visually Checked	9:00:22 AM	03/25/2020
Smoke Detector	Basement Room B58A	Visually Checked	9:00:25 AM	03/25/2020
Smoke Detector	Basement Storage Room	Visually Checked	9:00:28 AM	03/25/2020
Smoke Detector	Basement Store Room by Stair A	Visually Checked	8:36:59 AM	03/25/2020
Smoke Detector	Basement Store Room by Stair A	Visually Checked	8:37:05 AM	03/25/2020
Smoke Detector	Basement B15 Elevator Machine Rm	Visually Checked	9:00:49 AM	03/25/2020
Smoke Detector	Basement B51 elevator machine room	Visually Checked	9:00:58 AM	03/25/2020
Smoke Detector	Basement By Rm 2	Visually Checked	8:37:21 AM	03/25/2020
Smoke Detector	Basement Stair A	Visually Checked	8:36:39 AM	03/25/2020
Smoke Detector	1st By Conference Rm	Visually Checked	8:15:26 AM	03/25/2020
Smoke Detector	1st By Custodial Rm 113	Visually Checked	8:13:43 AM	03/25/2020
Smoke Detector	1st By Girls Rm By Stair A	Visually Checked	8:29:48 AM	03/25/2020
Smoke Detector	1st By Guidance	Visually Checked	8:14:45 AM	03/25/2020
Smoke Detector	1st By Guidance	Visually Checked	8:15:11 AM	03/25/2020
Smoke Detector	1st By Main office	Visually Checked	8:15:44 AM	03/25/2020
Smoke Detector	1st By Media Center	Visually Checked	8:29:20 AM	03/25/2020
Smoke Detector	1st By Nurse	Visually Checked	8:14:27 AM	03/25/2020
Smoke Detector	1st By Water Fountain	Visually Checked	8:14:16 AM	03/25/2020
Smoke Detector	1st Closet In Science Lab Rm 120	Visually Checked	8:59:15 AM	03/25/2020
Smoke Detector	1st Guidance By Rm 108A	Visually Checked	8:34:31 AM	03/25/2020
Smoke Detector	1st Guidance By Rm 108C	Visually Checked	8:34:40 AM	03/25/2020
Smoke Detector	1st Gym Lobby by room 161 thru entrance 162A	Visually Checked	8:40:13 AM	03/25/2020
Smoke Detector	1st Lobby Main Entrance	Visually Checked	8:39:18 AM	03/25/2020
Smoke Detector	1st Lobby	Visually Checked	8:30:28 AM	03/25/2020
Smoke Detector	1st Lobby	Visually Checked	8:30:59 AM	03/25/2020
Smoke Detector	1st Lobby	Visually Checked	8:39:04 AM	03/25/2020
Smoke Detector	1st Lobby Elevator By Music	Visually Checked	8:10:07 AM	03/25/2020
Smoke Detector	1st Lobby Elevator	Visually Checked	8:30:37 AM	03/25/2020
Smoke Detector	1st Lobby Elevator	Visually Checked	9:00:42 AM	03/25/2020
Smoke Detector	1st Office 106 Principal	Visually Checked	8:16:21 AM	03/25/2020
Smoke Detector	1st Office 107	Visually Checked	8:15:55 AM	03/25/2020
Smoke Detector	1st Office 107	Visually Checked	8:59:02 AM	03/25/2020
Smoke Detector	1st Office Copy Rm 107B	Visually Checked	8:58:59 AM	03/25/2020
Smoke Detector	1st Pupil Services Rm 109	Visually Checked	8:14:36 AM	03/25/2020
Smoke Detector	1st Room 110	Visually Checked	8:59:05 AM	03/25/2020
Smoke Detector	1st By Boys Locker Rm 160	Visually Checked	8:48:39 AM	03/25/2020
Smoke Detector	1st By Boys Locker Rm 160	Visually Checked	8:48:50 AM	03/25/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st By Gym Rm 162	Visually Checked	8:40:00 AM	03/25/2020
Smoke Detector	1st By Rm 127	Visually Checked	8:12:46 AM	03/25/2020
Smoke Detector	1st By Rm 127	Visually Checked	8:12:55 AM	03/25/2020
Smoke Detector	1st By 139 Science	Visually Checked	8:59:30 AM	03/25/2020
Smoke Detector	1st By 139 Science	Visually Checked	8:59:34 AM	03/25/2020
Smoke Detector	1st By 139A Science Prep Rm	Visually Checked	8:59:27 AM	03/25/2020
Smoke Detector	1st By Back Entrance	Visually Checked	8:11:20 AM	03/25/2020
Smoke Detector	1st By Back Entrance	Visually Checked	8:11:39 AM	03/25/2020
Smoke Detector	1st By Gym	Visually Checked	8:49:06 AM	03/25/2020
Smoke Detector	1st By Gym Storage 156	Visually Checked	8:45:02 AM	03/25/2020
Smoke Detector	1st By Music	Visually Checked	8:10:09 AM	03/25/2020
Smoke Detector	1st By Music	Visually Checked	8:10:19 AM	03/25/2020
Smoke Detector	1st By Rm 130	Visually Checked	8:12:32 AM	03/25/2020
Smoke Detector	1st By Rm 143	Visually Checked	8:09:01 AM	03/25/2020
Smoke Detector	1st By Rm 148	Visually Checked	8:49:38 AM	03/25/2020
Smoke Detector	1st By Rm 149	Visually Checked	8:49:52 AM	03/25/2020
Smoke Detector	1st By Rm 155 Maintance	Visually Checked	8:49:22 AM	03/25/2020
Smoke Detector	1st By Science 139	Visually Checked	8:11:03 AM	03/25/2020
Smoke Detector	1st By Science 139	Visually Checked	8:59:39 AM	03/25/2020
Smoke Detector	1st By Science Lab	Visually Checked	8:13:30 AM	03/25/2020
Smoke Detector	1st By Science Lab Rm 120	Visually Checked	8:13:10 AM	03/25/2020
Smoke Detector	1st By Science Lab Rm 120	Visually Checked	8:13:22 AM	03/25/2020
Smoke Detector	1st By Stair C	Visually Checked	8:12:08 AM	03/25/2020
Smoke Detector	1st By Stair E	Visually Checked	8:09:09 AM	03/25/2020
Smoke Detector	1st By Stair F	Visually Checked	8:51:26 AM	03/25/2020
Smoke Detector	1st By Stair G	Visually Checked	8:50:50 AM	03/25/2020
Smoke Detector	1st Courtyard Lobby	Visually Checked	8:10:40 AM	03/25/2020
Smoke Detector	1st In Science Lab Rm 120	Visually Checked	8:59:11 AM	03/25/2020
Smoke Detector	1st In Science Lab Rm 120	Visually Checked	8:59:20 AM	03/25/2020
Smoke Detector	1st Rm 130	Visually Checked	8:59:24 AM	03/25/2020
Smoke Detector	2nd By Room 237	Visually Checked	7:56:14 AM	03/25/2020
Smoke Detector	2nd By Stair F	Visually Checked	7:53:40 AM	03/25/2020
Smoke Detector	2nd By Stair G	Visually Checked	8:07:05 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 262	Visually Checked	8:05:44 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 262	Visually Checked	8:05:52 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 263	Visually Checked	8:03:48 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 265	Visually Checked	8:02:59 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 265	Visually Checked	8:03:30 AM	03/25/2020
Smoke Detector	2nd Corridor Between Stair C and D	Visually Checked	7:57:06 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 227	Visually Checked	7:57:53 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 229	Visually Checked	7:57:44 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 231	Visually Checked	7:57:29 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 232	Visually Checked	7:57:16 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 266A	Visually Checked	8:02:31 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 266A (Skylight Left Side)	Visually Checked	8:02:03 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 266A (Skylight Right Side)	Visually Checked	8:02:37 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 266A By Elevator	Visually Checked	8:02:08 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 266A Center	Visually Checked	8:02:19 AM	03/25/2020
Smoke Detector	2nd Corridor By Fountain	Visually Checked	7:59:39 AM	03/25/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd Corridor By Room 207	Visually Checked	8:01:10 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 209	Visually Checked	8:00:49 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 210	Visually Checked	8:00:39 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 211	Visually Checked	8:00:31 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 212	Visually Checked	8:00:20 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 214	Visually Checked	7:59:55 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 219A	Visually Checked	7:59:00 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 222	Visually Checked	7:58:19 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 225	Visually Checked	7:58:08 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 240	Visually Checked	7:55:50 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 240A	Visually Checked	7:56:01 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 242	Visually Checked	7:55:23 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 244	Visually Checked	7:55:21 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 248	Visually Checked	7:54:54 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 260	Visually Checked	8:06:16 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 260	Visually Checked	8:06:27 AM	03/25/2020
Smoke Detector	2nd Corridor By Room 262B	Visually Checked	8:06:05 AM	03/25/2020
Smoke Detector	2nd Corridor By Stair A	Visually Checked	8:01:35 AM	03/25/2020
Smoke Detector	2nd Corridor By Stair E	Visually Checked	7:54:30 AM	03/25/2020
Smoke Detector	2nd Corridor By Stair F Next To Faculty Toilet	Visually Checked	7:53:50 AM	03/25/2020
Smoke Detector	2nd East Elevator Lobby By Stair E	Visually Checked	7:55:00 AM	03/25/2020
Smoke Detector	2nd Main Entrance Elevator Lobby By Stair A	Visually Checked	8:01:54 AM	03/25/2020
Smoke Detector	2nd Outside Room 240A	Visually Checked	8:58:27 AM	03/25/2020
Smoke Detector	2nd Room 205 Science Lab	Visually Checked	8:57:53 AM	03/25/2020
Smoke Detector	2nd Room 205A Left	Visually Checked	8:57:58 AM	03/25/2020
Smoke Detector	2nd Room 205A Right	Visually Checked	8:58:01 AM	03/25/2020
Smoke Detector	2nd Room 206 Science Lab	Visually Checked	8:58:04 AM	03/25/2020
Smoke Detector	2nd Room 231 Science Lab	Visually Checked	8:58:08 AM	03/25/2020
Smoke Detector	2nd Room 231A	Visually Checked	8:58:20 AM	03/25/2020
Smoke Detector	2nd Room 237	Visually Checked	8:58:23 AM	03/25/2020
Smoke Detector	2nd Room 243	Visually Checked	8:58:30 AM	03/25/2020
Smoke Detector	2nd Room 243A	Visually Checked	8:58:35 AM	03/25/2020
Smoke Detector	2nd Room 260	Visually Checked	8:58:38 AM	03/25/2020
Smoke Detector	2nd Room 262B Electrical	Visually Checked	8:58:41 AM	03/25/2020
Smoke Detector	2nd West Elevator Lobby By Stair B	Visually Checked	7:59:16 AM	03/25/2020
Smoke Detector	2nd Room 262/263	Visually Checked	8:58:49 AM	03/25/2020
Smoke Detector	2nd Room 262/263	Visually Checked	9:00:53 AM	03/25/2020
Smoke Detector	2nd Room 262/263 Office	Visually Checked	8:58:45 AM	03/25/2020
Smoke Detector	2nd Room 264	Visually Checked	9:00:32 AM	03/25/2020
Smoke Detector	2nd Room 265	Visually Checked	9:00:36 AM	03/25/2020
Smoke Detector	2nd Room 265 Rear	Visually Checked	9:00:39 AM	03/25/2020
Smoke Detector	2nd Room 266A	Visually Checked	8:58:53 AM	03/25/2020
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	1st Office Copy Rm Top Left Set	Tested	8:20:13 AM	03/25/2020
Battery	1st Office Copy Rm Top Right Set	Visually Checked	8:21:48 AM	03/25/2020
Battery	1st Storage Room 156A	Visually Checked	9:17:30 AM	03/25/2020
Battery	2nd Electrical Room 221B By Elevator	Visually Checked	9:10:04 AM	03/25/2020

Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Battery	2nd Electrical Room 245A	Visually Checked	9:05:21 AM	03/25/2020

Service Summary

Generated by: BuildingReports.com

Building: Stamford BOE-Scofield School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	1
Battery	Visually Checked	4
Total		5
<i>Passed</i>		
Annunciator	Visually Checked	2
Battery	Visually Checked	2
Control Panel	Visually Checked	1
Damper Control	Visually Checked	1
Duct Detector	Visually Checked	25
Heat Detector	Visually Checked	23
Pull Station	Visually Checked	37
Smoke Detector	Visually Checked	131
Total		222
Grand Total		227






Auxiliary Functions Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Scofield School			Control Panel: 1 - EST EST-2	
<i>The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.</i>				
Type	Location	Comment	ScanID	Simulated
Passed				
Damper Control				
	Parking Gym Fitness	Passed	04061617	<input type="checkbox"/>
Heat Detector				
Shunt Trip	Basement B15 Elevator Machine Rm	Passed	20666612	
Shunt Trip	Basement b51 elevator machine room	Passed	51385725	
Smoke Detector				
Elevator Recall	Basement Elevator Lobby by Stair A	Passed	20666610	
Elevator Recall	Basement Lobby Elevator By B15 Elevator Machine	Passed	20666611	
Elevator Recall	Basement B15 Elevator Machine Rm	Passed	20666613	
Elevator Recall	Basement B51 elevator machine room	Passed	51385724	
Elevator Recall	1st Lobby Elevator By Music	Passed	20666609	
Elevator Recall	1st Lobby Elevator	Passed	20666607	
Elevator Recall	1st Lobby Elevator	Passed	20666608	
Elevator Recall	2nd East Elevator Lobby By Stair E	Passed	20667066	
Elevator Recall	2nd Main Entrance Elevator Lobby By Stair A	Passed	20667067	
Elevator Recall	2nd West Elevator Lobby By Stair B	Passed	20667065	

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Scofield School							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		 dB	 dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
Whole Facility				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Scofield School				Control Panel: 1 - EST EST-2			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	1st Office Copy Rm (FACP)	18AH	12V	13.12V	12Ah		
Sealed Lead Acid	1st Office Copy Rm Bottom Set	12AH	12V	12.75V	11Ah		
Failed/Other							
Battery							
Sealed Lead Acid	1st Office Copy Rm Top Left Set	8AH	12V	11.63V	flat		
Sealed Lead Acid	1st Office Copy Rm Top Right Set	8AH	12V	flat			
Sealed Lead Acid	1st Storage Room 156A	12AH	12V	12.71V	7.4Ah		
Sealed Lead Acid	2nd Electrical Room 221B By Elevator	12AH	12V	flat			
Sealed Lead Acid	2nd Electrical Room 245A	8AH	12V	12.82V	2.6Ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Scofield School				Control Panel: 1 - EST EST-2	
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		0.44%	1
Smoke Detector		Initiating		57.46%	131
Duct Detector		Initiating		10.96%	25
Pull Station		Initiating		16.23%	37
Heat Detector		Initiating		10.09%	23
Battery		Control		3.07%	7
Control Panel		Control		0.44%	1
Annunciator		Control		0.88%	2
Damper Control		Auxiliary		0.44%	1
Type	Qty	Model #	Description		Install Date
In Service - 3 Years to 5 Years					
Universal					
Battery	1	12120	Sealed Lead Acid		02/08/2017
Ultra Tech					
Battery	1	UB1280	Sealed Lead Acid		08/29/2016
Sealec Energy					
Battery	1	12120-F2	Sealed Lead Acid		01/01/2016
Universal					
Battery	1	UB12180	Sealed Lead Acid		01/01/2016
Battery	2	UB1280	Sealed Lead Acid		01/01/2016
In Service - 5 Years to 10 Years					
EST					
Heat Detector	2	SIGA-HRS	Rate-of-Rise		08/10/2012
Pull Station	6	SIGA-278	Dual Action		08/10/2012
Smoke Detector	34	SIGA-PS	Photoelectric		08/10/2012
Annunciator	2		LCD Display		08/06/2012
Control Panel	1	EST-2			08/06/2012
Damper Control	1	SIGA-HRS			08/06/2012
Duct Detector	24	SIGA-PS	Photoelectric		08/06/2012
Duct Detector	1	SIGA-SD	Photoelectric		08/06/2012
Heat Detector	4	283B	Fixed Temperature		08/06/2012
Heat Detector	4	SIGA-HFS	Fixed Temperature		08/06/2012
Heat Detector	13	SIGA-HRS	Rate-of-Rise		08/06/2012
Pull Station	31	SIGA-278	Dual Action		08/06/2012
Smoke Detector	97	SIGA-PS	Photoelectric		08/06/2012
Ultra Tech					

Battery	1	UT 1270	Sealed Lead Acid	07/02/2012
---------	---	---------	------------------	------------

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Scofield School

Control Panel: 1 - EST EST-2

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
0003	Battery	1st Office Copy Rm (FACP)	Sealed Lead Acid	04061663
0101	Duct Detector	2nd Corridor By Room 265 AC 1A Return	Photoelectric	04061540
0102	Duct Detector	2nd Corridor By Room 265 AC1A Supply	Photoelectric	20667059
0103	Smoke Detector	2nd Corridor By Room 266A (Skylight Right Side)	Photoelectric	20667057
0104	Smoke Detector	2nd Corridor By Room 266A (Skylight Left Side)	Photoelectric	20667058
0105	Smoke Detector	2nd Room 264	Photoelectric	04062210
0106	Smoke Detector	2nd Corridor By Room 265	Photoelectric	51385722
0107	Smoke Detector	2nd Corridor By Room 265	Photoelectric	04061538
0108	Smoke Detector	2nd Corridor By Room 262	Photoelectric	04061534
0109	Smoke Detector	2nd Room 265	Photoelectric	04062211
0110	Smoke Detector	2nd Corridor By Room 262	Photoelectric	04061531
0111	Smoke Detector	2nd Corridor By Room 263	Photoelectric	04061536
0112	Smoke Detector	2nd Room 262/263	Photoelectric	04061533
0113	Smoke Detector	2nd Room 262/263	Photoelectric	20667056
0114	Smoke Detector	2nd Room 262/263 Office	Photoelectric	04061532
0115	Smoke Detector	2nd Corridor By Room 262B	Photoelectric	04061529
0116	Smoke Detector	2nd Corridor By Room 260	Photoelectric	04061528
0117	Smoke Detector	2nd Corridor By Room 260	Photoelectric	04061526
0118	Smoke Detector	2nd Room 260	Photoelectric	04061527
0119	Smoke Detector	2nd By Stair F	Photoelectric	04061524
0120	Smoke Detector	2nd By Stair G	Photoelectric	04061522
0121	Smoke Detector	2nd Corridor By Stair F Next To Faculty Toilet	Photoelectric	04061521
0122	Smoke Detector	2nd Room 243	Photoelectric	04061511
0123	Smoke Detector	2nd Corridor By Room 248	Photoelectric	04061513
0124	Smoke Detector	2nd Corridor By Stair E	Photoelectric	04061515
0125	Smoke Detector	2nd Corridor By Room 244	Photoelectric	04061510
0126	Smoke Detector	2nd Corridor By Room 242	Photoelectric	04061509
0127	Smoke Detector	2nd Corridor By Room 240	Photoelectric	04061508
0128	Smoke Detector	2nd Corridor By Room 240A	Photoelectric	04061506
0129	Smoke Detector	2nd Outside Room 240A	Photoelectric	04061507
0130	Smoke Detector	2nd By Room 237	Photoelectric	04061505
0131	Smoke Detector	2nd Corridor Between Stair C and D	Photoelectric	04061500
0132	Smoke Detector	2nd Corridor By Room 232	Photoelectric	04061498
0133	Smoke Detector	2nd Corridor By Room 231	Photoelectric	04061495
0134	Smoke Detector	2nd Room 237	Photoelectric	04061504
0135	Smoke Detector	2nd Room 231A	Photoelectric	04061497
0136	Smoke Detector	2nd Room 231 Science Lab	Photoelectric	04061496
0137	Smoke Detector	2nd Corridor By Room 229	Photoelectric	04061494
0138	Smoke Detector	2nd Corridor By Room 227	Photoelectric	04061493

0139	Smoke Detector	2nd Corridor By Room 225	Photoelectric	04061490
0140	Smoke Detector	2nd Corridor By Room 266A By Elevator	Photoelectric	04061549
0141	Smoke Detector	2nd Corridor By Room 266A Center	Photoelectric	04061548
0142	Smoke Detector	2nd Corridor By Room 266A	Photoelectric	04061546
0143	Smoke Detector	2nd Room 266A	Photoelectric	04061547
0145	Smoke Detector	2nd Corridor By Stair A	Photoelectric	04061469
0146	Smoke Detector	2nd Corridor By Room 207	Photoelectric	04061474
0147	Smoke Detector	2nd Corridor By Room 209	Photoelectric	04061477
0148	Smoke Detector	2nd Corridor By Room 212	Photoelectric	04061481
0149	Smoke Detector	2nd Corridor By Room 211	Photoelectric	04061480
0150	Smoke Detector	2nd Corridor By Room 210	Photoelectric	04061479
0151	Smoke Detector	2nd Corridor By Fountain	Photoelectric	04061483
0152	Smoke Detector	2nd Corridor By Room 214	Photoelectric	04061482
0153	Smoke Detector	2nd Corridor By Room 219A	Photoelectric	04061484
0154	Smoke Detector	2nd Room 205 Science Lab	Photoelectric	04061470
0155	Smoke Detector	2nd Room 205A Left	Photoelectric	04061471
0156	Smoke Detector	2nd Room 206 Science Lab	Photoelectric	04061473
0157	Smoke Detector	2nd West Elevator Lobby By Stair B	Photoelectric	20667065
0158	Heat Detector	2nd Corridor 225B	Rate-of-Rise	04061488
0159	Smoke Detector	2nd Corridor By Room 222	Photoelectric	04061489
0160	Heat Detector	2nd Room 247A	Rate-of-Rise	04062209
0161	Smoke Detector	2nd East Elevator Lobby By Stair E	Photoelectric	20667066
0162	Duct Detector	2nd Corridor By Room 206 AC 2A-Supply	Photoelectric	04061475
0163	Duct Detector	2nd Corridor By Room 206 AC 2A-Return	Photoelectric	04061476
0164	Duct Detector	2nd Corridor By Room 219A Custodial Room AC 3B-Supply	Photoelectric	04061485
0165	Duct Detector	2nd Corridor By Room 219A Custodial Room AC 3B-Return	Photoelectric	20667064
0166	Duct Detector	2nd Corridor By Room 263 AC 1B Return	Photoelectric	04061535
0167	Duct Detector	2nd Corridor By Room 263 AC 1B Supply	Photoelectric	04061537
0168	Duct Detector	2nd Corridor Room 265 AC 6 Supply	Photoelectric	04061539
0169	Duct Detector	2nd Room 264 AC 6 Return	Photoelectric	20667060
0170	Duct Detector	2nd Corridor by Womens Room AC5B Supply	Photoelectric	04061519
0171	Smoke Detector	2nd Room 243A	Photoelectric	04061512
0172	Smoke Detector	2nd Room 265 Rear	Photoelectric	04062212
0173	Duct Detector	2nd Corridor By Room 209 AC 3A-Supply	Photoelectric	51385723
0174	Duct Detector	2nd Room 222 AC2A Supply	Photoelectric	20667061
0175	Duct Detector	2nd Room 222 AC2A Return	Photoelectric	20667062
0176	Duct Detector	2nd Corridor By Room 206 AC 3A-Return	Photoelectric	20667063
0177	Duct Detector	2nd Room 248 AC5A Return	Photoelectric	04061518
0178	Duct Detector	2nd Corridor By Room 234 AC4B Supply	Photoelectric	04061503
0179	Duct Detector	2nd Womens AC5B Return	Photoelectric	04061520
0180	Duct Detector	2nd Corridor Room 248 AC5A Supply	Photoelectric	04061514
0180	Duct Detector	2nd Corridor By Stair E AC5A Return	Photoelectric	04061517
0182	Duct Detector	2nd Corridor By Room 225 AC4A Supply	Photoelectric	04061492
0185	Smoke Detector	Basement Store Room by Stair A	Photoelectric	04061648
0186	Smoke Detector	Basement Store Room by Stair A	Photoelectric	04061649
0187	Smoke Detector	Basement Stair A	Photoelectric	04061638

0190	Duct Detector	2nd Corridor By Room 234 AC4B Return	Photoelectric	04061499
0191	Duct Detector	2nd Corridor By Room 225 AC4A Return	Photoelectric	56181712
0192	Smoke Detector	2nd Room 205A Right	Photoelectric	04061472
0193	Smoke Detector	2nd Room 262B Electrical	Photoelectric	04061530
0203	Battery	1st Office Copy Rm Top Left Set	Sealed Lead Acid	04061462
0205	Battery	1st Office Copy Rm Top Right Set	Sealed Lead Acid	04061465
0207	Battery	1st Office Copy Rm Bottom Set	Sealed Lead Acid	04061466
0233	Pull Station	2nd Corridor By Stair D	Dual Action	04061501
0236	Pull Station	2nd By Stair F	Dual Action	04061525
0237	Pull Station	2nd By Room 260	Dual Action	04061543
0238	Pull Station	2nd Corridor By Room 265	Dual Action	04061542
0239	Pull Station	2nd By Stair G	Dual Action	04061523
0240	Pull Station	2nd Corridor By Stair A	Dual Action	04061468
0244	Pull Station	2nd Corridor By Stair B	Dual Action	04061486
0245	Pull Station	2nd Corridor By Room 225B	Dual Action	04061487
0263	Pull Station	2nd Corridor By Stair C	Dual Action	04061502
0272	Pull Station	2nd Corridor By Stair E	Dual Action	04061516
0279	Pull Station	Basement Stair A	Dual Action	04061637
0301	Smoke Detector	1st By Stair F	Photoelectric	04061605
0302	Smoke Detector	1st By Stair G	Photoelectric	04061602
0303	Smoke Detector	1st By Stair E	Photoelectric	04061599
0305	Heat Detector	1st Storage Room 156	Rate-of-Rise	04061613
0306	Damper Control	Parking Gym Fitness		04061617
0307	Heat Detector	1st 159c phys Ed office in girls locker room	Rate-of-Rise	04061615
0308	Smoke Detector	1st By Gym Storage 156	Photoelectric	04061611
0309	Heat Detector	1st Storage Room 158	Rate-of-Rise	04061625
0310	Smoke Detector	1st Gym Lobby by room 161 thru entrance 162A	Photoelectric	04061623
0311	Heat Detector	1st Room 161	Rate-of-Rise	04061624
0313	Smoke Detector	1st Office 107	Photoelectric	04061552
0314	Smoke Detector	1st Office 106 Principal	Photoelectric	04061554
0315	Heat Detector	1st Boys Locker Rm 160	Rate-of-Rise	04061619
0316	Heat Detector	1st P.E. Office Rm 160C	Rate-of-Rise	04061621
0317	Smoke Detector	1st By Science Lab	Photoelectric	04061572
0318	Smoke Detector	1st By Science Lab Rm 120	Photoelectric	04061573
0319	Smoke Detector	1st By Science Lab Rm 120	Photoelectric	04061574
0320	Smoke Detector	1st By Rm 127	Photoelectric	04061578
0321	Smoke Detector	1st By Rm 127	Photoelectric	04061579
0322	Smoke Detector	1st By Rm 130	Photoelectric	04061581
0323	Smoke Detector	1st By Stair C	Photoelectric	04061583
0324	Smoke Detector	1st By Back Entrance	Photoelectric	04061586
0325	Smoke Detector	1st By Back Entrance	Photoelectric	04061588
0326	Smoke Detector	1st By Science 139	Photoelectric	04061592
0327	Smoke Detector	1st By Science 139	Photoelectric	04061593
0328	Smoke Detector	1st By Music	Photoelectric	04061597
0329	Smoke Detector	1st By Music	Photoelectric	04061598
0331	Smoke Detector	1st By Rm 143	Photoelectric	04061601
0332	Heat Detector	Basement Cafeteria Mechanical B7	Rate-of-Rise	20666617
0333	Heat Detector	Basement Cafeteria Mechanical B8 Electrical	Rate-of-Rise	20666616
0338	Smoke Detector	1st By Girls Rm By Stair A	Photoelectric	04061557
0339	Smoke Detector	1st By Media Center	Photoelectric	04061558

0340	Smoke Detector	1st By Main office	Photoelectric	04061559
0341	Smoke Detector	1st By Conference Rm	Photoelectric	04061560
0342	Smoke Detector	1st By Guidance	Photoelectric	04061561
0343	Smoke Detector	1st By Guidance	Photoelectric	04061564
0344	Smoke Detector	1st By Nurse	Photoelectric	04061566
0345	Smoke Detector	1st By Water Fountain	Photoelectric	04061568
0346	Smoke Detector	1st By Custodial Rm 113	Photoelectric	04061569
0347	Smoke Detector	1st Lobby	Photoelectric	04061636
0348	Smoke Detector	1st Lobby	Photoelectric	04061632
0349	Smoke Detector	1st Lobby	Photoelectric	04061631
0350	Smoke Detector	1st By Gym Rm 162	Photoelectric	04061630
0351	Smoke Detector	1st By Boys Locker Rm 160	Photoelectric	04061629
0352	Smoke Detector	1st By Boys Locker Rm 160	Photoelectric	04061628
0353	Smoke Detector	1st By Gym	Photoelectric	04061627
0354	Smoke Detector	1st By Rm 155 Maintance	Photoelectric	04061610
0355	Smoke Detector	1st By Rm 148	Photoelectric	04061607
0356	Smoke Detector	1st By Rm 149	Photoelectric	04061606
0357	Duct Detector	Basement Cafeteria Mechanical AC7 Supply	Photoelectric	04061659
0358	Duct Detector	Basement Cafeteria Mechanical AC7 Return	Photoelectric	04061660
0359	Smoke Detector	1st By 139 Science	Photoelectric	04061590
0360	Smoke Detector	1st By 139 Science	Photoelectric	04061591
0361	Smoke Detector	1st Rm 130	Photoelectric	04061580
0362	Smoke Detector	1st Courtyard Lobby	Photoelectric	04061595
0364	Smoke Detector	1st Guidance By Rm 108A	Photoelectric	04061562
0365	Smoke Detector	1st Guidance By Rm 108C	Photoelectric	04061563
0366	Smoke Detector	1st Pupil Services Rm 109	Photoelectric	04061565
0367	Smoke Detector	1st Room 110	Photoelectric	04061567
0368	Smoke Detector	1st In Science Lab Rm 120	Photoelectric	04061575
0369	Smoke Detector	1st Closet In Science Lab Rm 120	Photoelectric	04061576
0370	Smoke Detector	1st In Science Lab Rm 120	Photoelectric	04061577
0371	Heat Detector	1st Room 146B	Rate-of-Rise	20667068
0372	Smoke Detector	1st Office 107	Photoelectric	04061553
0373	Smoke Detector	1st By 139A Science Prep Rm	Photoelectric	04061589
0374	Smoke Detector	1st Office Copy Rm 107B	Photoelectric	04061551
0375	Heat Detector	Basement Cafeteria Kitchen	Rate-of-Rise	04061652
0376	Heat Detector	Basement Cafeteria Kitchen	Rate-of-Rise	04061653
0377	Smoke Detector	Basement Storage Room	Photoelectric	04061645
0378	Smoke Detector	Basement By Rm 2	Photoelectric	04061647
0379	Heat Detector	1st Storage Room 156A	Rate-of-Rise	04061614
0380	Heat Detector	Basement Cafeteria Custodial Rm B22	Rate-of-Rise	04061651
0384	Smoke Detector	Basement Room B57	Photoelectric	04061642
0385	Smoke Detector	Basement Room B58	Photoelectric	04061643
0386	Smoke Detector	Basement Room B58A	Photoelectric	04061644
0387	Smoke Detector	1st Lobby Main Entrance	Photoelectric	04061635
0388	Heat Detector	1st Bathroom Rm 160C boys locker room	Fixed Temperature	04061622
0389	Heat Detector	1st Boys Bathroom	Fixed Temperature	04061620
0390	Heat Detector	1st Gym Fitness Girls Rm	Fixed Temperature	04061618
0391	Heat Detector	1st Gym Bathroom in office 159c	Fixed Temperature	04061616
0407	Pull Station	1st By Stair G	Dual Action	04061603
0408	Pull Station	1st By Rm 155 Maintance	Dual Action	04061608

0411	Pull Station	1st By Science Lab	Dual Action	04061594
0412	Pull Station	1st Back Entrance	Dual Action	04061587
0413	Pull Station	1st Back Entrance	Dual Action	04061585
0418	Pull Station	Basement Cafeteria by Stair F	Dual Action	04061650
0419	Pull Station	Basement Cafeteria by Stair G	Dual Action	04061654
0420	Pull Station	Basement Stair G (below)	Dual Action	04061655
0421	Pull Station	1st By Gym	Dual Action	04061612
0424	Pull Station	1st Lobby Main Entrance	Dual Action	04061633
0425	Pull Station	1st Lobby Main Entrance	Dual Action	04061634
0434	Pull Station	1st Gym	Dual Action	04061626
0436	Pull Station	1st Side Entrance Stair C	Dual Action	04061584
0437	Pull Station	1st Side Entrance Stair D	Dual Action	04061582
0440	Pull Station	1st By Science Lab 120	Dual Action	04062224
0450	Pull Station	1st Stair A	Dual Action	23585840
0451	Battery	1st Storage Room 156A	Sealed Lead Acid	04062214
0452	Pull Station	1st Room 144	Dual Action	04061596
0453	Pull Station	1st Side Entrance By Storage 118	Dual Action	04061570
0456	Pull Station	1st Stair A	Dual Action	04061555
0457	Pull Station	1st Side Entrance Stair B	Dual Action	04061571
0457	Battery	2nd Electrical Room 221B By Elevator	Sealed Lead Acid	04590169
0458	Battery	2nd Electrical Room 245A	Sealed Lead Acid	04062207
0460	Pull Station	1st By Stair E	Dual Action	04061600
0461	Pull Station	Basement Cafeteria by Stair E	Dual Action	04061656
0461	Pull Station	Basement Stair E	Dual Action	04061657
0470	Heat Detector	Basement Boiler Room B55	Fixed Temperature	04061639
0471	Heat Detector	Basement Boiler Room B55	Fixed Temperature	04061640
0474	Pull Station	Basement Passage Way	Dual Action	04061646
0483	Pull Station	1st In Stair G	Dual Action	04061604
0486	Pull Station	Basement Boiler Room B55	Dual Action	04061641

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Rippowam Center
381 High Ridge Road
Stamford, CT 06904

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Mar 27, 2020



Building: Stamford BOE-Rippowam Center
Contact: Davor Lucaj
Title: Facilities Trades Manager

Company: TPC Associates, Inc.
Contact: Michael Hernandez
Title: Fire Alarm Inspector

Executive Summary





Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Rippowam Center	Contact: Davor Lucaj	
Address: 381 High Ridge Road	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06904	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Michael Hernandez	
Address: 261 Pepe's Farm Road	Phone: 203-878-1321	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: mhernandez@tpcsystems.com	
System Control Unit		
Manufacturer: EST	Inspection Date: 03/27/2020	IDC Style:
Model Number: EST-3	Install Date: 08/16/2019	SLC Style:
Software Version:	Version Date: 08/16/2019	NAC Style:
Location: 1st Hallway Outside Stair 5	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.60%	0	0%	0	0%	0	0%
Control	20	12.05%	20	100.00%	19	95.00%	1	5.00%
Initiating	145	87.35%	145	100.00%	145	100.00%	0	0%
Totals	166	100%	165	99.40%	164	99.39%	1	0.61%
Certification								
Company: TPC Associates, Inc.			Building: Stamford BOE-Rippowam Center					
Inspector: Michael Hernandez			Contact: Davor Lucaj					
								
Signed: Mar 27, 2020 2:23:18 PM			Signed: Mar 27, 2020 2:23:26 PM					
Michael Hernandez Certifications								
Certification Type					Number			
Inspectors Boot Camp								

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-Rippowam Center			Control Panel: 1 - EST EST-3	
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
 ScanID	 Location	 Problem	Address	 Reference
<i>Control</i>				
Battery				
04060734	1st Booster 2 Storage Room Beside Panel	Failed Test	1	NFPA 72 Table 10.4.2.2.5(a-e)

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-Rippowam Center			Control Panel: 1 - EST EST-3		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
Control					
Battery					
04060734	1st Booster 2 Storage Room Beside Panel	Replace		T/M	<input type="checkbox"/>
PO #: (none)				T/M	

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Rippowam Center		Control Panel: 1 - EST EST-3		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Battery	1st Amp 1 Storage Room Beside Panel	Tested	12:50:22 PM	03/27/2020
Battery	1st Amp 2 Storage Room Beside Panel	Tested	12:52:48 PM	03/27/2020
Battery	1st Booster 1 Storage Room Beside Panel	Tested	12:36:54 PM	03/27/2020
Battery	1st Booster 3 Storage Room Beside Panel	Tested	12:43:07 PM	03/27/2020
Battery	1st Booster 4 Storage Room Beside Panel	Tested	12:45:35 PM	03/27/2020
Battery	1st Booster 5 Storage Room Beside Panel	Tested	12:41:35 PM	03/27/2020
Battery	1st Booster 6 Storage Room Beside Panel	Tested	12:46:46 PM	03/27/2020
Battery	1st Booster 7 Storage Room Beside Panel	Tested	12:40:10 PM	03/27/2020
Battery	1st Booster 8 Storage Room Beside Panel	Tested	12:44:37 PM	03/27/2020
Battery	1st Hallway Outside Stair 5 Inside Control Panel	Tested	12:54:39 PM	03/27/2020
Control Panel	1st Hallway Outside Stair 5	Tested	2:04:38 PM	03/27/2020
Power Supply	1st Booster 1 Storage Room Beside Panel	Tested	12:36:48 PM	03/27/2020
Power Supply	1st Booster 2 Storage Room Beside Panel	Tested	12:49:54 PM	03/27/2020
Power Supply	1st Booster 3 Storage Room Beside Panel	Tested	12:43:05 PM	03/27/2020
Power Supply	1st Booster 4 Storage Room Beside Panel	Tested	12:45:33 PM	03/27/2020
Power Supply	1st Booster 5 Storage Room Beside Panel	Tested	12:41:31 PM	03/27/2020
Power Supply	1st Booster 6 Storage Room Beside Panel	Tested	12:46:41 PM	03/27/2020
Power Supply	1st Booster 7 Storage Room Beside Panel	Tested	12:40:06 PM	03/27/2020
Power Supply	1st Booster 8 Storage Room Beside Panel	Tested	12:44:34 PM	03/27/2020
Initiating				
Beam Detector	1st BEAM DETECTORS AUDITORIUM	Tested	2:04:33 PM	03/27/2020
Heat Detector	Basement HEATS BOILER RM	visually Checked	2:05:10 PM	03/27/2020
Heat Detector	1st AUDITORIUM SPARE	visually Checked	2:05:50 PM	03/27/2020
Heat Detector	Mezzanine HEAT AUD MECH RM STORAGE	visually Checked	2:05:54 PM	03/27/2020
Heat Detector	Mezzanine HEAT AUDITORIUM COSTUME STORAGE	visually Checked	2:04:48 PM	03/27/2020
Heat Detector	Mezzanine HEAT AUDITORIUM MECH ROOM	visually Checked	2:04:44 PM	03/27/2020
Heat Detector	Mezzanine HEAT SPOT LIGHT RM AUDITORIUM/MECH RM	visually Checked	2:05:45 PM	03/27/2020
Pull Station	Basement PULL BASEMENT AUD NORTH SIDE	Visually Checked	2:06:31 PM	03/27/2020
Pull Station	Basement PULL BASEMENT AUD SOUTH SIDE	Visually Checked	2:06:35 PM	03/27/2020
Pull Station	Basement PULL BASEMENT COMPUTER LAB	Visually Checked	2:10:07 PM	03/27/2020
Pull Station	Basement PULL BASEMENT COMPUTER OFFICE EXIT	Visually Checked	2:06:46 PM	03/27/2020
Pull Station	Basement PULL BASEMENT CORRIDOR	Visually Checked	2:10:11 PM	03/27/2020
Pull Station	Basement PULL BOILER ROOM EXIT	Visually Checked	2:10:29 PM	03/27/2020
Pull Station	Basement PULL BSMNT PLUMBING-ELEC MAINT.SHOP	Visually Checked	2:06:42 PM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	Basement PULL BSMNT WOOD SHOP	Visually Checked	2:06:38 PM	03/27/2020
Pull Station	1st PULL AUDITORIUM CONTROL ROOM	Visually Checked	2:10:04 PM	03/27/2020
Pull Station	1st PULL AUDITORIUM CORR NORTH SIDE	Visually Checked	2:06:02 PM	03/27/2020
Pull Station	1st PULL AUDITORIUM CORR SOUTH SIDE	Visually Checked	2:06:05 PM	03/27/2020
Pull Station	1st PULL AUDITORIUM LOBBY NORTH SIDE	Visually Checked	1:41:19 PM	03/27/2020
Pull Station	1st PULL AUDITORIUM LOBBY SOUTH SIDE	Visually Checked	1:42:08 PM	03/27/2020
Pull Station	1st PULL CAFE LOADING DOCK	Visually Checked	2:07:56 PM	03/27/2020
Pull Station	1st PULL EAST CAFE	Visually Checked	2:07:45 PM	03/27/2020
Pull Station	1st PULL EAST CAFE	Visually Checked	2:07:49 PM	03/27/2020
Pull Station	1st PULL EAST CAFE	Visually Checked	2:07:52 PM	03/27/2020
Pull Station	1st PULL EAST GYM ENTRANCE	Visually Checked	2:09:46 PM	03/27/2020
Pull Station	1st PULL FIRST FLOOR CORR BY STAIR # 1	Visually Checked	1:39:21 PM	03/27/2020
Pull Station	1st PULL FIRST FLOOR CORR BY STAIR # 2	Visually Checked	2:09:21 PM	03/27/2020
Pull Station	1st PULL FIRST FLOOR CORR BY STAIR # 3	Visually Checked	2:08:30 PM	03/27/2020
Pull Station	1st PULL FIRST FLOOR CORR BY STAIR # 4	Visually Checked	1:40:36 PM	03/27/2020
Pull Station	1st PULL FIRST FLOOR CORR BY STAIR # 6	Visually Checked	2:07:22 PM	03/27/2020
Pull Station	1st PULL FIRST FLOOR EAST CORR TO GYM	Visually Checked	2:10:00 PM	03/27/2020
Pull Station	1st PULL FIRST FLOOR IN STAIR # 3	Visually Checked	2:08:33 PM	03/27/2020
Pull Station	1st PULL FIRST FLOOR IN STAIR # 4	Visually Checked	1:40:49 PM	03/27/2020
Pull Station	1st PULL FIRST FLOOR IN STAIR # 5	Visually Checked	2:08:05 PM	03/27/2020
Pull Station	1st PULL FIRST FLOOR IN STAIR # 6	Visually Checked	2:07:42 PM	03/27/2020
Pull Station	1st PULL FIRST FLOOR STAIR # 5 CORR	Visually Checked	2:05:59 PM	03/27/2020
Pull Station	1st PULL HOME TEAM LOCKER ROOM	Visually Checked	2:09:57 PM	03/27/2020
Pull Station	1st PULL NORTH/EAST GYM ENTRANCE	Visually Checked	2:09:42 PM	03/27/2020
Pull Station	1st PULL NORTH/WEST GYM ENTRANCE	Visually Checked	2:09:39 PM	03/27/2020
Pull Station	1st PULL NORTHWEST ENTRANCE	Visually Checked	2:10:40 PM	03/27/2020
Pull Station	1st PULL STAGE NORTH	Visually Checked	2:06:56 PM	03/27/2020
Pull Station	1st PULL STAGE SOUTH	Visually Checked	2:06:53 PM	03/27/2020
Pull Station	1st PULL VISITING TEAM LOCKER ROOM	Visually Checked	2:09:50 PM	03/27/2020
Pull Station	1st PULL WEST CAFE	Visually Checked	2:07:59 PM	03/27/2020
Pull Station	1st PULL WEST GYM ENTRANCE	Visually Checked	2:09:25 PM	03/27/2020
Pull Station	2nd PULL 2ND FLOOR BY STAIR #5	Visually Checked	1:09:30 PM	03/27/2020
Pull Station	2nd PULL 2ND FLOOR BY STAIR #6	Visually Checked	1:07:14 PM	03/27/2020
Pull Station	2nd PULL 2ND FLOOR STAIR # 3	Visually Checked	1:15:04 PM	03/27/2020
Pull Station	2nd PULL 2ND FLOOR STAIR # 4	Visually Checked	1:20:40 PM	03/27/2020
Pull Station	2nd PULL SECOND FLOOR BY STAIR # 1	Visually Checked	1:18:04 PM	03/27/2020
Pull Station	2nd PULL SECOND FLOOR BY STAIR # 2	Visually Checked	1:16:24 PM	03/27/2020
Pull Station	Mezzanine PULL AUDITORIUM MECH NORTH EXIT	Visually Checked	2:06:19 PM	03/27/2020
Pull Station	Mezzanine PULL AUDITORIUM MECH SOUTH EXIT	Visually Checked	2:06:09 PM	03/27/2020
Pull Station	PULL FIRST FLOOR IN STAIR # 2	Visually Checked	2:10:36 PM	03/27/2020
Pull Station	PULL FIRST FLOOR WEST CORR TO GYM	Visually Checked	2:10:33 PM	03/27/2020
Pull Station	PULL WEST CAFE	Visually Checked	2:10:25 PM	03/27/2020
Remote Test Switch	Mezzanine DUCT SMOKE TEST SWITCH UV # 24	Tested	2:10:55 PM	03/27/2020
Remote Test Switch	Mezzanine DUCT SMOKE TEST SWITCH UV # 25	Tested	2:10:59 PM	03/27/2020
Remote Test Switch	Mezzanine DUCT SMOKE TEST SWITCH UV # 26	Tested	2:10:44 PM	03/27/2020
Remote Test Switch	Mezzanine DUCT SMOKE TEST SWITCH UV # 27	Tested	2:10:48 PM	03/27/2020
Remote Test Switch	Mezzanine DUCT SMOKE TEST SWITCH UV # 28	Tested	2:10:52 PM	03/27/2020
Smoke Detector	Basement SMOKE BSMNT UV MECH RM	Visually Checked	2:02:15 PM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Basement SMOKE ELECTRIC RM BASEMENT	Visually Checked	2:01:59 PM	03/27/2020
Smoke Detector	Basement SMOKE ELEVATOR RECALL BOTTOM SHAFT	Visually Checked	2:04:17 PM	03/27/2020
Smoke Detector	Basement SMOKE ELEVATOR RECALL MACHINE RM	Visually Checked	2:01:43 PM	03/27/2020
Smoke Detector	Basement SMOKE GENERATOR RM BASEMENT	Visually Checked	2:01:39 PM	03/27/2020
Smoke Detector	Basement SMOKE STORAGE RM BASEMENT	Visually Checked	2:02:12 PM	03/27/2020
Smoke Detector	1st DUCT SMOKE TEST SWITCH GUIDANCE	Visually Checked	2:04:13 PM	03/27/2020
Smoke Detector	1st DUCT SMOKE UNIT GUIDANCE	Visually Checked	2:02:45 PM	03/27/2020
Smoke Detector	1st SMOKE 1 AUDITORIUM MECH ROOM	Visually Checked	1:58:39 PM	03/27/2020
Smoke Detector	1st SMOKE AUDITORIUM CONTROL ROOM	Visually Checked	1:46:14 PM	03/27/2020
Smoke Detector	1st SMOKE FIRST FLOOR IN STAIR # 1	Visually Checked	1:39:15 PM	03/27/2020
Smoke Detector	1st SMOKE FIRST FLOOR IN STAIR # 3	Visually Checked	1:59:18 PM	03/27/2020
Smoke Detector	1st SMOKE FIRST FLOOR IN STAIR # 4	Visually Checked	1:40:41 PM	03/27/2020
Smoke Detector	1st SMOKE FIRST FLOOR IN STAIR # 5	Visually Checked	1:59:15 PM	03/27/2020
Smoke Detector	1st SMOKE FIRST FLOOR IN STAIR # 6	Visually Checked	1:59:11 PM	03/27/2020
Smoke Detector	1st SMOKE MAIN OFFICE	Visually Checked	2:01:01 PM	03/27/2020
Smoke Detector	1st SMOKE MAIN OFFICE	Visually Checked	2:01:05 PM	03/27/2020
Smoke Detector	2nd SMOKE ROOM # 210 ELEC CLOSET	Visually Checked	2:01:47 PM	03/27/2020
Smoke Detector	2nd SMOKE ROOM # 210 STORAGE	Visually Checked	1:46:03 PM	03/27/2020
Smoke Detector	2nd SMOKE ROOM # 228	Visually Checked	1:46:11 PM	03/27/2020
Smoke Detector	2nd SMOKE ROOM # 230	Visually Checked	1:46:07 PM	03/27/2020
Smoke Detector	2nd SMOKE ROOM # 233	Visually Checked	1:45:59 PM	03/27/2020
Smoke Detector	2nd SMOKE ROOM # 234	Visually Checked	1:45:56 PM	03/27/2020
Smoke Detector	2nd SMOKE ROOM # 235	Visually Checked	1:45:38 PM	03/27/2020
Smoke Detector	2nd SMOKE ROOM # 235	Visually Checked	1:45:42 PM	03/27/2020
Smoke Detector	2nd SMOKE ROOM # 237	Visually Checked	1:45:49 PM	03/27/2020
Smoke Detector	2nd SMOKE ROOM # 237	Visually Checked	1:45:53 PM	03/27/2020
Smoke Detector	2nd SMOKE SCIENCE STORGE BY ROOM # 237	Visually Checked	1:45:45 PM	03/27/2020
Smoke Detector	2nd SMOKE SECOND FLOOR ELEVATOR RECALL	Visually Checked	1:20:18 PM	03/27/2020
Smoke Detector	2nd SMOKE SECOND FLOOR IN STAIR # 1	Visually Checked	1:18:11 PM	03/27/2020
Smoke Detector	2nd SMOKE SECOND FLOOR IN STAIR # 2	Visually Checked	1:16:31 PM	03/27/2020
Smoke Detector	2nd SMOKE SECOND FLOOR IN STAIR # 3	Visually Checked	1:15:11 PM	03/27/2020
Smoke Detector	2nd SMOKE SECOND FLOOR IN STAIR # 6	Visually Checked	1:07:21 PM	03/27/2020
Smoke Detector	3rd SMOKE ELEVATOR RECALL TOP OF SHAFT	Visually Checked	2:04:21 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 10 GYM MECH RM	Visually Checked	2:01:19 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 11 GYM MECH RM	Visually Checked	2:00:28 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 12 GYM MECH RM	Visually Checked	2:00:38 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 13 GYM MECH RM	Visually Checked	2:00:53 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 17	Visually Checked	2:02:56 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 18	Visually Checked	2:02:49 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 24	Visually Checked	2:03:41 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 25 AUDITORIUM	Visually Checked	1:58:47 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 26 AUDITORIUM	Visually Checked	1:46:21 PM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 27 AUDITORIUM	Visually Checked	1:46:31 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 9 GYM MECH RM	Visually Checked	2:00:09 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 1 UV # 26 AUDITORIUM	Visually Checked	1:46:25 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 1 UV # 28 AUDITORIUM	Visually Checked	1:46:18 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 2 UV # 26 AUDITORIUM	Visually Checked	1:46:28 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 2 UV # 28 AUDITORIUM	Visually Checked	1:46:35 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 3 UV # 28 AUDITORIUM	Visually Checked	1:46:39 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 4 UV # 28 AUDITORIUM	Visually Checked	1:46:50 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 5 UV # 28 AUDITORIUM	Visually Checked	2:01:30 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 10 GYM MECH RM	Visually Checked	1:59:49 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 11 GYM MECH RM	Visually Checked	2:00:32 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 12 GYM MECH RM	Visually Checked	2:01:15 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 13 GYM MECH RM	Visually Checked	2:00:57 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 17	Visually Checked	2:02:06 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 18	Visually Checked	2:03:00 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 24	Visually Checked	1:58:51 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 24	Visually Checked	1:58:55 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 24 AUDITORIUM	Visually Checked	2:01:12 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 25 AUDITORIUM	Visually Checked	1:58:43 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 27 AUDITORIUM	Visually Checked	1:46:54 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 28	Visually Checked	1:46:45 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 9 GYM MECH RM	Visually Checked	2:00:13 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV # 18	Visually Checked	2:03:58 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV # 9	Visually Checked	1:59:45 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV #10	Visually Checked	1:59:41 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV #11	Visually Checked	1:59:37 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV #12	Visually Checked	1:59:29 PM	03/27/2020
Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV #13	Visually Checked	1:59:25 PM	03/27/2020
Smoke Detector	Mezzanine SMOKE 2 AUDITORIUM MECH ROOM	Visually Checked	2:02:52 PM	03/27/2020
Smoke Detector	Mezzanine SMOKE 3 AUDITORIUM MECH ROOM	Visually Checked	2:01:55 PM	03/27/2020
Smoke Detector	Mezzanine SMOKE 5 AUDITORIUM MECH ROOM	Visually Checked	1:47:07 PM	03/27/2020
Smoke Detector	Mezzanine SMOKE 5 AUDITORIUM MECH ROOM	Visually Checked	2:04:26 PM	03/27/2020
Smoke Detector	Mezzanine SMOKE AUDITORIUM MECH NORTH	Visually Checked	2:02:02 PM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	STAIR Mezzanine SMOKE AUDITORIUM MECH RM OVER UV # 25	Visually Checked	1:59:08 PM	03/27/2020
Smoke Detector	Mezzanine SMOKE AUDITORIUM MECH SOUTH STAIR	Visually Checked	2:01:22 PM	03/27/2020
Smoke Detector	ANSUL SYSTEM TRIP KITCHEN	Visually Checked	2:03:53 PM	03/27/2020
Smoke Detector	DUCT SMOKE TEST SWITCH UV # 17	Visually Checked	2:04:05 PM	03/27/2020
Smoke Detector	SMOKE FIRST FLOOR ELEVATOR RECALL	Visually Checked	2:01:51 PM	03/27/2020
Smoke Detector	SMOKE FIRST FLOOR IN STAIR # 2	Visually Checked	1:59:22 PM	03/27/2020
Smoke Detector	SMOKE ROOM # 227	Visually Checked	2:01:26 PM	03/27/2020
Smoke Detector	SMOKE SECOND FLOOR IN STAIR # 5	Visually Checked	2:03:06 PM	03/27/2020
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	1st Booster 2 Storage Room Beside Panel	Tested	12:39:28 PM	03/27/2020

Service Summary

Generated by: BuildingReports.com

Building: Stamford BOE-Rippowam Center

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Failed/Other</i>		
Battery	Tested	1
Total		1
<i>Passed</i>		
Battery	Tested	10
Beam Detector	Tested	1
Control Panel	Tested	1
Heat Detector	visually Checked	6
Power Supply	Tested	8
Pull Station	Visually Checked	49
Remote Test Switch	Tested	5
Smoke Detector	Visually Checked	84
Total		164
Grand Total		165




Auxiliary Functions Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Rippowam Center			Control Panel: 1 - EST EST-3	
<i>The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.</i>				
Type	Location	Comment	ScanID	Simulated
<i>Passed</i>				
Smoke Detector				
Elevator Recall	Basement SMOKE ELEVATOR RECALL BOTTOM SHAFT	Passed	56177907	

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Rippowam Center							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		◀ dB	◀ dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
Whole Facility				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Rippowam Center				Control Panel: 1 - EST EST-3			
The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	1st Amp 1 Storage Room Beside Panel	12Ah	12V	12.76V	11Ah		
Sealed Lead Acid	1st Amp 2 Storage Room Beside Panel	12Ah	12V	12.75V	8Ah		
Sealed Lead Acid	1st Booster 1 Storage Room Beside Panel	7Ah	12V	12.85v	7.2ah170		
Sealed Lead Acid	1st Booster 3 Storage Room Beside Panel	7Ah	12V	12.60V	5.8Ah		
	1st Booster 4 Storage Room Beside Panel	7Ah	12V	12.43V	5.4Ah		
Sealed Lead Acid	1st Booster 5 Storage Room Beside Panel	7Ah	12V	12.43V	6.4Ah		
	1st Booster 6 Storage Room Beside Panel	7Ah	12V	12.79V	5.8Ah		
Sealed Lead Acid	1st Booster 7 Storage Room Beside Panel	7Ah	12V	12.84v	5.8ah		
	1st Booster 8 Storage Room Beside Panel	7Ah	12V	12.85V	6.4Ah		
Sealed Lead Acid	1st Hallway Outside Stair 5 Inside Control Panel	12Ah	12V	12.72V	11Ah		
Failed/Other							
Battery							
Sealed Lead Acid	1st Booster 2 Storage Room Beside Panel	7Ah	12V	12.76v	4.1ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Rippowam Center			Control Panel: 1 - EST EST-3		
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		0.60%	1
Power Supply		Control		4.82%	8
Battery		Control		6.63%	11
Pull Station		Initiating		29.52%	49
Smoke Detector		Initiating		50.60%	84
Beam Detector		Initiating		0.60%	1
Control Panel		Control		0.60%	1
Heat Detector		Initiating		3.61%	6
Remote Test Switch		Initiating		3.01%	5
Type	Qty	Model #	Description		Install Date
In Service - 90 Days - 1 Year					
EST					
Smoke Detector	1	DTS			08/20/2019
Beam Detector	1	CT1			08/16/2019
Control Panel	1	EST-3			08/16/2019
Heat Detector	3	CT1			08/16/2019
Heat Detector	2	CT2			08/16/2019
Heat Detector	1	HFS			08/16/2019
Power Supply	8				08/16/2019
Pull Station	46	278			08/16/2019
Remote Test Switch	4	DTS			08/16/2019
Smoke Detector	7	DTS			08/16/2019
Smoke Detector	72	PS			08/16/2019
Smoke Detector	1	SD			08/16/2019
Power-Sonic					
Battery	1	PS-12120	Sealed Lead Acid		08/16/2019
Battery	1	PS-12120 F2	Sealed Lead Acid		08/16/2019
Ultra Tech					
Battery	1		Sealed Lead Acid		08/16/2019
Battery	1	UT 12120	Sealed Lead Acid		08/16/2019
Universal battery					
Battery	3		Sealed Lead Acid		08/16/2019
Battery	3	UB1280			08/16/2019
In Service - 2 Years to 3 Years					
Universal battery					

Battery	1	Sealed Lead Acid	09/16/2017
<i>In Service - 25 Years or Older</i>			
EST			
Pull Station	3	278	12/31/1969
Remote Test Switch	1	DTS	12/31/1969
Smoke Detector	1	CT1	12/31/1969
Smoke Detector	2	PS	12/31/1969

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Rippowam Center			Control Panel: 1 - EST EST-3	
<i>The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.</i>				
Address	Device Type	Location	Type	ScanID
Zone/Circuit: 03				
0001	Smoke Detector	2nd SMOKE SECOND FLOOR IN STAIR # 1		04060618
0002	Smoke Detector	2nd SMOKE SECOND FLOOR IN STAIR # 2		04060616
0003	Smoke Detector	2nd SMOKE SECOND FLOOR IN STAIR # 3		04060614
0004	Smoke Detector	1st SMOKE AUDITORIUM CONTROL ROOM		04060632
0005	Smoke Detector	1st SMOKE MAIN OFFICE		04060724
0006	Smoke Detector	1st SMOKE MAIN OFFICE		04060725
0007	Smoke Detector	1st SMOKE 1 AUDITORIUM MECH ROOM		04060655
0008	Smoke Detector	Mezzanine SMOKE 2 AUDITORIUM MECH ROOM		3993444929
0009	Smoke Detector	Mezzanine SMOKE 3 AUDITORIUM MECH ROOM		3993344205
0010	Heat Detector	Mezzanine HEAT AUD MECH RM STORAGE		56177911
0011	Smoke Detector	Mezzanine SMOKE AUDITORIUM MECH SOUTH STAIR		3993249999
0012	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 1 UV # 28 AUDITORIUM		04060642
0013	Smoke Detector	Mezzanine SMOKE AUDITORIUM MECH NORTH STAIR		3993346070
0014	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 28		04060650
0015	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 2 UV # 28 AUDITORIUM		04060648
0016	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 25 AUDITORIUM		04060657
0017	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 4 UV # 28 AUDITORIUM		04060651
0018	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 5 UV # 28 AUDITORIUM		3993283719
0019	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 27 AUDITORIUM		04060652
0020	Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 27 AUDITORIUM		04060647
0021	Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 26 AUDITORIUM		04060644
0022	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 1 UV # 26 AUDITORIUM		04060645
0023	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 2 UV # 26 AUDITORIUM		04060646
0024	Smoke Detector	Mezzanine SMOKE 5 AUDITORIUM MECH		04060654

		ROOM	
0024	Smoke Detector	Mezzanine SMOKE 5 AUDITORIUM MECH ROOM	56177910
0025	Smoke Detector	Mezzanine SMOKE AUDITORIUM MECH RM OVER UV # 25	04060665
0026	Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 25 AUDITORIUM	04060658
0027	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 24 AUDITORIUM	17014417
0028	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY 3 UV # 28 AUDITORIUM	04060649
0029	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 24	04060659
0030	Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 24	3993547613
0031	Smoke Detector	SMOKE FIRST FLOOR IN STAIR # 2	04060694
0032	Smoke Detector	1st SMOKE FIRST FLOOR IN STAIR # 1	04060719
0033	Smoke Detector	1st SMOKE FIRST FLOOR IN STAIR # 6	04060676
0034	Smoke Detector	1st DUCT SMOKE UNIT GUIDANCE	3993417800
0035	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 24	04060660
0036	Smoke Detector	1st SMOKE FIRST FLOOR IN STAIR # 4	04060721
0037	Smoke Detector	1st SMOKE FIRST FLOOR IN STAIR # 3	04060691
0038	Smoke Detector	SMOKE FIRST FLOOR ELEVATOR RECALL	3993343840
0039	Smoke Detector	2nd SMOKE SECOND FLOOR ELEVATOR RECALL	56177913
0040	Smoke Detector	3rd SMOKE ELEVATOR RECALL TOP OF SHAFT	56177908
0041	Smoke Detector	Basement SMOKE ELEVATOR RECALL BOTTOM SHAFT	56177907
0042	Smoke Detector	Basement SMOKE ELEVATOR RECALL MACHINE RM	3993300911
0131	Pull Station	1st PULL FIRST FLOOR CORR BY STAIR # 3	04060689
0132	Pull Station	1st PULL FIRST FLOOR IN STAIR # 3	04060690
0133	Pull Station	1st PULL FIRST FLOOR CORR BY STAIR # 2	04060692
0134	Pull Station	PULL FIRST FLOOR IN STAIR # 2	4899168162
0135	Pull Station	1st PULL FIRST FLOOR CORR BY STAIR # 6	04060675
0136	Pull Station	2nd PULL SECOND FLOOR BY STAIR # 1	04060617
0137	Pull Station	2nd PULL SECOND FLOOR BY STAIR # 2	04060615
0138	Pull Station	1st PULL AUDITORIUM LOBBY SOUTH SIDE	04060672
0139	Pull Station	1st PULL AUDITORIUM LOBBY NORTH SIDE	04060629
0140	Pull Station	1st PULL AUDITORIUM CORR NORTH SIDE	04060630
0141	Pull Station	1st PULL AUDITORIUM CORR SOUTH SIDE	04060631
0142	Pull Station	1st PULL STAGE NORTH	04060674
0143	Pull Station	1st PULL STAGE SOUTH	04060673
0144	Pull Station	Basement PULL BASEMENT AUD NORTH SIDE	04060666
0145	Pull Station	Basement PULL BASEMENT AUD SOUTH SIDE	04060667

0146	Pull Station	Basement PULL BSMNT PLUMBING-ELEC MAINT.SHOP	04060669
0147	Pull Station	Basement PULL BSMNT WOOD SHOP	04060668
0148	Pull Station	Basement PULL BASEMENT COMPUTER LAB	4899114701
0149	Pull Station	Basement PULL BASEMENT COMPUTER OFFICE EXIT	04060670
0150	Pull Station	1st PULL AUDITORIUM CONTROL ROOM	17014414
0153	Pull Station	1st PULL EAST CAFE	04060678
0154	Pull Station	Mezzanine PULL AUDITORIUM MECH SOUTH EXIT	04060635
0155	Remote Test Switch	Mezzanine DUCT SMOKE TEST SWITCH UV # 28	04060639
0156	Remote Test Switch	Mezzanine DUCT SMOKE TEST SWITCH UV # 27	04060638
0157	Remote Test Switch	Mezzanine DUCT SMOKE TEST SWITCH UV # 26	04060637
0158	Heat Detector	Mezzanine HEAT SPOT LIGHT RM AUDITORIUM/MECH RM	4958004226
0159	Heat Detector	1st AUDITORIUM SPARE	4958004233
0160	Heat Detector	Mezzanine HEAT AUDITORIUM MECH ROOM	04060663
0161	Heat Detector	Mezzanine HEAT AUDITORIUM COSTUME STORAGE	17014416
0162	Pull Station	Mezzanine PULL AUDITORIUM MECH NORTH EXIT	04060656
0169	Pull Station	1st PULL EAST CAFE	04060680
0170	Pull Station	1st PULL EAST CAFE	04060679
0171	Smoke Detector	ANSUL SYSTEM TRIP KITCHEN	4848233699
0178	Pull Station	1st PULL FIRST FLOOR CORR BY STAIR # 1	04060718
0179	Pull Station	1st PULL CAFE LOADING DOCK	04060681
0180	Pull Station	2nd PULL 2ND FLOOR STAIR # 4	04060619
0181	Pull Station	1st PULL WEST CAFE	04060683
0182	Pull Station	1st PULL FIRST FLOOR IN STAIR # 6	04060677
0183	Smoke Detector	1st DUCT SMOKE TEST SWITCH GUIDANCE	4850314898
0184	Pull Station	1st PULL FIRST FLOOR CORR BY STAIR # 4	04060720
0185	Pull Station	1st PULL FIRST FLOOR IN STAIR # 4	04060628
0189	Remote Test Switch	Mezzanine DUCT SMOKE TEST SWITCH UV # 24	04060640
0190	Remote Test Switch	Mezzanine DUCT SMOKE TEST SWITCH UV # 25	04060641
0200	Beam Detector	1st BEAM DETECTORS AUDITORIUM	56177906
0201	Pull Station	2nd PULL 2ND FLOOR STAIR # 3	04060613
0251	Smoke Detector	1st SMOKE FIRST FLOOR IN STAIR # 5	04060685
0252	Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 9 GYM MECH RM	04060705
0253	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 9 GYM MECH RM	04060706
0254	Power Supply	1st Booster 1 Storage Room Beside Panel	17014434
0254	Power Supply	1st Booster 2 Storage Room Beside Panel	17014435

0254	Power Supply	1st Booster 3 Storage Room Beside Panel	17014436
0254	Power Supply	1st Booster 4 Storage Room Beside Panel	17014437
0254	Power Supply	1st Booster 5 Storage Room Beside Panel	17014440
0254	Power Supply	1st Booster 6 Storage Room Beside Panel	17014438
0254	Power Supply	1st Booster 7 Storage Room Beside Panel	17014441
0254	Power Supply	1st Booster 8 Storage Room Beside Panel	17014439
0254	Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 10 GYM MECH RM	3993219107
0255	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 10 GYM MECH RM	04060704
0256	Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 11 GYM MECH RM	04060708
0257	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 11 GYM MECH RM	04060709
0258	Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 12 GYM MECH RM	04060710
0259	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 12 GYM MECH RM	21098547
0260	Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 13 GYM MECH RM	04060711
0261	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 13 GYM MECH RM	04060712
0262	Smoke Detector	SMOKE SECOND FLOOR IN STAIR # 5	3993535214
0263	Smoke Detector	2nd SMOKE SECOND FLOOR IN STAIR # 6	04060627
0264	Smoke Detector	Basement SMOKE GENERATOR RM BASEMENT	3993286901
0265	Smoke Detector	Basement SMOKE ELECTRIC RM BASEMENT	3993346018
0266	Smoke Detector	Basement SMOKE STORAGE RM BASEMENT	3993376404
0267	Smoke Detector	SMOKE ROOM # 227	3993281999
0268	Smoke Detector	2nd SMOKE ROOM # 228	04060624
0269	Smoke Detector	2nd SMOKE ROOM # 230	04060623
0270	Smoke Detector	2nd SMOKE ROOM # 210 STORAGE	04060622
0271	Smoke Detector	2nd SMOKE ROOM # 210 ELEC CLOSET	3993303868
0272	Smoke Detector	2nd SMOKE ROOM # 233	04060621
0273	Smoke Detector	2nd SMOKE ROOM # 234	04060620
0274	Smoke Detector	2nd SMOKE ROOM # 235	04060608
0275	Smoke Detector	2nd SMOKE ROOM # 235	04060609
0276	Smoke Detector	2nd SMOKE SCIENCE STORGE BY ROOM # 237	04060610
0277	Smoke Detector	2nd SMOKE ROOM # 237	04060611
0278	Smoke Detector	2nd SMOKE ROOM # 237	04060612
0279	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 18	3993458735
0280	Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 18	3993442901
0281	Smoke Detector	Mezzanine DUCT SMOKE RETURN UV # 17	3993445322
0282	Smoke Detector	Mezzanine DUCT SMOKE SUPPLY UV # 17	3993346094
0283	Smoke Detector	Basement SMOKE BSMNT UV MECH RM	3993403650
0399	Pull Station	1st PULL FIRST FLOOR STAIR # 5 CORR	04060606
0400	Pull Station	1st PULL FIRST FLOOR IN STAIR # 5	04060684
0401	Pull Station	PULL FIRST FLOOR WEST CORR TO GYM	4899116125

0402	Pull Station	1st PULL WEST GYM ENTRANCE	04060696
0403	Pull Station	1st PULL NORTH/WEST GYM ENTRANCE	04060697
0404	Pull Station	1st PULL FIRST FLOOR EAST CORR TO GYM	04060717
0405	Pull Station	1st PULL HOME TEAM LOCKER ROOM	04060716
0406	Pull Station	1st PULL VISITING TEAM LOCKER ROOM	04060715
0407	Pull Station	1st PULL EAST GYM ENTRANCE	04060714
0408	Pull Station	1st PULL NORTH/EAST GYM ENTRANCE	04060698
0409	Pull Station	2nd PULL 2ND FLOOR BY STAIR #5	04060607
0411	Heat Detector	Basement HEATS BOILER RM	4848238007
0412	Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV #10	04060702
0413	Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV #11	04060701
0414	Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV #12	04060700
0415	Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV #13	04060699
0416	Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV # 9	04060703
0417	Pull Station	2nd PULL 2ND FLOOR BY STAIR #6	04060626
0418	Pull Station	PULL WEST CAFE	4899115500
0430	Pull Station	Basement PULL BASEMENT CORRIDOR	4899114855
0432	Smoke Detector	DUCT SMOKE TEST SWITCH UV # 17	4850312535
0433	Smoke Detector	Mezzanine DUCT SMOKE TEST SWITCH UV # 18	4850312344
0453	Pull Station	Basement PULL BOILER ROOM EXIT	4899115739
0454	Pull Station	1st PULL NORTHWEST ENTRANCE	56177912

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Stamford High
School
55 Strawberry Hill Avenue
Stamford, CT 06902

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Mar 27, 2020

Building: Stamford BOE-Stamford High School
Contact: Davor Lucaj
Title: Facilities Trades Manager



Company: TPC Associates, Inc.
Contact: Luis De La Cruz
Title: Fire alarm inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Stamford High School		Contact: Davor Lucaj
Address: 55 Strawberry Hill Avenue		Phone: 203-977-6668
Address:		Fax:
City/State/Zip: Stamford, CT 06902		Mobile: 347-675-6021
Country: United States of America		Email: dlucaj@stamfordct.gov
Inspection Performed By		
Company: TPC Associates, Inc.		Inspector: Luis De La Cruz
Address: 261 Pepe's Farm Road		Phone: (203)878-1321
Address:		Fax:
City/State/Zip: Milford, Connecticut 06460		Mobile:
Country: United States of America		Email: Luis.delacruz@tpcsystems.com
System Control Unit		
Manufacturer: EST	Inspection Date: 03/27/2020	IDC Style:
Model Number: EST-3	Install Date: 08/24/2012	SLC Style:
Software Version:	Version Date: 07/16/2012	NAC Style:
Location: 1st Nurses Office	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type: Digital Communicator	Mfg: Radionics	Model #: D2071A
Test Time/Date: 3/27/20 9:49:55 AM	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.22%	0	0%	0	0%	0	0%
Control	20	4.48%	20	100.00%	20	100.00%	0	0%
Initiating	425	95.29%	425	100.00%	425	100.00%	0	0%
Totals	446	100%	445	99.78%	445	100.00%	0	0%

Certification	
<p>Company: TPC Associates, Inc.</p> <p>Inspector: Luis De La Cruz</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px auto;">  </div> <p>Signed: Mar 27, 2020 9:10:49 AM</p>	<p>Building: Stamford BOE-Stamford High School</p> <p>Contact: Davor Lucaj</p> <div style="border: 1px solid black; width: 150px; height: 40px; margin: 10px auto;">  </div> <p>Signed: Mar 27, 2020 9:15:01 AM</p>

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Stamford High School		Control Panel: 1 - EST EST-3			
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>					
Device Type	Location	Service	Time	Date	
Passed					
Control					
Annunciator	4th 1971 Level F/4 By Choral 402	Visually Checked	9:20:36 AM	03/27/2020	
Annunciator	4th Custodians Office	Visually Checked	9:20:40 AM	03/27/2020	
Annunciator	F Level Stair 18	Visually Checked	9:20:32 AM	03/27/2020	
Battery	1st Nurses Office Cab 1	Tested	8:06:00 AM	03/27/2020	
Battery	2nd 1927 Level B IEA Electrical Closet 229B Cab 1	Tested	8:25:03 AM	03/27/2020	
Battery	2nd 1927 Level B IEA Electrical Closet 229B Cab 2	Tested	8:26:37 AM	03/27/2020	
Battery	2nd 1927 Level B IEA Electrical Closet 229B Cab 3	Tested	9:08:41 AM	03/27/2020	
Battery	5th E Level Electrical Room 522B #1	Tested	7:48:40 AM	03/27/2020	
Battery	5th E Level Electrical Room 522B #2	Tested	7:50:39 AM	03/27/2020	
Communicator	1st Nurses Office	Tested	9:49:55 AM	03/27/2020	
Control Panel	1st Nurses Office	Visually Checked	9:49:43 AM	03/27/2020	
Initiating					
Duct Detector	2nd 1927 Level B FCU-B10 Corriador By Classroom 250	Visually Checked	9:50:19 AM	03/27/2020	
Duct Detector	2nd 1927 Level B FCU-B9 Corriador By Classroom 245	Visually Checked	9:50:25 AM	03/27/2020	
Duct Detector	2nd 1927 Level B FCU-C7 Corriador By Classroom 223	Visually Checked	9:50:07 AM	03/27/2020	
Duct Detector	2nd 1927 Level B FCU-C7 Corriador By Classroom 223	Visually Checked	9:50:29 AM	03/27/2020	
Duct Detector	2nd 1927 Level B Mechanical Equipment 237 Return	Visually Checked	9:50:32 AM	03/27/2020	
Duct Detector	2nd 1927 Level B RTU-C2 Duct Return	Visually Checked	9:50:22 AM	03/27/2020	
Duct Detector	2nd 1927 Level B RTU-C3 Corridor By Classroom 245	Visually Checked	9:50:11 AM	03/27/2020	
Duct Detector	2nd 1927 Level B RTU-C3 Corridor By Classroom 245	Visually Checked	9:50:15 AM	03/27/2020	
Duct Detector	5th 1927 Level E Machine rm 522	Visually Checked	9:51:22 AM	03/27/2020	
Duct Detector	5th 1927 Level E Machine rm 522	Visually Checked	9:51:25 AM	03/27/2020	
Duct Detector	5th 1927 Level E Machine rm 522	Visually Checked	9:51:28 AM	03/27/2020	
Heat Detector	5th 1927 Level E Crawl Space	Visually Checked	9:51:55 AM	03/27/2020	
Heat Detector	5th 1927 Level E Crawl Space	Visually Checked	9:51:58 AM	03/27/2020	
Heat Detector	5th 1927 Level E Crawl Space	Visually Checked	9:52:01 AM	03/27/2020	
Heat Detector	5th 1927 Level E Crawl Space	Visually Checked	9:52:05 AM	03/27/2020	

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	5th 1927 Level E Crawl Space	Visually Checked	9:52:08 AM	03/27/2020
Heat Detector	5th 1927 Level E Crawl Space	Visually Checked	9:52:10 AM	03/27/2020
Heat Detector	5th 1927 Level E Crawl Space	Visually Checked	9:52:14 AM	03/27/2020
Heat Detector	5th 1927 Level E Crawl Space	Visually Checked	9:52:21 AM	03/27/2020
Heat Detector	6th 1927 Level D Finishing Shop 616A	Visually Checked	9:53:19 AM	03/27/2020
Heat Detector	6th 1927 Level D Metal Shop 616A	Visually Checked	9:53:16 AM	03/27/2020
Heat Detector	6th 1927 Level D Wood Shop 616 Left	Visually Checked	9:51:44 AM	03/27/2020
Heat Detector	6th 1927 Level D Wood Shop 616 Right	Visually Checked	9:51:51 AM	03/27/2020
Initiating Device	2nd 1927 Level B FCU-B10 Duct	Visually Checked	9:21:15 AM	03/27/2020
Initiating Device	2nd 1927 Level B FCU-B9 Duct	Visually Checked	9:21:19 AM	03/27/2020
Initiating Device	2nd 1927 Level B Mechanical Equipment 237 Return	Visually Checked	9:21:45 AM	03/27/2020
Initiating Device	2nd 1927 Level B Mechanical Equipment 237 Supply	Visually Checked	9:21:41 AM	03/27/2020
Initiating Device	2nd 1927 Level B RTU-C2 Duct Return	Visually Checked	9:21:32 AM	03/27/2020
Initiating Device	2nd 1927 Level B RTU-C2 Duct Supply	Visually Checked	9:21:36 AM	03/27/2020
Initiating Device	2nd 1927 Level B RTU-C3 Duct Return	Visually Checked	9:21:24 AM	03/27/2020
Initiating Device	2nd 1927 Level B RTU-C3 Duct Supply	Visually Checked	9:21:29 AM	03/27/2020
Initiating Device	2nd 1927 Level B Electrical Closet 217	Visually Checked	8:22:26 AM	03/27/2020
Initiating Device	5th 1927 Level E Outside Cafe Faculty Dining ACU-1 Return	Visually Checked	9:21:01 AM	03/27/2020
Initiating Device	5th 1927 Level E Outside Cafe Faculty Dining ACU-1 Supply	Visually Checked	9:20:56 AM	03/27/2020
Initiating Device	5th 1927 Level E Outside Cafe Faculty Dining ACU-2 Return	Visually Checked	9:21:11 AM	03/27/2020
Initiating Device	5th 1927 Level E Outside Cafe Faculty Dining ACU-2 Supply	Visually Checked	9:21:07 AM	03/27/2020
Initiating Device	5th 1927 Level E Machine rm 522	Visually Checked	9:23:18 AM	03/27/2020
Initiating Device	5th 1927 Level E Machine rm 522	Visually Checked	9:23:21 AM	03/27/2020
Initiating Device	5th 1927 Level E Machine rm 522	Visually Checked	9:23:25 AM	03/27/2020
Initiating Device	6th 1927 Level D ACU-D3 Return	Visually Checked	9:21:54 AM	03/27/2020
Initiating Device	6th 1927 Level D ACU-D3 Supply	Visually Checked	9:21:48 AM	03/27/2020
Initiating Device	6th 1927 Level D ACU-D4 Return	Visually Checked	9:22:04 AM	03/27/2020
Initiating Device	6th 1927 Level D ACU-D4 Supply	Visually Checked	9:22:08 AM	03/27/2020
Pull Station	1st 1927 Level C Rear Side Exit Aud	Visually Checked	9:41:59 AM	03/27/2020
Pull Station	1st 1927 Level C Side Exit Aud	Visually Checked	9:42:09 AM	03/27/2020
Pull Station	1st 1927 Level C Top Stair 17	Visually Checked	9:42:05 AM	03/27/2020
Pull Station	2nd 1927 Level B By Classroom 250	Visually Checked	9:45:58 AM	03/27/2020
Pull Station	2nd 1927 Level B By Stair 10	Visually Checked	9:43:31 AM	03/27/2020
Pull Station	2nd 1927 Level B By Stair 11	Visually Checked	9:43:35 AM	03/27/2020
Pull Station	2nd 1927 Level B By Stair 7	Visually Checked	9:43:12 AM	03/27/2020
Pull Station	2nd 1927 Level B Corridor Between Stair 12/13	Visually Checked	9:46:04 AM	03/27/2020
Pull Station	2nd 1927 Level B Inside Stair 12	Visually Checked	9:43:41 AM	03/27/2020
Pull Station	2nd 1927 Level B Outside Stair 12	Visually Checked	9:43:47 AM	03/27/2020
Pull Station	2nd 1927 Level B Outside Stair 5	Visually Checked	9:43:00 AM	03/27/2020
Pull Station	2nd 1927 Level B Outside Stair 6	Visually Checked	9:43:08 AM	03/27/2020
Pull Station	2nd 1927 Level B Stair 13	Visually Checked	9:46:08 AM	03/27/2020
Pull Station	2nd 1927 Level B Stair 5	Visually Checked	9:43:04 AM	03/27/2020
Pull Station	2nd 1927 Level B Stair 9	Visually Checked	9:43:26 AM	03/27/2020
Pull Station	2nd 1927 Level B Top Of Stair 9	Visually Checked	9:43:18 AM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	3rd 1927 Level A By Stair 12	Visually Checked	9:45:54 AM	03/27/2020
Pull Station	3rd 1927 Level A By Stair 8	Visually Checked	9:43:22 AM	03/27/2020
Pull Station	3rd 1927 Level A Corridor 360	Visually Checked	9:45:50 AM	03/27/2020
Pull Station	3rd 1927 Level A Top Of Stair	Visually Checked	9:45:46 AM	03/27/2020
Pull Station	5th 1927 Level E By Crawl Space	Visually Checked	9:44:57 AM	03/27/2020
Pull Station	5th 1927 Level E Exit By Cafe	Visually Checked	9:45:10 AM	03/27/2020
Pull Station	5th 1927 Level E Stair 7 By Exit	Visually Checked	9:44:53 AM	03/27/2020
Pull Station	5th 1927 Level E Stair 7	Visually Checked	9:44:46 AM	03/27/2020
Pull Station	5th 1927 Level E Cafe Stair 13	Visually Checked	9:45:24 AM	03/27/2020
Pull Station	5th 1927 Level E Outside Stair 4	Visually Checked	9:45:02 AM	03/27/2020
Pull Station	5th 1927 Level E Outside Stair 6	Visually Checked	9:45:07 AM	03/27/2020
Pull Station	5th 1927 Level E Outside Cafe East Stair Tower	Visually Checked	9:45:18 AM	03/27/2020
Pull Station	5th 1927 Level E Outside Cafe East Wall	Visually Checked	9:45:15 AM	03/27/2020
Pull Station	5th 1927 Level E Outside Cafe Entrance	Visually Checked	9:46:52 AM	03/27/2020
Pull Station	5th 1927 Level E Outside Cafe Faculty Dining	Visually Checked	9:45:38 AM	03/27/2020
Pull Station	5th 1927 Level E Outside Cafe North Wall	Visually Checked	9:45:27 AM	03/27/2020
Pull Station	5th 1927 Level E Outside Cafe Stair 12	Visually Checked	9:45:34 AM	03/27/2020
Pull Station	5th 1927 Level D Outside Stair 7	Visually Checked	9:43:52 AM	03/27/2020
Pull Station	5th 1927 Level E Outside Stair 5 By Room 521	Visually Checked	9:46:55 AM	03/27/2020
Pull Station	6th 1927 Level D Corridor 638A	Visually Checked	9:44:25 AM	03/27/2020
Pull Station	6th 1927 Level D Corridor 638A	Visually Checked	9:45:42 AM	03/27/2020
Pull Station	6th 1927 Level D Stair 10	Visually Checked	9:44:01 AM	03/27/2020
Pull Station	6th 1927 Level D Stair 10	Visually Checked	9:46:47 AM	03/27/2020
Pull Station	6th 1927 Level D Stair 10 In Library	Visually Checked	9:44:05 AM	03/27/2020
Pull Station	6th 1927 Level D Stair 10 In Library	Visually Checked	9:44:11 AM	03/27/2020
Pull Station	6th 1927 Level D Stair 8	Visually Checked	9:43:56 AM	03/27/2020
Pull Station	6th 1927 Level D By Stair 6	Visually Checked	9:44:21 AM	03/27/2020
Pull Station	6th 1927 Level D Inside Stair 5	Visually Checked	9:44:16 AM	03/27/2020
Smoke Detector	2nd 1927 Level B 230 Firedoor Northside By Room 228	Visually Checked	9:26:04 AM	03/27/2020
Smoke Detector	2nd 1927 Level B 230 Firedoor Southside By Room 228	Visually Checked	9:26:07 AM	03/27/2020
Smoke Detector	2nd 1927 Level B 248 Firedoor North By Classroom 244	Visually Checked	9:27:22 AM	03/27/2020
Smoke Detector	2nd 1927 Level B 248 Firedoor South By Classroom 244	Visually Checked	9:27:26 AM	03/27/2020
Smoke Detector	2nd 1927 Level B By Stair 11	Visually Checked	9:26:58 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Corridor 208 By Room 201	Visually Checked	9:26:54 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Corridor 253A By Room 201	Visually Checked	9:26:50 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Corridor Between Stair 12/13	Visually Checked	9:30:03 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Corridor Between Stair 12/13	Visually Checked	9:30:11 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Custodian 203A	Visually Checked	9:29:52 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Custodian 212	Visually Checked	9:29:47 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Electrical Closet	Visually Checked	9:29:55 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Entrance To Stair 7	Visually Checked	9:26:23 AM	03/27/2020
Smoke Detector	2nd 1927 Level B IEA Electrical Closet 229B	Visually Checked	8:24:12 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Inside Stair 10	Visually Checked	9:27:18 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Inside Stair 12	Visually Checked	9:27:29 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Mechanical Equipment 237 Left Smoke	Visually Checked	9:30:18 AM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd 1927 Level B Mechanical Equipment 237 Right Smoke	Visually Checked	9:30:22 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Outside Stair 10	Visually Checked	9:27:14 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Outside Stair 12	Visually Checked	9:27:33 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Outside Stair 6	Visually Checked	9:26:19 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Stair 11 By Firedoors Eastside	Visually Checked	9:27:05 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Stair 11 By Firedoors Westside	Visually Checked	9:27:08 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Stair 11	Visually Checked	9:27:02 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Stair 13	Visually Checked	9:29:59 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Stair 13 By Firedoor	Visually Checked	9:30:07 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Storage 241C	Visually Checked	9:30:15 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Top Of Stair 5	Visually Checked	9:26:11 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Top Of Stair 6	Visually Checked	9:26:30 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Top Of Stair 7	Visually Checked	9:29:43 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Top Of Stair 9	Visually Checked	9:26:37 AM	03/27/2020
Smoke Detector	2nd 1927 LEV B SMOKE MECH RM 241A	Visually Checked	9:40:15 AM	03/27/2020
Smoke Detector	2nd 1927 Level B By Stair 8	Visually Checked	9:26:33 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Electrical Closet 217	Visually Checked	8:22:12 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Top Of Stair 8	Visually Checked	9:26:27 AM	03/27/2020
Smoke Detector	2nd 1927 LEV B SMOKE CORR 230 @ STAIR 5	Visually Checked	9:26:16 AM	03/27/2020
Smoke Detector	3rd 1927 Level A Corridor 360	Visually Checked	9:29:22 AM	03/27/2020
Smoke Detector	3rd 1927 Level A Corridor 360	Visually Checked	9:29:30 AM	03/27/2020
Smoke Detector	3rd 1927 Level A Top Of Stair	Visually Checked	9:29:26 AM	03/27/2020
Smoke Detector	3rd 1927 Level A Top Of Stair 12	Visually Checked	9:29:34 AM	03/27/2020
Smoke Detector	3rd Electrical Closet 376	Visually Checked	9:29:16 AM	03/27/2020
Smoke Detector	3rd Storage 374	Visually Checked	9:29:19 AM	03/27/2020
Smoke Detector	5th 1927 Level E By Storage 530	Visually Checked	7:53:33 AM	03/27/2020
Smoke Detector	5th 1927 Level E Custodian	Visually Checked	9:31:47 AM	03/27/2020
Smoke Detector	5th 1927 Level E Stair 4	Visually Checked	9:28:49 AM	03/27/2020
Smoke Detector	5th 1927 Level E Stair 5	Visually Checked	7:54:05 AM	03/27/2020
Smoke Detector	5th 1927 Level E Stair 6	Visually Checked	9:29:00 AM	03/27/2020
Smoke Detector	5th 1927 Level E Outside Stair 5	Visually Checked	7:53:38 AM	03/27/2020
Smoke Detector	5th 1927 Level E Outside Stair 6	Visually Checked	9:28:57 AM	03/27/2020
Smoke Detector	5th 1927 Level E Outside Cafe	Visually Checked	9:28:53 AM	03/27/2020
Smoke Detector	5th 1927 Level E Electrical closet by 523	Visually Checked	7:52:44 AM	03/27/2020
Smoke Detector	5th 1927 Level E Machine rm 522	Visually Checked	9:40:03 AM	03/27/2020
Smoke Detector	5th 1927 Level E Machine rm 522	Visually Checked	9:40:11 AM	03/27/2020
Smoke Detector	6th 1927 Level D Bridge	Visually Checked	9:28:00 AM	03/27/2020
Smoke Detector	6th 1927 Level D Bridge	Visually Checked	9:28:43 AM	03/27/2020
Smoke Detector	6th 1927 Level D Corridor 638A	Visually Checked	7:54:37 AM	03/27/2020
Smoke Detector	6th 1927 Level D Corridor By Room 622	Visually Checked	9:28:46 AM	03/27/2020
Smoke Detector	6th 1927 Level D Corridor By Sewing Classroom 640	Visually Checked	9:27:52 AM	03/27/2020
Smoke Detector	6th 1927 Level D Corridor By Wood Shop 616	Visually Checked	9:27:45 AM	03/27/2020
Smoke Detector	6th 1927 Level D Custodian 634C	Visually Checked	9:31:33 AM	03/27/2020
Smoke Detector	6th 1927 Level D Electrical Room	Visually Checked	9:31:42 AM	03/27/2020
Smoke Detector	6th 1927 Level D Electrical Room By Media Room	Visually Checked	9:31:23 AM	03/27/2020
Smoke Detector	6th 1927 Level D Home Economic Class North Side	Visually Checked	9:31:36 AM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	6th 1927 Level D Home Economic Class South Side	Visually Checked	9:31:39 AM	03/27/2020
Smoke Detector	6th 1927 Level D Inside Stair 7	Visually Checked	9:31:16 AM	03/27/2020
Smoke Detector	6th 1927 Level D office 618D	Visually Checked	9:39:46 AM	03/27/2020
Smoke Detector	6th 1927 Level D Outside Stair 7	Visually Checked	9:27:36 AM	03/27/2020
Smoke Detector	6th 1927 Level D prep rm 628	Visually Checked	9:39:37 AM	03/27/2020
Smoke Detector	6th 1927 Level D Room 623A Storage Thru 622	Visually Checked	9:31:13 AM	03/27/2020
Smoke Detector	6th 1927 Level D Stair 5	Visually Checked	7:54:27 AM	03/27/2020
Smoke Detector	6th 1927 Level D Stair 6	Visually Checked	9:27:56 AM	03/27/2020
Smoke Detector	6th 1927 Level D Stair 8	Visually Checked	9:30:56 AM	03/27/2020
Smoke Detector	6th 1927 Level D Storage	Visually Checked	9:31:28 AM	03/27/2020
Smoke Detector	6th 1927 Level D Storage 630A	Visually Checked	9:31:20 AM	03/27/2020
Smoke Detector	6th 1927 Level D Storage in Cisco Computer Lab 619	Visually Checked	9:31:08 AM	03/27/2020
Smoke Detector	6th 1927 Level D Storage in PC Tech Lab 617	Visually Checked	9:31:04 AM	03/27/2020
Smoke Detector	6th 1927 Level D telecom rm 631A	Visually Checked	9:39:42 AM	03/27/2020
Smoke Detector	6th 1927 Level D Wood Shop 616	Visually Checked	9:31:00 AM	03/27/2020
Smoke Detector	6th 1927 Level D Workroom 634	Visually Checked	9:30:53 AM	03/27/2020
Smoke Detector	6th 1927 Level D Inside Stair 5	Visually Checked	7:54:22 AM	03/27/2020

Building: Stamford BOE-Stamford High School

Control Panel: 2

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Control				
Battery	1st Nurses Booster Cab 2	Tested	8:00:08 AM	03/27/2020
Battery	1st Nurses Office Booster Cab 1	Tested	7:58:51 AM	03/27/2020
Battery	1st Nurses Office Cab 5	Tested	8:07:43 AM	03/27/2020
Initiating				
Duct Detector	1st 1927 Level C C9 corr145	Visually Checked	9:50:38 AM	03/27/2020
Duct Detector	1st 1927 Level C Corridor By Room 143 FCU-C2	Visually Checked	9:50:35 AM	03/27/2020
Duct Detector	1st 1927 Level C By Room 132 FCU-C12	Visually Checked	9:50:04 AM	03/27/2020
Pull Station	1st 1927 Level C By Small Auditorium 101	Visually Checked	9:42:27 AM	03/27/2020
Pull Station	1st 1927 Level C By Stair 5	Visually Checked	9:41:52 AM	03/27/2020
Pull Station	1st 1927 Level C By Stair 8	Visually Checked	9:49:06 AM	03/27/2020
Pull Station	1st 1927 Level C Rear Stage	Visually Checked	9:46:13 AM	03/27/2020
Pull Station	1st 1927 Level C Side Stage	Visually Checked	9:41:56 AM	03/27/2020
Pull Station	1st 1927 Level C Stage Exit Hall	Visually Checked	9:46:23 AM	03/27/2020
Pull Station	1st 1927 Level C Stair 13	Visually Checked	9:47:13 AM	03/27/2020
Pull Station	1st 1927 Level C Stair 16	Visually Checked	9:42:44 AM	03/27/2020
Pull Station	1st 1927 Level C Stair 16	Visually Checked	9:42:47 AM	03/27/2020
Pull Station	1st 1927 Level C Stair 5	Visually Checked	9:49:17 AM	03/27/2020
Pull Station	1st 1927 Level C Stair 9	Visually Checked	9:42:36 AM	03/27/2020
Pull Station	1st 1927 Level C Stair12	Visually Checked	9:42:23 AM	03/27/2020
Pull Station	1st 1927 Level C Stair12 By Guidance 147	Visually Checked	9:42:18 AM	03/27/2020
Pull Station	1st 1927 Level C Aud Rear Entrance	Visually Checked	9:42:13 AM	03/27/2020
Pull Station	1st 1927 Level C By Outside Stair 7	Visually Checked	9:42:40 AM	03/27/2020
Pull Station	1st 1927 Level C By Stair 10	Visually Checked	9:41:48 AM	03/27/2020
Pull Station	1st 1927 Level C By Stair 11	Visually Checked	7:56:28 AM	03/27/2020
Pull Station	1st 1927 Level C By Stair 6	Visually Checked	9:49:13 AM	03/27/2020
Pull Station	1st 1927 Level C By Aud Entrance	Visually Checked	9:46:27 AM	03/27/2020
Pull Station	1st 1927 Level C Main Entrance	Visually Checked	9:41:44 AM	03/27/2020
Pull Station	2nd 1927 Level B Entrance To Stair 16	Visually Checked	9:42:55 AM	03/27/2020
Pull Station	2nd 1927 Level B Stair 16	Visually Checked	9:42:51 AM	03/27/2020
Pull Station	2nd 1927 Level B Upper Stage Mech	Visually Checked	9:46:18 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Guidance 147	Visually Checked	9:24:35 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Learning Center	Visually Checked	9:25:26 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Nurses Room 149	Visually Checked	9:25:03 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Professional Library 144	Visually Checked	9:24:44 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Professional Library 144	Visually Checked	9:24:50 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Room 102A	Visually Checked	9:25:18 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Room 154	Visually Checked	9:24:55 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Small Auditorium 101	Visually Checked	9:25:12 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Stair 8	Visually Checked	9:25:30 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Stair 8	Visually Checked	9:26:41 AM	03/27/2020
Smoke Detector	1st 1927 Level C Corridor By Stage By FireDoor	Visually Checked	9:24:02 AM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st 1927 Level C Corridor By Stage By FireDoor	Visually Checked	9:24:31 AM	03/27/2020
Smoke Detector	1st 1927 Level C Custodian	Visually Checked	9:33:00 AM	03/27/2020
Smoke Detector	1st 1927 Level C Custodian 112	Visually Checked	9:32:56 AM	03/27/2020
Smoke Detector	1st 1927 Level C Custodian 124A	Visually Checked	9:32:44 AM	03/27/2020
Smoke Detector	1st 1927 Level C Guidance Phone Room	Visually Checked	9:33:03 AM	03/27/2020
Smoke Detector	1st 1927 Level C Guidance Storage By Vault	Visually Checked	9:33:06 AM	03/27/2020
Smoke Detector	1st 1927 Level C Heath Center 119A	Visually Checked	9:32:48 AM	03/27/2020
Smoke Detector	1st 1927 Level C Heath Center 119A	Visually Checked	9:32:52 AM	03/27/2020
Smoke Detector	1st 1927 Level C Room 150 Nurses Office Electrical Closet	Visually Checked	9:40:07 AM	03/27/2020
Smoke Detector	1st 1927 Level C Stair 11	Visually Checked	9:32:41 AM	03/27/2020
Smoke Detector	1st 1927 Level C Stair 16	Visually Checked	9:25:49 AM	03/27/2020
Smoke Detector	1st 1927 Level C Stair 16	Visually Checked	9:25:53 AM	03/27/2020
Smoke Detector	1st 1927 Level C Stair 5	Visually Checked	9:23:55 AM	03/27/2020
Smoke Detector	1st 1927 Level C Stair 6	Visually Checked	9:24:06 AM	03/27/2020
Smoke Detector	1st 1927 Level C Stair12	Visually Checked	9:24:47 AM	03/27/2020
Smoke Detector	1st 1927 Level C Storage	Visually Checked	9:30:26 AM	03/27/2020
Smoke Detector	1st 1927 Level C Storage	Visually Checked	9:30:32 AM	03/27/2020
Smoke Detector	1st 1927 Level C vestibule lobby by room 156	Visually Checked	9:25:22 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Heath Center 119A	Visually Checked	9:25:33 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Inside Stair 7	Visually Checked	9:25:45 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Outside Stair 7	Visually Checked	9:25:37 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Room 120	Visually Checked	9:25:42 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Room 162A	Visually Checked	9:23:34 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Room 167	Visually Checked	7:56:39 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Room 167	Visually Checked	9:23:40 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Stair 10	Visually Checked	9:23:31 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Stair 5	Visually Checked	9:23:51 AM	03/27/2020
Smoke Detector	1st 1927 Level C By Stair 6	Visually Checked	9:23:59 AM	03/27/2020
Smoke Detector	1st 1927 Level C In Stair 10	Visually Checked	9:32:37 AM	03/27/2020
Smoke Detector	1st 1927 Level C North Firedoor By Room 130	Visually Checked	9:23:43 AM	03/27/2020
Smoke Detector	1st 1927 Level C South Firedoor By Room 130	Visually Checked	9:23:47 AM	03/27/2020
Smoke Detector	1st 1927 Level C Stage Electrical Room	Visually Checked	9:30:41 AM	03/27/2020
Smoke Detector	1st 1927 Level C Stage Storage	Visually Checked	9:30:48 AM	03/27/2020
Smoke Detector	1st 1927 Level C Stage Storage Room	Visually Checked	9:30:45 AM	03/27/2020
Smoke Detector	1st 1927 LEV C SMOKE CUSTODIAN RM 155A	Visually Checked	9:29:12 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Entrance To Stair 16	Visually Checked	9:25:57 AM	03/27/2020
Smoke Detector	2nd 1927 Level B Top Of Stair 16	Visually Checked	9:26:00 AM	03/27/2020

Building: Stamford BOE-Stamford High School		Control Panel: 3		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
<i>Passed</i>				
Control				
Battery	1st Nurses Office Cab 2	Tested	8:03:00 AM	03/27/2020

Building: Stamford BOE-Stamford High School

Control Panel: 4

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Initiating				
Duct Detector	6th 1927 Level D class rm 610	Visually Checked	9:51:16 AM	03/27/2020
Duct Detector	F Level Gym Upper Mechanical	Visually Checked	9:51:09 AM	03/27/2020
Duct Detector	F Level Gym Upper Mechanical	Visually Checked	9:51:19 AM	03/27/2020
Duct Detector	F Level Mech Room Above Girls Locker Room	Visually Checked	9:50:59 AM	03/27/2020
	AHU-F1 Return			
Duct Detector	F Level Mech Room Above Girls Locker Room	Visually Checked	9:50:56 AM	03/27/2020
	AHU-F1 Supply			
Duct Detector	F Level Mech Room Above Girls Locker Room	Visually Checked	9:50:52 AM	03/27/2020
	AHU-F2 Supply			
Duct Detector	F Level Mech Room Above Girls Locker Room	Visually Checked	9:50:49 AM	03/27/2020
	AHU-F3 Supply			
Initiating Device	6th 1971 Level D/1 Electrical Room FCU-D1 Return	Visually Checked	9:22:38 AM	03/27/2020
Initiating Device	6th 1971 Level D/1 Electrical Room FCU-D1 Supply	Visually Checked	9:22:43 AM	03/27/2020
Initiating Device	6th 1971 Level D/1 Electrical Room FCU-D2 Return	Visually Checked	9:22:21 AM	03/27/2020
Initiating Device	6th 1971 Level D/1 Electrical Room FCU-D2 Return	Visually Checked	9:22:26 AM	03/27/2020
Initiating Device	6th 1971 Level D/1 Electrical Room FCU-D5	Visually Checked	9:22:13 AM	03/27/2020
Initiating Device	F Level Gym Upper Mechanical	Visually Checked	9:23:09 AM	03/27/2020
Initiating Device	F Level Gym Upper Mechanical	Visually Checked	9:23:14 AM	03/27/2020
Initiating Device	F Level Mech Room Above Girls Locker Room	Visually Checked	9:23:00 AM	03/27/2020
	AHU-F1 Return			
Initiating Device	F Level Mech Room Above Girls Locker Room	Visually Checked	9:23:04 AM	03/27/2020
	AHU-F1 Supply			
Initiating Device	F Level Mech Room Above Girls Locker Room	Visually Checked	9:22:50 AM	03/27/2020
	AHU-F2 Supply			
Initiating Device	F Level Mech Room Above Girls Locker Room	Visually Checked	9:22:57 AM	03/27/2020
	AHU-F3 Supply			
Pull Station	4th 1971 Level F/4 Choral 402	Visually Checked	9:47:24 AM	03/27/2020
Pull Station	4th 1971 Level F/4 Outside Choral 402	Visually Checked	9:47:34 AM	03/27/2020
Pull Station	5th 1971 Level E/2 By Firedoor	Visually Checked	9:47:01 AM	03/27/2020
Pull Station	5th 1971 Level E/2 By Room 515	Visually Checked	9:47:06 AM	03/27/2020
Pull Station	5th 1971 Level E/2 By Stair 1	Visually Checked	9:47:17 AM	03/27/2020
Pull Station	5th 1971 Level E/2 In By Stair 1	Visually Checked	9:47:20 AM	03/27/2020
Pull Station	6th 1971 Level D/1 By Room 610	Visually Checked	9:44:38 AM	03/27/2020
Pull Station	6th 1971 Level D/1 By Room 615	Visually Checked	9:44:42 AM	03/27/2020
Pull Station	6th 1971 Level D/1 In Stair by Room 615	Visually Checked	9:44:50 AM	03/27/2020
Pull Station	6th 1971 Level D/1 Stair 601C	Visually Checked	9:44:30 AM	03/27/2020
Pull Station	6th 1971 Level D/1 Stair 601C	Visually Checked	9:44:34 AM	03/27/2020
Pull Station	F Level Boys Locker Room	Visually Checked	9:49:10 AM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	F Level Boys Locker Room	Visually Checked	9:49:20 AM	03/27/2020
Pull Station	F Level Dance Class 405	Visually Checked	9:48:20 AM	03/27/2020
Pull Station	F Level Exercise Bike Room	Visually Checked	9:48:23 AM	03/27/2020
Pull Station	F Level Gym	Visually Checked	9:48:31 AM	03/27/2020
Pull Station	F Level Gym	Visually Checked	9:48:34 AM	03/27/2020
Pull Station	F Level Gym	Visually Checked	9:48:41 AM	03/27/2020
Pull Station	F Level Gym	Visually Checked	9:48:44 AM	03/27/2020
Pull Station	F Level Gym	Visually Checked	9:48:47 AM	03/27/2020
Pull Station	F Level Gym	Visually Checked	9:48:51 AM	03/27/2020
Pull Station	F Level Gym	Visually Checked	9:48:54 AM	03/27/2020
Pull Station	F Level Gym	Visually Checked	9:49:00 AM	03/27/2020
Pull Station	F Level Gym Lobby	Visually Checked	9:48:11 AM	03/27/2020
Pull Station	F Level Gym Lobby	Visually Checked	9:49:03 AM	03/27/2020
Pull Station	F Level Mech Room Above Girls Locker Room	Visually Checked	9:48:27 AM	03/27/2020
Smoke Detector	4th 1971 Level F/4 Lobby By Auto	Visually Checked	9:33:29 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 Bridge	Visually Checked	9:33:22 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 Bridge	Visually Checked	9:33:25 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 By Firedoor	Visually Checked	9:32:24 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 By Room 515	Visually Checked	9:32:04 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 By Stairs	Visually Checked	9:32:16 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 Custodian	Visually Checked	9:33:10 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 Electrical Room	Visually Checked	9:32:08 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 In Stair	Visually Checked	9:31:57 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 In Stairs	Visually Checked	9:32:20 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 Stair 1	Visually Checked	9:33:16 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 Stair 1	Visually Checked	9:33:19 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 Storage	Visually Checked	9:32:29 AM	03/27/2020
Smoke Detector	5th 1971 Level E/2 Storage 533	Visually Checked	9:32:34 AM	03/27/2020
Smoke Detector	5th Prep Room 501B 1971 LEV E SMOKE PLANT 5011	Visually Checked	9:29:04 AM	03/27/2020
Smoke Detector	5th Prep Room 501B 1971 LEV E SMOKE PLANT 5011	Visually Checked	9:29:08 AM	03/27/2020
Smoke Detector	6th 1927 Level D Bridge	Visually Checked	9:28:07 AM	03/27/2020
Smoke Detector	6th 1927 Level D Bridge	Visually Checked	9:28:11 AM	03/27/2020
Smoke Detector	6th 1927 Level D classroom 610	Visually Checked	9:39:51 AM	03/27/2020
Smoke Detector	6th 1971 Level D/1 Bridge	Visually Checked	9:28:34 AM	03/27/2020
Smoke Detector	6th 1971 Level D/1 Bridge	Visually Checked	9:28:39 AM	03/27/2020
Smoke Detector	6th 1971 Level D/1 By Room 610	Visually Checked	9:28:22 AM	03/27/2020
Smoke Detector	6th 1971 Level D/1 By Room 615	Visually Checked	9:28:18 AM	03/27/2020
Smoke Detector	6th 1971 Level D/1 Electrical Room	Visually Checked	9:32:01 AM	03/27/2020
Smoke Detector	6th 1971 Level D/1 Storage Room 602A	Visually Checked	9:39:58 AM	03/27/2020
Smoke Detector	6th 1971 Level D/1 By Stair 601C	Visually Checked	9:28:14 AM	03/27/2020
Smoke Detector	6th 1971 Level D/1 By Storage By Room 603	Visually Checked	9:31:54 AM	03/27/2020
Smoke Detector	6th 1971 Level D/1 By Storage By Room 609	Visually Checked	9:31:51 AM	03/27/2020
Smoke Detector	F Level Equipment Room	Visually Checked	9:36:15 AM	03/27/2020
Smoke Detector	F Level Gym Corridor Storage	Visually Checked	9:35:01 AM	03/27/2020
Smoke Detector	F Level Gym Corridor Storage/Elevator Room	Visually Checked	9:34:54 AM	03/27/2020
Smoke Detector	F Level Gym Electrical Room	Visually Checked	9:39:27 AM	03/27/2020
Smoke Detector	F Level Gym Mechanical	Visually Checked	9:39:32 AM	03/27/2020
Smoke Detector	F Level Gym Upper Mechanical	Visually Checked	9:39:16 AM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	F Level Gym Upper Mechanical	Visually Checked	9:39:21 AM	03/27/2020
Smoke Detector	F Level Mech Room Above Girls Locker Room Above Motor	Visually Checked	9:34:43 AM	03/27/2020
Smoke Detector	F Level Mech Room Above Girls Locker Room	Visually Checked	9:39:02 AM	03/27/2020
Smoke Detector	F Level Mech Room Above Girls Locker Room	Visually Checked	9:39:06 AM	03/27/2020
Smoke Detector	F Level Mech Room Above Girls Locker Room	Visually Checked	9:39:11 AM	03/27/2020
Smoke Detector	F Level Stair 1	Visually Checked	9:38:58 AM	03/27/2020
Smoke Detector	F Level Stair 2	Visually Checked	9:34:51 AM	03/27/2020
Smoke Detector	F Level Stair 3	Visually Checked	9:34:48 AM	03/27/2020
Smoke Detector	F Level Storage Room	Visually Checked	9:36:10 AM	03/27/2020

Building: Stamford BOE-Stamford High School

Control Panel: 12 - EST EST-3

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Control				
Battery	F Level IT Room 452 Booster 1	Tested	8:51:38 AM	03/27/2020
Battery	F Level IT Room 452 Booster 2	Tested	9:00:14 AM	03/27/2020
Battery	F Level IT Room 452 Booster 3	Tested	8:55:34 AM	03/27/2020
Battery	F Level IT Room 452 Panel Set	Tested	8:57:05 AM	03/27/2020
Control Panel	F Level IT Room 452	Tested	9:49:48 AM	03/27/2020
Initiating				
Duct Detector	8th By Stair 18 Return	Visually Checked	9:51:05 AM	03/27/2020
Duct Detector	8th By Stair 18 Supply	Visually Checked	9:51:12 AM	03/27/2020
Duct Detector	9th By Stair 18 Supply	Visually Checked	9:50:42 AM	03/27/2020
Duct Detector	9th By Stair 19 Return	Visually Checked	9:50:45 AM	03/27/2020
Heat Detector	7th Custodians Closet 722	Visually Checked	9:53:07 AM	03/27/2020
Heat Detector	7th Mens Locker 707 Bathroom	Visually Checked	9:53:13 AM	03/27/2020
Heat Detector	7th Mens Locker 707	Visually Checked	9:53:10 AM	03/27/2020
Heat Detector	7th Mens Room	Visually Checked	9:52:58 AM	03/27/2020
Heat Detector	7th Mens Room	Visually Checked	9:53:04 AM	03/27/2020
Heat Detector	7th Pantry	Visually Checked	9:52:51 AM	03/27/2020
Heat Detector	7th Womens Locker 707 Bathroom	Visually Checked	9:52:24 AM	03/27/2020
Heat Detector	7th Womens Locker 707	Visually Checked	9:52:18 AM	03/27/2020
Heat Detector	7th Womens Locker 707	Visually Checked	9:52:27 AM	03/27/2020
Heat Detector	7th Womens Room	Visually Checked	9:52:55 AM	03/27/2020
Heat Detector	7th Womens Room	Visually Checked	9:53:01 AM	03/27/2020
Heat Detector	8th Mens Room	Visually Checked	9:52:35 AM	03/27/2020
Heat Detector	8th Mens Room 817A	Visually Checked	9:52:31 AM	03/27/2020
Heat Detector	8th Womens Room	Visually Checked	9:52:47 AM	03/27/2020
Heat Detector	8th Womens Room 817B	Visually Checked	9:52:38 AM	03/27/2020
Heat Detector	9th Mens Room 917A	Visually Checked	9:51:41 AM	03/27/2020
Heat Detector	9th Mens Room 922	Visually Checked	9:51:37 AM	03/27/2020
Heat Detector	9th Womens Room 917B	Visually Checked	9:51:47 AM	03/27/2020
Heat Detector	9th Womens Room 921	Visually Checked	9:52:41 AM	03/27/2020
Heat Detector	F Level Tank Room 456	Visually Checked	9:52:44 AM	03/27/2020
Pull Station	7th Elevator Lobby	Visually Checked	9:47:30 AM	03/27/2020
Pull Station	7th Gym	Visually Checked	9:46:34 AM	03/27/2020
Pull Station	7th Gym	Visually Checked	9:46:38 AM	03/27/2020
Pull Station	7th Gym	Visually Checked	9:46:43 AM	03/27/2020
Pull Station	7th Stair 18	Visually Checked	9:48:06 AM	03/27/2020
Pull Station	7th Stair 19	Visually Checked	9:47:39 AM	03/27/2020
Pull Station	8th Stair 18	Visually Checked	9:48:03 AM	03/27/2020
Pull Station	8th Stair 19	Visually Checked	9:47:59 AM	03/27/2020
Pull Station	9th By Stair 18	Visually Checked	9:46:31 AM	03/27/2020
Pull Station	9th By Stair 19	Visually Checked	9:47:44 AM	03/27/2020
Pull Station	F Level Parking Garage Exit	Visually Checked	9:47:54 AM	03/27/2020
Pull Station	F Level Stair 18	Visually Checked	9:48:16 AM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	7th Corridor By 718	Visually Checked	9:38:17 AM	03/27/2020
Smoke Detector	7th Corridor By 724	Visually Checked	9:37:54 AM	03/27/2020
Smoke Detector	7th Corridor By 724	Visually Checked	9:37:58 AM	03/27/2020
Smoke Detector	7th Corridor By 724	Visually Checked	9:38:03 AM	03/27/2020
Smoke Detector	7th Corridor By Storage 732	Visually Checked	9:38:12 AM	03/27/2020
Smoke Detector	7th Data Room 719	Visually Checked	9:38:25 AM	03/27/2020
Smoke Detector	7th Electrical Closet 720	Visually Checked	9:38:21 AM	03/27/2020
Smoke Detector	7th Gym Storage	Visually Checked	9:36:49 AM	03/27/2020
Smoke Detector	7th Gym Storage	Visually Checked	9:36:54 AM	03/27/2020
Smoke Detector	7th Gym Vestibule	Visually Checked	9:33:47 AM	03/27/2020
Smoke Detector	7th Outside Room 710	Visually Checked	9:38:52 AM	03/27/2020
Smoke Detector	7th Outside Room 712	Visually Checked	9:38:41 AM	03/27/2020
Smoke Detector	7th Outside Room 714	Visually Checked	9:38:38 AM	03/27/2020
Smoke Detector	7th Outside Room 714	Visually Checked	9:38:45 AM	03/27/2020
Smoke Detector	7th Outside Room 716	Visually Checked	9:38:33 AM	03/27/2020
Smoke Detector	7th Ramp	Visually Checked	9:33:32 AM	03/27/2020
Smoke Detector	7th Ramp	Visually Checked	9:33:36 AM	03/27/2020
Smoke Detector	7th Ramp	Visually Checked	9:33:39 AM	03/27/2020
Smoke Detector	7th Stair 2	Visually Checked	9:33:43 AM	03/27/2020
Smoke Detector	7th Storage 732	Visually Checked	9:38:08 AM	03/27/2020
Smoke Detector	7th Storage Math 717	Visually Checked	9:38:29 AM	03/27/2020
Smoke Detector	8th By Elevator Lobby	Visually Checked	9:37:27 AM	03/27/2020
Smoke Detector	8th Corridor By Room 810	Visually Checked	9:37:15 AM	03/27/2020
Smoke Detector	8th Corridor By Room 812	Visually Checked	9:37:19 AM	03/27/2020
Smoke Detector	8th Corridor By Room 812	Visually Checked	9:37:23 AM	03/27/2020
Smoke Detector	8th Custodians Closet 822	Visually Checked	9:36:59 AM	03/27/2020
Smoke Detector	8th Data Room 819	Visually Checked	9:37:09 AM	03/27/2020
Smoke Detector	8th Electrical Closet 820	Visually Checked	9:37:04 AM	03/27/2020
Smoke Detector	8th Outside Room 816	Visually Checked	9:37:31 AM	03/27/2020
Smoke Detector	8th Outside Room 818	Visually Checked	9:37:36 AM	03/27/2020
Smoke Detector	8th Outside Room 824	Visually Checked	9:37:41 AM	03/27/2020
Smoke Detector	8th Outside Room 826	Visually Checked	9:37:46 AM	03/27/2020
Smoke Detector	8th Stair 18	Visually Checked	9:37:50 AM	03/27/2020
Smoke Detector	9th By Stair 19	Visually Checked	9:33:54 AM	03/27/2020
Smoke Detector	9th By Stair 18	Visually Checked	9:34:26 AM	03/27/2020
Smoke Detector	9th By Stair in 18	Visually Checked	9:34:30 AM	03/27/2020
Smoke Detector	9th Corridor By Room 912	Visually Checked	9:33:58 AM	03/27/2020
Smoke Detector	9th Corridor By Room 914	Visually Checked	9:34:01 AM	03/27/2020
Smoke Detector	9th Corridor By Room 916	Visually Checked	9:34:10 AM	03/27/2020
Smoke Detector	9th Corridor By Room 918	Visually Checked	9:34:13 AM	03/27/2020
Smoke Detector	9th Corridor By Room 924	Visually Checked	9:34:16 AM	03/27/2020
Smoke Detector	9th Corridor By Room 924	Visually Checked	9:34:20 AM	03/27/2020
Smoke Detector	9th Custodians Closet 922	Visually Checked	9:34:39 AM	03/27/2020
Smoke Detector	9th Data Room 919	Visually Checked	9:34:34 AM	03/27/2020
Smoke Detector	9th Electrical Room 920	Visually Checked	9:34:36 AM	03/27/2020
Smoke Detector	9th Elevator Lobby	Visually Checked	9:34:06 AM	03/27/2020
Smoke Detector	9th Stair 19	Visually Checked	9:33:51 AM	03/27/2020
Smoke Detector	F Level Corridor 450	Visually Checked	9:36:35 AM	03/27/2020
Smoke Detector	F Level Gym Corridor By Stair 18	Visually Checked	9:34:57 AM	03/27/2020
Smoke Detector	F Level Gym Corridor By Stair 18	Visually Checked	9:35:04 AM	03/27/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	F Level Gym Corridor	Visually Checked	9:35:22 AM	03/27/2020
Smoke Detector	F Level Gym Corridor	Visually Checked	9:35:26 AM	03/27/2020
Smoke Detector	F Level Mechanical Room 451	Visually Checked	9:36:31 AM	03/27/2020
Smoke Detector	F Level Parking Garage Exit Corridor	Visually Checked	9:35:31 AM	03/27/2020
Smoke Detector	F Level Parking Garage Exit Corridor	Visually Checked	9:36:07 AM	03/27/2020
Smoke Detector	F Level Parking Garage Exit	Visually Checked	9:36:19 AM	03/27/2020
Smoke Detector	F Level Parking Garage Exit	Visually Checked	9:36:23 AM	03/27/2020
Smoke Detector	F Level Stair 18	Visually Checked	9:38:48 AM	03/27/2020
Smoke Detector	F Level Electrical Service 453	Visually Checked	9:36:39 AM	03/27/2020
Smoke Detector	F Level IT Room 452	Visually Checked	8:51:34 AM	03/27/2020
Smoke Detector	F Level Storage 455	Visually Checked	9:36:44 AM	03/27/2020

Service Summary

Generated by: BuildingReports.com

Building: Stamford BOE-Stamford High School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Passed</i>		
Annunciator	Visually Checked	3
Battery	Tested	14
Communicator	Tested	1
Control Panel	Tested	1
Control Panel	Visually Checked	1
Duct Detector	Visually Checked	25
Heat Detector	Visually Checked	32
Initiating Device	Visually Checked	31
Pull Station	Visually Checked	105
Smoke Detector	Visually Checked	232
Total		445
Grand Total		445




Auxiliary Functions Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Stamford High School				Control Panel: 4	
<i>The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.</i>					
Type	Location		Comment	ScanID	Simulated
Passed					
Smoke Detector					
Elevator Recall	F Level Gym Corridor Storage/Elevator Room		Passed	20665831	

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Stamford High School								
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>								
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test		
		◀ dB	◀ dB	Voice	STI			
<i>Untested</i>								
Sound Test Points								
Whole Facility				<input type="checkbox"/>		0001		

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Stamford High School				Control Panel: 1 - EST EST-3			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	1st Nurses Office Cab 1	24	13.32	13.37V	45Ah		
Sealed Lead Acid	2nd 1927 Level B IEA Electrical Closet 229B Cab 1	4.1	12.75	12.76V	11Ah		
Sealed Lead Acid	2nd 1927 Level B IEA Electrical Closet 229B Cab 2	8	12.79	12.51V	7.6Ah		
Sealed Lead Acid	2nd 1927 Level B IEA Electrical Closet 229B Cab 3	2.2	12.88	12.88V	8.0Ah		
Sealed Lead Acid	5th E Level Electrical Room 522B #1	7.8	12.56	12.72V	7.6Ah		
Sealed Lead Acid	5th E Level Electrical Room 522B #2	7.6	12.60	12.54V	7.0Ah		

Building: Stamford BOE-Stamford High School				Control Panel: 2			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	1st Nurses Booster Cab 2			12.54V	7.0Ah		
Sealed Lead Acid	1st Nurses Office Booster Cab 1			12.69V	7.8Ah04		
					5		
Sealed Lead Acid	1st Nurses Office Cab 5	45045 900	13.44	13.35V	36Ah		

Building: Stamford BOE-Stamford High School				Control Panel: 3			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	1st Nurses Office Cab 2	24	13.38	13.38V	34Ah		

Building: Stamford BOE-Stamford High School

Control Panel: 12 - EST EST-3

The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<i>Passed</i>							
Battery							
Sealed Lead Acid	F Level IT Room 452 Booster 1	7.9	12.60	12.54V	7.8Ah		
Sealed Lead Acid	F Level IT Room 452 Booster 2	8	12.72	12.66V	7.6Ah		
Sealed Lead Acid	F Level IT Room 452 Booster 3	7.8	12.68	12.60V	6.8Ah		
Sealed Lead Acid	F Level IT Room 452 Panel Set	17	12.94	12.85V	14Ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Stamford High School

Control Panel: 1 - EST EST-3

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type	Category	% of Inventory	Quantity
Sound Test	Sound Test	0.22%	1
Battery	Control	3.14%	14
Smoke Detector	Initiating	52.02%	232
Pull Station	Initiating	23.54%	105
Initiating Device	Initiating	6.95%	31
Annunciator	Control	0.67%	3
Control Panel	Control	0.45%	2
Communicator	Control	0.22%	1
Duct Detector	Initiating	5.61%	25
Heat Detector	Initiating	7.17%	32

Type	Qty	Model #	Description	Install Date
<i>In Service - 90 Days - 1 Year</i>				
Universal				
Battery	1	UB12500	Sealed Lead Acid	08/21/2019
Battery	2	UB1280	Sealed Lead Acid	08/21/2019
<i>In Service - 3 Years to 5 Years</i>				
Universal				
Battery	2	UB1280	Sealed Lead Acid	02/07/2017
Universal Battery				
Battery	1	UB1280	Sealed Lead Acid	02/07/2017
<i>In Service - 5 Years to 10 Years</i>				
EST				
Annunciator	1	EST-3	LCD Display	08/24/2012
Control Panel	1	EST-3		08/24/2012
Radionics				
Communicator	1	D2071A	Digital Communicator	08/24/2012
EST				
Annunciator	2	EST-3	LCD Display	07/16/2012
Duct Detector	11	SIGA-PS	Photoelectric	07/16/2012
Heat Detector	12	SIGA-HFS	Fixed Temperature	07/16/2012
Initiating Device	20	SIGA-DTS	Supporting Field Device	07/16/2012
Pull Station	44	SIGA-278	Dual Action	07/16/2012
Smoke Detector	80	SIGA-PS	Photoelectric	07/16/2012

Building: Stamford BOE-Stamford High School				Control Panel: 2
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>				
Type	Qty	Model #	Description	Install Date
<i>In Service - 90 Days - 1 Year</i>				
EST				
Smoke Detector	1	SIGA-PS	Photoelectric	08/21/2019
<i>In Service - 3 Years to 5 Years</i>				
Universal				
Battery	2	UB1280	Sealed Lead Acid	02/07/2017
<i>In Service - 5 Years to 10 Years</i>				
EST				
Smoke Detector	1	SIGA-PS	Photoelectric	08/30/2014
Universal				
Battery	1	UB12500	Sealed Lead Acid	02/04/2014
EST				
Duct Detector	3	SIGA-PS	Photoelectric	07/16/2012
Pull Station	23	SIGA-278	Dual Action	07/16/2012
Smoke Detector	46	SIGA-PS	Photoelectric	07/16/2012
Building: Stamford BOE-Stamford High School				Control Panel: 3
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>				
Type	Qty	Model #	Description	Install Date
<i>In Service - 90 Days - 1 Year</i>				
Universal				
Battery	1	UB12500	Sealed Lead Acid	08/21/2019
Building: Stamford BOE-Stamford High School				Control Panel: 4
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>				
Type	Qty	Model #	Description	Install Date
<i>In Service - 5 Years to 10 Years</i>				

EST				
Duct Detector	7	SIGA-PS	Photoelectric	07/16/2012
Initiating Device	11	SIGA-DTS	Supporting Field Device	07/16/2012
Pull Station	26	SIGA-278	Dual Action	07/16/2012
Smoke Detector	1	SIGA-PD	Photoelectric	07/16/2012
Smoke Detector	42	SIGA-PS	Photoelectric	07/16/2012
Building: Stamford BOE-Stamford High School			Control Panel: 12 - EST EST-3	
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>				
Type	Qty	Model #	Description	Install Date
<i>In Service - 3 Years to 5 Years</i>				
Universal				
Battery	1	UB12180	Sealed Lead Acid	02/08/2017
Battery	2	UB1280	Sealed Lead Acid	02/08/2017
Battery	1	UB1280	Sealed Lead Acid	02/07/2017
<i>In Service - 5 Years to 10 Years</i>				
EST				
Control Panel	1	EST-3		08/24/2012
Duct Detector	4	SIGA-SD	Photoelectric	07/16/2012
Heat Detector	20	SIGA-HFS	Fixed Temperature	07/16/2012
Pull Station	12	SIGA-278	Dual Action	07/16/2012
Smoke Detector	1	SIGA-Pd	Photoelectric	07/16/2012
Smoke Detector	60	SIGA-PS	Photoelectric	07/16/2012

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Stamford High School

Control Panel: 1 - EST EST-3

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 01				
0615	Battery	1st Nurses Office Cab 1	Sealed Lead Acid	04590004
Zone/Circuit: 04				
0003	Smoke Detector	3rd Electrical Closet 376	Photoelectric	17013627
0004	Smoke Detector	3rd Storage 374	Photoelectric	17013628
0005	Smoke Detector	3rd 1927 Level A Top Of Stair	Photoelectric	17013631
0006	Smoke Detector	3rd 1927 Level A Corridor 360	Photoelectric	17013632
0009	Smoke Detector	3rd 1927 Level A Corridor 360	Photoelectric	17013633
0011	Smoke Detector	3rd 1927 Level A Top Of Stair 12	Photoelectric	17013635
0014	Smoke Detector	2nd 1927 Level B Top Of Stair 6	Photoelectric	04590076
0015	Smoke Detector	2nd 1927 Level B Outside Stair 6	Photoelectric	04590075
0019	Smoke Detector	2nd 1927 LEV B SMOKE MECH RM 241A	Photoelectric	27013671
0020	Smoke Detector	2nd 1927 Level B Storage 241C	Photoelectric	17013655
0022	Duct Detector	2nd 1927 Level B Mechanical Equipment 237 Return	Photoelectric	17013671
0023	Smoke Detector	2nd 1927 Level B Mechanical Equipment 237 Left Smoke	Photoelectric	17013667
0024	Smoke Detector	2nd 1927 Level B Mechanical Equipment 237 Right Smoke	Photoelectric	17013668
0026	Smoke Detector	2nd 1927 Level B Top Of Stair 5	Photoelectric	04590071
0030	Smoke Detector	2nd 1927 Level B 230 Firedoor Southside By Room 228	Photoelectric	04590069
0031	Smoke Detector	2nd 1927 LEV B SMOKE CORR 230 @ STAIR 5	Photoelectric	04590073
0033	Smoke Detector	2nd 1927 Level B 230 Firedoor Northside By Room 228	Photoelectric	04590068
0035	Smoke Detector	2nd 1927 Level B By Stair 11	Photoelectric	04590091
0036	Smoke Detector	2nd 1927 Level B Stair 11 By Firedoors Eastside	Photoelectric	04590094
0037	Smoke Detector	2nd 1927 Level B Stair 11 By Firedoors Westside	Photoelectric	04590095
0040	Duct Detector	2nd 1927 Level B FCU-C7 Corridor By Classroom 223	Photoelectric	17013665
0042	Smoke Detector	2nd 1927 Level B Entrance To Stair 7	Photoelectric	04590077
0043	Smoke Detector	2nd 1927 Level B Top Of Stair 7	Photoelectric	17013636
0044	Duct Detector	2nd 1927 Level B FCU-C7 Corridor By Classroom 223	Photoelectric	04590089
0045	Smoke Detector	2nd 1927 Level B Top Of Stair 8	Photoelectric	04590081
0046	Smoke Detector	2nd 1927 Level B By Stair 8	Photoelectric	04590082
0048	Smoke Detector	2nd 1927 Level B Custodian 203A	Photoelectric	17013639

0051	Smoke Detector	2nd 1927 Level B Corridor 208 By Room 201	Photoelectric	04590088
0053	Smoke Detector	2nd 1927 Level B Top Of Stair 9	Photoelectric	04590084
0055	Smoke Detector	2nd 1927 Level B Electrical Closet	Photoelectric	17013640
0058	Duct Detector	2nd 1927 Level B RTU-C2 Duct Return	Photoelectric	17013662
0061	Smoke Detector	2nd 1927 Level B Outside Stair 10	Photoelectric	04590096
0063	Duct Detector	2nd 1927 Level B FCU-B10 Corriador By Classroom 250	Photoelectric	17013663
0065	Duct Detector	2nd 1927 Level B FCU-B9 Corriador By Classroom 245	Photoelectric	17013664
0066	Duct Detector	2nd 1927 Level B RTU-C3 Corridor By Classroom 245	Photoelectric	04590102
0067	Smoke Detector	2nd 1927 Level B 248 Firedoor North By Classroom 244	Photoelectric	04590100
0068	Smoke Detector	2nd 1927 Level B 248 Firedoor South By Classroom 244	Photoelectric	04590101
0069	Duct Detector	2nd 1927 Level B RTU-C3 Corridor By Classroom 245	Photoelectric	04590099
0071	Smoke Detector	2nd 1927 Level B Inside Stair 12	Photoelectric	04590105
0072	Smoke Detector	2nd 1927 Level B Outside Stair 12	Photoelectric	04590103
0075	Smoke Detector	2nd 1927 Level B Corridor Between Stair 12/13	Photoelectric	17013653
0076	Smoke Detector	2nd 1927 Level B Corridor Between Stair 12/13	Photoelectric	17013652
0077	Smoke Detector	2nd 1927 Level B Stair 13	Photoelectric	17013650
0078	Smoke Detector	2nd 1927 Level B Stair 13 By Firedoor	Photoelectric	17013651
0084	Smoke Detector	2nd 1927 Level B Inside Stair 10	Photoelectric	04590098
0089	Smoke Detector	2nd 1927 Level B Electrical Closet 217	Photoelectric	17013637
0090	Smoke Detector	2nd 1927 Level B Corridor 253A By Room 201	Photoelectric	04590087
0091	Smoke Detector	2nd 1927 Level B Stair 11	Photoelectric	04590092
0093	Smoke Detector	2nd 1927 Level B Custodian 212	Photoelectric	17013638
0095	Smoke Detector	2nd 1927 Level B IEA Electrical Closet 229B	Photoelectric	17013641
0131	Pull Station	3rd 1927 Level A Top Of Stair	Dual Action	17013630
0135	Pull Station	3rd 1927 Level A Corridor 360	Dual Action	17013629
0138	Pull Station	3rd 1927 Level A By Stair 12	Dual Action	17013634
0141	Pull Station	2nd 1927 Level B Outside Stair 6	Dual Action	04590074
0150	Initiating Device	2nd 1927 Level B Mechanical Equipment 237 Supply	Supporting Field Device	17013669
0152	Initiating Device	2nd 1927 Level B Mechanical Equipment 237 Return	Supporting Field Device	17013670
0157	Pull Station	2nd 1927 Level B Stair 5	Dual Action	04590072
0158	Pull Station	2nd 1927 Level B Outside Stair 5	Dual Action	04590070
0166	Pull Station	2nd 1927 Level B By Stair 11	Dual Action	04590093
0176	Initiating Device	2nd 1927 Level B Electrical Closet 217	Supporting Field Device	17013666
0178	Pull Station	3rd 1927 Level A By Stair 8	Dual Action	04590080
0192	Pull Station	2nd 1927 Level B By Classroom 250	Dual Action	17013648
0195	Initiating Device	2nd 1927 Level B FCU-B10 Duct	Supporting Field Device	17013656
0196	Initiating Device	2nd 1927 Level B RTU-C3 Duct Return	Supporting Field Device	17013658

0197	Initiating Device	2nd 1927 Level B RTU-C3 Duct Supply	Supporting Field Device	17013659
0198	Initiating Device	2nd 1927 Level B FCU-B9 Duct	Supporting Field Device	17013657
0206	Pull Station	2nd 1927 Level B Corridor Between Stair 12/13	Dual Action	17013654
0208	Pull Station	2nd 1927 Level B Stair 13	Dual Action	17013649
0211	Initiating Device	2nd 1927 Level B RTU-C2 Duct Supply	Supporting Field Device	17013661
0213	Initiating Device	2nd 1927 Level B RTU-C2 Duct Return	Supporting Field Device	17013660
0214	Battery	2nd 1927 Level B IEA Electrical Closet 229B Cab 1	Sealed Lead Acid	17013644
0215	Battery	2nd 1927 Level B IEA Electrical Closet 229B Cab 2	Sealed Lead Acid	17013642
0216	Battery	2nd 1927 Level B IEA Electrical Closet 229B Cab 3	Sealed Lead Acid	17013646
0217	Pull Station	2nd 1927 Level B By Stair 10	Dual Action	04590097
0218	Pull Station	2nd 1927 Level B Outside Stair 12	Dual Action	04590104
0219	Pull Station	2nd 1927 Level B Inside Stair 12	Dual Action	04590106
0220	Pull Station	2nd 1927 Level B Top Of Stair 9	Dual Action	04590085
0221	Pull Station	2nd 1927 Level B Stair 9	Dual Action	04590086
0222	Pull Station	2nd 1927 Level B By Stair 7	Dual Action	04590078
0255	Smoke Detector	6th 1927 Level D Home Economic Class North Side	Photoelectric	20665738
0256	Smoke Detector	6th 1927 Level D Home Economic Class South Side	Photoelectric	20665739
0258	Smoke Detector	6th 1927 Level D Bridge	Photoelectric	04590127
0261	Smoke Detector	6th 1927 Level D Custodian 634C	Photoelectric	20665737
0263	Smoke Detector	6th 1927 Level D Storage	Photoelectric	20665736
0264	Smoke Detector	6th 1927 Level D Electrical Room By Media Room	Photoelectric	20665735
0273	Smoke Detector	6th 1927 Level D prep rm 628	Photoelectric	20665990
0277	Smoke Detector	6th 1927 Level D Storage 630A	Photoelectric	20665734
0278	Smoke Detector	6th 1927 Level D Room 623A Storage Thru 622	Photoelectric	20665732
0279	Smoke Detector	6th 1927 Level D telecom rm 631A	Photoelectric	20665991
0280	Smoke Detector	6th 1927 Level D Inside Stair 7	Photoelectric	20665733
0281	Smoke Detector	6th 1927 Level D Outside Stair 7	Photoelectric	04590109
0282	Smoke Detector	6th 1927 Level D Corridor By Room 622	Photoelectric	04590141
0283	Smoke Detector	6th 1927 Level D Bridge	Photoelectric	04590140
0285	Smoke Detector	6th 1927 Level D Wood Shop 616	Photoelectric	20665729
0286	Smoke Detector	6th 1927 Level D office 618D	Photoelectric	20665992
0287	Heat Detector	6th 1927 Level D Wood Shop 616 Left	Fixed Temperature	20665727
0288	Heat Detector	6th 1927 Level D Wood Shop 616 Right	Fixed Temperature	20665728
0289	Smoke Detector	6th 1927 Level D Storage in PC Tech Lab 617	Photoelectric	20665730
0290	Smoke Detector	6th 1927 Level D Stair 8	Photoelectric	20665726
0291	Smoke Detector	6th 1927 Level D Corridor By Wood Shop 616	Photoelectric	04590112
0292	Heat Detector	6th 1927 Level D Metal Shop 616A	Fixed Temperature	20665996
0293	Heat Detector	6th 1927 Level D Finishing Shop 616A	Fixed Temperature	20665997
0301	Smoke Detector	5th 1927 Level E By Storage 530	Photoelectric	04590148

0302	Smoke Detector	5th 1927 Level	E Outside Stair 5	Photoelectric	04590149
0303	Smoke Detector	5th 1927 Level	E Outside Stair 6	Photoelectric	04590153
0304	Smoke Detector	5th 1927 Level	E Stair 6	Photoelectric	04590154
0306	Smoke Detector	5th 1927 Level	E Outside Cafe	Photoelectric	04590151
0309	Smoke Detector	5th 1927 Level	E Custodian	Photoelectric	20665743
0316	Heat Detector	5th 1927 Level	E Crawl Space	Fixed Temperature	20665744
0317	Heat Detector	5th 1927 Level	E Crawl Space	Fixed Temperature	20665745
0318	Heat Detector	5th 1927 Level	E Crawl Space	Fixed Temperature	20665746
0319	Heat Detector	5th 1927 Level	E Crawl Space	Fixed Temperature	20665747
0320	Heat Detector	5th 1927 Level	E Crawl Space	Fixed Temperature	20665748
0321	Heat Detector	5th 1927 Level	E Crawl Space	Fixed Temperature	20665749
0322	Heat Detector	5th 1927 Level	E Crawl Space	Fixed Temperature	20665750
0323	Heat Detector	5th 1927 Level	E Crawl Space	Fixed Temperature	20665751
0326	Duct Detector	5th 1927 Level	E Machine rm 522	Photoelectric	20666006
0327	Duct Detector	5th 1927 Level	E Machine rm 522	Photoelectric	20666000
0328	Duct Detector	5th 1927 Level	E Machine rm 522	Photoelectric	20666004
0333	Smoke Detector	5th 1927 Level	E Machine rm 522	Photoelectric	20666008
0335	Smoke Detector	5th 1927 Level	E Machine rm 522	Photoelectric	20665999
0337	Smoke Detector	5th 1927 Level	E Stair 4	Photoelectric	04590147
0338	Smoke Detector	5th 1927 Level	E Stair 5	Photoelectric	04590150
0339	Smoke Detector	6th 1927 Level	D Workroom 634	Photoelectric	20665725
0340	Smoke Detector	5th 1927 Level	E Electrical closet by 523	Photoelectric	20665998
0341	Smoke Detector	6th 1927 Level	D Stair 6	Photoelectric	04590123
0342	Smoke Detector	6th 1927 Level	D Corridor By Sewing Classroom 640	Photoelectric	04590122
0343	Smoke Detector	6th 1927 Level	D Corridor 638A	Photoelectric	04590126
0344	Smoke Detector	6th 1927 Level	D Storage in Cisco Computer Lab 619	Photoelectric	20665731
0345	Smoke Detector	6th 1927 Level	D Inside Stair 5	Photoelectric	04590119
0346	Smoke Detector	6th 1927 Level	D Stair 5	Photoelectric	04590118
0347	Smoke Detector	6th 1927 Level	D Electrical Room	Photoelectric	20665740
0376	Pull Station	5th 1927 Level	E Outside Cafe East Wall	Dual Action	04590157
0380	Pull Station	6th 1927 Level	D By Stair 6	Dual Action	04590121
0383	Pull Station	6th 1927 Level	D Inside Stair 5	Dual Action	04590120
0384	Pull Station	5th 1927 Level	E Outside Cafe North Wall	Dual Action	04590161
0392	Pull Station	6th 1927 Level	D Stair 10	Dual Action	20665720
0393	Initiating Device	6th 1927 Level	D ACU-D4 Supply	Supporting Field Device	20665723
0394	Initiating Device	6th 1927 Level	D ACU-D4 Return	Supporting Field Device	20665724
0395	Initiating Device	6th 1927 Level	D ACU-D3 Supply	Supporting Field Device	20665721
0396	Initiating Device	6th 1927 Level	D ACU-D3 Return	Supporting Field Device	20665722
0405	Pull Station	6th 1927 Level	D Stair 8	Dual Action	04590114
0406	Pull Station	5th 1927 Level	E Outside Stair 6	Dual Action	04590152
0409	Pull Station	5th 1927 Level	E Exit By Cafe	Dual Action	04590155
0410	Pull Station	5th 1927 Level	E Outside Cafe Faculty Dining	Dual Action	04590163
0411	Initiating Device	5th 1927 Level	E Outside Cafe Faculty Dining ACU-2 Return	Supporting Field Device	04590167
0412	Initiating Device	5th 1927 Level	E Outside Cafe Faculty	Supporting Field	04590166

0413	Initiating Device	Dining ACU-2 Supply 5th 1927 Level E Outside Cafe Faculty	Device Supporting Field	04590165
0414	Initiating Device	Dining ACU-1 Return 5th 1927 Level E Outside Cafe Faculty	Device Supporting Field	04590164
0417	Pull Station	Dining ACU-1 Supply 5th 1927 Level E Outside Cafe Entrance	Dual Action	20665741
0418	Pull Station	5th 1927 Level E Outside Cafe East Stair Tower	Dual Action	04590158
0419	Pull Station	5th 1927 Level E Outside Cafe Stair 12	Dual Action	04590162
0421	Pull Station	5th 1927 Level E Cafe Stair 13	Dual Action	04590160
0446	Initiating Device	5th 1927 Level E Machine rm 522	Supporting Field Device	20666003
0448	Initiating Device	5th 1927 Level E Machine rm 522	Supporting Field Device	20666007
0450	Initiating Device	5th 1927 Level E Machine rm 522	Supporting Field Device	20666005
0454	Pull Station	5th 1927 Level E Stair 7	Dual Action	04590142
0455	Pull Station	5th 1927 Level E By Crawl Space	Dual Action	04590144
0456	Pull Station	5th 1927 Level E Stair 7 By Exit	Dual Action	04590143
0457	Pull Station	1st 1927 Level C Rear Side Exit Aud	Dual Action	04590035
0458	Pull Station	1st 1927 Level C Side Exit Aud	Dual Action	04590037
0459	Pull Station	5th 1927 Level D Outside Stair 7	Dual Action	04590110
0460	Pull Station	5th 1927 Level E Outside Stair 4	Dual Action	04590146
0461	Pull Station	5th 1927 Level E Outside Stair 5 By Room 521	Dual Action	20665742
0464	Battery	5th E Level Electrical Room 522B #1	Sealed Lead Acid	20666001
0465	Battery	5th E Level Electrical Room 522B #2	Sealed Lead Acid	20666002
0472	Pull Station	6th 1927 Level D Corridor 638A	Dual Action	04590125
0472	Pull Station	6th 1927 Level D Corridor 638A	Dual Action	04590U34
0475	Pull Station	6th 1927 Level D Stair 10 In Library	Dual Action	04590116
0476	Pull Station	6th 1927 Level D Stair 10 In Library	Dual Action	04590117
0477	Pull Station	6th 1927 Level D Stair 10	Dual Action	04590111
0479	Pull Station	1st 1927 Level C Top Stair 17	Dual Action	04590036

Building: Stamford BOE-Stamford High School

Control Panel: 2

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 01				
0615	Battery	1st Nurses Office Cab 5	Sealed Lead Acid	04590009
Zone/Circuit: 05				
0001	Smoke Detector	1st 1927 Level C Stair 6	Photoelectric	04590031
0004	Smoke Detector	1st 1927 Level C Stage Electrical Room	Photoelectric	20665704
0005	Smoke Detector	1st 1927 Level C Stage Storage	Photoelectric	20665707
0006	Smoke Detector	1st 1927 Level C Stage Storage Room	Photoelectric	20665706
0007	Smoke Detector	1st 1927 Level C Corridor By Stage By FireDoor	Photoelectric	04590032
0007	Smoke Detector	1st 1927 Level C By Stair 6	Photoelectric	04590030
0008	Smoke Detector	1st 1927 Level C By Stair 5	Photoelectric	04590027
0009	Smoke Detector	1st 1927 Level C Stair 5	Photoelectric	04590028
0012	Duct Detector	1st 1927 Level C By Room 132 FCU-C12	Photoelectric	04590025
0013	Smoke Detector	1st 1927 Level C South Firedoor By Room 130	Photoelectric	04590024
0017	Smoke Detector	1st 1927 Level C Stair 11	Photoelectric	20665771
0019	Smoke Detector	1st 1927 Level C North Firedoor By Room 130	Photoelectric	04590023
0020	Smoke Detector	1st 1927 Level C Stair 16	Photoelectric	04590062
0021	Smoke Detector	1st 1927 Level C Stair 16	Photoelectric	04590060
0023	Smoke Detector	1st 1927 Level C Custodian 124A	Photoelectric	20665772
0024	Smoke Detector	1st 1927 Level C By Inside Stair 7	Photoelectric	04590059
0025	Smoke Detector	1st 1927 Level C By Heath Center 119A	Photoelectric	04590055
0026	Smoke Detector	1st 1927 Level C By Room 120	Photoelectric	04590056
0027	Smoke Detector	1st 1927 Level C By Outside Stair 7	Photoelectric	04590057
0028	Smoke Detector	1st 1927 Level C Heath Center 119A	Photoelectric	20665773
0029	Smoke Detector	1st 1927 Level C Heath Center 119A	Photoelectric	20665774
0031	Smoke Detector	1st 1927 Level C By Stair 8	Photoelectric	04590053
0032	Smoke Detector	1st 1927 Level C By Stair 8	Photoelectric	04590083
0033	Smoke Detector	1st 1927 Level C Custodian 112	Photoelectric	20665775
0037	Smoke Detector	1st 1927 Level C By Learning Center	Photoelectric	04590052
0038	Smoke Detector	1st 1927 Level C By Room 102A	Photoelectric	04590051
0040	Smoke Detector	1st 1927 Level C By Room 154	Photoelectric	04590046
0041	Smoke Detector	1st 1927 Level C By Nurses Room 149	Photoelectric	04590045
0042	Smoke Detector	1st 1927 LEV C SMOKE CUSTODIAN RM 155A	Photoelectric	14590046
0044	Smoke Detector	1st 1927 Level C Room 150 Nurses Office Electrical Closet	Photoelectric	23587024
0048	Duct Detector	1st 1927 Level C C9 corr145	Photoelectric	20665711
0049	Smoke Detector	1st 1927 Level C By Professional Library 144	Photoelectric	04590044
0050	Smoke Detector	1st 1927 Level C By Professional Library 144	Photoelectric	04590043
0053	Duct Detector	1st 1927 Level C Corridor By Room 143	Photoelectric	20665710

		FCU-C2		
0056	Smoke Detector	1st 1927 Level C Guidance Storage By Vault	Photoelectric	20665778
0057	Smoke Detector	1st 1927 Level C Guidance Phone Room	Photoelectric	20665777
0068	Smoke Detector	1st 1927 Level C Storage	Photoelectric	20665700
0069	Smoke Detector	1st 1927 Level C Corridor By Stage By FireDoor	Photoelectric	04590033
0071	Smoke Detector	1st 1927 Level C By Room 167	Photoelectric	04590020
0072	Smoke Detector	1st 1927 Level C By Room 167	Photoelectric	04590019
0073	Smoke Detector	1st 1927 Level C By Room 162A	Photoelectric	04590018
0074	Smoke Detector	1st 1927 Level C By Stair 10	Photoelectric	04590017
0075	Smoke Detector	1st 1927 Level C By Small Auditorium 101	Photoelectric	04590048
0076	Smoke Detector	1st 1927 Level C vestibule lobby by room 156	Photoelectric	04590049
0077	Smoke Detector	1st 1927 Level C Stair12	Photoelectric	04590041
0078	Smoke Detector	1st 1927 Level C By Guidance 147	Photoelectric	04590040
0087	Smoke Detector	2nd 1927 Level B Top Of Stair 16	Photoelectric	04590067
0097	Smoke Detector	1st 1927 Level C Storage	Photoelectric	20665701
0098	Smoke Detector	1st 1927 Level C Custodian	Photoelectric	20665776
0100	Smoke Detector	1st 1927 Level C In Stair 10	Photoelectric	20665770
0101	Smoke Detector	2nd 1927 Level B Entrance To Stair 16	Photoelectric	04590066
0133	Battery	1st Nurses Booster Cab 2	Sealed Lead Acid	04590012
0134	Battery	1st Nurses Office Booster Cab 1	Sealed Lead Acid	04590010
0136	Pull Station	1st 1927 Level C By Stair 10	Dual Action	04590016
0142	Pull Station	1st 1927 Level C By Stair 6	Dual Action	23587022
0143	Pull Station	1st 1927 Level C Rear Stage	Dual Action	20665703
0144	Pull Station	1st 1927 Level C Side Stage	Dual Action	04590034
0145	Pull Station	1st 1927 Level C Stage Exit Hall	Dual Action	20665705
0148	Pull Station	1st 1927 Level C By Stair 5	Dual Action	04590026
0149	Pull Station	2nd 1927 Level B Upper Stage Mech	Dual Action	20665708
0153	Pull Station	1st 1927 Level C By Stair 11	Dual Action	04590021
0154	Pull Station	1st 1927 Level C Stair 16	Dual Action	04590063
0155	Pull Station	1st 1927 Level C Stair 5	Dual Action	23587023
0158	Pull Station	1st 1927 Level C By Outside Stair 7	Dual Action	04590058
0159	Pull Station	1st 1927 Level C Stair 16	Dual Action	04590061
0162	Pull Station	2nd 1927 Level B Stair 16	Dual Action	04590064
0165	Pull Station	1st 1927 Level C By Stair 8	Dual Action	23587021
0166	Pull Station	2nd 1927 Level B Entrance To Stair 16	Dual Action	04590065
0170	Pull Station	1st 1927 Level C Stair 9	Dual Action	04590050
0172	Pull Station	1st 1927 Level C By Small Auditorium 101	Dual Action	04590047
0178	Pull Station	1st 1927 Level C Main Entrance	Dual Action	04590015
0189	Pull Station	1st 1927 Level C Stair12 By Guidance 147	Dual Action	04590039
0190	Pull Station	1st 1927 Level C Aud Rear Entrance	Dual Action	04590038
0191	Pull Station	1st 1927 Level C By Aud Entrance	Dual Action	20665709
0192	Pull Station	1st 1927 Level C Stair12	Dual Action	04590042
0193	Pull Station	1st 1927 Level C Stair 13	Dual Action	20665779

Building: Stamford BOE-Stamford High School			Control Panel: 3	
<i>The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.</i>				
Address	Device Type	Location	Type	ScanID
Zone/Circuit: 01				
0615	Battery	1st Nurses Office Cab 2	Sealed Lead Acid	04590006

Building: Stamford BOE-Stamford High School

Control Panel: 4

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 02				
0001	Smoke Detector	6th 1971 Level D/1 By Storage By Room 609	Photoelectric	20665752
0005	Smoke Detector	6th 1971 Level D/1 By Storage By Room 603	Photoelectric	20665753
0007	Smoke Detector	6th 1971 Level D/1 Storage Room 602A	Photoelectric	20665995
0011	Smoke Detector	6th 1927 Level D Bridge	Photoelectric	04590129
0012	Smoke Detector	6th 1927 Level D Bridge	Photoelectric	04590128
0013	Smoke Detector	6th 1971 Level D/1 By Stair 601C	Photoelectric	04590131
0016	Smoke Detector	6th 1971 Level D/1 Bridge	Photoelectric	04590139
0017	Smoke Detector	6th 1971 Level D/1 Bridge	Photoelectric	04590138
0018	Smoke Detector	6th 1971 Level D/1 By Room 610	Photoelectric	04590133
0022	Duct Detector	6th 1927 Level D class rm 610	Photoelectric	20665994
0023	Smoke Detector	6th 1927 Level D classroom 610	Photoelectric	20665993
0029	Smoke Detector	6th 1971 Level D/1 By Room 615	Photoelectric	04590136
0031	Smoke Detector	6th 1971 Level D/1 Electrical Room	Photoelectric	20665754
0032	Smoke Detector	5th 1971 Level E/2 Storage	Photoelectric	20665768
0034	Smoke Detector	5th 1971 Level E/2 Storage 533	Photoelectric	20665769
0036	Smoke Detector	5th 1971 Level E/2 Custodian	Photoelectric	20665780
0039	Smoke Detector	5th 1971 Level E/2 Bridge	Photoelectric	20665783
0040	Smoke Detector	5th 1971 Level E/2 Bridge	Photoelectric	20665784
0041	Smoke Detector	5th Prep Room 501B 1971 LEV E SMOKE PLANT 5011	Photoelectric	10665782
0042	Smoke Detector	5th Prep Room 501B 1971 LEV E SMOKE PLANT 5011	Photoelectric	10665781
0043	Smoke Detector	5th 1971 Level E/2 Stair 1	Photoelectric	20665781
0044	Smoke Detector	5th 1971 Level E/2 Stair 1	Photoelectric	20665782
0045	Smoke Detector	5th 1971 Level E/2 In Stairs	Photoelectric	20665765
0046	Smoke Detector	5th 1971 Level E/2 By Stairs	Photoelectric	20665764
0047	Smoke Detector	5th 1971 Level E/2 By Firedoor	Photoelectric	20665766
0049	Smoke Detector	5th 1971 Level E/2 Electrical Room	Photoelectric	20665763
0051	Smoke Detector	5th 1971 Level E/2 By Room 515	Photoelectric	20665761
0052	Smoke Detector	5th 1971 Level E/2 In Stair	Photoelectric	20665760
0147	Pull Station	6th 1971 Level D/1 Stair 601C	Dual Action	04590130
0150	Pull Station	6th 1971 Level D/1 Stair 601C	Dual Action	04590132
0153	Pull Station	6th 1971 Level D/1 By Room 610	Dual Action	04590134
0155	Initiating Device	6th 1971 Level D/1 Electrical Room FCU-D5	Supporting Field Device	20665755
0157	Initiating Device	6th 1971 Level D/1 Electrical Room FCU-D2 Return	Supporting Field Device	20665756
0158	Initiating Device	6th 1971 Level D/1 Electrical Room FCU-D2 Return	Supporting Field Device	20665757
0160	Initiating Device	6th 1971 Level D/1 Electrical Room FCU-D1 Return	Supporting Field Device	20665758

0161	Initiating Device	6th 1971 Level D/1 Electrical Room FCU-D1 Supply	Supporting Field Device	20665759
0162	Pull Station	6th 1971 Level D/1 By Room 615	Dual Action	04590135
0164	Pull Station	6th 1971 Level D/1 In Stair by Room 615	Dual Action	04590137
0172	Pull Station	5th 1971 Level E/2 In By Stair 1	Dual Action	20665786
0176	Pull Station	5th 1971 Level E/2 By Stair 1	Dual Action	20665785
0177	Pull Station	5th 1971 Level E/2 By Firedoor	Dual Action	20665767
0181	Pull Station	5th 1971 Level E/2 By Room 515	Dual Action	20665762
0257	Smoke Detector	F Level Stair 3	Photoelectric	20665829
0260	Smoke Detector	F Level Storage Room	Photoelectric	20665839
0261	Smoke Detector	F Level Equipment Room	Photoelectric	20665840
0262	Smoke Detector	F Level Gym Mechanical	Photoelectric	20665980
0263	Smoke Detector	F Level Gym Electrical Room	Photoelectric	20665919
0272	Smoke Detector	F Level Gym Upper Mechanical	Photoelectric	20665916
0275	Duct Detector	F Level Gym Upper Mechanical	Photoelectric	20665918
0276	Duct Detector	F Level Gym Upper Mechanical	Photoelectric	20665914
0277	Smoke Detector	F Level Gym Upper Mechanical	Photoelectric	20665912
0278	Smoke Detector	F Level Stair 2	Photoelectric	20665830
0282	Smoke Detector	F Level Gym Corridor Storage/Elevator Room	Photoelectric	20665831
0283	Smoke Detector	F Level Gym Corridor Storage	Photoelectric	20665832
0284	Smoke Detector	F Level Mech Room Above Girls Locker Room	Photoelectric	20665907
0285	Duct Detector	F Level Mech Room Above Girls Locker Room AHU-F1 Supply	Photoelectric	20665826
0286	Duct Detector	F Level Mech Room Above Girls Locker Room AHU-F1 Return	Photoelectric	20665825
0287	Smoke Detector	F Level Mech Room Above Girls Locker Room	Photoelectric	20665908
0288	Smoke Detector	F Level Mech Room Above Girls Locker Room	Photoelectric	20665909
0291	Duct Detector	F Level Mech Room Above Girls Locker Room AHU-F3 Supply	Photoelectric	20665822
0292	Duct Detector	F Level Mech Room Above Girls Locker Room AHU-F2 Supply	Photoelectric	20665824
0306	Smoke Detector	F Level Mech Room Above Girls Locker Room Above Motor	Photoelectric	20665820
0307	Smoke Detector	F Level Stair 1	Photoelectric	20665905
0308	Smoke Detector	4th 1971 Level F/4 Lobby By Auto	Photoelectric	20665787
0385	Pull Station	F Level Boys Locker Room	Dual Action	23587019
0386	Pull Station	F Level Gym Lobby	Dual Action	20665900
0387	Pull Station	F Level Boys Locker Room	Dual Action	51386305
0390	Pull Station	F Level Gym	Dual Action	20665986
0393	Pull Station	F Level Gym Lobby	Dual Action	20665989
0394	Pull Station	F Level Gym	Dual Action	20665985
0403	Initiating Device	F Level Gym Upper Mechanical	Supporting Field Device	20665913
0404	Initiating Device	F Level Gym Upper Mechanical	Supporting Field Device	20665915
0407	Pull Station	F Level Gym	Dual Action	20665984
0408	Pull Station	F Level Gym	Dual Action	20665983
0409	Pull Station	F Level Gym	Dual Action	20665982

0410	Pull Station	F Level Gym	Dual Action	20665981
0411	Pull Station	F Level Gym	Dual Action	20665988
0412	Pull Station	F Level Gym	Dual Action	20665987
0425	Initiating Device	F Level Mech Room Above Girls Locker Room AHU-F1 Return	Supporting Field Device	20665827
0426	Initiating Device	F Level Mech Room Above Girls Locker Room AHU-F1 Supply	Supporting Field Device	20665828
0429	Initiating Device	F Level Mech Room Above Girls Locker Room AHU-F3 Supply	Supporting Field Device	20665821
0431	Initiating Device	F Level Mech Room Above Girls Locker Room AHU-F2 Supply	Supporting Field Device	20665823
0437	Pull Station	F Level Mech Room Above Girls Locker Room	Dual Action	20665906
0440	Pull Station	F Level Dance Class 405	Dual Action	20665903
0441	Pull Station	F Level Exercise Bike Room	Dual Action	20665904
0442	Pull Station	4th 1971 Level F/4 Outside Choral 402	Dual Action	20665789
0445	Pull Station	4th 1971 Level F/4 Choral 402	Dual Action	20665788

Building: Stamford BOE-Stamford High School

Control Panel: 12 - EST EST-3

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 04				
0001	Battery	F Level IT Room 452 Booster 1	Sealed Lead Acid	20665851
0001	Battery	F Level IT Room 452 Booster 2	Sealed Lead Acid	20665850
0001	Battery	F Level IT Room 452 Booster 3	Sealed Lead Acid	20665847
Zone/Circuit: 05				
0001	Smoke Detector	7th Corridor By 724	Photoelectric	20665878
0002	Smoke Detector	7th Corridor By 724	Photoelectric	20665879
0003	Smoke Detector	7th Corridor By 724	Photoelectric	20665880
0004	Smoke Detector	7th Corridor By 718	Photoelectric	20665887
0005	Heat Detector	7th Mens Room	Fixed Temperature	20665890
0006	Heat Detector	7th Womens Room	Fixed Temperature	20665886
0007	Heat Detector	7th Custodians Closet 722	Fixed Temperature	20665891
0007	Heat Detector	7th Pantry	Fixed Temperature	20665882
0008	Smoke Detector	7th Storage 732	Photoelectric	20665881
0009	Smoke Detector	7th Corridor By Storage 732	Photoelectric	20665885
0010	Heat Detector	7th Mens Room	Fixed Temperature	20665884
0011	Heat Detector	7th Womens Room	Fixed Temperature	20665883
0012	Smoke Detector	7th Outside Room 716	Photoelectric	20665893
0013	Smoke Detector	7th Outside Room 714	Photoelectric	20665894
0014	Smoke Detector	7th Outside Room 714	Photoelectric	20665895
0016	Smoke Detector	7th Outside Room 712	Photoelectric	20665896
0017	Smoke Detector	7th Outside Room 710	Photoelectric	20665897
0018	Smoke Detector	7th Stair 2	Photoelectric	20665795
0022	Heat Detector	7th Womens Locker 707 Bathroom	Fixed Temperature	20665799
0023	Heat Detector	7th Mens Locker 707 Bathroom	Fixed Temperature	20665899
0024	Smoke Detector	7th Electrical Closet 720	Photoelectric	20665888
0025	Smoke Detector	7th Storage Math 717	Photoelectric	20665892
0026	Smoke Detector	7th Data Room 719	Photoelectric	20665889
0027	Heat Detector	7th Womens Locker 707	Fixed Temperature	20665797
0028	Heat Detector	7th Womens Locker 707	Fixed Temperature	20665798
0029	Heat Detector	7th Mens Locker 707	Fixed Temperature	20665898
0030	Smoke Detector	F Level Gym Corridor By Stair 18	Photoelectric	20665833
0031	Smoke Detector	F Level Gym Corridor	Photoelectric	20665836
0032	Smoke Detector	F Level Gym Corridor	Photoelectric	20665835
0033	Smoke Detector	F Level Gym Corridor By Stair 18	Photoelectric	20665834
0034	Smoke Detector	F Level Parking Garage Exit Corridor	Photoelectric	20665837
0035	Smoke Detector	F Level Parking Garage Exit Corridor	Photoelectric	20665838
0040	Smoke Detector	F Level Mechanical Room 451	Photoelectric	20665844
0041	Smoke Detector	F Level Electrical Service 453	Photoelectric	20665855
0042	Smoke Detector	F Level Storage 455	Photoelectric	20665857
0043	Smoke Detector	F Level IT Room 452	Photoelectric	20665854
0044	Smoke Detector	F Level Corridor 450	Photoelectric	20665845
0046	Smoke Detector	F Level Parking Garage Exit	Photoelectric	20665842
0047	Smoke Detector	F Level Stair 18	Photoelectric	20665901

0048	Smoke Detector	7th Ramp	Photoelectric	20665791
0049	Smoke Detector	7th Ramp	Photoelectric	20665790
0050	Smoke Detector	7th Ramp	Photoelectric	20665792
0051	Smoke Detector	F Level Parking Garage Exit	Photoelectric	20665841
0052	Heat Detector	F Level Tank Room 456	Fixed Temperature	20665856
0053	Smoke Detector	7th Gym Vestibule	Photoelectric	20665796
0126	Pull Station	7th Stair 18	Dual Action	20665877
0130	Pull Station	7th Stair 19	Dual Action	20665794
0131	Pull Station	7th Gym	Dual Action	20665717
0133	Pull Station	7th Elevator Lobby	Dual Action	20665793
0142	Pull Station	F Level Stair 18	Dual Action	20665902
0143	Pull Station	F Level Parking Garage Exit	Dual Action	20665843
0211	Heat Detector	9th Mens Room 917A	Fixed Temperature	20665713
0251	Smoke Detector	8th Corridor By Room 810	Photoelectric	20665867
0252	Smoke Detector	8th Corridor By Room 812	Photoelectric	20665868
0253	Smoke Detector	8th Corridor By Room 812	Photoelectric	20665869
0254	Smoke Detector	8th By Elevator Lobby	Photoelectric	20665870
0256	Smoke Detector	8th Data Room 819	Photoelectric	20665863
0257	Smoke Detector	8th Electrical Closet 820	Photoelectric	20665862
0258	Heat Detector	8th Mens Room 817A	Fixed Temperature	20665801
0259	Heat Detector	8th Womens Room 817B	Fixed Temperature	20665802
0260	Heat Detector	8th Womens Room	Fixed Temperature	20665861
0261	Smoke Detector	8th Custodians Closet 822	Photoelectric	20665860
0262	Heat Detector	8th Mens Room	Fixed Temperature	20665800
0263	Smoke Detector	8th Outside Room 816	Photoelectric	20665871
0264	Smoke Detector	8th Outside Room 818	Photoelectric	20665872
0265	Smoke Detector	8th Outside Room 824	Photoelectric	20665873
0266	Smoke Detector	8th Outside Room 826	Photoelectric	20665874
0267	Smoke Detector	8th Stair 18	Photoelectric	20665875
0268	Smoke Detector	9th Stair 19	Photoelectric	20665803
0269	Smoke Detector	9th By Stair 19	Photoelectric	20665804
0270	Smoke Detector	9th Corridor By Room 912	Photoelectric	20665806
0271	Smoke Detector	9th Corridor By Room 914	Photoelectric	20665807
0273	Smoke Detector	9th Elevator Lobby	Photoelectric	20665808
0274	Smoke Detector	9th By Stair in 18	Photoelectric	20665814
0275	Smoke Detector	9th By Stair 18	Photoelectric	20665813
0276	Smoke Detector	9th Corridor By Room 924	Photoelectric	20665812
0277	Smoke Detector	9th Corridor By Room 924	Photoelectric	20665811
0278	Smoke Detector	9th Corridor By Room 918	Photoelectric	20665810
0279	Smoke Detector	9th Corridor By Room 916	Photoelectric	20665809
0280	Smoke Detector	9th Custodians Closet 922	Photoelectric	20665818
0281	Heat Detector	9th Womens Room 921	Fixed Temperature	20665817
0282	Smoke Detector	9th Electrical Room 920	Photoelectric	20665816
0283	Smoke Detector	9th Data Room 919	Photoelectric	20665815
0284	Duct Detector	8th By Stair 18 Supply	Photoelectric	20665865
0285	Duct Detector	8th By Stair 18 Return	Photoelectric	20665864
0286	Duct Detector	9th By Stair 19 Return	Photoelectric	20665805
0287	Duct Detector	9th By Stair 18 Supply	Photoelectric	20665716
0292	Heat Detector	9th Mens Room 922	Fixed Temperature	20665712
0309	Smoke Detector	7th Gym Storage	Photoelectric	20665859
0310	Smoke Detector	7th Gym Storage	Photoelectric	20665858
0312	Heat Detector	9th Womens Room 917B	Fixed Temperature	20665714
0376	Pull Station	8th Stair 19	Dual Action	20665866

0377	Pull Station	8th Stair 18	Dual Action	20665876
0380	Pull Station	9th By Stair 18	Dual Action	20665715
0383	Pull Station	9th By Stair 19	Dual Action	20665819
0386	Pull Station	7th Gym	Dual Action	20665719
0387	Pull Station	7th Gym	Dual Action	20665718
Zone/Circuit: 08				
0615	Battery	F Level IT Room 452 Panel Set	Sealed Lead Acid	20665852

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-West Hill High
School
125 Roxbury Road
Stamford, CT 06904

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Mar 24, 2020



Building: Stamford BOE-West Hill High School
Contact: Davor Lucaj
Title: Facilities Trades Manager

Company: TPC Associates, Inc.
Contact: Michael Hernandez
Title: Fire Alarm Inspector

Executive Summary





Generated by: BuildingReports.com







Building Information		
Building: Stamford BOE-West Hill High School	Contact: Davor Lucaj	
Address: 125 Roxbury Road	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06904	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Michael Hernandez	
Address: 261 Pepe's Farm Road	Phone: 203-878-1321	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: mhernandez@tpcsystems.com	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.27%	1	100.00%	0	0%	1	100.00%
Control	22	5.96%	22	100.00%	20	90.91%	2	9.09%
Initiating	346	93.77%	343	99.13%	343	100.00%	0	0%
Totals	369	100%	366	99.19%	363	99.18%	3	0.82%
Certification								
Company: TPC Associates, Inc.				Building: Stamford BOE–West Hill High School				
Inspector: Michael Hernandez				Contact: Davor Lucaj				
								
Signed: Mar 24, 2020 10:57:19 AM				Signed: Mar 24, 2020 10:57:17 AM				
Michael Hernandez Certifications								
Certification Type						Number		
Inspectors Boot Camp								

Discrepancy Report

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill High School			Control Panel: 1	
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
 ScanID	 Location	 Problem	Address	 Reference
<i>Control</i>				
Battery				
04060433	Basement Boiler Room Booster Cab 2	Failed Test	1	NFPA 72 Table 10.4.2.2.5(a-e)
20667138	Basement Boiler Room Booster Cab 6	Failed Test	1	NFPA 72 Table 10.4.2.2.5(a-e)

Building: Stamford BOE-West Hill High School		Control Panel: n/a		
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i></p>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
Sound Test	 Location	 Problem	Device	 Reference
<i>Sound Testing</i>				
Sound Test	 Location	 Problem	Device	 Reference
Sound Test Points				
0001	WHOLE FACILITY	Damaged/Worn	Sound Test	

Proposed Solutions Report

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill High School					Control Panel: 1	
<p><i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i></p>						
ScanID	Location	Solution	Model #	Cost	Fix	
Control						
Battery						
04060433	Basement Boiler Room Booster Cab 2	Replace	UB1280	T/M	<input type="checkbox"/>	
20667138	Basement Boiler Room Booster Cab 6	Replace	UB1280	T/M	<input type="checkbox"/>	
Building: Stamford BOE-West Hill High School					Control Panel: n/a	
<p><i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i></p>						
ScanID	Location	Solution	Description	Cost	Fix	
Sound Testing						
Sound Test						
0001	WHOLE FACILITY	Replace	Red, Square, Wall – Surface	T/M	<input type="checkbox"/>	
				PO #: (none)	T/M	

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill High School			Control Panel: 1		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>					
Device Type	Location		Service	Time	Date
Passed					
Control					
Annunciator	1st A Wing Custodians office by loading dock		Visually Checked	10:31:23 AM	03/24/2020
Battery	Basement Boiler Room Battery Cab 2		Visually Checked	9:39:16 AM	03/24/2020
Battery	Basement Boiler Room Booster Cab 1		Visually Checked	9:23:41 AM	03/24/2020
Battery	Basement Boiler Room Booster Cab 6		Visually Checked	9:17:28 AM	03/24/2020
Battery	Basement Storage Room By Custodian Office Battery Cab 3		Visually Checked	10:52:46 AM	03/24/2020
Battery	Basement Storage Room By Custodian Office Booster Cab 1		Visually Checked	10:48:37 AM	03/24/2020
Battery	Basement Storage Room By Custodian Office Booster Cab 2		Visually Checked	10:45:49 AM	03/24/2020
Battery	Basement Storage Room By Custodian Office Booster Cab 3		Visually Checked	10:43:21 AM	03/24/2020
Battery	Basement Storage Room By Custodian Office Booster Cab 4		Visually Checked	10:40:40 AM	03/24/2020
Battery	1st 500 Electrical Room		Visually Checked	8:37:52 AM	03/24/2020
Battery	1st 500 Electrical Room		Visually Checked	8:38:48 AM	03/24/2020
Battery	1st Gym Electrical/Custodian		Visually Checked	8:13:37 AM	03/24/2020
Battery	1st Raynur Office Storage Room Battery Cab 1		Visually Checked	9:55:36 AM	03/24/2020
Battery	1st Raynur Office Storage Room Battery Cab 2		Visually Checked	9:52:28 AM	03/24/2020
Battery	1st Raynur Office Storage Room Battery Cab 2 (Lower Set)		Visually Checked	9:49:23 AM	03/24/2020
Battery	1st Raynur Office Storage Room Battery Cab 2 (Upper Set)		Visually Checked	9:48:35 AM	03/24/2020
Battery	1st Raynur Office Storage Room Battery Cab 3 (Right Set)		Visually Checked	9:46:18 AM	03/24/2020
Battery	1st Raynur Office Storage Room Battery Cab 4		Visually Checked	10:03:36 AM	03/24/2020
Power Supply	2nd 500 Wing Electrical Room		Visually Checked	8:37:48 AM	03/24/2020
Power Supply	2nd 500 Wing Electrical Room		Visually Checked	8:37:50 AM	03/24/2020
Initiating					
Beam Detector	New Gym		Visually Checked	8:06:54 AM	03/24/2020
Beam Detector	New Gym		Visually Checked	8:06:55 AM	03/24/2020
Duct Detector	2nd North Between Boys/Girls Room Above Ceiling		Visually Checked	7:46:35 AM	03/24/2020
Duct Detector	2nd 600 Wing	Corridor By Room 606	Visually Checked	7:48:07 AM	03/24/2020
Duct Detector	2nd 600 Wing	Corridor By Room 613	Visually Checked	7:49:19 AM	03/24/2020
Duct Detector	2nd 600 Wing	Corridor By Room 613-614	Visually Checked	7:49:26 AM	03/24/2020
Duct Detector	2nd 600 Wing	Room 615/616 Prep Room 3	Visually Checked	7:50:50 AM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Duct Detector	2nd 600 Wing Room 615/616 Prep Room 3	Visually Checked	10:21:55 AM	03/24/2020
Duct Detector	2nd 600 Wing Corridor Outside 609	Visually Checked	7:48:03 AM	03/24/2020
Duct Detector	Penthouse A Wing AC-1	Visually Checked	9:56:20 AM	03/24/2020
Duct Detector	Penthouse A Wing AC-2	Visually Checked	9:56:44 AM	03/24/2020
Duct Detector	Penthouse A Wing AC-3	Visually Checked	9:56:49 AM	03/24/2020
Duct Detector	Penthouse C Wing AC-7 Return	Visually Checked	9:07:41 AM	03/24/2020
Duct Detector	Penthouse C Wing AC-9	Visually Checked	9:05:26 AM	03/24/2020
Duct Detector	Penthouse C Wing AC-9 Supply	Visually Checked	9:05:41 AM	03/24/2020
Duct Detector	Penthouse C Wing Catwalk North Entrance	Visually Checked	10:03:12 AM	03/24/2020
Duct Detector	Penthouse C Wing Up Catwalk Up Ladder	Visually Checked	10:03:25 AM	03/24/2020
Duct Detector	Penthouse C Wing Up Catwalk	Visually Checked	10:03:20 AM	03/24/2020
Duct Detector	Lower New Gym By Girls PE Office	Visually Checked	8:08:13 AM	03/24/2020
Duct Detector	New Gym By Girls PE Office	Visually Checked	8:08:14 AM	03/24/2020
Heat Detector	Basement Below Stage Chiller Pump Room Front	Visually Checked	10:37:10 AM	03/24/2020
Heat Detector	Basement Below Stage Chiller/Pump Room	Visually Checked	10:37:14 AM	03/24/2020
Heat Detector	Basement Below Stage Generator Room	Visually Checked	10:37:18 AM	03/24/2020
Heat Detector	Basement Below Stage Switchgear Room	Visually Checked	10:37:07 AM	03/24/2020
Heat Detector	Basement Below Stage By Exit Chiller Pump Room	Visually Checked	10:37:25 AM	03/24/2020
Heat Detector	Basement Below Stage Center Chiller Pump Room	Visually Checked	10:37:21 AM	03/24/2020
Heat Detector	1st 500 Wing Elevator Machine Room Outside Entrance	Visually Checked	10:31:04 AM	03/24/2020
Heat Detector	1st A Wing Business Office Across from Room 115	Visually Checked	10:29:30 AM	03/24/2020
Heat Detector	1st A Wing Custodial Port by Room 109	Visually Checked	10:32:02 AM	03/24/2020
Heat Detector	1st A Wing Electrical Closet 158	Visually Checked	10:32:10 AM	03/24/2020
Heat Detector	1st A Wing Physics Room 112	Visually Checked	10:29:54 AM	03/24/2020
Heat Detector	1st A Wing Port By Music Room	Visually Checked	10:27:42 AM	03/24/2020
Heat Detector	1st A Wing Prep Room Room 112/113 Storage	Visually Checked	10:29:50 AM	03/24/2020
Heat Detector	1st A Wing Prep Room Storage Room 112/113	Visually Checked	10:32:06 AM	03/24/2020
Heat Detector	1st A Wing Room 109 Left	Visually Checked	10:29:37 AM	03/24/2020
Heat Detector	1st A Wing Room 109 Right	Visually Checked	10:29:34 AM	03/24/2020
Heat Detector	1st A Wing Room 118 Stage	Visually Checked	10:31:11 AM	03/24/2020
Heat Detector	1st A Wing Science Room 107 Left	Visually Checked	10:28:31 AM	03/24/2020
Heat Detector	1st A Wing Science Room 107 Right	Visually Checked	10:28:34 AM	03/24/2020
Heat Detector	1st A Wing Science Room 113	Visually Checked	10:29:47 AM	03/24/2020
Heat Detector	1st A Wing Science Room 114 Left	Visually Checked	10:29:40 AM	03/24/2020
Heat Detector	1st A Wing Science Room 115 Left	Visually Checked	10:28:27 AM	03/24/2020
Heat Detector	1st A Wing Science Room 115 Right	Visually Checked	10:28:24 AM	03/24/2020
Heat Detector	1st A Wing Storage Room Behind 118 Stage	Visually Checked	10:28:06 AM	03/24/2020
Heat Detector	1st Above Stage Right	Visually Checked	10:31:30 AM	03/24/2020
Heat Detector	1st 500 Wing In Boys Room	Visually Checked	8:33:05 AM	03/24/2020
Heat Detector	1st 500 Wing In Girls Room	Visually Checked	8:32:42 AM	03/24/2020
Heat Detector	1st 500 Wing Staff Mens Restroom	Visually Checked	8:32:17 AM	03/24/2020
Heat Detector	1st 500 Wing Staff Womens Restroom	Visually Checked	8:32:23 AM	03/24/2020
Heat Detector	1st A Wing Custodian Port by rm 116	Visually Checked	10:31:07 AM	03/24/2020
Heat Detector	1st Main Office Communication Room	Visually Checked	10:27:49 AM	03/24/2020
Heat Detector	2nd A Wing Custodian By Room 209	Visually Checked	10:21:35 AM	03/24/2020
Heat Detector	2nd A Wing Electrical By Room 218	Visually Checked	10:20:43 AM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	2nd A Wing English Department	Visually Checked	10:21:28 AM	03/24/2020
Heat Detector	2nd A Wing Janitors Closet By Room 219	Visually Checked	10:20:10 AM	03/24/2020
Heat Detector	2nd A Wing Language Department By Room 204	Visually Checked	10:18:35 AM	03/24/2020
Heat Detector	2nd A Wing Room 202B	Visually Checked	10:18:31 AM	03/24/2020
Heat Detector	2nd A Wing Room 214	Visually Checked	10:21:32 AM	03/24/2020
Heat Detector	2nd 600 Wing Room 612	Visually Checked	10:21:59 AM	03/24/2020
Heat Detector	2nd 600 Wing Room 613/614 Prep Room 2	Visually Checked	7:49:40 AM	03/24/2020
Heat Detector	2nd 600 Wing Room 613/614 Prep Room 2	Visually Checked	7:49:49 AM	03/24/2020
Heat Detector	2nd 600 Wing Room 615/616 Prep Room 3	Visually Checked	7:50:42 AM	03/24/2020
Heat Detector	2nd 600 Wing Room 615/616 Prep Room 3	Visually Checked	7:50:52 AM	03/24/2020
Heat Detector	2nd 600's Corridor Boys Restroom	Visually Checked	7:46:48 AM	03/24/2020
Heat Detector	2nd Girls Restroom 600's Corridor	Visually Checked	7:45:54 AM	03/24/2020
Heat Detector	2nd Media Center Kitchen	Visually Checked	10:20:03 AM	03/24/2020
Heat Detector	2nd Mens Staff 600's Corridor	Visually Checked	7:46:18 AM	03/24/2020
Heat Detector	2nd Womens Staff Restroom 600's Corridor	Visually Checked	7:46:11 AM	03/24/2020
Heat Detector	Penthouse A Wing	Visually Checked	9:57:05 AM	03/24/2020
Heat Detector	Penthouse A Wing	Visually Checked	9:57:14 AM	03/24/2020
Heat Detector	Penthouse C Wing Catwalk North Entrance	Visually Checked	10:03:08 AM	03/24/2020
Heat Detector	Penthouse C Wing Catwalk South	Visually Checked	10:03:16 AM	03/24/2020
Heat Detector	Ground A Wing Arts And Crafts Room 12	Visually Checked	10:08:49 AM	03/24/2020
Heat Detector	Ground A Wing Custodial Port By Boys Room	Visually Checked	10:09:36 AM	03/24/2020
Heat Detector	Ground A Wing Pottery Room 10	Visually Checked	10:08:56 AM	03/24/2020
Heat Detector	Ground A Wing Room 9	Visually Checked	10:09:40 AM	03/24/2020
Heat Detector	Ground A Wing Art Room 11	Visually Checked	10:08:46 AM	03/24/2020
Heat Detector	Ground A Wing Auto By Exit	Visually Checked	10:09:22 AM	03/24/2020
Heat Detector	Ground A Wing Auto Class	Visually Checked	10:09:26 AM	03/24/2020
Heat Detector	Ground A Wing Auto Shop Room 3 Storage	Visually Checked	10:12:20 AM	03/24/2020
Heat Detector	Ground A Wing Fitness Room	Visually Checked	10:09:15 AM	03/24/2020
Heat Detector	Ground A Wing Fitness Room	Visually Checked	10:09:19 AM	03/24/2020
Heat Detector	Ground A Wing Wood Finishing Room	Visually Checked	10:10:12 AM	03/24/2020
Heat Detector	Ground A Wing Wood Shop	Visually Checked	10:09:29 AM	03/24/2020
Heat Detector	Ground A Wing Wood Shop West	Visually Checked	10:09:33 AM	03/24/2020
Heat Detector	Ground Craft Room Off Stage	Visually Checked	9:00:46 AM	03/24/2020
Heat Detector	Ground Garage by Loading Dock	Visually Checked	10:10:51 AM	03/24/2020
Heat Detector	Ground Garage By Loading Dock	Visually Checked	10:10:55 AM	03/24/2020
Heat Detector	Ground Garage By Loading Dock	Visually Checked	10:10:58 AM	03/24/2020
Heat Detector	Ground Garage By Loading Dock	Visually Checked	10:12:05 AM	03/24/2020
Heat Detector	Ground Mechanical Room Inside Garage	Visually Checked	10:11:02 AM	03/24/2020
Heat Detector	Ground Mens Restroom by Garage	Visually Checked	10:12:09 AM	03/24/2020
Heat Detector	Ground Womens Restroom by Garage Above Ceiling	Visually Checked	10:12:13 AM	03/24/2020
Heat Detector	Lower New Gym Mens PE Office Bathroom	Visually Checked	10:42:35 AM	03/24/2020
Heat Detector	Lower New Gym PE Office Bathroom	Visually Checked	10:42:38 AM	03/24/2020
Heat Detector	Lower Level New Gym Boys Bathroom	Visually Checked	8:10:15 AM	03/24/2020
Heat Detector	Lower Level New Gym Girls Bathroom	Visually Checked	8:07:14 AM	03/24/2020
Pull Station	Basement Below Stage Chiller Room By Exit	Visually Checked	10:37:29 AM	03/24/2020
Pull Station	Basement Switchgear Room Under Stage	Visually Checked	10:37:32 AM	03/24/2020
Pull Station	1st A Wing By Main Office	Visually Checked	8:47:26 AM	03/24/2020
Pull Station	1st A Wing Music Room	Visually Checked	10:27:35 AM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	1st A Wing Outside Main Office	Visually Checked	8:51:11 AM	03/24/2020
Pull Station	1st A Wing Rear Center Exit Band Entrance	Visually Checked	10:28:02 AM	03/24/2020
Pull Station	1st A Wing By Room 101	Visually Checked	10:27:14 AM	03/24/2020
Pull Station	1st A Wing By Room 105	Visually Checked	10:27:18 AM	03/24/2020
Pull Station	1st A Wing By Room 111	Visually Checked	10:27:21 AM	03/24/2020
Pull Station	1st North Corridor By Stage Exit	Visually Checked	9:04:13 AM	03/24/2020
Pull Station	1st Outside Gym Corridor Exit Door	Visually Checked	8:25:55 AM	03/24/2020
Pull Station	1st Southeast By Exit Door	Visually Checked	10:31:33 AM	03/24/2020
Pull Station	1st Southwest By Rear Exit	Visually Checked	10:27:39 AM	03/24/2020
Pull Station	1st Stage Left On Stage	Visually Checked	10:31:27 AM	03/24/2020
Pull Station	1st 500 Wing Corridor By Exit	Visually Checked	10:29:14 AM	03/24/2020
Pull Station	2nd 600 Wing Corridor By Stair 1	Visually Checked	10:22:08 AM	03/24/2020
Pull Station	2nd 600 Wing Corridor by Stair 2 Room 611	Visually Checked	10:22:03 AM	03/24/2020
Pull Station	2nd A Wing By Cafe	Visually Checked	8:03:17 AM	03/24/2020
Pull Station	2nd A Wing By Room 202B	Visually Checked	8:01:45 AM	03/24/2020
Pull Station	2nd A Wing By Room 206	Visually Checked	8:00:48 AM	03/24/2020
Pull Station	2nd A Wing Stair 6 By Room 210	Visually Checked	10:18:13 AM	03/24/2020
Pull Station	2nd A Wing Outside Media Center	Visually Checked	10:18:09 AM	03/24/2020
Pull Station	2nd 500 Wing Corridor By Electrical Room	Visually Checked	10:22:16 AM	03/24/2020
Pull Station	2nd 500 Wing corridor By Exit	Visually Checked	10:21:11 AM	03/24/2020
Pull Station	2nd Gym	Visually Checked	10:18:28 AM	03/24/2020
Pull Station	2nd Gym	Visually Checked	10:21:20 AM	03/24/2020
Pull Station	3rd A Wing Stair 7	Visually Checked	10:17:19 AM	03/24/2020
Pull Station	Penthouse A Wing	Visually Checked	9:56:03 AM	03/24/2020
Pull Station	Ground A Wing Arts And Crafts Room 12	Visually Checked	10:08:27 AM	03/24/2020
Pull Station	Ground A Wing By Rear Music Exit	Visually Checked	9:11:21 AM	03/24/2020
Pull Station	Ground A Wing By Room 1	Visually Checked	9:35:00 AM	03/24/2020
Pull Station	Ground A Wing By Room 11	Visually Checked	10:08:31 AM	03/24/2020
Pull Station	Ground A Wing Corridor by Room 4	Visually Checked	10:09:03 AM	03/24/2020
Pull Station	Ground A Wing Pottery Room 10	Visually Checked	10:08:53 AM	03/24/2020
Pull Station	Ground A Wing Room 9	Visually Checked	10:09:43 AM	03/24/2020
Pull Station	Ground A Wing Stair By Room 7	Visually Checked	10:09:00 AM	03/24/2020
Pull Station	Ground A Wing Art Room 11	Visually Checked	10:08:42 AM	03/24/2020
Pull Station	Ground A Wing Auto By Exit	Visually Checked	10:08:38 AM	03/24/2020
Pull Station	Ground A Wing Fitness Room	Visually Checked	10:08:35 AM	03/24/2020
Pull Station	Ground A Wing Wood Shop	Visually Checked	10:09:07 AM	03/24/2020
Pull Station	Ground Right Of Stage By Curtain	Visually Checked	8:59:32 AM	03/24/2020
Pull Station	Ground Storage By Loading Dock	Visually Checked	10:10:40 AM	03/24/2020
Pull Station	Ground Auditorium/Stage Right Workroom	Visually Checked	9:00:34 AM	03/24/2020
Pull Station	Ground Garage By Loading Dock	Visually Checked	10:10:37 AM	03/24/2020
Pull Station	Lower New Gym Entrance	Visually Checked	10:42:52 AM	03/24/2020
Pull Station	Lower New Gym Exit rear	Visually Checked	10:42:45 AM	03/24/2020
Pull Station	Lower New Gym Exit Rear	Visually Checked	10:42:49 AM	03/24/2020
Pull Station	Lower New Gym Lobby	Visually Checked	10:42:56 AM	03/24/2020
Smoke Detector	1st A Wing Main Office	Visually Checked	8:48:56 AM	03/24/2020
Smoke Detector	1st A Wing Main Office	Visually Checked	8:49:21 AM	03/24/2020
Smoke Detector	1st A Wing Main Office	Visually Checked	10:29:57 AM	03/24/2020
Smoke Detector	1st A Wing Port Outside Room 6/7	Visually Checked	10:31:40 AM	03/24/2020
Smoke Detector	1st A Wing Chemistry Prep Room Behind 114	Visually Checked	10:28:13 AM	03/24/2020
Smoke Detector	1st A Wing Chemistry Prep Room 109	Visually Checked	10:28:09 AM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st A Wing Chemistry Prep Room Behind 115	Visually Checked	10:28:17 AM	03/24/2020
Smoke Detector	1st A Wing Chemistry Storage Off Prep Room Behind 109	Visually Checked	10:28:21 AM	03/24/2020
Smoke Detector	1st A Wing ROTC Storage Room Across From Elevator	Visually Checked	10:31:43 AM	03/24/2020
Smoke Detector	1st A Wing Science Room 114 Right	Visually Checked	10:29:43 AM	03/24/2020
Smoke Detector	1st Elevator Lobby 500 Wing Corridor By Exit	Visually Checked	8:33:24 AM	03/24/2020
Smoke Detector	1st File Storage Main Office	Visually Checked	10:27:52 AM	03/24/2020
Smoke Detector	1st Main Switch Gear Room	Visually Checked	10:29:17 AM	03/24/2020
Smoke Detector	1st 500 Wing CAPT Storage Room	Visually Checked	8:40:55 AM	03/24/2020
Smoke Detector	1st 500 Wing Corridor By Room 501/503	Visually Checked	8:34:58 AM	03/24/2020
Smoke Detector	1st 500 Wing Corridor By Room 509/508	Visually Checked	8:35:31 AM	03/24/2020
Smoke Detector	1st 500 Wing Corridor By Staff Restrooms	Visually Checked	8:29:26 AM	03/24/2020
Smoke Detector	1st 500s Uniform Room	Visually Checked	10:29:20 AM	03/24/2020
Smoke Detector	1st Corridor 500 Wing Admin. Storage Room	Visually Checked	8:43:00 AM	03/24/2020
Smoke Detector	1st Corridor 500 Wing Admin.	Visually Checked	8:42:49 AM	03/24/2020
Smoke Detector	1st Corridor 500 Wing Admin.	Visually Checked	8:43:19 AM	03/24/2020
Smoke Detector	1st Corridor 500 Wing By 507 Computer Lab	Visually Checked	8:41:29 AM	03/24/2020
Smoke Detector	1st Corridor 500 Wing By Conference Room	Visually Checked	8:41:44 AM	03/24/2020
Smoke Detector	1st Corridor 500 Wing By Main Office	Visually Checked	8:41:58 AM	03/24/2020
Smoke Detector	1st Corridor Passageway West To 500 Wing	Visually Checked	8:29:20 AM	03/24/2020
Smoke Detector	1st Corridor 500 Wing Admin.	Visually Checked	8:42:35 AM	03/24/2020
Smoke Detector	1st Custodial Room by Room 512	Visually Checked	8:40:02 AM	03/24/2020
Smoke Detector	1st Storage Room by Room 511	Visually Checked	8:40:22 AM	03/24/2020
Smoke Detector	2nd 500 Corridor By 512 Room	Visually Checked	8:39:48 AM	03/24/2020
Smoke Detector	2nd 500 Corridor By Teachers Room	Visually Checked	8:40:36 AM	03/24/2020
Smoke Detector	2nd 600 Wing Elevator Lobby	Visually Checked	7:47:02 AM	03/24/2020
Smoke Detector	2nd A Wing Audio Visual Center	Visually Checked	10:18:39 AM	03/24/2020
Smoke Detector	2nd A Wing Corridor East To Cafe By Doors	Visually Checked	7:45:28 AM	03/24/2020
Smoke Detector	2nd 500 Wing Corridor By Boys Room	Visually Checked	8:42:10 AM	03/24/2020
Smoke Detector	2nd 500 Wing Corridor By Electrical Room	Visually Checked	8:35:54 AM	03/24/2020
Smoke Detector	2nd 500 Wing Corridor By Electrical Room	Visually Checked	8:35:58 AM	03/24/2020
Smoke Detector	2nd 500 Wing Corridor By Electrical Room	Visually Checked	8:36:02 AM	03/24/2020
Smoke Detector	2nd 500 Wing Corridor By Exit	Visually Checked	8:33:27 AM	03/24/2020
Smoke Detector	2nd 500 Wing Corridor By Exit	Visually Checked	8:33:31 AM	03/24/2020
Smoke Detector	2nd 500 Wing Corridor By Girls Room	Visually Checked	8:32:32 AM	03/24/2020
Smoke Detector	2nd 500 Wing Corridor By Room 505	Visually Checked	8:35:08 AM	03/24/2020
Smoke Detector	2nd 500 Wing Corridor By Room 507	Visually Checked	8:35:19 AM	03/24/2020
Smoke Detector	2nd 500 Wing Corridor Passageway East	Visually Checked	8:45:00 AM	03/24/2020
Smoke Detector	2nd 500 Wing Corridor Passageway East	Visually Checked	8:45:02 AM	03/24/2020
Smoke Detector	2nd 500 Wing Custodial Port	Visually Checked	7:45:13 AM	03/24/2020
Smoke Detector	2nd 500 Wing Electrical Room By 510	Visually Checked	10:22:13 AM	03/24/2020
Smoke Detector	2nd 600 Wing Corridor By Room 614	Visually Checked	7:50:15 AM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd 600 Wing Corridor Room 613	Visually Checked	7:49:20 AM	03/24/2020
Smoke Detector	2nd 600 Wing Corridor By Room 601	Visually Checked	7:47:34 AM	03/24/2020
Smoke Detector	2nd 600 Wing Corridor By Room 604	Visually Checked	7:47:47 AM	03/24/2020
Smoke Detector	2nd 600 Wing Corridor By Room 606	Visually Checked	7:47:59 AM	03/24/2020
Smoke Detector	2nd 600 Wing Corridor By Room 609	Visually Checked	7:48:10 AM	03/24/2020
Smoke Detector	2nd 600 Wing Corridor By Room 615	Visually Checked	7:50:27 AM	03/24/2020
Smoke Detector	2nd 600 Wing Corridor By Room 616	Visually Checked	7:51:10 AM	03/24/2020
Smoke Detector	2nd 600 Wing Corridor By Stair 1	Visually Checked	7:47:07 AM	03/24/2020
Smoke Detector	2nd 600 Wing Corridor By Stair 1	Visually Checked	7:47:17 AM	03/24/2020
Smoke Detector	2nd 600 Wing Corridor By Stair 2 Room 611	Visually Checked	7:48:53 AM	03/24/2020
Smoke Detector	2nd 600 Wing Corridor By Stair 2 Room 611	Visually Checked	7:48:57 AM	03/24/2020
Smoke Detector	2nd 600 Wing Inside Stair 2	Visually Checked	7:49:01 AM	03/24/2020
Smoke Detector	2nd 600 Wing Inside Stair 1	Visually Checked	7:47:10 AM	03/24/2020
Smoke Detector	2nd Corridor Outside Cafe By Double Doors	Visually Checked	7:45:09 AM	03/24/2020
Smoke Detector	2nd Corridor Outside Cafe By Double Doors	Visually Checked	7:45:25 AM	03/24/2020
Smoke Detector	2nd Corridor Outside Cafe By Double Doors	Visually Checked	7:46:37 AM	03/24/2020
Smoke Detector	2nd Corridor Outside Cafe	Visually Checked	7:45:43 AM	03/24/2020
Smoke Detector	Penthouse A Wing	Visually Checked	9:56:13 AM	03/24/2020
Smoke Detector	Auditorium Projection Booth	Visually Checked	10:17:44 AM	03/24/2020
Smoke Detector	Ground A Wing Electrical	Visually Checked	10:09:11 AM	03/24/2020
Smoke Detector	Ground A Wing Elevator Machine Room	Visually Checked	10:09:47 AM	03/24/2020
Smoke Detector	Ground B Wing Electrical Room Behind Stage	Visually Checked	10:10:23 AM	03/24/2020
Smoke Detector	Ground Storage By Loading Dock	Visually Checked	10:10:44 AM	03/24/2020
Smoke Detector	Ground Storage Room By Loading Dock	Visually Checked	10:10:47 AM	03/24/2020
Smoke Detector	Lower New Gym Storage	Visually Checked	8:12:06 AM	03/24/2020
Smoke Detector	Lower New Gym Storage	Visually Checked	10:42:42 AM	03/24/2020
Smoke Detector	Lower New Gym Lobby	Visually Checked	8:12:44 AM	03/24/2020
Smoke Detector	Lower New Gym Sprinkler/Electrical	Visually Checked	10:42:24 AM	03/24/2020
Smoke Detector	Lower Freshmen Gym Lobby	Visually Checked	8:05:44 AM	03/24/2020
Smoke Detector	Lower Freshmen Gym Lobby	Visually Checked	8:05:51 AM	03/24/2020
Smoke Detector	Lower Level 600 Wing Elevator Machine Room	Visually Checked	10:48:14 AM	03/24/2020
	Outside Entrance			
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
Control				
Battery	Basement Boiler Room Booster Cab 2	Tested	9:26:58 AM	03/24/2020
Battery	Basement Boiler Room Booster Cab 6	Visually Checked	9:17:10 AM	03/24/2020
Device Type	Location	Service	Time	Date
<i>Untested</i>				
Initiating				
Heat Detector	600 Wing Top Of Shaft			
Heat Detector	600 Wing Elevator Pit			
Smoke Detector	600 Wing Elevator Top of Shaft			

Building: Stamford BOE-West Hill High School

Control Panel: 2

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Initiating				
Duct Detector	2nd B Wing Penthouse AC 4 Return	Visually Checked	10:20:57 AM	03/24/2020
Duct Detector	2nd B Wing Penthouse AC 4 Supply	Visually Checked	10:20:53 AM	03/24/2020
Duct Detector	2nd B Wing Penthouse AC 5 Supply	Visually Checked	10:21:00 AM	03/24/2020
Heat Detector	1st B Wing B304	Visually Checked	10:30:01 AM	03/24/2020
Heat Detector	1st B Wing B305	Visually Checked	10:30:07 AM	03/24/2020
Heat Detector	1st B Wing B306	Visually Checked	10:30:10 AM	03/24/2020
Heat Detector	1st B Wing B307	Visually Checked	10:30:14 AM	03/24/2020
Heat Detector	1st B Wing Math Department	Visually Checked	10:30:17 AM	03/24/2020
Heat Detector	1st B Wing Port By 302	Visually Checked	10:31:58 AM	03/24/2020
Heat Detector	1st B Wing Room 323	Visually Checked	10:31:15 AM	03/24/2020
Heat Detector	1st B Wing Science Department	Visually Checked	10:27:56 AM	03/24/2020
Heat Detector	1st B Wing B310	Visually Checked	10:30:46 AM	03/24/2020
Heat Detector	1st B Wing B313	Visually Checked	10:30:29 AM	03/24/2020
Heat Detector	1st B Wing B315	Visually Checked	10:30:32 AM	03/24/2020
Heat Detector	1st B Wing B321	Visually Checked	10:30:36 AM	03/24/2020
Heat Detector	1st B Wing Room 308	Visually Checked	10:30:21 AM	03/24/2020
Heat Detector	1st B Wing Room 309	Visually Checked	10:30:43 AM	03/24/2020
Heat Detector	1st B Wing By Port By Room B322	Visually Checked	10:30:59 AM	03/24/2020
Heat Detector	2nd B Wing Custodian Port By Cafe	Visually Checked	7:52:12 AM	03/24/2020
Heat Detector	2nd B Wing Penthouse	Visually Checked	10:21:39 AM	03/24/2020
Heat Detector	2nd B Wing Penthouse	Visually Checked	10:21:43 AM	03/24/2020
Heat Detector	2nd B Wing Custodian Port By Room 405	Visually Checked	10:21:50 AM	03/24/2020
Heat Detector	2nd B Wing Custodian Port By Room 432	Visually Checked	10:21:46 AM	03/24/2020
Pull Station	1st B Wing By 302	Visually Checked	10:10:16 AM	03/24/2020
Pull Station	1st B Wing By B306/B307	Visually Checked	10:10:48 AM	03/24/2020
Pull Station	1st B Wing By Room B312	Visually Checked	10:11:41 AM	03/24/2020
Pull Station	1st B Wing Main Lobby	Visually Checked	10:27:25 AM	03/24/2020
Pull Station	1st B Wing Passage A352 By Room 312 By Double Doors Closet in Storage	Visually Checked	10:13:12 AM	03/24/2020
Pull Station	1st B Wing By Room 317	Visually Checked	10:27:28 AM	03/24/2020
Pull Station	2nd B Wing By Room 411	Visually Checked	10:18:20 AM	03/24/2020
Pull Station	2nd B Wing By Room 427	Visually Checked	10:18:24 AM	03/24/2020
Pull Station	2nd B Wing Corridor Stair By Room 400/Media Center	Visually Checked	10:18:17 AM	03/24/2020
Pull Station	2nd B Wing Penthouse	Visually Checked	10:20:50 AM	03/24/2020
Smoke Detector	1st B Wing Electrical Room by 321	Visually Checked	10:29:03 AM	03/24/2020
Smoke Detector	1st B Wing Main Office By Panel	Visually Checked	10:09:14 AM	03/24/2020
Smoke Detector	1st B Wing Main Office By Smaller Offices	Visually Checked	10:09:24 AM	03/24/2020
Smoke Detector	1st B Wing Main Office	Visually Checked	10:09:07 AM	03/24/2020
Smoke Detector	1st B Wing Math Department Storage	Visually Checked	10:28:50 AM	03/24/2020
Smoke Detector	1st B Wing Passage A352 By Room 312 By Double Doors Closet in Storage	Visually Checked	10:30:50 AM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st B Wing Passage A352 By Room 312 By Double Doors Storage	Visually Checked	10:13:21 AM	03/24/2020
Smoke Detector	1st B Wing Passage A352 By Room 312 By Double Doors	Visually Checked	10:13:05 AM	03/24/2020
Smoke Detector	1st B Wing Passage A352 By Room 312 By Double Doors	Visually Checked	10:13:29 AM	03/24/2020
Smoke Detector	1st B Wing Passage A352 By Room 312	Visually Checked	10:12:56 AM	03/24/2020
Smoke Detector	1st B Wing Rm 314 Storage	Visually Checked	10:28:54 AM	03/24/2020
Smoke Detector	1st B Wing Room 316A Speech	Visually Checked	10:30:55 AM	03/24/2020
Smoke Detector	1st B Wing Science Department Storage	Visually Checked	10:27:59 AM	03/24/2020
Smoke Detector	1st B Wing Science Department Storage By Room 319	Visually Checked	10:31:19 AM	03/24/2020
Smoke Detector	1st B Wing Special ED Hall	Visually Checked	10:29:07 AM	03/24/2020
Smoke Detector	1st B Wing Special ED Storage	Visually Checked	10:29:10 AM	03/24/2020
Smoke Detector	1st B Wing Storage A51	Visually Checked	10:31:55 AM	03/24/2020
Smoke Detector	1st B Wing Prep Room Smoke 1	Visually Checked	10:28:57 AM	03/24/2020
Smoke Detector	1st B Wing Prep Room Smoke 2	Visually Checked	10:29:00 AM	03/24/2020
Smoke Detector	1st B Wing Prep Room Storage	Visually Checked	10:30:25 AM	03/24/2020
Smoke Detector	2nd B Wing Electrical Room by Room 414	Visually Checked	10:20:46 AM	03/24/2020
Smoke Detector	2nd B Wing Room 401 Storage	Visually Checked	10:21:04 AM	03/24/2020
Smoke Detector	2nd B Wing Room 403 Office/Storage	Visually Checked	10:21:07 AM	03/24/2020

Building: Stamford BOE-West Hill High School

Control Panel: 3

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Initiating				
Duct Detector	1st Gym V-3	Visually Checked	10:28:47 AM	03/24/2020
Duct Detector	1st Gym V-5	Visually Checked	10:28:44 AM	03/24/2020
Duct Detector	Penthouse Penthouse gym/cafe V 10 supply	Visually Checked	10:04:20 AM	03/24/2020
Duct Detector	Penthouse Penthouse gym/cafe V 12 supply	Visually Checked	10:04:24 AM	03/24/2020
Duct Detector	Penthouse Penthouse gym/cafe V 5 return	Visually Checked	10:03:52 AM	03/24/2020
Duct Detector	Penthouse Penthouse gym/cafe V 7 return	Visually Checked	10:04:04 AM	03/24/2020
Duct Detector	Penthouse Penthouse gym/cafe V 7 supply	Visually Checked	10:04:00 AM	03/24/2020
Duct Detector	Penthouse Penthouse gym/cafe V 7supply2	Visually Checked	10:03:56 AM	03/24/2020
Duct Detector	Penthouse Penthouse gym/cafe V 8 return	Visually Checked	10:04:08 AM	03/24/2020
Duct Detector	Penthouse Penthouse gym/cafe V 8 supply	Visually Checked	10:04:12 AM	03/24/2020
Duct Detector	Penthouse Penthouse gym/cafe V 8 supply	Visually Checked	10:04:16 AM	03/24/2020
Duct Detector	Ground Custodian Office V13 #1	Visually Checked	10:10:33 AM	03/24/2020
Duct Detector	Ground Head Custodian Inter Office V13#2	Visually Checked	10:10:27 AM	03/24/2020
Heat Detector	1st Boys Locker Room Custodial Port	Visually Checked	8:18:30 AM	03/24/2020
Heat Detector	1st Girls Locker Room Port Janitor Closet	Visually Checked	10:29:23 AM	03/24/2020
Heat Detector	2nd B Cafe Prep Area Left Of Hood	Visually Checked	7:42:43 AM	03/24/2020
Heat Detector	2nd B Cafe Prep Area Right Side of Hood	Visually Checked	7:43:16 AM	03/24/2020
Heat Detector	2nd B Cafe Serving Line	Visually Checked	7:43:34 AM	03/24/2020
Heat Detector	2nd B Cafe Serving Line	Visually Checked	7:43:47 AM	03/24/2020
Heat Detector	2nd Kitchen A Side Serving Line	Visually Checked	7:42:19 AM	03/24/2020
Heat Detector	2nd Kitchen A Side Serving Line	Visually Checked	10:20:06 AM	03/24/2020
Heat Detector	Penthouse gym/cafe Mechanical rm heat 1	Visually Checked	10:04:44 AM	03/24/2020
Heat Detector	Penthouse gym/cafe Mechanical rm heat 2	Visually Checked	10:04:37 AM	03/24/2020
Heat Detector	Penthouse gym/cafe Mechanical rm heat 2	Visually Checked	10:04:41 AM	03/24/2020
Heat Detector	Penthouse gym/cafe Mechanical rm heat 4	Visually Checked	10:04:33 AM	03/24/2020
Heat Detector	Penthouse gym/cafe Mechanical rm heat 5	Visually Checked	10:04:29 AM	03/24/2020
Heat Detector	Ground Garage Left Of Loading Dock	Visually Checked	10:12:25 AM	03/24/2020
Heat Detector	Ground Pool Storage Under Bleachers	Visually Checked	10:10:16 AM	03/24/2020
Heat Detector	Ground Pool Mechanical Room	Visually Checked	10:12:17 AM	03/24/2020
Heat Detector	Lower New Gym Sprinkler/ Electrical	Visually Checked	10:42:32 AM	03/24/2020
Heat Detector	Lower Laundry Room By Dock	Visually Checked	10:42:59 AM	03/24/2020
Heat Detector	Lower Level Custodian Port by Mens Lockers	Visually Checked	10:48:22 AM	03/24/2020
Heat Detector	Lower Level Pool Storage Under Bleachers	Visually Checked	10:48:26 AM	03/24/2020
Pull Station	1st Outside Gym Corridor Gym Hall Behind Girls Locker	Visually Checked	8:30:18 AM	03/24/2020
Pull Station	1st Pool Bleacher Area by Dock	Visually Checked	10:27:45 AM	03/24/2020
Pull Station	1st Girls Auxilary Gym	Visually Checked	10:29:26 AM	03/24/2020
Pull Station	1st Girls Auxilary Gym	Visually Checked	10:32:15 AM	03/24/2020
Pull Station	1st Main Gym	Visually Checked	8:20:35 AM	03/24/2020
Pull Station	1st Main Gym	Visually Checked	8:24:37 AM	03/24/2020
Pull Station	1st Wrestling gym	Visually Checked	10:28:37 AM	03/24/2020
Pull Station	2nd North Cafe by Stairs 901	Visually Checked	8:04:13 AM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	2nd Girls Auxiliary Gym Corridor	Visually Checked	10:21:16 AM	03/24/2020
Pull Station	2nd Gym Corridor Middle Outside Boys Locker Room	Visually Checked	10:21:25 AM	03/24/2020
Pull Station	Lower Lobby Pool Lobby	Visually Checked	10:48:31 AM	03/24/2020
Pull Station	Penthouse North Gym/Cafe	Visually Checked	10:05:34 AM	03/24/2020
Pull Station	Penthouse South Gym Penthouse	Visually Checked	10:04:52 AM	03/24/2020
Pull Station	Penthouse Penthouse gym/cafe	Visually Checked	10:04:48 AM	03/24/2020
Pull Station	Ground Pool Deck Area	Visually Checked	10:10:09 AM	03/24/2020
Pull Station	Ground Lobby By Room 757	Visually Checked	10:09:54 AM	03/24/2020
Pull Station	Ground Pool Lobby By Room 751	Visually Checked	10:09:50 AM	03/24/2020
Pull Station	Lower Main Gym Foyer	Visually Checked	10:42:13 AM	03/24/2020
Pull Station	Lower Main Gym Lobby	Visually Checked	10:42:09 AM	03/24/2020
Pull Station	Lower Corridor By Custodian /Electrical	Visually Checked	8:12:38 AM	03/24/2020
Pull Station	Lower Receiving Dock Entrance	Visually Checked	10:42:17 AM	03/24/2020
Smoke Alarm	Penthouse gym/cafe	Visually Checked	10:05:29 AM	03/24/2020
Smoke Alarm	Penthouse Penthouse gym/cafe	Visually Checked	10:04:56 AM	03/24/2020
Smoke Detector	1st Gym Electrical Room	Visually Checked	10:27:32 AM	03/24/2020
Smoke Detector	1st Gym Trainers Room	Visually Checked	10:28:41 AM	03/24/2020
Smoke Detector	1st Wrestling Room Storage	Visually Checked	10:31:36 AM	03/24/2020
Smoke Detector	2nd Kitchen Port Slop Sink	Visually Checked	7:41:30 AM	03/24/2020
Smoke Detector	Lower Lobby Pool/Elevator Lobby	Visually Checked	10:48:36 AM	03/24/2020
Smoke Detector	Lower Lobby Pool/Elevator Machine Room	Visually Checked	10:48:41 AM	03/24/2020
Smoke Detector	Ground Custodian Port Room 755	Visually Checked	10:10:19 AM	03/24/2020
Smoke Detector	Lower Pool Office Storage	Visually Checked	10:42:21 AM	03/24/2020

Service Summary

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill High School		
The Service Summary section provides an overview of the services performed in this report.		
Device Type	Service	Quantity
Failed/Other		
Battery	Tested	1
Battery	Visually Checked	1
Total		2
Passed		
Annunciator	Visually Checked	1
Battery	Visually Checked	17
Beam Detector	Visually Checked	2
Duct Detector	Visually Checked	34
Heat Detector	Visually Checked	117
Power Supply	Visually Checked	2
Pull Station	Visually Checked	79
Smoke Alarm	Visually Checked	2
Smoke Detector	Visually Checked	109
Total		363
Untested		
Heat Detector		2
Smoke Detector		1
Total		3
Grand Total		368




Auxiliary Functions Testing

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill High School				Control Panel: 1
<p><i>The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.</i></p>				
Type	Location	Comment	ScanID	Simulated
Passed				
Heat Detector				
Shunt Trip	1st 500 Wing Elevator Machine Room Outside Entrance	Passed	20668293	
Smoke Detector				
Elevator Recall	1st Elevator Lobby 500 Wing Corridor By Exit	Passed	17012978	
Elevator Recall	2nd 600 Wing Elevator Lobby	Passed	20668288	
Elevator Recall	Lower Level 600 Wing Elevator Machine Room Outside Entrance	Passed	20668292	
Untested				
Heat Detector				
Shunt Trip	600 Wing Top Of Shaft		20668289	
Shunt Trip	600 Wing Elevator Pit		20668291	
Smoke Detector				
Elevator Recall	600 Wing Elevator Top of Shaft		20668290	
Building: Stamford BOE-West Hill High School				Control Panel: 3
<p><i>The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.</i></p>				
Type	Location	Comment	ScanID	Simulated
Passed				
Heat Detector				
Shunt Trip	Ground Garage Left Of Loading Dock	Passed	23587357	
Smoke Detector				
Elevator Recall	1st Wrestling Room Storage	Passed	21099784	

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill High School								
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>								
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test		
		◀ dB	◀ dB	Voice	STI			
<i>Failed/Other</i>								
Sound Test Points								
WHOLE FACILITY	Damaged/Worn			<input type="checkbox"/>		0001		

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill High School				Control Panel: 1			
The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	Basement Boiler Room Battery Cab 2	55Ah	12V		80%		
Sealed Lead Acid	Basement Boiler Room Booster Cab 1	8AH	12V	12.57V	7Ah		
Sealed Lead Acid	Basement Boiler Room Booster Cab 6	8AH	12V	12.59V	7AH		
Sealed Lead Acid	Basement Storage Room By Custodian Office Battery Cab 3	35Ah	12V	13.19V	19Ah		
Sealed Lead Acid	Basement Storage Room By Custodian Office Booster Cab 1	8AH	12V	12.69V	5Ah		
Sealed Lead Acid	Basement Storage Room By Custodian Office Booster Cab 2	8AH	12V	12.65V	7.4Ah		
Sealed Lead Acid	Basement Storage Room By Custodian Office Booster Cab 3	8AH	12V	12.69V	7.8Ah		
Sealed Lead Acid	Basement Storage Room By Custodian Office Booster Cab 4	8AH	12V	12.68V	7.9Ah		
Sealed Lead Acid	1st 500 Electrical Room	8AH	12V	12.78V	6.0Ah		
Sealed Lead Acid	1st 500 Electrical Room	8AH	12V	12.72V	7.Ah		
Sealed Lead Acid	1st Gym Electrical/Custodian	8AH	12V	12.69V	7.2Ah		
Sealed Lead Acid	1st Raynur Office Storage Room Battery Cab 1	18AH	12V	12.29V	14Ah		
Sealed Lead Acid	1st Raynur Office Storage Room Battery Cab 2	18AH	12V	12.82V	17Ah		
Sealed Lead Acid	1st Raynur Office Storage Room Battery Cab 2 (Lower Set)	8AH	12V	12.60V	5.8Ah		
Sealed Lead Acid	1st Raynur Office Storage Room Battery Cab 2 (Upper Set)	8AH	12V	12.59V	7.8Ah		
Sealed Lead Acid	1st Raynur Office Storage Room Battery Cab 3 (Right Set)	8AH	12V	12.66V	7.6Ah		
Sealed Lead Acid	1st Raynur Office Storage Room Battery Cab 4	8Ah	12V	12.88v	7.6Ah		
Failed/Other							
Battery							
Sealed Lead Acid	Basement Boiler Room Booster Cab 2	8AH	12V	12.56V	4Ah		

Sealed Lead Acid	Basement Boiler Room Booster Cab 6	8AH	12V	12.60V	2.5Ah
------------------	---------------------------------------	-----	-----	--------	-------

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill High School				Control Panel: 1
<p><i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Device or Type	Category	% of Inventory	Quantity	
Heat Detector	Initiating	32.25%	119	
Smoke Detector	Initiating	29.81%	110	
Duct Detector	Initiating	9.21%	34	
Pull Station	Initiating	21.41%	79	
Beam Detector	Initiating	0.54%	2	
Battery	Control	5.15%	19	
Sound Test	Sound Test	0.27%	1	
Power Supply	Control	0.54%	2	
Smoke Alarm	Initiating	0.54%	2	
Annunciator	Control	0.27%	1	
Type	Qty	Model #	Description	Install Date
<i>In Service - 3 Years to 5 Years</i>				
Power-Sonic				
Battery	1	PS-12550 U	Sealed Lead Acid	02/08/2017
Universal				
Battery	2	UB12220	Sealed Lead Acid	02/08/2017
Battery	1	UB12350	Sealed Lead Acid	02/08/2017
Battery	15	UB1280	Sealed Lead Acid	02/08/2017
<i>In Service - 5 Years to 10 Years</i>				
Beam Detector	2			07/23/2012
EST				
Annunciator	1	EST3	LCD Display	07/23/2012
Duct Detector	8	SIGA-PS	Photoelectric	07/23/2012
Duct Detector	9	SIGA-SD	Photoelectric	07/23/2012
Heat Detector	3	283B	Fixed Temperature	07/23/2012
Heat Detector	52	SIGA-HFS	Fixed Temperature	07/23/2012
Heat Detector	24	SIGA-HRS	Rate-of-Rise	07/23/2012
Power Supply	1	Booster		07/23/2012
Power Supply	1	Booster panel		07/23/2012
Pull Station	35	SIGA-270	Single Action	07/23/2012
Pull Station	13	SIGA-278	Dual Action	07/23/2012
Smoke Detector	78	SIGA-PS	Photoelectric	07/23/2012
Smoke Detector	1	SIGA2-PS	Photoelectric	07/23/2012
EST00000000				
Duct Detector	1	SIGA-PS	Photoelectric	07/23/2012

Building: Stamford BOE-West Hill High School	Control Panel: 2
---	-------------------------

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Type	Qty	Model #	Description	Install Date
<i>In Service - 5 Years to 10 Years</i>				
EST				
Duct Detector	3	SIGA-PS	Photoelectric	07/23/2012
Heat Detector	2	283B	Fixed Temperature	07/23/2012
Heat Detector	10	SIGA-HFS	Fixed Temperature	07/23/2012
Heat Detector	8	SIGA-HRS	Rate-of-Rise	07/23/2012
Pull Station	9	SIGA-270	Single Action	07/23/2012
Pull Station	1	SIGA-278	Dual Action	07/23/2012
Smoke Detector	23	SIGA-PS	Photoelectric	07/23/2012

Building: Stamford BOE-West Hill High School	Control Panel: 3
---	-------------------------

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Type	Qty	Model #	Description	Install Date
<i>In Service - 5 Years to 10 Years</i>				
EST				
Duct Detector	13	SIGA-PS	Photoelectric	07/23/2012
Heat Detector	5	283B	Fixed Temperature	07/23/2012
Heat Detector	12	SIGA-HFS	Fixed Temperature	07/23/2012
Heat Detector	1	SIGA-HRS	Rate-of-Rise	07/23/2012
Heat Detector	2	SIGA2-HFS	Fixed Temperature	07/23/2012
Pull Station	4	SIGA-270	Dual Action	07/23/2012
Pull Station	15	SIGA-270	Single Action	07/23/2012
Pull Station	2	SIGA-278	Dual Action	07/23/2012
Smoke Alarm	2	SIGA-PD		07/23/2012
Smoke Detector	8	SIGA-PS	Photoelectric	07/23/2012

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill High School

Control Panel: 1

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 12				
0002	Heat Detector	Ground A Wing Custodial Port By Boys Room	Fixed Temperature	04060418
0003	Heat Detector	Ground A Wing Arts And Crafts Room 12	Rate-of-Rise	04060399
0004	Heat Detector	Ground A Wing Auto By Exit	Rate-of-Rise	04060414
0005	Heat Detector	Ground A Wing Auto Class	Rate-of-Rise	04060415
0006	Heat Detector	Ground A Wing Fitness Room	Fixed Temperature	04060413
0007	Heat Detector	Ground A Wing Fitness Room	Fixed Temperature	04060412
0008	Heat Detector	Ground A Wing Art Room 11	Fixed Temperature	04060398
0009	Heat Detector	Ground A Wing Auto Shop Room 3 Storage	Fixed Temperature	21099776
0010	Heat Detector	Ground A Wing Pottery Room 10	Fixed Temperature	04060401
0011	Smoke Detector	1st A Wing Port Outside Room 6/7	Photoelectric	21099785
0012	Heat Detector	2nd A Wing Language Department By Room 204	Fixed Temperature	04062279
0013	Heat Detector	2nd A Wing English Department	Fixed Temperature	20666100
0014	Heat Detector	2nd A Wing Electrical By Room 218	Rate-of-Rise	04062293
0015	Heat Detector	2nd A Wing Janitors Closet By Room 219	Rate-of-Rise	04062292
0016	Heat Detector	2nd A Wing Room 214	Rate-of-Rise	20666101
0017	Heat Detector	2nd A Wing Custodian By Room 209	Fixed Temperature	20666108
0018	Heat Detector	2nd A Wing Room 202B	Rate-of-Rise	04062277
0019	Duct Detector	Penthouse A Wing AC-2	Photoelectric	04062340
0021	Duct Detector	Penthouse A Wing AC-1	Photoelectric	04062339
0022	Smoke Detector	Penthouse A Wing	Photoelectric	04062338
0023	Heat Detector	Ground A Wing Wood Shop	Rate-of-Rise	04060416
0025	Heat Detector	Ground A Wing Wood Shop West	Rate-of-Rise	04060417
0026	Heat Detector	Ground A Wing Wood Finishing Room	Rate-of-Rise	04062311
0027	Heat Detector	1st A Wing Prep Room Room 112/113 Storage	Rate-of-Rise	20666115
0028	Heat Detector	1st A Wing Science Room 113	Rate-of-Rise	20666114
0029	Heat Detector	1st A Wing Electrical Closet 158	Fixed Temperature	23587360
0030	Heat Detector	1st A Wing Science Room 107 Left	Rate-of-Rise	04062323
0031	Heat Detector	1st A Wing Custodial Port by Room 109	Rate-of-Rise	23587358
0032	Heat Detector	1st A Wing Room 118 Stage	Fixed Temperature	20668295
0033	Heat Detector	1st A Wing Storage Room Behind 118 Stage	Rate-of-Rise	04062316
0034	Heat Detector	1st A Wing Science Room 115 Left	Rate-of-Rise	04062322
0035	Heat Detector	1st A Wing Science Room 107 Right	Rate-of-Rise	04062324
0036	Heat Detector	1st A Wing Room 109 Left	Rate-of-Rise	20666111

0037	Heat Detector	1st A Wing Prep Room Storage Room 112/113	Rate-of-Rise	23587359
0038	Heat Detector	1st A Wing Custodian Port by rm 116	Fixed Temperature	20668294
0039	Heat Detector	1st A Wing Room 109 Right	Rate-of-Rise	20666110
0040	Smoke Detector	1st A Wing Chemistry Prep Room 109	Photoelectric	04062317
0041	Smoke Detector	1st A Wing Chemistry Prep Room Behind 115	Photoelectric	04062319
0042	Heat Detector	1st A Wing Science Room 115 Right	Rate-of-Rise	04062321
0043	Smoke Detector	1st A Wing Chemistry Storage Off Prep Room Behind 109	Photoelectric	04062320
0044	Smoke Detector	1st A Wing Science Room 114 Right	Photoelectric	20666113
0045	Heat Detector	Ground A Wing Room 9	Fixed Temperature	04060420
0046	Heat Detector	1st A Wing Science Room 114 Left	Rate-of-Rise	20666112
0047	Heat Detector	1st A Wing Business Office Across from Room 115	Rate-of-Rise	20666109
0048	Heat Detector	1st A Wing Physics Room 112	Rate-of-Rise	20666117
0049	Smoke Detector	Ground A Wing Electrical	Photoelectric	04060411
0050	Smoke Detector	1st A Wing Chemistry Prep Room Behind 114	Photoelectric	04062318
0051	Smoke Detector	1st A Wing ROTC Storage Room Across From Elevator	Photoelectric	23587353
0120	Duct Detector	Penthouse A Wing AC-3	Photoelectric	04062341
0132	Pull Station	Ground A Wing Fitness Room	Single Action	04060395
0133	Pull Station	Ground A Wing Arts And Crafts Room 12	Single Action	04060393
0134	Pull Station	Ground A Wing By Room 11	Single Action	04060394
0135	Pull Station	Ground A Wing Art Room 11	Single Action	04060397
0136	Pull Station	Ground A Wing Auto By Exit	Single Action	04060396
0137	Pull Station	Ground A Wing Pottery Room 10	Single Action	04060400
0144	Pull Station	2nd A Wing By Room 202B	Single Action	20666102
0145	Pull Station	3rd A Wing Stair 7	Single Action	04060376
0146	Pull Station	2nd A Wing Stair 6 By Room 210	Single Action	04060374
0147	Pull Station	2nd A Wing By Room 206	Single Action	04060375
0153	Pull Station	Penthouse A Wing	Single Action	04062337
0154	Heat Detector	Penthouse A Wing	Fixed Temperature	20666104
0155	Heat Detector	Penthouse A Wing	Fixed Temperature	20666103
0158	Pull Station	Ground A Wing By Room 1	Single Action	04060392
0159	Pull Station	Ground A Wing Stair By Room 7	Single Action	04060402
0160	Pull Station	Ground A Wing Room 9	Single Action	04060421
0161	Pull Station	Ground A Wing Corridor by Room 4	Single Action	04060403
0162	Pull Station	1st A Wing By Room 111	Single Action	04060372
0165	Pull Station	1st A Wing By Room 105	Single Action	04060371
0169	Pull Station	1st A Wing By Main Office	Single Action	04060369
0170	Pull Station	1st A Wing By Room 101	Single Action	04060370
0174	Pull Station	Ground A Wing Wood Shop	Single Action	04060404
Zone/Circuit: 13				
0001	Duct Detector	Penthouse C Wing AC-7 Return	Photoelectric	20666139
0002	Duct Detector	Penthouse C Wing AC-9 Supply	Photoelectric	20666140
0004	Smoke Detector	1st A Wing Main Office	Photoelectric	20666118
0005	Smoke Detector	1st Main Switch Gear Room	Photoelectric	17013137
0006	Heat Detector	Penthouse C Wing Catwalk North Entrance	Fixed Temperature	20666142
0007	Heat Detector	Penthouse C Wing Catwalk South	Fixed Temperature	20666145

0008	Heat Detector	1st A Wing Port By Music Room	Fixed Temperature	04060447
0009	Duct Detector	Penthouse C Wing Up Catwalk Up Ladder	Photoelectric	20666147
0010	Duct Detector	Penthouse C Wing Up Catwalk	Photoelectric	20666146
0011	Duct Detector	Penthouse C Wing Catwalk North Entrance	Photoelectric	20666144
0013	Heat Detector	1st Above Stage Right	Fixed Temperature	21098071
0013	Duct Detector	Penthouse C Wing AC-9	Photoelectric	20666141
0014	Heat Detector	Ground Craft Room Off Stage	Fixed Temperature	21098068
0015	Heat Detector	Basement Below Stage Chiller/Pump Room	Fixed Temperature	21098074
0016	Smoke Detector	2nd A Wing Audio Visual Center	Photoelectric	04062280
0017	Heat Detector	Basement Below Stage Switchgear Room	Fixed Temperature	21098072
0018	Smoke Detector	1st A Wing Main Office	Photoelectric	04060366
0019	Smoke Detector	1st File Storage Main Office	Photoelectric	04062295
0020	Smoke Detector	1st A Wing Main Office	Photoelectric	04060365
0021	Heat Detector	1st Main Office Communication Room	Fixed Temperature	04062294
0022	Smoke Detector	Auditorium Projection Booth	Photoelectric	21098096
0023	Heat Detector	2nd Media Center Kitchen	Fixed Temperature	04062281
0024	Heat Detector	Basement Below Stage Chiller Pump Room Front	Fixed Temperature	21098073
0025	Smoke Detector	Ground A Wing Elevator Machine Room	Photoelectric	04060446
0026	Smoke Detector	Ground B Wing Electrical Room Behind Stage	Photoelectric	20666148
0027	Heat Detector	Basement Below Stage By Exit Chiller Pump Room	Fixed Temperature	21098077
0028	Heat Detector	Basement Below Stage Center Chiller Pump Room	Fixed Temperature	21098076
0138	Pull Station	Ground A Wing By Rear Music Exit	Single Action	04060405
0139	Pull Station	1st A Wing Music Room	Single Action	04060406
0140	Pull Station	1st North Corridor By Stage Exit	Single Action	04060407
0141	Pull Station	1st A Wing Rear Center Exit Band Entrance	Dual Action	04062315
0142	Pull Station	1st Southwest By Rear Exit	Single Action	04060410
0147	Pull Station	Basement Below Stage Chiller Room By Exit	Single Action	21098078
0149	Pull Station	Ground Right Of Stage By Curtain	Single Action	04060409
0150	Pull Station	1st Stage Left On Stage	Single Action	21098070
0152	Pull Station	Ground Auditorium/Stage Right Workroom	Single Action	04060408
0154	Pull Station	1st Southeast By Exit Door	Single Action	21098079
0158	Heat Detector	Basement Below Stage Generator Room	Fixed Temperature	21098075
0160	Pull Station	Basement Switchgear Room Under Stage	Single Action	21098080
0167	Pull Station	1st A Wing Outside Main Office	Single Action	04060368
0172	Pull Station	2nd A Wing By Cafe	Single Action	04062282
0173	Pull Station	2nd A Wing Outside Media Center	Single Action	04060373
Zone/Circuit: 16				
0001	Smoke Detector	2nd 500 Corridor By Teachers Room	Photoelectric	21098108
0002	Smoke Detector	1st Corridor 500 Wing By Main Office	Photoelectric	21098123
0003	Smoke Detector	2nd 500 Wing Corridor By Electrical Room	Photoelectric	21098115
0004	Smoke Detector	1st Corridor Passageway West To 500 Wing	Photoelectric	17013139

0005	Smoke Detector	1st 500 Wing Corridor By Room 501/503	Photoelectric	17012987
0006	Smoke Detector	2nd 500 Wing Corridor By Room 505	Photoelectric	17012975
0007	Heat Detector	Ground Garage By Loading Dock	Fixed Temperature	20668303
0008	Smoke Detector	Lower New Gym Storage	Photoelectric	20668322
0009	Heat Detector	Ground Garage By Loading Dock	Fixed Temperature	20668306
0010	Smoke Detector	Ground Storage Room By Loading Dock	Photoelectric	20668301
0011	Heat Detector	Ground Garage by Loading Dock	Fixed Temperature	20668302
0012	Heat Detector	Ground Mechanical Room Inside Garage	Fixed Temperature	20668305
0013	Smoke Detector	Ground Storage By Loading Dock	Photoelectric	20668300
0014	Smoke Detector	Lower New Gym Sprinkler/Electrical	Photoelectric	20668316
0015	Smoke Detector	2nd 500 Wing Corridor By Boys Room	Photoelectric	17012981
0016	Smoke Detector	1st Elevator Lobby 500 Wing Corridor By Exit	Photoelectric	17012978
0017	Smoke Detector	1st Corridor 500 Wing Admin. Storage Room	Photoelectric	21098121
0018	Smoke Detector	2nd 500 Corridor By 512 Room	Photoelectric	21098109
0019	Heat Detector	Ground Garage By Loading Dock	Fixed Temperature	20668304
0020	Smoke Detector	1st Corridor 500 Wing Admin.	Photoelectric	21098120
0021	Smoke Detector	2nd 500 Wing Corridor By Exit	Photoelectric	17012979
0022	Smoke Detector	1st Storage Room by Room 511	Photoelectric	21098110
0023	Smoke Detector	1st 500 Wing Corridor By Staff Restrooms	Photoelectric	17013138
0024	Smoke Detector	1st 500 Wing CAPT Storage Room	Photoelectric	21099777
0025	Smoke Detector	2nd 500 Wing Corridor By Exit	Photoelectric	17012980
0026	Smoke Detector	1st Corridor 500 Wing Admin.	Photoelectric	21098124
0027	Smoke Detector	1st Corridor 500 Wing Admin.	Photoelectric	21098122
0028	Smoke Detector	2nd 500 Wing Corridor By Girls Room	Photoelectric	17012977
0029	Smoke Detector	1st 500 Wing Corridor By Room 509/508	Photoelectric	17012986
0030	Smoke Detector	2nd 500 Wing Corridor By Electrical Room	Photoelectric	21098116
0031	Smoke Detector	2nd 500 Wing Electrical Room By 510	Photoelectric	21098111
0032	Smoke Detector	2nd 500 Wing Corridor By Room 507	Photoelectric	17012974
0034	Smoke Detector	Lower New Gym Storage	Photoelectric	20668325
0035	Heat Detector	1st 500 Wing In Boys Room	Fixed Temperature	17012985
0036	Heat Detector	1st 500 Wing Staff Womens Restroom	Fixed Temperature	17012982
0037	Heat Detector	1st 500 Wing Staff Mens Restroom	Fixed Temperature	17012983
0038	Heat Detector	1st 500 Wing Elevator Machine Room Outside Entrance	Fixed Temperature	20668293
0040	Heat Detector	Ground Mens Restroom by Garage	Fixed Temperature	20668307
0041	Heat Detector	Ground Womens Restroom by Garage Above Ceiling	Fixed Temperature	20668308
0042	Heat Detector	1st 500 Wing In Girls Room	Fixed Temperature	17012984
0043	Smoke Detector	1st Custodial Room by Room 512	Photoelectric	21099778
0044	Heat Detector	Lower Level New Gym Girls Bathroom	Fixed Temperature	20668320
0045	Heat Detector	Lower New Gym PE Office Bathroom	Fixed Temperature	20668321
0046	Smoke Detector	Lower New Gym Lobby	Photoelectric	20668318
0047	Smoke Detector	2nd 500 Wing Corridor Passageway East	Photoelectric	17013141
0048	Heat Detector	Lower Level New Gym Boys Bathroom	Fixed Temperature	21099783
0049	Smoke Detector	2nd 500 Wing Corridor Passageway East	Photoelectric	20668287
0050	Smoke Detector	Lower Level 600 Wing Elevator Machine	Photoelectric	20668292

0051	Smoke Detector	Room Outside Entrance 1st Corridor 500 Wing	Photoelectric	21098126
0052	Smoke Detector	By Conference Room 2nd 500 Wing Corridor By Electrical	Photoelectric	21098117
0053	Smoke Detector	Room 1st Corridor 500 Wing	Photoelectric	21098125
0054	Smoke Detector	By 507 Computer Lab		
0055	Smoke Detector	Lower Freshmen Gym Lobby	Photoelectric	20668324
0056	Heat Detector	Lower New Gym Mens PE Office	Fixed Temperature	20668319
0057	Smoke Detector	Bathroom		
0058	Smoke Detector	1st 500s Uniform Room	Photoelectric	17013142
0059	Smoke Detector	Lower Freshmen Gym Lobby	Photoelectric	20668323
0137	Duct Detector	New Gym By Girls PE Office	Photoelectric	20668284
0149	Duct Detector	Lower New Gym By Girls PE Office	Photoelectric	20668283
0158	Pull Station	Ground Garage By Loading Dock	Dual Action	20668298
0159	Pull Station	1st 500 Wing Corridor By Exit	Dual Action	17012988
0160	Pull Station	2nd 500 Wing Corridor By Electrical	Dual Action	21098114
0161	Pull Station	Room		
0168	Pull Station	2nd 500 Wing corridor By Exit	Dual Action	17012976
0169	Pull Station	1st Outside Gym Corridor Exit Door	Dual Action	17013140
0170	Pull Station	Ground Storage By Loading Dock	Dual Action	20668299
0171	Pull Station	Lower New Gym Exit rear	Dual Action	20668326
0172	Pull Station	Lower New Gym Lobby	Dual Action	20668329
0173	Pull Station	Lower New Gym Exit Rear	Dual Action	20668327
0174	Pull Station	Lower New Gym Entrance	Dual Action	20668328
0175	Beam Detector	New Gym		20668281
0176	Beam Detector	New Gym		20668282
Zone/Circuit: 17				
0001	Smoke Detector	2nd 600 Wing Corridor By Room 609	Photoelectric	20668363
0002	Smoke Detector	2nd 600 Wing Corridor By Room 606	Photoelectric	20668368
0003	Duct Detector	2nd 600 Wing Corridor Outside 609	Photoelectric	20668367
0004	Duct Detector	2nd 600 Wing Room 615/616 Prep	Photoelectric	20668346
0005	Smoke Detector	Room 3		
0006	Smoke Detector	2nd 600 Wing Inside Stair 1	Photoelectric	20668374
0007	Duct Detector	2nd North Between Boys/Girls Room	Photoelectric	21098107
0008	Smoke Detector	Above Ceiling		
0009	Smoke Detector	2nd Corridor Outside Cafe By Double	Photoelectric	21098127
0010	Duct Detector	Doors		
0011	Duct Detector	2nd 600 Wing Room 615/616 Prep	Photoelectric	20668344
0012	Duct Detector	Room 3		
0013	Duct Detector	2nd 600 Wing Corridor By Room 606	Photoelectric	20668365
0014	Duct Detector	2nd 600 Wing Corridor By Room 613	Photoelectric	20668357
0015	Duct Detector	2nd 600 Wing Corridor By Room	Photoelectric	20668354
0016	Heat Detector	613-614		
0017	Heat Detector	2nd Girls Restroom 600's Corridor	Fixed Temperature	21098104
0018	Heat Detector	2nd 600 Wing Room 612	Fixed Temperature	20668353
0019	Heat Detector	2nd Womens Staff Restroom 600's	Fixed Temperature	21098102
0020	Heat Detector	Corridor		
0021	Heat Detector	2nd 600 Wing Room 615/616 Prep	Fixed Temperature	20668347
0022	Heat Detector	Room 3		
0023	Heat Detector	2nd Mens Staff 600's Corridor	Fixed Temperature	21098101
0024	Heat Detector	2nd 600 Wing Room 615/616 Prep	Fixed Temperature	20668348
0025	Heat Detector	Room 3		

0018	Heat Detector	2nd 600 Wing Room 613/614 Prep Room 2	Fixed Temperature	20668350
0019	Heat Detector	2nd 600 Wing Room 613/614 Prep Room 2	Fixed Temperature	20668351
0020	Smoke Detector	2nd 600 Wing Corridor By Stair 1	Photoelectric	20668371
0022	Heat Detector	2nd 600's Corridor Boys Restroom	Fixed Temperature	21098106
0023	Smoke Detector	2nd 600 Wing Corridor By Stair 1	Photoelectric	20668373
0025	Smoke Detector	2nd 600 Wing Corridor By Room 604	Photoelectric	20668369
0026	Smoke Detector	2nd Corridor Outside Cafe By Double Doors	Photoelectric	21098105
0027	Smoke Detector	2nd Corridor Outside Cafe By Double Doors	Photoelectric	21098129
0028	Smoke Detector	2nd A Wing Corridor East To Cafe By Doors	Photoelectric	21098100
0029	Smoke Detector	2nd 600 Wing Elevator Lobby	Photoelectric	20668288
0030	Smoke Detector	2nd 600 Wing Corridor By Room 614	Photoelectric	20668352
0031	Smoke Detector	2nd 600 Wing Corridor By Stair 2 Room 611	Photoelectric	20668360
0032	Smoke Detector	2nd 600 Wing Corridor By Stair 2 Room 611	Photoelectric	20668361
0033	Smoke Detector	2nd 600 Wing Corridor By Room 615	Photoelectric	20668349
0034	Smoke Detector	2nd 600 Wing Inside Stair 2	Photoelectric	20668359
0035	Smoke Detector	2nd Corridor Outside Cafe	Photoelectric	21098103
0037	Smoke Detector	2nd 600 Wing Corridor Room 613	Photoelectric	20668358
0038	Smoke Detector	2nd 600 Wing Corridor By Room 616	Photoelectric	20668342
0039	Smoke Detector	2nd 600 Wing Corridor By Room 601	Photoelectric	20668370
0046	Smoke Detector	2nd 500 Wing Custodial Port	Photoelectric	21098128
0145	Pull Station	2nd 600 Wing Corridor by Stair 2 Room 611	Dual Action	20668362
0146	Pull Station	2nd 600 Wing Corridor By Stair 1	Dual Action	20668372
1449	Pull Station	2nd Gym	Single Action	04060389
1464	Pull Station	2nd Gym	Single Action	17013147
3763	Heat Detector	600 Wing Elevator Pit	Fixed Temperature	20668291
3763	Heat Detector	600 Wing Top Of Shaft	Fixed Temperature	20668289
3926	Smoke Detector	600 Wing Elevator Top of Shaft	Photoelectric	20668290

Building: Stamford BOE-West Hill High School

Control Panel: 2

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 03				
0001	Duct Detector	2nd B Wing Penthouse AC 5 Supply	Photoelectric	04062358
0002	Smoke Detector	1st B Wing Special ED Storage	Photoelectric	04062370
0003	Smoke Detector	1st B Wing Main Office By Panel	Photoelectric	04062299
0004	Smoke Detector	1st B Wing Main Office	Photoelectric	04062298
0005	Smoke Detector	2nd B Wing Room 401 Storage	Photoelectric	04062359
0006	Smoke Detector	1st B Wing Main Office By Smaller Offices	Photoelectric	04062300
0007	Smoke Detector	1st B Wing Science Department Storage	Photoelectric	04062309
0008	Smoke Detector	2nd B Wing Electrical Room by Room 414	Photoelectric	04062354
0009	Smoke Detector	2nd B Wing Room 403 Office/Storage	Photoelectric	04062360
0010	Smoke Detector	1st B Wing Room 316A Speech	Photoelectric	20666136
0011	Smoke Detector	1st B Wing Prep Room Smoke 1	Photoelectric	04062366
0012	Smoke Detector	1st B Wing Math Department Storage	Photoelectric	04062364
0013	Smoke Detector	1st B Wing Science Department Storage By Room 319	Photoelectric	20668335
0014	Smoke Detector	1st B Wing Rm 314 Storage	Photoelectric	04062365
0015	Smoke Detector	1st B Wing Prep Room Smoke 2	Photoelectric	04062367
0016	Smoke Detector	1st B Wing Prep Room Storage	Photoelectric	20666128
0017	Smoke Detector	1st B Wing Electrical Room by 321	Photoelectric	04062368
0018	Heat Detector	1st B Wing Room 309	Rate-of-Rise	20666132
0019	Heat Detector	2nd B Wing Custodian Port By Room 405	Fixed Temperature	20668341
0020	Heat Detector	1st B Wing Port By 302	Rate-of-Rise	23587355
0021	Heat Detector	2nd B Wing Custodian Port By Room 432	Fixed Temperature	20668340
0023	Heat Detector	1st B Wing Science Department	Rate-of-Rise	04062308
0024	Heat Detector	1st B Wing Math Department	Fixed Temperature	20666126
0025	Heat Detector	1st B Wing B315	Fixed Temperature	20666130
0026	Heat Detector	1st B Wing B304	Rate-of-Rise	20666122
0027	Heat Detector	1st B Wing B306	Rate-of-Rise	20666124
0028	Heat Detector	1st B Wing Room 308	Fixed Temperature	20666127
0029	Heat Detector	1st B Wing B310	Rate-of-Rise	20666133
0030	Heat Detector	1st B Wing By Port By Room B322	Fixed Temperature	20666137
0031	Heat Detector	1st B Wing B313	Fixed Temperature	20666129
0032	Heat Detector	1st B Wing B305	Rate-of-Rise	20666123
0033	Heat Detector	1st B Wing B321	Fixed Temperature	20666131
0034	Heat Detector	1st B Wing B307	Rate-of-Rise	20666125
0036	Heat Detector	2nd B Wing Custodian Port By Cafe	Fixed Temperature	20668336
0038	Heat Detector	1st B Wing Room 323	Fixed Temperature	20668334
0039	Duct Detector	2nd B Wing Penthouse AC 4 Return	Photoelectric	04062357
0040	Duct Detector	2nd B Wing Penthouse AC 4 Supply	Photoelectric	04062356
0041	Smoke Detector	1st B Wing Passage A352 By Room 312 By Double Doors Closet in Storage	Photoelectric	20666134
0042	Smoke Detector	1st B Wing Storage A51	Photoelectric	23587354
0043	Smoke Detector	1st B Wing Passage A352 By Room 312	Photoelectric	04062305

		By Double Doors		
0044	Smoke Detector	1st B Wing Passage A352 By Room 312	Photoelectric	04062302
0045	Smoke Detector	1st B Wing Passage A352 By Room 312	Photoelectric	04062306
		By Double Doors Storage		
0046	Smoke Detector	1st B Wing Passage A352 By Room 312	Photoelectric	04062304
		By Double Doors		
0047	Smoke Detector	1st B Wing Special ED Hall	Photoelectric	04062369
0132	Pull Station	1st B Wing By Room B312	Single Action	04060384
0133	Pull Station	1st B Wing By Room 317	Single Action	04060383
0134	Pull Station	2nd B Wing Penthouse	Single Action	04062355
0135	Pull Station	2nd B Wing Corridor Stair By Room	Single Action	04060377
		400/Media Center		
0136	Pull Station	1st B Wing Main Lobby	Single Action	04060380
0137	Pull Station	1st B Wing By 302	Single Action	04060381
0138	Pull Station	1st B Wing By B306/B307	Single Action	04060382
0139	Pull Station	2nd B Wing By Room 411	Single Action	04060378
0140	Pull Station	2nd B Wing By Room 427	Single Action	04060379
0145	Heat Detector	2nd B Wing Penthouse	Fixed Temperature	20668337
0148	Heat Detector	2nd B Wing Penthouse	Fixed Temperature	20668338
0155	Pull Station	1st B Wing Passage A352 By Room 312	Dual Action	04062303
		By Double Doors Closet in Storage		

Building: Stamford BOE-West Hill High School

Control Panel: 3

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 02				
0001	Duct Detector	Penthouse Penthouse gym/cafe V 7 return	Photoelectric	04062346
0002	Duct Detector	Penthouse Penthouse gym/cafe V 7 supply	Photoelectric	04062345
0003	Duct Detector	Penthouse Penthouse gym/cafe V 8 return	Photoelectric	04062347
0004	Duct Detector	Penthouse Penthouse gym/cafe V 10 supply	Photoelectric	04062351
0005	Duct Detector	1st Gym V-5	Photoelectric	04062362
0006	Duct Detector	Penthouse Penthouse gym/cafe V 8 supply	Photoelectric	04062350
0007	Duct Detector	Penthouse Penthouse gym/cafe V 7supply2	Photoelectric	04062344
0008	Duct Detector	Penthouse Penthouse gym/cafe V 8 supply	Photoelectric	04062349
0009	Duct Detector	1st Gym V-3	Photoelectric	04062363
0010	Smoke Detector	1st Gym Trainers Room	Photoelectric	04062361
0011	Smoke Detector	1st Wrestling Room Storage	Photoelectric	21099784
0012	Smoke Detector	1st Gym Electrical Room	Photoelectric	04060386
0013	Duct Detector	Ground Head Custodian Inter Office V13#2	Photoelectric	20668296
0014	Duct Detector	Ground Custodian Office V13 #1	Photoelectric	20668297
0015	Smoke Detector	Lower Lobby Pool/Elevator Machine Room	Photoelectric	21099781
0016	Smoke Detector	Lower Pool Office Storage	Photoelectric	04062330
0017	Smoke Detector	2nd Kitchen Port Slop Sink	Photoelectric	23587356
0018	Heat Detector	Lower Level Pool Storage Under Bleachers	Fixed Temperature	20668332
0019	Heat Detector	2nd B Cafe Prep Area Right Side of Hood	Fixed Temperature	04062287
0020	Heat Detector	Lower New Gym Sprinkler/ Electrical	Fixed Temperature	20668317
0021	Heat Detector	Ground Pool Storage Under Bleachers	Fixed Temperature	04062329
0022	Heat Detector	1st Girls Locker Room Port Janitor Closet	Fixed Temperature	17013144
0023	Heat Detector	Ground Pool Mechanical Room	Fixed Temperature	20668333
0024	Heat Detector	2nd Kitchen A Side Serving Line	Fixed Temperature	04062284
0025	Heat Detector	Lower Level Custodian Port by Mens Lockers	Fixed Temperature	20668331
0026	Heat Detector	2nd Kitchen A Side Serving Line	Fixed Temperature	04062285
0027	Heat Detector	2nd B Cafe Serving Line	Fixed Temperature	04062288
0028	Heat Detector	1st Boys Locker Room Custodial Port	Fixed Temperature	04062327
0029	Heat Detector	2nd B Cafe Serving Line	Fixed Temperature	04062289
0030	Heat Detector	Ground Garage Left Of Loading Dock	Fixed Temperature	23587357
0031	Heat Detector	Lower Laundry Room By Dock	Rate-of-Rise	20668330
0032	Smoke Detector	Lower Lobby Pool/Elevator Lobby	Photoelectric	04060455
0033	Duct Detector	Penthouse Penthouse gym/cafe V 12	Photoelectric	04062352

0034	Duct Detector	supply Penthouse Penthouse gym/cafe V 5 return	Photoelectric	04062342
0035	Smoke Detector	Ground Custodian Port Room 755	Photoelectric	04062331
0036	Heat Detector	2nd B Cafe Prep Area Left Of Hood	Fixed Temperature	04062286
0048	Smoke Alarm	Penthouse gym/cafe		51386304
0135	Pull Station	1st Main Gym	Single Action	04060388
0136	Pull Station	Lower Receiving Dock Entrance	Dual Action	04060448
0137	Pull Station	Ground Pool Deck Area	Dual Action	04060452
0138	Pull Station	1st Pool Bleacher Area by Dock	Dual Action	04060453
0139	Pull Station	Ground Pool Lobby By Room 751	Dual Action	04060450
0140	Pull Station	2nd Gym Corridor Middle Outside Boys Locker Room	Single Action	17013148
0141	Pull Station	Lower Lobby Pool Lobby	Dual Action	04060454
0142	Pull Station	Ground Lobby By Room 757	Dual Action	04060451
0143	Pull Station	Lower Main Gym Foyer	Single Action	04060391
0144	Pull Station	2nd Girls Auxilary Gym Corridor	Single Action	17013143
0145	Pull Station	Penthouse Penthouse gym/cafe	Single Action	51386301
0146	Smoke Alarm	Penthouse Penthouse gym/cafe		51386303
0147	Pull Station	Lower Corridor By Custodian /Electrical	Single Action	04062325
0148	Pull Station	1st Main Gym	Single Action	04060390
0151	Pull Station	Penthouse North Gym/Cafe	Single Action	51386312
Zone/Circuit: 2				
0152	Pull Station	Penthouse South Gym Penthouse	Single Action	51386302
Zone/Circuit: 02				
0155	Pull Station	1st Girls Auxilary Gym	Single Action	17013146
0158	Heat Detector	Penthouse gym/cafe Mechanical rm heat 5	Fixed Temperature	20668309
0164	Heat Detector	Penthouse gym/cafe Mechanical rm heat 2	Fixed Temperature	20668314
0165	Heat Detector	Penthouse gym/cafe Mechanical rm heat 1	Fixed Temperature	20668315
0166	Heat Detector	Penthouse gym/cafe Mechanical rm heat 4	Fixed Temperature	20668310
0181	Heat Detector	Penthouse gym/cafe Mechanical rm heat 2	Fixed Temperature	20668313
0186	Pull Station	1st Wrestling gym	Single Action	04062326
0187	Pull Station	Lower Main Gym Lobby	Single Action	04060385
Zone/Circuit: 2				
194	Pull Station	1st Girls Auxilary Gym	Single Action	47370589
Zone/Circuit: 02				
0195	Pull Station	1st Outside Gym Corridor Gym Hall Behind Girls Locker	Single Action	04062328
0196	Pull Station	2nd North Cafe by Stairs 901	Single Action	04062353

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-West Hill Vo-Ag
Annex
125 Roxbury Rd
Stamford, CT 06902

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Mar 24, 2020

Building: Stamford BOE-West Hill Vo-Ag Annex
Contact: Davor Lucaj
Title: Facilities Trades Manager



Company: TPC Associates, Inc.
Contact: Michael Hernandez
Title: Fire Alarm Inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-West Hill Vo-Ag Annex	Contact: Davor Lucaj	
Address: 125 Roxbury Rd	Phone: 203-977-6668	
Address:	Fax:	
City/State/Zip: Stamford, CT 06902	Mobile: 347-675-6021	
Country: United States of America	Email: dlucaj@stamfordct.gov	
Inspection Performed By		
Company: TPC Associates, Inc.	Inspector: Michael Hernandez	
Address: 261 Pepe's Farm Road	Phone: 203-878-1321	
Address:	Fax:	
City/State/Zip: Milford, Connecticut 06460	Mobile:	
Country: United States of America	Email: mhernandez@tpcsystems.com	
System Control Unit		
Manufacturer: Edwards	Inspection Date: 03/24/2020	IDC Style:
Model Number: FireShield Plus	Install Date: 08/09/2007	SLC Style:
Software Version:	Version Date: 08/09/2007	NAC Style:
Location: 2nd F.A.C.P.	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	4.17%	0	0%	0	0%	0	0%
Control	2	8.33%	2	100.00%	2	100.00%	0	0%
Initiating	21	87.50%	21	100.00%	21	100.00%	0	0%
Totals	24	100%	23	95.83%	23	100.00%	0	0%

Certification	
Company: TPC Associates, Inc. Inspector: Michael Hernandez <div style="border: 1px solid black; padding: 5px; margin-top: 10px;">  </div> Signed: Mar 24, 2020 10:58:07 AM	Building: Stamford BOE-West Hill Vo-Ag Annex Contact: Davor Lucaj <div style="border: 1px solid black; padding: 5px; margin-top: 10px;">  </div> Signed: Mar 24, 2020 10:57:40 AM

Michael Hernandez Certifications	
Certification Type	Number
Inspectors Boot Camp	

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill Vo-Ag Annex		Control Panel: 1 - Edwards FireShield Plus		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Battery	2nd F.A.C.P.	Tested	10:22:56 AM	03/24/2020
Control Panel	2nd F.A.C.P.	Tested	10:21:07 AM	03/24/2020
Initiating				
Heat Detector	1st Boiler Rm	Visually Checked	10:26:06 AM	03/24/2020
Heat Detector	1st Custodian Rm	Visually Checked	10:26:02 AM	03/24/2020
Heat Detector	1st Back Rm	Visually Checked	10:22:24 AM	03/24/2020
Heat Detector	1st Back Rm	visually Checked	10:22:30 AM	03/24/2020
Heat Detector	1st Back Rm	Visually Checked	10:22:48 AM	03/24/2020
Heat Detector	1st Men's Bathroom	Visually Checked	10:25:59 AM	03/24/2020
Heat Detector	1st Women's Bathroom	Visually Checked	10:25:56 AM	03/24/2020
Heat Detector	2nd Back Rm	Visually Checked	10:26:10 AM	03/24/2020
Pull Station	1st Back Entrance	Visually Checked	10:26:15 AM	03/24/2020
Pull Station	1st Main Entrance	Visually Checked	10:17:38 AM	03/24/2020
Pull Station	1st Main Entrance	Visually Checked	10:26:22 AM	03/24/2020
Pull Station	1st Shop	Visually Checked	10:26:19 AM	03/24/2020
Smoke Detector	1st Corridor	Visually Checked	10:26:26 AM	03/24/2020
Smoke Detector	1st Corridor	Visually Checked	10:26:30 AM	03/24/2020
Smoke Detector	1st Corridor	Visually Checked	10:26:33 AM	03/24/2020
Smoke Detector	1st Ejector Rm	Visually Checked	10:23:58 AM	03/24/2020
Smoke Detector	2nd Back Rm	Visually Checked	10:22:12 AM	03/24/2020
Smoke Detector	2nd Front Room	Visually Checked	10:26:37 AM	03/24/2020
Smoke Detector	2nd Near Panel	Visually Checked	10:26:51 AM	03/24/2020
Smoke Detector	2nd Storeroom	Visually Checked	10:26:41 AM	03/24/2020
Smoke Detector	2nd Top of Stairwell	Visually Checked	10:23:49 AM	03/24/2020

Service Summary

Generated by: BuildingReports.com




Building: Stamford BOE-West Hill Vo-Ag Annex

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Passed</i>		
Battery	Tested	1
Control Panel	Tested	1
Heat Detector	Visually Checked	7
Heat Detector	visually Checked	1
Pull Station	Visually Checked	4
Smoke Detector	Visually Checked	9
Total		23
Grand Total		23

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill Vo-Ag Annex								
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>								
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test		
		◀ dB	◀ dB	Voice	STI			
<i>Untested</i>								
Sound Test Points								
Whole Facility				<input type="checkbox"/>		0001		

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill Vo-Ag Annex				Control Panel: 1 - Edwards FireShield Plus			
<i>The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	2nd F.A.C.P.	8AH	12V	12.38V	7.8Ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-West Hill Vo-Ag Annex			Control Panel: 1 - Edwards FireShield Plus		
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>					
Device or Type		Category		% of Inventory	Quantity
Sound Test		Sound Test		4.17%	1
Pull Station		Initiating		16.67%	4
Control Panel		Control		4.17%	1
Smoke Detector		Initiating		37.50%	9
Heat Detector		Initiating		33.33%	8
Battery		Control		4.17%	1
Type	Qty	Model #	Description		Install Date
In Service - 2 Years to 3 Years					
System Sensor					
Smoke Detector	1	2WB	Photoelectric		12/07/2017
Universal					
Battery	1	UB1280	Sealed Lead Acid		12/07/2017
In Service - 10 Years to 15 Years					
Edwards					
Control Panel	1	FireShield Plus			08/09/2007
Heat Detector	8	283B	Fixed Temperature		08/09/2007
Smoke Detector	8	6270B	Photoelectric		08/09/2007
Gamewell					
Pull Station	4	Dual Action			08/09/2007

Fire Alarm and Life Safety System Inspection Certificate

For

Stamford BOE-Academy of Info
Tech & Engineering
411 High Ridge Rd
Stamford, Ct 06905

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Mar 24, 2020



Building: Stamford BOE-Academy of Info Tech &
Engineering
Contact: Davor Lucaj
Title: Facilities Trades Manager

Company: TPC Associates, Inc.
Contact: Michael Hernandez
Title: Fire Alarm Inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Stamford BOE-Academy of Info Tech & Engineering		Contact: Davor Lucaj
Address: 411 High Ridge Rd		Phone: 203-977-6668
Address:		Fax:
City/State/Zip: Stamford, Ct 06905		Mobile: 347-675-6021
Country: United States of America		Email: dlucaj@stamfordct.gov
Inspection Performed By		
Company: TPC Associates, Inc.		Inspector: Michael Hernandez
Address: 261 Pepe's Farm Road		Phone: 203-878-1321
Address:		Fax:
City/State/Zip: Milford, Connecticut 06460		Mobile:
Country: United States of America		Email: mhernandez@tpcsystems.com
System Control Unit		
Manufacturer: EST	Inspection Date: 03/24/2020	IDC Style:
Model Number: EST-3	Install Date: 07/19/2012	SLC Style:
Software Version:	Version Date: 07/19/2012	NAC Style:
Location: 1st Maintenance Office	Current Protection:	
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.30%	0	0%	0	0%	0	0%
Control	27	8.18%	27	100.00%	27	100.00%	0	0%
Initiating	302	91.52%	302	100.00%	302	100.00%	0	0%
Totals	330	100%	329	99.70%	329	100.00%	0	0%
Certification								
Company: TPC Associates, Inc.			Building: Stamford BOE-Academy of Info Tech & Engineering					
Inspector: Michael Hernandez			Contact: Davor Lucaj					
								
Signed: Mar 24, 2020 1:30:57 PM			Signed: Mar 24, 2020 1:30:27 PM					
Michael Hernandez Certifications								
Certification Type					Number			
Inspectors Boot Camp								

Inspection & Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Academy of Info Tech & Engineering		Control Panel: 1 - EST EST-3		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
Passed				
Control				
Annunciator	1st Lobby Main Office	Visually Checked	1:06:44 PM	03/24/2020
Annunciator	1st Main Lobby By Main Office	Visually Checked	1:06:53 PM	03/24/2020
Battery	1st Electrical Closet By Stair A (Center Booster)	Tested	11:40:50 AM	03/24/2020
Battery	1st Electrical Closet By Stair A (Left Booster)	Tested	11:39:48 AM	03/24/2020
Battery	1st Electrical Closet By Stair A (Right Booster)	Tested	11:41:42 AM	03/24/2020
Battery	1st Electrical Closet By Elevator (Bottom Booster)	Tested	11:34:32 AM	03/24/2020
Battery	1st Electrical Closet By Elevator (Top Booster)	Tested	11:35:45 AM	03/24/2020
Battery	1st Maintance Office Left	Tested	11:30:50 AM	03/24/2020
Battery	1st Maintance Office Right	Tested	11:30:18 AM	03/24/2020
Battery	2nd Inside Library Electrical Closet (Left Booster)	Tested	11:47:41 AM	03/24/2020
Battery	2nd Inside Library Electrical Closet (Right Booster)	Tested	11:48:37 AM	03/24/2020
Battery	2nd Electrical Closet By Stair A	Tested	11:44:17 AM	03/24/2020
Battery	3rd Electrical Closet By Elevator (Right Booster)	Tested	11:56:54 AM	03/24/2020
Battery	3rd Electrical Closet By Elevator Left Booster	Tested	11:56:13 AM	03/24/2020
Battery	3rd Electrical Closet By Stair A	Tested	11:53:38 AM	03/24/2020
Control Panel	1st Maintenance Office	Tested	11:59:05 AM	03/24/2020
Power Supply	1st Electrical Closet By Stair A (Center Booster)	Tested	11:39:45 AM	03/24/2020
Power Supply	1st Electrical Closet By Stair A (Left Booster)	Tested	11:39:30 AM	03/24/2020
Power Supply	1st Electrical Closet By Stair A (Right Booster)	Tested	11:39:47 AM	03/24/2020
Power Supply	1st Electrical Closet By Elevator (Bottom Booster)	Tested	11:34:17 AM	03/24/2020
Power Supply	1st Electrical Closet By Elevator (Top Booster)	Tested	11:35:32 AM	03/24/2020
Power Supply	2nd Inside Library Electrical Closet (Left Booster)	Tested	11:47:33 AM	03/24/2020
Power Supply	2nd Inside Library Electrical Closet (Right Booster)	Tested	11:47:31 AM	03/24/2020
Power Supply	2nd Electrical Closet By Stair A	Tested	11:44:06 AM	03/24/2020
Power Supply	3rd Electrical Closet By Stair A	Tested	11:53:13 AM	03/24/2020
Power Supply	3rd Electrical Closet By Elevator	Tested	11:55:56 AM	03/24/2020
Power Supply	3rd Electrical Closet By Elevator	Tested	11:56:02 AM	03/24/2020
Initiating				
Duct Detector	1st Gym HV-1 Return	Visually Checked	1:16:30 PM	03/24/2020
Duct Detector	1st Gym HV-1 Supply	Visually Checked	1:16:40 PM	03/24/2020
Duct Detector	3rd Alcove By Cisco Lab 310 AHU-6 Return	Visually Checked	11:40:13 AM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Duct Detector	3rd Alcove By Cisco Lab 310 AHU-6 Supply	Visually Checked	11:40:22 AM	03/24/2020
Duct Detector	3rd By Room 306A AHU-4 Supply	Visually Checked	11:44:27 AM	03/24/2020
Duct Detector	3rd Chemical Storage By Room 314 AHU-2 Return	Visually Checked	1:01:55 PM	03/24/2020
Duct Detector	3rd Corridor By Class Room 300 AHU-3 Return	Visually Checked	11:45:26 AM	03/24/2020
Duct Detector	3rd Corridor By Class Room 300 AHU-3 Supply	Visually Checked	11:45:22 AM	03/24/2020
Duct Detector	3rd Corridor By Top Of Atrium Stairs AHU-5 Supply	Visually Checked	11:41:05 AM	03/24/2020
Duct Detector	3rd Office/Prep Room By Room 315 AHU-2 Supply	Visually Checked	1:01:59 PM	03/24/2020
Duct Detector	3rd Office/Storage Room By Room 313 AHU-9 Return	Visually Checked	1:01:21 PM	03/24/2020
Duct Detector	3rd Office/Storage Room By Room 313 AHU-9 Supply	Visually Checked	1:01:52 PM	03/24/2020
Duct Detector	3rd Print Room 318 AHU-8 Return	Visually Checked	12:27:09 PM	03/24/2020
Duct Detector	3rd Print Room 318 AHU-8 Supply	Visually Checked	12:27:12 PM	03/24/2020
Duct Detector	3rd Room 305A AHU-4 Return	Visually Checked	1:01:17 PM	03/24/2020
Duct Detector	3rd Teachers Work Room AHU-1 Return	Visually Checked	1:04:11 PM	03/24/2020
Duct Detector	3rd Teachers Work Room AHU-1 Supply	Visually Checked	1:04:07 PM	03/24/2020
Duct Detector	Mezzanine Above Kitchen Mech Rm above AHU-7 Supply	Visually Checked	1:04:59 PM	03/24/2020
Duct Detector	Mezzanine Above Kitchen Mech Rm AHU-7 Return	Visually Checked	1:05:03 PM	03/24/2020
Heat Detector	1st Cafe Boys Rm	Visually Checked	1:09:16 PM	03/24/2020
Heat Detector	1st Cafe Girls Rm	Visually Checked	1:07:52 PM	03/24/2020
Heat Detector	1st Cafe Food Kiosk	Visually Checked	1:10:11 PM	03/24/2020
Heat Detector	1st Cafe Food Kiosk	Visually Checked	1:10:15 PM	03/24/2020
Heat Detector	1st Cafe Kitchen	Visually Checked	1:13:20 PM	03/24/2020
Heat Detector	1st Cafe Kitchen	Visually Checked	1:13:29 PM	03/24/2020
Heat Detector	1st Cafe Kitchen	Visually Checked	1:13:48 PM	03/24/2020
Heat Detector	1st Cafe Kitchen	Visually Checked	1:13:56 PM	03/24/2020
Heat Detector	1st Cafe Kitchen	Visually Checked	1:14:04 PM	03/24/2020
Heat Detector	1st Cafe Kitchen	Visually Checked	1:14:11 PM	03/24/2020
Heat Detector	1st Cafe Kitchen	Visually Checked	1:14:55 PM	03/24/2020
Heat Detector	1st Cafe Kitchen Office	visually Checked	1:15:19 PM	03/24/2020
Heat Detector	1st Cafe Kitchen restroom	Visually Checked	1:14:36 PM	03/24/2020
Heat Detector	1st Cafe Kitchen By Exit	Visually Checked	1:14:21 PM	03/24/2020
Heat Detector	1st Cafe Kitchen By restroom	Visually Checked	1:14:28 PM	03/24/2020
Heat Detector	1st Cafe Recieving Dock Thru Kitchen Passage	visually Checked	1:15:54 PM	03/24/2020
Heat Detector	1st Kitchen Storage	visually Checked	1:15:16 PM	03/24/2020
Heat Detector	1st Mech Room	Visually Checked	1:04:55 PM	03/24/2020
Heat Detector	1st Mech Room	Visually Checked	1:04:57 PM	03/24/2020
Heat Detector	1st Mech Room	Visually Checked	1:04:58 PM	03/24/2020
Heat Detector	1st Mech Room	Visually Checked	1:05:00 PM	03/24/2020
Heat Detector	1st Mech Room	Visually Checked	1:05:02 PM	03/24/2020
Heat Detector	1st Mech Room	Visually Checked	1:05:02 PM	03/24/2020
Heat Detector	1st Mech Room	Visually Checked	1:05:04 PM	03/24/2020
Heat Detector	1st Mech Room	Visually Checked	1:05:04 PM	03/24/2020
Heat Detector	1st Mech Room	Visually Checked	1:05:05 PM	03/24/2020
Heat Detector	1st Art Rm 101	visually Checked	1:13:12 PM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	1st Boys Rm	Visually Checked	12:06:11 PM	03/24/2020
Heat Detector	1st Boys Locker	Visually Checked	12:58:58 PM	03/24/2020
Heat Detector	1st Boys Locker	visually Checked	1:10:07 PM	03/24/2020
Heat Detector	1st Boys Locker	visually Checked	1:10:13 PM	03/24/2020
Heat Detector	1st Boys Locker	visually Checked	1:16:23 PM	03/24/2020
Heat Detector	1st Class 110	visually Checked	1:05:48 PM	03/24/2020
Heat Detector	1st Class 110	visually Checked	1:06:04 PM	03/24/2020
Heat Detector	1st Class 111	visually Checked	1:05:57 PM	03/24/2020
Heat Detector	1st Class 111	visually Checked	1:06:01 PM	03/24/2020
Heat Detector	1st Girls Bathroom Locker Rm	visually Checked	1:09:37 PM	03/24/2020
Heat Detector	1st Girls Bathroom Locker Rm	visually Checked	1:11:09 PM	03/24/2020
Heat Detector	1st Girls Bathroom Locker Rm	visually Checked	1:16:27 PM	03/24/2020
Heat Detector	1st Girls Bathroom	Visually Checked	1:02:24 PM	03/24/2020
Heat Detector	1st Girls Rm	Visually Checked	12:07:52 PM	03/24/2020
Heat Detector	1st Ladies Faculty	visually Checked	1:05:41 PM	03/24/2020
Heat Detector	1st Main Office Principal	visually Checked	1:06:59 PM	03/24/2020
Heat Detector	1st Mens Faculty	visually Checked	1:05:45 PM	03/24/2020
Heat Detector	1st Mens Faculty Bathroom	visually Checked	1:12:13 PM	03/24/2020
Heat Detector	1st Nurse Suite (Office 114) Bathroom	visually Checked	1:07:22 PM	03/24/2020
Heat Detector	1st Womans Faculty Bathroom	visually Checked	1:12:17 PM	03/24/2020
Heat Detector	2nd North Boys Restroom	Visually Checked	11:57:08 AM	03/24/2020
Heat Detector	2nd North Girls Restroom	Visually Checked	11:57:23 AM	03/24/2020
Heat Detector	2nd Girls Faculty Bathroom	Visually Checked	12:33:28 PM	03/24/2020
Heat Detector	2nd Inside Boys Bathroom	Visually Checked	11:52:45 AM	03/24/2020
Heat Detector	2nd Inside Girls Bathroom	Visually Checked	11:52:23 AM	03/24/2020
Heat Detector	2nd Inside Library Bathroom	Visually Checked	12:46:59 PM	03/24/2020
Heat Detector	2nd Mens Faculty Bathroom	Visually Checked	12:32:59 PM	03/24/2020
Heat Detector	3rd Boys Bathroom By Lockers	Visually Checked	11:39:53 AM	03/24/2020
Heat Detector	3rd Girls Bathroom By Lockers	visually Checked	11:39:58 AM	03/24/2020
Heat Detector	3rd Mens By Passage Teacher Work rm	visually Checked	1:03:23 PM	03/24/2020
Heat Detector	3rd Mens By Passage Teacher Work rm	visually Checked	1:03:27 PM	03/24/2020
Heat Detector	3rd mens Rm	visually Checked	1:03:49 PM	03/24/2020
Heat Detector	3rd Room 309	Visually Checked	12:07:32 PM	03/24/2020
Heat Detector	3rd Room 309	Visually Checked	12:07:37 PM	03/24/2020
Heat Detector	3rd Room 315	Visually Checked	12:13:49 PM	03/24/2020
Heat Detector	3rd Room 315	Visually Checked	12:13:58 PM	03/24/2020
Heat Detector	3rd Womens Rm	Visually Checked	12:30:13 PM	03/24/2020
Heat Detector	3rd Boys Rm	Visually Checked	11:47:03 AM	03/24/2020
Heat Detector	3rd Girls Rm	Visually Checked	11:47:23 AM	03/24/2020
Heat Detector	3rd rm 312 Physics	visually Checked	1:03:31 PM	03/24/2020
Heat Detector	3rd rm 312 Physics	visually Checked	1:03:35 PM	03/24/2020
Heat Detector	3rd rm 313 Bio Earth	visually Checked	1:01:09 PM	03/24/2020
Heat Detector	3rd rm 313 Bio Earth	visually Checked	1:01:14 PM	03/24/2020
Heat Detector	3rd Room 314	Visually Checked	12:12:51 PM	03/24/2020
Heat Detector	3rd Room 314	Visually Checked	12:12:54 PM	03/24/2020
Heat Detector	Mezzanine Above Kitchen Mech Rm above AHU-7	visually Checked	1:04:56 PM	03/24/2020
Heat Detector	Mezzanine Above Kitchen Mech Room	visually Checked	1:05:16 PM	03/24/2020
Heat Detector	Mezzanine Above Kitchen Mech Room	visually Checked	1:05:20 PM	03/24/2020
Pull Station	1st Entrance Lobby By 115 Fitness	Visually Checked	1:14:47 PM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	1st North Outside Courtyard	Visually Checked	1:07:09 PM	03/24/2020
Pull Station	1st North Outside Courtyard	Visually Checked	1:07:14 PM	03/24/2020
Pull Station	1st North Outside Courtyard	Visually Checked	1:17:57 PM	03/24/2020
Pull Station	1st By Stair D	Visually Checked	1:05:38 PM	03/24/2020
Pull Station	1st Cafe By Exit	Visually Checked	1:15:23 PM	03/24/2020
Pull Station	1st Cafe By Exit	Visually Checked	1:17:36 PM	03/24/2020
Pull Station	1st Cafe entrance	Visually Checked	1:17:25 PM	03/24/2020
Pull Station	1st Cafe Recieving Dock Thru Kitchen Passage	Visually Checked	1:15:50 PM	03/24/2020
Pull Station	1st Class Room 111	Visually Checked	1:05:51 PM	03/24/2020
Pull Station	1st Corridor by Stair C	Visually Checked	1:13:53 PM	03/24/2020
Pull Station	1st Corridor to Stair A	Visually Checked	1:14:00 PM	03/24/2020
Pull Station	1st Corridor to Stair B	Visually Checked	1:13:56 PM	03/24/2020
Pull Station	1st Gym	Visually Checked	1:07:30 PM	03/24/2020
Pull Station	1st Gym	Visually Checked	1:07:41 PM	03/24/2020
Pull Station	1st Gym	Visually Checked	1:07:44 PM	03/24/2020
Pull Station	1st Gym	Visually Checked	1:08:02 PM	03/24/2020
Pull Station	1st Gym	Visually Checked	1:08:06 PM	03/24/2020
Pull Station	1st Kitchen exit	Visually Checked	1:17:40 PM	03/24/2020
Pull Station	1st Mech Room	Visually Checked	1:05:11 PM	03/24/2020
Pull Station	1st Mech Room	Visually Checked	1:05:57 PM	03/24/2020
Pull Station	1st Mechanical Room Under Floor Thru Metal Grate/Hatch in Floor	Visually Checked	1:16:44 PM	03/24/2020
Pull Station	1st Class 110	Visually Checked	1:06:07 PM	03/24/2020
Pull Station	1st Main Lobby	Visually Checked	1:06:18 PM	03/24/2020
Pull Station	1st Main Office Principal	Visually Checked	1:07:06 PM	03/24/2020
Pull Station	1st Switchgear By Stair A	Visually Checked	1:11:40 PM	03/24/2020
Pull Station	2nd West Corridor By Stair D	Visually Checked	1:04:29 PM	03/24/2020
Pull Station	2nd AAE Rm 210	Visually Checked	12:38:04 PM	03/24/2020
Pull Station	2nd AAE Rm 211	Visually Checked	12:39:57 PM	03/24/2020
Pull Station	2nd By Stair A	Visually Checked	11:56:34 AM	03/24/2020
Pull Station	2nd By Stair B	Visually Checked	11:55:26 AM	03/24/2020
Pull Station	2nd By Stair C	Visually Checked	11:53:01 AM	03/24/2020
Pull Station	2nd Library	Visually Checked	12:42:11 PM	03/24/2020
Pull Station	2nd Library	Visually Checked	12:43:44 PM	03/24/2020
Pull Station	3rd By Stair A	Visually Checked	1:03:52 PM	03/24/2020
Pull Station	3rd By Stair B	Visually Checked	1:04:00 PM	03/24/2020
Pull Station	3rd Cisco Rm 310	Visually Checked	12:18:46 PM	03/24/2020
Pull Station	3rd Cisco Rm 311	Visually Checked	12:18:50 PM	03/24/2020
Pull Station	3rd Library Entrance	Visually Checked	1:02:51 PM	03/24/2020
Pull Station	3rd Library Entrance	Visually Checked	1:02:54 PM	03/24/2020
Pull Station	3rd Stair C	Visually Checked	1:02:03 PM	03/24/2020
Pull Station	3rd Stair D	Visually Checked	1:02:07 PM	03/24/2020
Pull Station	3rd Room 309	Visually Checked	12:07:41 PM	03/24/2020
Pull Station	3rd rm 312 Physics	Visually Checked	1:03:38 PM	03/24/2020
Pull Station	3rd rm 313 Bio Earth	Visually Checked	1:03:42 PM	03/24/2020
Pull Station	3rd rm 314 Chem Lab	Visually Checked	12:25:14 PM	03/24/2020
Pull Station	3rd rm 315 Chem Lab	Visually Checked	12:14:22 PM	03/24/2020
Pull Station	Mezzanine Above Kitchen Mech Rm	Visually Checked	1:20:34 PM	03/24/2020
Smoke Detector	1st Atruim Corridor Lockers By Rm 110	Visually Checked	12:05:29 PM	03/24/2020
Smoke Detector	1st Atruim Corridor By Rm 110	Visually Checked	12:05:19 PM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Atruim Corridor By Rm 111	Visually Checked	12:05:07 PM	03/24/2020
Smoke Detector	1st Atruim Stair D	Visually Checked	12:04:12 PM	03/24/2020
Smoke Detector	1st Atruim Stair D	Visually Checked	12:04:36 PM	03/24/2020
Smoke Detector	1st Atruim By Electrical	Visually Checked	12:03:58 PM	03/24/2020
Smoke Detector	1st By Corridor to Gym Rm 118 Fitness	Visually Checked	1:16:35 PM	03/24/2020
Smoke Detector	1st By Corridor to Gym Rm 118 Fitness	Visually Checked	1:17:00 PM	03/24/2020
Smoke Detector	1st By Stair D	Visually Checked	12:04:45 PM	03/24/2020
Smoke Detector	1st Cafe	Visually Checked	1:28:17 PM	03/24/2020
Smoke Detector	1st Cafeteria	Visually Checked	1:09:27 PM	03/24/2020
Smoke Detector	1st Cafeteria	Visually Checked	1:26:54 PM	03/24/2020
Smoke Detector	1st Cafeteria	Visually Checked	1:27:04 PM	03/24/2020
Smoke Detector	1st Cafeteria	Visually Checked	1:27:34 PM	03/24/2020
Smoke Detector	1st Corridor Atruim By 107	Visually Checked	12:15:11 PM	03/24/2020
Smoke Detector	1st Corridor Atruim By 108	Visually Checked	12:15:01 PM	03/24/2020
Smoke Detector	1st Corridor Atruim By Stair C	Visually Checked	12:08:01 PM	03/24/2020
Smoke Detector	1st Corridor Atruim Entry	Visually Checked	12:14:49 PM	03/24/2020
Smoke Detector	1st Corridor Atruim Entry	Visually Checked	1:08:26 PM	03/24/2020
Smoke Detector	1st Corridor Atruim Entry	Visually Checked	1:09:11 PM	03/24/2020
Smoke Detector	1st Corridor By Main Office	Visually Checked	12:14:11 PM	03/24/2020
Smoke Detector	1st Corridor By Main Office	Visually Checked	12:14:32 PM	03/24/2020
Smoke Detector	1st Corridor By Main Office	Visually Checked	12:14:40 PM	03/24/2020
Smoke Detector	1st Corridor By Nurse Suite Office 114	Visually Checked	12:13:52 PM	03/24/2020
Smoke Detector	1st Corridor By Nurse Suite Office 114	Visually Checked	12:14:03 PM	03/24/2020
Smoke Detector	1st Corridor Lockers By Rm 110	Visually Checked	12:05:40 PM	03/24/2020
Smoke Detector	1st Corridor Lockers	Visually Checked	12:06:44 PM	03/24/2020
Smoke Detector	1st Corridor by 104 Music	Visually Checked	12:08:38 PM	03/24/2020
Smoke Detector	1st Corridor by 104 Music	Visually Checked	12:08:54 PM	03/24/2020
Smoke Detector	1st Corridor by 105 Music	Visually Checked	12:08:16 PM	03/24/2020
Smoke Detector	1st Corridor by 105 Music	Visually Checked	12:08:33 PM	03/24/2020
Smoke Detector	1st Corridor to Gym	Visually Checked	12:09:43 PM	03/24/2020
Smoke Detector	1st Corridor to Gym	Visually Checked	12:10:09 PM	03/24/2020
Smoke Detector	1st Corridor to Gym	Visually Checked	12:10:41 PM	03/24/2020
Smoke Detector	1st Corridor to Gym	Visually Checked	12:11:07 PM	03/24/2020
Smoke Detector	1st Corridor to Gym	Visually Checked	12:11:17 PM	03/24/2020
Smoke Detector	1st Corridor to Gym	Visually Checked	12:11:32 PM	03/24/2020
Smoke Detector	1st Corridor to Stair A	Visually Checked	12:10:01 PM	03/24/2020
Smoke Detector	1st Corridor to Stair B	Visually Checked	12:09:07 PM	03/24/2020
Smoke Detector	1st Corridor to Stair B	Visually Checked	12:09:21 PM	03/24/2020
Smoke Detector	1st Corridor to Stair B	Visually Checked	12:09:35 PM	03/24/2020
Smoke Detector	1st Custodial By Lockers	Visually Checked	12:05:55 PM	03/24/2020
Smoke Detector	1st Electrical By Maintance	Visually Checked	1:05:35 PM	03/24/2020
Smoke Detector	1st Gym Storage	Visually Checked	1:07:48 PM	03/24/2020
Smoke Detector	1st Gym Storage	Visually Checked	1:07:52 PM	03/24/2020
Smoke Detector	1st Kitchen Passage Door By Exit To Outside 12ft Ladder	Visually Checked	1:15:47 PM	03/24/2020
Smoke Detector	1st Kitchen Passage Above Duct Work Door By Exit To Outside (12ft Ladder)	Visually Checked	1:16:20 PM	03/24/2020
Smoke Detector	1st Maintenance	Visually Checked	1:08:10 PM	03/24/2020
Smoke Detector	1st Room 113 P.C. Workshop	Visually Checked	1:17:04 PM	03/24/2020
Smoke Detector	1st Room 113 P.C. Workshop	Visually Checked	1:17:19 PM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Storage By 115 Fitness	Visually Checked	1:09:32 PM	03/24/2020
Smoke Detector	1st Storage Inside Rm 115 Fitness	Visually Checked	1:09:23 PM	03/24/2020
Smoke Detector	1st Storeage Art Rm 101	Visually Checked	1:12:58 PM	03/24/2020
Smoke Detector	1st Storeage by Stair B	Visually Checked	1:13:50 PM	03/24/2020
Smoke Detector	1st Art Rm 101	Visually Checked	1:12:52 PM	03/24/2020
Smoke Detector	1st Boys Locker in Alcove	Visually Checked	1:10:26 PM	03/24/2020
Smoke Detector	1st Class 110 Storage	Visually Checked	1:06:10 PM	03/24/2020
Smoke Detector	1st Class 110	Visually Checked	1:06:13 PM	03/24/2020
Smoke Detector	1st Electrical By Stair A	Visually Checked	1:11:13 PM	03/24/2020
Smoke Detector	1st Girls Bathroom Locker Rm Alcove	Visually Checked	1:11:05 PM	03/24/2020
Smoke Detector	1st Nurse Suite Office 114	Visually Checked	1:07:27 PM	03/24/2020
Smoke Detector	1st Swichgear By Stair A	Visually Checked	12:59:58 PM	03/24/2020
Smoke Detector	1st Vestabule in Gym between Lockers	Visually Checked	1:10:46 PM	03/24/2020
Smoke Detector	2nd East Corridor By 204 Digital Art	Visually Checked	11:55:06 AM	03/24/2020
Smoke Detector	2nd East Corridor By 205 Art	Visually Checked	11:54:32 AM	03/24/2020
Smoke Detector	2nd East Corridor By 206 IT	Visually Checked	11:54:08 AM	03/24/2020
Smoke Detector	2nd East Corridor By 206 IT	Visually Checked	11:54:18 AM	03/24/2020
Smoke Detector	2nd North Corridor By Girls Restroom By Windows	Visually Checked	11:57:32 AM	03/24/2020
Smoke Detector	2nd North Corridor By Womans Faculty Area By Windows	Visually Checked	11:56:05 AM	03/24/2020
Smoke Detector	2nd North Corridor By Womans Faculty Area By Windows	Visually Checked	11:56:21 AM	03/24/2020
Smoke Detector	2nd Southeast Corridor By Locker	Visually Checked	11:52:10 AM	03/24/2020
Smoke Detector	2nd Southeast Custodian	Visually Checked	1:04:41 PM	03/24/2020
Smoke Detector	2nd Southeast Storage By Rm 210	Visually Checked	1:04:38 PM	03/24/2020
Smoke Detector	2nd West By Guidance Corridor By IT Closet	Visually Checked	11:58:32 AM	03/24/2020
Smoke Detector	2nd West By Guidance Corridor By IT Closet	Visually Checked	1:04:25 PM	03/24/2020
Smoke Detector	2nd West Corridor By Guidance Rm 216	Visually Checked	11:58:20 AM	03/24/2020
Smoke Detector	2nd West Corridor By Rm 217	Visually Checked	11:57:41 AM	03/24/2020
Smoke Detector	2nd West Corridor By Rm 217	Visually Checked	11:57:56 AM	03/24/2020
Smoke Detector	2nd West Corridor Atruim	Visually Checked	11:50:42 AM	03/24/2020
Smoke Detector	2nd West Corridor Atruim	Visually Checked	11:58:48 AM	03/24/2020
Smoke Detector	2nd West Corridor Atruim Balcony	Visually Checked	11:50:57 AM	03/24/2020
Smoke Detector	2nd West Corridor By Stair D	Visually Checked	11:51:08 AM	03/24/2020
Smoke Detector	2nd AAE Closet Rm 210	Visually Checked	12:39:12 PM	03/24/2020
Smoke Detector	2nd AAE Rm 210	Visually Checked	12:38:17 PM	03/24/2020
Smoke Detector	2nd AAE Rm 211	Visually Checked	12:39:44 PM	03/24/2020
Smoke Detector	2nd By Security Rm 214	Visually Checked	12:52:29 PM	03/24/2020
Smoke Detector	2nd Corridor Storage By Stair B	Visually Checked	1:04:45 PM	03/24/2020
Smoke Detector	2nd Corridor By Mens Faculty BathRm	Visually Checked	11:56:30 AM	03/24/2020
Smoke Detector	2nd Corridor By Rm 200	Visually Checked	11:55:41 AM	03/24/2020
Smoke Detector	2nd Corridor By Rm 218	Visually Checked	11:55:54 AM	03/24/2020
Smoke Detector	2nd Corridor By Stair B	Visually Checked	11:55:23 AM	03/24/2020
Smoke Detector	2nd Guidance By Office 4	Visually Checked	12:50:14 PM	03/24/2020
Smoke Detector	2nd Guidance Rm 216	Visually Checked	12:49:55 PM	03/24/2020
Smoke Detector	2nd Inside Library Closet By Bathroom	Visually Checked	12:47:35 PM	03/24/2020
Smoke Detector	2nd Inside Library Closet	Visually Checked	12:43:21 PM	03/24/2020
Smoke Detector	2nd Inside Library Electrical Closet	Visually Checked	12:45:53 PM	03/24/2020
Smoke Detector	2nd Inside Library Study Area	Visually Checked	12:40:50 PM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd Inside Library Study Area	Visually Checked	12:41:33 PM	03/24/2020
Smoke Detector	2nd Inside Library Video Storage Rm 213.	Visually Checked	1:04:34 PM	03/24/2020
Smoke Detector	2nd Inside Library Workroom	Visually Checked	12:44:23 PM	03/24/2020
Smoke Detector	2nd IT Closet By Guidance	Visually Checked	12:54:06 PM	03/24/2020
Smoke Detector	2nd Library	Visually Checked	12:42:45 PM	03/24/2020
Smoke Detector	2nd Sitting Area by Room 205	Visually Checked	11:54:51 AM	03/24/2020
Smoke Detector	2nd Atruim By 210	Visually Checked	11:51:38 AM	03/24/2020
Smoke Detector	2nd Atruim By 210	Visually Checked	11:52:03 AM	03/24/2020
Smoke Detector	2nd Atruim By 211	Visually Checked	11:51:25 AM	03/24/2020
Smoke Detector	2nd Atruim By Stair C	Visually Checked	11:51:53 AM	03/24/2020
Smoke Detector	2nd Atruim By Stair C	Visually Checked	11:52:57 AM	03/24/2020
Smoke Detector	2nd Atruim	Visually Checked	11:53:15 AM	03/24/2020
Smoke Detector	2nd Atruim	Visually Checked	11:53:25 AM	03/24/2020
Smoke Detector	2nd Atruim	Visually Checked	11:53:36 AM	03/24/2020
Smoke Detector	2nd Electrical	Visually Checked	12:55:45 PM	03/24/2020
Smoke Detector	2nd Rm 218	Visually Checked	12:55:08 PM	03/24/2020
Smoke Detector	3rd Book Storage	Visually Checked	12:24:04 PM	03/24/2020
Smoke Detector	3rd Corridor Atruim By Lockers	Visually Checked	11:38:54 AM	03/24/2020
Smoke Detector	3rd Corridor Atruim By Lockers	Visually Checked	11:40:35 AM	03/24/2020
Smoke Detector	3rd Corridor Atruim By Rm 309	Visually Checked	11:43:34 AM	03/24/2020
Smoke Detector	3rd Corridor Atruim By Rm 309	Visually Checked	11:43:44 AM	03/24/2020
Smoke Detector	3rd Corridor Atruim By Rm 309	Visually Checked	11:43:55 AM	03/24/2020
Smoke Detector	3rd Corridor By 300	Visually Checked	11:45:48 AM	03/24/2020
Smoke Detector	3rd Corridor By 302	Visually Checked	11:45:33 AM	03/24/2020
Smoke Detector	3rd Corridor By 318 Print	Visually Checked	11:46:00 AM	03/24/2020
Smoke Detector	3rd Corridor By Mens rm	Visually Checked	11:46:17 AM	03/24/2020
Smoke Detector	3rd Corridor By rm 314 Chem Lab	Visually Checked	11:48:27 AM	03/24/2020
Smoke Detector	3rd Corridor By Boys Rm	Visually Checked	11:46:59 AM	03/24/2020
Smoke Detector	3rd Corridor By Girls Rm	Visually Checked	11:47:13 AM	03/24/2020
Smoke Detector	3rd Corridor By rm 313 Bio Earth	Visually Checked	11:48:55 AM	03/24/2020
Smoke Detector	3rd Corridor By rm 313 Bio Earth	Visually Checked	11:49:04 AM	03/24/2020
Smoke Detector	3rd Corridor By rm 315 Chem Lab	Visually Checked	11:47:46 AM	03/24/2020
Smoke Detector	3rd Corridor By rm 315 Chem Lab	Visually Checked	11:47:53 AM	03/24/2020
Smoke Detector	3rd Corridor By rm 315 Chem Lab	Visually Checked	11:48:08 AM	03/24/2020
Smoke Detector	3rd Corridor by Room 314 Chem Lab	Visually Checked	11:48:18 AM	03/24/2020
Smoke Detector	3rd Corridor Passage Teacher Work rm	Visually Checked	1:03:07 PM	03/24/2020
Smoke Detector	3rd Corridor By Room 304	Visually Checked	11:45:14 AM	03/24/2020
Smoke Detector	3rd Corridor By Room 305	Visually Checked	11:44:51 AM	03/24/2020
Smoke Detector	3rd Corridor By Room 305A	Visually Checked	11:45:02 AM	03/24/2020
Smoke Detector	3rd Corridor By Room 306	Visually Checked	11:44:40 AM	03/24/2020
Smoke Detector	3rd Corridor By Room 306A	Visually Checked	11:44:18 AM	03/24/2020
Smoke Detector	3rd Electrical By Stair A	Visually Checked	1:03:57 PM	03/24/2020
Smoke Detector	3rd Electrical By Library	Visually Checked	1:03:00 PM	03/24/2020
Smoke Detector	3rd Electrical By Lockers	Visually Checked	12:20:18 PM	03/24/2020
Smoke Detector	3rd Experiment storage rm by 312 Library	Visually Checked	12:05:53 PM	03/24/2020
Smoke Detector	3rd IT Closet Across rm 314 Chem Lab	Visually Checked	1:03:46 PM	03/24/2020
Smoke Detector	3rd Janitor By Lockers	Visually Checked	11:39:11 AM	03/24/2020
Smoke Detector	3rd Office Prep By rm 315 Chem Lab	Visually Checked	12:15:20 PM	03/24/2020
Smoke Detector	3rd Room 309 Prep Room	Visually Checked	12:09:19 PM	03/24/2020
Smoke Detector	3rd Storage By 303	Visually Checked	1:04:04 PM	03/24/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	3rd Storage By rm 314 Chem Lab	Visually Checked	12:16:10 PM	03/24/2020
Smoke Detector	3rd Storage By rm 313 Bio Earth	Visually Checked	12:05:17 PM	03/24/2020
Smoke Detector	3rd Teachers Lounge Library	Visually Checked	12:22:14 PM	03/24/2020
Smoke Detector	3rd 318 Print	Visually Checked	12:26:56 PM	03/24/2020
Smoke Detector	3rd Atruim By Electrical Rm	Visually Checked	11:42:40 AM	03/24/2020
Smoke Detector	3rd Atruim By Office Storage	Visually Checked	11:49:10 AM	03/24/2020
Smoke Detector	3rd Atruim By Office Storage	Visually Checked	11:49:54 AM	03/24/2020
Smoke Detector	3rd Atruim By Rm 310	Visually Checked	11:41:21 AM	03/24/2020
Smoke Detector	3rd Atruim By Rm 311	Visually Checked	11:41:38 AM	03/24/2020
Smoke Detector	3rd Atruim By Stair C	Visually Checked	11:40:55 AM	03/24/2020
Smoke Detector	3rd Atruim By Stair C	Visually Checked	11:43:20 AM	03/24/2020
Smoke Detector	3rd Atruim By Stair D	Visually Checked	11:41:51 AM	03/24/2020
Smoke Detector	3rd Atruim By Teachers Workroom	Visually Checked	11:42:02 AM	03/24/2020

Service Summary

Generated by: BuildingReports.com




Building: Stamford BOE-Academy of Info Tech & Engineering

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Passed</i>		
Annunciator	Visually Checked	2
Battery	Tested	13
Control Panel	Tested	1
Duct Detector	Visually Checked	19
Heat Detector	Visually Checked	44
Heat Detector	visually Checked	31
Power Supply	Tested	11
Pull Station	Visually Checked	48
Smoke Detector	Visually Checked	160
Total		329
Grand Total		329

Sound and Visual Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Academy of Info Tech & Engineering							
<i>The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.</i>							
 Location	 Comment	Ambient	Alarm	 Intelligibility		Sound Test	
		◀ dB	◀ dB	Voice	STI		
<i>Untested</i>							
Sound Test Points							
Whole Building				<input type="checkbox"/>		0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Stamford BOE-Academy of Info Tech & Engineering				Control Panel: 1 - EST EST-3			
The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
Passed							
Battery							
Sealed Lead Acid	1st Electrical Closet By Stair A (Center Booster)	7.8	12.53	12.79V	7.4Ah		
Sealed Lead Acid	1st Electrical Closet By Stair A (Left Booster)	7.8	12.60	12.66V	7.6Ah		
Sealed Lead Acid	1st Electrical Closet By Stair A (Right Booster)	7.8	12.54	12.38V	7.6Ah		
Sealed Lead Acid	1st Electrical Closet By Elevator (Bottom Booster)	7.8	12.71	12.40V	7.8Ah		
Sealed Lead Acid	1st Electrical Closet By Elevator (Top Booster)	7.8	12.75	12.62V	7.8ah		
Sealed Lead Acid	1st Maintance Office Left	50	12		85%		
Sealed Lead Acid	1st Maintance Office Right	50	12		85%		
Sealed Lead Acid	2nd Inside Library Electrical Closet (Left Booster)	7.8	12.60	12.75V	7.6Ah		
Sealed Lead Acid	2nd Inside Library Electrical Closet (Right Booster)	7.2	12.60	12.56V	7.8Ah		
Sealed Lead Acid	2nd Electrical Closet By Stair A	7.8	12.51	12.78V	7.4Ah		
Sealed Lead Acid	3rd Electrical Closet By Elevator (Right Booster)	7.9	12.46	12.69V	7.8Ah		
Sealed Lead Acid	3rd Electrical Closet By Elevator Left Booster	7.6	12.56	12.81V	6.4Ah		
Sealed Lead Acid	3rd Electrical Closet By Stair A	7.8	12.68	12.60V	7.8Ah		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Stamford BOE-Academy of Info
Tech & Engineering

Control Panel: 1 - EST EST-3

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type	Category	% of Inventory	Quantity
Sound Test	Sound Test	0.30%	1
Battery	Control	3.94%	13
Power Supply	Control	3.33%	11
Smoke Detector	Initiating	48.48%	160
Heat Detector	Initiating	22.73%	75
Duct Detector	Initiating	5.76%	19
Pull Station	Initiating	14.55%	48
Control Panel	Control	0.30%	1
Annunciator	Control	0.61%	2

Type	Qty	Model #	Description	Install Date
<i>In Service - 2 Years to 3 Years</i>				
Universal				
Battery	5	UB1280	Sealed Lead Acid	11/15/2017
<i>In Service - 3 Years to 5 Years</i>				
Universal				
Battery	2	UB12500	Sealed Lead Acid	02/10/2017
Battery	5	UB1280	Sealed Lead Acid	02/10/2017
Battery	1	UB1280	Sealed Lead Acid	02/01/2017
<i>In Service - 5 Years to 10 Years</i>				
EST				
Annunciator	2	3-ANN	LCD Display	07/19/2012
Control Panel	1	EST-3		07/19/2012
Duct Detector	19	SIGA-SD	Photoelectric	07/19/2012
Heat Detector	20	SIGA-HFS	Fixed Temperature	07/19/2012
Heat Detector	55	SIGA-HRS	Rate-of-Rise	07/19/2012
Power Supply	11	BPS10		07/19/2012
Pull Station	1	SIGA-270	Single Action	07/19/2012
Pull Station	44	SIGA-278	Dual Action	07/19/2012
Smoke Detector	16	SIGA-PS	Photoelectric	07/19/2012
	0			
<i>In Service - 10 Years to 15 Years</i>				
EST				
Pull Station	3	SIGA-278	Dual Action	10/21/2009

Zone Address Report

Generated by: BuildingReports.com

Building: Stamford BOE-Academy of Info
Tech & Engineering

Control Panel: 1 - EST EST-3

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: 01				
0615	Battery	1st Maintance Office Left	Sealed Lead Acid	20666309
Zone/Circuit: 06				
0001	Smoke Detector	1st Gym Storage	Photoelectric	17012628
0002	Smoke Detector	1st Gym Storage	Photoelectric	17012629
0003	Smoke Detector	1st By Corridor to Gym Rm 118 Fitness	Photoelectric	20666228
0004	Smoke Detector	1st By Corridor to Gym Rm 118 Fitness	Photoelectric	20666227
0005	Smoke Detector	1st Vestabule in Gym between Lockers	Photoelectric	17014559
0007	Smoke Detector	1st Swichgear By Stair A	Photoelectric	17014571
0008	Smoke Detector	1st Electrical By Stair A	Photoelectric	17014569
0009	Heat Detector	1st Womans Faculty Bathroom	Rate-of-Rise	17014573
0011	Heat Detector	1st Mens Faculty Bathroom	Rate-of-Rise	17014572
0012	Smoke Detector	1st Corridor to Gym	Photoelectric	17014590
0013	Smoke Detector	1st Corridor to Stair A	Photoelectric	17014589
0014	Smoke Detector	1st Corridor to Gym	Photoelectric	17014588
0015	Heat Detector	1st Boys Locker	Rate-of-Rise	21097623
0016	Heat Detector	1st Boys Locker	Fixed Temperature	17014556
0017	Heat Detector	1st Boys Locker	Fixed Temperature	17014557
0018	Smoke Detector	1st Boys Locker in Alcove	Photoelectric	17014558
0019	Heat Detector	1st Boys Locker	Fixed Temperature	20666223
0020	Heat Detector	1st Girls Bathroom Locker Rm	Fixed Temperature	20666224
0021	Smoke Detector	1st Girls Bathroom Locker Rm Alcove	Photoelectric	17014560
0022	Heat Detector	1st Girls Bathroom Locker Rm	Fixed Temperature	17014561
0023	Heat Detector	1st Girls Bathroom Locker Rm	Fixed Temperature	17014554
0024	Heat Detector	1st Girls Bathroom	Rate-of-Rise	17014562
0025	Smoke Detector	1st Corridor to Gym	Photoelectric	17014591
0026	Smoke Detector	1st Corridor to Gym	Photoelectric	17014595
0027	Smoke Detector	1st Corridor to Gym	Photoelectric	17014594
0028	Smoke Detector	1st Corridor to Gym	Photoelectric	17014593
0029	Smoke Detector	1st Storage By 115 Fitness	Photoelectric	17014552
0030	Smoke Detector	1st Storage Inside Rm 115 Fitness	Photoelectric	17014551
0031	Smoke Detector	1st Corridor By Nurse Suite Office 114	Photoelectric	17014596
0032	Smoke Detector	1st Corridor By Nurse Suite Office 114	Photoelectric	17014597
0033	Smoke Detector	1st Nurse Suite Office 114	Photoelectric	17012623
0034	Heat Detector	1st Nurse Suite (Office 114) Bathroom	Rate-of-Rise	17012622
0035	Smoke Detector	1st Corridor By Main Office	Photoelectric	17014598
0037	Smoke Detector	1st Corridor By Main Office	Photoelectric	17014599
0038	Smoke Detector	1st Room 113 P.C. Workshop	Photoelectric	20666244
0039	Smoke Detector	1st Room 113 P.C. Workshop	Photoelectric	20666245
0044	Smoke Detector	1st Corridor By Main Office	Photoelectric	17014600

0045	Duct Detector	1st Gym HV-1 Return	Photoelectric	20666225
0046	Duct Detector	1st Gym HV-1 Supply	Photoelectric	20666226
0126	Pull Station	1st Gym	Dual Action	17012626
0127	Pull Station	1st Gym	Dual Action	17012624
0128	Pull Station	1st Gym	Dual Action	17012625
0129	Pull Station	1st Gym	Dual Action	17012631
0130	Pull Station	1st Gym	Dual Action	17012630
0136	Heat Detector	1st Main Office Principal	Rate-of-Rise	17012617
0141	Pull Station	1st Switchgear By Stair A	Dual Action	17014570
0150	Pull Station	1st Corridor to Stair A	Dual Action	17014587
0151	Pull Station	1st North Outside Courtyard	Dual Action	17012620
0153	Pull Station	1st Entrance Lobby By 115 Fitness	Dual Action	17014592
0155	Pull Station	1st North Outside Courtyard	Dual Action	48218848
0166	Pull Station	1st Main Office Principal	Dual Action	17012618
0166	Power Supply	1st Electrical Closet By Stair A (Left Booster)		17014568
0168	Power Supply	1st Electrical Closet By Stair A (Center Booster)		17014567
0170	Power Supply	1st Electrical Closet By Stair A (Right Booster)		17014566
	Annunciator	1st Lobby Main Office	LCD Display	17012615
	Annunciator	1st Main Lobby By Main Office	LCD Display	17012616
Zone/Circuit: 08				
0615	Battery	1st Maintenance Office Right	Sealed Lead Acid	20666308
Zone/Circuit: 16				
0001	Smoke Detector	1st Storage Art Rm 101	Photoelectric	17014575
0002	Smoke Detector	1st Art Rm 101	Photoelectric	17014574
0003	Smoke Detector	1st Corridor to Stair B	Photoelectric	17014585
0004	Smoke Detector	1st Corridor to Stair B	Photoelectric	17014584
0005	Smoke Detector	1st Storage by Stair B	Photoelectric	17014577
0006	Smoke Detector	1st Corridor by 104 Music	Photoelectric	17014582
0007	Smoke Detector	1st Corridor by 104 Music	Photoelectric	17014581
0008	Smoke Detector	1st Corridor by 105 Music	Photoelectric	17014580
0009	Smoke Detector	1st Corridor by 105 Music	Photoelectric	17014579
0010	Smoke Detector	1st Corridor Atrium By Stair C	Photoelectric	17014537
0011	Smoke Detector	1st Custodial By Lockers	Photoelectric	17012605
0012	Heat Detector	1st Boys Rm	Rate-of-Rise	17012603
0013	Heat Detector	1st Girls Rm	Rate-of-Rise	17012610
0014	Smoke Detector	1st Corridor Lockers	Photoelectric	17014538
0015	Heat Detector	1st Mens Faculty	Rate-of-Rise	17012602
0016	Heat Detector	1st Ladies Faculty	Rate-of-Rise	17012601
0017	Smoke Detector	1st Corridor Lockers By Rm 110	Photoelectric	17014539
0018	Heat Detector	1st Class 110	Rate-of-Rise	17012604
0019	Smoke Detector	1st Class 110 Storage	Photoelectric	17012612
0020	Heat Detector	1st Class 110	Rate-of-Rise	17012609
0021	Heat Detector	1st Class 111	Rate-of-Rise	17012608
0022	Heat Detector	1st Class 111	Rate-of-Rise	17012607
0023	Smoke Detector	1st Atrium Corridor Lockers By Rm 110	Photoelectric	17014540
0024	Smoke Detector	1st Atrium Corridor By Rm 110	Photoelectric	17014541
0025	Smoke Detector	1st Atrium Corridor By Rm 111	Photoelectric	17014542
0026	Smoke Detector	1st By Stair D	Photoelectric	17014549
0027	Smoke Detector	1st Cafeteria	Photoelectric	17014545

0028	Smoke Detector	1st Cafeteria	Photoelectric	17014548
0029	Smoke Detector	1st Kitchen Passage Door By Exit To Outside 12ft Ladder	Photoelectric	20666216
0030	Smoke Detector	1st Kitchen Passage Above Duct Work Door By Exit To Outside (12ft Ladder)	Photoelectric	20666219
0031	Heat Detector	1st Cafe Recieving Dock Thru Kitchen Passage	Rate-of-Rise	20666218
0032	Heat Detector	1st Kitchen Storage	Rate-of-Rise	20666207
0033	Heat Detector	1st Cafe Kitchen restroom	Rate-of-Rise	20666206
0034	Heat Detector	1st Cafe Kitchen By restroom	Fixed Temperature	20666205
0035	Heat Detector	1st Cafe Kitchen By Exit	Fixed Temperature	20666204
0036	Heat Detector	1st Cafe Kitchen Office	Rate-of-Rise	20666208
0037	Heat Detector	1st Cafe Kitchen	Fixed Temperature	17012585
0038	Heat Detector	1st Cafe Kitchen	Fixed Temperature	17012584
0039	Heat Detector	1st Cafe Kitchen	Fixed Temperature	17012583
0040	Heat Detector	1st Cafe Kitchen	Fixed Temperature	20666201
0041	Heat Detector	1st Cafe Kitchen	Fixed Temperature	20666200
0042	Heat Detector	1st Cafe Kitchen	Fixed Temperature	20666203
0043	Heat Detector	1st Cafe Kitchen	Fixed Temperature	20666202
0044	Heat Detector	1st Cafe Food Kiosk	Fixed Temperature	17012581
0045	Smoke Detector	1st Cafe	Photoelectric	17012582
0046	Heat Detector	1st Cafe Food Kiosk	Fixed Temperature	17012580
0046	Control Panel	1st Maintenance Office		23585594
0047	Smoke Detector	1st Cafeteria	Photoelectric	17014547
0048	Heat Detector	1st Cafe Boys Rm	Rate-of-Rise	17012594
0049	Heat Detector	1st Cafe Girls Rm	Rate-of-Rise	17012590
0050	Smoke Detector	1st Cafeteria	Photoelectric	17014546
0051	Smoke Detector	1st Atruim Stair D	Photoelectric	17014544
0052	Smoke Detector	1st Atruim Stair D	Photoelectric	17014543
0053	Smoke Detector	1st Atruim By Electrical	Photoelectric	17014550
0054	Smoke Detector	1st Electrical By Maintance	Photoelectric	17012599
0055	Heat Detector	1st Art Rm 101	Rate-of-Rise	17014576
0056	Smoke Detector	1st Corridor to Stair B	Photoelectric	17014586
0057	Heat Detector	1st Mech Room	Rate-of-Rise	17012586
0058	Heat Detector	1st Mech Room	Rate-of-Rise	17012587
0059	Heat Detector	1st Mech Room	Rate-of-Rise	17012588
0060	Heat Detector	1st Mech Room	Rate-of-Rise	17012589
0061	Heat Detector	1st Mech Room	Rate-of-Rise	17012591
0062	Heat Detector	1st Mech Room	Rate-of-Rise	17012592
0063	Heat Detector	1st Mech Room	Rate-of-Rise	17012593
0064	Heat Detector	1st Mech Room	Rate-of-Rise	17012595
0065	Heat Detector	1st Mech Room	Rate-of-Rise	17012597
0067	Smoke Detector	1st Corridor Atruim Entry	Photoelectric	17014532
0068	Smoke Detector	1st Corridor Atruim Entry	Photoelectric	17014533
0069	Smoke Detector	1st Class 110	Photoelectric	17012613
0070	Smoke Detector	1st Corridor Atruim Entry	Photoelectric	17014534
0071	Smoke Detector	1st Corridor Atruim By 108	Photoelectric	17014535
0072	Smoke Detector	1st Corridor Atruim By 107	Photoelectric	17014536
0073	Smoke Detector	1st Maintenance	Photoelectric	17014447
0073	Smoke Detector	3rd Room 309 Prep Room	Photoelectric	21097622
0126	Pull Station	1st Corridor to Stair B	Dual Action	17014583
0129	Pull Station	1st North Outside Courtyard	Dual Action	17012619
0134	Pull Station	1st Corridor by Stair C	Dual Action	17014578

0135	Pull Station	1st Class 110	Dual Action	17012611
0143	Pull Station	1st Class Room 111	Dual Action	17012606
0144	Pull Station	1st By Stair D	Dual Action	17012600
0149	Pull Station	1st Cafe entrance	Dual Action	20666250
0153	Pull Station	1st Cafe By Exit	Dual Action	20666215
0155	Pull Station	1st Cafe Recieving Dock Thru Kitchen Passage	Dual Action	20666217
0160	Pull Station	1st Kitchen exit	Dual Action	20666252
0170	Pull Station	1st Mech Room	Dual Action	17012598
0188	Pull Station	1st Mechanical Room Under Floor Thru Metal Grate/Hatch in Floor	Single Action	20666229
0190	Pull Station	1st Mech Room	Dual Action	17012596
0205	Pull Station	1st Main Lobby	Dual Action	17012614
0251	Duct Detector	3rd Office/Storage Room By Room 313 AHU-9 Supply	Photoelectric	20666234
0252	Duct Detector	3rd Office/Storage Room By Room 313 AHU-9 Return	Photoelectric	20666233
0253	Duct Detector	3rd Office/Prep Room By Room 315 AHU-2 Supply	Photoelectric	20666236
0254	Duct Detector	3rd Chemical Storage By Room 314 AHU-2 Return	Photoelectric	20666235
0255	Duct Detector	3rd Print Room 318 AHU-8 Supply	Photoelectric	20666238
0256	Duct Detector	3rd Print Room 318 AHU-8 Return	Photoelectric	20666237
0257	Duct Detector	3rd Corridor By Class Room 300 AHU-3 Supply	Photoelectric	20666240
0258	Duct Detector	3rd Corridor By Class Room 300 AHU-3 Return	Photoelectric	20666239
0259	Duct Detector	3rd By Room 306A AHU-4 Supply	Photoelectric	17013843
0260	Duct Detector	3rd Room 305A AHU-4 Return	Photoelectric	20666232
0261	Duct Detector	3rd Alcove By Cisco Lab 310 AHU-6 Supply	Photoelectric	20666242
0262	Duct Detector	3rd Alcove By Cisco Lab 310 AHU-6 Return	Photoelectric	20666243
0263	Duct Detector	3rd Corridor By Top Of Atrium Stairs AHU-5 Supply	Photoelectric	20666241
0265	Duct Detector	3rd Teachers Work Room AHU-1 Supply	Photoelectric	23028754
0266	Duct Detector	3rd Teachers Work Room AHU-1 Return	Photoelectric	23028755
Zone/Circuit: 17				
0001	Smoke Detector	2nd Electrical	Photoelectric	17014498
0002	Smoke Detector	2nd Rm 218	Photoelectric	17014493
0003	Smoke Detector	2nd North Corridor By Womans Faculty Area By Windows	Photoelectric	17014502
0004	Smoke Detector	2nd North Corridor By Womans Faculty Area By Windows	Photoelectric	17014501
0005	Smoke Detector	2nd Corridor By Rm 218	Photoelectric	17014492
0006	Smoke Detector	2nd Corridor By Rm 200	Photoelectric	17014491
0007	Smoke Detector	2nd Corridor By Stair B	Photoelectric	17014489
0008	Smoke Detector	2nd East Corridor By 204 Digital Art	Photoelectric	17014487
0009	Smoke Detector	2nd Sitting Area by Room 205	Photoelectric	20666230
0010	Smoke Detector	2nd East Corridor By 205 Art	Photoelectric	17014486
0011	Smoke Detector	2nd East Corridor By 206 IT	Photoelectric	17014485
0012	Smoke Detector	2nd East Corridor By 206 IT	Photoelectric	17014484
0013	Smoke Detector	2nd Atrium By Stair C	Photoelectric	17014513

0014	Smoke Detector	2nd Southeast Custodian	Photoelectric	17014480
0015	Heat Detector	2nd Inside Boys Bathroom	Rate-of-Rise	17014481
0016	Heat Detector	2nd Inside Girls Bathroom	Rate-of-Rise	17014482
0017	Smoke Detector	2nd Southeast Corridor By Locker	Photoelectric	17014479
0018	Smoke Detector	2nd Atruim By 210	Photoelectric	17014515
0019	Smoke Detector	2nd Southeast Storage By Rm 210	Photoelectric	17014478
0020	Smoke Detector	2nd Atruim By Stair C	Photoelectric	17014514
0021	Smoke Detector	2nd AAE Closet Rm 210	Photoelectric	17014476
0022	Smoke Detector	2nd Atruim By 210	Photoelectric	17014516
0023	Smoke Detector	2nd Atruim By 211	Photoelectric	17014517
0024	Smoke Detector	2nd West Corridor Atruim Balcony	Photoelectric	17014455
0025	Smoke Detector	2nd West Corridor By Stair D	Photoelectric	17014456
0026	Smoke Detector	2nd Library	Photoelectric	17014458
0027	Smoke Detector	2nd Inside Library Study Area	Photoelectric	17014460
0028	Smoke Detector	2nd Inside Library Study Area	Photoelectric	17014461
0032	Heat Detector	Mezzanine Above Kitchen Mech Room	Fixed Temperature	20666214
0033	Heat Detector	Mezzanine Above Kitchen Mech Rm above AHU-7	Fixed Temperature	20666209
0034	Duct Detector	Mezzanine Above Kitchen Mech Rm above AHU-7 Supply	Photoelectric	20666211
0035	Duct Detector	Mezzanine Above Kitchen Mech Rm AHU-7 Return	Photoelectric	20666212
0036	Heat Detector	Mezzanine Above Kitchen Mech Room	Fixed Temperature	20666213
0038	Smoke Detector	2nd Inside Library Closet By Bathroom	Photoelectric	17014469
0039	Heat Detector	2nd Inside Library Bathroom	Rate-of-Rise	17014468
0040	Smoke Detector	2nd Inside Library Workroom	Photoelectric	17014471
0041	Smoke Detector	2nd Inside Library Electrical Closet	Photoelectric	17014463
0042	Smoke Detector	2nd Inside Library Closet	Photoelectric	17014462
0043	Smoke Detector	2nd West Corridor Atruim	Photoelectric	17014454
0045	Smoke Detector	2nd Inside Library Video Storage Rm 213.	Photoelectric	17014477
0046	Smoke Detector	2nd By Security Rm 214	Photoelectric	17014449
0049	Smoke Detector	2nd West Corridor Atruim	Photoelectric	17014453
0050	Smoke Detector	2nd Atruim	Photoelectric	17014510
0051	Smoke Detector	2nd Atruim	Photoelectric	17014511
0052	Smoke Detector	2nd Atruim	Photoelectric	17014512
0053	Smoke Detector	2nd Guidance By Office 4	Photoelectric	17014450
0054	Smoke Detector	2nd West By Guidance Corridor By IT Closet	Photoelectric	17014451
0055	Smoke Detector	2nd Guidance Rm 216	Photoelectric	17014448
0056	Smoke Detector	2nd IT Closet By Guidance	Photoelectric	17014509
0057	Smoke Detector	2nd West Corridor By Guidance Rm 216	Photoelectric	17014508
0058	Smoke Detector	2nd West Corridor By Rm 217	Photoelectric	17014507
0059	Smoke Detector	2nd West Corridor By Rm 217	Photoelectric	17014506
0060	Heat Detector	2nd North Girls Restroom	Rate-of-Rise	17014504
0061	Heat Detector	2nd North Boys Restroom	Rate-of-Rise	17014505
0062	Smoke Detector	2nd North Corridor By Girls Restroom By Windows	Photoelectric	17014503
0063	Heat Detector	2nd Girls Faculty Bathroom	Rate-of-Rise	17014494
0064	Heat Detector	2nd Mens Faculty Bathroom	Rate-of-Rise	17014495
0065	Smoke Detector	2nd Corridor By Mens Faculty BathRm	Photoelectric	17014496
0068	Smoke Detector	2nd AAE Rm 210	Photoelectric	17014475
0069	Smoke Detector	2nd AAE Rm 211	Photoelectric	17014473

0070	Smoke Detector	2nd Corridor Storage By Stair B	Photoelectric	17014490
0071	Smoke Detector	2nd West By Guidance Corridor By IT Closet	Photoelectric	17014452
0126	Pull Station	1st Cafe By Exit	Dual Action	20666251
0132	Pull Station	2nd By Stair B	Dual Action	17014488
0136	Pull Station	2nd By Stair C	Dual Action	17014483
0137	Pull Station	2nd AAE Rm 210	Dual Action	17014474
0138	Pull Station	2nd AAE Rm 211	Dual Action	17014472
0142	Pull Station	2nd West Corridor By Stair D	Dual Action	17014457
0144	Pull Station	2nd Library	Dual Action	17014459
0145	Pull Station	Mezzanine Above Kitchen Mech Rm	Dual Action	20666210
0147	Pull Station	2nd Library	Dual Action	17014470
0156	Pull Station	2nd By Stair A	Dual Action	17014497
0158	Battery	2nd Electrical Closet By Stair A	Sealed Lead Acid	17014500
0158	Power Supply	2nd Electrical Closet By Stair A		17014499
0162	Battery	2nd Inside Library Electrical Closet (Left Booster)	Sealed Lead Acid	17014466
0162	Power Supply	2nd Inside Library Electrical Closet (Left Booster)		17014464
0164	Battery	2nd Inside Library Electrical Closet (Right Booster)	Sealed Lead Acid	17014467
0164	Power Supply	2nd Inside Library Electrical Closet (Right Booster)		17014465
0166	Battery	1st Electrical Closet By Stair A (Left Booster)	Sealed Lead Acid	17014565
0168	Battery	1st Electrical Closet By Stair A (Center Booster)	Sealed Lead Acid	17014564
0170	Battery	1st Electrical Closet By Stair A (Right Booster)	Sealed Lead Acid	17014563
0172	Battery	1st Electrical Closet By Elevator (Top Booster)	Sealed Lead Acid	23028759
0172	Power Supply	1st Electrical Closet By Elevator (Top Booster)		23028757
0175	Battery	1st Electrical Closet By Elevator (Bottom Booster)	Sealed Lead Acid	23028758
0175	Power Supply	1st Electrical Closet By Elevator (Bottom Booster)		23028756
0177	Power Supply	3rd Electrical Closet By Elevator		20666265
0177	Battery	3rd Electrical Closet By Elevator Left Booster	Sealed Lead Acid	20666266
0179	Power Supply	3rd Electrical Closet By Elevator		20666264
0179	Battery	3rd Electrical Closet By Elevator (Right Booster)	Sealed Lead Acid	20666267
0181	Battery	3rd Electrical Closet By Stair A	Sealed Lead Acid	20666301
0181	Power Supply	3rd Electrical Closet By Stair A		20666300
0251	Smoke Detector	3rd Electrical By Stair A	Photoelectric	20666299
0252	Smoke Detector	3rd Corridor By Mens rm	Photoelectric	20666297
0253	Smoke Detector	3rd Corridor By 318 Print	Photoelectric	20666302
0254	Smoke Detector	3rd 318 Print	Photoelectric	20666303
0255	Smoke Detector	3rd Corridor By 300	Photoelectric	20666304
0256	Smoke Detector	3rd Corridor By 302	Photoelectric	20666305
0257	Smoke Detector	3rd Storage By 303	Photoelectric	20666307
0258	Smoke Detector	3rd Corridor By Room 304	Photoelectric	17013832

0259	Smoke Detector	3rd Book Storage	Photoelectric	17013833
0260	Smoke Detector	3rd Corridor By Room 305A	Photoelectric	17013831
0261	Smoke Detector	3rd Corridor By Room 305	Photoelectric	17013830
0262	Smoke Detector	3rd Corridor By Room 306	Photoelectric	17013829
0263	Smoke Detector	3rd Corridor By Room 306A	Photoelectric	17013828
0264	Smoke Detector	3rd Atruim By Stair C	Photoelectric	17014518
0265	Smoke Detector	3rd Janitor By Lockers	Photoelectric	20666254
0266	Heat Detector	3rd Boys Bathroom By Lockers	Rate-of-Rise	20666255
0267	Heat Detector	3rd Girls Bathroom By Lockers	Rate-of-Rise	20666256
0268	Smoke Detector	3rd Corridor Atruim By Lockers	Photoelectric	17014530
0269	Smoke Detector	3rd Corridor Atruim By Lockers	Photoelectric	17014531
0271	Smoke Detector	3rd Electrical By Lockers	Photoelectric	20666257
0272	Smoke Detector	3rd Atruim By Stair C	Photoelectric	17014519
0273	Smoke Detector	3rd Atruim By Rm 310	Photoelectric	17014520
0274	Smoke Detector	3rd Atruim By Rm 311	Photoelectric	17014521
0275	Smoke Detector	3rd Atruim By Stair D	Photoelectric	17014523
0276	Smoke Detector	3rd Atruim By Teachers Workroom	Photoelectric	17014522
0277	Heat Detector	3rd Mens By Passage Teacher Work rm	Rate-of-Rise	20666270
0278	Heat Detector	3rd Mens By Passage Teacher Work rm	Rate-of-Rise	20666269
0279	Smoke Detector	3rd Corridor Passage Teacher Work rm	Photoelectric	20666268
0280	Smoke Detector	3rd Teachers Lounge Library	Photoelectric	20666271
0281	Smoke Detector	3rd Electrical By Library	Photoelectric	20666263
0282	Smoke Detector	3rd Atruim By Electrical Rm	Photoelectric	17014524
0284	Heat Detector	3rd rm 312 Physics	Rate-of-Rise	20666272
0285	Heat Detector	3rd rm 312 Physics	Rate-of-Rise	20666273
0286	Smoke Detector	3rd Experiment storage rm by 312 Library	Photoelectric	20666275
0287	Smoke Detector	3rd Atruim By Office Storage	Photoelectric	17014525
0288	Smoke Detector	3rd Corridor Atruim By Rm 309	Photoelectric	17014527
0289	Smoke Detector	3rd Corridor Atruim By Rm 309	Photoelectric	17014528
0290	Smoke Detector	3rd Corridor Atruim By Rm 309	Photoelectric	17014529
0291	Smoke Detector	3rd Corridor By rm 313 Bio Earth	Photoelectric	20666278
0292	Smoke Detector	3rd Corridor By rm 313 Bio Earth	Photoelectric	20666279
0294	Heat Detector	3rd Room 309	Rate-of-Rise	17013840
0295	Heat Detector	3rd Room 309	Rate-of-Rise	17013841
0296	Smoke Detector	3rd Corridor By rm 314 Chem Lab	Photoelectric	20666282
0297	Smoke Detector	3rd IT Closet Across rm 314 Chem Lab	Photoelectric	20666281
0298	Smoke Detector	3rd Storage By rm 313 Bio Earth	Photoelectric	20666277
0299	Heat Detector	3rd rm 313 Bio Earth	Rate-of-Rise	17013838
0300	Heat Detector	3rd rm 313 Bio Earth	Rate-of-Rise	17013839
0301	Smoke Detector	3rd Corridor by Room 314 Chem Lab	Photoelectric	20666231
0302	Smoke Detector	3rd Storage By rm 314 Chem Lab	Photoelectric	20666283
0303	Heat Detector	3rd Room 314	Rate-of-Rise	17013836
0304	Heat Detector	3rd Room 314	Rate-of-Rise	17013837
0305	Smoke Detector	3rd Corridor By rm 315 Chem Lab	Photoelectric	20666288
0306	Smoke Detector	3rd Office Prep By rm 315 Chem Lab	Photoelectric	20666287
0307	Heat Detector	3rd Room 315	Rate-of-Rise	17013835
0308	Heat Detector	3rd Room 315	Rate-of-Rise	17013834
0309	Smoke Detector	3rd Corridor By rm 315 Chem Lab	Photoelectric	20666290
0310	Smoke Detector	3rd Corridor By rm 315 Chem Lab	Photoelectric	20666289
0311	Smoke Detector	3rd Corridor By Girls Rm	Photoelectric	20666291
0312	Heat Detector	3rd Girls Rm	Rate-of-Rise	20666292
0313	Heat Detector	3rd Boys Rm	Rate-of-Rise	20666293

0314	Smoke Detector	3rd Corridor By Boys Rm	Photoelectric	20666294
0315	Heat Detector	3rd Womens Rm	Rate-of-Rise	20666295
0316	Heat Detector	3rd mens Rm	Rate-of-Rise	20666296
0317	Smoke Detector	3rd Atruim By Office Storage	Photoelectric	17014526
0379	Pull Station	3rd By Stair A	Dual Action	20666298
0380	Pull Station	3rd By Stair B	Dual Action	20666306
0383	Pull Station	3rd Stair C	Dual Action	20666253
0388	Pull Station	3rd Cisco Rm 310	Dual Action	20666258
0389	Pull Station	3rd Cisco Rm 311	Dual Action	20666259
0393	Pull Station	3rd Stair D	Dual Action	20666260
0395	Pull Station	3rd Library Entrance	Dual Action	20666261
0400	Pull Station	3rd Library Entrance	Dual Action	20666262
0401	Pull Station	3rd rm 312 Physics	Dual Action	20666274
0405	Pull Station	3rd Room 309	Dual Action	17013842
0407	Pull Station	3rd rm 313 Bio Earth	Dual Action	20666276
0408	Pull Station	3rd rm 314 Chem Lab	Dual Action	20666280
0409	Pull Station	3rd rm 315 Chem Lab	Dual Action	20666284