

DOCUMENT 00 43 36

DESIGNATED SUBCONTRACTORS LIST

TO BE EXECUTED BY BIDDER AND SUBMITTED WITH BID

George Hall New Multi-Purpose Building Project #19-143 ("Project" or "Contract")

1. **Listed.** Bidder must list hereinafter the name and location of each subcontractor who will be employed, and the scope of Work that each will perform if the Contract is awarded to the Bidder. Bidder acknowledges and agrees that under Public Contract Code section 4100, et seq., it must clearly identify the name and location of each subcontractor who will perform work or labor or render service to the Bidder in or about the construction of the Work in an amount in excess of one-half of one percent (1/2 of 1%) of Bidder's total Bid.
2. **CSLB Number.** Bidder must provide the Contractor State License Board number ("CSLB No.") for all listed subcontractors.
3. **DIR Number.** Bidder must provide the Department of Industrial Relations registration number ("DIR No.") for all listed subcontractors.
4. **Same Scope.** If more than one subcontractor is named for the same scope of Work, state with specificity the particular scope or portion that each subcontractor will perform.
5. **No Vendors or Suppliers.** Bidder need not list entities that are only vendors or suppliers of materials.
6. **Not Listed.** As to any Work that Bidder fails to list that is in excess of one-half of one percent (1/2 of 1%) of Bidder's total Bid, Bidder agrees that it is qualified to perform that scope of Work and will perform that scope of Work, or be subjected to penalty under applicable law.
7. **Alternate Work.** If alternate bids are called for and Bidder intends to use Subcontractors different from or in addition to those Subcontractors listed for work under the base Bid, Bidder must list Subcontractors that will perform Work in an amount in excess of one half of one percent (1/2 of 1%) of Bidder's total Bid, including alternates.
8. **DVBEs.** Bidder must indicate which, if any, of its subcontractors are disabled veteran business enterprises (DVBE) and the estimated percentage of the Work those subcontractor(s) will perform.
9. **Bidders may correct inadvertent error(s) in listing subcontractors' CSLB Nos. or DIR Nos. within twenty-four (24) hours after bid opening.**
10. **Additional Sheets.** If further space is required for the list of proposed subcontractors, additional sheets showing the required information, as indicated below, shall be attached hereto and made a part of this document and submitted with this form.

I certify and declare under penalty of perjury under the laws of the State of California that all the information listed on the following page(s) is complete, true, and correct.

Date: 12/02/2021  
Proper Name of Bidder: Bana Builders, Inc.  
Signature: J. Ramezanbeigi  
Print Name: Jahan Ramezanbeigi  
Title: President

Subcontractor Name: Contra Costa Door Location: Concord

Scope of Work: Over Head Coilng Door

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 186913 DIR No.: 100006268

Subcontractor Name: Arrow Lift of CA Location: Clavis

Scope of Work: wheel chair lifts

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 995486 DIR No.: 100002783

Subcontractor Name: RCM Location: Tracy

Scope of Work: Fire sprinkler

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 793205 DIR No.: 100006192

Subcontractor Name: U.S.A Shade Location: NAPA

Scope of Work: shade structure

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 989458 DIR No.: 1000003533

Subcontractor Name: Cyclone Fence & Iron Inc Location: San Martin

Scope of Work: Chain link Fence / Ornamental

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 966827 DIR No.: 100008661

Subcontractor Name: Dinelli plumbing Location: Foster city

Scope of Work: plumbing

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 801472 DIR No.: 100000999

Subcontractor Name: ARGO Construction inc Location: S.F

Scope of Work: Rough Framing

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 857620 DIR No.: 1000005050

Subcontractor Name: KZ Tile Location: S.F

Scope of Work: CERAMIC TILE

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 767277 DIR No.: 1000001756

Subcontractor Name: SJ Albanis Location: SANTA CLARA

Scope of Work: Demo/Grading/Paving/Asphalt/Form/Rebar/Concrete slab/concrete structural

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 299880 DIR No.: 1000002678

Subcontractor Name: Thompson Construction Group Location: Emeryville

Scope of Work: Resinous Flooring

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 701197 DIR No.: 1000006482

Subcontractor Name: Los Loza inc Location: Castro Valley

Scope of Work: Irrigation, planting, Artificial Turf

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 985575 DIR No.: 1000707281

Subcontractor Name: Pioneer Roofing Location: S.F

Scope of Work: METAL ROOF PANELS, METAL WALL PANELS/Equipment screen/PVC Roofing

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 777064 DIR No.: 1000008195

Subcontractor Name: Kim's Flooring Location: S.F

Scope of Work: Resilient Flooring/Resilient Base

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 739226 DIR No.: 1000006544

Subcontractor Name: Blue skies painting Location: S.F

Scope of Work: PAINTING

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 902215 DIR No.: 1000041825

Subcontractor Name: TIK Location: S.F

Scope of Work: METAL FAB

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 904248 DIR No.: 1000002777

END OF DOCUMENT

Scope of Work: \_\_\_\_\_  
If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

Subcontractor Name: JMA Construction Location: S.F

Scope of Work: CABINET

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 949071 DIR No.: 1000008440

Subcontractor Name: ATLANTIS INTERIOR Location: Sausalito

Scope of Work: Acoustical ceiling / Acoustical suspension system / Acv. Treated

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 618201 DIR No.: 1000028777

Subcontractor Name: M.K. pipe line Location: Brisbane

Scope of Work: Under Ground

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 856827 DIR No.: 1000000631

Subcontractor Name: Foot Hill mechanical Location: LOS GATOS

Scope of Work: mechanical

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 363862 DIR No.: 1000000433

Subcontractor Name: Arning-Johnson Comp Location: HAYWARD

Scope of Work: 072013, 074236

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 652025 DIR No.: 1000000625

Subcontractor Name: Core Glass & Aluminium inc Location: S. S.F

Scope of Work: 084110, 084113, 084414, 083000

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 924066 DIR No.: 1000005004

Subcontractor Name: HARRISON Drywall Location: SF

Scope of Work: Gypsum wall / cement plaster

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 620446 DIR No.: ~~1000004951~~

Subcontractor Name: PACIFIC Powers & System Location: FAIRFIELD

Scope of Work: ELECTRICAL

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: 458315 DIR No.: 1000000158

END OF DOCUMENT

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

END OF DOCUMENT

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

END OF DOCUMENT

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

**Subcontractor Name:** \_\_\_\_\_ **Location:** \_\_\_\_\_

Scope of Work: \_\_\_\_\_

If DVBE, Percent of Work: \_\_\_\_\_ % CSLB No.: \_\_\_\_\_ DIR No.: \_\_\_\_\_

END OF DOCUMENT