Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

December 15, 2020

Mr. Michael Bryniarski
Director of Facilities
Lancaster Central School District
177 Central Avenue
Lancaster, NY 14086

RE: Investigation and Sampling of Drinking Water for Lead Concentrations

Dear Mr. Bryniarski:

Included with this letter is Stohl Environmental LLC's report for the Water Sampling performed at the educational buildings of the Lancaster Central School District, including:

- Como Park Elementary – 1985 Como Park Boulevard, Lancaster, New York.

This report is prepared to assist the District in complying with the requirements of NYS regulations, *SUBPART 67-4: Lead Testing in School Drinking Water*, by identifying the sources of potable water with lead concentrations greater than the NYS "Action Level of 15 parts per billion (ppb)".

The Investigation and Sampling was performed on October 24, 2020. The Protocol for the Investigation followed the requirements of NYS regulations as well as USEPA Technical Guidance Document "3-T's for Reducing Lead in Drinking Water in Schools".

As detailed in Section 1.2 *(Executive Summary)* of the accompanying report, based upon the sampling and analysis performed, 7 source of potable water in Como Park Elementary has been identified as having a lead concentration in water above the NYS Action Level of 15 parts per billion. To comply with NYS regulations, Response actions as identified in this report by the District are required.

Thank you for the opportunity to be of service to Lancaster Central School District.

Sincerely,
Stohl Environmental, LLC.

Eric Henderson Jr.
Senior Project Manager

Investigation and Sampling Of Sources of Potable Water For Lead Concentrations

Prepared for:

Lancaster Central School District

Prepared by:

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Conditions as of October 24, 2020

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

Summary Tabulation

Lead in Drinking Water Investigation

1.1. Scope of Work and Sampling Protocol

1.2. Executive Summary of Sampling and Analysis

1.3. Response Actions Required Under NYS Regulations

1.4. Laboratory Analytical Reports by Building

1.5. Laboratory Certifications

1.6. Chains of Custody

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.1 Scope of Work and Sampling Protocol:

Stohl Environmental was retained by Lancaster Central School District to perform sampling and analysis of potable water for elevated lead concentrations. Sampling was performed in the following buildings:

- Como Park Elementary – 1985 Como Park Boulevard, Lancaster, New York.

Scope of Work:

Stohl Environmental was charged with collecting first-draw water samples from outlets within the Como Park Elementary. Outlets are defined in NYS regulations as: "a potable water fixture currently or potentially used for drinking or cooking purposes, including but not limited to a bubbler, drinking fountain, or faucets".

Sampling Protocol:

In accordance with NYS regulations, ***Subpart 67-4: Lead Testing in School Drinking Water***, and the EPA guidance document, ***'3Ts for Reducing Lead in Drinking Water in Schools"***, Stohl Environmental's protocol can be summarized as follows:

- **First-draw samples** of 250 milliliters (mL) were collected from cold water outlets before any water was used. Sampling was coordinated with District representatives to assure that water was motionless in the pipes for a minimum of 8 hours, but not more than 18 hours before sample collection.

- **Laboratory Analysis:** Samples were submitted following strict chain-of-custody protocols to an independent laboratory approved by the NYS Department of Health's Environmental Laboratory Approval Program (ELAP).

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.2 Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Confirmatory Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb
Como Park Elementary	10/24/2020	68	61	7	N/A	N/A

****** Confirmatory samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Listing of Outlets Requiring Remediation

Locations of Outlets Analyzed above the NYS Action Level of 15 parts per billion based upon Analysis of First Draw Samples:

Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb
169.4-10	Room 114	Bubbler	181
169.4-20	Room 207	Sink	15.4
169.4-21	Room 208	Sink	47.0
169.4-30	Room 204	Sink	18.2
169.4-31	Room 211	Sink	18.1
169.4-57	Room 223	Sink	18.9
169.4-62	Girls Lav 220 Far Right	Sink	16.6

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.3 Response Actions Required Under NYS Regulations, Section 67-4.4:

For outlets analyzed with a lead concentration in excess of the NYS Action Level, regulations require:

(a) Prohibit use of the outlet until:

(1) a lead remediation plan is implemented to mitigate the lead level of such outlet; and

(2) test results indicate that the lead levels are at or below the action level;

(b) provide building occupants with an adequate supply of potable water for drinking and cooking until remediation is performed;

(c) report the test results to the local health department as soon as practicable, but no more than 1 business day after the school received the laboratory report; and

(d) notify all staff and all persons in parental relation to students of the test results, in writing, as soon as practicable but no more than 10 business days after the school received the laboratory report.

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.4 Laboratory Analytical Reports by Building

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 20-10-06125

Client: Stohl Environmental
3860 California Road
Orchard Park, NY 14127

Received Date: 10/29/2020
Reported Date: 11/23/2020
Sampled By: P Nichols/C Schultz
Tech Certification #:

Project/Test Address: 2020L-169.4; Como Park Elementary; 1985 Como Park Blvd; Lancaster, NY 14086

Client Number:
33-5980

Laboratory Results

Fax Number:
716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06125-001	169.4-1	10/24/2020	MAIN OFFICE LAV	<1.00	11/19/2020	
20-10-06125-002	169.4-2	10/24/2020	MAIN OFFICE HALLWAY LAV	2.14	11/19/2020	
20-10-06125-003	169.4-3A	10/24/2020	MAIN OFFICE HALL FNTN LEFT	<1.00	11/19/2020	
20-10-06125-004	169.4-3B	10/24/2020	MAIN OFFICE HALL FNTN LEFT	<1.00	11/19/2020	
20-10-06125-005	169.4-4	10/24/2020	MAIN OFFICE HALL FNTN RIGHT	<1.00	11/19/2020	
20-10-06125-006	169.4-5	10/24/2020	GIRLS LAV BY KITCHEN	5.08	11/19/2020	
20-10-06125-007	169.4-6	10/24/2020	ROOM 107	6.61	11/19/2020	
20-10-06125-008	169.4-7	10/24/2020	ROOM 108 SINK	7.03	11/19/2020	
20-10-06125-009	169.4-8	10/24/2020	ROOM 108 BUBBLER	1.34	11/19/2020	
20-10-06125-010	169.4-9	10/24/2020	ROOM 114	3.40	11/19/2020	
20-10-06125-011	169.4-10	10/24/2020	ROOM 114	181	11/11/2020	
20-10-06125-012	169.4-11	10/24/2020	ROOM 114 LAV	14.3	11/19/2020	

Client Number: 33-5980 Report Number: 20-10-06125

Project/Test Address: 2020L-169.4; Como Park Elementary; 1985 Como Park Blvd; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06125-013	169.4-12	10/24/2020	ROOM 109	5.24	11/19/2020	
20-10-06125-014	169.4-13	10/24/2020	ROOM 113	7.11	11/19/2020	
20-10-06125-015	169.4-14	10/24/2020	ROOM 113	6.03	11/19/2020	
20-10-06125-016	169.4-15	10/24/2020	ROOM 110 ART ROOM LEFT	1.42	11/19/2020	
20-10-06125-017	169.4-16	10/24/2020	ROOM 110 ART ROOM RIGHT	1.36	11/19/2020	
20-10-06125-018	169.4-17	10/24/2020	ROOM 110 ART ROOM LAV	5.29	11/19/2020	
20-10-06125-019	169.4-18	10/24/2020	ROOM 112	6.75	11/19/2020	
20-10-06125-020	169.4-19	10/24/2020	ROOM 111	2.90	11/19/2020	
20-10-06125-021	169.4-20	10/24/2020	ROOM 207	15.4	11/19/2020	
20-10-06125-022	169.4-21	10/24/2020	ROOM 208	47.0	11/19/2020	
20-10-06125-023	169.4-22A	10/24/2020	HALLWAY FOUNTAIN OUTSIDE 205	<1.00	11/19/2020	
20-10-06125-024	169.4-22B	10/24/2020	HALLWAY FOUNTAIN OUTSIDE 205	<1.00	11/19/2020	
20-10-06125-025	169.4-23	10/24/2020	BOYS LAV 206 LEFT	9.32	11/19/2020	
20-10-06125-026	169.4-25	10/24/2020	ROOM 209	5.06	11/19/2020	
20-10-06125-027	169.4-26	10/24/2020	ROOM 205	10.4	11/19/2020	
20-10-06125-028	169.4-28	10/24/2020	GIRLS AVE 210	3.88	11/19/2020	
20-10-06125-029	169.4-30	10/24/2020	ROOM 204	18.2	11/19/2020	
20-10-06125-030	169.4-31	10/24/2020	ROOM 211	18.1	11/19/2020	
20-10-06125-031	169.4-32	10/24/2020	ROOM 203	14.4	11/19/2020	
20-10-06125-032	169.4-33	10/24/2020	ROOM 202	7.86	11/19/2020	

Client Number: 33-5980 Report Number: 20-10-06125

Project/Test Address: 2020L-169.4; Como Park Elementary; 1985 Como Park Blvd; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06125-033	169.4-34	10/24/2020	FACULTY LAV 2ND FL	1.44	11/19/2020	
20-10-06125-034	169.4-35	10/24/2020	ROOM 212 FACULTY ROOM	9.83	11/19/2020	
20-10-06125-035	169.4-36	10/24/2020	KITCHEN HAND WASH	1.95	11/19/2020	
20-10-06125-036	169.4-37	10/24/2020	KITCHEN DISH SPRAYER	2.49	11/19/2020	
20-10-06125-037	169.4-38	10/24/2020	KITCHEN 2 BAY SINK	5.34	11/19/2020	
20-10-06125-038	169.4-39	10/24/2020	ROOM 119	3.16	11/19/2020	
20-10-06125-039	169.4-40	10/24/2020	ROOM 120	3.95	11/19/2020	
20-10-06125-040	169.4-42	10/24/2020	GIRLS LOCKER ROOM	2.57	11/19/2020	
20-10-06125-041	169.4-43A	10/24/2020	HALLWAY OUTSIDE 129	<1.00	11/19/2020	
20-10-06125-042	169.4-43B	10/24/2020	HALLWAY OUTSIDE 129	<1.00	11/19/2020	
20-10-06125-043	169.4-44	10/24/2020	127 LIBRARY MEDIA CENTER	14.6	11/19/2020	
20-10-06125-044	169.4-45	10/24/2020	ROOM 126 MAIN	13.6	11/19/2020	
20-10-06125-045	169.4-46	10/24/2020	ROOM 126 LAV	10.5	11/19/2020	
20-10-06125-046	169.4-47	10/24/2020	ROOM 125 MAIN	8.74	11/19/2020	
20-10-06125-047	169.4-48	10/24/2020	ROOM 125 LAV	4.42	11/19/2020	
20-10-06125-048	169.4-49	10/24/2020	ROOM 106 NURSE MAIN	13.8	11/19/2020	
20-10-06125-049	169.4-50	10/24/2020	ROOM 106 NURSE LAV	13.8	11/19/2020	
20-10-06125-050	169.4-51	10/24/2020	FOUNTAIN OUTSIDE NURSE	5.01	11/19/2020	
20-10-06125-051	169.4-52	10/24/2020	FOUNTAIN OUTSIDE 227	5.64	11/19/2020	
20-10-06125-052	169.4-53	10/24/2020	ROOM 227	1.47	11/19/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-06125

Project/Test Address: 2020L-169.4; Como Park Elementary; 1985 Como Park Blvd; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06125-053	169.4-54	10/24/2020	ROOM 226	<1.00	11/19/2020	
20-10-06125-054	169.4-55	10/24/2020	ROOM 225	<1.00	11/19/2020	
20-10-06125-055	169.4-56	10/24/2020	ROOM 224	1.75	11/19/2020	
20-10-06125-056	169.4-57	10/24/2020	ROOM 223	18.9	11/19/2020	
20-10-06125-057	169.4-58	10/24/2020	ROOM 222 FAC MAIN	1.96	11/19/2020	
20-10-06125-058	169.4-59	10/24/2020	ROOM 222 FAC LAV LEFT	2.69	11/19/2020	
20-10-06125-059	169.4-60	10/24/2020	ROOM 222 FAC LAV RIGHT	9.79	11/19/2020	
20-10-06125-060	169.4-61A	10/24/2020	FOUNTAIN OUTSIDE 222 FAC	<1.00	11/19/2020	
20-10-06125-061	169.4-61B	10/24/2020	FOUNTAIN OUTSIDE 222 FAC	<1.00	11/19/2020	
20-10-06125-062	169.4-62	10/24/2020	GIRLS LAV 220 FAR LEFT	16.6	11/20/2020	
20-10-06125-063	169.4-65	10/24/2020	GIRLS LAV 220 FAR RIGHT	4.67	11/19/2020	
20-10-06125-064	169.4-66	10/24/2020	BOYS 218 LAV LEFT	8.32	11/19/2020	
20-10-06125-065	169.4-68	10/24/2020	ROO 216 MAIN	1.30	11/19/2020	
20-10-06125-066	169.4-69	10/24/2020	ROOM 216 LAV	3.31	11/19/2020	
20-10-06125-067	169.4-70	10/24/2020	ROOM 215	3.86	11/19/2020	
20-10-06125-068	169.4-71	10/24/2020	ROOM 214	3.33	11/19/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-06125

Project/Test Address: 2020L-169.4; Como Park Elementary; 1985 Como Park Blvd; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NY 11714

Reviewed By Authorized Signatory: Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.5 Laboratory Certifications

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER

Expires 12:01 AM April 01, 2021
Issued April 01, 2020

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MS. JULIE DICKERSON
ENVIRONMENTAL HAZARDS SERVICES, LLC
7469 WHITEPINE ROAD
N. CHESTERFIELD, VA 23237

NY Lab Id No: 11714

is hereby APPROVED as an Environmental Laboratory in conformance with the National Environmental Laboratory Accreditation Conference Standards (2003) for the category ENVIRONMENTAL ANALYSES POTABLE WATER
All approved analytes are listed below:

Metals I

Copper, Total	SM 19, 21-23 3113B (-04,-10)
Lead, Total	SM 19, 21-23 3113B (-04,-10)

NEW YORK STATE | Department of Health

Serial No.: 61514

Property of the New York State Department of Health. Certificates are valid only at the address shown, must be conspicuously posted, and are printed on secure paper. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify the laboratory's accreditation status.

NELAP RECOGNIZED TNI ACCREDITATION BODY

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.6 Chains of Custody

20-10-06125

Stohl ENVIRONMEN

3860 California Road, Orchard Park, New Yo
PHONE (716) 312-0070 FAX (716) 312-8
WWW.STOHLENVIRONMENTAL.COM

Due Date:
11/27/2020
(Friday)
AE

# of Custody Document

(Lab Name) EHS

TOHL Job # 2020L-169.4

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Como Park Elementary

Location: 1985 Como Park Blvd Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
1	169.4-1	Main Office Lav	Sink	11:00			
2	169.4-2	Main Office Hallway Lav	Sink	11:01			
3	169.4-3A	Main Office Hall Fntn Left	DFA	11:02			
4	169.4-3B	Main Office Hall Fntn Left	DFB	11:03			
5	169.4-4	Main Office Hall Fntn Right	DFA	11:04			
6	169.4-5	Girls Lav by Kitchen	Sink	11:05			
7	169.4-6	Room 107	Sink	11:06			
8	169.4-7	Room 108 Sink	Sink	11:07			
9	169.4-8	Room 108 Bubbler	Bubbler	11:08			
10	169.4-9	Room 114	Sink	11:09			
11	169.4-10	Room 114	Bubbler	11:10			
12	169.4-11	Room 114 Lav	Sink	11:11			
13	169.4-12	Room 109	Sink	11:12			
14	169.4-13	Room 113	Sink	11:13			
15	169.4-14	Room 113	Bubbler	11:14			
16	169.4-15	Room 110 Art Room Left	Sink	11:15			
17	169.4-16	Room 110 Art Room Right	Sink	11:16			
18	169.4-17	Room 110 Art Room Lav	Sink	11:17			

Notes:
Please e-mail lab results to labs@stohlenv.com ☑ If checked, also e-mail results to: Ehenderson@StohlEnv.com

Sampled By: P.Nichols, C.Schultz Print Name — Stohl Env: P.Nichols, C.Schultz Date: 10/24/2020

Relinquished By: [signature] Print Name — Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): [signature] Date: 10/29/20 Time: 5:30p

Sample Login (Name / Lab): [signature] Date: 11/17/20 Time: 4:44 PM

Analysis (Name / Lab): [signature] Date: 11/20/20 Time: 8:10 am

QA/QC Review (Name / Lab): [signature] Date: 11/22/20 Time: hun

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Chain of Custody Document

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.4

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Como Park Elementary

Location: 1985 Como Park Blvd Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround 20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
19	169.4-18	Room 112	Sink	11:18			
20	169.4-19	Room 111	Sink	11:19			
21	169.4-20	Room 207	Sink	11:20			
22	169.4-21	Room 208	sink	11:21			
23	169.4-22A	Hallway Fountain Outside 205	Sink	11:22			
24	169.4-22B	Hallway Fountain Outside 205	Sink	11:23			
25	169.4-23	Boys Lav 206 Left	Sink	11:24			
26	169.4-25	Room 209	Sink	11:25			
27	169.4-26	Room 205	Sink	11:26			
28	169.4-28	Girls Ave 210	Sink	11:27			
29	169.4-30	Room 204	Sink	11:28			
30	169.4-31	Room 211	Sink	11:29			
31	169.4-32	Room 203	Sink	11:30			
32	169.4-33	Room 202	Sink	11:31			
33	169.4-34	Faculty Lav 2nd Fl	Sink	11:32			
34	169.4-35	Room 212 Faculty Room	Sink	11:33			
35	169.4-36	Kitchen Hand Wash	Sink	11:34			
36	169.4-37	Kitchen Dish Sprayer	Sink	11:35			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: P.Nichols, C.Schultz Print Name — Stohl Env: P.Nichols, C.Schultz — Date: 10/24/2020

Relinquished By: [signature] Print Name — Stohl Env: Eric Henderson Jr. — Date: 10/26/2020

Received (Name / Lab): T Lohman — Date: 10/29/20 — Time: 5:30

Sample Login (Name / Lab): Liam Brom — Date: 11/17/20 — Time: 4:48 PM

Analysis (Name / Lab): J. Hertzler — Date: 11/20/20 — Time: 8:10 am

QA/QC Review (Name / Lab): [signature] — Date: 11/22/20 — Time: Noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Chain of Custody Document

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.4

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Como Park Elementary

Location: 1985 Como Park Blvd Lancaster, NY 14086

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
37	169.4-38	Kitchen 2 Bay Sink	Sink	11:36			
38	169.4-39	Room 119	Sink	11:37			
39	169.4-40	Room 120	Sink	11:38			
40	169.4-42	Girls Locker Room	Sink	11:39			
41	169.4-43A	Hallway Outside 129	DFA	11:40			
42	169.4-43B	Hallway Outside 129	DFB	11:41			
43	169.4-44	127 Library Media Center	Sink	11:42			
44	169.4-45	Room 126 Main	Sink	11:43			
45	169.4-46	Room 126 Lav	Sink	11:44			
46	169.4-47	Room 125 Main	Sink	11:45			
47	169.4-48	Room 125 Lav	Sink	11:46			
48	169.4-49	Room 106 Nurse Main	Sink	11:47			
49	169.4-50	Rom 106 Nurse Lav	Sink	11:48			
50	169.4-51	Fountain Outside Nurse	DFA	11:49			
51	169.4-52	Fountain Outside 227	DFA	11:50			
52	169.4-53	Room 227	Sink	11:51			
53	169.4-54	Room 226	Sink	11:52			
54	169.4-55	Room 225	Sink	11:53			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: P.Nichols, C.Schultz Print Name Stohl Env: P.Nichols, C.Schultz Date: 10/24/2020

Relinquished By: E. Henderson Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): T. Lohman Date: 10/29/20 Time: 5:30

Sample Login (Name / Lab): Lori Blom Date: 11/17/20 Time: 449PM

Analysis (Name / Lab): J. Hertzler Date: 11/20/20 Time: 8:10 am

QA/QC Review (Name / Lab): [illegible] Date: 11/23/20 Time: [illegible]

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.4

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Como Park Elementary

Location: 1985 Como Park Blvd Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
55	169.4-56	Room 224	Sink	11:54			
56	169.4-57	Room 223	Sink	11:55			
57	169.4-58	Room 222 Fac Main	Sink	11:56			
58	169.4-59	Room 222 Fac Lav Left	Sink	11:57			
59	169.4-60	Room 222 Fac Lav Right	Sink	11:58			
60	169.4-61A	Fountain Outside 222 Fac	DFA	11:59			
61	169.4-61B	Fountain Outside 222 Fac	DFB	12:00			
62	169.4-62	Girls Lav 220 Far Left	Sink	12:01			
63	169.4-65	Girls Lav 220 Far Right	Sink	12:02			
64	169.4-66	Boys 218 Lav Left	Sink	12:03			
65	169.4-68	Room 216 Main	Sink	12:04			
66	169.4-69	Room 216 Lav	Sink	12:05			
67	169.4-70	Room 215	Sink	12:06			
68	169.4-71	Room 214	Sink	12:07			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: P.Nichols, C.Schultz Print Name Stohl Env: P.Nichols, C.Schultz Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): T. Ishaque Date: 10/29/20 Time: 5:3[illegible]

Sample Login (Name / Lab): Traci Blom Date: 11/7/20 Time: 4:51PM

Analysis (Name / Lab): G. Hertzler Date: 11/20/20 Time: 8:10 am

QA/QC Review (Name / Lab): [signature] Date: 11/22/20 Time: Noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM