Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

December 15, 2020

Mr. Michael Bryniarski
Director of Facilities
Lancaster Central School District
177 Central Avenue
Lancaster, NY 14086

RE: Investigation and Sampling of Drinking Water for Lead Concentrations

Dear Mr. Bryniarski:

Included with this letter is Stohl Environmental LLC's report for the Water Sampling performed at the educational buildings of the Lancaster Central School District, including:

- Hillview Elementary – 11 Pleasantview Drive, Lancaster, New York.

This report is prepared to assist the District in complying with the requirements of NYS regulations, *SUBPART 67-4: Lead Testing in School Drinking Water*, by identifying the sources of potable water with lead concentrations greater than the NYS "Action Level of 15 parts per billion (ppb)".

The Investigation and Sampling was performed on October 24, 2020. The Protocol for the Investigation followed the requirements of NYS regulations as well as USEPA Technical Guidance Document "3-T's for Reducing Lead in Drinking Water in Schools".

As detailed in Section 1.2 *(Executive Summary)* of the accompanying report, based upon the sampling and analysis performed, 2 source of potable water in Hillview Elementary has been identified as having a lead concentration in water above the NYS Action Level of 15 parts per billion. To comply with NYS regulations, Response actions as identified in this report by the District are required.

Thank you for the opportunity to be of service to Lancaster Central School District.

Sincerely,
Stohl Environmental, LLC.

Eric Henderson Jr.
Senior Project Manager

Investigation and Sampling Of Sources of Potable Water For Lead Concentrations

Prepared for:

Lancaster Central School District

Prepared by:

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Conditions as of October 24, 2020

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

Summary Tabulation

Lead in Drinking Water Investigation

1.1. Scope of Work and Sampling Protocol

1.2. Executive Summary of Sampling and Analysis

1.3. Response Actions Required Under NYS Regulations

1.4. Laboratory Analytical Reports by Building

1.5. Laboratory Certifications

1.6. Chains of Custody

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.1 Scope of Work and Sampling Protocol:

Stohl Environmental was retained by Lancaster Central School District to perform sampling and analysis of potable water for elevated lead concentrations. Sampling was performed in the following buildings:

- Hillview Elementary – 11 Pleasantview Drive, Lancaster, New York.

Scope of Work:

Stohl Environmental was charged with collecting first-draw water samples from outlets within Hillview Elementary. Outlets are defined in NYS regulations as: "a potable water fixture currently or potentially used for drinking or cooking purposes, including but not limited to a bubbler, drinking fountain, or faucets".

Sampling Protocol:

In accordance with NYS regulations, ***Subpart 67-4: Lead Testing in School Drinking Water***, and the EPA guidance document, ***'3Ts for Reducing Lead in Drinking Water in Schools"***, Stohl Environmental's protocol can be summarized as follows:

- **First-draw samples** of 250 milliliters (mL) were collected from cold water outlets before any water was used. Sampling was coordinated with District representatives to assure that water was motionless in the pipes for a minimum of 8 hours, but not more than 18 hours before sample collection.

- **Laboratory Analysis:** Samples were submitted following strict chain-of-custody protocols to an independent laboratory approved by the NYS Department of Health's Environmental Laboratory Approval Program (ELAP).

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.2 Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Confirmatory Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples at of Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples at of Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb
Hillview Elementary	10/24/2020	92	90	2	N/A	N/A

****** Confirmatory samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Listing of Outlets Requiring Remediation

Locations of Outlets Analyzed above the NYS Action Level of 15 parts per billion based upon Analysis of First Draw Samples:

Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb
169.6-65	Outdoor Lav Girls Side 12	Sink	62.9
169.6-66	Outdoor Lav Boys Side 9	Sink	41.9

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.3 Response Actions Required Under NYS Regulations, Section 67-4.4:

For outlets analyzed with a lead concentration in excess of the NYS Action Level, regulations require:

(a) Prohibit use of the outlet until:

(1) a lead remediation plan is implemented to mitigate the lead level of such outlet; and

(2) test results indicate that the lead levels are at or below the action level;

(b) provide building occupants with an adequate supply of potable water for drinking and cooking until remediation is performed;

(c) report the test results to the local health department as soon as practicable, but no more than 1 business day after the school received the laboratory report; and

(d) notify all staff and all persons in parental relation to students of the test results, in writing, as soon as practicable but no more than 10 business days after the school received the laboratory report.

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.4 Laboratory Analytical Reports by Building

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 20-10-06122

Client: Stohl Environmental
3860 California Road
Orchard Park, NY 14127

Received Date: 10/29/2020
Reported Date: 11/20/2020
Sampled By: C Schultz/P Nichols
Tech Certification #:

Project/Test Address: 2020L-169.6; Hillview Elementary; 11 Pleasantview Dr; Lancaster, NY 14086

Client Number: 33-5980

Laboratory Results

Fax Number: 716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06122-001	169.6-1	10/24/2020	KITCHEN 3 BAY LEFT	3.68	11/18/2020	
20-10-06122-002	169.6-2	10/24/2020	KITCHEN 3 BAY RIGHT	3.37	11/18/2020	
20-10-06122-003	169.6-3	10/24/2020	KITCHEN LAV	5.77	11/18/2020	
20-10-06122-004	169.6-4	10/24/2020	KITCHEN DISH SPRAYER	1.13	11/18/2020	
20-10-06122-005	169.6-5	10/24/2020	CAFETERIA FOUNTAIN	9.79	11/18/2020	
20-10-06122-006	169.6-6	10/24/2020	1ST WING GIRLS LAV LEFT	2.22	11/18/2020	
20-10-06122-007	169.6-7	10/24/2020	1ST WING GIRLS LAV RIGHT	2.07	11/18/2020	
20-10-06122-008	169.6-8A	10/24/2020	1ST WING FOUNTAIN	<1.00	11/18/2020	
20-10-06122-009	169.6-8B	10/24/2020	1ST WING FOUNTAIN	<1.00	11/18/2020	
20-10-06122-010	169.6-9	10/24/2020	1ST WING BOYS LAV LEFT	1.49	11/18/2020	
20-10-06122-011	169.6-10	10/24/2020	1ST WING BOYS LAV RIGHT	1.28	11/18/2020	
20-10-06122-012	169.6-11	10/24/2020	PRINCIPALS OFFICE LAV	5.41	11/18/2020	
20-10-06122-013	169.6-12	10/24/2020	ROOM 1 MAIN	<1.00	11/18/2020	

Client Number: 33-5980 Report Number: 20-10-06122

Project/Test Address: 2020L-169.6; Hillview Elementary; 11 Pleasantview Dr; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06122-014	169.6-13	10/24/2020	ROOM 1 MAIN	<1.00	11/18/2020	
20-10-06122-015	169.6-14	10/24/2020	ROOM 1 LAV	2.91	11/18/2020	
20-10-06122-016	169.6-15	10/24/2020	ROOM 8 MAIN	<1.00	11/18/2020	
20-10-06122-017	169.6-16	10/24/2020	ROOM 8 MAIN	<1.00	11/18/2020	
20-10-06122-018	169.6-17	10/24/2020	ROOM 7 MAIN	<1.00	11/18/2020	
20-10-06122-019	169.6-18	10/24/2020	ROOM 7 MAIN	<1.00	11/18/2020	
20-10-06122-020	169.6-19	10/24/2020	ROOM 3 MAIN	1.63	11/18/2020	
20-10-06122-021	169.6-20	10/24/2020	ROOM 3 MAIN	<1.00	11/18/2020	
20-10-06122-022	169.6-21	10/24/2020	ROOM 3 LAV	3.44	11/18/2020	
20-10-06122-023	169.6-22	10/24/2020	ROOM 6 MAIN	<1.00	11/18/2020	
20-10-06122-024	169.6-23	10/24/2020	ROOM 6 MAIN	1.70	11/18/2020	
20-10-06122-025	169.6-24	10/24/2020	ROOM 5 MAIN	2.99	11/18/2020	
20-10-06122-026	169.6-25	10/24/2020	ROOM 5 MAIN	5.84	11/18/2020	
20-10-06122-027	169.6-26	10/24/2020	ROOM 5 LAV	5.28	11/18/2020	
20-10-06122-028	169.6-27	10/24/2020	ROOM 4 MAIN	3.15	11/18/2020	
20-10-06122-029	169.6-28	10/24/2020	ROOM 4 MAIN	2.25	11/18/2020	
20-10-06122-030	169.6-29	10/24/2020	ROOM 4 LAV	3.87	11/18/2020	
20-10-06122-031	169.6-30	10/24/2020	ROOM 44 FAC LAV RIGHT	3.73	11/18/2020	
20-10-06122-032	169.6-31	10/24/2020	ROOM 44 FAC LAV LEFT	1.71	11/18/2020	
20-10-06122-033	169.6-32	10/24/2020	ROOM 9 MAIN	1.38	11/18/2020	

Client Number: 33-5980 Report Number: 20-10-06122

Project/Test Address: 2020L-169.6; Hillview Elementary; 11 Pleasantview Dr; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06122-034	169.6-33	10/24/2020	ROOM 9 MAIN	2.00	11/18/2020	
20-10-06122-035	169.6-34	10/24/2020	ROOM 9 LAV	<1.00	11/18/2020	
20-10-06122-036	169.6-35	10/24/2020	NURSE MAIN	5.54	11/18/2020	
20-10-06122-037	169.6-36	10/24/2020	NURSE EXAM	8.11	11/18/2020	
20-10-06122-038	169.6-37	10/24/2020	NURSE LAV	2.15	11/18/2020	
20-10-06122-039	169.6-38	10/24/2020	ROOM 10	4.62	11/18/2020	
20-10-06122-040	169.6-39	10/24/2020	ROOM 10	1.99	11/18/2020	
20-10-06122-041	169.6-40	10/24/2020	ROOM 42 ART MAIN LEFT	<1.00	11/18/2020	
20-10-06122-042	169.6-41	10/24/2020	ROOM 42 ART MAIN RIGHT	<1.00	11/18/2020	
20-10-06122-043	169.6-42	10/24/2020	ROOM 42 ART OFFICE LEFT	<1.00	11/18/2020	
20-10-06122-044	169.6-43	10/24/2020	ROOM 42 ART OFFICE RIGHT	3.92	11/18/2020	
20-10-06122-045	169.6-44	10/24/2020	MAIN HALLWAY BOYS LAV LEFT	2.60	11/18/2020	
20-10-06122-046	169.6-45	10/24/2020	MAIN HALLWAY BOYS LAV RIGHT	2.02	11/18/2020	
20-10-06122-047	169.6-46A	10/24/2020	MAIN HALLWAY FOUNTAIN	<1.00	11/18/2020	
20-10-06122-048	169.6-46B	10/24/2020	MAIN HALLWAY FOUNTAIN	<1.00	11/18/2020	
20-10-06122-049	169.6-47	10/24/2020	2ND WING GIRLS LAV LEFT	2.54	11/18/2020	
20-10-06122-050	169.6-48	10/24/2020	2ND WING GIRLS LAV CENTER	1.65	11/18/2020	
20-10-06122-051	169.6-49	10/24/2020	2ND WING GIRLS LAV RIGHT	4.67	11/18/2020	
20-10-06122-052	169.6-50	10/24/2020	ROOM 16 MAIN	2.49	11/18/2020	
20-10-06122-053	169.6-51	10/24/2020	ROOM 16 MAIN	2.65	11/18/2020	

Client Number: 33-5980 Report Number: 20-10-06122

Project/Test Address: 2020L-169.6; Hillview Elementary; 11 Pleasantview Dr; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06122-054	169.6-52	10/24/2020	ROOM 11	4.82	11/19/2020	
20-10-06122-055	169.6-53	10/24/2020	ROOM 11	5.63	11/19/2020	
20-10-06122-056	169.6-54	10/24/2020	ROOM 15	3.38	11/19/2020	
20-10-06122-057	169.6-55	10/24/2020	ROOM 15	1.89	11/19/2020	
20-10-06122-058	169.6-56	10/24/2020	ROOM 12	3.17	11/19/2020	
20-10-06122-059	169.6-57	10/24/2020	ROOM 12	1.75	11/19/2020	
20-10-06122-060	169.6-58	10/24/2020	ROOM 14	3.25	11/19/2020	
20-10-06122-061	169.6-59	10/24/2020	ROOM 14	3.29	11/19/2020	
20-10-06122-062	169.6-60	10/24/2020	ROOM 13	1.10	11/19/2020	
20-10-06122-063	169.6-61	10/24/2020	ROOM 13	1.38	11/19/2020	
20-10-06122-064	169.6-62A	10/24/2020	GYM HAL FOUNTAIN	<1.00	11/19/2020	
20-10-06122-065	169.6-62B	10/24/2020	GYM HALL FOUNTAIN	<1.00	11/19/2020	
20-10-06122-066	169.6-63	10/24/2020	GIRLS LOCKER COACH OFFICE	7.41	11/19/2020	
20-10-06122-067	169.6-64	10/24/2020	GIRLS LOCKER ROOM	13.6	11/19/2020	
20-10-06122-068	169.6-65	10/24/2020	OUTDOOR LAV GIRLS SIDE 12	62.9	11/19/2020	
20-10-06122-069	169.6-66	10/24/2020	OUTDOOR LAV BOYS SIDE 9	41.9	11/19/2020	
20-10-06122-070	169.6-67	10/24/2020	BOYS GYM OFFICE	6.73	11/19/2020	
20-10-06122-071	169.6-68	10/24/2020	OT ROOM	1.20	11/19/2020	
20-10-06122-072	169.6-69	10/24/2020	FAC LAV BY MEDIA CENTER	<1.00	11/19/2020	
20-10-06122-073	169.6-70	10/24/2020	FOUNTAIN BY MEDIA CENTER	6.51	11/19/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-06122

Project/Test Address: 2020L-169.6; Hillview Elementary; 11 Pleasantview Dr; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06122-074	169.6-71	10/24/2020	MEDIA CENTER	1.96	11/19/2020	
20-10-06122-075	169.6-72	10/24/2020	ROOM 26	1.13	11/19/2020	
20-10-06122-076	169.6-74	10/24/2020	ROOM 17	3.83	11/19/2020	
20-10-06122-077	169.6-76	10/24/2020	ROOM 25	1.43	11/19/2020	
20-10-06122-078	169.6-78	10/24/2020	ROOM 18	1.77	11/19/2020	
20-10-06122-079	169.6-80	10/24/2020	3RD WING GIRLS LAV LEFT	2.15	11/19/2020	
20-10-06122-080	169.6-81	10/24/2020	3RD WING GIRLS LAV RIGHT	2.02	11/19/2020	
20-10-06122-081	169.6-82A	10/24/2020	3RD WING FOUNTAIN	<1.00	11/19/2020	
20-10-06122-082	169.6-82B	10/24/2020	3RD WING FOUNTAIN	<1.00	11/19/2020	
20-10-06122-083	169.6-83	10/24/2020	3RD WING BOYS LAV LEFT	1.29	11/19/2020	
20-10-06122-084	169.6-84	10/24/2020	3RD WING BOYS LAV CENTER	1.51	11/19/2020	
20-10-06122-085	169.6-85	10/24/2020	3RD WING BOYS LAV RIGHT	1.07	11/19/2020	
20-10-06122-086	169.6-86	10/24/2020	ROOM 24	1.79	11/19/2020	
20-10-06122-087	169.6-88	10/24/2020	ROOM 19	1.28	11/19/2020	
20-10-06122-088	169.6-90	10/24/2020	ROOM 23	1.48	11/19/2020	
20-10-06122-089	169.6-92	10/24/2020	ROOM 20	2.14	11/19/2020	
20-10-06122-090	169.6-94	10/24/2020	ROOM 22	1.35	11/19/2020	
20-10-06122-091	169.6-96	10/24/2020	ROOM 21	3.00	11/19/2020	
20-10-06122-092	169.6-98	10/24/2020	BASEMENT	7.17	11/19/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-06122

Project/Test Address: 2020L-169.6; Hillview Elementary; 11 Pleasantview Dr; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NY 11714

Reviewed By Authorized Signatory: Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.5 Laboratory Certifications

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER

Expires 12:01 AM April 01, 2021
Issued April 01, 2020

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MS. JULIE DICKERSON
ENVIRONMENTAL HAZARDS SERVICES, LLC
7469 WHITEPINE ROAD
N. CHESTERFIELD, VA 23237

NY Lab Id No: 11714

is hereby APPROVED as an Environmental Laboratory in conformance with the National Environmental Laboratory Accreditation Conference Standards (2003) for the category ENVIRONMENTAL ANALYSES POTABLE WATER
All approved analytes are listed below:

Metals I

Copper, Total	SM 19, 21-23 3113B (-04,-10)
Lead, Total	SM 19, 21-23 3113B (-04,-10)

NEW YORK STATE | Department of Health

Serial No.: 61514

Property of the New York State Department of Health. Certificates are valid only at the address shown, must be conspicuously posted, and are printed on secure paper. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify the laboratory's accreditation status.

NELAP RECOGNIZED TNI ACCREDITATION BODY

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.6 Chains of Custody

20-10-06122

Stohl ENVIRONMEN

3860 California Road, Orchard Park, New Yo
PHONE (716) 312-0070 FAX (716) 312-8
WWW.STOHLENVIRONMENTAL.COI

Due Date:
11/27/2020
(Friday)
AE

# of Custody Document

(Lab Name) EHS

TOHL Job # 2020L-169.6

SI

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Hillview Elementary

Location: 11 Pleasantview Dr Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
1	169.6-1	Kitchen 3 bay Left	Sink	1:55			
2	169.6-2	Kitchen 3 Bay Right	Sink	1:56			
3	169.6-3	Kitchen Lav	Sink	1:57			
4	169.6-4	Kitchen Dish Sprayer	Sink	1:58			
5	169.6-5	Cafeteria Fountain	DFA	1:59			
6	169.6-6	1st Wing Girls Lav Left	Sink	2:00			
7	169.6-7	1st Wing Girls Lav Right	Sink	2:01			
8	169.6-8A	1st Wing Fountain	DFA	2:02			
9	169.6-8B	1st Wing Fountain	DFB	2:03			
10	169.6-9	1st Wing Boys Lav Left	Sink	2:04			
11	169.6-10	1st Wing Boys Lav Right	Sink	2:05			
12	169.6-11	Principals Office Lav	Sink	2:06			
13	169.6-12	Room 1 Main	Sink	2:07			
14	169.6-13	Room 1 Main	Bubbler	2:08			
15	169.6-14	Room 1 Lav	Sink	2:09			
16	169.6-15	Room 8 Main	Sink	2:10			
17	169.6-16	Room 8 Main	Bubbler	2:11			
18	169.6-17	Room 7 Main	Sink	2:12			

Notes:
Please e-mail lab results to labs@stohlenv.com ☑ If checked, also e-mail results to: Ehenderson@StohlEnv.com

Sampled By:	C.Schultz, P.Nichols	Print Name	Stohl Env: C.Schultz, P.Nichols	Date:	10/24/2020
Relinquished By:	E. Henderson	Print Name	Stohl Env: Eric Henderson Jr.	Date:	10/26/2020
Received (Name / Lab):	T. Mohammed		Date: 10/29/20	Time:	5:20p
Sample Login (Name / Lab):	Placi Boom		Date: 11/17/20	Time:	4:29 PM
Analysis (Name / Lab):	A. Hertzler		Date: 11/19/20	Time:	11 am
QA/QC Review (Name / Lab):	Mellid		Date: 11/24/20	Time:	11 AM
Archived / Released:		QA/QC InterLAB Use:	Date:	Time:	

6/22

Chain of Custody Document

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.6

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Hillview Elementary

Location: 11 Pleasantview Dr Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
19	169.6-18	Room 7 Main	Bubbler	2:13			
20	169.6-19	Room 3 Main	Sink	2:14			
21	169.6-20	Room 3 Main	Bubbler	2:15			
22	169.6-21	Room 3 Lav	Sink	2:16			
23	169.6-22	Room 6 Main	Sink	2:17			
24	169.6-23	Room 6 Main	Bubbler	2:18			
25	169.6-24	Room 5 Main	Sink	2:19			
26	169.6-25	Room 5 Main	Bubbler	2:20			
27	169.6-26	Room 5 Lav	Sink	2:21			
28	169.6-27	Room 4 Main	Sink	2:22			
29	169.6-28	Room 4 Main	Bubbler	2:23			
30	169.6-29	Room 4 Lav	Sink	2:24			
31	169.6-30	Room 44 Fac Lav Right	Sink	2:25			
32	169.6-31	Room 44 Fac Lav Left	Sink	2:26			
33	169.6-32	Room 9 Main	Sink	2:27			
34	169.6-33	Room 9 Main	Bubbler	2:28			
35	169.6-34	Room 9 Lav	Sink	2:29			
36	169.6-35	Nurse Main	Sink	2:30			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: E. Henderson Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): T. Ishman Date: 10/29/20 Time: 5:20p

Sample Login (Name / Lab): Traci Blom Date: 11/4/20 Time: 431 PM

Analysis (Name / Lab): G. Hertzler Date: 11/19/20 Time: 11 am

QA/QC Review (Name / Lab): Merrill Date: 11/20/20 Time: noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

6122

Chain of Custody Document

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.6

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Hillview Elementary

Location: 11 Pleasantview Dr Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
37	169.6-36	Nurse Exam	Sink	2:31			
38	169.6-37	Nurse Lav	Sink	2:32			
39	169.6-38	Room 10	Sink	2:33			
40	169.6-39	Room 10	Bubbler	2:34			
41	169.6-40	Room 42 Art Main Left	Sink	2:35			
42	169.6-41	Room 42 Art Main Right	Sink	2:36			
43	169.6-42	Room 42 Art Office Left	Sink	2:37			
44	169.6-43	Room 42 Art Office Right	Sink	2:38			
45	169.6-44	Main Hallway Boys Lav Left	Sink	2:39			
46	169.6-45	Main Hallway Boys Lav Right	Sink	2:40			
47	169.6-46A	Main Hallway Fountain	DFA	2:41			
48	169.6-46B	Main Hallway Fountain	DFB	2:42			
49	169.6-47	2nd Wing Girls Lav Left	Sink	2:43			
50	169.6-48	2nd Wing Girls Lav Center	Sink	2:44			
51	169.6-49	2nd Wing Girls Lav Right	Sink	2:45			
52	169.6-50	Room 16 Main	Sink	2:46			
53	169.6-51	Room 16 Main	Bubbler	2:47			
54	169.6-52	Room 11	Sink	2:48			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): T. Lohmann Date: 10/29/20 Time: 5:29

Sample Login (Name / Lab): Tiara Bloom Date: 11/17/20 Time: 432 PM

Analysis (Name / Lab): J. Hertzler Date: 11/19/20 Time: 11 am

QA/QC Review (Name / Lab): [signature] Date: 11/20/20 Time: noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

6/22

Chain of Custody Document

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.6

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Hillview Elementary

Location: 11 Pleasantview Dr Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
55	169.6-53	Room 11	Bubbler	2:49			
56	169.6-54	Room 15	Sink	2:50			
57	169.6-55	Room 15	Bubbler	2:51			
58	169.6-56	Room 12	Sink	2:52			
59	169.6-57	Room 12	Bubbler	2:53			
60	169.6-58	Room 14	Sink	2:54			
61	169.6-59	Room 14	Bubbler	2:55			
62	169.6-60	Room 13	Sink	2:56			
63	169.6-61	Room 13	Bubbler	2:57			
64	169.6-62A	Gym Hall Fountain	DFA	2:58			
65	169.6-62B	Gym Hall Fountain	DFB	2:59			
66	169.6-63	Girls Locker Coach Office	Sink	3:00			
67	169.6-64	Girls Locker Room	Sink	3:01			
68	169.6-65	Outdoor Lav Girls Side (12)	Sink	3:02			
69	169.6-66	Outdoor Lav Boys Side (9)	Sink	3:03			
70	169.6-67	Boys Gym Office	Sink	3:04			
71	169.6-68	OT Room	Sink	3:05			
72	169.6-69	Fac Lav by Media Center	Sink	3:06			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): T. Mohammed Date: 10/29/20 Time: 5:29

Sample Login (Name / Lab): Staci Boom Date: 11/17/20 Time: 433 PM

Analysis (Name / Lab): J. Hertzler Date: 11/19/20 Time: 11 am

QA/QC Review (Name / Lab): [signature] Date: 11/20/20 Time: NWR

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

6122

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.6

Client: Lancaster CSD Contact: Michael Bryniarski

Building: Hillview Elementary Location: 11 Pleasantview Dr Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
73	169.6-70	Fountain by Media Center	DFA	3:07			
74	169.6-71	Media Center	Sink	3:08			
75	169.6-72	Room 26	Sink	3:09			
76	169.6-74	Room 17	Sink	3:10			
77	169.6-76	Room 25	Sink	3:11			
78	169.6-78	Room 18	Sink	3:12			
79	169.6-80	3rd Wing Girls Lav Left	Sink	3:13			
80	169.6-81	3rd Wing Girls Lav Right	Sink	3:14			
81	169.6-82A	3rd Wing Fountain	DFA	3:15			
82	169.6-82B	3rd Wing Fountain	DFB	3:16			
83	169.6-83	3rd Wing Boys Lav Left	Sink	3:17			
84	169.6-84	3rd Wing Boys Lav center	Sink	3:18			
85	169.6-85	3rd Wing Boys Lav Right	Sink	3:19			
86	169.6-86	Room 24	Sink	3:20			
87	169.6-88	Room 19	Sink	3:21			
88	169.6-90	Room 23	Sink	3:22			
89	169.6-92	Room 20	Sink	3:23			
90	169.6-94	Room 22	Sink	3:24			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): T. Lohman Date: 10/29/20 Time: 5:29

Sample Login (Name / Lab): Traci Blume Date: 11/17/20 Time: 4:34 PM

Analysis (Name / Lab): J. Hertzler Date: 11/19/20 Time: 11 am

QA/QC Review (Name/Lab): [signature] Date: 11/20/20 Time: Noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

6122

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.6

Client: Lancaster CSD Contact: Michael Bryniarski

Building: Hillview Elementary Location: 11 Pleasantview Dr Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
91 169.6-96	Room 21	Sink	3:25			
92 169.6-98	Basement	Sink	3:26			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: E. Henderson Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): T. Lohmann Date: 10/29/20 Time: 5:29p

Sample Login (Name / Lab): Traci Bloom Date: 11/17/20 Time: 4:30 PM

Analysis (Name / Lab): J. Hertzler Date: 11/19/20 Time: 11 am

QA/QC Review (Name / Lab): Melissa Date: 11/20/20 Time: noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

BLANK



3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM