Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

December 15, 2020

Mr. Michael Bryniarski
Director of Facilities
Lancaster Central School District
177 Central Avenue
Lancaster, NY 14086

RE: Investigation and Sampling of Drinking Water for Lead Concentrations

Dear Mr. Bryniarski:

Included with this letter is Stohl Environmental LLC's report for the Water Sampling performed at the educational buildings of the Lancaster Central School District, including:

- John A. Sciole Elementary – 86 Alys Drive, Lancaster, New York.

This report is prepared to assist the District in complying with the requirements of NYS regulations, *SUBPART 67-4: Lead Testing in School Drinking Water*, by identifying the sources of potable water with lead concentrations greater than the NYS "Action Level of 15 parts per billion (ppb)".

The Investigation and Sampling was performed on October 24, 2020. The Protocol for the Investigation followed the requirements of NYS regulations as well as USEPA Technical Guidance Document "3-T's for Reducing Lead in Drinking Water in Schools".

As detailed in Section 1.2 *(Executive Summary)* of the accompanying report, based upon the sampling and analysis performed, 3 source of potable water in John A. Sciole Elementary has been identified as having a lead concentration in water above the NYS Action Level of 15 parts per billion. To comply with NYS regulations, Response actions as identified in this report by the District are required.

Thank you for the opportunity to be of service to Lancaster Central School District.

Sincerely,
Stohl Environmental, LLC.

Eric Henderson Jr.
Senior Project Manager

Investigation and Sampling Of Sources of Potable Water For Lead Concentrations

Prepared for:

Lancaster Central School District

Prepared by:

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Conditions as of October 24, 2020

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

Summary Tabulation

Lead in Drinking Water Investigation

1.1. Scope of Work and Sampling Protocol

1.2. Executive Summary of Sampling and Analysis

1.3. Response Actions Required Under NYS Regulations

1.4. Laboratory Analytical Reports by Building

1.5. Laboratory Certifications

1.6. Chains of Custody

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.1 Scope of Work and Sampling Protocol:

Stohl Environmental was retained by Lancaster Central School District to perform sampling and analysis of potable water for elevated lead concentrations. Sampling was performed in the following buildings:

- John A. Sciole Elementary – 86 Alys Drive, Lancaster, New York.

Scope of Work:

Stohl Environmental was charged with collecting first-draw water samples from outlets within John A. Sciole Elementary. Outlets are defined in NYS regulations as: "a potable water fixture currently or potentially used for drinking or cooking purposes, including but not limited to a bubbler, drinking fountain, or faucets".

Sampling Protocol:

In accordance with NYS regulations, ***Subpart 67-4: Lead Testing in School Drinking Water***, and the EPA guidance document, ***'3Ts for Reducing Lead in Drinking Water in Schools"***, Stohl Environmental's protocol can be summarized as follows:

- **First-draw samples** of 250 milliliters (mL) were collected from cold water outlets before any water was used. Sampling was coordinated with District representatives to assure that water was motionless in the pipes for a minimum of 8 hours, but not more than 18 hours before sample collection.

- **Laboratory Analysis:** Samples were submitted following strict chain-of-custody protocols to an independent laboratory approved by the NYS Department of Health's Environmental Laboratory Approval Program (ELAP).

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.2 Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Confirmatory Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb
John A. Sciole Elementary	10/24/2020	68	65	3	N/A	N/A

****** Confirmatory samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Listing of Outlets Requiring Remediation

Locations of Outlets Analyzed above the NYS Action Level of 15 parts per billion based upon Analysis of First Draw Samples:

Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb
169.7-2	Room 1	Sink	23.0
169.7-25	Faculty Lav Left	Sink	N/A
169.7-32	Room 18	Sink	N/A
169.7-57	Outdoor Restroom	Sink	17.2
169.7-61	Kitchen Pan Fill	Sink	25.7

N/A = Not Analyzed. The laboratory received the sample empty and was not able to be analyzed. Location should be resampled and analyzed at a later date.

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.3 Response Actions Required Under NYS Regulations, Section 67-4.4:

For outlets analyzed with a lead concentration in excess of the NYS Action Level, regulations require:

(a) Prohibit use of the outlet until:

(1) a lead remediation plan is implemented to mitigate the lead level of such outlet; and

(2) test results indicate that the lead levels are at or below the action level;

(b) provide building occupants with an adequate supply of potable water for drinking and cooking until remediation is performed;

(c) report the test results to the local health department as soon as practicable, but no more than 1 business day after the school received the laboratory report; and

(d) notify all staff and all persons in parental relation to students of the test results, in writing, as soon as practicable but no more than 10 business days after the school received the laboratory report.

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.4 Laboratory Analytical Reports by Building

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 20-10-06130

Client: Stohl Environmental
3860 California Road
Orchard Park, NY 14127

Received Date: 10/29/2020
Reported Date: 11/24/2020
Sampled By: C Schultz/P Nichols
Tech Certification #:

Project/Test Address: 2020L-169.7; John A Sciole Elementary; 86 Alys Dr; Depew, NY 14043

Client Number: 33-5980

Laboratory Results

Fax Number: 716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06130-001	169.7-1	10/24/2020	ROOM 2	<1.00	11/20/2020	
20-10-06130-002	169.7-2	10/24/2020	ROOM 1	23.0	11/20/2020	
20-10-06130-003	169.7-3	10/24/2020	ROOM 4	4.27	11/20/2020	
20-10-06130-004	169.7-4	10/24/2020	ROOM 3	9.10	11/20/2020	
20-10-06130-005	169.7-5	10/24/2020	ROOM 6	8.81	11/20/2020	
20-10-06130-006	169.7-6	10/24/2020	ROOM 5	3.99	11/20/2020	
20-10-06130-007	169.7-7	10/24/2020	ROOM 8	4.45	11/20/2020	
20-10-06130-008	169.7-8	10/24/2020	ROOM 7	6.16	11/20/2020	
20-10-06130-009	169.7-9	10/24/2020	ROOM 10	5.75	11/20/2020	
20-10-06130-010	169.7-10	10/24/2020	ROOM 9	7.43	11/20/2020	
20-10-06130-011	169.7-11	10/24/2020	ROOM 12	3.29	11/20/2020	
20-10-06130-012	169.7-12	10/24/2020	ROOM 11	5.80	11/23/2020	
20-10-06130-013	169.7-13	10/24/2020	3 GRADE GIRLS LAV LEFT	2.45	11/23/2020	

Client Number: 33-5980 Report Number: 20-10-06130

Project/Test Address: 2020L-169.7; John A Sciole Elementary; 86 Alys Dr; Depew, NY 14043

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06130-014	169.7-14	10/24/2020	3 GRADE GIRLS LAV LEFT CENTER	3.71	11/23/2020	
20-10-06130-015	169.7-15	10/24/2020	3 GRADE GIRL LAV RIGHT CENTER	6.41	11/23/2020	
20-10-06130-016	169.7-16	10/24/2020	3 GRADE GIRLS LAV RIGHT	1.11	11/23/2020	
20-10-06130-017	169.7-17A	10/24/2020	3RD GRADE HALL FOUNTAIN	<1.00	11/23/2020	
20-10-06130-018	169.7-17B	10/24/2020	3RD GRADE HALL FOUNTAIN	<1.00	11/23/2020	
20-10-06130-019	169.7-18	10/24/2020	3 GRADE BOY LAV LEFT	1.93	11/23/2020	
20-10-06130-020	169.7-19	10/24/2020	3 GRADE BOY LAV LEFT CENTER	2.39	11/23/2020	
20-10-06130-021	169.7-20	10/24/2020	3 GRADE BOY LAV RIGHT CENTER	3.34	11/23/2020	
20-10-06130-022	169.7-21	10/24/2020	3 GRADE BOY LAV RIGHT	1.16	11/23/2020	
20-10-06130-023	169.7-22	10/24/2020	ROOM 25	3.22	11/23/2020	
20-10-06130-024	169.7-23	10/24/2020	ROOM 26	2.50	11/23/2020	
20-10-06130-025	169.7-24	10/24/2020	LIBRARY MEDIA CENTER	2.16	11/23/2020	
20-10-06130-026	169.7-26	10/24/2020	FAC LAV RIGHT	3.89	11/23/2020	
20-10-06130-027	169.7-27A	10/24/2020	K1 WING FOUNTAIN	<1.00	11/23/2020	
20-10-06130-028	169.7-27B	10/24/2020	K1 WING FOUNTAIN	<1.00	11/23/2020	
20-10-06130-029	169.7-28	10/24/2020	ROOM 14	<1.00	11/23/2020	
20-10-06130-030	169.7-29	10/24/2020	ROOM 13	2.84	11/23/2020	
20-10-06130-031	169.7-30	10/24/2020	ROOM 16	1.33	11/23/2020	
20-10-06130-032	169.7-31	10/24/2020	ROOM 15	2.59	11/23/2020	
20-10-06130-033	169.7-33	10/24/2020	ROOM 19	1.41	11/23/2020	

Client Number: 33-5980 Report Number: 20-10-06130

Project/Test Address: 2020L-169.7; John A Sciole Elementary; 86 Alys Dr; Depew, NY 14043

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06130-034	169.7-34	10/24/2020	ROOM 20	2.92	11/23/2020	
20-10-06130-035	169.7-35	10/24/2020	ROOM 19	4.58	11/23/2020	
20-10-06130-036	169.7-36	10/24/2020	ROOM 22	4.26	11/23/2020	
20-10-06130-037	169.7-37	10/24/2020	ROOM 21	1.39	11/23/2020	
20-10-06130-038	169.7-38	10/24/2020	ROOM 24	8.56	11/23/2020	
20-10-06130-039	169.7-39	10/24/2020	ROOM 23	3.97	11/23/2020	
20-10-06130-040	169.7-40	10/24/2020	ART ROOM FRONT LEFT	9.45	11/23/2020	
20-10-06130-041	169.7-41	10/24/2020	ART ROOM FRONT CENTER	3.29	11/23/2020	
20-10-06130-042	169.7-42	10/24/2020	ART ROOM FRONT RIGHT	1.27	11/23/2020	
20-10-06130-043	169.7-43	10/24/2020	ART ROOM REAR LEFT	1.06	11/23/2020	
20-10-06130-044	169.7-44	10/24/2020	ART ROOM REAR CENTER	1.74	11/23/2020	
20-10-06130-045	169.7-45	10/24/2020	ART ROOM REAR RIGHT	4.70	11/23/2020	
20-10-06130-046	169.7-46	10/24/2020	WOMENS LAV BY MAIN OFFICE	4.65	11/23/2020	
20-10-06130-047	169.7-47	10/24/2020	NURSE 138 MAIN LEFT	<1.00	11/23/2020	
20-10-06130-048	169.7-48	10/24/2020	NURSE 138 MAIN LEFT	<1.00	11/23/2020	
20-10-06130-049	169.7-49	10/24/2020	NURSE 138 MAIN RIGHT	<1.00	11/23/2020	
20-10-06130-050	169.7-50	10/24/2020	NURSE 138 EXAM ROOM	<1.00	11/23/2020	
20-10-06130-051	169.7-51	10/24/2020	NURSE 138 LAV	<1.00	11/23/2020	
20-10-06130-052	169.7-52	10/24/2020	BOYS LAV BY NURSE	1.02	11/23/2020	
20-10-06130-053	169.7-53	10/24/2020	OT/PT ROOM	3.47	11/23/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-06130

Project/Test Address: 2020L-169.7; John A Sciole Elementary; 86 Alys Dr; Depew, NY 14043

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06130-054	169.7-54	10/24/2020	MENS PHYS ED OFFICE	8.13	11/23/2020	
20-10-06130-055	169.7-55	10/24/2020	ENL ROOM	4.41	11/23/2020	
20-10-06130-056	169.7-56	10/24/2020	WOMENS PHYS ED OFFICE	3.57	11/23/2020	
20-10-06130-057	169.7-57	10/24/2020	OUTDOOR RESTROOM	17.2	11/23/2020	
20-10-06130-058	169.7-58	10/24/2020	CUSTODIANS OFFICE	6.33	11/23/2020	
20-10-06130-059	169.7-59	10/24/2020	KITCHEN HANDWASH	8.52	11/23/2020	
20-10-06130-060	169.7-60	10/24/2020	KITCHEN PREP TABLE SINGLE BAY	9.06	11/23/2020	
20-10-06130-061	169.7-61	10/24/2020	KITCHEN PAN FILL	25.7	11/23/2020	
20-10-06130-062	169.7-62	10/24/2020	KITCHEN 3 BAY LEFT SINK	13.2	11/23/2020	
20-10-06130-063	169.7-63	10/24/2020	KITCHEN 3 BAY RIGHT	3.19	11/23/2020	
20-10-06130-064	169.7-64	10/24/2020	KITCHEN 2 BAY	<1.00	11/23/2020	
20-10-06130-065	169.7-65	10/24/2020	KITCHEN DISH SPRAYER	3.07	11/23/2020	
20-10-06130-066	169.7-66	10/24/2020	KITCHEN LAV	3.09	11/23/2020	
20-10-06130-067	169.7-67A	10/24/2020	CAFETERIA	<1.00	11/23/2020	
20-10-06130-068	169.7-67B	10/24/2020	CAFETERIA	<1.00	11/23/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-06130

Project/Test Address: 2020L-169.7; John A Sciole Elementary; 86 Alys Dr; Depew, NY 14043

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NY 11714

Reviewed By Authorized Signatory: Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.5 Laboratory Certifications

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER

Expires 12:01 AM April 01, 2021
Issued April 01, 2020

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MS. JULIE DICKERSON
ENVIRONMENTAL HAZARDS SERVICES, LLC
7469 WHITEPINE ROAD
N. CHESTERFIELD, VA 23237

NY Lab Id No: 11714

is hereby APPROVED as an Environmental Laboratory in conformance with the National Environmental Laboratory Accreditation Conference Standards (2003) for the category ENVIRONMENTAL ANALYSES POTABLE WATER
All approved analytes are listed below:

Metals I

Copper, Total	SM 19, 21-23 3113B (-04,-10)
Lead, Total	SM 19, 21-23 3113B (-04,-10)

NEW YORK STATE | Department of Health

Serial No.: 61514

Property of the New York State Department of Health. Certificates are valid only at the address shown, must be conspicuously posted, and are printed on secure paper. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify the laboratory's accreditation status.

NELAP RECOGNIZED TNI ACCREDITATION BODY

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.6 Chains of Custody

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.7

Client: Lancaster CSD Contact: Michael Bryniarski

Building: John A Sciole Elementary Location: 86 Alys Dr Depew, NY 14043

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
1	169.7-1	Room 2	Sink	12:35			
2	169.7-2	Room 1	Sink	12:36			
3	169.7-3	Room 4	Sink	12:37			
4	169.7-4	Room 3	Sink	12:38			
5	169.7-5	Room 6	Sink	12:39			
6	169.7-6	Room 5	Sink	12:40			
7	169.7-7	Room 8	Sink	12:41			
8	169.7-8	Room 7	Sink	12:42			
9	169.7-9	Room 10	Sink'	12:43			
10	169.7-10	Room 9	Sink	12:44			
11	169.7-11	Room 12	Sink	12:45			
12	169.7-12	Room 11	Sink	12:46			
13	169.7-13	3 Grade Girls Lav Left	Sink	12:47			
14	169.7-14	3 Grade Girls Lav Left Center	Sink	12:48			
15	169.7-15	3 Grade Girl Lav Right Center	Sink	12:49			
16	169.7-16	3 Grade Girls Lav Right	Sink	12:50			
17	169.7-17A	3rd Grade Hall Fountain	DFA	12:51			
18	169.7-17B	3rd Grade Hall Fountain	DFB	12:52			

20-10-06130

Due Date:
11/27/2020
(Friday)
AE

TM

Notes:
Please e-mail lab results to labs@stohlenv.com ☑ If checked, also e-mail results to: Ehenderson@StohlEnv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): Stone Stone Date: 10/29/20 Time: 6:40 pm

Sample Login (Name / Lab): T. Wohlgemuth Date: 11/17/20 Time: 5:30

Analysis (Name / Lab): J. Hertzler Date: 11/23/20 Time: 3:35 pm

QA/QC Review (Name / Lab): [signature] Date: 11/24/20 Time: 1pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

6/30

Chain of Custody Document

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.7

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: John A Sciole Elementary

Location: 86 Alys Dr Depew, NY 14043

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
19	169.7-18	3 Grade Boy Lav Left	Sink	12:53			
20	169.7-19	3 Grade Boy Lav Left Center	Sink	12:54			
21	169.7-20	3 Grade Boy Lav Right Center	Sink	12:55			
22	169.7-21	3 Grade Boy Lav Right	Sink	12:56			
23	169.7-22	Room 25	Sink	12:57			
24	169.7-23	Room 26	Sink	12:58			
25	169.7-24	Library Media Center	Sink	12:59			
	* 169.7-25	Fac Lav Left	sink	13:00	sample rcvd empty	LAD 10/30/2020	
26	169.7-26	Fac Lav Right	Sink	13:01			
27	169.7-27A	K1 Wing Fountain	DFA	13:02			
28	169.7-27B	K1 Wing Fountain	DFB	13:03			
29	169.7-28	Room 14	Sink	13:04			
30	169.7-29	Room 13	Sink	13:05			
31	169.7-30	Room 16	Sink	13:06			
32	169.7-31	Room 15	Sink	13:07			
	* 169.7-32	Room 18	Sink	13:08	Sample rcvd empty	LAD 10/30/2020	
33	169.7-33	Room 19	Sink	13:09			
34	169.7-34	Room 20	Sink	13:10			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): [signature] Date: 10/29/20 Time: 6:40pm

Sample Login (Name / Lab): [signature] Date: 11/17/20 Time: 5:30

Analysis (Name / Lab): [signature] Date: 11/23/20 Time: 3:35 pm

QA/QC Review (Name / Lab): [signature] Date: 11/24/20 Time: 1pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

6130

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.7

Client: Lancaster CSD Contact: Michael Bryniarski

Building: John A Sciole Elementary Location: 86 Alys Dr Depew, NY 14043

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
35	169.7-35	Room 19	Sink	13:11			
36	169.7-36	Room 22	Sink	13:12			
37	169.7-37	Room 21	Sink	13:13			
38	169.7-38	Room 24	Sink	13:14			
39	169.7-39	Room 23	Sink	13:15			
40	169.7-40	Art Room Front Left	Sink	13:16			
41	169.7-41	Art Room Front Center	Sink	13:17			
42	169.7-42	Art Room Front Right	Sink	13:18			
43	169.7-43	Art Room Rear Left	Sink	13:19			
44	169.7-44	Art Room Rear Center	Sink	13:20			
45	169.7-45	Art Room Rear Right	Sink	13:21			
46	169.7-46	Womens Lav by Main Office	Sink	13:22			
47	169.7-47	Nurse 138 Main Left	Sink	13:23			
48	169.7-48	Nurse 138 Main Left	Bubber	13:24			
49	169.7-49	Nurse 138 Main Right	Sink	13:25			
50	169.7-50	Nurse 138 Exam Room	Sink	13:26			
51	169.7-51	Nurse 138 Lav	Sink	13:27			
52	169.7-52	Boys Lav by Nurse	Sink	13:28			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: E. Henderson Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): Stone, STONE Date: 10/29/20 Time: 6:40pm

Sample Login (Name / Lab): T. Mohammad Date: 11/17/20 Time: 5:30

Analysis (Name / Lab): J. Hertzler Date: 11/23/20 Time: 3:35 pm

QA/QC Review (Name / Lab): M. Mehlenbacher Date: 11/24/20 Time: 1pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

6/30

Chain of Custody Document

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.7

Client: Lancaster CSD Contact: Michael Bryniarski

Building: John A Sciole Elementary Location: 86 Alys Dr Depew, NY 14043

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
53	169.7-53	OT/PT Room	Sink	13:29			
54	169.7-54	Mens Phys Ed Office	Sink	13:30			
55	169.7-55	ENL Room	Sink	13:31			
56	169.7-56	Womens Phys Ed Office	Sink	13:32			
57	169.7-57	Outdoor Restroom	Sink	13:33			
58	169.7-58	Custodian's Office	Sink	13:34			
59	169.7-59	Kitchen Handwash	Sink	13:35			
60	169.7-60	Kitchen Prep Table Single Bay	Sink	13:36			
61	169.7-61	Kitchen Pan Fill	Sink	13:37			
62	169.7-62	Kitchen 3 Bay Left Sink	Sink	13:38			
63	169.7-63	Kitchen 3 Bay Right	Sink	13:39			
64	169.7-64	Kitchen 2 Bay	Sink	13:40			
65	169.7-65	Kitchen Dish Sprayer	Sink	13:41			
66	169.7-66	Kitchen Lav	Sink	13:42			
67	169.7-67A	Cafeteria	DFA	13:43			
68	169.7-67B	Cafeteria	DFB	13:44			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): TStone / Stohl Date: 10/29/20 Time: 6:40 pm

Sample Login (Name / Lab): T.Schaaf Date: 11/17/20 Time: 5:30p

Analysis (Name / Lab): J. Hartzler Date: 11/23/20 Time: 3:35 pm

QA/QC Review (Name / Lab): Metrosol Date: 11/24/20 Time: 1pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM