Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

December 15, 2020

Mr. Michael Bryniarski
Director of Facilities
Lancaster Central School District
177 Central Avenue
Lancaster, NY 14086

RE: Investigation and Sampling of Drinking Water for Lead Concentrations

Dear Mr. Bryniarski:

Included with this letter is Stohl Environmental LLC's report for the Water Sampling performed at the educational buildings of the Lancaster Central School District, including:

- William Street School – 5201 William Street, Lancaster, New York.

This report is prepared to assist the District in complying with the requirements of NYS regulations, *SUBPART 67-4: Lead Testing in School Drinking Water*, by identifying the sources of potable water with lead concentrations greater than the NYS "Action Level of 15 parts per billion (ppb)".

The Investigation and Sampling was performed on October 24, 2020. The Protocol for the Investigation followed the requirements of NYS regulations as well as USEPA Technical Guidance Document "3-T's for Reducing Lead in Drinking Water in Schools".

As detailed in Section 1.2 *(Executive Summary)* of the accompanying report, based upon the sampling and analysis performed, 6 source of potable water in William Street School has been identified as having a lead concentration in water above the NYS Action Level of 15 parts per billion. To comply with NYS regulations, Response actions as identified in this report by the District are required.

Thank you for the opportunity to be of service to Lancaster Central School District.

Sincerely,
Stohl Environmental, LLC.

Eric Henderson Jr.
Senior Project Manager

Investigation and Sampling Of Sources of Potable Water For Lead Concentrations

Prepared for:

Lancaster Central School District

Prepared by:

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Conditions as of October 24, 2020

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

Summary Tabulation

Lead in Drinking Water Investigation

1.1. Scope of Work and Sampling Protocol

1.2. Executive Summary of Sampling and Analysis

1.3. Response Actions Required Under NYS Regulations

1.4. Laboratory Analytical Reports by Building

1.5. Laboratory Certifications

1.6. Chains of Custody

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.1 Scope of Work and Sampling Protocol:

Stohl Environmental was retained by Lancaster Central School District to perform sampling and analysis of potable water for elevated lead concentrations. Sampling was performed in the following buildings:

- William Street School – 5201 William Street, Lancaster, New York.

Scope of Work:

Stohl Environmental was charged with collecting first-draw water samples from outlets within William Street School. Outlets are defined in NYS regulations as: "a potable water fixture currently or potentially used for drinking or cooking purposes, including but not limited to a bubbler, drinking fountain, or faucets".

Sampling Protocol:

In accordance with NYS regulations, ***Subpart 67-4: Lead Testing in School Drinking Water***, and the EPA guidance document, ***'3Ts for Reducing Lead in Drinking Water in Schools"***, Stohl Environmental's protocol can be summarized as follows:

- **First-draw samples** of 250 milliliters (mL) were collected from cold water outlets before any water was used. Sampling was coordinated with District representatives to assure that water was motionless in the pipes for a minimum of 8 hours, but not more than 18 hours before sample collection.

- **Laboratory Analysis:** Samples were submitted following strict chain-of-custody protocols to an independent laboratory approved by the NYS Department of Health's Environmental Laboratory Approval Program (ELAP).

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.2 Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Confirmatory Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb
William Street School	10/17/2020	214	208	6	N/A	N/A

****** Confirmatory samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Listing of Outlets Requiring Remediation

Locations of Outlets Analyzed above the NYS Action Level of 15 parts per billion based upon Analysis of First Draw Samples:

Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb
169.3-16	Serving Hand Wash	Sink	22.8
169.3-35	B106 Sprayer	Sink	16.8
169.3-43	B112 Band Lesson	Sink	28.3
169.3-123	B206 Sprayer	Sink	66.4
169.3-127	B204 Front	Sink	121
169.3-150	B218	Sink	N/A
169.3-187	D232 Sprayer	Sink	18.6

N/A = Not Analyzed. The laboratory received the sample empty and was not able to be analyzed. Location should be resampled and analyzed at a later date.

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.3 Response Actions Required Under NYS Regulations, Section 67-4.4:

For outlets analyzed with a lead concentration in excess of the NYS Action Level, regulations require:

(a) Prohibit use of the outlet until:

(1) a lead remediation plan is implemented to mitigate the lead level of such outlet; and

(2) test results indicate that the lead levels are at or below the action level;

(b) provide building occupants with an adequate supply of potable water for drinking and cooking until remediation is performed;

(c) report the test results to the local health department as soon as practicable, but no more than 1 business day after the school received the laboratory report; and

(d) notify all staff and all persons in parental relation to students of the test results, in writing, as soon as practicable but no more than 10 business days after the school received the laboratory report.

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.4 Laboratory Analytical Reports by Building

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 20-10-06128

Client: Stohl Environmental
3860 California Road
Orchard Park, NY 14127

Received Date: 10/29/2020
Reported Date: 11/24/2020
Sampled By: C Schultz/P Nichols
Tech Certification #:

Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Client Number: 33-5980

Laboratory Results

Fax Number: 716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-001	169.3-1	10/24/2020	LOADING DOCK LEFT LAV	<1.00	11/19/2020	
20-10-06128-002	169.3-2	10/24/2020	LOADING DOCK RIGHT LAV	<1.00	11/19/2020	
20-10-06128-003	169.3-3	10/24/2020	KITCHEN HANDWASH BY FREEZERS	1.97	11/19/2020	
20-10-06128-004	169.3-4	10/24/2020	KITCHEN 2 BAY	<1.00	11/19/2020	
20-10-06128-005	169.3-5	10/24/2020	KITCHEN SINGLE BAY	1.41	11/19/2020	
20-10-06128-006	169.3-6	10/24/2020	KITCHEN HANDWASH CORNER	9.18	11/19/2020	
20-10-06128-007	169.3-7	10/24/2020	KITCHEN DISH SPRAYER	<1.00	11/19/2020	
20-10-06128-008	169.3-8	10/24/2020	KITCHEN DISH SINGLE BAY	2.24	11/19/2020	
20-10-06128-009	169.3-9	10/24/2020	KITCHEN DISH 2 BAY	<1.00	11/19/2020	
20-10-06128-010	169.3-10	10/24/2020	KITCHEN KETTLE	7.81	11/19/2020	
20-10-06128-011	169.3-11	10/24/2020	KITCHEN SINGLE BY COFFEE	5.57	11/19/2020	
20-10-06128-012	169.3-12	10/24/2020	DISHWASHER LEFT	<1.00	11/19/2020	
20-10-06128-013	169.3-13	10/24/2020	DISHWASHER RIGHT	1.40	11/19/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-06128

Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-014	169.3-14	10/24/2020	DISH SRAYER BY CAFE	2.90	11/19/2020	
20-10-06128-015	169.3-15	10/24/2020	DISH ROOM HANDWASH	3.01	11/19/2020	
20-10-06128-016	169.3-16	10/24/2020	SERVING HANDWASH	22.8	11/19/2020	
20-10-06128-017	169.3-17	10/24/2020	SERVING HANDWASH BY FRIDGES	2.26	11/19/2020	
20-10-06128-018	169.3-18	10/24/2020	HANDWASH BY STOVE	12.7	11/19/2020	
20-10-06128-019	169.3-19	10/24/2020	HANDWASH BY OFFICE	1.50	11/19/2020	
20-10-06128-020	169.3-20	10/24/2020	KITCHEN ICE MACHINE	<1.00	11/19/2020	
20-10-06128-021	169.3-21A	10/24/2020	CAFETERIA	<1.00	11/19/2020	
20-10-06128-022	169.3-21B	10/24/2020	CAFETERIA	<1.00	11/19/2020	
20-10-06128-023	169.3-22	10/24/2020	GIRLS LAV B1 LEFT	<1.00	11/19/2020	
20-10-06128-024	169.3-23	10/24/2020	GIRLS LAV B1 CENTER	<1.00	11/19/2020	
20-10-06128-025	169.3-24	10/24/2020	GIRLS LAV B1 RIGHT	<1.00	11/19/2020	
20-10-06128-026	169.3-25	10/24/2020	BOYS LAV B1 LEFT	<1.00	11/19/2020	
20-10-06128-027	169.3-26	10/24/2020	BOYS LAV B1 CENTER	<1.00	11/19/2020	
20-10-06128-028	169.3-27	10/24/2020	BOYS LAV B1 RIGHT	<1.00	11/19/2020	
20-10-06128-029	169.3-28A	10/24/2020	B1 FOUNTAIN	<1.00	11/19/2020	
20-10-06128-030	169.3-28B	10/24/2020	B1 FOUNTAIN	<1.00	11/19/2020	
20-10-06128-031	169.3-29	10/24/2020	B109	<1.00	11/19/2020	
20-10-06128-032	169.3-30	10/24/2020	B108	<1.00	11/20/2020	
20-10-06128-033	169.3-31	10/24/2020	B107	<1.00	11/20/2020	

Client Number: 33-5980 Report Number: 20-10-06128
Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-034	169.3-32A	10/24/2020	B COMMON FOUNTAIN	<1.00	11/20/2020	
20-10-06128-035	169.3-32B	10/24/2020	B COMMON FOUNTAIN	<1.00	11/20/2020	
20-10-06128-036	169.3-33	10/24/2020	B106 FRONT	4.17	11/20/2020	
20-10-06128-037	169.3-34	10/24/2020	B106 REAR	<1.00	11/20/2020	
20-10-06128-038	169.3-35	10/24/2020	B106 SPRAYER	16.8	11/13/2020	
20-10-06128-039	169.3-36	10/24/2020	LEFT LAV OUTSIDE B105	<1.00	11/20/2020	
20-10-06128-040	169.3-37	10/24/2020	B105 FAC	<1.00	11/20/2020	
20-10-06128-041	169.3-38	10/24/2020	RIGHT LAV OUTSIDE B105	<1.00	11/20/2020	
20-10-06128-042	169.3-39	10/24/2020	B104	<1.00	11/20/2020	
20-10-06128-043	169.3-40	10/24/2020	B103	6.28	11/20/2020	
20-10-06128-044	169.3-41	10/24/2020	B102	<1.00	11/20/2020	
20-10-06128-045	169.3-42	10/24/2020	B101	<1.00	11/20/2020	
20-10-06128-046	169.3-43	10/24/2020	B112 BAND LESSON	28.3	11/20/2020	
20-10-06128-047	169.3-44	10/24/2020	B113 LIBRARY CLASSROOM	<1.00	11/20/2020	
20-10-06128-048	169.3-45	10/24/2020	D117 MAIN OFFICE KIT	<1.00	11/20/2020	
20-10-06128-049	169.3-46	10/24/2020	D117 MAIN OFFICE LAV	<1.00	11/20/2020	
20-10-06128-050	169.3-47	10/24/2020	C132 CHORUS	<1.00	11/20/2020	
20-10-06128-051	169.3-48	10/24/2020	C133 SINK	<1.00	11/20/2020	
20-10-06128-052	169.3-49	10/24/2020	C133 FOUNTAIN	<1.00	11/20/2020	
20-10-06128-053	169.3-50	10/24/2020	C1 WOMENS FAC LAV	<1.00	11/20/2020	

Client Number: 33-5980 Report Number: 20-10-06128

Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-054	169.3-51	10/24/2020	C1 MENS FAC LAV	<1.00	11/20/2020	
20-10-06128-055	169.3-52	10/24/2020	C1 GIRLS GANG LEFT	<1.00	11/20/2020	
20-10-06128-056	169.3-53	10/24/2020	C1 GIRLS GANG LEFT CENTER	<1.00	11/20/2020	
20-10-06128-057	169.3-54	10/24/2020	C1 GIRLS GANG RIGHT CENTER	<1.00	11/20/2020	
20-10-06128-058	169.3-56	10/24/2020	C1 BOYS GANG LEFT	<1.00	11/20/2020	
20-10-06128-059	169.3-57	10/24/2020	C1 BOYS GANG LEFT CENTER	<1.00	11/20/2020	
20-10-06128-060	169.3-58	10/24/2020	C1 BOYS GANG R CENTER	<1.00	11/20/2020	
20-10-06128-061	169.3-59	10/24/2020	C1 BOYS GANG RIGHT	<1.00	11/20/2020	
20-10-06128-062	169.3-60	10/24/2020	C1 BOYS SIDE FOUNTAIN LEFT	<1.00	11/20/2020	
20-10-06128-063	169.3-61	10/24/2020	C1 BOYS SIDE FOUNTAIN RIGHT	<1.00	11/20/2020	
20-10-06128-064	169.3-62	10/24/2020	C1 GIRLS SIDE FOUNTAIN LEFT	<1.00	11/20/2020	
20-10-06128-065	169.3-63	10/24/2020	C1 GIRLS SIDE FOUNTAIN RIGHT	<1.00	11/20/2020	
20-10-06128-066	169.3-64	10/24/2020	C146	6.25	11/20/2020	
20-10-06128-067	169.3-65	10/24/2020	C145	2.16	11/20/2020	
20-10-06128-068	169.3-66	10/24/2020	C144	1.98	11/20/2020	
20-10-06128-069	169.3-67	10/24/2020	C143	2.34	11/20/2020	
20-10-06128-070	169.3-68	10/24/2020	C142	1.48	11/20/2020	
20-10-06128-071	169.3-69	10/24/2020	C141	1.18	11/20/2020	
20-10-06128-072	169.3-70	10/24/2020	C139	2.84	11/20/2020	
20-10-06128-073	169.3-71	10/24/2020	C138	3.29	11/20/2020	

Client Number: 33-5980 Report Number: 20-10-06128

Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-074	169.3-72	10/24/2020	C137	2.35	11/20/2020	
20-10-06128-075	169.3-73	10/24/2020	C136	1.39	11/20/2020	
20-10-06128-076	169.3-74	10/24/2020	C135	2.44	11/20/2020	
20-10-06128-077	169.3-75	10/24/2020	C134	3.61	11/20/2020	
20-10-06128-078	169.3-76	10/24/2020	D118 NURSE MAIN	<1.00	11/20/2020	
20-10-06128-079	169.3-77	10/24/2020	D118 NURSE EXAM	<1.00	11/20/2020	
20-10-06128-080	169.3-78	10/24/2020	D118 NURSE LAV	<1.00	11/20/2020	
20-10-06128-081	169.3-79	10/24/2020	GIRLS POOL LOCKER RM LEFT	2.34	11/20/2020	
20-10-06128-082	169.3-80	10/24/2020	GIRLS POOL LOCKER RM CENTER	1.67	11/20/2020	
20-10-06128-083	169.3-81	10/24/2020	GIRLS POOL LOCKER RM RIGHT	1.75	11/20/2020	
20-10-06128-084	169.3-82	10/24/2020	BOYS POOL LOCKER RM LEFT	1.01	11/20/2020	
20-10-06128-085	169.3-83	10/24/2020	BOYS POOL LOCKER RM CENTER	<1.00	11/20/2020	
20-10-06128-086	169.3-84	10/24/2020	BOYS POOL LOCKER RM RIGHT	<1.00	11/20/2020	
20-10-06128-087	169.3-85	10/24/2020	NEW GYM GIRL SIDE FNTN LEFT	<1.00	11/20/2020	
20-10-06128-088	169.3-86	10/24/2020	NEW GYM GIRL SIDE FNTN RIGHT	<1.00	11/20/2020	
20-10-06128-089	169.3-87	10/24/2020	NEW GYM BOY SIDE FNTN LEFT	<1.00	11/20/2020	
20-10-06128-090	169.3-88	10/24/2020	NEW GYM BOY SIDE FNTN RIGHT	<1.00	11/20/2020	
20-10-06128-091	169.3-90	10/24/2020	OLD GYM BOYS LOCKER CENTER	<1.00	11/20/2020	
20-10-06128-092	169.3-91	10/24/2020	OLD GYM BOYS LOCKER RIGHT	<1.00	11/20/2020	
20-10-06128-093	169.3-92	10/24/2020	OLD GYM BOYS COACH OFFICE	<1.00	11/20/2020	

Client Number: 33-5980 Report Number: 20-10-06128
Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-094	169.3-93	10/24/2020	OLD GYM GIRLS LOCKER LFET	<1.00	11/20/2020	
20-10-06128-095	169.3-94	10/24/2020	OLD GYM GIRLS LOCKER CENTER	<1.00	11/20/2020	
20-10-06128-096	169.3-95	10/24/2020	OLD GYM GIRLS LOCKER RIGHT	<1.00	11/20/2020	
20-10-06128-097	169.3-96	10/24/2020	OLD GYM GIRLS COACH OFFICE	<1.00	11/20/2020	
20-10-06128-098	169.3-97A	10/24/2020	OLD GYM GIRLS SIDE FOUNTAIN	<1.00	11/20/2020	
20-10-06128-099	169.3-97B	10/24/2020	OLD GYM GIRLS SIDE FOUNTAIN	<1.00	11/20/2020	
20-10-06128-100	169.3-98	10/24/2020	D BOYS GANG LEFT	<1.00	11/20/2020	
20-10-06128-101	169.3-99	10/24/2020	D BOYS GANG CENTER	<1.00	11/20/2020	
20-10-06128-102	169.3-100	10/24/2020	D BOYS GANG RIGHT	<1.00	11/20/2020	
20-10-06128-103	169.3-101	10/24/2020	D GIRLS GANG LEFT	<1.00	11/20/2020	
20-10-06128-104	169.3-102	10/24/2020	D GIRLS GANG CENTER	<1.00	11/20/2020	
20-10-06128-105	169.3-103	10/24/2020	D GIRLS GANG RIGHT	<1.00	11/20/2020	
20-10-06128-106	169.3-104A	10/24/2020	D FOUNTAIN	<1.00	11/20/2020	
20-10-06128-107	169.3-104B	10/24/2020	D FOUNTAIN	<1.00	11/20/2020	
20-10-06128-108	169.3-105	10/24/2020	D122	9.90	11/20/2020	
20-10-06128-109	169.3-106	10/24/2020	D123	<1.00	11/20/2020	
20-10-06128-110	169.3-107	10/24/2020	D124	<1.00	11/20/2020	
20-10-06128-111	169.3-108A	10/24/2020	D REAR FOUNTAIN	<1.00	11/20/2020	
20-10-06128-112	169.3-108B	10/24/2020	D REAR FOUNTAIN	<1.00	11/20/2020	
20-10-06128-113	169.3-109	10/24/2020	D125	<1.00	11/20/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-06128

Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-114	169.3-110	10/24/2020	D MENS FAC LAV	<1.00	11/20/2020	
20-10-06128-115	169.3-111	10/24/2020	D126	2.02	11/20/2020	
20-10-06128-116	169.3-112	10/24/2020	D WOMENS FAC LAV	<1.00	11/20/2020	
20-10-06128-117	169.3-113	10/24/2020	D127	<1.00	11/20/2020	
20-10-06128-118	169.3-114	10/24/2020	D128	<1.00	11/20/2020	
20-10-06128-119	169.3-115	10/24/2020	D129	<1.00	11/20/2020	
20-10-06128-120	169.3-116	10/24/2020	D130	<1.00	11/20/2020	
20-10-06128-121	169.3-117	10/24/2020	B210	<1.00	11/20/2020	
20-10-06128-122	169.3-118	10/24/2020	B209	1.03	11/20/2020	
20-10-06128-123	169.3-119	10/24/2020	B208	1.37	11/20/2020	
20-10-06128-124	169.3-120A	10/24/2020	B REAR FOUNTAIN	<1.00	11/20/2020	
20-10-06128-125	169.3-120B	10/24/2020	B REAR FOUNTAIN	<1.00	11/20/2020	
20-10-06128-126	169.3-121	10/24/2020	B206 FRONT	12.1	11/20/2020	
20-10-06128-127	169.3-122	10/24/2020	B206 REAR	<1.00	11/20/2020	
20-10-06128-128	169.3-123	10/24/2020	B206 SPRAYER	66.4	11/13/2020	
20-10-06128-129	169.3-124	10/24/2020	B WOMENS FAC LAV	<1.00	11/20/2020	
20-10-06128-130	169.3-125	10/24/2020	B205	1.23	11/20/2020	
20-10-06128-131	169.3-126	10/24/2020	B MENS FAC LAV	<1.00	11/20/2020	
20-10-06128-132	169.3-127	10/24/2020	B204 FRONT	121	11/13/2020	
20-10-06128-133	169.3-128	10/24/2020	B204 REAR	<1.00	11/20/2020	

Client Number: 33-5980 Report Number: 20-10-06128
Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-134	169.3-130	10/24/2020	B203	1.33	11/20/2020	
20-10-06128-135	169.3-131	10/24/2020	B202	<1.00	11/20/2020	
20-10-06128-136	169.3-132	10/24/2020	B201	1.28	11/20/2020	
20-10-06128-137	169.3-133	10/24/2020	B2 FOUNTAIN	<1.00	11/20/2020	
20-10-06128-138	169.3-134	10/24/2020	B2 BOYS GANG LEFT	<1.00	11/20/2020	
20-10-06128-139	169.3-135	10/24/2020	B2 BOYS GANG CENTER	<1.00	11/20/2020	
20-10-06128-140	169.3-136	10/24/2020	B2 BOYS GANG RIGHT	<1.00	11/20/2020	
20-10-06128-141	169.3-137	10/24/2020	B2 GIRLS GANG LAV LEFT	<1.00	11/20/2020	
20-10-06128-142	169.3-139	10/24/2020	B2 GIRLS GANG LAV RIGHT	<1.00	11/20/2020	
20-10-06128-143	169.3-140	10/24/2020	B200	<1.00	11/20/2020	
20-10-06128-144	169.3-141	10/24/2020	B211	<1.00	11/20/2020	
20-10-06128-145	169.3-142	10/24/2020	B213	2.24	11/20/2020	
20-10-06128-146	169.3-143	10/24/2020	B214	1.74	11/20/2020	
20-10-06128-147	169.3-144	10/24/2020	B215B CENTER FRONT	<1.00	11/20/2020	
20-10-06128-148	169.3-145	10/24/2020	B215B CENTER REAR	3.14	11/23/2020	
20-10-06128-149	169.3-146	10/24/2020	B215B CORNER HANDWASH	1.21	11/20/2020	
20-10-06128-150	169.3-147	10/24/2020	B215A LEFT FRONT	<1.00	11/20/2020	
20-10-06128-151	169.3-148	10/24/2020	B215A RIGHT REAR	<1.00	11/20/2020	
20-10-06128-152	169.3-149	10/24/2020	B217	<1.00	11/20/2020	
20-10-06128-153	169.3-151	10/24/2020	C2 GIRLS SIDE FOUNTAIN LFT	<1.00	11/20/2020	

Client Number: 33-5980 Report Number: 20-10-06128
Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-154	169.3-152	10/24/2020	C2 GIRLS SIDE FOUNTAIN RIGHT	<1.00	11/20/2020	
20-10-06128-155	169.3-153	10/24/2020	C253	5.64	11/20/2020	
20-10-06128-156	169.3-154	10/24/2020	C252	<1.00	11/20/2020	
20-10-06128-157	169.3-155	10/24/2020	C251	3.88	11/20/2020	
20-10-06128-158	169.3-156	10/24/2020	C250	1.05	11/20/2020	
20-10-06128-159	169.3-157	10/24/2020	C249	<1.00	11/20/2020	
20-10-06128-160	169.3-158	10/24/2020	C248	<1.00	11/20/2020	
20-10-06128-161	169.3-159	10/24/2020	C246	<1.00	11/20/2020	
20-10-06128-162	169.3-160	10/24/2020	C245	<1.00	11/20/2020	
20-10-06128-163	169.3-161	10/24/2020	C244	3.65	11/20/2020	
20-10-06128-164	169.3-162	10/24/2020	C243	<1.00	11/20/2020	
20-10-06128-165	169.3-163	10/24/2020	C242	2.58	11/20/2020	
20-10-06128-166	169.3-164	10/24/2020	C241	<1.00	11/20/2020	
20-10-06128-167	169.3-165	10/24/2020	C2 BOYS SIDE FOUNTAIN LEFT	<1.00	11/20/2020	
20-10-06128-168	169.3-166	10/24/2020	C2 BOYS SIDE FOUNTAIN RIGHT	<1.00	11/20/2020	
20-10-06128-169	169.3-167	10/24/2020	C2 BOYS LAV LEFT	<1.00	11/20/2020	
20-10-06128-170	169.3-168	10/24/2020	C2 BOYS LAV LEFT CENTER	<1.00	11/20/2020	
20-10-06128-171	169.3-169	10/24/2020	C2 BOYS LAV RIGHT CENTER	<1.00	11/20/2020	
20-10-06128-172	169.3-170	10/24/2020	C2 BOYS LAV RIGHT	<1.00	11/20/2020	
20-10-06128-173	169.3-171	10/24/2020	C2 GIRLS LAV LEFT	<1.00	11/20/2020	

Client Number: 33-5980 Report Number: 20-10-06128
Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-174	169.3-172	10/24/2020	C2 GIRLS LAV LEFT CENTER	<1.00	11/20/2020	
20-10-06128-175	169.3-173	10/24/2020	C2 GIRLS LAV RIGHT CENTER	<1.00	11/20/2020	
20-10-06128-176	169.3-174	10/24/2020	C2 GIRLS LAV RIGHT	<1.00	11/20/2020	
20-10-06128-177	169.3-175	10/24/2020	C2 MENS FAC LAV	<1.00	11/20/2020	
20-10-06128-178	169.3-176	10/24/2020	C2 WOMENS FAC LAV	<1.00	11/20/2020	
20-10-06128-179	169.3-177	10/24/2020	C240 FRONT MIDDLE	<1.00	11/20/2020	
20-10-06128-180	169.3-178	10/24/2020	C240 BACK MIDDLE	<1.00	11/20/2020	
20-10-06128-181	169.3-179	10/24/2020	C239	<1.00	11/20/2020	
20-10-06128-182	169.3-180	10/24/2020	C219	2.48	11/20/2020	
20-10-06128-183	169.3-181	10/24/2020	D228	<1.00	11/20/2020	
20-10-06128-184	169.3-182	10/24/2020	D229	<1.00	11/20/2020	
20-10-06128-185	169.3-183	10/24/2020	D230	<1.00	11/20/2020	
20-10-06128-186	169.3-184A	10/24/2020	D REAR FOUNTAIN	<1.00	11/20/2020	
20-10-06128-187	169.3-184B	10/24/2020	D REAR FOUNTAIN	<1.00	11/20/2020	
20-10-06128-188	169.3-185	10/24/2020	D232 FRONT	3.66	11/20/2020	
20-10-06128-189	169.3-186	10/24/2020	D232 REAR	1.99	11/20/2020	
20-10-06128-190	169.3-187	10/24/2020	D232 SPRAYER	18.6	11/20/2020	
20-10-06128-191	169.3-188	10/24/2020	D MENS FAC LAV	<1.00	11/20/2020	
20-10-06128-192	169.3-189	10/24/2020	D233	<1.00	11/20/2020	
20-10-06128-193	169.3-190	10/24/2020	D WOMENS FAC LAV	<1.00	11/20/2020	

Client Number: 33-5980 Report Number: 20-10-06128

Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-194	169.3-191	10/24/2020	D234 FRONT	8.94	11/20/2020	
20-10-06128-195	169.3-192	10/24/2020	D234 REAR	<1.00	11/20/2020	
20-10-06128-196	169.3-194	10/24/2020	D235	<1.00	11/20/2020	
20-10-06128-197	169.3-195	10/24/2020	D236	<1.00	11/20/2020	
20-10-06128-198	169.3-196	10/24/2020	D237	<1.00	11/20/2020	
20-10-06128-199	169.3-197A	10/24/2020	D2 FOUNTAIN	<1.00	11/20/2020	
20-10-06128-200	169.3-197B	10/24/2020	D2 FOUNTAIN	<1.00	11/20/2020	
20-10-06128-201	169.3-198	10/24/2020	D2 BOYS GANG LEFT	<1.00	11/20/2020	
20-10-06128-202	169.3-199	10/24/2020	D2 BOYS GANG CENTER	<1.00	11/20/2020	
20-10-06128-203	169.3-200	10/24/2020	D2 BOYS GANG RIGHT	<1.00	11/20/2020	
20-10-06128-204	169.3-201	10/24/2020	D2 GIRLS GANG LEFT	<1.00	11/20/2020	
20-10-06128-205	169.3-202	10/24/2020	D2 GIRLS GANG CENTER	<1.00	11/20/2020	
20-10-06128-206	169.3-203	10/24/2020	D2 GIRLS GANG RIGHT	<1.00	11/20/2020	
20-10-06128-207	169.3-204	10/24/2020	D238	<1.00	11/20/2020	
20-10-06128-208	169.3-205	10/24/2020	D227	<1.00	11/20/2020	
20-10-06128-209	169.3-206	10/24/2020	D226	<1.00	11/20/2020	
20-10-06128-210	169.3-207	10/24/2020	D225	<1.00	11/20/2020	
20-10-06128-211	169.3-208	10/24/2020	D224	<1.00	11/20/2020	
20-10-06128-212	169.3-209	10/24/2020	D222	<1.00	11/20/2020	
20-10-06128-213	169.3-210	10/24/2020	D221	<1.00	11/20/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-06128

Project/Test Address: 2020L-169.3; William Street School; 5201 William St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-06128-214	169.3-211	10/24/2020	D220	1.04	11/20/2020	

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NY 11714

Reviewed By Authorized Signatory: Melissa Kanode

Missy Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.5 Laboratory Certifications

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER

Expires 12:01 AM April 01, 2021
Issued April 01, 2020

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MS. JULIE DICKERSON
ENVIRONMENTAL HAZARDS SERVICES, LLC
7469 WHITEPINE ROAD
N. CHESTERFIELD, VA 23237

NY Lab Id No: 11714

is hereby APPROVED as an Environmental Laboratory in conformance with the National Environmental Laboratory Accreditation Conference Standards (2003) for the category ENVIRONMENTAL ANALYSES POTABLE WATER
All approved analytes are listed below:

Metals I

Copper, Total	SM 19, 21-23 3113B (-04,-10)
Lead, Total	SM 19, 21-23 3113B (-04,-10)

NEW YORK STATE | Department of Health

Serial No.: 61514

Property of the New York State Department of Health. Certificates are valid only at the address shown, must be conspicuously posted, and are printed on secure paper. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify the laboratory's accreditation status.

NELAP RECOGNIZED TNI ACCREDITATION BODY

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.6 Chains of Custody

20-10-06128

Stohl ENVIRONMENT

3860 California Road, Orchard Park, New York
PHONE (716) 312-0070 FAX (716) 312-809
WWW.STOHLENVIRONMENTAL.COM

Due Date:
11/27/2020
(Friday)
AE

Custody Document

ab Name) EHS

)HL Job # 2020L-169.3

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: William Street School

Location: 5201 William St Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
1	169.3-1	Loading Dock Left Lav	Sink	8:00			
2	169.3-2	Loading Dock Right Lav	Sink	8:01			
3	169.3-3	Kitchen Handwash by freezers	Sink	8:02			
4	169.3-4	Kitchen 2 bay	Sink	8:03			
5	169.3-5	Kitchen Single Bay	Sink	8:04			
6	169.3-6	Kitchen Handwash Corner	Sink	8:05			
7	169.3-7	Kitchen Dish Sprayer	sink	8:06			
8	169.3-8	Kitchen Dish Single Bay	Sink	8:07			
9	169.3-9	Kitchen Dish 2 bay	Sink	8:08			
10	169.3-10	Kitchen Kettle	Sink	8:09			
11	169.3-11	Kitchen Single by Coffee	sink	8:10			
12	169.3-12	Dishwasher Left	Sink	8:11			
13	169.3-13	Dishwasher Right	Sink	8:12			
14	169.3-14	Dish Sprayer by Cafe	Sink	8:13			
15	169.3-15	Dish Room Handwash	Sink	8:14			
16	169.3-16	Serving Handwash	Sink	8:15			
17	169.3-17	Serving Handwash by Fridges	Sink	8:16			
18	169.3-18	Handwash by Stove	Sink	8:17			

Notes:

Please e-mail lab results to labs@stohlenv.com ☑ If checked, also e-mail results to: Ehenderson@StohlEnv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): TStone Stone Date: 10/29/20 Time: 6:27pm

Sample Login (Name / Lab): Ryan Blom Date: 11/18/20 Time: 934AM

Analysis (Name / Lab): J. Hertzler Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name / Lab): [signature] Date: 11/24/20 Time: [illegible]

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

10128

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.3

Client: Lancaster CSD Contact: Michael Bryniarski

Building: William Street School Location: 5201 William St Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
19	169.3-19	Handwash by Office	Sink	8:18			
20	169.3-20	Kitchen Ice Machine	IM	8:19			
21	169.3-21A	Cafeteria	DFA	8:20			
22	169.3-21B	Cafeteria	DFB	8:21			
23	169.3-22	Girls Lav B1 Left	Sink	8:22			
24	169.3-23	Girls Lav B1 Center	Sink	8:23			
25	169.3-24	Girls Lav B1 Right	Sink	8:24			
26	169.3-25	Boys Lav B1 Left	Sink	8:25			
27	169.3-26	Boys Lav B1 Center	Sink	8:26			
28	169.3-27	Boys Lav B1 Right	Sink	8:27			
29	169.3-28A	B1 Fountain	Dfa	8:28			
30	169.3-28B	B1 Fountain	DFB	8:29			
31	169.3-29	B109	Sink	8:30			
32	169.3-30	B108	Sink	8:31			
33	169.3-31	B107	Sink	8:32			
34	169.3-32A	B Common Fountain	DFA	8:33			
35	169.3-32B	B Common Fountain	DFB	8:34			
36	169.3-33	B106 Front	Sink	8:35			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: E. Henderson Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): TStone TStone Date: 10/29/20 Time: 6:27pm

Sample Login (Name / Lab): Staci Bloom Date: 11/8/20 Time: 937Am

Analysis (Name / Lab): J. Hertzler Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name / Lab): Date: 11/24/20 Time: 1pm

Archived / Released: QA/QC InterLAB Use: Date: Time:

6/28

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.3

Client: Lancaster CSD Contact: Michael Bryniarski

Building: William Street School Location: 5201 William St Lancaster, NY 14086

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
37	169.3-34	B106 Rear	Sink	8:36			
38	169.3-35	B106 Sprayer	Sink	8:37			
39	169.3-36	Left Lav Outside B105	Sink	8:38			
40	169.3-37	B105 Fac	Sink	8:39			
41	169.3-38	Right Lav Outsidee B105	Sink	8:40			
42	169.3-39	B104	Sink	8:41			
43	169.3-40	B103	Sink	8:42			
44	169.3-41	B102	Sink	8:43			
45	169.3-42	B101	Sink	8:44			
46	169.3-43	B112 Band Lesson	Sink	8:45			
47	169.3-44	B113 Library Classroom	Sink	8:46			
48	169.3-45	D117 Main Office Kit	Sink	8:47			
49	169.3-46	D117 Main Office Lav	Sink	8:48			
50	169.3-47	C132 Chorus	Sink	8:49			
51	169.3-48	C133 Sink	Sink	8:50			
52	169.3-49	C133 Fountain	Bubbler	8:51			
53	169.3-50	C1 Womens Fac Lav	Sink	8:52			
54	169.3-51	C1 Mens Fac Lav	Sink	8:53			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): Tracy Bloom T3 [signature] Date: ~~11/3~~ 10/29/20 Time: 6:27pm

Sample Login (Name / Lab): Tracy Bloom Date: 11/18/20 Time: 9:10 AM

Analysis (Name / Lab): G. Hertzler Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name / Lab): Melissa Date: 11/24/20 Time: 1pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

6128

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.3

Client: Lancaster CSD Contact: Michael Bryniarski

Building: William Street School Location: 5201 William St Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
55	169.3-52	C1 Girls Gang Left	Sink	8:54			
56	169.3-53	C1 Girls Gang Left Center	Sink	8:55			
57	169.3-54	C1 Girls Gang Right Center	Sink	8:56			
58	169.3-56	C1 Boys Gang Left	Sink	8:57			
59	169.3-57	C1 Boys Gang Left Center	Sink	8:58			
60	169.3-58	C1 Boys Gang R Center	Sink	8:59			
61	169.3-59	C1 Boys Gang Right	Sink	9:00			
62	169.3-60	C1 Boys Side Fountain Left	Bubbler	9:01			
63	169.3-61	C1 Boys Side Fountain Right	Sink	9:02			
64	169.3-62	C1 Girls Side Fountain Left	Bubbler	9:03			
65	169.3-63	C1 Girls Side Fountain Right	Sink	9:04			
66	169.3-64	C146	Sink	9:05			
67	169.3-65	C145	Sink	9:06			
68	169.3-66	C144	Sink	9:07			
69	169.3-67	C143	Sink	9:08			
70	169.3-68	C142	Sink	9:09			
71	169.3-69	C141	Sink	9:10			
72	169.3-70	C139	Sink	9:11			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): TStone TStone Date: 10/29/20 Time: 6:22pm

Sample Login (Name / Lab): T.Ishom Date: 11/19/20 Time: 4pm

Analysis (Name / Lab): J. Hertzler Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name / Lab): Mehard Date: 11/24/20 Time: 1pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

1128

Chain of Custody Document

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.3

Client: Lancaster CSD Contact: Michael Bryniarski

Building: William Street School Location: 5201 William St Lancaster, NY 14086

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
73	169.3-71	C138	Sink	9:12			
74	169.3-72	C137	Sink	9:13			
75	169.3-73	C136	Sink	9:14			
76	169.3-74	C135	Sink	9:15			
77	169.3-75	C134	Sink	9:16			
78	169.3-76	D118 Nurse Main	Sink	9:17			
79	169.3-77	D118 Nurse Exam	Sink	9:18			
80	169.3-78	D118 Nurse Lav	Sink	9:19			
81	169.3-79	Girls Pool Locker Rm Left	Sink	9:20			
82	169.3-80	Girls Pool Locker Rm Center	Sink	9:21			
83	169.3-81	Girls Pool Locker Rm Right	Sink	9:22			
84	169.3-82	Boys Pool Locker Rm Left	Sink	9:23			
85	169.3-83	Boys Pool Locker Rm Center	Sink	9:24			
86	169.3-84	Boys Pool Locker Rm Right	Sink	9:25			
87	169.3-85	New Gym Girl Side Fntn Left	Sink	9:26			
88	169.3-86	New Gym Girl Side Fntn Right	Sink	9:27			
89	169.3-87	New Gym Boy Side Fntn Left	Sink	9:28			
90	169.3-88	New Gym Boy Side Fntn Right	Sink	9:29			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): [signature] Date: 10/29/20 Time: 6:27pm

Sample Login (Name / Lab): T. Johnson Date: 11/9/20 Time: 4pm

Analysis (Name / Lab): J. Hertzler Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name/Lab): [signature] Date: 11/24/20 Time: 6p

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.3

Client: Lancaster CSD Contact: Michael Bryniarski

Building: William Street School Location: 5201 William St Lancaster, NY 14086

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
91	169.3-90	Old Gym Boys Locker Center	Sink	9:30			
92	169.3-91	Old Gym Boys Locker Right	Sink	9:31			
93	169.3-92	Old Gym Boys Coach Office	Sink	9:32			
94	169.3-93	Old Gym Girls Locker Left	Sink	9:33			
95	169.3-94	Old Gym Girls Locker Center	Sink	9:34			
96	169.3-95	Old Gym Girls Locker Right	Sink	9:35			
97	169.3-96	Old Gym Girls Coach Office	Sink	9:36			
98	169.3-97A	Old Gym Girls side Fountain	DFA	9:37			
99	169.3-97B	Old Gym Girls Side Fountain	DFB	9:38			
100	169.3-98	D Boys Gang Left	Sink	9:39			
101	169.3-99	D Boys Gang Center	Sink	9:40			
102	169.3-100	D Boys Gang Right	Sink	9:41			
103	169.3-101	D Girls Gang left	Sink	9:42			
104	169.3-102	D Girls Gang Center	Sink	9:43			
105	169.3-103	D Girls Gang Right	Sink	9:44			
106	169.3-104A	D Fountain	DFA	9:45			
107	169.3-104B	D Fountain	DFB	9:46			
108	169.3-105	D122	Sink	9:47			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): [signature] Date: 10/29/20 Time: 10:27pm

Sample Login (Name / Lab): [signature] Date: 11/19/20 Time: 4pm

Analysis (Name / Lab): [signature] Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name / Lab): [signature] Date: 11/24/20 Time: 1pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

6128

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.3

Client: Lancaster CSD Contact: Michael Bryniarski

Building: William Street School Location: 5201 William St Lancaster, NY 14086

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
109	169.3-106	D123	Sink	9:48			
110	169.3-107	D124	Sink	9:49			
111	169.3-108A	D Rear Fountain	DFA	9:50			
112	169.3-108B	D Rear Fountain	DFB	9:51			
113	169.3-109	D125	Sink	9:52			
114	169.3-110	D Mens Fac Lav	Sink	9:53			
115	169.3-111	D126	Sink	9:54			
116	169.3-112	D Womens Fac Lav	Sink	9:55			
117	169.3-113	D127	Sink	9:56			
118	169.3-114	D128	Sink	9:57			
119	169.3-115	D129	Sink	9:58			
120	169.3-116	D130	Sink	9:59			
121	169.3-117	B210	Sink	10:00			
122	169.3-118	B209	Sink	10:01			
123	169.3-119	B208	Sink	10:02			
124	169.3-120A	B Rear Fountain	DFA	10:03			
125	169.3-120B	B Rear Fountain	DFB	10:04			
126	169.3-121	B206 Front	Sink	10:05			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: E. Henderson Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): T Stone / Stone Date: 10/29/20 Time: 6:27pm

Sample Login (Name / Lab): T Schramm Date: 11/19/20 Time: 4pm

Analysis (Name / Lab): J. Hertzler Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name / Lab): M Mehler Date: 11/24/20 Time: 1pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

6128

Chain of Custody Document

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.3

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: William Street School

Location: 5201 William St Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
127	169.3-122	B206 Rear	Sink	10:06			
128	169.3-123	B206 Sprayer	Sink	10:07			
129	169.3-124	B Womens Fac Lav	Sink	10:08			
130	169.3-125	B205	Sink	10:09			
131	169.3-126	B Mens Fac Lav	Sink	10:10			
132	169.3-127	B204 Front	Sink	10:11			
133	169.3-128	B204 Rear	Sink	10:12			
134	169.3-130	B203	Sink	10:13			
135	169.3-131	B202	Sink	10:14			
136	169.3-132	B201	Sink	10:15			
137	169.3-133	B2 Fountain	DFA	10:16			
138	169.3-134	B2 Boys Gang eft	Sink	10:17			
139	169.3-135	B2 Boys Gang Center	Sink	10:18			
140	169.3-136	B2 Boys Gang Right	Sink	10:19			
141	169.3-137	B2 Girls Gang Lav Left	Sink	10:20			
142	169.3-139	B2 Girls Gang Lav Right	Sink	10:21			
143	169.3-140	B200	Sink	10:22			
144	169.3-141	B211	Sink	10:23			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): TStone JStone Date: 10/29/20 Time: 6:27pm

Sample Login (Name / Lab): [signature] Date: 11/19/20 Time: 4pm

Analysis (Name / Lab): J. Hertzler Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name / Lab): Melnick Date: 11/24/20 Time: 1pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.3

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: William Street School

Location: 5201 William St Lancaster, NY 14086

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
145	169.3-142	B213	Sink	10:24			
146	169.3-143	B214	Sink	10:25			
147	169.3-144	B215B Center Front	Sink	10:26			
148	169.3-145	B215B Center Rear	Sink	10:27			
149	169.3-146	B215B Corner Handwash	Sink	10:28			
150	169.3-147	B215A Left Front	Sink	10:29			
151	169.3-148	B215A Right Rear	Sink	10:30			
152	169.3-149	B217	Sink	10:31			
*	169.3-150	B218	Sink	10:32	recieved empty	ND 10/30/2020	
153	169.3-151	C2 Girls Sid Fountain Lft	Bubbler	10:33			
154	169.3-152	C2 Girls Side Fountain Right	Bubbler	10:34			
155	169.3-153	C253	Sink	10:35			
156	169.3-154	C252	Sink	10:36			
157	169.3-155	C251	Sink	10:37			
158	169.3-156	C250	Sink	10:38			
159	169.3-157	C249	Sink	10:39			
160	169.3-158	C248	Sink	10:40			
161	169.3-159	C246	Sink	10:41			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): TStone/Stohl Date: 10/29/20 Time: 10:27pm

Sample Login (Name / Lab): T Isherman/ Date: 11/19/20 Time: 4pm

Analysis (Name / Lab): J Hertzler Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name / Lab): M Lehner Date: 11/24/20 Time: 1pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

6128

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.3

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: William Street School

Location: 5201 William St Lancaster, NY 14086

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
162	169.3-160	C245	Sink	10:42			
163	169.3-161	C244	Sink	10:43			
164	169.3-162	C243	Sink	10:44			
165	169.3-163	C242	Sink	10:45			
166	169.3-164	C241	Sink	10:46			
167	169.3-165	C2 Boys Side Fountain Left	Bubbler	10:47			
168	169.3-166	C2 Boys Side Fountain Right	Bubbler	10:48			
169	169.3-167	C2 Boys Lav Left	Sink	10:49			
170	169.3-168	C2 Boys Lav Left Center	Sink	10:50			
171	169.3-169	C2 Boys Lav Right Center	Sink	10:51			
172	169.3-170	C2 Boys Lav Right	Sink	10:52			
173	169.3-171	C2 Girls Lav Left	Sink	10:53			
174	169.3-172	C2 Girls Lav Left Center	Sink	10:54			
175	169.3-173	C2 Girls Lav Right Cnter	Sink	10:55			
176	169.3-174	C2 Girls Lav Right	Sink	10:56			
177	169.3-175	C2 Mens Fac Lav	Sink	10:57			
178	169.3-176	C2 Womens Fac Lav	Sink	10:58			
179	169.3-177	C240 Front Middle	Sink	10:59			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): TStone Stohl Date: 10/29/20 Time: 6:27pm

Sample Login (Name / Lab): [signature] Date: 11/19/20 Time: 4pm

Analysis (Name / Lab): [signature] Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name / Lab): [signature] Date: 11/24/20 Time: 1pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

10128

Chain of Custody Document

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.3

Client: Lancaster CSD Contact: Michael Bryniarski

Building: William Street School Location: 5201 William St Lancaster, NY 14086

LEAD

Water by AAS-GF: ASTM D3559-03D, US EPA 200.9 X

Turnaround

20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
178	169.3-178	C240 Back Middle	Sink	11:00			
179	169.3-179	C239	Sink	11:01			
180	169.3-180	C219	Sink	11:02			
181	169.3-181	D228	Sink	11:03			
182	169.3-182	D229	Sink	11:04			
183	169.3-183	D230	Sink	11:05			
184	169.3-184A	D Rear Fountain	DFA	11:06			
185	169.3-184B	D Rear Fountain	DFB	11:07			
186	169.3-185	D232 Front	Sink	11:08			
187	169.3-186	D232 Rear	Sink	11:09			
188	169.3-187	D232 Sprayer	Sink	11:10			
189	169.3-188	D Mens Fac Lav	Sink	11:11			
190	169.3-189	D233	Sink	11:12			
191	169.3-190	D Womens Fac Lav	Sink	11:13			
192	169.3-191	D234 Front	Sink	11:14			
193	169.3-192	D234 Rear	Sink	11:15			
194	169.3-194	D235	Sink	11:16			
195	169.3-195	D236	Sink	11:17			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: E. Henderson Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): T Stone Stohl Date: 10/29/20 Time: 10:27pm

Sample Login (Name / Lab): T Johnson Date: 11/19/20 Time: 4pm

Analysis (Name / Lab): J. Hertzler Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name / Lab): [signature] Date: 11/24/20 Time: 1pm

Archived / Released: ____ QA/QC InterLAB Use: ____ Date: ____ Time: ____

6128

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.3

Client: Lancaster CSD Contact: Michael Bryniarski

Building: William Street School Location: 5201 William St Lancaster, NY 14086

LEAD

Water by AAS-GF: ASTM D3559-03D, US EPA 200.9 — X

Turnaround: 20 Days

	Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
198	169.3-196	D237	Sin	11:18			
199	169.3-197A	D2 Fountain	DFA	11:19			
200	169.3-197B	D2 fountain	DFB	11:20			
201	169.3-198	D2 Boys Gang Left	Sink	11:21			
202	169.3-199	D2 Boys Gang Center	Sink	11:22			
203	169.3-200	D2 Boys Gang Right	Sink	11:23			
204	169.3-201	D2 Girls Gang Left	sink	11:24			
205	169.3-202	D2 Girls gang Center	Sink	11:25			
206	169.3-203	D2 Girls Gang Right	Sink	11:26			
207	169.3-204	D238	Sink	11:27			
208	169.3-205	D227	Sink	11:28			
209	169.3-206	D226	Sink	11:29			
210	169.3-207	D225	Sink	11:30			
211	169.3-208	D224	Sink	11:31			
212	169.3-209	D222	Sink	11:32			
213	169.3-210	D221	Sink	11:33			
214	169.3-211	D220	Sink	11:34			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C.Schultz, P.Nichols Print Name Stohl Env: C.Schultz, P.Nichols Date: 10/24/2020

Relinquished By: E. Henderson Print Name Stohl Env: Eric Henderson Jr. Date: 10/26/2020

Received (Name / Lab): TStone Stone Date: 10/29/20 Time: 6:27pm

Sample Login (Name / Lab): T Sherman Date: 11/19/20 Time: 4pm

Analysis (Name / Lab): J. Hertzler Date: 11/23/20 Time: 8:42 am

QA/QC Review (Name / Lab): M Date: 11/24/20 Time: 1p

Archived / Released: ____ QA/QC InterLAB Use: ____ Date: ____ Time: ____

BLANK



3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM