Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

Decmber 15, 2020

Mr. Michael Bryniarski
Director of Facilities
Lancaster Central School District
177 Central Avenue
Lancaster, NY 14086

RE: Investigation and Sampling of Drinking Water for Lead Concentrations

Dear Mr. Bryniarski:

Included with this letter is Stohl Environmental LLC's report for the Water Sampling performed at the educational buildings of the Lancaster Central School District, including:

- Lancaster Middle School – 148 Aurora Street, Lancaster, New York.

This report is prepared to assist the District in complying with the requirements of NYS regulations, *SUBPART 67-4: Lead Testing in School Drinking Water*, by identifying the sources of potable water with lead concentrations greater than the NYS "Action Level of 15 parts per billion (ppb)".

The Investigation and Sampling was performed on October 17, 2020. The Protocol for the Investigation followed the requirements of NYS regulations as well as USEPA Technical Guidance Document "3-T's for Reducing Lead in Drinking Water in Schools".

As detailed in Section 1.2 *(Executive Summary)* of the accompanying report, based upon the sampling and analysis performed, 10 sources of potable water in the Middle School have been identified as having lead concentrations in water above the NYS Action Level of 15 parts per billion. To comply with NYS regulations, Response actions as identified in this report by the District are required.

Thank you for the opportunity to be of service to Lancaster Central School District.

Sincerely,
Stohl Environmental, LLC.



Eric Henderson Jr.
Senior Project Manager

Investigation and Sampling Of Sources of Potable Water For Lead Concentrations

Prepared for:

Lancaster Central School District

Prepared by:

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Conditions as of October 17, 2020

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

Summary Tabulation

Lead in Drinking Water Investigation

1.1. Scope of Work and Sampling Protocol

1.2. Executive Summary of Sampling and Analysis

1.3. Response Actions Required Under NYS Regulations

1.4. Laboratory Analytical Reports by Building

1.5. Laboratory Certifications

1.6. Chains of Custody

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.1 Scope of Work and Sampling Protocol:

Stohl Environmental was retained by Lancaster Central School District to perform sampling and analysis of potable water for elevated lead concentrations. Sampling was performed in the following buildings:

- Lancaster Middle School – 148 Aurora Street, Lancaster, New York.

Scope of Work:

Stohl Environmental was charged with collecting first-draw water samples from outlets within the Middle School. Outlets are defined in NYS regulations as: "a potable water fixture currently or potentially used for drinking or cooking purposes, including but not limited to a bubbler, drinking fountain, or faucets".

Sampling Protocol:

In accordance with NYS regulations, ***Subpart 67-4: Lead Testing in School Drinking Water***, and the EPA guidance document, ***'3Ts for Reducing Lead in Drinking Water in Schools"***, Stohl Environmental's protocol can be summarized as follows:

- **First-draw samples** of 250 milliliters (mL) were collected from cold water outlets before any water was used. Sampling was coordinated with District representatives to assure that water was motionless in the pipes for a minimum of 8 hours, but not more than 18 hours before sample collection.

- **Laboratory Analysis:** Samples were submitted following strict chain-of-custody protocols to an independent laboratory approved by the NYS Department of Health's Environmental Laboratory Approval Program (ELAP).

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.2 Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Confirmatory Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb
Middle School	10/17/2020	123	113	10	N/A	N/A

****** Confirmatory samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Listing of Outlets Requiring Remediation

Locations of Outlets Analyzed above the NYS Action Level of 15 parts per billion based upon Analysis of First Draw Samples:

Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb
169.2-31	Room 217 Vestibule	Sink	36.6
169.2-32	Room 218	Sink	62.6
169.2-34	Art Room 112 Far Left	Sink	40.4
169.2-35	Art Room 112 Far Center	Sink	18.8
169.2-36	Art Room 112 Far Right	Sink	32.5
169.2-37	Art Room 112 Closet Left	Sink	61.2
169.2-38	Art Room 112 Close Center	Sink	20.9
169.2-39	Art Room 112 Close Right	Sink	15.7
169.2-52	Room 108	Sink	33.5
169.2-98	Room 120	Sink	15.4

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.3 Response Actions Required Under NYS Regulations, Section 67-4.4:

For outlets analyzed with a lead concentration in excess of the NYS Action Level, regulations require:

(a) Prohibit use of the outlet until:

(1) a lead remediation plan is implemented to mitigate the lead level of such outlet; and

(2) test results indicate that the lead levels are at or below the action level;

(b) provide building occupants with an adequate supply of potable water for drinking and cooking until remediation is performed;

(c) report the test results to the local health department as soon as practicable, but no more than 1 business day after the school received the laboratory report; and

(d) notify all staff and all persons in parental relation to students of the test results, in writing, as soon as practicable but no more than 10 business days after the school received the laboratory report.

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.4 Laboratory Analytical Reports by Building

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 20-10-04914

Client: Stohl Environmental
3860 California Road
Orchard Park, NY 14127

Received Date: 10/22/2020
Reported Date: 11/13/2020
Sampled By: Christine Schultz
Tech Certification #:

Project/Test Address: 2020L-169.2; Lancaster Middle School; 148 Aurora St; Lancaster, NY 14086

Client Number: 33-5980

Laboratory Results

Fax Number: 716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04914-001	169.2-1	10/17/2020	3RD FLOOR BOYS LAV	2.68	11/10/2020	
20-10-04914-002	169.2-2A	10/17/2020	304 HALLWAY	1.94	11/10/2020	
20-10-04914-003	169.2-2B	10/17/2020	304 HALLWAY	<1.00	11/10/2020	
20-10-04914-004	169.2-3A	10/17/2020	306 HALLWAY	<1.00	11/10/2020	
20-10-04914-005	169.2-3B	10/17/2020	306 HALLWAY	<1.00	11/10/2020	
20-10-04914-006	169.2-4	10/17/2020	3RD FLOOR GIRLS LAV	<1.00	11/10/2020	
20-10-04914-007	169.2-5	10/17/2020	200 HALLWAY GIRLS LAV LEFT	3.06	11/10/2020	
20-10-04914-008	169.2-6	10/17/2020	200 HALLWAY GIRLS LAV CENTER	4.73	11/10/2020	
20-10-04914-009	169.2-7	10/17/2020	200 HALLWAY GIRLS LAV RIGHT	1.96	11/10/2020	
20-10-04914-010	169.2-8A	10/17/2020	200 HALLWAY	<1.00	11/10/2020	
20-10-04914-011	169.2-8B	10/17/2020	200 HALLWAY	<1.00	11/10/2020	
20-10-04914-012	169.2-9	10/17/2020	200 HALLWAY BOYS LAV LEFT	3.38	11/10/2020	
20-10-04914-013	169.2-10	10/17/2020	200 HALLWAY BOYS LAV CENTER	2.21	11/10/2020	

Client Number: 33-5980 Report Number: 20-10-04914

Project/Test Address: 2020L-169.2; Lancaster Middle School; 148 Aurora St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04914-014	169.2-11	10/17/2020	200 HALLWAY BOYS LAV RIGHT	2.39	11/10/2020	
20-10-04914-015	169.2-12	10/17/2020	206/204 MIDDLE OFFICE RIGHT	8.72	11/10/2020	
20-10-04914-016	169.2-13	10/17/2020	206/204 MIDDLE OFFICE LEFT	7.73	11/10/2020	
20-10-04914-017	169.2-14A	10/17/2020	206 HALLWAY	<1.00	11/10/2020	
20-10-04914-018	169.2-14B	10/17/2020	206 HALLWAY	<1.00	11/10/2020	
20-10-04914-019	169.2-15	10/17/2020	ART ROOM 209 LEFT	12.1	11/10/2020	
20-10-04914-020	169.2-16	10/17/2020	ART ROOM 209 RIGHT	14.1	11/10/2020	
20-10-04914-021	169.2-17	10/17/2020	214 HALLWAY BOYS LAV LEFT	2.20	11/10/2020	
20-10-04914-022	169.2-18A	10/17/2020	214 HALLWAY	<1.00	11/10/2020	
20-10-04914-023	169.2-18B	10/17/2020	214 HALLWAY	<1.00	11/11/2020	
20-10-04914-024	169.2-19A	10/17/2020	LIBRARY HALLWAY	<1.00	11/11/2020	
20-10-04914-025	169.2-19B	10/17/2020	LIBRARY HALLWAY	<1.00	11/11/2020	
20-10-04914-026	169.2-20	10/17/2020	LIBRARY KITCHENETTE	2.91	11/11/2020	
20-10-04914-027	169.2-21	10/17/2020	LIBRARY HALLWAY GIRLS LAV	1.82	11/11/2020	
20-10-04914-028	169.2-22	10/17/2020	2ND FLOOR FAC LAV	1.70	11/11/2020	
20-10-04914-029	169.2-23	10/17/2020	2ND FLOOR LOUNGE WATER COOLER	<1.00	11/11/2020	
20-10-04914-030	169.2-24	10/17/2020	2ND FLOOR LOUNGE LAV	1.61	11/11/2020	
20-10-04914-031	169.2-25	10/17/2020	ROOM 216 EAST	9.98	11/11/2020	
20-10-04914-032	169.2-26	10/17/2020	ROOM 216 SOUTH	6.79	11/06/2020	
20-10-04914-033	169.2-27	10/17/2020	ROOM 216 WEST	2.52	11/11/2020	

Client Number: 33-5980 Report Number: 20-10-04914

Project/Test Address: 2020L-169.2; Lancaster Middle School; 148 Aurora St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04914-034	169.2-28	10/17/2020	ROOM 216 NORTH	3.40	11/11/2020	
20-10-04914-035	169.2-29	10/17/2020	ROOM 217 NORTH	11.6	11/11/2020	
20-10-04914-036	169.2-30	10/17/2020	ROOM 217 EAST	9.45	11/11/2020	
20-10-04914-037	169.2-31	10/17/2020	ROOM 217 WEST	36.6	11/11/2020	
20-10-04914-038	169.2-32	10/17/2020	ROOM 218	62.6	11/11/2020	
20-10-04914-039	169.2-33	10/17/2020	ROOM 111	3.45	11/11/2020	
20-10-04914-040	169.2-34	10/17/2020	ART ROOM 112 FAR LEFT	40.4	11/11/2020	
20-10-04914-041	169.2-35	10/17/2020	ART ROOM 112 FAR CENTER	18.8	11/11/2020	
20-10-04914-042	169.2-36	10/17/2020	ART ROOM 112 FAR RIGHT	32.5	11/11/2020	
20-10-04914-043	169.2-37	10/17/2020	ART ROOM 112 CLOSE LEFT	61.2	11/11/2020	
20-10-04914-044	169.2-38	10/17/2020	ART ROOM 112 CLOSE CENTER	20.9	11/11/2020	
20-10-04914-045	169.2-39	10/17/2020	ART ROOM 112 CLOSE RIGHT	15.7	11/11/2020	
20-10-04914-046	169.2-40	10/17/2020	FACULTY ROOM BY 113 LAV	5.59	11/11/2020	
20-10-04914-047	169.2-41	10/17/2020	MUSIC ROOM 113	1.14	11/11/2020	
20-10-04914-048	169.2-42	10/17/2020	AUDITORIUM GIRLS LAV LEFT	<1.00	11/11/2020	
20-10-04914-049	169.2-43	10/17/2020	AUDITORIUM GIRLS LAV RIGHT	<1.00	11/11/2020	
20-10-04914-050	169.2-44	10/17/2020	COUNSELING CENTER	1.25	11/11/2020	
20-10-04914-051	169.2-45	10/17/2020	ADMIN OFFICE KITCHENETTE	<1.00	11/11/2020	
20-10-04914-052	169.2-46	10/17/2020	ADMIN OFFICE LAV	1.79	11/11/2020	
20-10-04914-053	169.2-47	10/17/2020	AUDITORIUM BOYS LAV LEFT	1.21	11/11/2020	

Client Number: 33-5980 Report Number: 20-10-04914

Project/Test Address: 2020L-169.2; Lancaster Middle School; 148 Aurora St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04914-054	169.2-48	10/17/2020	AUDITORIUM BOYS LAV RIGHT	<1.00	11/11/2020	
20-10-04914-055	169.2-49	10/17/2020	COPY ROOM LAV	1.72	11/11/2020	
20-10-04914-056	169.2-51	10/17/2020	ROOM 108A	10.5	11/11/2020	
20-10-04914-057	169.2-52	10/17/2020	ROOM 108	33.5	11/11/2020	
20-10-04914-058	169.2-53	10/17/2020	NURSE ICE MACHINE	<1.00	11/11/2020	
20-10-04914-059	169.2-54	10/17/2020	NURSE BACK LAV	7.17	11/11/2020	
20-10-04914-060	169.2-55	10/17/2020	NURSE MAIN HANDWASH	7.14	11/11/2020	
20-10-04914-061	169.2-56	10/17/2020	NURSE FRONT LAV	1.24	11/11/2020	
20-10-04914-062	169.2-57A	10/17/2020	106 HALLWAY	<1.00	11/11/2020	
20-10-04914-063	169.2-57B	10/17/2020	106 HALLWAY	<1.00	11/11/2020	
20-10-04914-064	169.2-58	10/17/2020	104/106 MIDDLE OFFICE LEFT	2.67	11/11/2020	
20-10-04914-065	169.2-59	10/17/2020	104/106 MIDDLE OFFICE RIGHT	3.42	11/11/2020	
20-10-04914-066	169.2-60	10/17/2020	100 HALLWAY MENS LAV LEFT	2.77	11/11/2020	
20-10-04914-067	169.2-61	10/17/2020	100 HALLWAY MENS LAV CENTER	2.83	11/11/2020	
20-10-04914-068	169.2-62	10/17/2020	100 HALLWAY MENS LAV RIGHT	2.09	11/11/2020	
20-10-04914-069	169.2-63A	10/17/2020	100 HALLWAY	<1.00	11/11/2020	
20-10-04914-070	169.2-63B	10/17/2020	100 HALLWAY	<1.00	11/11/2020	
20-10-04914-071	169.2-64	10/17/2020	100 HALLWAY GIRLS LAV LEFT	4.19	11/11/2020	
20-10-04914-072	169.2-65	10/17/2020	100 HALLWAY GIRLS LAV CENTER	2.78	11/11/2020	
20-10-04914-073	169.2-66	10/17/2020	100 HALLWAY GIRLS LAV RIGHT	4.76	11/11/2020	

Client Number: 33-5980 Report Number: 20-10-04914

Project/Test Address: 2020L-169.2; Lancaster Middle School; 148 Aurora St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04914-074	169.2-67	10/17/2020	SHOP ROOM 164	<1.00	11/11/2020	
20-10-04914-075	169.2-68	10/17/2020	GIRLS LOCKER ROOM HALLWAY LEFT	<1.00	11/11/2020	
20-10-04914-076	169.2-69	10/17/2020	GIRLS LOCKER ROOM HALLWAY RIGHT	<1.00	11/11/2020	
20-10-04914-077	169.2-70	10/17/2020	GIRLS TEAM ROOM	12.6	11/11/2020	
20-10-04914-078	169.2-71	10/17/2020	GIRLS GYM LOCKER VESTIBULE LEFT	<1.00	11/11/2020	
20-10-04914-079	169.2-72	10/17/2020	GIRLS GYM LOCKER VESTIBULE RIGHT	<1.00	11/11/2020	
20-10-04914-080	169.2-73	10/17/2020	GIRLS GYM LOCKER LAV LEFT	3.12	11/11/2020	
20-10-04914-081	169.2-74	10/17/2020	GIRLS GYM LOCKER LAV LEFT CENTER	2.00	11/11/2020	
20-10-04914-082	169.2-75	10/17/2020	GIRLS GYM LOCKER LAV RIGHT CENTER	2.13	11/11/2020	
20-10-04914-083	169.2-76	10/17/2020	GIRLS GYM LOCKER LAV RIGHT	2.07	11/11/2020	
20-10-04914-084	169.2-77	10/17/2020	GIRLS GYM COACH OFFICE LAV	4.19	11/11/2020	
20-10-04914-085	169.2-78	10/17/2020	GIRLS LAV BY 159 LEFT	2.03	11/11/2020	
20-10-04914-086	169.2-79	10/17/2020	GIRLS LAV BY 159 LEFT CENTER	2.03	11/11/2020	
20-10-04914-087	169.2-80	10/17/2020	GIRLS LAV BY 159 RIGHT CENTER	2.64	11/11/2020	
20-10-04914-088	169.2-81	10/17/2020	GIRLS LAV BY 159 RIGHT	2.68	11/11/2020	
20-10-04914-089	169.2-82	10/17/2020	FAC WORK ROOM 159	<1.00	11/11/2020	
20-10-04914-090	169.2-83	10/17/2020	FAC WORK ROOM 155	1.84	11/11/2020	
20-10-04914-091	169.2-84	10/17/2020	BOYS LAV BY 155 LEFT	1.21	11/11/2020	
20-10-04914-092	169.2-85	10/17/2020	BOYS LAV BY 155 LEFT CENTER	1.00	11/11/2020	
20-10-04914-093	169.2-86	10/17/2020	BOYS LAV BY 155 RIGHT CENTER	<1.00	11/11/2020	

Client Number: 33-5980 Report Number: 20-10-04914

Project/Test Address: 2020L-169.2; Lancaster Middle School; 148 Aurora St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04914-094	169.2-88	10/17/2020	BOYS TEAM ROOM	6.25	11/11/2020	
20-10-04914-095	169.2-89	10/17/2020	BOYS LOCKER ROOM HALLWAY LEFT	<1.00	11/11/2020	
20-10-04914-096	169.2-90	10/17/2020	BOYS LOCKER ROOM HALLWAY RIGHT	<1.00	11/11/2020	
20-10-04914-097	169.2-91	10/17/2020	BOYS GRM COACH OFFICE LAV	1.71	11/11/2020	
20-10-04914-098	169.2-92	10/17/2020	BOYS GYM LOCKER VESTIBULE	<1.00	11/11/2020	
20-10-04914-099	169.2-93	10/17/2020	BOYS GYM LOCKER LAV LEFT	2.72	11/11/2020	
20-10-04914-100	169.2-94	10/17/2020	BOYS GYM LOCKER LAV LEFT CENTER	2.85	11/11/2020	
20-10-04914-101	169.2-95	10/17/2020	BOYS GYM LOCKER LAV RIGHT CENTER	1.97	11/11/2020	
20-10-04914-102	169.2-96	10/17/2020	BOYS GYM LOCKER LAV RIGHT	1.92	11/11/2020	
20-10-04914-103	169.2-97A	10/17/2020	CAFE HALLWAY	<1.00	11/11/2020	
20-10-04914-104	169.2-97B	10/17/2020	CAFE HALLWAY	<1.00	11/11/2020	
20-10-04914-105	169.2-98	10/17/2020	ROOM 120	15.4	11/11/2020	
20-10-04914-106	169.2-100	10/17/2020	KITCHEN LAV	2.23	11/11/2020	
20-10-04914-107	169.2-101	10/17/2020	KITCHEN KETTLE SPRAYER	3.58	11/11/2020	
20-10-04914-108	169.2-102	10/17/2020	KITCHEN SINGLE BAY BY KETTLE	1.31	11/11/2020	
20-10-04914-109	169.2-103	10/17/2020	KITCHEN DISH SPRAYER SOUTH WALL LEFT	3.04	11/11/2020	
20-10-04914-110	169.2-104	10/17/2020	KITCHEN DISH SPRAYER SOUTH WALL RIGHT	8.66	11/11/2020	
20-10-04914-111	169.2-105	10/17/2020	KITCHEN DISH SPRAY BY 3 BAY	5.82	11/11/2020	
20-10-04914-112	169.2-106	10/17/2020	KITCHEN FAUCET NEXT TO 3 BAY	4.83	11/11/2020	
20-10-04914-113	169.2-107	10/17/2020	KITCHEN 3 BAY LEFT	6.00	11/11/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-04914

Project/Test Address: 2020L-169.2; Lancaster Middle School; 148 Aurora St; Lancaster, NY 14086

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04914-114	169.2-108	10/17/2020	KITCHEN 3 BAY RIGHT	3.71	11/11/2020	
20-10-04914-115	169.2-109	10/17/2020	KITCHEN HANDWASH BY DISH ROOM	3.14	11/11/2020	
20-10-04914-116	169.2-110	10/17/2020	KITCHEN SPRAYER NEXT TO 2 BAY	13.2	11/11/2020	
20-10-04914-117	169.2-111	10/17/2020	KITCHEN 2 BAY	3.09	11/11/2020	
20-10-04914-118	169.2-112	10/17/2020	KITCHEN HANDWASH BY SERVING	1.28	11/11/2020	
20-10-04914-119	169.2-113A	10/17/2020	CAFE FOUNTAIN	<1.00	11/11/2020	
20-10-04914-120	169.2-113B	10/17/2020	CAFE FOUNTAIN	<1.00	11/11/2020	
20-10-04914-121	169.2-114A	10/17/2020	116 HALLWAY	<1.00	11/11/2020	
20-10-04914-122	169.2-114B	10/17/2020	116 HALLWAY	<1.00	11/11/2020	
20-10-04914-123	169.2-115	10/17/2020	116 HALLWAY LAV	1.83	11/11/2020	

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NY 11714

Reviewed By Authorized Signatory: Melissa Kanode

Missy Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.5 Laboratory Certifications

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER

Expires 12:01 AM April 01, 2021
Issued April 01, 2020

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MS. JULIE DICKERSON
ENVIRONMENTAL HAZARDS SERVICES, LLC
7469 WHITEPINE ROAD
N. CHESTERFIELD, VA 23237

NY Lab Id No: 11714

is hereby APPROVED as an Environmental Laboratory in conformance with the National Environmental Laboratory Accreditation Conference Standards (2003) for the category ENVIRONMENTAL ANALYSES POTABLE WATER
All approved analytes are listed below:

Metals I

Copper, Total	SM 19, 21-23 3113B (-04,-10)
Lead, Total	SM 19, 21-23 3113B (-04,-10)

NEW YORK STATE | Department of Health

Serial No.: 61514

Property of the New York State Department of Health. Certificates are valid only at the address shown, must be conspicuously posted, and are printed on secure paper. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify the laboratory's accreditation status.

NELAP RECOGNIZED TNI ACCREDITATION BODY

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.6 Chains of Custody

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.2

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster Middle School

Location: 148 Aurora St. Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.2-1	3rd Floor Boys Lav	Sink	12:15			
169.2-2A	304 Hallway	DF	12:16			
169.2-2B	304 Hallway	DFB	12:17			
169.2-3A	306 Hallway	DF	12:18			
169.2-3B	306 Halway	DFB	12:19			
169.2-4	3rd Floor Girls Lav	Sink	12:20			
169.2-5	200 Hallway Girls Lav Left	Sink	12:21			
169.2-6	200 Hallway Girls Lav Center	Sink	12:22			
169.2-7	200 Hallway Girls Lav Right	Sink	12:23			
169.2-8A	200 Hallway	DF	12:24			
169.2-8B	200 Hallway	DFB	12:25			
169.2-9	200 Hallway Boys Lav Left	sink	12:26			
169.2-10	200 Hallway Boys Lav Center	SInk	12:27			
169.2-11	200 Hallway Boys Lav Right	Sink	12:28			
169.2-12	206/204 Middle Office Right	Sink	12:29			
169.2-13	206/204 Midde Office Left	Sink	12:30			
169.2-14A	206 Hallway	DF	12:31			
169.2-14B	206 Hallway	DFB	12:32			

20-10-04914

Due Date:
11/19/2020
(Thursday)
AE

Notes:
Please e-mail lab results to labs@stohlenv.com ☑ If checked, also e-mail results to: Ehenderson@StohlEnv.com

Sampled By: Christine Schultz Print Name Stohl Env: Christine Schultz Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KT HARRIS Date: 10.22.20 Time: 1:42 pm

Sample Login (Name / Lab): ALowery Atwery Date: 11/6/20 Time: 3:15 pm

Analysis (Name / Lab): A. Hertzog Date: 11/11/20 Time: 7 pm

QA/QC Review (Name / Lab): Relinquished Date: 11/13/20 Time: Noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.2

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster Middle School

Location: 148 Aurora St. Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.2-15	Art Room 209 Left	Sink	12:33			
169.2-16	Art Room 209 Right	Sink	12:34			
169.2-17	214 Hallway Boys Lav Left	Sink	12:35			
169.2-18A	214 Hallway	DF	12:36			
169.2-18B	214 Hallway	DFB	12:37			
169.2-19A	Library Hallway	DF	12:38			
169.2-19B	Library Hallway	DFB	12:39			
169.2-20	Library Kitchenette	Sink	12:40			
169.2-21	Library Hallway Girls Lav	Sink	12:41			
169.2-22	2nd Floor Fac Lav	Sink	12:42			
169.2-23	2nd Floor Lounge Water Cooler	Water Cooler	12:43			
169.2-24	2nd Flor Lounge Lav	Sink	12:44			
169.2-25	Room 216 East	Sink	12:45			
169.2-26	Room 216 South	Sink	12:46			
169.2-27	Room 216 West	Sink	12:47			
169.2-28	Room 216 North	Sink	12:48			
169.2-29	Room 217 North	Sink	12:49			
169.2-30	Room 217 East	Sink	12:50			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: Christine Schultz Print Name Stohl Env: Christine Schultz Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): K THARRIS [signature] Date: 10-22-20 Time: 1:42pm

Sample Login (Name / Lab): ALowery ALowery Date: 11/6/20 Time: 3:27 PM

Analysis (Name / Lab): [signature] Date: 11/11/20 Time: 7pm

QA/QC Review (Name / Lab): [signature] Date: 11/13/20 Time: Noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.2

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster Middle School

Location: 148 Aurora St. Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.2-31	Room 217 West	Sink	12:51			
169.2-32	Room 218	Sink	12:52			
169.2-33	Room 111	Sink	12:53			
169.2-34	Art Room 112 Far Left	Sink	12:54			
169.2-35	Art Room 112 Far Center	Sink	12:55			
169.2-36	Art Room 112 Far Right	Sink	12:56			
169.2-37	Art Room 112 Close Left	Sink	12:57			
169.2-38	Art Room 112 Close Center	Sink	12:58			
169.2-39	Art Room 112 Close Right	Sink	12:59			
169.2-40	Faculty room by 113 Lav	SInk	13:00			
169.2-41	Music Room 113	Sink	13:01			
169.2-42	Auditorium Girls Lav Left	Sink	13:02			
169.2-43	Auditorium Girls Lav Right	Sink	13:03			
169.2-44	Counseling Center	Sink	13:04			
169.2-45	Admin Office Kitchenette	Sink	13:05			
169.2-46	Admin Office Lav	Sink	13:06			
169.2-47	Auditorium Boys Lav Left	Sink	13:07			
169.2-48	Auditorium Boys Lav right	Sink	13:08			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: Christine Schultz Print Name Stohl Env: Christine Schultz Date: 10/17/2020

Relinquished By: E. Henderson Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KT HARRIS Date: 10-22-20 Time: 1:42 pm

Sample Login (Name / Lab): Traci Blom Date: 11/12/20 Time: 924 Am

Analysis (Name / Lab): J. Dertzler Date: 11/11/20 Time: 7 pm

QA/QC Review (Name / Lab): Mel Date: 11/13/20 Time: Noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.2

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster Middle School

Location: 148 Aurora St. Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.2-49	Copy Room Lav	Sink	13:09			
169.2-51	Room 108A	Sink	13:10			
169.2-52	Room 108	Sink	13:11			
169.2-53	Nurse Ice Machine	IM	13:12			
169.2-54	Nurse Back Lav	Sink	13:13			
169.2-55	Nurse Main Handwash	Sink	13:14			
169.2-56	Nurse Front Lav	Sink	13:15			
169.2-57A	106 Hallway	DF	13:16			
169.2-57B	106 Hallway	DFB	13:17			
169.2-58	104/106 Middle Office Left	Sink	13:18			
169.2-59	104/106 Middle Office Right	Sink	13:19			
169.2-60	100 Hallway Mens Lav Left	Sink	13:20			
169.2-61	100 Hallway Mens Lav Center	Sink	13:21			
169.2-62	100 Hallway Mens Lav Right	Sink	13:22			
169.2-63A	100 Hallway	DF	13:23			
169.2-63B	100 Hallway	DFB	13:24			
169.2-64	100 Hallway Girls Lav Left	Sink	13:25			
169.2-65	100 Hallway Girls Lav Center	Sink	13:26			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: Christine Schultz Print Name Stohl Env: Christine Schultz Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KT HARRIS Date: 10.22.20 Time: 1:42 pm

Sample Login (Name / Lab): [signature] Date: 11/12/20 Time: 9:27 AM

Analysis (Name / Lab): [signature] Date: 11/11/20 Time: 7 pm

QA/QC Review (Name / Lab): [signature] Date: 11/13/20 Time: Noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.2

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster Middle School

Location: 148 Aurora St. Lancaster, NY 14086

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.2-66	100 Hallway Girls Lav Right	Sink	13:27			
169.2-67	Shop Room 164	Sink	13:28			
169.2-68	Girls Locker Room Halway Left	DF	13:29			
169.2-69	Girls Locker Room Hallway Right	DF	13:30			
169.2-70	Girls Team Room	Sink	13:31			
169.2-71	Girls Gym Locker Vestibule Left	DF	13:32			
169.2-72	Girls Gym Locker Vestibu Right	DF	13:33			
169.2-73	Girls Gym Locker Lav Left	Sink	13:34			
169.2-74	Gils Gym Locker Lav Left Center	Sink	13:35			
169.2-75	Girls Gym Locker Lav Right Center	Sink	13:36			
169.2-76	Girls Gym Locker Lav Right	Sink	13:37			
169.2-77	Girls Gym Coach Office Lav	Sink	13:38			
169.2-78	Girls Lav by 159 Left	Sink	13:39			
169.2-79	Girls Lav by 159 Left Center	Sink	13:40			
169.2-80	Girls Lav by 159 Right Center	Sink	13:41			
169.2-81	Girls Lav by 159 Right	Sink	13:42			
169.2-82	Fac Work Room 159	Sink	13:43			
169.2-83	Fac Work Room 155	Sink	13:44			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: Christine Schultz Print Name Stohl Env: Christine Schultz Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KT HARRIS [signature] Date: 10.22.20 Time: 1:42 pm

Sample Login (Name / Lab): [signature] Date: 11/12/20 Time: 929 AM

Analysis (Name / Lab): [signature] Date: 11/11/20 Time: 7 pm

QA/QC Review (Name/Lab): [signature] Date: 11/13/20 Time: Noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.2

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster Middle School

Location: 148 Aurora St. Lancaster, NY 14086

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.2-84	Boys Lav by 155 Left	Sink	13:45			
169.2-85	Boys Lav by 155 Left Center	Sink	13:46			
169.2-86	Boys Lav by 155 Right center	Sink	13:47			
169.2-88	Boys Team Room	Sink	13:48			
169.2-89	Boys Locker Rom Hallway Left	DF	13:49			
169.2-90	Boys Locker Room Hallway Right	DF	13:50			
169.2-91	Boys Gym Coach Office Lav	Sink	13:51			
169.2-92	Boys Gym Locker Vestibule	DF	13:52			
169.2-93	Boys Gym Locker Lav Left	Sink	13:53			
169.2-94	Boys Gym Locker Lav Left Center	Sink	13:54			
169.2-95	Boys Gym Locker Lav Right Center	Sink	13:55			
169.2-96	Boys Gym Locker Lav Right	Sink	13:56			
169.2-97A	Cafe Hallway	DF	13:57			
169.2-97B	Cafe Hallway	DFB	13:58			
169.2-98	Room 120	Sink	13:59			
169.2-100	Kitchen Lav	Sink	14:00			
169.2-101	Kitchen Kettle Sprayer	Sink	14:01			
169.2-102	Kitchen Single Bay by Kettle	Sink	14:02			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: Christine Schultz Print Name Stohl Env: Christine Schultz Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KT HARRIS Date: 10.22.20 Time: 1:42 pm

Sample Login (Name / Lab): [signature] Date: 11/12/20 Time: 931AM

Analysis (Name / Lab): [signature] Date: 11/11/20 Time: 7 pm

QA/QC Review (Name / Lab): [signature] Date: 11/13/20 Time: noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.2

Client: Lancaster CSD Contact: Michael Bryniarski

Building: Lancaster Middle School Location: 148 Aurora St. Lancaster, NY 14086

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.2-103	Kitchen Dish Sprayer South Wall Left	Sink	14:03			
169.2-104	Kitchen Dish Sprayer South Wall Right	Sink	14:04			
169.2-105	Kitchen Dish Spray by 3 Bay	Sink	14:05			
169.2-106	Kitchen Faucet Next to 3 Bay	Sink	14:06			
169.2-107	Kitchen 3 Bay Left	Sink	14:07			
169.2-108	Kitchen 3 Bay Right	Sink	14:08			
169.2-109	Kitchen Handwash by Dish Room	Sink	14:09			
169.2-110	Kitchen Sprayer Next to 2 Bay	Sink	14:10			
169.2-111	Kitchen 2 Bay	Sink	14:11			
169.2-112	Kitchen Handwash by Serving	Sink	14:12			
169.2-113A	Cafe Fountain	DF	14:13			
169.2-113B	Cafe Fountain	DFB	14:14			
169.2-114A	116 Hallway	DF	14:15			
169.2-114B	116 Hallway	DFB	14:16			
169.2-115	116 Hallway Lav	Sink	14:17			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: Christine Schultz Print Name Stohl Env: Christine Schultz Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KT HARRIS [signature] Date: 10-22-20 Time: 1:42 pm

Sample Login (Name / Lab): Traci Bloom Date: 11/12/20 Time: 932 AM

Analysis (Name / Lab): J. Hertzler Date: 11/11/20 Time: 7 pm

QA/QC Review (Name / Lab): [signature] Date: 11/13/20 Time: noon

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____