Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

December 15, 2020

Mr. Michael Bryniarski
Director of Facilities
Lancaster Central School District
177 Central Avenue
Lancaster, NY 14086

RE: Investigation and Sampling of Drinking Water for Lead Concentrations

Dear Mr. Bryniarski:

Included with this letter is Stohl Environmental LLC's report for the Water Sampling performed at the educational buildings of the Lancaster Central School District, including:

- Lancaster High School – 1 Forton Drive, Lancaster, New York.

This report is prepared to assist the District in complying with the requirements of NYS regulations, *SUBPART 67-4: Lead Testing in School Drinking Water*, by identifying the sources of potable water with lead concentrations greater than the NYS "Action Level of 15 parts per billion (ppb)".

The Investigation and Sampling was performed on October 17, 2020. The Protocol for the Investigation followed the requirements of NYS regulations as well as USEPA Technical Guidance Document "3-T's for Reducing Lead in Drinking Water in Schools".

As detailed in Section 1.2 *(Executive Summary)* of the accompanying report, based upon the sampling and analysis performed, 25 sources of potable water in the High School have been identified as having lead concentrations in water above the NYS Action Level of 15 parts per billion. To comply with NYS regulations, Response actions as identified in this report by the District are required.

Thank you for the opportunity to be of service to Lancaster Central School District.

Sincerely,
Stohl Environmental, LLC.



Eric Henderson Jr.
Senior Project Manager

Investigation and Sampling Of Sources of Potable Water For Lead Concentrations

Prepared for:

Lancaster Central School District

Prepared by:

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Conditions as of October 17, 2020

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

Summary Tabulation

Lead in Drinking Water Investigation

1.1. Scope of Work and Sampling Protocol

1.2. Executive Summary of Sampling and Analysis

1.3. Response Actions Required Under NYS Regulations

1.4. Laboratory Analytical Reports by Building

1.5. Laboratory Certifications

1.6. Chains of Custody

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.1 Scope of Work and Sampling Protocol:

Stohl Environmental was retained by Lancaster Central School District to perform sampling and analysis of potable water for elevated lead concentrations. Sampling was performed in the following buildings:

- Lancaster High School – 1 Forton Drive, Lancaster, New York.

Scope of Work:

Stohl Environmental was charged with collecting first-draw water samples from outlets within the High School. Outlets are defined in NYS regulations as: "a potable water fixture currently or potentially used for drinking or cooking purposes, including but not limited to a bubbler, drinking fountain, or faucets".

Sampling Protocol:

In accordance with NYS regulations, ***Subpart 67-4: Lead Testing in School Drinking Water***, and the EPA guidance document, ***'3Ts for Reducing Lead in Drinking Water in Schools"***, Stohl Environmental's protocol can be summarized as follows:

- **First-draw samples** of 250 milliliters (mL) were collected from cold water outlets before any water was used. Sampling was coordinated with District representatives to assure that water was motionless in the pipes for a minimum of 8 hours, but not more than 18 hours before sample collection.

- **Laboratory Analysis:** Samples were submitted following strict chain-of-custody protocols to an independent laboratory approved by the NYS Department of Health's Environmental Laboratory Approval Program (ELAP).

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.2 Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Confirmatory Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb
High School	10/17/2020	238	213	25	N/A	N/A

****** Confirmatory samples are samples collected subsequent to “Step 1” First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Stohl ENVIRONMENTAL

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

Listing of Outlets Requiring Remediation

Locations of Outlets Analyzed above the NYS Action Level of 15 parts per billion based upon Analysis of First Draw Samples:

Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb
169.1-5	Kitchen Center Single Bay	Sink	19.6
169.1-34	Shop Room 168 Center	Sink	36.1
169.1-36	Boys Pool Locker Room	Sink	16.7
169.1-37	Boys Pool Locker Room	DF	30.8
169.1-39	Tech Room 167 Left	Sink	47.0
169.1-42	Tech Room 166 Left	Sink	36.9
169.1-44	Tech Room 166 Right	Sink	15.7
169.1-45	Tech Room 166 Far Right	Bub	26.8
169.1-83	Art Room 151 Front Sink Left	Sink	15.3
169.1-111	Credit Union 140	Sink	17.6
169.1-119	Room 138A	Sink	18.9
169.1-120	Room 136A	Sink	24.5
169.1-150	Room 111A Office Area	Sink	52.1
169.1-152	Room 114A	Sink	15.7
169.1-155	S11/S12 Prep Room	Sink	48.5
169.1-156	S13 Hallway	DF	33.8
169.1-157	Si3/S14 Prep Room	Sink	37.5
169.1-161	Room 128A	Sink	15.3
169.1-171	Room 129 Back	Sink	16.1
169.1-180	Faculty Lav 112A Right	Sink	19.1
169.1-182	2nd Floor North Men's Faculty Lav Center	Sink	35.5
169.1-183	2nd Floor North Men's Faculty Lav Right	Sink	54.4
169.1-184	2nd Floor North Women's Faculty Lav Left	Sink	35.5
169.1-223	Room 217 North	Sink	19.9
169.1-228	Room 221	Sink	16.3

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.3 Response Actions Required Under NYS Regulations, Section 67-4.4:

For outlets analyzed with a lead concentration in excess of the NYS Action Level, regulations require:

(a) Prohibit use of the outlet until:

(1) a lead remediation plan is implemented to mitigate the lead level of such outlet; and

(2) test results indicate that the lead levels are at or below the action level;

(b) provide building occupants with an adequate supply of potable water for drinking and cooking until remediation is performed;

(c) report the test results to the local health department as soon as practicable, but no more than 1 business day after the school received the laboratory report; and

(d) notify all staff and all persons in parental relation to students of the test results, in writing, as soon as practicable but no more than 10 business days after the school received the laboratory report.

Stohl ENVIRONMENTAL
3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.4 Laboratory Analytical Reports by Building

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 20-10-04809

Client: Stohl Environmental
3860 California Road
Orchard Park, NY 14127

Received Date: 10/22/2020
Reported Date: 11/17/2020
Sampled By: C Schultz/P Nichols
Tech Certification #:

Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Client Number: 33-5980

Laboratory Results

Fax Number: 716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-001	169.1-1	10/17/2020	KITCHEN 2 BAY LEFT	<1.00	11/11/2020	
20-10-04809-002	169.1-2	10/17/2020	KITCHEN SINGLE BAY	8.83	11/11/2020	
20-10-04809-003	169.1-3	10/17/2020	KITCHEN DISHWASH 3 BAY LEFT	3.63	11/11/2020	
20-10-04809-004	169.1-4	10/17/2020	KITCHEN DISHWASH 3 BAY RIGHT	5.84	11/11/2020	
20-10-04809-005	169.1-5	10/17/2020	KITCHEN CENTER SINGLE BAY	19.6	11/11/2020	
20-10-04809-006	169.1-6	10/17/2020	KITCHEN KETTLE	9.55	11/11/2020	
20-10-04809-007	169.1-7	10/17/2020	KITCHEN STEAMER	12.4	11/11/2020	
20-10-04809-008	169.1-8	10/17/2020	KITCHEN STAFF LAV	1.78	11/11/2020	
20-10-04809-009	169.1-9	10/17/2020	KITCHEN ICE MACHINE	<1.00	11/11/2020	
20-10-04809-010	169.1-10	10/17/2020	DISH RM SPRAYER	<1.00	11/11/2020	
20-10-04809-011	169.1-11	10/17/2020	DISH RM SINK LEFT	<1.00	11/11/2020	
20-10-04809-012	169.1-12	10/17/2020	DISH RM SINK RIGHT	6.42	11/11/2020	
20-10-04809-013	169.1-13A	10/17/2020	FACULTY DINING RM	4.38	11/11/2020	

Client Number: 33-5980 Report Number: 20-10-04809

Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-014	169.1-13B	10/17/2020	FACULTY DINING RM	2.68	11/11/2020	
20-10-04809-015	169.1-14	10/17/2020	CAFETERIA LEFT FOUNTAIN	2.91	11/11/2020	
20-10-04809-016	169.1-15A	10/17/2020	CAFETERIA RIGHT FOUNTAIN	2.74	11/11/2020	
20-10-04809-017	169.1-15B	10/17/2020	CAFETERIA RIGHT FOUNTAIN	3.09	11/13/2020	
20-10-04809-018	169.1-16	10/17/2020	NORTH ENTRANCE LOBBY LEFT	<1.00	11/13/2020	
20-10-04809-019	169.1-17A	10/17/2020	NORTH ENTRANCE LOBBY RIGHT	<1.00	11/13/2020	
20-10-04809-020	169.1-17B	10/17/2020	NORTH ENTRANCE LOBBY RIGHT	<1.00	11/13/2020	
20-10-04809-021	169.1-18	10/17/2020	GIRLS GYM COACH N13 LAV	<1.00	11/13/2020	
20-10-04809-022	169.1-19	10/17/2020	GIRLS GYM LOCKER RM LEFT	<1.00	11/13/2020	
20-10-04809-023	169.1-20	10/17/2020	GIRLS GYM LOCKER RM RIGHT	<1.00	11/13/2020	
20-10-04809-024	169.1-21	10/17/2020	GIRLS GANG LAV LEFT	<1.00	11/13/2020	
20-10-04809-025	169.1-22	10/17/2020	GIRLS GANG LAV LEFT CENTER	<1.00	11/13/2020	
20-10-04809-026	169.1-23	10/17/2020	GIRLS GANG LAV RIGHT CENTER	<1.00	11/13/2020	
20-10-04809-027	169.1-24	10/17/2020	GIRLS GANG LAV RIGHT	<1.00	11/13/2020	
20-10-04809-028	169.1-25	10/17/2020	SINGLE LAV LEFT OF N16	<1.00	11/13/2020	
20-10-04809-029	169.1-26	10/17/2020	BOYS GANG LAV LEFT	<1.00	11/13/2020	
20-10-04809-030	169.1-27	10/17/2020	BOYS GANG LAV CENTER	<1.00	11/13/2020	
20-10-04809-031	169.1-28	10/17/2020	BOYS GANG LAV RIGHT	<1.00	11/13/2020	
20-10-04809-032	169.1-29	10/17/2020	BOYS GYM LOCKER RM LEFT	<1.00	11/13/2020	
20-10-04809-033	169.1-30	10/17/2020	BOYS GYM LOCKER RM RIGHT	<1.00	11/13/2020	

Client Number: 33-5980 Report Number: 20-10-04809

Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-034	169.1-31	10/17/2020	BOYS GYM COACH N18 LAV	<1.00	11/13/2020	
20-10-04809-035	169.1-32	10/17/2020	LAUNDRY N19 HANDWASH	2.62	11/13/2020	
20-10-04809-036	169.1-33	10/17/2020	SHOP RM 168 LEFT	1.98	11/13/2020	
20-10-04809-037	169.1-34	10/17/2020	SHOP RM 168 CENTER	36.1	11/13/2020	
20-10-04809-038	169.1-35	10/17/2020	SHOP RM 168 RIGHT	2.08	11/13/2020	
20-10-04809-039	169.1-36	10/17/2020	BOYS POOL LOCKER RM	16.7	11/13/2020	
20-10-04809-040	169.1-37	10/17/2020	BOYS POOL LOCKER RM	30.8	11/13/2020	
20-10-04809-041	169.1-38	10/17/2020	BOYS VESTIBULE LAV	7.34	11/13/2020	
20-10-04809-042	169.1-39	10/17/2020	TECH RM 167 LEFT	47.0	11/13/2020	
20-10-04809-043	169.1-40	10/17/2020	TECH RM 167 CENTER	<1.00	11/13/2020	
20-10-04809-044	169.1-41	10/17/2020	TECH RM 167 RIGHT	3.14	11/13/2020	
20-10-04809-045	169.1-42	10/17/2020	TECH RM 166 LEFT	36.9	11/13/2020	
20-10-04809-046	169.1-43	10/17/2020	TECH RM 166 CENTER	10.2	11/13/2020	
20-10-04809-047	169.1-44	10/17/2020	TECH RM 166 RIGHT	15.7	11/13/2020	
20-10-04809-048	169.1-45	10/17/2020	TECH RM 166 FAR RIGHT	26.8	11/13/2020	
20-10-04809-049	169.1-46	10/17/2020	POOL/166 HALLWAY	1.74	11/13/2020	
20-10-04809-050	169.1-47	10/17/2020	FIELD HOUSE HALLWAY LAV	4.08	11/13/2020	
20-10-04809-051	169.1-49	10/17/2020	SHOP RM 153 CENTER	<1.00	11/13/2020	
20-10-04809-052	169.1-50	10/17/2020	SHOP RM 153 RIGHT	<1.00	11/13/2020	
20-10-04809-053	169.1-51	10/17/2020	ART RM 151	8.14	11/13/2020	

Client Number: 33-5980 Report Number: 20-10-04809

Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-054	169.1-52	10/17/2020	BOYS FH LOCKER 1 LEFT	9.55	11/13/2020	
20-10-04809-055	169.1-53	10/17/2020	BOYS FH LOCKER 1 L CENTER	5.39	11/13/2020	
20-10-04809-056	169.1-54	10/17/2020	BOYS FH LOCKER 1 R CENTER	5.43	11/13/2020	
20-10-04809-057	169.1-55	10/17/2020	BOYS FH LOCKER 1 RIGHT	5.22	11/13/2020	
20-10-04809-058	169.1-56	10/17/2020	GIRLS FH LOCKER 1 LEFT	9.95	11/13/2020	
20-10-04809-059	169.1-57	10/17/2020	GIRLS FH LOCKER 1 L CENTER	4.11	11/13/2020	
20-10-04809-060	169.1-58	10/17/2020	GIRLS FH LOCKER 1 R CENTER	5.10	11/13/2020	
20-10-04809-061	169.1-59	10/17/2020	GIRLS FH LOCKER 1 RIGHT	3.06	11/13/2020	
20-10-04809-062	169.1-60	10/17/2020	BOYS FH LOCKER 2 LEFT	3.89	11/13/2020	
20-10-04809-063	169.1-61	10/17/2020	BOYS FH LOCKER 2 L CENTER	3.84	11/13/2020	
20-10-04809-064	169.1-62	10/17/2020	BOYS FH LOCKER 2 R CENTER	2.53	11/13/2020	
20-10-04809-065	169.1-63	10/17/2020	BOYS FH LOCKER 2 RIGHT	5.46	11/13/2020	
20-10-04809-066	169.1-64	10/17/2020	GIRLS FH LOCKER 2 LEFT	4.33	11/13/2020	
20-10-04809-067	169.1-65	10/17/2020	GIRLS FH LOCKER 2 L CENTER	1.70	11/13/2020	
20-10-04809-068	169.1-66	10/17/2020	GIRLS FH LOCKER 2 R CENTER	2.12	11/13/2020	
20-10-04809-069	169.1-67	10/17/2020	GIRLS FH LOCKER 2 RIGHT	3.98	11/13/2020	
20-10-04809-070	169.1-68	10/17/2020	TRAINERS RM 157 ICE	<1.00	11/13/2020	
20-10-04809-071	169.1-69	10/17/2020	TRAINERS RM 157	<1.00	11/13/2020	
20-10-04809-072	169.1-70	10/17/2020	GIRLS COACH'S OFFICE 159	3.55	11/13/2020	
20-10-04809-073	169.1-71	10/17/2020	BOYS COACH'S OFFICE 160	1.66	11/13/2020	

Client Number: 33-5980 Report Number: 20-10-04809

Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-074	169.1-72A	10/17/2020	FIELD HOUSE FOUNTAIN LEFT	<1.00	11/13/2020	
20-10-04809-075	169.1-72B	10/17/2020	FIELD HOUSE FOUNTAIN LEFT	<1.00	11/13/2020	
20-10-04809-076	169.1-73A	10/17/2020	FIELD HOUSE FOUNTAIN RIGHT	<1.00	11/13/2020	
20-10-04809-077	169.1-73B	10/17/2020	FIELD HOUSE FOUNTAIN RIGHT	<1.00	11/13/2020	
20-10-04809-078	169.1-74	10/17/2020	FIELD HOUSE MEN'S LAV LEFT	3.54	11/13/2020	
20-10-04809-079	169.1-75	10/17/2020	FH MEN'S LAV L CENTER	2.00	11/13/2020	
20-10-04809-080	169.1-76	10/17/2020	FH MEN'S LAV R CENTER	2.93	11/13/2020	
20-10-04809-081	169.1-77	10/17/2020	FH MEN'S LAV RIGHT	2.73	11/13/2020	
20-10-04809-082	169.1-78	10/17/2020	FH WOMEN'S LAV LEFT	13.1	11/13/2020	
20-10-04809-083	169.1-78	10/17/2020	FH WOMEN'S LAV L CENTER	4.92	11/13/2020	
20-10-04809-084	169.1-80	10/17/2020	FH WOMEN'S LAV R CENTER	4.51	11/13/2020	
20-10-04809-085	169.1-81	10/17/2020	FH WOMEN'S LAV RIGHT	5.52	11/13/2020	
20-10-04809-086	169.1-82	10/17/2020	MUSIC RM 174.4	1.05	11/13/2020	
20-10-04809-087	169.1-83	10/17/2020	ART RM 151 FRONT SINK LEFT	15.3	11/13/2020	
20-10-04809-088	169.1-84	10/17/2020	ART RM 151 FRONT SINK CENTER	3.96	11/13/2020	
20-10-04809-089	169.1-85	10/17/2020	ART RM 151 FRONT SINK RIGHT	12.0	11/13/2020	
20-10-04809-090	169.1-86	10/17/2020	ART RM 151 BACK SINK LEFT	6.93	11/13/2020	
20-10-04809-091	169.1-87	10/17/2020	ART RM 151 BACK SINK CENTER	2.02	11/13/2020	
20-10-04809-092	169.1-88	10/17/2020	ART RM 151 BACK SINK RIGHT	11.9	11/13/2020	
20-10-04809-093	169.1-89	10/17/2020	ART RM 150 FRONT SINK LEFT	4.89	11/13/2020	

Client Number: 33-5980 Report Number: 20-10-04809

Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-094	169.1-90	10/17/2020	ART RM 150 FRONT SINK CENTER	6.09	11/13/2020	
20-10-04809-095	169.1-91	10/17/2020	ART RM 150 FRONT SINK RIGHT	4.15	11/13/2020	
20-10-04809-096	169.1-92	10/17/2020	ART RM 150 BACK SINK LEFT	2.31	11/13/2020	
20-10-04809-097	169.1-93	10/17/2020	ART RM 150 BACK SINK CENTER	1.55	11/13/2020	
20-10-04809-098	169.1-94	10/17/2020	ART RM 150 BACK SINK RIGHT	<1.00	11/13/2020	
20-10-04809-099	169.1-95A	10/17/2020	ART RM 150 HALLWAY	<1.00	11/13/2020	
20-10-04809-100	169.1-95B	10/17/2020	ART RM 150 HALLWAY	<1.00	11/13/2020	
20-10-04809-101	169.1-96	10/17/2020	STAGE RM 174.3	2.95	11/13/2020	
20-10-04809-102	169.1-97	10/17/2020	ART RM 149 LEFT	12.2	11/13/2020	
20-10-04809-103	169.1-98	10/17/2020	ART RM 149 LEFT CENTER	3.27	11/13/2020	
20-10-04809-104	169.1-99	10/17/2020	ART RM 149 RIGHT CENTER	2.25	11/13/2020	
20-10-04809-105	169.1-100	10/17/2020	ART RM 149 RIGHT	13.4	11/13/2020	
20-10-04809-106	169.1-101	10/17/2020	ART RM 147 HALLWAY	3.91	11/13/2020	
20-10-04809-107	169.1-102	10/17/2020	ART RM 147 LEFT	14.4	11/13/2020	
20-10-04809-108	169.1-103	10/17/2020	ART RM 147 RIGHT	5.94	11/13/2020	
20-10-04809-109	169.1-104	10/17/2020	RM 146	11.3	11/13/2020	
20-10-04809-110	169.1-105	10/17/2020	RM 145	2.06	11/13/2020	
20-10-04809-111	169.1-106	10/17/2020	RM 143B	3.48	11/13/2020	
20-10-04809-112	169.1-107	10/17/2020	RM 143 HALLWAY	3.58	11/13/2020	
20-10-04809-113	169.1-108	10/17/2020	143 HALL WOMEN'S FAC LEFT	7.36	11/13/2020	

Client Number: 33-5980 Report Number: 20-10-04809

Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-114	169.1-109	10/17/2020	143 HALL WOMEN'S FAC RIGHT	5.26	11/13/2020	
20-10-04809-115	169.1-110	10/17/2020	143 HALLWAY MEN'S FAC LEFT	5.63	11/13/2020	
20-10-04809-116	169.1-111	10/17/2020	CREDIT UNION 140	17.6	11/13/2020	
20-10-04809-117	169.1-112	10/17/2020	BOYS LAV B7	1.76	11/13/2020	
20-10-04809-118	169.1-113	10/17/2020	RM 138 HALLWAY	<1.00	11/13/2020	
20-10-04809-119	169.1-114	10/17/2020	GIRLS LAV G7 LEFT	9.82	11/13/2020	
20-10-04809-120	169.1-115	10/17/2020	GIRLS LAV G7 CENTER	5.12	11/13/2020	
20-10-04809-121	169.1-116	10/17/2020	GIRLS LAV G7 RIGHT	2.63	11/13/2020	
20-10-04809-122	169.1-117	10/17/2020	RM 141 LEFT	5.69	11/13/2020	
20-10-04809-123	169.1-118	10/17/2020	RM 141 RIGHT	2.56	11/13/2020	
20-10-04809-124	169.1-119	10/17/2020	RM 138A	18.9	11/13/2020	
20-10-04809-125	169.1-120	10/17/2020	RM 136A	24.5	11/13/2020	
20-10-04809-126	169.1-121	10/17/2020	RM 133 HALLWAY	2.33	11/13/2020	
20-10-04809-127	169.1-122	10/17/2020	FITNESS CENTER 163	1.08	11/13/2020	
20-10-04809-128	169.1-123	10/17/2020	FITNESS CENTER/POOL HALLWAY	14.4	11/13/2020	
20-10-04809-129	169.1-124	10/17/2020	GIRLS POOL LOCKER RM	11.8	11/13/2020	
20-10-04809-130	169.1-125	10/17/2020	GIRLS POOL LOCKER RM	11.6	11/13/2020	
20-10-04809-131	169.1-126	10/17/2020	GIRLS POOL VESTIBULE	3.41	11/13/2020	
20-10-04809-132	169.1-127A	10/17/2020	RM 174 HALLWAY	<1.00	11/13/2020	
20-10-04809-133	169.1-127B	10/17/2020	RM 174 HALLWAY	<1.00	11/13/2020	

Client Number: 33-5980 Report Number: 20-10-04809

Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-134	169.1-128	10/17/2020	ACCESSIBLE LAV	5.87	11/13/2020	
20-10-04809-135	169.1-129	10/17/2020	MENS MAIN OFFICE FRONT LEFT	2.14	11/13/2020	
20-10-04809-136	169.1-130	10/17/2020	MENS MO BACK LEFT	5.98	11/13/2020	
20-10-04809-137	169.1-131	10/17/2020	MENS MO BACK RIGHT	3.98	11/13/2020	
20-10-04809-138	169.1-132	10/17/2020	MENS MO FRONT RIGHT	1.68	11/13/2020	
20-10-04809-139	169.1-133	10/17/2020	WOMENS MAIN OFFICE LEFT	3.54	11/13/2020	
20-10-04809-140	169.1-134	10/17/2020	WOMEN'S MAIN OFFICE CENTER	1.16	11/13/2020	
20-10-04809-141	169.1-135	10/17/2020	WOMEN'S MAIN OFFICE RIGHT	1.07	11/13/2020	
20-10-04809-142	169.1-136	10/17/2020	PRINCIPALS OFFICE LAV	3.11	11/13/2020	
20-10-04809-143	169.1-137	10/17/2020	MAIN OFFICE LAV	2.48	11/13/2020	
20-10-04809-144	169.1-138A	10/17/2020	MAIN OFFICE HALLWAY	<1.00	11/13/2020	
20-10-04809-145	169.1-138B	10/17/2020	MAIN OFFICE HALLWAY	<1.00	11/13/2020	
20-10-04809-146	169.1-139	10/17/2020	RM 184 LOUNGE	<1.00	11/13/2020	
20-10-04809-147	169.1-140	10/17/2020	NURSE OFFICE LAV	<1.00	11/13/2020	
20-10-04809-148	169.1-141	10/17/2020	NURSE OFFICE KTICHEN	<1.00	11/13/2020	
20-10-04809-149	169.1-142	10/17/2020	RM 102 HALLWAY LAV	3.65	11/13/2020	
20-10-04809-150	169.1-143	10/17/2020	RM 105 HALLWAY	<1.00	11/13/2020	
20-10-04809-151	169.1-144	10/17/2020	LADIES LAV G3 LEFT	7.36	11/13/2020	
20-10-04809-152	169.1-145	10/17/2020	LADIES LAV G3 CENTER	9.32	11/13/2020	
20-10-04809-153	169.1-146	10/17/2020	LADIES LAV G3 RIGHT	2.77	11/13/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-04809

Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-154	169.1-147	10/17/2020	MENS LAV B3 LEFT	3.88	11/13/2020	
20-10-04809-155	169.1-148	10/17/2020	MENS LAV B3 CENTER	2.92	11/13/2020	
20-10-04809-156	169.1-149	10/17/2020	MENS LAV B3 RIGHT	2.52	11/13/2020	
20-10-04809-157	169.1-150	10/17/2020	RM 111A OFFICE AREA	52.1	11/13/2020	
20-10-04809-158	169.1-151	10/17/2020	RM 114	14.3	11/13/2020	
20-10-04809-159	169.1-152	10/17/2020	RM 114A	15.7	11/13/2020	
20-10-04809-160	169.1-153	10/17/2020	RM 116 HALLWAY	1.06	11/13/2020	
20-10-04809-161	169.1-154	10/17/2020	RM 116	10.4	11/13/2020	
20-10-04809-162	169.1-155	10/17/2020	S11/S12 PREP RM	48.5	11/13/2020	
20-10-04809-163	169.1-156	10/17/2020	S13 HALLWAY	33.8	11/13/2020	
20-10-04809-164	169.1-157	10/17/2020	S13/S14 PREP RM	37.5	11/13/2020	
20-10-04809-165	169.1-158	10/17/2020	S15/S16 PREP RM	14.4	11/13/2020	
20-10-04809-166	169.1-159	10/17/2020	RM 124	<1.00	11/13/2020	
20-10-04809-167	169.1-160	10/17/2020	RM 125 HALLWAY	<1.00	11/13/2020	
20-10-04809-168	169.1-161	10/17/2020	RM 128A	15.3	11/13/2020	
20-10-04809-169	169.1-162	10/17/2020	BOYS LAV B5 LEFT	8.37	11/13/2020	
20-10-04809-170	169.1-163	10/17/2020	BOYS LAV B5 RIGHT	7.13	11/13/2020	
20-10-04809-171	169.1-164	10/17/2020	GIRLS LAV G5 LEFT	8.66	11/13/2020	
20-10-04809-172	169.1-165	10/17/2020	GIRLS LAV G5 CENTER	5.45	11/13/2020	
20-10-04809-173	169.1-166	10/17/2020	GIRLS LAV G5 RIGHT	10.5	11/13/2020	

Client Number: 33-5980 Report Number: 20-10-04809

Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-174	169.1-167	10/17/2020	RM 128 FRONT	14.2	11/13/2020	
20-10-04809-175	169.1-168	10/17/2020	RM 128 BACK	3.93	11/13/2020	
20-10-04809-176	169.1-169	10/17/2020	RM 130A	9.27	11/13/2020	
20-10-04809-177	169.1-170	10/17/2020	RM 129 FRONT	2.70	11/13/2020	
20-10-04809-178	169.1-171	10/17/2020	RM 129 BACK	16.1	11/13/2020	
20-10-04809-179	169.1-172	10/17/2020	RM 131A	11.2	11/13/2020	
20-10-04809-180	169.1-173	10/17/2020	RM 130 FRONT	3.95	11/13/2020	
20-10-04809-181	169.1-174	10/17/2020	RM 130 NORTH WALL CENTER	10.3	11/13/2020	
20-10-04809-182	169.1-175	10/17/2020	RM 131 FRONT	5.17	11/13/2020	
20-10-04809-183	169.1-176	10/17/2020	RM 131 BACK	7.91	11/13/2020	
20-10-04809-184	169.1-177	10/17/2020	FAC LAV 112B LEFT	3.56	11/13/2020	
20-10-04809-185	169.1-178	10/17/2020	FAC LAV 112B RIGHT	2.90	11/13/2020	
20-10-04809-186	169.1-179	10/17/2020	FAC LAV 112A LEFT	12.6	11/13/2020	
20-10-04809-187	169.1-180	10/17/2020	FAC LAV 112A RIGHT	19.1	11/13/2020	
20-10-04809-188	169.1-181	10/17/2020	2ND FL NORTH MENS FAC LEFT	14.8	11/13/2020	
20-10-04809-189	169.1-182	10/17/2020	2ND FL N MENS FAC CENTER	35.5	11/13/2020	
20-10-04809-190	169.1-183	10/17/2020	2ND FL N MENS FAC RIGHT	54.4	11/13/2020	
20-10-04809-191	169.1-184	10/17/2020	2ND FL N WOMEN'S FAC LEFT	35.5	11/13/2020	
20-10-04809-192	169.1-185	10/17/2020	2ND FL N WO FAC LEFT CENTER	12.0	11/13/2020	
20-10-04809-193	169.1-186	10/17/2020	2ND FL N WO FAC RIGHT CENTER	5.99	11/13/2020	

Client Number: 33-5980 Report Number: 20-10-04809
Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-194	169.1-187	10/17/2020	2ND FL N WOMEN'S FAC RIGHT	3.11	11/13/2020	
20-10-04809-195	169.1-188	10/17/2020	RM 200.10	6.81	11/13/2020	
20-10-04809-196	169.1-189	10/17/2020	RM 200.10 HALLWAY	2.32	11/13/2020	
20-10-04809-197	169.1-190	10/17/2020	RM 207 HALLWAY	<1.00	11/13/2020	
20-10-04809-198	169.1-191	10/17/2020	GIRLS LAV G4 LEFT	6.27	11/13/2020	
20-10-04809-199	169.1-192	10/17/2020	GIRLS LAV G4 CENTER	2.21	11/16/2020	
20-10-04809-200	169.1-193	10/17/2020	GIRLS LAV G4 RIGHT	3.07	11/13/2020	
20-10-04809-201	169.1-194	10/17/2020	BOYS LAV B4 LEFT	4.42	11/13/2020	
20-10-04809-202	169.1-195	10/17/2020	BOYS LAV B4 CENTER	3.51	11/13/2020	
20-10-04809-203	169.1-196	10/17/2020	BOYS LAV B4 RIGHT	6.40	11/13/2020	
20-10-04809-204	169.1-197	10/17/2020	RM 210	6.00	11/13/2020	
20-10-04809-205	169.1-199	10/17/2020	FAC RM 243 LADIES LAV	2.95	11/13/2020	
20-10-04809-206	169.1-200	10/17/2020	FAC RM 243 MENS LAV	4.28	11/13/2020	
20-10-04809-207	169.1-201	10/17/2020	FAC RM 243 KITCHENETTE	1.17	11/13/2020	
20-10-04809-208	169.1-202	10/17/2020	BOYS LAV B8 LEFT	4.47	11/13/2020	
20-10-04809-209	169.1-203	10/17/2020	BOYS LAV B8 CENTER	3.14	11/13/2020	
20-10-04809-210	169.1-204	10/17/2020	BOYS LAV B8 RIGHT	1.51	11/13/2020	
20-10-04809-211	169.1-205	10/17/2020	BETWEEN LAVS B8 AND G8	1.20	11/13/2020	
20-10-04809-212	169.1-206	10/17/2020	GIRLS LAV G8 LEFT	<1.00	11/13/2020	
20-10-04809-213	169.1-207	10/17/2020	GIRLS LAV G8 CENTER	4.77	11/13/2020	

Client Number: 33-5980 Report Number: 20-10-04809
Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-214	169.1-208	10/17/2020	GIRLS LAV G8 RIGHT	6.29	11/13/2020	
20-10-04809-215	169.1-209	10/17/2020	RM 233 HALLWAY	2.49	11/13/2020	
20-10-04809-216	169.1-210	10/17/2020	RM 227 HALLWAY	1.00	11/13/2020	
20-10-04809-217	169.1-211	10/17/2020	GIRLS LAV G6 LEFT	5.84	11/13/2020	
20-10-04809-218	169.1-212	10/17/2020	GIRLS LAV G6 CENTER	1.61	11/13/2020	
20-10-04809-219	169.1-213	10/17/2020	GIRLS LAV G6 RIGHT	2.01	11/13/2020	
20-10-04809-220	169.1-214	10/17/2020	BOYS LAV B6 LEFT	2.24	11/13/2020	
20-10-04809-221	169.1-215	10/17/2020	BOYS LAV B6 RIGHT	3.09	11/13/2020	
20-10-04809-222	169.1-216	10/17/2020	BOYS SOUTH LAV LEFT	<1.00	11/13/2020	
20-10-04809-223	169.1-217	10/17/2020	BOYS SOUTH LAV RIGHT	<1.00	11/13/2020	
20-10-04809-224	169.1-218	10/17/2020	SOUTH END LOBBY LEFT	<1.00	11/13/2020	
20-10-04809-225	169.1-219	10/17/2020	SOUTH END LOBBY RIGHT	<1.00	11/13/2020	
20-10-04809-226	169.1-220	10/17/2020	GIRLS SOUTH LAV LEFT	1.56	11/13/2020	
20-10-04809-227	169.1-221	10/17/2020	GIRLS SOUTH LAV RIGHT	1.71	11/13/2020	
20-10-04809-228	169.1-222	10/17/2020	RM 216	8.62	11/13/2020	
20-10-04809-229	169.1-223	10/17/2020	RM 217 NORTH	19.9	11/13/2020	
20-10-04809-230	169.1-224	10/17/2020	RM 217 SOUTH	6.40	11/13/2020	
20-10-04809-231	169.1-225	10/17/2020	RM 217 SOUTHWEST	12.5	11/13/2020	
20-10-04809-232	169.1-226	10/17/2020	RM 217 NORTHWEST	10.8	11/13/2020	
20-10-04809-233	169.1-228	10/17/2020	RM 221.2	16.3	11/13/2020	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 Report Number: 20-10-04809

Project/Test Address: 2020L-169.1; Lancaster High School; 1 Forton Drive; Lancaster, NY

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
20-10-04809-234	169.1-229	10/17/2020	MEDIA CENTER 245.2	2.76	11/13/2020	
20-10-04809-235	169.1-230	10/17/2020	BSMT RIFLE RANGE HALLWAY	5.68	11/13/2020	
20-10-04809-236	169.1-231	10/17/2020	BSMT RIFLE RANGE HALLWAY	5.03	11/13/2020	
20-10-04809-237	169.1-232	10/17/2020	BASEMENT LAUNDRY RM	5.43	11/13/2020	
20-10-04809-238	169.1-233	10/17/2020	BASEMENT STAFF LAV	9.10	11/13/2020	

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NY 11714

Reviewed By Authorized Signatory: Melissa Kanode

Missy Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.5 Laboratory Certifications

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER

Expires 12:01 AM April 01, 2021
Issued April 01, 2020

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MS. JULIE DICKERSON
ENVIRONMENTAL HAZARDS SERVICES, LLC
7469 WHITEPINE ROAD
N. CHESTERFIELD, VA 23237

NY Lab Id No: 11714

is hereby APPROVED as an Environmental Laboratory in conformance with the National Environmental Laboratory Accreditation Conference Standards (2003) for the category ENVIRONMENTAL ANALYSES POTABLE WATER
All approved analytes are listed below:

Metals I

Copper, Total	SM 19, 21-23 3113B (-04,-10)
Lead, Total	SM 19, 21-23 3113B (-04,-10)

NEW YORK STATE | Department of Health

Serial No.: 61514

Property of the New York State Department of Health. Certificates are valid only at the address shown, must be conspicuously posted, and are printed on secure paper. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify the laboratory's accreditation status.

NELAP RECOGNIZED TNI ACCREDITATION BODY

3860 California Road
Orchard Park, New York 14127
(P) 716-312-0070 (F) 716-312-8092
www.stohlenvironmental.com

1.6 Chains of Custody

Chain of Custody Document

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-1	Kitchen 2 Bay Left	Sink	8:00			
169.1-2	Kitchen Single Bay	Sink	8:01			
169.1-3	Kitchen Dishwash 3 Bay Left	Sink	8:02			
169.1-4	Kitchen Dishwash 3 Bay Right	Sink	8:03			
169.1-5	Kitchen Center Single Bay	Sink	8:04			
169.1-6	Kitchen Kettle	Sink	8:05			
169.1-7	Kitchen Steamer	Sink	8:06			
169.1-8	Kitchen Staff Lav	Sink	8:07			
169.1-9	Kitchen Ice Machine	IM	8:08			
169.1-10	Dish Rm Sprayer	Sink	8:09			
169.1-11	Dish Rm Sink Left	Sink	8:10			
169.1-12	Dish Rm Sink Right	Sink	8:11			
169.1-13A	Faculty Dining Rm	DFA	8:12			
169.1-13B	Faculty Dining Rm	DFB	8:13			
169.1-14	Cafeteria Left Fountain	DFA	8:14			
169.1-15A	Cafeteria Right Fountain	DFA	8:15			
169.1-15B	Cafeteria Right Fountain	DFB	8:16			
169.1-16	North Entrance Lobby Left	DFA	8:17			

20-10-04809

Due Date:
11/19/2020
(Thursday)
AE

Notes:
Please e-mail lab results to labs@stohlenv.com ☑ If checked, also e-mail results to: Ehenderson@StohlEnv.com

Sampled By:	C. Schultz, P. Nichols	Print Name	Stohl Env: C. Schultz, P. Nichols	Date:	10/17/2020
Relinquished By:		Print Name	Stohl Env: Eric Henderson Jr.	Date:	10/19/2020
Received (Name / Lab):	KT HARRIS		Date: 10/21/20	Time:	11:32 AM
Sample Login (Name / Lab):	Traci Bloom		Date: Traci Bloom	Time:	329PM
Analysis (Name / Lab):			Date: 11/16/20	Time:	8:40 am
QA/QC Review (Name / Lab):			Date: 11/17/20	Time:	3pm
Archived / Released:		QA/QC InterLAB Use:	Date:	Time:	

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-17A	North Entrance Lobby Right	DFA	8:18			
169.1-17B	North Entrance Lobby Right	DFB	8:19			
169.1-18	Girl's Gym Coach N13 Lav	Sink	8:20			
169.1-19	Girls Gym Locker Rm Left	Sink	8:21			
169.1-20	Girls Gym Locker Rm Right	Sink	8:22			
169.1-21	Girls Gang Lav Left	Sink	8:23			
169.1-22	Girls Gang Lav Left Center	Sink	8:24			
169.1-23	Girls Gang Lav Right Center	Sink	8:25			
169.1-24	Girls Gang Lav Right	Sink	8:26			
169.1-25	Single Lav Left of N16	Sink	8:27			
169.1-26	Boys Gang Lav Left	Sink	8:28			
169.1-27	Boys Gang Lav Center	Sink	8:29			
169.1-28	Boys Gang Lav Right	Sink	8:30			
169.1-29	Boys Gym Locker Rm Left	Sink	8:31			
169.1-30	Boys Gym Locker Rm Right	Sink	8:32			
169.1-31	Boys Gym Coach N18 Lav	Sink	8:33			
169.1-32	Laundry N19 Handwash	Sink	8:34			
169.1-33	Shop Rm 168 Left	Sink	8:35			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KTHARRIS [signature] Date: 10-22-20 Time: 11:33 am

Sample Login (Name / Lab): Traci Blann [signature] Date: 11/6/20 Time: 351 PM

Analysis (Name / Lab): [signature] Date: 11/16/20 Time: 8:40 am

QA/QC Review (Name / Lab): [signature] Date: 11/17/20 Time: 3pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-34	Shop Rm 168 Center	Sink	8:36			
169.1-35	Shop Rm 168 Right	Sink	8:37			
169.1-36	Boys Pool Locker Rm	Sink	8:38			
169.1-37	Boys Pool Locker Rm	DFA	8:39			
169.1-38	Boys Vestibule Lav	Sink	8:40			
169.1-39	Tech Rm 167 Left	Sink	8:41			
169.1-40	Tech Rm 167 Center	Sink	8:42			
169.1-41	Tech Rm 167 Right	Sink	8:43			
169.1-42	Tech Rm 166 Left	Sink	8:44			
169.1-43	Tech Rm 166 center	Sink	8:45			
169.1-44	Tech Rm 166 Right	Sink	8:46			
169.1-45	Tech Rm 166 Far Right	Bubbler	8:47			
169.1-46	Pool/ 166 Hallway	DFA	8:48			
169.1-47	Field House Hallway Lav	Sink	8:49			
169.1-49	Shop Rm 153 Center	Sink	8:50			
169.1-50	Shop Rm 153 Right	Sink	8:51			
169.1-51	Art Rm 151	Sink	8:52			
169.1-52	Boys FH Locker 1 Left	Sink	8:53			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: E. Henderson Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KTHARRIS K Harris Date: 10.22.20 Time: 11:32 AM

Sample Login (Name / Lab): Traci Blom Traci Blom Date: 11/6/20 Time: 334PM

Analysis (Name / Lab): J. Hertzler Date: 11/16/20 Time: 8:40 am

QA/QC Review (Name / Lab): Date: 11/17/20 Time: 3pm

Archived / Released: QA/QC InterLAB Use: Date: Time:

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-53	Boy FH Locker 1 L Center	Sink	8:54			
169.1-54	Boys FH Locker 1 R Center	Sink	8:55			
169.1-55	Boys FH Locker 1 Right	Sink	8:56			
169.1-56	Girls FH Locker 1 Left	Sink	8:57			
169.1-57	Girls FH Locker 1 L Center	Sink	8:58			
169.1-58	Girls FH Locker 1 R Center	Sink	8:59			
169.1-59	Girls FH Locker 1 Right	Sink	9:00			
169.1-60	Boys FH Locker 2 Left	Sink	9:01			
169.1-61	Boys FH Locker 2 L Center	Sink	9:02			
169.1-62	Boys FH Locker 2 R Center	Sink	9:03			
169.1-63	Boys FH Locker 2 Right	Sink	9:04			
169.1-64	Girls FH Locker 2 Left	Sink	9:05			
169.1-65	Girls FH Locker 2 L Center	Sink	9:06			
169.1-66	Girls FH Locker 2 R Center	Sink	9:07			
169.1-67	Girls FH Locker 2 Right	Sink	9:08			
169.1-68	Trainers Rm 157 Ice	IM	9:09			
169.1-69	Trainers Rm 157	Sink	9:10			
169.1-70	Girls Coach's Office 159	Sink	9:11			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name — Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: E. Henderson Print Name — Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KT HARRIS E. Henderson Date: 10/22/20 Time: 10:32 AM

Sample Login (Name / Lab): Trai Bon Flaci Bon Date: 11/16/20 Time: 336PM

Analysis (Name / Lab): G. Hertzler Date: 11/16/20 Time: 8:40 am

QA/QC Review (Name / Lab): [illegible] Date: 11/17/20 Time: 3pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD Contact: Michael Bryniarski

Building: Lancaster High School Location: 1 Forton Drive, Lancaster NY

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-71	Boys Coach's Office 160	Sink	9:12			
169.1-72A	Field House Fountain Left	DFA	9:13			
169.1-72B	Field House Fountain Left	DFB	9:14			
169.1-73A	Field House Fountain Right	DFA	9:15			
169.1-73B	Field House Fountain Right	DFB	9:16			
169.1-74	Field House Men's Lav Left	Sink	9:17			
169.1-75	FH Men's Lav L Center	Sink	9:18			
169.1-76	FH Men's Lav R Center	Sink	9:19			
169.1-77	FH Men's Lav Right	Sink	9:20			
169.1-78	FH Women's Lav Left	Sink	9:21			
169.1-79	FH Women's Lav L Center	Sink	9:22			
169.1-80	FH Women's Lav R Center	Sink	9:23			
169.1-81	FH Women's Lav Right	Sink	9:24			
169.1-82	Music Rm 174.4	Sink	9:25			
169.1-83	Art Rm 151 Front Sink Left	Sink	9:26			
169.1-84	Art Rm 151 Front Sink Center	Sink	9:27			
169.1-85	Art Rm 151 Front Sink Right	Sink	9:28			
169.1-86	Art Rm 151 Back Sink Left	Sink	9:29			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KTHARRIS [signature] Date: 10/22/20 Time: 10:52 AM

Sample Login (Name / Lab): Travis Boom [signature] Date: 11/6/20 Time: 338PM

Analysis (Name / Lab): [signature] Date: 11/16/20 Time: 8:40 am

QA/QC Review (Name/Lab): [signature] Date: 11/17/20 Time: 3pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD Contact: Michael Bryniarski

Building: Lancaster High School Location: 1 Forton Drive, Lancaster NY

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-87	Art Rm 151 Back Sink Center	Sink	9:30			
169.1-88	Art Rm 151 Back Sink Right	Sink	9:31			
169.1-89	Art Rm 150 Front Sink Left	Sink	9:32			
169.1-90	Art Rm 150 Front Sink Center	Sink	9:33			
169.1-91	Art Rm 150 Front Sink Right	Sink	9:34			
169.1-92	Art Rm 150 Back Sink Left	Sink	9:35			
169.1-93	Art Rom 150 Back Sink Center	Sink	9:36			
169.1-94	Art Rm 150 Back Sink Right	Sink	9:37			
169.1-95A	Art Rm 150 Hallway	DFA	9:38			
169.1-95B	Art Rm 150 Hallway	DFB	9:39			
169.1-96	Stage Rm 174.3	Sink	9:40			
169.1-97	Art Rm 149 Left	Sink	9:41			
169.1-98	Art Rm 149 Left Center	Sink	9:42			
169.1-99	Art Rm 149 Right Center	Sink	9:43			
169.1-100	Art Rm 149 Right	Sink	9:44			
169.1-101	Art Rm 147 Hallway	DFA	9:45			
169.1-102	Art Rm 147 Left	Sink	9:46			
169.1-103	Art Rm 147 Right	Sink	9:47			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KT HARRIS [signature] Date: 10/22/20 Time: 10:32 AM

Sample Login (Name / Lab): Trani Boom [signature] Date: 11/6/20 Time: 3:41 PM

Analysis (Name / Lab): J. Hartzler Date: 11/16/20 Time: 8:40 am

QA/QC Review (Name / Lab): [signature] Date: 11/17/20 Time: 3pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-104	Rm 146	Sink	9:48			
169.1-105	Rm 145	Sink	9:49			
169.1-106	Rm 143B	Sink	9:50			
169.1-107	Rm 143 Hallway	DFA	9:51			
169.1-108	143 Hall Women's Fac Left	Sink	9:52			
169.1-109	143 Hall Women's Fac Right	Sink	9:53			
169.1-110	143 Hallway Men's Fac Left	Sink	9:54			
169.1-111	Credit Union 140	Sink	9:55			
169.1-112	Boys Lav B7	Sink	9:56			
169.1-113	Rm 138 Hallway	DFA	9:57			
169.1-114	Girls Lav G7 Left	Sink	9:58			
169.1-115	Girls Lav G7 Center	Sink	9:59			
169.1-116	Girls Lav G7 Right	Sink	10:00			
169.1-117	Rm 141 Left	Sink	10:01			
169.1-118	Rm 141 Right	Sink	10:02			
169.1-119	Rm 138A	Sink	10:03			
169.1-120	Rm 136A	Sink	10:04			
169.1-121	Rm 133 Hallway	Sink	10:05			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): K THARRIS [signature] Date: 10.22.20 Time: 10:32 am

Sample Login (Name / Lab): Traci Bloom Traci Bloom Date: 11/16/20 Time: 343 PM

Analysis (Name / Lab): [signature] Date: 11/16/20 Time: 8:40 am

QA/QC Review (Name / Lab): [signature] Date: 11/17/20 Time: 3pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-122	Fitness Center 163	DFA	10:06			
169.1-123	Fitness Center/Pool Hallway	DFA	10:07			
169.1-124	Girls Pool Locker Rm	Bubbler	10:08			
169.1-125	Girls Pool Locker Rm	Sink	10:09			
169.1-126	Girls Pool Vestibule	Sink	10:10			
169.1-127A	Rm 174 Hallway	DFA	10:11			
169.1-127B	Rm 174 Hallway	DFB	10:12			
169.1-128	Accessible Lav	Sink	10:13			
169.1-129	Mens Main Office Front Left	Sink	10:14			
169.1-130	Mens MO Back Left	Sink	10:15			
169.1-131	Mens MO Back Right	Sink	10:16			
169.1-132	Mens MO Front Right	Sink	10:17			
169.1-133	Women's Main Office Left	Sink	10:18			
169.1-134	Women's Main Office Center	Sink	10:19			
169.1-135	Women's Main Office Right	Sink	10:20			
169.1-136	Principals Office Lav	Sink	10:21			
169.1-137	Main Office Lav	Sink	10:22			
169.1-138A	Main Office Hallway	DFA	10:23			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): K FHARRIS [signature] Date: 10.22.20 Time: 10:32 AM

Sample Login (Name / Lab): [signature] Date: 11/6/20 Time: 345PM

Analysis (Name / Lab): [signature] Date: 11/16/20 Time: 8:40 am

QA/QC Review (Name / Lab): [signature] Date: 11/17/20 Time: 3pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-138B	Main Office Hallway	DFB	10:24			
169.1-139	Rm 184 Lounge	Sink	10:25			
169.1-140	Nurse Office Lav	Sink	10:26			
169.1-141	Nurse Office Kitchen	Sink	10:27			
169.1-142	Rm 102 Hallway Lav	Sink	10:28			
169.1-143	Rm 105 Hallway	DFA	10:29			
169.1-144	Ladies Lav G3 Left	Sink	10:30			
169.1-145	Ladies Lav G3 Center	Sink	10:31			
169.1-146	Ladies Lav G3 Right	Sink	10:32			
169.1-147	Mens Lav B3 Left	Sink	10:33			
169.1-148	Mens Lav B3 Center	Sink	10:34			
169.1-149	Mens Lav B3 Right	Sink	10:35			
169.1-150	Rm 111A (Office Area)	Sink	10:36			
169.1-151	Rm 114	Sink	10:37			
169.1-152	Rm 114A	Sink	10:38			
169.1-153	Rm 116 Hallway	DFA	10:39			
169.1-154	Rm 116	Sink	10:40			
169.1-155	S11/S12 Prep Rm	Sink	10:41			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): K THARRIS [signature] Date: 10.22.20 Time: 10:32 AM

Sample Login (Name / Lab): [signature] Date: 11/16/20 Time: 347 PM

Analysis (Name / Lab): [signature] Date: 11/16/20 Time: 8:40 am

QA/QC Review (Name / Lab): [signature] Date: 11/17/20 Time: 3 pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-156	S13 Hallway	DFA	10:42			
169.1-157	S13/S14 Prep Rm	Sink	10:43			
169.1-158	S15/S16 Prep Rm	Sink	10:44			
169.1-159	Rm 124	Sink	10:45			
169.1-160	Rm 125 Hallway	DFA	10:46			
169.1-161	Rm 128A	Sink	10:47			
169.1-162	Boys Lav B5 Left	Sink	10:48			
169.1-163	Boys Lav B5 Right	Sink	10:49			
169.1-164	Girls Lav G5 Left	Sink	10:50			
169.1-165	Girls Lav G5 Center	Sink	10:51			
169.1-166	Girls Lav G5 Right	Sink	10:52			
169.1-167	Rm 128 Front	Sink	10:53			
169.1-168	Rm 128 Back	Sink	10:54			
169.1-169	Rm 130A	Sink	10:55			
169.1-170	Rm 129 Front	Sink	10:56			
169.1-171	Rm 129 Back	Sink	10:57			
169.1-172	Rm 131A	Sink	10:58			
169.1-173	Rm 130 Front	Sink	10:59			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KT HARRIS [signature] Date: 10.22.20 Time: 10:32 AM

Sample Login (Name / Lab): Tracy Beam [signature] Date: 11/6/20 Time: 349 PM

Analysis (Name / Lab): G. Hertzler Date: 11/16/20 Time: 8:40 am

QA/QC Review (Name / Lab): [signature] Date: 11/17/20 Time: 3p

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD

Water by AAS-GF: ASTM D3559-03D, US EPA 200.9 X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-174	Rm 130 North Wall Center	Sink	11:00			
169.1-175	Rm 131 Front	Sink	11:01			
169.1-176	Rm 131 Back	Sink	11:02			
169.1-177	Fac Lav 112B Left	Sink	11:03			
169.1-178	Fac Lav 112B Right	Sink	11:04			
169.1-179	Fac Lav 112A Left	Sink	11:05			
169.1-180	Fac Lav 112A Right	Sink	11:06			
169.1-181	2nd Fl North Mens Fac Left	Sink	11:07			
169.1-182	2nd Fl N Mens Fac Center	Sink	11:08			
169.1-183	2nd Fl N Mens Fac Right	Sink	11:09			
169.1-184	2nd Fl N Women's Fac Left	Sink	11:10			
169.1-185	2nd Fl N Wo Fac Left Center	Sink	11:11			
169.1-186	2nd Fl N Wo Fac Right Center	Sink	11:12			
169.1-187	2nd Fl N Women's Fac Right	Sink	11:13			
169.1-188	Rm 200.10	Sink	11:14			
169.1-189	Rm 200.10 Hallway	DFA	11:15			
169.1-190	Rm 207 Hallway	DFA	11:16			
169.1-191	Girls Lav G4 Left	Sink	11:17			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KTHARRIS K Harris Date: 10.22.20 Time: 10:32 AM

Sample Login (Name / Lab): Traci Boone Traci Boone Date: 11/6/20 Time: 352PM

Analysis (Name / Lab): J. Hertzler Date: 11/16/20 Time: 8:40 am

QA/QC Review (Name / Lab): [signature] Date: 11/17/20 Time: 3pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD

Water by AAS-GF: ASTM D3559-03D, US EPA 200.9 X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-192	Girls Lav G4 Center	Sink	11:18			
169.1-193	Girls Lav G4 Right	Sink	11:19			
169.1-194	Boys Lav B4 Left	Sink	11:20			
169.1-195	Boys Lav B4 Center	Sink	11:21			
169.1-196	Boys Lav B4 Right	Sink	11:22			
169.1-197	Rm 210	Sink	11:23			
169.1-199	Fac Rm 243 Ladies Lav	Sink	11:24			
169.1-200	Fac Rm 243 Mens Lav	Sink	11:25			
169.1-201	Fac Rm 243 Kitchenette	Sink	11:26			
169.1-202	Boys Lav B8 left	Sink	11:27			
169.1-203	Boys Lav B8 Center	Sink	11:28			
169.1-204	Boys Lav B8 Right	Sink	11:29			
169.1-205	Between Lavs B8 and G8	DFA	11:30			
169.1-206	Girls Lav G8 Left	Sink	11:31			
169.1-207	Girls Lav G8 Center	Sink	11:32			
169.1-208	Girls Lav G8 right	Sink	11:33			
169.1-209	Rm 233 Hallway	DFA	11:34			
169.1-210	Rm 227 Hallway	DFA	11:35			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): R. HARRIS [signature] Date: 10.22.20 Time: 10:32 AM

Sample Login (Name / Lab): Traci Blom Traci Blom Date: 11/6/20 Time: 354 PM

Analysis (Name / Lab): G. Hertzler Date: 11/16/20 Time: 8:40am

QA/QC Review (Name / Lab): [signature] Date: 11/17/20 Time: 3p

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD

Water by AAS-GF: ASTM D3559-03D, US EPA 200.9 — X

Turnaround: 20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-211	Girls Lav G6 Left	Sink	11:36			
169.1-212	Girls Lav G6 Center	Sink	11:37			
169.1-213	Girls Lav G6 Right	Sink	11:38			
169.1-214	Boys Lav B6 Left	Sink	11:39			
169.1-215	Boys Lav B6 Right	Sink	11:40			
169.1-216	Boys South Lav Left	Sink	11:41			
169.1-217	Boys South Lav Right	Sink	11:42			
169.1-218	South End Lobby Left	DFA	11:43			
169.1-219	South End Lobby Right	DFA	11:44			
169.1-220	Girls South Lav Left	Sink	11:45			
169.1-221	Girls South Lav Right	Sink	11:46			
169.1-222	Rm 216	Sink	11:47			
169.1-223	Rm 217 North	Sink	11:48			
169.1-224	Rm 217 South	Sink	11:49			
169.1-225	Rm 217 Southwest	Sink	11:50			
169.1-226	Rm 217 Northwest	Sink	11:51			
169.1-228	Rm 221.2	Sink	11:52			
169.1-229	Media Center 245.2	Sink	11:53			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name — Stohl Env: C. Schultz, P. Nichols — Date: 10/17/2020

Relinquished By: [signature] Print Name — Stohl Env: Eric Henderson Jr. — Date: 10/19/2020

Received (Name / Lab): K THARRIS K Harris — Date: 10/22/20 — Time: 10:32 AM

Sample Login (Name / Lab): Traci Brown Traci Brown — Date: 11/6/20 — Time: 356 PM

Analysis (Name / Lab): J. Hertzler — Date: 11/16/20 — Time: 8:40 am

QA/QC Review (Name / Lab): [signature] — Date: 11/17/20 — Time: 3p

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-169.1

Client: Lancaster CSD

Contact: Michael Bryniarski

Building: Lancaster High School

Location: 1 Forton Drive, Lancaster NY

LEAD

Water by AAS-GF: ASTM D3559-03D, US EPA 200.9 X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
169.1-230	Bsmt Rifle Range Hallway	Sink	11:54			
169.1-231	Bsmt Rifle Range Hallway	DFA	11:55			
169.1-232	Basement Laundry Rm	Sink	11:56			
169.1-233	Basement Staff Lav	Sink	11:57			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: C. Schultz, P. Nichols Print Name Stohl Env: C. Schultz, P. Nichols Date: 10/17/2020

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 10/19/2020

Received (Name / Lab): KTHARRIS QC Diamond Date: 10.22.20 Time: 10:32 AM

Sample Login (Name / Lab): Traci Boon Traci Boon Date: 11/6/20 Time: 357PM

Analysis (Name / Lab): J. Hertzler Date: 11/16/20 Time: 8:40 am

QA/QC Review (Name / Lab): [signature] Date: 11/17/20 Time: 3 pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

BLANK



3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM