

Glen Cove School District
Districtwide Lead in Water – Addendum
Fall 2016



ENVIROSCIENCE
CONSULTANTS INC.

2150 Smithtown Avenue
Ronkonkoma, NY 11779
(631) 580-3191
WWW.ENVIROHEALTH.ORG



2150 Smithtown Ave., Suite 3, Ronkonkoma, NY 11779
T: 631.580.3191 • F: 631.580.3195 • W: envirohealth.org

January 24, 2017

To: Glen Cove School District

Attached please find the results and remediation response of sampling performed in compliance with the United States Environmental Protection Agency's "3T's for Reducing Lead in Drinking Water in Schools", October, 2006 and New York State Department of Health Subpart 67-4 of Title 10, September 2016.

Sincerely,

A handwritten signature in black ink, which appears to read "Glenn Neuschwender". The signature is fluid and cursive, written over a white background.

Glenn Neuschwender
President

**Appendix A
Connolly Elementary School**

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 107	WF	1.4	-	-	None	-	-
Room 105	WF	6	-	-	None	-	-
Room 106	WF	4.2	-	-	None	-	-
Room 103	WF	18	<1.0	1.2	FR	Completed FR	4.8
Room 104	SK	14	-	-	None	-	-
Room 102	WF	12	-	-	None	-	-
Room 101	WF	33	1.7	<1.0	FR	Completed FR	6.1
Hall Next to Gym	WF	<1.0	-	-	None	-	-
Room 111	WF	6.8	-	-	None	-	-
Room 112	SK	10	-	-	None	-	-
Room 114	WF	7.1	-	-	None	-	-
Room 113	WF	3.5	-	-	None	-	-
Room 116	WF	7.4	-	-	None	-	-
Room 115	WF	7.9	-	-	None	-	-
Room 118	WF	17	1.5	<1.0	FR	Completed FR	21 (Aug. 24, 2016) #3.3 (Sept. 29, 2016)
Kitchen Dishwashing	SK	2.7	-	-	None	-	-
Kitchen Prep	SK	7.9	-	-	None	-	-
Kitchen Handwashing	SK	5.6	-	-	None	-	-
Café	WF	<1.0	-	-	None	-	-
Nurse Office	SK	3.5	-	-	None	-	-
Faculty Lounge	SK	19	7.1	2.6	FR	Completed FR	16 (Aug. 24, 2016) #4.6 (Sept. 29, 2016)

Action Level = 15.0 parts per billion (ppb) (ug/L)



Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 115	SK	46			FR	SIGN	-
Room 113	SK	17			FR	SIGN	-
Room 111	SK	21			FR	SIGN	-
Room 116	SK	13			None	-	-
Room 114	SK	3.2			None	-	-
Room 112	WF	5.7			None	-	-
Girls BR by Room 113 @ (A)	SK	5.8			None	-	-
Girls BR by Room 113 @ (B)	SK	2.8			None	-	-
Girls BR by Room 113 @ (C)	SK	11			None	-	-
Boys BR by Room 111 @ (A)	SK	5.3			None	-	-
Boys BR by Room 111 @ (B)	SK	2.3			None	-	-
Boys BR by Room 111 @ (C)	SK	10			None	-	-
Room 110	SK	5.9			None	-	-
Library	SK	24			FR	SIGN	-
Library	WF	97			FR	CAP	-
Faculty Mens BR	SK	2.4			None	-	-
Faculty Womens BR	SK	3.5			None	-	-
Room 107	SK	1.8			None	-	-
Room 108 BR	SK	17			FR	SIGN	-
Room 105	SK	6.9			None	-	-
Room 106	SK	26			FR	SIGN	-
Room 103	SK	5.4			None	-	-

Glen Cove School District
Connolly Elementary School

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 102 BR	SK	12			None	-	-
Room 101B BR	SK	8.7			None	-	-
Room 101A	SK	28			FR	SIGN	-
Room 99 BR	SK	<1.0			None	-	-
Room 100 BR	SK	10			None	-	-
Room 117B BR	SK	7.7			None	-	-
Room 124	WF	5.1			None	-	-
Room 124	SK	20			FR	SIGN	-
Room 124 BR	SK	11			None	-	-
Room 118	SK	11			None	-	-
Room 118 BR	SK	2.1			None	-	-
Art Room 120-122 @ (A)	SK	20			FR	SIGN	-
Art Room 120-122 @ (B)	SK	17			FR	SIGN	-
Art Room 120-122 @ (C)	SK	5.1			None	-	-
Art Room 120-122 @ (D)	SK	3.4			None	-	-
Kitchen BR	SK	3.2			None	-	-
Room 104	WF	11			None	-	-

Appendix B
Deasy Elementary School

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Hall by Room 201	WF	<1.0	-	-	None	-	-
Nurse Office	SK	12	-	-	None	-	-
Hall by Room 209	WF	1.4	-	-	None	-	-
Hall by Room 107	WF	1.4	-	-	None	-	-
Hall by Room 108	WF	2.5	-	-	None	-	-
Hall by Faculty Lounge	WF	1.1	-	-	None	-	-
Faculty Lounge	SK	16	22	19	FRSLVPA	CAP	29 (Aug. 24, 2016) 27 (Sept. 30, 2016)
Hall by Room 96	WF	1.2	-	-	None	-	-
Office In Basement	SK	6.6	-	-	None	-	-
Pre-K 2	WF	4.5	-	-	None	-	-
Pre-K 1	SK	11	-	-	None	-	-
1910 Lower Corridor	WF	<1.0	-	-	None	-	-
Special Ed Room 303	SK	53	25	5.3	FRSLV	CAP	-
2nd Fl. Girls BR @ (A)	SK	14	-	-	None	-	-
2nd Fl. Girls BR @ (B)	SK	12	-	-	None	-	-
2nd Fl. Girls BR @ (C)	SK	19	-	-	FR	SIGN	-
2nd Fl. Boys BR @ (A)	SK	15	-	-	None	-	-
2nd Fl. Boys BR @ (B)	SK	3.9	-	-	None	-	-
2nd Fl. Boys BR @ (C)	SK	12	-	-	None	-	-
1st Fl. Boys BR @ (A)	SK	<2.5	-	-	None	-	-
1st Fl. Boys BR @ (B)	SK	36	-	-	FR	SIGN	-



Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
1st Fl. Boys BR @ (C)	SK	4.2	-	-	None	-	-
1st Fl. Girls BR @ (A)	SK	3.4	-	-	None	-	-
1st Fl. Girls BR @ (B)	SK	11	-	-	None	-	-
1st Fl. Girls BR @ (C)	SK	11	-	-	None	-	-
Room 104 BR	SK	16			FR	SIGN	-
Room 105 BR	SK	9.7	-	-	None	-	-
Principals BR	SK	8.7	-	-	None	-	-
Special Ed. Room 201	SK	35			FR	CAP	-
Special Ed. Room 201	SK	18			FR	CAP	-
Basement Room 101 BR	SK	<2.5	-	-	None	-	-
Basement Boys BR @ (A)	SK	20			FR	SIGN	-
Basement Boys BR @ (B)	SK	8.4	-	-	None	-	-
Basement Girls BR @ (A)	SK	7.5	-	-	None	-	-
Basement Girls BR @ (B)	SK	25			FR	SIGN	-
Art Room (L.L. 1910) @ (A)	SK	14	-	-	None	-	-
Art Room (L.L. 1910) @ (B)	SK	15	-	-	None	-	-
Art Room (L.L. 1910) @ (C)	SK	16			FR	SIGN	-
Art Room (L.L. 1910)	SS	14	-	-	None	-	-
Pre-K 2	SK	7.7	-	-	None	-	-
1910 Girls BR @ (A)	SK	15	-	-	None	-	-
1910 Girls BR @ (B)	SK	7	-	-	None	-	-
1910 Girls BR @ (C)	SK	7.4	-	-	None	-	-
1910 Boys BR @ (A)	SK	7.1	-	-	None	-	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
1910 Boys BR @ (B)	SK	<2.5	-	-	None	-	-
1910 Boys BR @ (C)	SK	6.3	-	-	None	-	-
1910 Library	SK	3.4	-	-	None	-	-

Appendix C
Gribbin Elementary School

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
SK by Kitchen Main Desk	SK	3.4	-	-	None	-	-
Kitchen BR	SK	29	11	10	FR	SIGN	19 (Aug. 24, 2016) 17 (Sept. 30, 2016)
Kitchen Prep (left)	SK	5.8	-	-	None	-	-
Kitchen Prep (right)	SK	3.8	-	-	None	-	-
Nurse Office	SK	9	-	-	None	-	-
Nurse Office BR	SK	12	-	-	None	-	-
WF by Art Room	WF	10	-	-	None	-	-
Art Room	WF	7	-	-	None	-	-
Faculty Room	SK	14	-	-	None	-	-
Room 114	WF	6.5	-	-	None	-	-
Room 113	WF	18	5.2	4.2	FR	Completed FR	15
Room 115	WF	9.7	-	-	None	-	-
Room 112	WF	6.2	-	-	None	-	-
Room 116	WF	7.6	-	-	None	-	-
Room 111	WF	13	-	-	None	-	-
WF by Room 111	WF	8.7	-	-	None	-	-
Room 117	WF	7	-	-	None	-	-
Room 110	WF	9.3	-	-	None	-	-
WF by Room 10	WF	8.6	-	-	None	-	-
Room 14	WF	5.8	-	-	None	-	-
Room 13	WF	6.2	-	-	None	-	-
Room 12	WF	9.3	-	-	None	-	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 11	WF	10	-	-	None	-	-
Room 15	WF	11	-	-	None	-	-
Room 10	WF	5.6	-	-	None	-	-
Room 16	WF	6.3	-	-	None	-	-
Room 20	WF	12	-	-	None	-	-
Room 17	WF	6.6	-	-	None	-	-
Room 19	WF	10	-	-	None	-	-
Room 18	WF	12	-	-	None	-	-
Custodial BR	SK	12	-	-	None	-	-
Womens Faculty BR	SK	13	-	-	None	-	-
Mens Faculty BR	SK	8.9	-	-	None	-	-
Faculty Room	WC	<1.0	-	-	None	-	-
Room 117	SK	7.6	-	-	None	-	-
Room 116	SK	5.1	-	-	None	-	-
Room 115	SK	7.7	-	-	None	-	-
Room 114	SK	6.9	-	-	None	-	-
Room 113	SK	6.4	-	-	None	-	-
Room 112	SK	8.4	-	-	None	-	-
Room 111	SK	8.2	-	-	None	-	-
Room 110	SK	5.2	-	-	None	-	-
Room 14	SK	6.5	-	-	None	-	-
Room 13	SK	8	-	-	None	-	-
Room 12	SK	14	-	-	None	-	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 11	SK	7.8	-	-	None	-	-
Room 15	SK	6.7	-	-	None	-	-
Room 10	SK	5.8	-	-	None	-	-
Room 16	SK	7.1	-	-	None	-	-
Room 20	SK	10	-	-	None	-	-
Room 17	SK	15	-	-	None	-	-
Room 19	SK	8.3	-	-	None	-	-
Room 18	SK	6.5	-	-	None	-	-

Appendix D
Landing Elementary School

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
All Purpose Room	SS	6.6	-	-	None	-	-
WF by Room 119	WF	1.9	-	-	None	-	-
WF by Room 102	WF	<1.0	-	-	None	-	-
WF by Principals Office	WF	<1.0	-	-	None	-	-
Nurse Office	SK	4.4	-	-	None	-	-
WF by Room 207	WF	<1.0	-	-	None	-	-
Faculty Room	SK	6.6	-	-	None	-	-
WF by Room 209	WF	<1.0	-	-	None	-	-
Girl's BR by Custodian Office @ (A)	SK	5	-	-	None	-	-
Girl's BR by Custodian Office @ (B)	SK	3.3	-	-	None	-	-
Principal's Office BR	SK	40			FR	SIGN	-
Boy's BR by Room 106 @ (A)	SK	2.8	-	-	None	-	-
Boy's BR by Room 106 @ (B)	SK	<2.5	-	-	None	-	-
Room 005 BR	SK	<2.5	-	-	None	-	-
Room 002 BR	SK	15			None		
Art Room @ (A)	SK	9.5	-	-	None	-	-
Art Room @ (B)	SK	9.3	-	-	None	-	-
Food Service Line	SK	13	-	-	None	-	-
Room 120 @ (A)	SK	<2.5	-	-	None	-	-
Room 120 @ (B)	SK	<2.5	-	-	None	-	-
Room 114	SK	32			FR	SIGN	-
Room 119	SK	16			FR	SIGN	-
Faculty BR by Room 119	SK	2.9	-	-	None	-	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 115 BR	SK	<2.5	-	-	None	-	-
Room 116	SK	34			FR	SIGN	-
Girl's BR by Room 209 @ (A)	SK	<2.5	-	-	None	-	-
Girl's BR by Room 209 @ (B)	SK	<2.5	-	-	None	-	-
Faculty BR by Room 203	SK	<2.5	-	-	None	-	-
Room 204	SK	9.5	-	-	None	-	-
Room 207	SK	26			FR	SIGN	-
Boy's BR by Room 206 @ (A)	SK	10	-	-	None	-	-
Boy's BR by Room 206 @ (B)	SK	6.8	-	-	None	-	-

Appendix E
R.M. Finley Middle School

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Corridor by Principal Office	WF	<1.0	-	-	None	-	-
Corridor by Art Room	WF	<1.0	-	-	None	-	-
Home & Careers 1	SK	10	-	-	None	-	-
Home & Careers 2	SK	15	131	16	None	Replaced	Pending Retest
Home & Careers 3	SK	5.5	-	-	None	-	-
Home & Careers 4	SK	3	-	-	None	-	-
Health Office	SK	4.1	-	-	None	-	-
Outside Room 119	WF	1.3	-	-	None	-	-
Outside Room 213	WF	<1.0	-	-	None	-	-
Outside Room 201	WF	<1.0	-	-	None	-	-
Outside Room 407	WF	<1.0	-	-	None	-	-
Outside Room 406	WF	<1.0	-	-	None	-	-
Corridor 1910 (Solo)	WF	<1.0	-	-	None	-	-
Corridor 1910 (left)	WF	1.6	-	-	None	-	-
Corridor 1910 (right)	WF	1	-	-	None	-	-
Kitchen Handwash	SK	18	1.9	<1.0	FR	Completed FR	7.7
Kitchen Handwash	SK	13	-	-	None	-	-
Kitchen Wall w/o Windows (left)	SK	6.1	-	-	None	-	-
Kitchen Wall w/o Windows (middle)	SK	5.9	-	-	None	-	-
Kitchen Wall w/o Windows (right)	SK	5.9	-	-	None	-	-
Kitchen Pot Filler 1	SK	8.3	-	-	None	-	-
Kitchen Pot Filler 2	SK	10	-	-	None	-	-
Kitchen Prep (right)	SK	9.8	-	-	None	-	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen Prep (left)	SK	14	-	-	None	-	-
Kitchen White Sink	SK	11	-	-	None	-	-
Café by Serving Area	WF	12	-	-	None	-	-
Café by Faculty Room	WF	1.7	-	-	None	-	-
Lower Gym (outside)	SP	13	-	-	None	-	-
Upper Gym	WF	2.9	-	-	None	-	-
Slop Sink for Sports Coolers	SS	4.9	-	-	None	-	-
Girls Locker Room	WF	1.7	-	-	None	-	-
Boys Locker Room	WF	2.4	-	-	None	-	-
Outside Room 502	WF	3.7	-	-	None	-	-
Outside Room 504	WF	4.7	-	-	None	-	-
Outside Room 606	WF	9	-	-	None	-	-
Outside Room 604	WF	10	-	-	None	-	-
Main Office BR	SK	2	-	-	None	-	-
Principals Office BR	SK	3.9	-	-	None	-	-
Assistant Principal BR	SK	3.8	-	-	None	-	-
Boy's BR by RM 101 @ (A)	SK	9.2	-	-	None	-	-
Boy's BR by RM 101 @ (B)	SK	3.1	-	-	None	-	-
Boy's BR by RM 101 @ (C)	SK	4.5	-	-	None	-	-
Custodial Shop by RM 101	SS	1.6	-	-	None	-	-
Metal Shop @ (A)	SK	8.6	-	-	None	-	-
Metal Shop @ (B)	SK	8.7	-	-	None	-	-
Work Shop @ (A)	SK	12	-	-	None	-	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Work Shop @ (B)	SK	4.8	-	-	None	-	-
Room 114A @ (A)	SK	4	-	-	None	-	-
Room 114A @ (B)	SK	2.2	-	-	None	-	-
Room 114A @ (C)	SK	5.2	-	-	None	-	-
Room 114A @ (D)	SK	6.9	-	-	None	-	-
Room 114B @ (A)	SK	2.1	-	-	None	-	-
Room 114B @ (B)	SK	2.9	-	-	None	-	-
Room 115B @ (A)	SK	12	-	-	None	-	-
Room 115B @ (B)	SK	9.4	-	-	None	-	-
Girl's BR by RM 118 @ (A)	SK	10	-	-	None	-	-
Girl's BR by RM 118 @ (B)	SK	3.5	-	-	None	-	-
Girl's BR by RM 118 @ (C)	SK	7.1	-	-	None	-	-
Girl's BR by Auditorium @ (A)	SK	12	-	-	None	-	-
Girl's BR by Auditorium @ (B)	SK	<1.0	-	-	None	-	-
Boy's BR by Auditorium @ (A)	SK	24	-	-	FR	SIGN	-
Boy's BR by Auditorium @ (B)	SK	24	-	-	FR	SIGN	-
Boy's Dressing Room	SK	25	-	-	FR	SIGN	-
Boy's Dressing Room BR	SK	6.5	-	-	None	-	-
Girl's Dressing Room	SK	31	-	-	FR	SIGN	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Girl's Dressing Room BR	SK	7.1	-	-	None	-	-
Room 220 BR	SK	50			FR	SIGN	-
BR by RM 218 @ (A)	SK	15	-	-	None	-	-
BR by RM 218 @ (B)	SK	2.9	-	-	None	-	-
BR by RM 218 @ (C)	SK	<1.0	-	-	None	-	-
Faculty Room	SK	6.1	-	-	None	-	-
Faculty Room BR	SK	3.4	-	-	None	-	-
Testing Center	SK	60			FR	SIGN	-
200 Wing Boy's BR @ (A)	SK	11	-	-	None	-	-
200 Wing Boy's BR @ (B)	SK	2.9	-	-	None	-	-
200 Wing Girl's BR @ (A)	SK	14	-	-	None	-	-
200 Wing Girl's BR @ (B)	SK	<1.0	-	-	None	-	-
200 Wing Girl's BR @ (C)	SK	5.4	-	-	None	-	-
Room 202 @ (A)	SK	9.4	-	-	None	-	-
Room 202 @ (B)	SK	14	-	-	None	-	-
400 Wing Boy's BR @ (A)	SK	4.8	-	-	None	-	-
400 Wing Boy's BR @ (B)	SK	5.1	-	-	None	-	-
400 Wing Boy's BR @ (C)	SK	6.1	-	-	None	-	-
400 Wing Boy's BR @ (D)	SK	6.7	-	-	None	-	-
400 Wing Girl's BR @ (A)	SK	16			FR	SIGN	-
400 Wing Girl's BR @ (B)	SK	4	-	-	None	-	-
400 Wing Girl's BR @ (C)	SK	6.9	-	-	None	-	-
400 Wing Girl's BR @ (D)	SK	7.5	-	-	None	-	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
300 Wing Boy's BR @ (A)	SK	27			FR	SIGN	-
300 Wing Boy's BR @ (B)	SK	1.6	-	-	None	-	-
300 Wing Boy's BR @ (C)	SK	4.1	-	-	None	-	-
300 Wing Boy's BR @ (D)	SK	2.1	-	-	None	-	-
300 Wing Girl's BR @ (A)	SK	2.8	-	-	None	-	-
300 Wing Girl's BR @ (B)	SK	3.1	-	-	None	-	-
300 Wing Girl's BR @ (C)	SK	3.1	-	-	None	-	-
300 Wing Girl's BR @ (D)	SK	1.7	-	-	None	-	-
Old Faculty Room	SK	16			FR	SIGN	-
Old Faculty Room Women's BR	SK	13	-	-	None	-	-
Old Faculty Room Men's BR	SK	16			FR	SIGN	-
Gym	IM	<1.0	-	-	None	-	-
Women's Faculty BR by RM 502 @ (A)	SK	7.3	-	-	None	-	-
Women's Faculty BR by RM 502 @ (B)	SK	11	-	-	None	-	-
Women's Faculty BR by RM 502 @ (C)	SK	9.1	-	-	None	-	-
Men's Faculty BR by RM 502 @ (A)	SK	7.3	-	-	None	-	-
Men's Faculty BR by RM 502 @ (B)	SK	22			FR	SIGN	-
Room 502	SK	45			FR	SIGN	-
Girl's BR by RM 604 @ (A)	SK	13	-	-	None	-	-
Girl's BR by RM 604 @ (B)	SK	14	-	-	None	-	-
Girl's BR by RM 604 @ (C)	SK	55			FR	SIGN	-
Boy's BR by RM 604 @ (A)	SK	13	-	-	None	-	-
Boy's BR by RM 604 @ (B)	SK	4.4	-	-	None	-	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 608	SK	8.7	-	-	None	-	-
Old Faculty Room	SPRAY	12	-	-	None	-	-

**Appendix F
Glen Cove High School**

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen Sink Across from Freezer	SK	4.9	-	-	None	-	-
Kitchen Pot	SK	1.6	-	-	None	-	-
Kitchen Prep	SK	6.5	-	-	None	-	-
Kitchen Food Prep	SK	3.8	-	-	None	-	-
Kitchen Hand Washing	SK	2.5	-	-	None	-	-
Kitchen Sink Next to Oven	SK	16	1.1	<1.0	FR	Completed FR	11
Hallway by Room 103	WF	1.3	-	-	None	-	-
Nurse Office	SK	5.9	-	-	None	-	-
WF Hall by Room 123	WF	1.9	-	-	None	-	-
Gym	WF	1.2	-	-	None	-	-
Boys LR (left)	WF	<1.0	-	-	None	-	-
Boys LR (right)	WF	<1.0	-	-	None	-	-
Corridor by Gym	WF	2	-	-	None	-	-
Girls LR	SK	2.7	-	-	None	-	-
Outside Girls LR	WF	2.2	-	-	None	-	-
Outside Girls Shower (right)	WF	4.6	-	-	None	-	-
Outside Girls Shower (left)	WF	<1.0	-	-	None	-	-
Outside Café	WF	<1.0	-	-	None	-	-
SS for Sports Cooler (by Womens BR)	SS	1.1	-	-	None	-	-
SS for Sports Cooler (Boys LR)	SS	4.1	-	-	None	-	-
Corridor By Guidance Office	WF	35	74	18	FRSLVPA	Completed FRSL	3
Corridor by Mac Lab	WF	2.2	-	-	None	-	-
SK Teachers Lounge	SK	2.4	-	-	None	-	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
WF in Hall by Room 22	WF	9.1	-	-	None	-	-
Boys Coaches Office	SK	1.9	-	-	None	-	-
Hall by Room 234	WF	1.5	-	-	None	-	-
Library Office	SK	12	-	-	None	-	-
Admin Building	SK	21	16	7.1	FRSLV	Completed FRSL	11
Maintenance Building	SK	6.8	-	-	None	-	-
Kitchen Across from Freezer	SPRAY	21	-	-	FR	SIGN	-
Kitchen Pot Filler @ (B)	SP	7.3	-	-	None	-	-
Kitchen 3 Bay @ (A)	SK	77	-	-	FR	SIGN	-
Kitchen BR	SK	9.6	-	-	None	-	-
Boys LR BR @ (A)	SK	4	-	-	None	-	-
Boys LR BR @ (B)	SK	3.1	-	-	None	-	-
Boys LR BR @ (C)	SK	<2.5	-	-	None	-	-
Girls Coaches Office	SK	<2.5	-	-	None	-	-
Girls LR BR @ (B)	SK	3	-	-	None	-	-
Girls BR by Café 2 @ (B)	SK	4.1	-	-	None	-	-
Boys BR by Café 2	SK	10	-	-	None	-	-
Girls BR by Room 130 @ (A)	SK	113	-	-	FR	SIGN	-
Girls BR by Room 130 @ (B)	SK	7.6	-	-	None	-	-
Girls BR by Room 130 @ (C)	SK	11	-	-	None	-	-
Girls BR by Room 130 @ (D)	SK	52	-	-	FR	SIGN	-
Boys BR by Room 130 @ (A)	SK	19	-	-	FR	SIGN	-
Boys BR by Room 130 @ (B)	SK	7.3	-	-	None	-	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Womens Faculty BR in Gallery @ (A)	SK	3.3	-	-	None	-	-
Womens Faculty BR in Gallery @ (B)	SK	7	-	-	None	-	-
Mens Faculty BR in Gallery @ (A)	SK	19			FR	SIGN	-
Mens Faculty BR in Gallery @ (B)	SK	13	-	-	None	-	-
Art Room 134 Unit @ (A)	SK	23			FR	SIGN	-
Art Room 134 Unit @ (B)	SK	81			FR	SIGN	-
Art Room 134 Unit @ (C)	SK	42			FR	SIGN	-
Art Room 134 Unit @ (D)	SK	4.6	-	-	None	-	-
Art Room 132 Unit @ (A)	SK	12	-	-	None	-	-
Art Room 132 Unit @ (B)	SK	7.7	-	-	None	-	-
Art Room 132 Unit @ (C)	SK	5	-	-	None	-	-
Art Room 132 Unit @ (D)	SK	15	-	-	None	-	-
Art Room 132 Unit @ (E)	SK	7.9	-	-	None	-	-
Art Room 132 Unit @ (F)	SK	25			FR	CAP	-
Clay Room 130 @ (A)	SS	33			FR	SIGN	-
Clay Room 130 @ (B)	SS	16			FR	SIGN	-
Room 143 @ (A)	SK	19			FR	CAP	-
Room 143 @ (B)	SK	12	-	-	None	-	-
Room 138 @ (A)	SK	23			FR	SIGN	-
Room 138 @ (B)	SK	23			FR	CAP	-
D Room BR	SK	12	-	-	None	-	-
Main Office Womens BR	SK	10	-	-	None	-	-
Main Office Mens BR	SK	16			FR	SIGN	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Mens Faculty BR by Room 103	SK	9.8	-	-	None	-	-
Womens Faculty BR by Room 103	SK	7.6	-	-	None	-	-
Girls BR by Room 103 @ (A)	SK	2.9	-	-	None	-	-
Girls BR by Room 103 @ (B)	SK	<2.5	-	-	None	-	-
Girls BR by Room 103 @ (C)	SK	3.4	-	-	None	-	-
Girls BR by Room 103 @ (D)	SK	5.5	-	-	None	-	-
Boys BR by Room 103 @ (A)	SK	3.1	-	-	None	-	-
Boys BR by Room 103 @ (B)	SK	<2.5	-	-	None	-	-
Boys BR by Room 103 @ (C)	SK	<2.5	-	-	None	-	-
Boys BR by Room 103 @ (D)	SK	<2.5	-	-	None	-	-
Nurses Office BR	SK	6.7	-	-	None	-	-
Mens Faculty BR by Room 212 @ (A)	SK	9.7	-	-	None	-	-
Mens Faculty BR by Room 212 @ (B)	SK	20			FR	SIGN	-
Womens Faculty BR by Room 212 @ (A)	SK	5.2	-	-	None	-	-
Womens Faculty BR by Room 212 @ (B)	SK	10	-	-	None	-	-
Womens Faculty BR by Room 212 @ (C)	SK	<2.5	-	-	None	-	-
Tennis Courts Office BR	SK	16			FR	SIGN	-
Tennis Courts Ladies BR	SK	3	-	-	None	-	-
Tennis Courts Mens BR	SK	7.9	-	-	None	-	-
Tennis Courts	WF	<2.5	-	-	None	-	-
Booster Club Kitchen	SK	3.1	-	-	None	-	-
Booster Club Boys BR	SK	5.8	-	-	None	-	-
Booster Club Girls BR @ (A)	SK	116			FR	SIGN	-

Lead in Drinking Water Test Results

As of 1/24/17

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Booster Club Girls BR @ (B)	SK	76	-	-	FR	SIGN	-
CC by Front Gym	IM	6.1	-	-	None	-	-

Code Key

Remediation Type Codes

FR	=	Fixture replacement
FRSLV	=	Replacement of fixture, supply lines, and valves
FRSLVPA	=	Replacement of fixture, supply lines, valves and plumbing assessment
SIGN	=	Warning sign posting
CAP	=	Remove fixture or cap line

Room ID Codes

CC	=	Custodian Closet
MPR	=	Multi Purpose Room
Café	=	Cafeteria
Sci	=	Science Lab
PE	=	Physical Ed
BR	=	Bathroom
LR	=	Locker Room
RM	=	Room

Fixture Type Codes

WF	=	Water Fountain
SK	=	Sink
SS	=	Slop Sink
SP	=	Spigot
PF	=	Pot Filler
HB	=	Hose Bib
IM	=	Ice Machine
WC	=	Water Cooler
SH	=	Shower

Result Code

ND	=	Not Detected
<	=	Less Than
-	=	No Testing Required



ENVIROSCIENCE
CONSULTANTS INC.