

Water Testing Results - Pleasant Hill School District
Action Level is 15 parts per billion (ppb)

Fixture Location / Description	Fixture ID #	Test Date	Test Results (ppb)
COPPER:			
Elementary Wrestling Drinking Fountain	20810105-001DW	3/16/2023	ND
Elementary Library West Drinking Fountain	20810109-001DW	3/16/2023	ND
Elementary K-1 Commons Drinking Fountain	20810100-001DW	3/16/2023	0.271
Elementary #17 Drinking Fountain	20810100-002DW	3/16/2023	0.21
Elementary #14 Drinking Fountain	20810100-003DW	3/16/2023	0.286
High School Canteen / Sink	20810201-001KF	3/15/2023	0.282
High School Library South Sink	20810206-002SF	3/16/2023	0.499
High School Office Staff LR / Sink	20810209-001KF	3/16/2023	0.283
High School Band Room Sink	20810202-001CF	3/16/2023	0.323
District Office Kitchen Sink	20810000-001KF	3/15/2023	ND
Elementary Nurse Room Sink	20810100-025NS	3/15/2023	0.191
Elementary #9 Drinking Fountain	20810100-087DW	3/16/2023	0.364
Elementary Lunchroom Drinking Fountain	20810104-004DW	3/15/2023	ND
Community Center Drinking Fountain	20810110-002DW	3/16/2023	0.267
High School Choir Drinking Fountain	20810202-004DW	3/16/2023	0.416
High School Auxillary Gym Upper Drinking Fountain	20810203-002DW	3/16/2023	ND
High School Main Gym Commons Drinking Fountain	20810201-002DW	3/15/2023	0.238
High School S2 Classroom Center Sink	20810200-025CF	3/16/2023	0.454
High School Vestibule Upper Drinking Fountain	20810200-017DW	3/15/2023	0.114
Middle School Vestibule Lower Drinking Fountain	20810200-016DW	3/15/2023	0.104

ND = Not Detected at the Reporting Limit