



20-21 Wagaraw Road – Bldg. 35E, Fair Lawn, NJ 07410
PH (973) 636-9145 FAX (973) 636-9144
Email: Envirovision@optonline.net

CLIENT: Springfield Public Schools Project Number 21-358
PROJECT: Lead (Pb) in Water Sampling Jonathan Dayton High School
Elementary School ADDRESS: 139 Mountain Avenue, Springfield NJ 07081
FIELD TECHNICIANS: Leonardo Bitondo REPORT DATE: September 15, 2021

As per your request, EnviroVision Consultants, Inc. was contracted by Springfield Public Schools to conduct Lead (Pb) in water sampling at the Jonathan Dayton High School on August 27, 2021. The sample locations, in addition to a unique sample location code was determined/assigned by school district personnel. The school district performed the proper flushing of outlets prior to sampling and EnviroVision was instructed to collect only first draw samples for this sampling event. The school district's corresponding flushing logs should be attached to this report.

The facility was closed at the time of sampling in order to prevent occupants from utilizing any water outlets. After flushing, the water in the facility must remain motionless in the plumbing fixtures for a minimum of 8 hours, but no more than 48 hours. Cold water samples were collected in pre-cleaned high-density polyethylene (HDPE) 250mL wide mouth bottles.

Samples were analyzed at EMSL Analytical, Inc. in Cinnaminson, New Jersey *(NJDEP#03036), accredited in accordance with NELAC (National Environmental Laboratory Accreditation Conference). The analytical method utilized was inductively coupled plasma mass spectrometry ICP-MS (EPA 200.8).

Eighteen of the thirty-one initially requested samples were collected from the Jonathan Dayton High School. The remaining water outlets were either permanently out of service or disabled due to Covid-19 restrictions.

Results: Eleven of the samples analyzed were either "None Detected" or less than the EPA established threshold for lead in drinking water. However, seven of the samples were above the allowable limit established by The United States Environmental Protection Agency (USEPA) of 15 parts per billion (ppb). When a water outlet/faucet meets or exceeds the USEPA threshold, EnviroVision recommends that the outlet/faucet be immediately put out of service until the system can be further evaluated and proper remedial action is achieved.



JONATHAN DAYTON HIGH SCHOOL- LEAD (Pb) in Water Results of Concern

Outlet ID/Sample Number	Location	Results
EC4(JD)	Culinary Arts	16.0 ppb
FP4 (JD)	Culinary Arts	76.3 ppb
FP5 (JD)	Culinary Arts	45.8 ppb
TL2 (JD)	2 nd floor Teacher Lounge	25.7 ppb
FP3 (JD)	Basement Kitchen	35.2 ppb
TL1 (JD)	Guidance Office Break Room Sink	18.5 ppb
EC1 (JD)	Culinary Arts	34.5 ppb

Due to the elevated levels in the above outlets, we recommend that some or all of the following steps be taken at this time;

- Closure of the affected water outlet(s) until the system can be further evaluated and proper remedial action is achieved.
- Removal and replacement with non-lead containing fixtures.
- Installation of filtration systems.
- Development of a Flushing Program for those taps high in lead and turbidity (this may include automatic flushing systems).
- Contact the local water utility company to obtain information about their corrosion control procedures and how it might affect the District's control plans.
- Permanent closure of outlet(s).

Once the remedial action(s) are complete, follow up testing is required to ensure alterations/replacement to plumbing fixtures has lowered the amount of lead to acceptable levels.

I have also enclosed documents with detailed steps from the New Jersey Department of Environmental Protection regarding notifications that must be made, posting of results, and initial and long-term remedial requirements.



Page 3 (Jonathan Dayton High School)

Project Number 21-358

If you have any questions, or if we could be of any further assistance, please feel free to contact our office. EnviroVision looks forward to providing you with the service and attention to detail you have come to expect from us.

Sincerely,
EnviroVision Consultants, Inc.

Cathy DiNardo

Cathy DiNardo, Project Manager

Attached: Lab results, Associated data sheets, DEP Overview of Lead in Drinking Water at School Facilities, DEP Guidance for Selecting a Remedial Measure for Lead Removal



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone: (856) 303-2500 Fax: (856) 858-4571 Email: EnvChemistry2@emsl.com

Attn:

**Leonardo Bitondo
EnviroVision Consultants, Inc
20-21 Wagaraw Rd
Bldg 35E
Fair Lawn, NJ 07410**

9/13/2021

Phone: (973) 636-9145
Fax: (973) 636-9144

The following analytical report covers the analysis performed on samples submitted to EMSL Analytical, Inc. on 8/30/2021. The results are tabulated on the attached data pages for the following client designated project:

Jonathan Dayton High School

The reference number for these samples is EMSL Order #012110093. Please use this reference when calling about these samples. If you have any questions, please do not hesitate to contact me at (856) 303-2500.

Approved By:

Phillip Worby, Environmental Chemistry
Laboratory Director



The test results contained within this report meet the requirements of NELAP and/or the specific certification program that is applicable, unless otherwise noted.

NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, CA ELAP 1877

The samples associated with this report were received in good condition unless otherwise noted. This report relates only to those items tested as received by the laboratory. The QC data associated with the sample results meet the recovery and precision requirements established by the NELAP, unless specifically indicated. All results for soil samples are reported on a dry weight basis, unless otherwise noted. This report may not be reproduced except in full and without written approval by EMSL Analytical, Inc.

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012110093

CustomerID: RAMA51

CustomerPO:

ProjectID:

Attn: **Leonardo Bitondo**
EnviroVision Consultants, Inc
20-21 Wagaraw Rd
Bldg 35E
Fair Lawn, NJ 07410

Phone: (973) 636-9145
 Fax: (973) 636-9144
 Received: 8/30/2021 09:00 AM

Project: **Jonathan Dayton High School****Analytical Results**

Client Sample Description Blank **Collected:** 8/27/2021 **Lab ID:** 012110093-0001

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	9/9/2021 VD	9/9/2021 16:46 VD

Client Sample Description WC1-JOB5 **Collected:** 8/27/2021 **Lab ID:** 012110093-0002

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	9/9/2021 VD	9/9/2021 16:50 VD

Client Sample Description FP1-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0003

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	8.69	1.00 µg/L	9/9/2021 VD	9/9/2021 16:51 VD

Client Sample Description FP2-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0004

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	1.29	1.00 µg/L	9/9/2021 VD	9/9/2021 16:53 VD

Client Sample Description EC3-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0005

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	6.39	1.00 µg/L	9/9/2021 VD	9/9/2021 17:00 VD

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012110093

CustomerID: RAMA51

CustomerPO:

ProjectID:

Attn: **Leonardo Bitondo**
EnviroVision Consultants, Inc
20-21 Wagaraw Rd
Bldg 35E
Fair Lawn, NJ 07410

Phone: (973) 636-9145
Fax: (973) 636-9144
Received: 8/30/2021 09:00 AM

Project: **Jonathan Dayton High School****Analytical Results**

Client Sample Description EC4-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0006

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	16.0	1.00 µg/L	9/9/2021 VD	9/9/2021 17:01 VD

Client Sample Description FP4-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0007

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	76.3	1.00 µg/L	9/8/2021 KG	9/9/2021 13:48 JW

Client Sample Description FP5-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0008

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	45.8	1.00 µg/L	9/9/2021 VD	9/9/2021 17:03 VD

Client Sample Description TL2-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0009

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	25.7	1.00 µg/L	9/9/2021 VD	9/9/2021 17:04 VD

Client Sample Description WC4-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0010

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	9/9/2021 VD	9/9/2021 17:05 VD

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012110093

CustomerID: RAMA51

CustomerPO:

ProjectID:

Attn: **Leonardo Bitondo**
EnviroVision Consultants, Inc
20-21 Wagaraw Rd
Bldg 35E
Fair Lawn, NJ 07410

Phone: (973) 636-9145
Fax: (973) 636-9144
Received: 8/30/2021 09:00 AM

Project: **Jonathan Dayton High School****Analytical Results**

Client Sample Description FP6-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0011

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.68	1.00 µg/L	9/9/2021 VD	9/9/2021 17:07 VD

Client Sample Description FP3-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0012

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	35.2 D	2.00 µg/L	9/9/2021 VD	9/10/2021 09:12 VD

Client Sample Description IM1-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0013

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	1.58	1.00 µg/L	9/9/2021 VD	9/9/2021 17:15 VD

Client Sample Description KC1-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0014

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	11.0	1.00 µg/L	9/9/2021 VD	9/9/2021 17:16 VD

Client Sample Description WC3-BFJD **Collected:** 8/27/2021 **Lab ID:** 012110093-0015

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	9/9/2021 VD	9/9/2021 17:18 VD

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012110093

CustomerID: RAMA51

CustomerPO:

ProjectID:

Attn: **Leonardo Bitondo**
EnviroVision Consultants, Inc
20-21 Wagaraw Rd
Bldg 35E
Fair Lawn, NJ 07410

Phone: (973) 636-9145
 Fax: (973) 636-9144
 Received: 8/30/2021 09:00 AM

Project: **Jonathan Dayton High School****Analytical Results**

Client Sample Description WC2-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0016

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	9/9/2021 VD	9/9/2021 17:19 VD

Client Sample Description TL1-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0017

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	18.5	1.00 µg/L	9/9/2021 VD	9/9/2021 17:21 VD

Client Sample Description EC1-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0018

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	34.5	1.00 µg/L	9/8/2021 KG	9/9/2021 13:51 JW

Client Sample Description EC2-JD **Collected:** 8/27/2021 **Lab ID:** 012110093-0019

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	11.5	1.00 µg/L	9/9/2021 VD	9/9/2021 17:22 VD

Definitions:

MDL - method detection limit

J - Result was below the reporting limit, but at or above the MDL

ND - indicates that the analyte was not detected at the reporting limit

RL - Reporting Limit (Analytical)

D - Dilution Sample required a dilution which was used to calculate final results

200 Rt. 130 N
Cinnaminson, NJ 08077

PHONE: (800) 220-3675
EMAIL: EnvChemistry2@EMSL.co

Environmental Chemistry Chain of Custody

EMSL Order Number / Lab Use Only

012110093

EMSL ANALYTICAL, INC.

Customer Information		Billing Information		Billing ID:	
Company Name: EnviroVision		Company Name: U.S.A.M.E.			
Contact Name: Leonardo Bitondo		Billing Contact:			
Street Address: 20-21 Wagaraw Road-Bldg-35E		Street Address:			
City, State, Zip: Fair Lawn, New Jersey		City, State, Zip:			
Phone: 973 636 9145		Phone:			
Email(s) for Report: Envirovision@optonline.net		Email(s) for Invoice:			
Project Name/No: Jonathan Dayton High School		US State where samples collected: NJ		State of Connecticut (CT) must select project location: Residential (Non-Taxable) ☐ Commercial (Taxable) ☐ State Reporting Required? ☐ Yes ☐ No	
EMSL LIMS Project ID: (If applicable, EMSL will provide)		PWS ID:			
Samples for Compliance? ☒ Yes ☐ No		If Yes, for NPDES? ☐ Yes ☐ No		Other (Specify)	
Samples Collected by (Check One): ☐ EMSL ☐ CLIENT		Samples Received Chilled? ☐ Yes ☐ No		Sample(s) Temperature Upon Receipt (LAB ONLY)	
Sampled By Name: Leo Bitondo		Sampled By Signature: <i>[Signature]</i>		No. of Samples in Shipment:	
Turn-Around-Time (TAT): 2 Weeks		Standard Turn-Around-Time: 2 Weeks		1 Week ☐ 2 Days ☐ 3 Days ☐ 4 Days ☐ 1 Day ☐	
The following TAT's are subject to Lab approval. Call lab to confirm TAT before submitting:		List Test(s) Needed (Write in test below, then check on sample line.):		Comments	
Client Sample ID	Comp	Date / Time Collected	Grab	Matrix	Preservative
1 Blank		8/27/21		W=Water S=Soil A=Air SL=Sludge O=Other	1 HCL 2 HNO3 3 H2SO4 4 ICE 5 Other
2 WCL-3086					
3 FP1-JD					
4 FP2-JD					
Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)					
Reporting Requirements: ☐ Results Only ☐ Results and QC ☐ Reduced Deliverables ☐ HazResults EDD ☐ Excel ☐ Other (Describe Above)					
Method of Shipment: Drop off					
Relinquished by: Leo Bitondo					
Relinquished by: Leo Bitondo					
Date/Time: 8/27/21					
Date/Time: 8/27/21					
Received by: Leo Bitondo					
Received by: Leo Bitondo					
Date/Time: 8/27/21					
Date/Time: 8/27/21					

Controlled Document - COC-07-Chemistry-R11-0226/2021

Page 1 of 2

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by the customer.

8/27/21 8:30pm
Eduym 08/30/21 9:00 am Rec. period 8/27/21

RECEIVED
Date/Time: **8/27/21**
Date/Time: **8/27/21**
Date/Time: **8/27/21**
Date/Time: **8/27/21**

Environmental Chemistry Chain of Custody

EMSL Order Number / Lab Use Only

012110093

EMSL Analytical, Inc.
200 Rt. 130 N
Cinnaminson, NJ 08077PHONE (800) 220-3875
EMAIL EnvChemistry2@EMSL.com

EMSL ANALYTICAL, INC.

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)

Client Sample ID	Comp	Grab	Date / Time Collected	Matrix	Preservative	List Test(s) Needed (Write in test below, then check on sample line.)							Comments	
						Test 1	Test 2	Test 3	Test 4	Test 5	Test 6	Test 7		Test 8
5 EC3-JD	☐	☐	8/27/21	W	2	☒	☐	☐	☐	☐	☐	☐	☐	NO odor / no color
6 EC4-JD	☐	☐		W		☒	☐	☐	☐	☐	☐	☐	☐	-11-
7 FP4-JD	☐	☐		W		☒	☐	☐	☐	☐	☐	☐	☐	-11-
8 FP5-JD	☐	☐		W		☒	☐	☐	☐	☐	☐	☐	☐	-11-
9 TL2-JD	☐	☐		W		☒	☐	☐	☐	☐	☐	☐	☐	-11-
10 WC4-JD	☐	☐		W		☒	☐	☐	☐	☐	☐	☐	☐	-11-
11 FP6-JD	☐	☐		W		☒	☐	☐	☐	☐	☐	☐	☐	-11-
	☐	☐				☐	☐	☐	☐	☐	☐	☐	☐	

Method of Shipment		Sample Condition Upon Receipt	
Relinquished by: <i>[Signature]</i>	Date/Time: 8/27/21	Received by:	Date/Time:
Relinquished by:	Date/Time:	Received by:	Date/Time:

RECEIVED

Controlled Document - CQC-07 Chemistry R11 02/23/2021

☐ AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.

BY EMSL PISCATAWAY Page 2 of 2

Environmental Chemistry Chain of Custody

EMSL Order Number / Lab Use Only

012110093

EMSL Analytical, Inc.
200 RL 130 N
Cinnaminson, NJ 08077

PHONE (800) 220-3675
EMAIL EnvChemistry2@EMSL.com

EMSL ANALYTICAL, INC.

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information
Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)

Client Sample ID	Comp	Grab	Date / Time Collected	Matrix	Preservative	List Test(s) Needed (Write in test below, then check on sample line.)						Comments
						Test 1	Test 2	Test 3	Test 4	Test 5	Test 6	
FP3-50	☐	☐	8/29/21	W	2	☒	☐	☐	☐	☐	☐	
Im1-50	☐	☐	↓	W	2	☒	☐	☐	☐	☐	☐	
KC1-50	☐	☐	↓	W	2	☒	☐	☐	☐	☐	☐	
WC3-BF50	☐	☐	↓	↓	↓	☒	☐	☐	☐	☐	☐	
WC2-50	☐	☐	↓	↓	↓	☒	☐	☐	☐	☐	☐	
TL1-50	☐	☐	↓	↓	↓	☒	☐	☐	☐	☐	☐	
EC1-50	☐	☐	↓	↓	↓	☒	☐	☐	☐	☐	☐	
EC2-50	☐	☐	↓	↓	↓	☒	☐	☐	☐	☐	☐	

Method of Shipment: _____

Relinquished by: See Barb Date/Time: 8/29/21

Relinquished by: _____ Date/Time: _____

Received by: _____ Date/Time: _____

Received by: _____ Date/Time: _____

RECEIVED

Controlled Document - CQC-07 Chemistry R11 02/20/2021

AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.) ☐

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.

Drinking Water Outlet Inventory

Name of School: JONATHAN DAYTON HIGH SCHOOL Address: 139 MOUNTAIN AVE.

Grade Levels: 9 THRU 12 Year School Constructed: 1937 Renovated/Additions: 1951, 1973

Individual school project officer Name/Signature: _____ Date Completed: _____

#1	Type	Location	Code	Operational ² (Y/N)	Signs of Corrosion ³ (Y/N)	Filter ⁴ (Y/N)	Brass Fittings, Faucets or valves? (Y/N)	Aerator/ Screen (Y/N)	Motion Activated (Y/N)	Chiller (Y/N)	Water Cooler		Comments
											Make	Model	
1	Fountain/ bottle filler	Cafeteria	WC 1	Yes	No	Yes	Yes	yes	Yes	Yes	Elkay	EZ H20	Installed 2016
2	Food Prep	Basement Kitchen	FP 1	yes	No	No	Yes	No	No	No			
3	Food Prep	Basement Kitchen	FP 2	Yes	No	No	Yes	No	No	No			
4	Food Prep	Basement Kitchen	FP 3	Yes	No	No	Yes	No	No	No			
5	Porcelain Drinking Bubbler	Weight room changing area	DW 1	no	Yes	No	Yes	No	No	No	American Standard		Removed 2020
6	Ice Maker	Trainers Room	IM 1	Yes	No	Yes	Yes	No	No	Yes			

¹ Number outlets starting at the closest outlet to the Point of Entry (POE).

² Document if permanently or temporarily out of service on the Attachment B- Plumbing Profile.

³ Signs of corrosion detected, such as but not limited to frequent leaks, rust-colored water, or stained fixtures, dishes, or laundry.

⁴ Document on Attachment D- Filter Inventory.

SPRINGFIELD PUBLIC SCHOOLS Sampling Plan
January 4, 2017

Version 1

7	Porcelain bubbler Steel	Basement Hallway	DW 2	No		Yes	No	Yes	No	No	No	American Standard	None found	Removed 2020
8	Porcelain Drinking Bubbler	Basement Hallway	DW 3	No	Yes	No	No	Yes	No	No	No	American Standard	N/A	Removed 2020
9	Porcelain Drinking Bubbler	East gym Hallway	DW 4	No	No	No	No	Yes	No	No	No	American Standard	N/A	Removed 2020
10	Sink	Guidance Office	KC 1	Yes	No	Yes	No	Yes	Yes	No	No			
11	Stainless Steel	1 st floor hallway by main entrance	WC 3	Yes	No	Yes	Yes	Yes	Yes	Yes	Yes	Elkay	EZ20	Installed 3/2017
12	Sink	Nurses office	NS 1	Yes	No	Yes	No	No	No	No	No			Removed 2020
13	Stainless Steel	1 st floor hallway by auditorium	DW 5	Yes	No	Yes	No	No	No	no	no			
14	Fountain Bottle filler	1 st floor by media center	WC 2	no	Yes	Yes	no	yes	no	no	no	Elkay	EZ H20	
15	Drinking Bubbler	2 nd floor hallway Balcony area	DW 6	No	Yes	Yes	No	No	No	No	No			Removed 2020
16	Drinking Bubbler	2 nd floor hallway by Rm 217	DW 7	No	Yes	Yes	No	Yes	No	No	No			Removed 2020
17	Drinking Bubbler	2 nd floor by room 217	DW 8	No	Yes	Yes	No	Yes	No	No	No			Removed 2020
18	Teacher lounge sink	Guidance Office Break Room	TL 1	Yes	No	Yes	No	Yes	Yes	No	No			
19	Stainless Steel	Culinary arts	EC 1	Yes	No	Yes	No	Yes	Yes	No	No			

SPRINGFIELD PUBLIC SCHOOLS Sampling Plan
January 4, 2017
HS
Version 1

20	Stainless Steel	Culinary Arts	EC 2	Yes	No	No	Yes	Yes	No	No		
21	Stainless Steel	Culinary Arts	EC 3	Yes	No	No	Yes	Yes	No	No		
22	Stainless Steel	Culinary Arts	EC 4	Yes	No	No	Yes	Yes	No	No		
23	Stainless Steel	Culinary Arts	FP 4	Yes	No	No	Yes	Yes	No	No		
24	Stainless Steel	Culinary Arts	FP 5	Yes	No	No	Yes	Yes	No	No		
25	Drinking Bubbler	2 nd floor hallway by rm 205	DW 9	No	No	No	Yes	No	No	No	Removed 20/20	
26	Drinking Bubbler	2 nd floor by room 205	DW 10	No	No	No	Yes	No	No	No	Removed 2020	
27	Porcelain	2 nd floor teachers room	TL 2	Yes	No	Yes	Yes	Yes	No	No		
28	Water cooler	2 nd floor hallway outside Bd office	WC4	Yes	No	Yes	Yes	Yes	Yes	Elkay	EZ20	Installed 3/2017
29	Stainless steel sink	Board office	FP6	Yes	No	Yes	No	Yes	No	No		
30	Drinking Bubbler	Concession stand	CS1	Yes	No	No	Yes	Yes	No	No		
31	Drinking Bubbler	Concession stand	CS2	Yes	No	No	Yes	Yes	No	No		