

SAMPLE NAME	SAMPLE LOCATION	DATE COLLECTED	RESULT	QUALIFIER	UNIT	REPORTING LIMIT
IR-10-1-103-DWC-P-01	Water Fountain w/ Cooler located outside RM 103	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-1-103-DWC-SS-01	Water Fountain w/ Cooler located outside RM 103	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-1-103-DWC-F-01	Water Fountain w/ Cooler located outside RM 103	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-1-103-WBF-P-02	Water Bottle Filler located outside RM 103	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-1-103-WBF-SS-02	Water Bottle Filler located outside RM 103	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-1-103-WBF-F-02	Water Bottle Filler located outside RM 103	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-1-CAF-DW-P-03	Water Fountain in Cafeteria	12/21/2022	0.0034		mg/L	0.0020
IR-10-1-CAF-DW-SS-03	Water Fountain in Cafeteria	12/21/2022	0.0021		mg/L	0.0020
IR-10-1-CAF-DW-F-03	Water Fountain in Cafeteria	12/21/2022	0.0030		mg/L	0.0020
IR-10-1-CAF-DW-P-04	Water Fountain in Cafeteria	12/21/2022	0.019		mg/L	0.0020
IR-10-1-CAF-DW-SS-04	Water Fountain in Cafeteria	12/21/2022	0.090		mg/L	0.0020
IR-10-1-CAF-DW-F-04	Water Fountain in Cafeteria	12/21/2022	0.061		mg/L	0.0020
IR-10-1-KIT-KF-P-05	Faucet located in Kitchen	12/21/2022	0.0020	U	mg/L	0.0020

Immediate Remedial Response
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet,Provide Filters at Problem Tap, Continous Daily/Weekly Flushing, Provide Bottle Water, Resample
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet,Provide Filters at Problem Tap, Continous Daily/Weekly Flushing, Provide Bottle Water, Resample
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet,Provide Filters at Problem Tap, Continous Daily/Weekly Flushing, Provide Bottle Water, Resample
NA

Long-Term Remedial Response
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
Provide Filters, Repalce Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
Provide Filters, Repalce Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
Provide Filters, Repalce Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
NA



IR-10-1-129-DW-F-10	Water Fountain located outside RM 129	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA
IR-10-1-139-DW-P-11	Water Fountain located outside RM 139	12/21/2022	0.00067	J	mg/L	0.0020	NA	NA
IR-10-1-139-DW-SS-11	Water Fountain located outside RM 139	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA
IR-10-1-139-DW-F-11	Water Fountain located outside RM 139	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA
IR-10-1-139-DW-P-12	Water Fountain located outside RM 139	12/21/2022	0.00076	J	mg/L	0.0020	NA	NA
IR-10-1-139-DW-SS-12	Water Fountain located outside RM 139	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA
IR-10-1-139-DW-F-12	Water Fountain located outside RM 139	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA
IR-10-1-144-DWC-P-13	Water Fountain with Cooler Located outside RM 144	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA
IR-10-1-144-DWC-SS-13	Water Fountain with Cooler Located outside RM 144	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA
IR-10-1-144-DWC-F-13	Water Fountain with Cooler Located outside RM 144	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA
IR-10-1-144-WBF-P-14	Water Bottle Filler located outside RM 144	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA
IR-10-1-144-WBF-SS-14	Water Bottle Filler located outside RM 144	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA
IR-10-1-144-WBF-F-14	Water Bottle Filler located outside RM 144	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA
IR-10-2-214-DWC-P-15	Water Fountain with Cooler Located outside RM 214	12/21/2022	0.0020	U	mg/L	0.0020	NA	NA

IR-10-2-214-DWC-SS-15	Water Fountain with Cooler Located outside RM 214	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-2-214-DWC-F-15	Water Fountain with Cooler Located outside RM 214	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-2-214-WBF-P-16	Water Bottle Filler Located Outside RM 214	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-2-214-WBF-SS-16	Water Bottle Filler Located Outside RM 214	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-2-214-WBF-F-16	Water Bottle Filler Located Outside RM 214	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-2-205-DW-P-17	Water Fountain Located Outside RM 205	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-2-205-DW-SS-17	Water Fountain Located Outside RM 205	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-2-205-DW-F-17	Water Fountain Located Outside RM 205	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-2-205-DW-P-18	Water Fountain Located Outside RM 205	12/21/2022	0.00097	J	mg/L	0.0020
IR-10-2-205-DW-SS-18	Water Fountain Located Outside RM 205	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-2-205-DW-F-18	Water Fountain Located Outside RM 205	12/21/2022	0.0020	U	mg/L	0.0020
IR-10-1-117-DWC-P-19	Water Fountain w/ Cooler located outside RM 117	12/21/2022	0.080		mg/L	0.0020
IR-10-1-117-DWC-SS-19	Water Fountain w/ Cooler located outside RM 117	12/21/2022	0.10		mg/L	0.0020
IR-10-1-117-DWC-F-19	Water Fountain w/ Cooler located outside RM 117	12/21/2022	0.14		mg/L	0.0020

NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet, Provide Filters at Problem Tap, Continuous Daily/Weekly Flushing, Provide Bottle Water, Resample
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet, Provide Filters at Problem Tap, Continuous Daily/Weekly Flushing, Provide Bottle Water, Resample
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet, Provide Filters at Problem Tap, Continuous Daily/Weekly Flushing, Provide Bottle Water, Resample

NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
NA
Provide Filters, Repair Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
Provide Filters, Repair Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
Provide Filters, Repair Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample

Key - Sample Name

Key - Qualifier

P	Primary Sample
SS	Sequential Sample
F	Flush Sample

U	Not Detected in Laboratory Analysis
J	Result is Between Laboratory Detection Limit & Laboratory Reporting Limit