

Water Sampling Log

Name of Building: Blairstown School
 Building Owner: Blairstown Board of Education

Date Collected: 22-Mar-22
 Sample Collected by: Alex Lahey

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Results (µg/L)	
							Cu	Pb
RK-032222-01	1	1st	Sink Faucet		Basement Room 35	07:04	X	12.5
RK-032222-02	2	1st	Sink Faucet		Maintenance Office	07:06	X	ND
RK-032222-03	3	1st	Sink Faucet		Room 52 - Nurse's Office	07:09	X	2.3
RK-032222-04	4	1st	Sink Faucet		Kitchen Sink, left side only	07:12	X	9.6
RK-032222-05	5	1st	Bottle Filler	Elkay	Main Hallway - outside Main Office	07:16	X	ND
RK-032222-06	6	1st	Chiller	Elkay	2nd Floor Hallway - outside Room 32	07:19	X	1.4
RK-032222-07	7	1st	Sink Faucet		Teachers' Lounge	07:21	X	ND
RK-032222-08	8	1st	Bottle Filler	Elkay	Gym entrance Lobby	07:24	X	ND
RK-032222-09	9	1st	Sink Faucet		Room 49, with coffee maker	07:28	X	1.1
RK-032222-10	10	1st	Chiller	SunRoc	Hallway - outside Room 27	07:31	X	416
RK-032222-11	11	1st	Sink Faucet		Library Office 63	07:34	X	16.3
RK-032222-12	12	1st	Chiller	Elkay	Hallway - outside Room 23	07:37	X	ND
RK-032222-13	13	1st	Bottle Filler	Elkay	1st floor Hallway - by lavatories, opposite Room 3	07:40	X	ND
RK-032222-14	14	1st	Chiller	Elkay	Room 4	07:42	X	ND
RK-032222-15	15	1st	Chiller	Elkay	Hallway - outside Room 6, left side	07:44	X	41.6
RK-032222-16	16	1st	Chiller	Elkay	Hallway - outside Room 6, right side	07:45	X	21.8
RK-032222-17	17	1st	Chiller	Elkay	Room 5	07:47	X	5.3
RK-032222-18	18	1st	Chiller	Elkay	Room 6	07:48	X	ND
RK-032222-19	19	1st	Bottle Filler	Elkay	2nd floor Hallway - by lavatories, opposite Room 12	07:51	X	ND
RK-032222-20	20	1st	Chiller	Elkay	Hallway - outside Room 15, left side	07:54	X	1.2

Sample Type:

1st: First Draw sample collected after water sat in pipe between 8 and 18 hours

FL: Water flushed through tap for at least 2 minutes

ND: means Not Detected at or above the Reliability Detection Limit (RDL) of 0.0010 mg/L for Lead.

