

Assessment Results Exceedance Table

Of the 87 samples collected at Croton-Harmon High School, 44 (50.6%) had lead concentrations that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Croton-Harmon High School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/19/16	CHHS-03	1 st	Sinkin Room 103 Bathroom	37.3
10/19/16	CHHS-04	1 st	Sink in Room 103	83.7
10/19/16	CHHS-08	1 st	Sink in Bathroom near Room 105	19.8
10/19/16	CHHS-13	1 st	Sink in Room 106 Bathroom (Right)	855
10/19/16	CHHS-15	1 st	Shower Room Hose	37.2
10/19/16	CHHS-19	2 nd	Sink in Room 200B By Entrance	19.0
10/19/16	CHHS-20	2 nd	Sink in Room 200B Facing Wall (Left Sink, Left Faucet)	23.1
10/19/16	CHHS-22	2 nd	Sink in Room 200B Facing Wall (Center Sink, Left Faucet)	15.2
10/19/16	CHHS-24	2 nd	Sink in Room 200B Facing Wall (Right Sink, Left Faucet)	21.4
10/19/16	CHHS-25	2 nd	Sink in Room 200B Facing Wall (Right Sink, Right Faucet)	31.9
10/19/16	CHHS-27	2 nd	Sink in Room 200B Facing Window (Left Sink, Left Faucet)	44.3
10/19/16	CHHS-28	2 nd	Sink in Room 200B Facing Window (Left Sink, Right Faucet)	70.6
10/19/16	CHHS-29	2 nd	Second Sink from Left in Room 200B Facing Window (Right Faucet)	37.3
10/19/16	CHHS-33	2 nd	Fourth Sink from Left in Room 200B Facing Window (Left Faucet)	21.3
10/19/16	CHHS-34	2 nd	Fourth Sink from Left in Room 200B Facing Window (Right Faucet)	22.4
10/19/16	CHHS-35	2 nd	Far Right Sink in Room 200B Facing Window (Left Faucet)	46.2
10/19/16	CHHS-36	2 nd	Far Right Sink in Room 200B Facing Window (Right Faucet)	50.4
10/19/16	CHHS-37	2 nd	Sink in Room 200C	39.1
10/19/16	CHHS-39	2 nd	Sink in Room 200A Facing Window (Left Sink, Left Faucet)	122
10/19/16	CHHS-49	2 nd	Sink in Room 200A, Exhaust Hood	161
10/19/16	CHHS-50	2 nd	Left Sink Facing Wall in Room 200A (Left Faucet)	44.6
10/19/16	CHHS-53	2 nd	Center Sink Facing Wall in Room 200A (Right Faucet)	28.4
10/19/16	CHHS-54	2 nd	Right Sink Facing Wall in Room 200A (Left Faucet)	16.0
10/19/16	CHHS-56	2 nd	Sink in Room 201F	27.7
10/19/16	CHHS-57	2 nd	Sink in Room 204	25.0
10/19/16	CHHS-65	3 rd	Sink in Room 306 (Left)	70.8
10/19/16	CHHS-66	3 rd	Sink in Room 306 (Center)	71.9
10/19/16	CHHS-67	3 rd	Sink in Room 306 (Right)	108
10/19/16	CHHS-71	3 rd	Sink in Room 309 (Left)	110
10/19/16	CHHS-72	3 rd	Sink in Room 309 (Right)	207

Croton-Harmon High School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/19/16	CHHS-73	3 rd	Sink in Room 311 (2)	201
10/19/16	CHHS-74	3 rd	Sink in Room 311 (3)	177
10/19/16	CHHS-75	3 rd	Sink in Room 311 (4)	179
10/19/16	CHHS-76	3 rd	Sink in Room 311 (5)	218
10/19/16	CHHS-77	3 rd	Sink in Room 311 (6)	352
10/19/16	CHHS-78	3 rd	Sink in Room 311 Wash Sink	247
10/19/16	CHHS-79	3 rd	Sink in Room 312 Prep Room	133
10/19/16	CHHS-80	3 rd	Sink in Room 312 (1)	234
10/19/16	CHHS-81	3 rd	Sink in Room 312 (2)	155
10/19/16	CHHS-82	3 rd	Sink in Room 312 (3)	203
10/19/16	CHHS-83	3 rd	Sink in Room 312	111
10/19/16	CHHS-84	3 rd	Sink in Room 312 – Hose	31.1
10/19/16	CHHS-85	1 st	Hose Bib Outside of Room 103	96.8
10/19/16	CHHS-87	1 st	Hose Bib Outside of Boiler Room	55.1