

Combined CTE @ Midland Ave.



Week Ending June 30, 2023

Combined CTE @ Midland Ave.

➤ **Current and Upcoming Work Effort:**

- Exterior precast panel demolition complete and staining ongoing
- Site and MEP demolition continued
- Concrete slab work continued
- Masonry walls topped out and bracing continuing on Levels 3 and 4
- Ductwork installation continued on Levels 3 and 4
- Plumbing above ceiling continued on Levels 3 and 4
- Precast panels to continue cleaning and stain applied
- Site excavation to continue on bus loop
- Windows to start after fireproofing on roof decking
- Ductwork installation to continue
- Electrical and plumbing wall rough-Ins to continue with masonry

Existing precast panels being stained and new steel progeessing



Week Ending June 30, 2023

New exterior steel being erected on Midland



Week Ending June 30, 2023

New grease trap set



Week Ending June 30, 2023

Train area being filled with stone



Week Ending June 30, 2023

Existing cooling towers removed



Week Ending June 30, 2023

Roofing cap sheet progressing



Week Ending June 30, 2023

Roofing cap sheet progressing



Week Ending June 30, 2023

New roof curbs set



Week Ending June 30, 2023

Rendered site plan



Week Ending June 30, 2023

Midland Town Branch Trail Rendering



Week Ending June 30, 2023