




Site Access Plan  
PSD Maintenance and Central Laundry  
324 9th St. N.W.  
Puyallup, WA 98371

Scale:  
NTS  
Drawn By:  
RG  
Date:  
June 2019  
Site/ Bldg/ Floor No.  
79-Site  
Range/ Township/ Section:  
04-20-28  
Parcel Number(s):  
0420282096

Sheet No.  
C1 of 1



STANDARD "CAR" STALLS WEST END	101
STANDARD "TRUCK" STALLS EAST END	51
"B" FULL BUS PARKING	80
"SB" SMALL BUS PARKING	26

# Building Access Photo Locations



# Maintenance/Central Laundry Building ADA Site Photos

1



From ADA stalls in the parking lot, continue up the asphalt ramp and follow the sidewalk on the south side of the building for access. Note that the asphalt ramp from the parking lot does not meet all ADA standards.

2



Continue heading east, past the Transportation building and bus garage. Through the bus parking area, at the other (eastern- most) end of the site, lies the Maintenance building. Enter through the nearest door, located at the northwest corner of the building.

ADA Site Photos  
PSD Maintenance/Central Laundry  
324 9th St. N.W.  
Puyallup, WA 98371

Scale:  
NTS

Drawn By:  
RG

Date:  
June 2019

Site/ Bldg/ Floor No.  
79-Site

Range/ Township/ Section:

Parcel Number(s):

Sheet No.

C1 of 1