Combined CTE @ Midland Ave.





Combined CTE @ Midland Ave.


Current and Upcoming Work Effort:


- Exterior precast panel demolition complete
- Site and MEP demolition continued
- Concrete slab work continued
- Masonry walls topped out and bracing continuing on Levels 3 and 4
- Ductwork installation continued on Levels 3 and 4
- Plumbing above ceiling continued on Levels 3 and 4
- Precast panels to continue cleaning and stain applied
- Site excavation to start on bus loop
- Windows to start after fireproofing on roof decking
- Ductwork installation to continue
- Electrical and plumbing wall rough-Ins to continue with masonry


















Rendered Site Plan



