Combined CTE @ Midland Ave.




Combined CTE @ Midland Ave.

Current and Upcoming Work Effort:


- Interior and site demo continuing on Levels 2 and 1, Level 1
- Level 3 structural framing continued, elevator pit walls poured, forms stipped
- Level 4 windows removed
- Masonry walls have continued on Levels 3, and 2
- Ductwork installation continued on Levels 4 and 3
- Interior demo to continue on Levels 2 and 1, exterior panels to start being removed
- Level 3 structural framing to continue
- Door frame and masonry installation to continue as needed on Levels 3 and 2
- Fireproofing to continue on Level 2
- Ductwork installation to continue
- Electrical and plumbing wall rough-Ins to continue with masonry
- Roofing base sheet work to continue and should complete, and cap sheet on penthouses

Exterior precast panels completely removed





Concrete poured over portion of existing slab





Interior demo work continues on the first and second floor




Structural framing added in preparation for additional flooring



New elevator shaft walls being built



Concrete slab work continues







Rendered Site Plan



