


NOTES:

- There is no curb cut from the parking lot to allow access to the building and/or field
- A key must be obtained from Security to open the locked gates.



Field and Building Access Photo Locations

Curb cuts do not meet ADA standards



Scale: NTS
Drawn By: RG
Date: May 2019
Site/ Bldg/ Floor No. 15-Site
Range/ Township/ Section: 04-19-05
Parcel Number(s): 4005000271

Woodland Field and Building Access Picture Index

1



From main ADA stalls in parking lot, use the crosswalk and curb cut to gain access to the sidewalk. Note that the curb cut does not meet all ADA standards. For building access, use the nearest door, at the southwest corner of the school.

2



The other ADA stalls, at the east end of the parking lot, are both car stalls. The curb cut does not meet all ADA standards.

3



Note that the right ADA stall at the east end of the parking lot looks very wide due to there being excess room.

4



For field access, continue to the north western part of the parking lot. Continue straight through the vehicle gate, and follow the pathway, on your left, out to the fields. Note that this gate is locked at most times. A key may be obtained from Security.