


School Name: **Oak Park Building (OP)**Date: **5/4/2023**


Floor	Room Number	Location	Sample ID	Type S = Sink WC = Water Cooler BF = Bottle Filler SP = Sprayer	Lead Result (ppb)	Copper Result (ppb)
First Floor	-	Hallway	1-OP-Hall 119-WC	WC	1.66	629
First Floor	-	Hallway	2-OP-Hall 119-BF	BF	2.37	757
First Floor	121	Classroom	3-OP-121-S	S	12.6	66.5
First Floor	-	Food Lab	4-OP-Food Lab-S	S	<0.5	1280
First Floor	-	Food Lab	5-OP-Food Lab-S	S	2.41	15.3
First Floor	-	Food Lab	6-OP-Food Lab-SP	SP	1.49	168
First Floor	-	Hallway	7-OP-Hall-WC(L)	WC	<0.5	88.2
First Floor	-	Hallway	8-OP-Hall-WC(R)	WC	<0.5	56.7
First Floor	-	Hallway	9-OP-Hall-BF	BF	<0.5	33.2
First Floor	129	Classroom	10-OP-129-S	S	2.22	34.6
First Floor	148	Classroom	11-OP-148-S	S	3.76	89.1
First Floor	131B	Classroom	12-OP-131B-S	S	3.12	142

Oak Park Elementary
 First Floor
 Lead in Drinking Water
 Project #23072





Only the newly renovated section of the building was tested.

Oak Park Elementary
 First Floor
 Copper in Drinking Water
 Project #23072





Only the newly renovated section of the building was tested.

Oak Park Elementary
Second Floor
Lead in Drinking Water
Project #23072



Second floor not tested

Oak Park Elementary
Second Floor
Copper in Drinking Water
Project #23072



Second floor not tested