

## TSC

LOCATION	SAMPLE ID	DATE	LEAD RESULT
Maintenance Shop	22430014-001SF23A	4/21/2023	2.66
Driver's Lounge	22430014-002WB23A	4/21/2023	ND
Driver's Lounge/Left Sink	22430014-003SF23A	4/21/2023	0.229
Driver's Lounge/Right Sink	22430014-004SF23A	4/21/2023	0.414
Staff Office Lounge	22430014-005WB23A	4/21/2023	ND
Staff Office Lounge	22430014-006SF23A	4/21/2023	1.47
Reception Lobby	22430014-007DW23A	4/21/2023	0.939
Office 130/Left Sink	22430014-008SF23A <i>(restricted access)</i>	4/21/2023	46.5
Office 130/Left Sink	22430014-008SF23B <i>(restricted access)</i>	4/21/2023	41.5
Office 130/Left Sink	22430014-008SF23C <i>(flush sample)</i>	4/21/2023	8.11
Office 130/Left Sink	22430014-008SF23D <i>(restricted access)</i>	8/8/2023	30.3
Office 130/Left Sink	22430014-008SF23E <i>(flush)</i>	8/8/2023	1.4
Office 130/Right Sink	22430014-009SF23A <i>(restricted access)</i>	4/21/2023	268
Office 130/Right Sink	22430014-009SF23B <i>(post-mitigation)</i>	4/21/2023	2.59
Hall 138/Left Fountain	22430014-010DW23A	4/21/2023	0.791
Hall 138/Right Fountain	22430014-011DW23A	4/21/2023	0.855
Shop A Break Room	22430014-012WB23A	4/21/2023	ND
Shop A Break Room	22430014-013SF23A	4/21/2023	0.458