Lead in School Drinking Water Report

Monroe High School

Date(s) collected: 2023-04-22
Date(s) analyzed: 2023-05-02

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
373367	Main Building	Sink - Multi-Compartment	Kitchen	Largest 3 tier sink across from dishwasher	Tap	29
373670	Main Building	Fountain	Weight Room	Only fountain	Water Fountain	19
373372	Main Building	Pot Filler	Kitchen	Next to ovens 2 of 2 one on right	Tap	14
373366	Main Building	Sink - Multi-Compartment	Kitchen	Largest 3 tier sink across from dish washer	Tap	7
373666	Main Building	Sink - Multi-Compartment	Concession Stand	Only sink	Tap	7
373667	Main Building	Sink - Multi-Compartment	Concession Stand	Only sink	Sprayer	6
373689	Stadium concession stand	Sink	Concessions	Sink in back	Tap	3

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
373369	Main Building	Sink - Multi-Compartment	Kitchen	Vegetable prep sink	Tap	2
373376	Portable 1/2	Fountain	Outside Of Pods Next To Outdoor Restrooms	In between men's and women's bathroom outside	Water Fountain	2
373355	Main Building	Sink - Multi-Compartment	Room 512	Sink 1 of 3 sink on island	Tap	1
373669	Main Building	Fountain	Athletic Hallway	Next to stop ACI	Water Fountain	1
373356	Main Building	Sink - Multi-Compartment	Room 512	Sink on island	Sprayer	<1
373357	Main Building	Sink - Multi-Compartment	Room 512	Sink 2 of 3 sink closest to window	Tap	<1
373358	Main Building	Sink - Multi-Compartment	Room 512	Sink 3 of 3 sink on back wall	Tap	<1
373359	Main Building	Sink - Multi-Compartment	Room 512	Sink 3 of 3 on back wall	Sprayer	<1
373360	Main Building	Fountain	Hallway	Pod 700 fountain next to women's restroom	Water Fountain	<1
373361	Main Building	Fountain	Pod 700	Next to men's restroom	Water Fountain	<1
373362	Main Building	Fountain	Hallway	Across from A.T.L.	Water Fountain	<1
373363	Main Building	Fountain - Multi-Level with Bottle Filler	Cafeteria	Only fountain	Water Bottle Filler	<1
373364	Main Building	Fountain - Multi-Level with Bottle	Cafeteria	Only fountain	Water Fountain	<1

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
		Filler				
373365	Main Building	Sink	Kitchen	Left of dishwasher	Sprayer	<1
373368	Main Building	Sink - Multi-Compartment	Kitchen	2 tier sink next to bun warmer	Tap	<1
373370	Main Building	Sink	Kitchen	Vegetable prep sink	Sprayer	<1
373371	Main Building	Pot Filler	Kitchen	Next to ovens 1 of 2 one on left	Tap	<1
373373	Main Building	Fountain - Multi-Level with Bottle Filler	Pod 500	Next to women's restrooms	Water Bottle Filler	<1
373374	Main Building	Fountain - Multi-Level with Bottle Filler	Pod 500	Next to women's restroom	Water Fountain	<1
373375	Main Building	Fountain	Pod 500	Next to men's restroom	Water Fountain	<1
373377	Main Building	Fountain - Multi-Level with Bottle Filler	Pod 100	Next to men's restroom	Water Bottle Filler	<1
373378	Main Building	Fountain - Multi-Level with Bottle Filler	Pod 100	Next to men's restroom	Water Fountain	<1
373379	Main Building	Fountain	Pod 100	Next to women's restroom	Water Fountain	<1
373663	Main Building	Fountain	Gymnasium	SW fountain	Water Fountain	<1
373664	Main Building	Fountain	Gymnasium	NE fountain	Water Fountain	<1
373665	Main	Fountain	Girls Locker	Only	Water	<1

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
	Building		Room	fountain	Fountain	
373668	Main Building	Fountain	Boys Locker Room	Only fountain	Water Fountain	<1
373671	Main Building	Fountain	Pod 300	Next to women's restroom	Tap	<1
373672	Main Building	Sink	Room 109	Only sink	Tap	<1
373673	Main Building	Sink	Kitchen In Between Rooms 108 And 109	Sink 1 of 2 sink by fridge	Tap	<1
373674	Main Building	Sink	Kitchen In Between Rooms 108 And 109	Sink 2 of 2 next to oven	Tap	<1
373676	Main Building	Sink	Room 108	Only sink	Tap	<1
373677	Main Building	Sink	Health Room.	Only sink	Tap	<1
373678	Main Building	Fountain	Offices	Only fountain	Water Fountain	<1
373679	Main Building	Fountain	Pod 200	Next to women's restroom	Water Fountain	<1
373680	Main Building	Fountain	Pod 200	Next to men's restroom	Water Bottle Filler	<1
373681	Main Building	Fountain - Multi-Level with Bottle Filler	Pod 200	Next to men's restroom	Water Fountain	<1
373682	Main Building	Fountain	Pod 400	Next girls locker room	Water Fountain	<1
373683	Main Building	Fountain	Pod 400	Next to men's restroom	Water Fountain	<1
373684	Main	Fountain	Pod 600	Next to	Water	<1

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
	Building			women's restroom	Fountain	
373685	Main Building	Fountain	Pod 600	Next to men's restrooom	Water Fountain	<1
373686	Main Building	Fountain	Pod 800	Next to women's restroom	Water Fountain	<1
373687	Main Building	Ice Machine	Kitchen	Only ice machine	Other	<1
373688	Stadium concession stand	Sink	Concession Stand	Sink with hot water outlet	Tap	<1

EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: **leadfreekids@doh.wa.gov**