



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

September 30, 2021

Ron Havniar
Medford School District
815 S Oakdale Ave
Medford, OR 97501
TEL: 541-842-3646
FAX 541-842-1160

RE: 32-Jefferson 2021 Lead Testing

Order No.: 21090842

Dear Ron Havniar:

Neilson Research Corporation received 95 sample(s) on 9/21/2021 for the analyses presented in the following report.

The results relate only to the parameters tested or to the sample as received by the laboratory. This report shall not be reproduced except in full, without the written approval of Neilson Research Corporation. If you have any questions regarding these test results, please feel free to call.

Sincerely,
Neilson Research Corporation

Tamra Schmedemann
Senior Project Manager
245 S Grape St
Medford, OR 97501



Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Case Narrative

WO#: 21090842
Date: 9/30/2021

CLIENT: Medford School District

Project: 32-Jefferson 2021 Lead Testing

The analyses were performed according to the guidelines in the Neilson Research Corporation Quality Assurance Program. This report contains analytical results for the sample(s) as received by the laboratory.

Neilson Research Corporation certifies that this report is in compliance with the requirements of NELAP. No unusual difficulties were experienced during analysis of this batch except as noted below or qualified with data flags on the reports.

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-01 **Client Sample ID:** Room 3-Sink (Staff Work Room)
Collection Date: 9/21/2021 6:00:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 3-Sink (Staff Work Room)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.30		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-02 **Client Sample ID:** Hallway Outside Room 3-DF
Collection Date: 9/21/2021 6:00:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Hallway Outside Room 3-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-03 **Client Sample ID:** Hallway Outside Room 3-Bottle Filler
Collection Date: 9/21/2021 6:00:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Hallway Outside Room 3-Bottle Filler

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-04 **Client Sample ID:** Womens RR (3A)-Sink (Across frm Main Off)
Collection Date: 9/21/2021 6:01:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Womens RR (3A)-Sink (Across frm Main Off)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.903		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-05 **Client Sample ID:** Unisex RR (3B)-Sink (Across frm Main Off)
Collection Date: 9/21/2021 6:01:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Unisex RR (3B)-Sink (Across frm Main Off)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	9.37		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-06 **Client Sample ID:** Health Room-Sink
Collection Date: 9/21/2021 6:02:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Health Room-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.73		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-07 **Client Sample ID:** Kitchen-Hand Sink (South)
Collection Date: 9/21/2021 6:04:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Kitchen-Hand Sink (South)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.97		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-08 **Client Sample ID:** Kitchen-Food Prep Sink (West)
Collection Date: 9/21/2021 6:04:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Kitchen-Food Prep Sink (West)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.90		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-09 **Client Sample ID:** Kitchen-Pre-Rinse Sink (North Wall)
Collection Date: 9/21/2021 6:05:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Kitchen-Pre-Rinse Sink (North Wall)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	6.94		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-10 **Client Sample ID:** Kitchen-Hand Sprayer (North Wall)
Collection Date: 9/21/2021 6:05:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Kitchen-Hand Sprayer (North Wall)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.75		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-11 **Client Sample ID:** Staff Break Room (Room 2)-Sink
Collection Date: 9/21/2021 6:07:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Staff Break Room (Room 2)-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	6.57		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-12 **Client Sample ID:** Boys RR (2A) by Custodial Off-Sink A (L)
Collection Date: 9/21/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Boys RR (2A) by Custodial Off-Sink A (L)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.42		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-13 **Client Sample ID:** Boys RR (2A) by Custodial Off-Sink B (C)
Collection Date: 9/21/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Boys RR (2A) by Custodial Off-Sink B (C)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.95		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-14 **Client Sample ID:** Boys RR (2A) by Custodial Off-Sink C (R)
Collection Date: 9/21/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Boys RR (2A) by Custodial Off-Sink C (R)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.70		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-15 **Client Sample ID:** Girls RR (2B) by Staff Break Rm-Sink A (L)
Collection Date: 9/21/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Girls RR (2B) by Staff Break Rm-Sink A (L)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.64		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-16 **Client Sample ID:** Girls RR (2B) by Staff Break Rm-Sink B (C)
Collection Date: 9/21/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Girls RR (2B) by Staff Break Rm-Sink B (C)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.60		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-17 **Client Sample ID:** Girls RR (2B) by Staff Break Rm-Sink C (R)
Collection Date: 9/21/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Girls RR (2B) by Staff Break Rm-Sink C (R)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.00		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-18 **Client Sample ID:** Hallway Outside Boys RR (22A)-DF
Collection Date: 9/21/2021 6:00:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Hallway Outside Boys RR (22A)-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-19 **Client Sample ID:** Hallway Outside Boys RR (22A)-Bottle Filler
Collection Date: 9/21/2021 6:01:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Hallway Outside Boys RR (22A)-Bottle Filler

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-20 **Client Sample ID:** Boys RR (22A)-Sink (L)
Collection Date: 9/21/2021 6:02:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Boys RR (22A)-Sink (L)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.73		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-21 **Client Sample ID:** Boys RR (22A)-Sink (C)
Collection Date: 9/21/2021 6:03:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Boys RR (22A)-Sink (C)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.79		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-22 **Client Sample ID:** Boys RR (22A)-Sink (R)
Collection Date: 9/21/2021 6:04:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Boys RR (22A)-Sink (R)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.94		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-23 **Client Sample ID:** Room 22-DF
Collection Date: 9/21/2021 6:05:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 22-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.594		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-24 **Client Sample ID:** Room 22-Sink
Collection Date: 9/21/2021 6:06:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 22-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	9.11		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-25 **Client Sample ID:** Room 23-DF
Collection Date: 9/21/2021 6:07:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 23-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	10.3		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-26 **Client Sample ID:** Room 23-Sink
Collection Date: 9/21/2021 6:08:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 23-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	7.64		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-27 **Client Sample ID:** Room 24-DF
Collection Date: 9/21/2021 6:09:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 24-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	10.0		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-28 **Client Sample ID:** Room 24-Sink
Collection Date: 9/21/2021 6:10:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 24-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	9.94		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-29 **Client Sample ID:** Room 25-DF
Collection Date: 9/21/2021 6:11:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 25-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	10.1		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-30 **Client Sample ID:** Room 25-Sink
Collection Date: 9/21/2021 6:12:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 25-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	61.9	*	0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-31 **Client Sample ID:** Room 26-DF
Collection Date: 9/21/2021 6:13:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 26-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.65		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-32 **Client Sample ID:** Room 26-Sink
Collection Date: 9/21/2021 6:14:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 26-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	20.8	*	0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-33 **Client Sample ID:** Girls RR (26A) Across frm Rm 29-Sink (L)
Collection Date: 9/21/2021 6:15:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Girls RR (26A) Across frm Rm 29-Sink (L)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.79		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-34 **Client Sample ID:** Girls RR (26A) Across frm Rm 29-Sink (C)
Collection Date: 9/21/2021 6:16:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Girls RR (26A) Across frm Rm 29-Sink (C)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.906		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-35 **Client Sample ID:** Girls RR (26A) Across frm Rm 29-Sink (R)
Collection Date: 9/21/2021 6:17:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Girls RR (26A) Across frm Rm 29-Sink (R)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.73		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-36 **Client Sample ID:** Gym-DF
Collection Date: 9/21/2021 6:01:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Gym-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.33		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-37 **Client Sample ID:** Media Center-DF (Upper)
Collection Date: 9/21/2021 6:04:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Media Center-DF (Upper)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.347		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-38 **Client Sample ID:** Media Center-DF (Lower)
Collection Date: 9/21/2021 6:05:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Media Center-DF (Lower)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.805		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-39 **Client Sample ID:** Media Center-Sink Next to DF
Collection Date: 9/21/2021 6:05:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Media Center-Sink Next to DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	8.94		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-40 **Client Sample ID:** Media Center Storage/Work Rm-Sink
Collection Date: 9/21/2021 6:07:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Media Center Storage/Work Rm-Sink

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.78		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-41 **Client Sample ID:** Playground (Outside)-DF (Upper)
Collection Date: 9/21/2021 6:10:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Playground (Outside)-DF (Upper)

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.08		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-42 **Client Sample ID:** Playground (Outside)-DF (Lower)
Collection Date: 9/21/2021 6:11:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Playground (Outside)-DF (Lower)

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.83		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-43 **Client Sample ID:** Room 6-DF
Collection Date: 9/21/2021 6:13:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 6-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.495		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-44 **Client Sample ID:** Room 6-Sink
Collection Date: 9/21/2021 6:13:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 6-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	8.49		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-45 **Client Sample ID:** Room 7-DF
Collection Date: 9/21/2021 6:15:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 7-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.73		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-46 **Client Sample ID:** Room 7-Sink
Collection Date: 9/21/2021 6:15:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 7-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	6.15		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-47 **Client Sample ID:** Room 9-DF
Collection Date: 9/21/2021 6:16:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 9-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.61		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-48 **Client Sample ID:** Room 9-Sink
Collection Date: 9/21/2021 6:16:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 9-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.87		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-49 **Client Sample ID:** Across from Rm 9-DF (Hallway)
Collection Date: 9/21/2021 6:18:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Across from Rm 9-DF (Hallway)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	8.63		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-50 **Client Sample ID:** Boys RR (Rm 10A) Across frm Rm 9-Sink-L
Collection Date: 9/21/2021 6:20:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Boys RR (Rm 10A) Across frm Rm 9-Sink-L

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.86		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-51 **Client Sample ID:** Boys RR (Rm 10A) Across frm Rm 9-Sink-C
Collection Date: 9/21/2021 6:20:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Boys RR (Rm 10A) Across frm Rm 9-Sink-C

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.79		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-52 **Client Sample ID:** Boys RR (Rm 10A) Across frm Rm 9-Sink-R
Collection Date: 9/21/2021 6:20:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Boys RR (Rm 10A) Across frm Rm 9-Sink-R

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.769		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-53 **Client Sample ID:** Room 10-DF
Collection Date: 9/21/2021 6:02:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 10-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.37		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-54 **Client Sample ID:** Room 10-Sink
Collection Date: 9/21/2021 6:03:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 10-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	7.79		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-55 **Client Sample ID:** Room 11-DF
Collection Date: 9/21/2021 6:06:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 11-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.64		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-56 **Client Sample ID:** Room 11-Sink
Collection Date: 9/21/2021 6:07:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 11-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.09		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-57 **Client Sample ID:** Girls RR (Rm 10B) Across frm Rm 9-Sink (L)
Collection Date: 9/21/2021 6:13:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Girls RR (Rm 10B) Across frm Rm 9-Sink (L)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.00		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-58 **Client Sample ID:** Girls RR (Rm 10B) Across frm Rm 9-Sink (C)
Collection Date: 9/21/2021 6:13:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Girls RR (Rm 10B) Across frm Rm 9-Sink (C)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.87		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-59 **Client Sample ID:** Girls RR (Rm 10B) Across frm Rm 9-Sink (R)
Collection Date: 9/21/2021 6:13:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Girls RR (Rm 10B) Across frm Rm 9-Sink (R)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.07		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-60 **Client Sample ID:** Room 12-DF
Collection Date: 9/21/2021 6:17:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 12-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.88		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-61 **Client Sample ID:** Room 12-Sink
Collection Date: 9/21/2021 6:17:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 12-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.863		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-62 **Client Sample ID:** Room 13-DF
Collection Date: 9/21/2021 6:19:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 13-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.11		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-63 **Client Sample ID:** Room 13-Sink
Collection Date: 9/21/2021 6:19:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 13-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.11		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-64 **Client Sample ID:** Room 18-DF
Collection Date: 9/21/2021 6:23:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 18-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.431		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-65 **Client Sample ID:** Room 18-Sink
Collection Date: 9/21/2021 6:23:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 18-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.88		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-66 **Client Sample ID:** Room 19-DF
Collection Date: 9/21/2021 6:25:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 19-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.952		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-67 **Client Sample ID:** Room 19-Sink
Collection Date: 9/21/2021 6:25:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 19-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.48		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-68 **Client Sample ID:** Room 20-DF
Collection Date: 9/21/2021 6:26:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 20-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.801		0.103	ppb	1	9/24/2021	15.0	A

Lab ID: 21090842-69 **Client Sample ID:** Room 20-Sink
Collection Date: 9/21/2021 6:26:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 20-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.10		0.103	ppb	1	9/24/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-70 **Client Sample ID:** CDC Staff RR-Sink
Collection Date: 9/21/2021 6:04:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** CDC Staff RR-Sink

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.11		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-71 **Client Sample ID:** CDC Girls/Boys RR-Sink
Collection Date: 9/21/2021 6:12:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** CDC Girls/Boys RR-Sink

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.595		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-72 **Client Sample ID:** CDC-DF (by Kitchen)
Collection Date: 9/21/2021 6:06:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** CDC-DF (by Kitchen)

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.77		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-73
Collection Date: 9/21/2021 6:11:00 AM
Matrix: Drinking Water
Client Sample ID: CDC Kitchen-Sink
Collected By:
Sample Location: CDC Kitchen-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.761		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-74
Collection Date: 9/21/2021 6:10:00 AM
Matrix: Drinking Water
Client Sample ID: CDC Counter-Sink (By Utility Sink/Bk Door)
Collected By:
Sample Location: CDC Counter-Sink (By Utility Sink/Bk Door)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	5.17		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-75
Collection Date: 9/21/2021 6:08:00 AM
Matrix: Drinking Water
Client Sample ID: CDC-White Utility Sink (by Back Door)
Collected By:
Sample Location: CDC-White Utility Sink (by Back Door)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.96		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-76 **Client Sample ID:** Room 27-DF
Collection Date: 9/21/2021 6:00:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 27-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.04		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-77 **Client Sample ID:** Room 27-Sink
Collection Date: 9/21/2021 6:01:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 27-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	13.1		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-78 **Client Sample ID:** Room 28-DF
Collection Date: 9/21/2021 6:03:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 28-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.599		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-79 Client Sample ID: Room 28-Sink
Collection Date: 9/21/2021 6:04:00 AM Collected By:
Matrix: Drinking Water Sample Location: Room 28-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.42		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-80 Client Sample ID: Room 29-DF
Collection Date: 9/21/2021 6:05:00 AM Collected By:
Matrix: Drinking Water Sample Location: Room 29-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.16		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-81 Client Sample ID: Room 29-Sink
Collection Date: 9/21/2021 6:06:00 AM Collected By:
Matrix: Drinking Water Sample Location: Room 29-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.756		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-82 **Client Sample ID:** Room 30-DF
Collection Date: 9/21/2021 6:07:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 30-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.52		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-83 **Client Sample ID:** Room 30-Sink
Collection Date: 9/21/2021 6:08:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 30-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	12.4		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-84 **Client Sample ID:** Room 31-DF
Collection Date: 9/21/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 31-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.16		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-85 **Client Sample ID:** Room 31-Sink
Collection Date: 9/21/2021 6:10:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 31-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	9.74		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-86 **Client Sample ID:** Room 32-DF
Collection Date: 9/21/2021 6:11:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 32-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.762		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-87 **Client Sample ID:** Room 32-Sink
Collection Date: 9/21/2021 6:12:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 32-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.73		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-88 **Client Sample ID:** Room 33-DF
Collection Date: 9/21/2021 6:14:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 33-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.31		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-89 **Client Sample ID:** Room 33-Sink
Collection Date: 9/21/2021 6:15:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 33-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	6.75		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-90 **Client Sample ID:** Room 34-DF
Collection Date: 9/21/2021 6:16:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 34-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.06		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-91 **Client Sample ID:** Room 34-Sink
Collection Date: 9/21/2021 6:17:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 34-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.614		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-92 **Client Sample ID:** Unisex RR (34A Adjacent to Rm 34)-Sink
Collection Date: 9/21/2021 6:18:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Unisex RR (34A Adjacent to Rm 34)-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.81		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-93 **Client Sample ID:** Unisex RR (35A Adjacent to Rm 35)-Sink
Collection Date: 9/21/2021 6:19:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Unisex RR (35A Adjacent to Rm 35)-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.03		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090842

Date Reported: 9/30/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090842
Received Date: 9/21/2021 9:45:00 AM
Reported Date: 9/30/2021 9:14:01 AM

Sample Information:

Lab ID: 21090842-94 **Client Sample ID:** Room 35-DF
Collection Date: 9/21/2021 6:21:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 35-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.29		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090842-95 **Client Sample ID:** Room 35-Sink
Collection Date: 9/21/2021 6:22:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 35-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.914		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090842
30-Sep-21

Client: Medford School District
Project: 32-Jefferson 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: 21090842-95AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: Room 35-Sink	Batch ID: 14208	TestNo: E200.8	E200.8	Analysis Date: 9/25/2021	SeqNo: 397606						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	101	0.104	100	0.914	100	70	130				
------	-----	-------	-----	-------	-----	----	-----	--	--	--	--

Sample ID: 21090842-95AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: Room 35-Sink	Batch ID: 14208	TestNo: E200.8	E200.8	Analysis Date: 9/25/2021	SeqNo: 397607						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	102	0.104	100	0.914	101	70	130	101	1.31	20	
------	-----	-------	-----	-------	-----	----	-----	-----	------	----	--

Sample ID: MB-14204	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: PBW	Batch ID: 14204	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397669						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	ND	0.103									
------	----	-------	--	--	--	--	--	--	--	--	--

Sample ID: LCS-14204	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: LCSW	Batch ID: 14204	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397670						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	102	0.104	100	0	102	85	115				
------	-----	-------	-----	---	-----	----	-----	--	--	--	--

Qualifiers:	* Value exceeds Maximum Contaminant Level.	C1 Sample container temperature is out of limit as specified at testcode	H Holding times for preparation or analysis exceed
MI Recovery outside control limits due to Matrix Interference	ND Not Detected at the Reporting Limit	PL Permit Limit	
RL Reporting Detection Limit			

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090842
30-Sep-21

Client: Medford School District
Project: 32-Jefferson 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: 21090842-20AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: Boys RR (22A)-Sink	Batch ID: 14204	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397693						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	102	0.104	100	2.73	99.6	70	130				
------	-----	-------	-----	------	------	----	-----	--	--	--	--

Sample ID: 21090842-20AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: Boys RR (22A)-Sink	Batch ID: 14204	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397694						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	101	0.104	100	2.73	98.6	70	130	102	0.959	20	
------	-----	-------	-----	------	------	----	-----	-----	-------	----	--

Sample ID: MB-14205	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: PBW	Batch ID: 14205	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397697						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	ND	0.103									
------	----	-------	--	--	--	--	--	--	--	--	--

Sample ID: LCS-14205	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: LCSW	Batch ID: 14205	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397698						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	105	0.104	100	0	105	85	115				
------	-----	-------	-----	---	-----	----	-----	--	--	--	--

Qualifiers:

* Value exceeds Maximum Contaminant Level.	C1 Sample container temperature is out of limit as specified at testcode	H Holding times for preparation or analysis exceed
MI Recovery outside control limits due to Matrix Interference	ND Not Detected at the Reporting Limit	PL Permit Limit
RL Reporting Detection Limit		

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090842
30-Sep-21

Client: Medford School District
Project: 32-Jefferson 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: 21090842-40AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: Media Center Storag	Batch ID: 14205	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397721						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	101	0.104	100	1.78	99.4	70	130				
------	-----	-------	-----	------	------	----	-----	--	--	--	--

Sample ID: 21090842-40AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: Media Center Storag	Batch ID: 14205	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397722						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	105	0.104	100	1.78	103	70	130	101	3.43	20	
------	-----	-------	-----	------	-----	----	-----	-----	------	----	--

Sample ID: MB-14206	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: PBW	Batch ID: 14206	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397725						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	ND	0.103									
------	----	-------	--	--	--	--	--	--	--	--	--

Sample ID: LCS-14206	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: LCSW	Batch ID: 14206	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397726						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	103	0.104	100	0	103	85	115				
------	-----	-------	-----	---	-----	----	-----	--	--	--	--

Qualifiers:	* Value exceeds Maximum Contaminant Level.	C1 Sample container temperature is out of limit as specified at testcode	H Holding times for preparation or analysis exceed
MI Recovery outside control limits due to Matrix Interference	ND Not Detected at the Reporting Limit	PL Permit Limit	
RL Reporting Detection Limit			

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090842
30-Sep-21

Client: Medford School District
Project: 32-Jefferson 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: 21090842-60AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: Room 12-DF	Batch ID: 14206	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397749						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	103	0.104	100	1.88	101	70	130				
------	-----	-------	-----	------	-----	----	-----	--	--	--	--

Sample ID: 21090842-60AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: Room 12-DF	Batch ID: 14206	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397750						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	104	0.104	100	1.88	103	70	130	103	0.999	20	
------	-----	-------	-----	------	-----	----	-----	-----	-------	----	--

Sample ID: MB-14207	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: PBW	Batch ID: 14207	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397753						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	ND	0.103									
------	----	-------	--	--	--	--	--	--	--	--	--

Sample ID: LCS-14207	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: LCSW	Batch ID: 14207	TestNo: E200.8	E200.8	Analysis Date: 9/24/2021	SeqNo: 397754						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	104	0.104	100	0	104	85	115				
------	-----	-------	-----	---	-----	----	-----	--	--	--	--

Qualifiers:	* Value exceeds Maximum Contaminant Level.	C1 Sample container temperature is out of limit as specified at testcode	H Holding times for preparation or analysis exceed
MI Recovery outside control limits due to Matrix Interference	ND Not Detected at the Reporting Limit	PL Permit Limit	
RL Reporting Detection Limit			

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090842
30-Sep-21

Client: Medford School District
Project: 32-Jefferson 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: 21090842-80AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: Room 29-DF	Batch ID: 14207	TestNo: E200.8	E200.8	Analysis Date: 9/25/2021	SeqNo: 397777						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	100	0.104	100	1.16	99.0	70	130				
------	-----	-------	-----	------	------	----	-----	--	--	--	--

Sample ID: 21090842-80AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: Room 29-DF	Batch ID: 14207	TestNo: E200.8	E200.8	Analysis Date: 9/25/2021	SeqNo: 397778						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	102	0.104	100	1.16	101	70	130	100	1.82	20	
------	-----	-------	-----	------	-----	----	-----	-----	------	----	--

Sample ID: MB-14208	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: PBW	Batch ID: 14208	TestNo: E200.8	E200.8	Analysis Date: 9/25/2021	SeqNo: 397781						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	ND	0.103									
------	----	-------	--	--	--	--	--	--	--	--	--

Sample ID: LCS-14208	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/22/2021	RunNo: 24795						
Client ID: LCSW	Batch ID: 14208	TestNo: E200.8	E200.8	Analysis Date: 9/25/2021	SeqNo: 397782						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	102	0.104	100	0	102	85	115				
------	-----	-------	-----	---	-----	----	-----	--	--	--	--

Qualifiers:	* Value exceeds Maximum Contaminant Level.	C1 Sample container temperature is out of limit as specified at testcode	H Holding times for preparation or analysis exceed
MI Recovery outside control limits due to Matrix Interference	ND Not Detected at the Reporting Limit	PL Permit Limit	
RL Reporting Detection Limit			

Original

Sample Log-In Check List

Client Name: **MedfordSchoolDist**

Work Order Number: **21090842**

RcptNo: **1**

Logged by: **Haylee Crowe** 9/21/2021 9:45:00 AM

Completed By: **Michelle Harsh** 9/23/2021 2:37:49 PM

Reviewed By: **Dorie Maier** 9/30/2021 8:41:00 AM

[Handwritten signatures: Haylee Crowe, Michelle Harsh, Dorie Maier]

Chain of Custody

1. Is Chain of Custody complete? Yes ☒ No ☐ Not Present ☐
2. How was the sample delivered? Client

Log In

3. Coolers are present? Yes ☐ No ☐ NA ☒
4. Shipping container/cooler in good condition? Yes ☒ No ☐
Custody seals intact on shipping container/cooler? Yes ☐ No ☐ Not Present ☒
No. Seal Date: Signed By:
5. Was an attempt made to cool the samples? Yes ☐ No ☐ NA ☒
6. Were all samples received at a temperature of >0° C to 6.0°C Yes ☐ No ☐ NA ☒
7. Sample(s) in proper container(s)? Yes ☒ No ☐
8. Sufficient sample volume for indicated test(s)? Yes ☒ No ☐
9. Are samples (except VOA and ONG) properly preserved? Yes ☒ No ☐
10. Was preservative added to bottles? Yes ☒ No ☐ NA ☐
11. Is the headspace in the VOA vials less than 1/4 inch or 6 mm? Yes ☐ No ☐ HNO3 pH <2
No VOA Vials ☒
12. Were any sample containers received broken? Yes ☐ No ☒
13. Does paperwork match bottle labels? Yes ☒ No ☐
(Note discrepancies on chain of custody)
14. Are matrices correctly identified on Chain of Custody? Yes ☒ No ☐
15. Is it clear what analyses were requested? Yes ☒ No ☐
16. Were all holding times able to be met? Yes ☒ No ☐
(If no, notify customer for authorization.)

Special Handling (if applicable)

17. Was client notified of all discrepancies with this order? Yes ☐ No ☐ NA ☒

Person Notified: Date:
By Whom: Via: ☐ eMail ☐ Phone ☐ Fax ☐ In Person
Regarding:
Client Instructions:

18. Additional remarks:

Samples submitted for sample IDs 21090842-30A, -79A, -83A, -85A contained visible sediment.

Cooler Information

Cooler No	Temp °C	Condition	Seal Intact	Seal No	Seal Date	Signed By
-----------	---------	-----------	-------------	---------	-----------	-----------

Chain of Custody Record

Page 1 of 62

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Section A Required Client Information	Section B Required Project Information	Section C Invoice Information	Section D Rush Status (Subject to Scheduling)
Company: MSD 549C	Project Name: 2021 Lead Testing	Attention: Accounting	☐ Standard 10-14 Days
Address: 815 South Oakdale Avenue	Project Number: 32 - Jefferson	Company Name: Medford School District	☐ 5 Business Days (50% surcharge)
Medford, OR 97501	Report <u>ron.havnear@medford.k12.or.us</u>	Address: 815 South Oakdale Avenue	☐ 3 Business Days (75% surcharge)
Email: <u>ron.havnear@medford.k12.or.us</u>	Copy T <u>andy.chasteen@medford.k12.or.us</u>	Medford, OR 97501	☐ 24 - 48 hours (100% surcharge)
Phone: 541-840-4315 Fax:		P.O. # 61172	☐ Other _____
Collected By (Print):			Authorized ☐ Yes ☐ No
Collected By (Sign):			
Email Report ☐ Yes ☐ No	Mail Report ☐ Yes ☐ No		
Fax Report ☐ Yes ☐ No			

Section E Sample Information	Matrix*	Date Collected	Time Collect	No. of Containers	Analysis Requested	Remarks/Field Data	NRC Sample # (Lab Use Only)
Room 3 - Sink (Staff Work Room)	DW	9/14/2021	6:04	1			1
Hallway Outside Room 3 - Drinking Fountain	DW	9/14/2021	6:04	1			2
Hallway Outside Room 3 - Bottle Filler	DW	9/14/2021	6:04	1			3
Women's Restroom (3A) - Sink (Across From The Main Office)	DW	9/14/2021	6:01	1			4
Unisex Restroom (3B) - Sink (Across From The Main Office)	DW	9/14/2021	6:01	1			5
Health Room - Sink	DW	9/14/2021	6:02	1			6
~~Health Room - Refrigerator Ice Maker~~	~~DW~~	~~9/14/2021~~	~~6:02~~	~~1~~			
Kitchen - Hand Sink (South)	DW	9/14/2021	6:04	1			7
Kitchen - Food Prep Sink (West)	DW	9/14/2021	6:04	1			8
Kitchen - Pre-rinse Sink (North Wall)	DW	9/14/2021	6:05	1			9
Kitchen - Hand Sprayer (North Wall)	DW	9/14/2021	6:05	1			10
Staff Break Room (Room 2) - Sink	DW	9/14/2021	6:07	1			11
Boy's Restroom (Room 2A) By Custodial Office - Sink A (Left)	DW	9/14/2021	6:09	1			12
Boy's Restroom (Room 2A) By Custodial Office - Sink B (Center)	DW	9/14/2021	6:09	1			13
Boy's Restroom (Room 2A) By Custodial Office - Sink C(Right)	DW	9/14/2021	6:09	1			14
Girl's Restroom (Room 2B) By Staff Break Room - Sink A (Left)	DW	9/14/2021	6:09	1			15
Girl's Restroom (Room 2B) By Staff Break Room - Sink B(Center)	DW	9/14/2021	6:09	1			16
Girl's Restroom (Room 2B) By Staff Break Room - Sink C(Right)	DW	9/14/2021	6:09	1			17

Page 41 of 53

Client accepted at diff
time than other oc



245 South Grape Street * Medford, OR 97501
(541) 770-5678 fax (541) 770-2901

Chain of Custody Record

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Page 2 of 3

Section A

Required Client Information

Company:	MSD 549C
Address:	815 South Oakdale Avenue
	Medford, OR 97501
Email:	ron.havnear@medford.k12.or.us
Phone:	541-840-4315
Fax:	

Collected By (Print): Marlon Taylor

Collected By (Sign): Marlen Laub

Email Report	☐ Yes	☐ No	Mail Report	☐ Yes	☐ No
--------------	------------------------------	-----------------------------	-------------	------------------------------	-----------------------------

Fax Report ____ Yes ____ No	
-----------------------------	--

Section B

Required Project Information

Project Name:	2021 Lead Testing
Project Number:	32 - Jefferson
Report	ron.havnear@medford.k12.or.us
Copy To	andy.chasteen@medford.k12.or.us

Section C
Invoice Information

Attention: Accounting
Company Name: Medford School District
Address: 815 South Oakdale Avenue
Medford, OR 97501
P.O. # 61172

Section D
Rush Status (Subject to Scheduling)

_____	Standard 10-14 Days
_____	5 Business Days (50% surcharge)
_____	3 Business Days (75% surcharge)
_____	24 - 48 hours (100% surcharge)
_____	Other

Authorized	Yes	No
------------	-----	----

Section E

Sample Information

Sample ID	Matrix*	Date Collected	Time Collect	No. of Samples	Remarks/Field Data	NRC Sample # (Lab Use Only)
In Hallway Outside Boy's Restroom (22A) - Drinking Fountain	DW	9/21/2021	6:00 AM	1		18
In Hallway Outside Boy's Restroom (22A) - Bottle Filler	DW	9/21/2021	6:01 AM	1		19
Boy's Restroom (22A) - Sink (Left)	DW	9/21/2021	6:02 AM	1		20
Boy's Restroom (22A) - Sink (Center)	DW	9/21/2021	6:03 AM	1		21
Boy's Restroom (22A) - Sink (Right)	DW	9/21/2021	6:04 AM	1		22
Room 22 - Drinking Fountain	DW	9/21/2021	6:05 AM	1		23
Room 22 - Sink	DW	9/21/2021	6:06 AM	1		24
Room 23 - Drinking Fountain	DW	9/21/2021	6:07 AM	1		25
Room 23 - Sink	DW	9/21/2021	6:08 AM	1		26
Room 24 - Drinking Fountain	DW	9/21/2021	6:09 AM	1		27
Room 24 - Sink	DW	9/21/2021	6:10 AM	1		28
Room 25 - Drinking Fountain	DW	9/21/2021	6:11 AM	1		29
Room 25 - Sink	DW	9/21/2021	6:12 AM	1		30
Room 26 - Drinking Fountain	DW	9/21/2021	6:13 AM	1		31
Room 26 - Sink	DW	9/21/2021	6:14 AM	1		32
Girl's Restroom (Room 26A) Across From Rm 29 - Sink (Left)	DW	9/21/2021	6:15 AM	1		33
Girl's Restroom (Room 26A) Across From Rm 29 - Sink (Center)	DW	9/21/2021	6:16 AM	1		34
Girl's Restroom (Room 26A) Across From Rm 29 - Sink (Right)	DW	9/21/2021	6:17 AM	1		35
						X

Page 43 of 53

[illegible]



Environmental Testing Laboratory
245 South Grape Street * Medford, OR 97501
(541) 770-5678 fax (541) 770-2901

Chain of Custody Record

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Page 1 of 3

Section A

Required Client Information

Company:	MSD 549C		
Address:	815 South Oakdale Avenue		
	Medford, OR 97501		
Email:	ron.havnear@medford.k12.or.us		
Phone:	541-840-4315	Fax:	

Collected By (Print):

Collected By (Sign):

Email Report	Yes	No	Mail Report	Yes	No
--------------	-----	----	-------------	-----	----

Fax Report	Yes	No
------------	-----	----

Section B

Required Project Information

Project Name:	2021 Lead Testing
Project Number:	32 - Jefferson
Report	ron.havnear@medford.k12.or.us
Copy To	andy.chasteen@medford.k12.or.us

Section C
Invoice Information

Attention: Accounting
Company Name: Medford School District
Address: 815 South Oakdale Avenue
Medford, OR 97501
P.O. # 61172

Section D
Rush Status (Subject to Scheduling)

_____	Standard 10-14 Days
_____	5 Business Days (50% surcharge)
_____	3 Business Days (75% surcharge)
_____	24 - 48 hours (100% surcharge)
_____	Other

Authorized _____ Yes _____ No _____

Section E
Sample Information[illegible]

*Matrix: DW - Drinking Water WW - Wastewater W - Water S - Soil/Solid SL - Sludge O - Oil WP - Wipe OT - Other

Time

Received By Laboratory:

A crow

9/2/21

1944

Lab Use Only

Field Blank Included: ☐ Yes ☒ No

Received Via ☐ UPS ☐ FedEx ☐ Other ☒ Hand

Payment:	<u>Invoice</u>	Cash	VISA, M/C	Check #	Amount
----------	----------------	------	-----------	---------	--------

client accepted at diff time
than org. coc SNS 9/21



Environmental Testing Laboratory
245 South Grape Street * Medford, OR 97501
(541) 770-5678 fax (541) 770-2901

Chain of Custody Record

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Page 1 of 3

4

Section A

Required Client Information

Company:	MSD 549C	
Address:	815 South Oakdale Avenue	
	Medford, OR 97501	
Email:	ron.havnear@medford.k12.or.us	
Phone:	541-840-4315	Fax:

Section B

Required Project Information

Project Name:	2021 Lead Testing
Project Number:	32 - Jefferson
Report	ron.havnear@medford.k12.or.us
Copy To	andy.chasteen@medford.k12.or.us

Section C
Invoice Information

Attention:	Accounting
Company Name:	Medford School District
Address:	815 South Oakdale Avenue
	Medford, OR 97501
P.O. #	61172

Section D
Rush Status (Subject to Scheduling)

_____	Standard 10-14 Days
_____	5 Business Days (50% surcharge)
_____	3 Business Days (75% surcharge)
_____	24 - 48 hours (100% surcharge)
_____	Other

Authorized _____ Yes _____ No _____

Collected By (Print):

Collected By (Sign):

Email Report ____ Yes ____ No	Mail Report ____ Yes ____ No
-------------------------------	------------------------------

Fax Report ☐ Yes ☐ No

Section E

Sample Information

Sample ID	Matrix*	Date Collected	Time Collect	No.
Room 10 - Drinking Fountain	DW	9/14/2021	6:02	1
Room 10 - Sink	DW	9/14/2021	6:03	1
Room 11 - Drinking Fountain	DW	9/14/2021	6:06	1
Room 11 - Sink	DW	9/14/2021	6:07	1
Girl's Restroom (Room 10B) Across From Rm 9 - Sink (Left)	DW	9/14/2021	6:13	1
Girl's Restroom (Room 10B) Across From Rm 9 - Sink (Center)	DW	9/14/2021	6:13	1
Girl's Restroom (Room 10B) Across From Rm 9 - Sink (Right)	DW	9/14/2021	6:13	1
Room 12 - Drinking Fountain	DW	9/14/2021	6:17	1
Room 12 - Sink	DW	9/14/2021	6:17	1
Room 13 - Drinking Fountain	DW	9/14/2021	6:19	1
Room 13 - Sink	DW	9/14/2021	6:19	1
Room 18 - Drinking Fountain	DW	9/14/2021	6:23	1
Room 18 - Sink	DW	9/14/2021	6:23	1
Room 19 - Drinking Fountain	DW	9/14/2021	6:25	1
Room 19 - Sink	DW	9/14/2021	6:25	1
Room 20 - Drinking Fountain	DW	9/14/2021	6:26	1
Room 20 - Sink	DW	9/14/2021	6:26	1
		9/20/2021		

Page 47 of 53

*Matrix: DW - Drinking Water WW - Wastewater W - Water S - Soil/Solid SL - Sludge O - Oil WP - Wipe OT - Other

Relinquish/Receive

Sign

Print

Date _____

Time

Relinquished By:

Received By:

Relinquished By:

Received By:

Relinquished By:

Received By Laboratory:

Lab Use Only

Temp: Ani

4°C +/- 2°C: Yes ☒ No

Received on Ice: ☒ Yes ☐ No

Number of Bottles Received:

pH Checked: 10.5


COC Seals Intact: ☐ Yes ☐ No ☒ NA

Field Blank Included: ☐ Yes ☒ No

Received Via ☐ UPS ☐ FedEx ☐ Other ☒ Hand

Payment:	☒ Invoice	☐ Cash	☐ VISA, M/C	☐ Check #	☐ Amount
----------	---	-------------------------------	------------------------------------	----------------------------------	---------------------------------

9:44 error
9/21/24
SNS



This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Page 1 of 3

Company:	MSD 549C		
Address:	815 South Oakdale Avenue		
	Medford, OR 97501		
Email:	ron.havnear@medford.k12.or.us		
Phone:	541-840-4315	Fax:	

Project Name:	2021 Lead Testing
Project Number:	32 - Jefferson
Report	ron.havnear@medford.k12.or.us
Copy To	andy.chasteen@medford.k12.or.us

Attention: Accounting
Company Name: Medford School District
Address: 815 South Oakdale Avenue
Medford, OR 97501
P.O. # 61172

_____	Standard 10-14 Days
_____	5 Business Days (50% surcharge)
_____	3 Business Days (75% surcharge)
_____	24 - 48 hours (100% surcharge)
_____	Other _____
Authorized _____ Yes _____ No _____	

Collected By (Print):

Collected By (Sign):

Email Report	Yes	No	Mail Report	Yes	No
--------------	-----	----	-------------	-----	----

Fax Report ☐ Yes ☐ No[illegible]

Analysis Requested

No. of Containers

NRC Workorder # 21090842
(Lab Use Only)

Remarks/Field Data

NRC Sample #
(Lab Use Only)

*Matrix: DW - Drinking Water WW - Wastewater W - Water S - Soil/Solid SL - Sludge O - Oil WP - Wipe OT - Other

Section F					
Relinquish/Receive		Sign	Print	Date	Time
Relinquished By:		<i>Andy T. Chasteen</i>	ANDY T. CHASTEEN	9/21/21	9:45 am
Received By:					
Relinquished By:					
Received By:					9:11
Relinquished By:					
Received By Laboratory:			IT Crime	9/21/21	9:45

Lab Use Only		
Temp:	4°C +/- 2°C: Yes ☒ No ☐	
Received on Ice:	Yes ☒ No ☐	
Number of Bottles Received:	pH Checked: ☒	
COC Seals Intact:	Yes ☐ No ☒	
Field Blank Included:	Yes ☒ No ☐	
Via	UPS ☐ FedEX ☐ Other ☒	Hand ☐
ISA, M/C	Check #	Amount

Payment: ☒ Invoice	☐ Cash	☐ VISA, M/C	☐ Check #	☐ Amount
--	-------------------------------	------------------------------------	----------------------------------	---------------------------------

Client accepted at diff
time on ather cc
Shg
q/h



Environmental Testing Laboratory
245 South Grape Street * Medford, OR 97501
(541) 770-5678 fax (541) 770-2901

Chain of Custody Record

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

aw
9/22/21
\$16
Page 1 of 3

Section A Required Client Information	Section B Required Project Information	Section C Invoice Information	Section D Rush Status (Subject to Scheduling)
Company: MSD 549C	Project Name: 2021 Lead Testing	Attention: Accounting	☐ Standard 10-14 Days
Address: 815 South Oakdale Avenue	Project Number: 32 - Jefferson	Company Name: Medford School District	☐ 5 Business Days (50% surcharge)
Medford, OR 97501	Report <u>ron.havniar@medford.k12.or.us</u>	Address: 815 South Oakdale Avenue	☐ 3 Business Days (75% surcharge)
Email: <u>ron.havniar@medford.k12.or.us</u>	Copy T <u>andy.chasteen@medford.k12.o</u>	Medford, OR 97501	☐ 24 - 48 hours (100% surcharge)
Phone: 541-840-4315 Fax:		P.O. # 61172	☐ Other _____
Collected By (Print):			Authorized ☐ Yes ☐ No

Collected By (Sign): _____

Email Report ☐ Yes ☐ No Mail Report ☐ Yes ☐ No

Fax Report ☐ Yes ☐ No

Section E Sample Information

Sample ID	Matrix*	Date Collected	Time Collect	No.												Remarks/Field Data	NRC Sample # (Lab Use Only)
Room 27 - Drinking Fountain	DW	9/21/2021	600	1													76
Room 27 - Sink	DW	9/21/2021	601	1													77
Room 28 - Drinking Fountain	DW	9/21/2021	603	1													78
Room 28 - Sink	DW	9/21/2021	604	1													79
Room 29 - Drinking Fountain	DW	9/21/2021	605	1													80
Room 29 - Sink	DW	9/21/2021	606	1													81
Room 30 - Drinking Fountain	DW	9/21/2021	607	1													82
Room 30 - Sink	DW	9/21/2021	608	1													83
Room 31 - Drinking Fountain	DW	9/21/2021	609	1													84
Room 31 - Sink	DW	9/21/2021	610	1													85
Room 32 - Drinking Fountain	DW	9/21/2021	611	1													86
Room 32 - Sink	DW	9/21/2021	612	1													87
Room 33 - Drinking Fountain	DW	9/21/2021	614	1													88
Room 33 - Sink	DW	9/21/2021	615	1													89
Room 34 - Drinking Fountain	DW	9/21/2021	616	1													90
Room 34 - Sink	DW	9/21/2021	617	1													91
Unisex Restroom (34A - Adjacent To Room 34) - Sink	DW	9/21/2021	618	1													92
Unisex Restroom (35A - Adjacent To Room 35) - Sink	DW	9/21/2021	619	1													93
Room 35 - Drinking Fountain	DW	9/21/2021	621	1													94
Room 35 - Sink	DW	9/21/2021	622	1													95

Page 51 of 53

B	Analyte detected in the associated method blank.
BA	BOD Alternative Calculation: The initial results performed by Standard Methods did not fall within parameters of the Standard Methods calculation. An alternate approved calculation was performed using the HACH method and the value reported is an estimated concentration.
C	Sample(s) does not meet NELAP/ORELAP sample acceptance criteria. See Case Narrative.
C1	Sample(s) does not meet NELAP/ORELAP sample acceptance criteria for temperature.
CF	Results confirmed by re-analysis.
CU	Cleanup performed as specified by method.
D1	The diesel elution pattern for the sample is not typical.
D2	The sample appears to be a heavier hydrocarbon range than diesel.
D3	The sample appears to be a lighter hydrocarbon range than diesel.
D4	Detected hydrocarbons do not have pattern and range consistent with typical petroleum products and may be due to biogenic interference.
D5	Detected hydrocarbons in the diesel range appear to be weathered diesel.
E	Estimated value.
ER	Elevated reporting limit due to matrix. Report limits (MDLs, MRLs & PQLs) are adjusted based on variations in sample preparation amounts, analytical dilutions, and percent solids, where applicable.
FC	Fecal Coliforms: Sample(s) received past 40 CFR Part 136 specified holding time. Results reported as estimated values.
G1	The gasoline elution pattern for the sample is not typical.
G2	The sample appears to be a heavier hydrocarbon range than gasoline.
G3	The sample appears to be a lighter hydrocarbon range than gasoline.
G4	Detected hydrocarbons in the gasoline range appear to be weathered gasoline.
HP	Sample re-analysis performed outside of method specified holding time.
HR	Sample received outside of method specified holding time.
HS	Sample analyzed for volatile organics contained headspace.
HT	At the client's request, the sample was analyzed outside of method specified holding time.
H	Analysis performed outside of method specified holding time.
J	Analyte detected below the Minimum Reporting Limit (MRL) and above the Method Detection Limit (MDL). The J flag result is an estimated value and the user should be aware that this data is of limited reliability.
L	Dissolved metals were not filtered within 15 minutes of collection per 40 CFR Part 136.
MI	Surrogate, Duplicate Sample (DUP) or Matrix Spikes recoveries are out of control limits due to matrix interference. Sample results may be biased.
N	See Case Narrative on page 2 of report.
NLR	No Legionella Recovered.
PLR	Presence of Legionella Recovered.
Q	Initial calibration verification (ICV), continuing calibration verification (CCV) or laboratory control sample (LCS) exceeded high recovery limits, but associated samples are non-detect and the sample results are not affected. Data meets EPA/NELAP requirements.
R	Relative percent difference (RPD) is outside of the accepted recovery limits.
R1	Relative percent difference (RPD) is outside of the accepted recovery limits. However, analyses are not controlled on RPD values for sample concentrations that are less than the reporting limit.
R3	The relative percent difference (RPD) and/or percent recovery for the duplicate (DUP) or matrix spike (MS)/matrix spike duplicate (MSD) cannot be accurately calculated due to the concentration of analyte already present in the sample.
R4	Duplicate analysis failed due to result being at or near the method reporting limit.
S	Surrogate and/or matrix spike recovery is outside of the accepted recovery limits. Sample results may be biased.
S1	Surrogate or matrix spike recovery is outside of control limits due to dilution necessary for analysis.
SC	Sub-contracted to another laboratory for analysis.
SP	Sample(s) were not collected per EPA Method 5035A protocols. The results are considered minimum values.
#	Value exceeds regulatory level for TCLP contaminant.
X1	The motor oil elution pattern for the sample is not typical.
X2	The sample appears to be a heavier hydrocarbon range than motor oil.
X3	The sample appears to be a lighter hydrocarbon range than motor oil.
*	Value exceeds Maximum Contaminant Level or is outside the acceptable range.
