



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

October 05, 2021

Ron Havniar
Medford School District
815 S Oakdale Ave
Medford, OR 97501
TEL: 541-842-3646
FAX 541-842-1160

RE: 44-Oak Grove 2021 Lead Testing

Order No.: 21090922

Dear Ron Havniar:

Neilson Research Corporation received 114 sample(s) on 9/22/2021 for the analyses presented in the following report.

The results relate only to the parameters tested or to the sample as received by the laboratory. This report shall not be reproduced except in full, without the written approval of Neilson Research Corporation. If you have any questions regarding these test results, please feel free to call.

Sincerely,
Neilson Research Corporation

Tamra Schmedemann
Senior Project Manager
245 S Grape St
Medford, OR 97501



Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Case Narrative

WO#: 21090922
Date: 10/5/2021

CLIENT: Medford School District

Project: 44-Oak Grove 2021 Lead Testing

The analyses were performed according to the guidelines in the Neilson Research Corporation Quality Assurance Program. This report contains analytical results for the sample(s) as received by the laboratory.

Neilson Research Corporation certifies that this report is in compliance with the requirements of NELAP. No unusual difficulties were experienced during analysis of this batch except as noted below or qualified with data flags on the reports.

Sample ID 21090922-084A was not sampled but was on the COC. This sample was cancelled. TRS

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-001 **Client Sample ID:** Staff Breakroom-Sink
Collection Date: 9/22/2021 6:01:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Staff Breakroom-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.762		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-002 **Client Sample ID:** Staff Break Room-Insta Hot
Collection Date: 9/22/2021 6:02:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Staff Break Room-Insta Hot

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.175		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-003 **Client Sample ID:** Multipurpose Room-DF
Collection Date: 9/22/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Multipurpose Room-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.83		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-004 **Client Sample ID:** Multipurpose Room-Sink
Collection Date: 9/22/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Multipurpose Room-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.28		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-005 **Client Sample ID:** S of Office Behind Sliding Door-Sink
Collection Date: 9/22/2021 6:06:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** S of Office Behind Sliding Door-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.59		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-006 **Client Sample ID:** Girls Restroom Near MPR-Sink (L)
Collection Date: 9/22/2021 6:12:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Girls Restroom Near MPR-Sink (L)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.74		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-007 **Client Sample ID:** Girls Restroom Near MPR-Sink (R)
Collection Date: 9/22/2021 6:12:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Girls Restroom Near MPR-Sink (R)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.70		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-008 **Client Sample ID:** Boys Restroom Near MPR-Sink (L)
Collection Date: 9/22/2021 6:14:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Boys Restroom Near MPR-Sink (L)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.27		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-009 **Client Sample ID:** Boys Restroom Near MPR-Sink (R)
Collection Date: 9/22/2021 6:14:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Boys Restroom Near MPR-Sink (R)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.09		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-010 **Client Sample ID:** Gym Entrance-DF (Upper)
Collection Date: 9/22/2021 6:19:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Gym Entrance-DF (Upper)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.09		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-011 **Client Sample ID:** Gym Entrance-DF (Lower)
Collection Date: 9/22/2021 6:19:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Gym Entrance-DF (Lower)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.33		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-012 **Client Sample ID:** Media Center Unisex Restroom-Sink
Collection Date: 9/22/2021 6:16:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Media Center Unisex Restroom-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.16		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-013 **Client Sample ID:** Room 18-DF
Collection Date: 9/22/2021 6:01:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 18-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.117		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-014 **Client Sample ID:** Room 18-Sink
Collection Date: 9/22/2021 6:02:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 18-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.88		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-015 **Client Sample ID:** Room 19-DF
Collection Date: 9/22/2021 6:04:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 19-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.838		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-016 **Client Sample ID:** Room 19-Sink
Collection Date: 9/22/2021 6:05:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 19-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.78		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-017 **Client Sample ID:** Room 20-DF
Collection Date: 9/22/2021 6:06:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 20-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.573		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-018 **Client Sample ID:** Room 20-Sink
Collection Date: 9/22/2021 6:06:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 20-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.30		0.103	ppb	1	9/25/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-019 **Client Sample ID:** Room 21-DF
Collection Date: 9/22/2021 6:09:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 21-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.53		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-020 **Client Sample ID:** Room 21-Sink
Collection Date: 9/22/2021 6:09:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 21-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.34		0.103	ppb	1	9/25/2021	15.0	A

Lab ID: 21090922-021 **Client Sample ID:** Room 22-DF
Collection Date: 9/22/2021 6:11:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 22-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-022 **Client Sample ID:** Room 22-Sink
Collection Date: 9/22/2021 6:12:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 22-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.830		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-023 **Client Sample ID:** Room 23-DF
Collection Date: 9/22/2021 6:13:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 23-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-024 **Client Sample ID:** Room 23-Sink
Collection Date: 9/22/2021 6:13:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 23-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.54		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-025 **Client Sample ID:** Room 24-DF
Collection Date: 9/22/2021 6:15:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 24-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.88		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-026 **Client Sample ID:** Room 24-Sink
Collection Date: 9/22/2021 6:15:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 24-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.63		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-027 **Client Sample ID:** Room 25-DF
Collection Date: 9/22/2021 6:17:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 25-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.917		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-028 **Client Sample ID:** Room 25-Sink
Collection Date: 9/22/2021 6:17:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 25-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.11		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-029 **Client Sample ID:** Room 26-DF
Collection Date: 9/22/2021 6:19:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 26-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.872		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-030 **Client Sample ID:** Room 26-Sink
Collection Date: 9/22/2021 6:19:00 AM **Collected By:** Gary Severe
Matrix: Drinking Water **Sample Location:** Room 26-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.88		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-031 **Client Sample ID:** Room 8-DF
Collection Date: 9/22/2021 6:01:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 8-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	5.27		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-032 **Client Sample ID:** Room 8-Sink
Collection Date: 9/22/2021 6:02:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 8-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.36		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-033 **Client Sample ID:** Room 9-DF
Collection Date: 9/22/2021 6:03:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 9-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.41		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-034 **Client Sample ID:** Room 9-Sink
Collection Date: 9/22/2021 6:04:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 9-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.31		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-035 **Client Sample ID:** Room 10-DF
Collection Date: 9/22/2021 6:05:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 10-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.10		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-036 **Client Sample ID:** Room 10-Sink
Collection Date: 9/22/2021 6:06:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 10-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.39		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-037 **Client Sample ID:** Near Room 10 Girls RR-Sink (L)
Collection Date: 9/22/2021 6:07:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Near Room 10 Girls RR-Sink (L)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.71		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-038 **Client Sample ID:** Near Room 10 Girls RR-Sink (R)
Collection Date: 9/22/2021 6:08:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Near Room 10 Girls RR-Sink (R)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.17		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-039 **Client Sample ID:** Near Room 10 Boys RR-Sink (L)
Collection Date: 9/22/2021 6:09:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Near Room 10 Boys RR-Sink (L)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.49		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-040 **Client Sample ID:** Near Room 10 Boys RR-Sink (R)
Collection Date: 9/22/2021 6:10:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Near Room 10 Boys RR-Sink (R)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	5.10		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-041 **Client Sample ID:** Room 14-DF
Collection Date: 9/22/2021 6:11:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 14-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.07		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-042 **Client Sample ID:** Room 14-Sink
Collection Date: 9/22/2021 6:12:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 14-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.05		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-043 **Client Sample ID:** Room 15-DF
Collection Date: 9/22/2021 6:13:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 15-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.25		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-044 **Client Sample ID:** Room 15-Sink
Collection Date: 9/22/2021 6:14:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 15-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.17		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-045 **Client Sample ID:** Room 16-DF
Collection Date: 9/22/2021 6:15:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 16-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.995		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-046 **Client Sample ID:** Room 16-Sink
Collection Date: 9/22/2021 6:16:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 16-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.587		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-047 **Client Sample ID:** Room 17-DF
Collection Date: 9/22/2021 6:17:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 17-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.724		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-048 **Client Sample ID:** Room 17-Sink
Collection Date: 9/22/2021 6:18:00 AM **Collected By:** Marlon Taylor
Matrix: Drinking Water **Sample Location:** Room 17-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-049 **Client Sample ID:** Room 11-DF
Collection Date: 9/22/2021 6:01:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 11-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.64		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-050 **Client Sample ID:** Room 11-Sink
Collection Date: 9/22/2021 6:02:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 11-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	5.34		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-051 **Client Sample ID:** Room 12-DF
Collection Date: 9/22/2021 6:03:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 12-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.96		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-052 **Client Sample ID:** Room 12-Sink
Collection Date: 9/22/2021 6:04:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 12-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.39		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-053 **Client Sample ID:** Room 13-DF
Collection Date: 9/22/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 13-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	7.48		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-054 **Client Sample ID:** Room 13-Sink
Collection Date: 9/22/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 13-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.96		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-055 **Client Sample ID:** La Clinica Exam Room #1-Sink
Collection Date: 9/22/2021 6:16:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** La Clinica Exam Room #1-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.05		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-056 **Client Sample ID:** La Clinica Exam Room #2-Sink
Collection Date: 9/22/2021 6:16:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** La Clinica Exam Room #2-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.04		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-057 **Client Sample ID:** La Clinica Lab Room-Sink
Collection Date: 9/22/2021 6:17:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** La Clinica Lab Room-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.26		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-058 **Client Sample ID:** La Clinica Restroom-Sink
Collection Date: 9/22/2021 6:18:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** La Clinica Restroom-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.20		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-059 **Client Sample ID:** Near Room 1 Men's RR-Sink (1) L
Collection Date: 9/22/2021 6:00:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Near Room 1 Men's RR-Sink (1) L

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.49		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-060 **Client Sample ID:** Near Room 1 Men's RR-Sink (2) M
Collection Date: 9/22/2021 6:00:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Near Room 1 Men's RR-Sink (2) M

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	6.84		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-061 **Client Sample ID:** Near Room 1 Men's RR-Sink (3) R
Collection Date: 9/22/2021 6:00:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Near Room 1 Men's RR-Sink (3) R

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	5.61		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-062 **Client Sample ID:** Near Room 1 Women's RR-Sink (1) L
Collection Date: 9/22/2021 6:02:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Near Room 1 Women's RR-Sink (1) L

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.85		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-063 **Client Sample ID:** Near Room 1 Women's RR-Sink (2) M
Collection Date: 9/22/2021 6:02:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Near Room 1 Women's RR-Sink (2) M

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.80		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-064 **Client Sample ID:** Near Room 1 Women's RR-Sink (3) R
Collection Date: 9/22/2021 6:02:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Near Room 1 Women's RR-Sink (3) R

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.67		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-065 **Client Sample ID:** Near Room 1 Women's RR-DF
Collection Date: 9/22/2021 6:05:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Near Room 1 Women's RR-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.22		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-066 **Client Sample ID:** Room 1-DF
Collection Date: 9/22/2021 6:07:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 1-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.72		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-067 **Client Sample ID:** Room 1-Sink
Collection Date: 9/22/2021 6:07:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 1-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.93		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-068 **Client Sample ID:** Room 2-DF
Collection Date: 9/22/2021 6:10:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 2-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.05		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-069 **Client Sample ID:** Room 2-Sink
Collection Date: 9/22/2021 6:10:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 2-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.83		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-070 **Client Sample ID:** Room 3-DF
Collection Date: 9/22/2021 6:13:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 3-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	5.73		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-071 **Client Sample ID:** Room 3-Sink
Collection Date: 9/22/2021 6:14:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 3-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.96		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-072 **Client Sample ID:** Room 4-DF
Collection Date: 9/22/2021 6:15:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 4-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.16		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-073 **Client Sample ID:** Room 4-Sink
Collection Date: 9/22/2021 6:16:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 4-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.39		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-074 **Client Sample ID:** Room 6-DF
Collection Date: 9/22/2021 6:17:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 6-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	5.05		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-075 **Client Sample ID:** Room 6-Sink
Collection Date: 9/22/2021 6:17:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 6-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	5.09		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-076 **Client Sample ID:** Outside Room 6 Staff Unisex RR-Sink
Collection Date: 9/22/2021 6:20:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 6 Staff Unisex RR-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-077 **Client Sample ID:** Room 7-DF
Collection Date: 9/22/2021 6:21:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 7-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	16.8	*	0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-078 **Client Sample ID:** Room 7-Sink
Collection Date: 9/22/2021 6:22:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Room 7-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.05		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-079 **Client Sample ID:** N Side of Kitchen Men's RR-Sink (L)
Collection Date: 9/22/2021 6:02:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** N Side of Kitchen Men's RR-Sink (L)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.15		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-080 **Client Sample ID:** N Side of Kitchen Men's RR-Sink (R)
Collection Date: 9/22/2021 6:02:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** N Side of Kitchen Men's RR-Sink (R)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	5.13		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-081 **Client Sample ID:** N Side of Kitchen Women's RR-Sink (L)
Collection Date: 9/22/2021 6:03:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** N Side of Kitchen Women's RR-Sink (L)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.92		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-082 **Client Sample ID:** N Side of Kitchen Women's RR-Sink (R)
Collection Date: 9/22/2021 6:03:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** N Side of Kitchen Women's RR-Sink (R)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.01		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-083 **Client Sample ID:** N Side of Kitchen-DF (Outside)
Collection Date: 9/22/2021 6:03:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** N Side of Kitchen-DF (Outside)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.34		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-085 **Client Sample ID:** Inside Kitchen Unisex RR (East)- Sink
Collection Date: 9/22/2021 6:25:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Inside Kitchen Unisex RR (East)- Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	10.6		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-086 Client Sample ID: Kitchen-Sink (Food Prep-Triple Sink)
Collection Date: 9/22/2021 6:14:00 AM Collected By:
Matrix: Drinking Water Sample Location: Kitchen-Sink (Food Prep-Triple Sink)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	28.8	*	0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-087 Client Sample ID: Kitchen-Sink (Food Prep-Island)
Collection Date: 9/22/2021 6:14:00 AM Collected By:
Matrix: Drinking Water Sample Location: Kitchen-Sink (Food Prep-Island)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.38		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-088 Client Sample ID: Kitchen-Sink (Pre-rinse/Dishwasher)
Collection Date: 9/22/2021 6:14:00 AM Collected By:
Matrix: Drinking Water Sample Location: Kitchen-Sink (Pre-rinse/Dishwasher)

Trace Metals by EPA 200.8 ICP-MS						Analyst: SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	6.22		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-089 **Client Sample ID:** Office C/Ram Store-Sink
Collection Date: 9/22/2021 6:15:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Office C/Ram Store-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.49		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-090 **Client Sample ID:** Cafeteria-DF
Collection Date: 9/22/2021 6:16:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Cafeteria-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.958		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-091 **Client Sample ID:** Cafeteria-Bottle Filler
Collection Date: 9/22/2021 6:16:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Cafeteria-Bottle Filler

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.39		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-092 **Client Sample ID:** Health Room-Sink
Collection Date: 9/22/2021 6:31:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Health Room-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.11		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-093 **Client Sample ID:** Health Rm-Unisex Bathroom-Sink
Collection Date: 9/22/2021 6:31:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Health Rm-Unisex Bathroom-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.99		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-094 **Client Sample ID:** Staff Work Rm-Unisex Restroom-Sink
Collection Date: 9/22/2021 6:32:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Staff Work Rm-Unisex Restroom-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.59		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-095 **Client Sample ID:** Kitchen Office Hand Sink
Collection Date: 9/22/2021 6:28:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Kitchen Office Hand Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	10.8		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-096 **Client Sample ID:** Kitchen Unisex West
Collection Date: 9/22/2021 6:25:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Kitchen Unisex West

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	27.7	*	0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-097 **Client Sample ID:** Outside Room 26 Boys RR-Sink (1)
Collection Date: 9/22/2021 6:06:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Boys RR-Sink (1)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	6.62		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-098 **Client Sample ID:** Outside Room 26 Boys RR-Sink (2)
Collection Date: 9/22/2021 6:06:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Boys RR-Sink (2)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.12		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-099 **Client Sample ID:** Outside Room 26 Boys RR-Sink (3)
Collection Date: 9/22/2021 6:06:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Boys RR-Sink (3)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.17		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-100 **Client Sample ID:** Outside Room 26 Boys RR-Sink (4)
Collection Date: 9/22/2021 6:07:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Boys RR-Sink (4)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	7.18		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-101 **Client Sample ID:** Outside Room 26 Boys RR-Sink (5)
Collection Date: 9/22/2021 6:07:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Boys RR-Sink (5)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-102 **Client Sample ID:** Outside Room 26 Boys RR-Sink (6)
Collection Date: 9/22/2021 6:08:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Boys RR-Sink (6)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.56		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-103 **Client Sample ID:** Outside Room 26 Boys RR-Sink (7)
Collection Date: 9/22/2021 6:08:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Boys RR-Sink (7)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	5.95		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-104 **Client Sample ID:** Outside Room 26 Boys RR-Sink (8)
Collection Date: 9/22/2021 6:08:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Boys RR-Sink (8)

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	7.27		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-105 **Client Sample ID:** Outside Room 26 Boys RR-Sink (9)
Collection Date: 9/22/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Boys RR-Sink (9)

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.39		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-106 **Client Sample ID:** Outside Room 26 Women's RR-Sink (1)
Collection Date: 9/22/2021 6:09:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Women's RR-Sink (1)

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.62		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-107 **Client Sample ID:** Outside Room 26 Women's RR-Sink (2)
Collection Date: 9/22/2021 6:11:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Women's RR-Sink (2)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.56		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-108 **Client Sample ID:** Outside Room 26 Women's RR-Sink (3)
Collection Date: 9/22/2021 6:11:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Women's RR-Sink (3)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	4.88		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-109 **Client Sample ID:** Outside Room 26 Women's RR-Sink (4)
Collection Date: 9/22/2021 6:11:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Women's RR-Sink (4)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.59		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-110 **Client Sample ID:** Outside Room 26 Women's RR-Sink (5)
Collection Date: 9/22/2021 6:12:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Women's RR-Sink (5)

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	3.64		0.515	ppb	1	10/1/2021	15.0	A

Lab ID: 21090922-111 **Client Sample ID:** Outside Room 26 Women's RR-Sink (6)
Collection Date: 9/22/2021 6:12:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Women's RR-Sink (6)

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	50.4	*	0.100	ppb	1	9/27/2021	15.0	A

Lab ID: 21090922-112 **Client Sample ID:** Outside Room 26 Women's RR-Sink (7)
Collection Date: 9/22/2021 6:13:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Women's RR-Sink (7)

Trace Metals by EPA 200.8 ICP-MS							Analyst; SJS	
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.69		0.515	ppb	1	10/1/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 21090922

Date Reported: 10/5/2021

Medford School District
815 S Oakdale Ave
Medford, OR 97501

Lab Order: 21090922
Received Date: 9/22/2021 11:04:00 AM
Reported Date: 10/5/2021 12:00:55 PM

Sample Information:

Lab ID: 21090922-113 **Client Sample ID:** Outside Room 26 Women's RR-Sink (8)
Collection Date: 9/22/2021 6:14:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Women's RR-Sink (8)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	5.83		0.515	ppb	1	10/2/2021	15.0	A

Lab ID: 21090922-114 **Client Sample ID:** Outside Room 26 Women's RR-Sink (9)
Collection Date: 9/22/2021 6:14:00 AM **Collected By:**
Matrix: Drinking Water **Sample Location:** Outside Room 26 Women's RR-Sink (9)

Trace Metals by EPA 200.8 ICP-MS						Analyst; SJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	7.23		0.515	ppb	1	10/2/2021	15.0	A

QUALIFIERS	*	Value exceeds Maximum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcod
	E	Value above quantitation range	H	Holding times for preparation or analysis exceeded
	J	Analyte detected below quantitation limits	MI	Recovery outside control limits due to Matrix Interference
	ND	Not Detected at the Reporting Limit	PL	Permit Limit
	R	RPD outside accepted recovery limits		

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Original

Results are out of the EPA limits



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090922
05-Oct-21

Client: Medford School District
Project: 44-Oak Grove 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: MB-14229	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/23/2021	RunNo: 24795
Client ID: PBW	Batch ID: 14229	TestNo: E200.8	E200.8	Analysis Date: 9/25/2021	SeqNo: 397638
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead ND 0.103

Sample ID: LCS-14229	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/23/2021	RunNo: 24795
Client ID: LCSW	Batch ID: 14229	TestNo: E200.8	E200.8	Analysis Date: 9/25/2021	SeqNo: 397638
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 103 0.104 100 0 103 85 115

Sample ID: 21090922-020AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/23/2021	RunNo: 24795
Client ID: Room 21-Sink	Batch ID: 14229	TestNo: E200.8	E200.8	Analysis Date: 9/25/2021	SeqNo: 397662
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 103 0.104 100 2.34 101 70 130

Sample ID: 21090922-020AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/23/2021	RunNo: 24795
Client ID: Room 21-Sink	Batch ID: 14229	TestNo: E200.8	E200.8	Analysis Date: 9/25/2021	SeqNo: 397663
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 103 0.104 100 2.34 100 70 130 103 0.749 20

Qualifiers: * Value exceeds Maximum Contaminant Level. C1 Sample container temperature is out of limit as specified at testcode H Holding times for preparation or analysis exceed
MI Recovery outside control limits due to Matrix Interference ND Not Detected at the Reporting Limit PL Permit Limit
RL Reporting Detection Limit

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090922
05-Oct-21

Client: Medford School District
Project: 44-Oak Grove 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: MB-14242	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/24/2021	RunNo: 24824
Client ID: PBW	Batch ID: 14242	TestNo: E200.8	E200.8	Analysis Date: 9/27/2021	SeqNo: 398324
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead	ND	0.100			
------	----	-------	--	--	--

Sample ID: LCS-14242	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/24/2021	RunNo: 24824
Client ID: LCSW	Batch ID: 14242	TestNo: E200.8	E200.8	Analysis Date: 9/27/2021	SeqNo: 398325
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead	105	0.100	100	0	105	85	115			
------	-----	-------	-----	---	-----	----	-----	--	--	--

Sample ID: 21090952-01AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/24/2021	RunNo: 24824
Client ID: BatchQC	Batch ID: 14242	TestNo: E200.8	E200.8	Analysis Date: 9/27/2021	SeqNo: 398332
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead	96.6	0.100	100	0.0320	96.5	70	130			
------	------	-------	-----	--------	------	----	-----	--	--	--

Sample ID: 21090952-01AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/24/2021	RunNo: 24824
Client ID: BatchQC	Batch ID: 14242	TestNo: E200.8	E200.8	Analysis Date: 9/27/2021	SeqNo: 398333
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead	102	0.100	100	0.0320	102	70	130	96.6	5.25	20
------	-----	-------	-----	--------	-----	----	-----	------	------	----

Qualifiers:	* Value exceeds Maximum Contaminant Level.	C1 Sample container temperature is out of limit as specified at testcode	H Holding times for preparation or analysis exceed
MI Recovery outside control limits due to Matrix Interference	ND Not Detected at the Reporting Limit	PL Permit Limit	
RL Reporting Detection Limit			

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090922
05-Oct-21

Client: Medford School District
Project: 44-Oak Grove 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: MB-14300	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: PBW	Batch ID: 14300	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400237
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead ND 0.515

Sample ID: LCS-14300	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: LCSW	Batch ID: 14300	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400238
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 101 0.520 100 0 101 85 115

Sample ID: 21090922-039AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: Near Room 10 Boys	Batch ID: 14300	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400260
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 102 0.520 100 2.49 99.1 70 130

Sample ID: 21090922-039AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: Near Room 10 Boys	Batch ID: 14300	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400261
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 100 0.520 100 2.49 97.9 70 130 102 1.17 20

Qualifiers: * Value exceeds Maximum Contaminant Level.
MI Recovery outside control limits due to Matrix Interference
RL Reporting Detection Limit
C1 Sample container temperature is out of limit as specified at testcode
ND Not Detected at the Reporting Limit
H Holding times for preparation or analysis exceed
PL Permit Limit

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090922
05-Oct-21

Client: Medford School District
Project: 44-Oak Grove 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: MB-14301	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: PBW	Batch ID: 14301	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400265
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead ND 0.515

Sample ID: LCS-14301	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: LCSW	Batch ID: 14301	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400266
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 98.0 0.520 100 0 98.0 85 115

Sample ID: 21090922-059AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: Near Room 1 Men's	Batch ID: 14301	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400288
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 101 0.520 100 4.49 96.7 70 130

Sample ID: 21090922-059AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: Near Room 1 Men's	Batch ID: 14301	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400289
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 101 0.520 100 4.49 96.5 70 130 101 0.199 20

Qualifiers: * Value exceeds Maximum Contaminant Level. C1 Sample container temperature is out of limit as specified at testcode H Holding times for preparation or analysis exceed
MI Recovery outside control limits due to Matrix Interference ND Not Detected at the Reporting Limit PL Permit Limit
RL Reporting Detection Limit

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090922
05-Oct-21

Client: Medford School District
Project: 44-Oak Grove 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: MB-14302	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: PBW	Batch ID: 14302	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400293
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead ND 0.515

Sample ID: LCS-14302	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: LCSW	Batch ID: 14302	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400294
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 98.2 0.520 100 0 98.2 85 115

Sample ID: 21090922-079AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: N Side of Kitchen M	Batch ID: 14302	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400316
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 104 0.520 100 4.15 99.5 70 130

Sample ID: 21090922-079AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: N Side of Kitchen M	Batch ID: 14302	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400317
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 101 0.520 100 4.15 96.6 70 130 104 2.79 20

Qualifiers: * Value exceeds Maximum Contaminant Level.
MI Recovery outside control limits due to Matrix Interference
RL Reporting Detection Limit
C1 Sample container temperature is out of limit as specified at testcode
ND Not Detected at the Reporting Limit
H Holding times for preparation or analysis exceed
PL Permit Limit

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090922
05-Oct-21

Client: Medford School District
Project: 44-Oak Grove 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: MB-14303	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: PBW	Batch ID: 14303	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400321
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead ND 0.515

Sample ID: LCS-14303	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: LCSW	Batch ID: 14303	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400322
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 96.7 0.520 100 0 96.7 85 115

Sample ID: 21090922-099AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: Outside Room 26 Bo	Batch ID: 14303	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400343
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 98.2 0.520 100 3.17 95.0 70 130

Sample ID: 21090922-099AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: Outside Room 26 Bo	Batch ID: 14303	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400344
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 99.0 0.520 100 3.17 95.8 70 130 98.2 0.787 20

Qualifiers: * Value exceeds Maximum Contaminant Level. C1 Sample container temperature is out of limit as specified at testcode H Holding times for preparation or analysis exceed
MI Recovery outside control limits due to Matrix Interference ND Not Detected at the Reporting Limit PL Permit Limit
RL Reporting Detection Limit

Original



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 21090922
05-Oct-21

Client: Medford School District
Project: 44-Oak Grove 2021 Lead Testing

TestCode: LEAD_DW

Sample ID: MB-14304	SampType: MBLK	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: PBW	Batch ID: 14304	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400348
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead	ND	0.515			
------	----	-------	--	--	--

Sample ID: LCS-14304	SampType: LCS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: LCSW	Batch ID: 14304	TestNo: E200.8	E200.8	Analysis Date: 10/1/2021	SeqNo: 400349
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead	99.4	0.520	100	0	99.4 85 115
------	------	-------	-----	---	-------------

Sample ID: 21090922-113AMS	SampType: MS	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: Outside Room 26 W	Batch ID: 14304	TestNo: E200.8	E200.8	Analysis Date: 10/2/2021	SeqNo: 400364
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead	104	0.520	100	5.83	98.2 70 130
------	-----	-------	-----	------	-------------

Sample ID: 21090922-113AMSD	SampType: MSD	TestCode: LEAD_DW	Units: ppb	Prep Date: 9/29/2021	RunNo: 24950
Client ID: Outside Room 26 W	Batch ID: 14304	TestNo: E200.8	E200.8	Analysis Date: 10/2/2021	SeqNo: 400365
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead	101	0.520	100	5.83	95.0 70 130 104 3.13 20
------	-----	-------	-----	------	-------------------------

Qualifiers:	* Value exceeds Maximum Contaminant Level.	C1 Sample container temperature is out of limit as specified at testcode	H Holding times for preparation or analysis exceed
	MI Recovery outside control limits due to Matrix Interference	ND Not Detected at the Reporting Limit	PL Permit Limit
	RL Reporting Detection Limit		

Original

Sample Log-In Check List

Client Name: **MedfordSchoolDist**

Work Order Number: **21090922**

RcptNo: **1**

Logged by: **Sarah Spence** **9/22/2021 11:04:00 AM**

Sarah Spence

Completed By: **Krizzle Calip** **9/23/2021 7:40:21 AM**

Krizzle Calip

Reviewed By: **Dorie Maier** **10/5/2021 11:38:58 AM**

Dorie Maier

Chain of Custody

1. Is Chain of Custody complete? Yes ☒ No ☐ Not Present ☐
2. How was the sample delivered? Client

Log In

3. Coolers are present? Yes ☐ No ☐ NA ☒
4. Shipping container/cooler in good condition? Yes ☒ No ☐
Custody seals intact on shipping container/cooler? Yes ☐ No ☐ Not Present ☒
No. Seal Date: Signed By:
5. Was an attempt made to cool the samples? Yes ☐ No ☐ NA ☒
6. Were all samples received at a temperature of >0° C to 6.0°C Yes ☐ No ☐ NA ☒
7. Sample(s) in proper container(s)? Yes ☒ No ☐
8. Sufficient sample volume for indicated test(s)? Yes ☒ No ☐
9. Are samples (except VOA and ONG) properly preserved? Yes ☒ No ☐
10. Was preservative added to bottles? Yes ☒ No ☐ NA ☐
11. Is the headspace in the VOA vials less than 1/4 inch or 6 mm? Yes ☐ No ☐ HNO3 pH<2
No VOA Vials ☒
12. Were any sample containers received broken? Yes ☐ No ☒
13. Does paperwork match bottle labels? Yes ☒ No ☐
(Note discrepancies on chain of custody)
14. Are matrices correctly identified on Chain of Custody? Yes ☒ No ☐
15. Is it clear what analyses were requested? Yes ☒ No ☐
16. Were all holding times able to be met? Yes ☒ No ☐
(If no, notify customer for authorization.)

Special Handling (if applicable)

17. Was client notified of all discrepancies with this order? Yes ☐ No ☐ NA ☒


Person Notified: Date:
By Whom: Via: ☐ eMail ☐ Phone ☐ Fax ☐ In Person
Regarding:
Client Instructions:

18. Additional remarks:

The samples submitted for sample IDs 21090922-11A, -19A and -86A contained visible sediments.

Cooler Information

Cooler No	Temp °C	Condition	Seal Intact	Seal No	Seal Date	Signed By
-----------	---------	-----------	-------------	---------	-----------	-----------



1 of 7

Page 1 of 3

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Section D
Rush Status (Subject to Scheduling)

Company: MSD 549C	Project Name: 2021 Lead Testing	Attention: Accounting	___ Standard 10-14 Days
Address: 815 South Oakdale Avenue	Project Number: ~~32~~ Jefferson 44 Oak Grove	Company Name: Medford School District	___ 5 Business Days (50% surcharge)
Medford, OR 97501	Report <u>ron.havnear@medford.k12.or.us</u>	Address: 815 South Oakdale Avenue	___ 3 Business Days (75% surcharge)
Email: <u>ron.havnear@medford.k12.or.us</u>	Copy To <u>andy.chasteen@medford.k12.or.us</u>	Medford, OR 97501	___ 24 - 48 hours (100% surcharge)
Phone: 541-840-4315 Fax: _____	_____	P.O. # 61172	___ Other _____
Collected By (Print): _____			Authorized ___ Yes ___ No

Collected By (Sign):	
Email Report ___ Yes ___ No	Mail Report ___ Yes ___ No
Fax Report ___ Yes ___ No	

Section E

Sample Information

[illegible]



Environmental Testing Laboratory
245 South Grape Street * Medford, OR 97501
(541) 770-5678 fax (541) 770-2901

Chain of Custody Record

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Page 1 of 3

Section A

Required Client Information

Company:	MSD 549C
Address:	815 South Oakdale Avenue
	Medford, OR 97501
Email:	<u>ron.havnear@medford.k12.or.us</u>
Phone:	541-840-4315
	Fax:
Collected By (Print):	Gary Severe
Collected By (Sign):	
Email Report ☐ Yes ☐ No	Mail Report ☐ Yes ☐ No
Fax Report ☐ Yes ☐ No	

Section B

Required Project Information

Project Name: 2021 Lead Testing
Project Number: 44 - Oak Grove
Report ron.havnear@medford.k12.or.
Copy T andy.chasteen@medford.k12.o

Section C

Invoice Information

Attention: Accounting
Company Name: Medford School District
Address: 815 South Oakdale Avenue
Medford, OR 97501
P.O. # 61172

Section D
Rush Status (Subject to Scheduling)

_____	Standard 10-14 Days
_____	5 Business Days (50% surcharge)
_____	3 Business Days (75% surcharge)
_____	24 - 48 hours (100% surcharge)
_____	Other _____
_____	Authorized _____ Yes _____ No _____

Section E

Sample Information

[illegible]

Chain of Custody Record

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

3 of 7
Page 1 of 3

Section A Required Client Information	Section B Required Project Information	Section C Invoice Information	Section D Rush Status (Subject to Scheduling)
Company: MSD 549C	Project Name: 2021 Lead Testing	Attention: Accounting	☐ Standard 10-14 Days
Address: 815 South Oakdale Avenue	Project Number: 32 Jefferson 44 Oak Grove	Company Name: Medford School District	☐ 5 Business Days (50% surcharge)
Medford, OR 97501	Report ron.havnear@medford.k12.or.us	Address: 815 South Oakdale Avenue	☐ 3 Business Days (75% surcharge)
Email: ron.havnear@medford.k12.or.us	Copy T andy.chasteen@medford.k12.or.us	Medford, OR 97501	☐ 24 - 48 hours (100% surcharge)
Phone: 541-840-4315 Fax:		P.O. # 61172	☐ Other
Collected By (Print): Mark Taylor			Authorized ☐ Yes ☐ No
Collected By (Sign): <i>Mark Taylor</i>			
Email Report ☐ Yes ☐ No Mail Report ☐ Yes ☐ No			
Fax Report ☐ Yes ☐ No			

				Analysis Requested												NRC Workorder # 21090922-03A (Lab Use Only)	
Sample ID	Matrix*	Date Collected	Time Collect	No. of Containers												Remarks/Field Data	NRC Sample # (Lab Use Only)
Room 8 - Drinking Fountain	DW	9/21/2021	6:01 AM														31
Room 8 - Sink	DW	9/21/2021	6:02 AM														32
Room 9 - Drinking Fountain	DW	9/21/2021	6:03 AM														33
Room 9 - Sink	DW	9/21/2021	6:04 AM														34
Room 10 - Drinking Fountain	DW	9/21/2021	6:05 AM														35
Room 10 - Sink	DW	9/21/2021	6:06 AM														36
Near Room 10 Girl's Restroom - Sink (Left)	DW	9/21/2021	6:07 AM														37
Near Room 10 Girl's Restroom - Sink (Right)	DW	9/21/2021	6:08 AM														38
Near Room 10 Boy's Restroom - Sink (Left)	DW	9/21/2021	6:09 AM														39
Near Room 10 Boy's Restroom - Sink (Right)	DW	9/21/2021	6:10 AM														40
Room 14 - Drinking Fountain	DW	9/21/2021	6:11 AM														41
Room 14 - Sink	DW	9/21/2021	6:12 AM														42
Room 15 - Drinking Fountain	DW	9/21/2021	6:13 AM														43
Room 15 - Sink	DW	9/21/2021	6:14 AM														44
Room 16 - Drinking Fountain	DW	9/21/2021	6:15 AM														45
Room 16 - Sink	DW	9/21/2021	6:16 AM														46
Room 17 - Drinking Fountain	DW	9/21/2021	6:17 AM														47
Room 17 - Sink	DW	9/21/2021	6:18 AM														48
		22															



4087

Page 1 of 3

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Section D
Rush Status (Subject to Scheduling)

Company: MSD 549C	Project Name: 2021 Lead Testing	Attention: Accounting	_____ Standard 10-14 Days
Address: 815 South Oakdale Avenue	Project Number: 44 - Oak Grove	Company Name: Medford School District	_____ 5 Business Days (50% surcharge)
Medford, OR 97501	Report ron.havnear@medford.k12.or.us	Address: 815 South Oakdale Avenue	_____ 3 Business Days (75% surcharge)
Email: ron.havnear@medford.k12.or.us	Copy T andy.chasteen@medford.k12.or.us	Medford, OR 97501	_____ 24 - 48 hours (100% surcharge)
Phone: 541-840-4315 Fax: _____	_____	P.O. # 61172	_____ Other _____
Collected By (Print): _____			Authorized _____ Yes _____ No

Collected By (Sign):	
Email Report ___ Yes ___ No	Mail Report ___ Yes ___ No
Fax Report ___ Yes ___ No	

Analysis Requested

[illegible]

Section F

Relinquish/Receive

Section G

Lab Use Only

Received Via ☐ UPS ☐ FedEx ☐ Other ☒ Hand

Payment: ☒ Invoice ☐ Cash ☐ VISA, M/C ☐ Check # ☐ Amount

Chain of Custody Record

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Page 1 of 3

Section A Required Client Information	Section B Required Project Information	Section C Invoice Information	Section D Rush Status (Subject to Scheduling)
Company: MSD 549C	Project Name: 2021 Lead Testing	Attention: Accounting	☐ Standard 10-14 Days
Address: 815 South Oakdale Avenue	Project Number: ~~32~~ <u>Jefferson 44</u> <u>oak</u> <u>grove</u>	Company Name: Medford School District	☐ 5 Business Days (50% surcharge)
Medford, OR 97501	Report <u>ron.havnear@medford.k12.or.</u>	Address: 815 South Oakdale Avenue	☐ 3 Business Days (75% surcharge)
Email: <u>ron.havnear@medford.k12.or.us</u>	Copy T <u>andy.chasteen@medford.k12.o</u>	Medford, OR 97501	☐ 24 - 48 hours (100% surcharge)
Phone: 541-840-4315 Fax:		P.O. # 61172	☐ Other
Collected By (Print):			Authorized ☐ Yes ☐ No

Collected By (Sign):

Email Report ☐ Yes ☐ No Mail Report ☐ Yes ☐ No

Fax Report ☐ Yes ☐ No

Section E Sample Information

Sample ID				Matrix*	Date Collected	Time Collect	No. of Containers	Analysis Requested										NRC Workorder # <u>21090922-05A</u> (Lab Use Only)	
Sample ID				Matrix*	Date Collected	Time Collect	No. of Containers											Remarks/Field Data	NRC Sample # (Lab Use Only)
Near Room 1 Men's Restroom - Sink (1) <u>L</u>				DW	9/21/2021	<u>6:00</u>	1												<u>59</u>
Near Room 1 Men's Restroom - Sink (2) <u>m</u>				DW	9/21/2021	<u>6:00</u>	1												<u>60</u>
Near Room 1 Men's Restroom - Sink (3) <u>R</u>				DW	9/21/2021	<u>6:00</u>	1												<u>61</u>
Near Room 1 Women's Restroom - Sink (1) <u>L</u>				DW	9/21/2021	<u>6:02</u>	1												<u>62</u>
Near Room 1 Women's Restroom - Sink (2) <u>m</u>				DW	9/21/2021	<u>6:02</u>	1												<u>63</u>
Near Room 1 Women's Restroom - Sink (3) <u>R</u>				DW	9/21/2021	<u>6:02</u>	1												<u>64</u>
Near Room 1 / Women's Restroom - Drinking Fountain				DW	9/21/2021	<u>6:05</u>	1												<u>65</u>
Room 1 - Drinking Fountain				DW	9/21/2021	<u>6:07</u>	1												<u>66</u>
Room 1 - Sink				DW	9/21/2021	<u>6:07</u>	1												<u>67</u>
Room 2 - Drinking Fountain				DW	9/21/2021	<u>6:10</u>	1												<u>68</u>
Room 2 - Sink				DW	9/21/2021	<u>6:10</u>	1												<u>69</u>
Room 3 - Drinking Fountain				DW	9/21/2021	<u>6:13</u>	1												<u>70</u>
Room 3 - Sink				DW	9/21/2021	<u>6:14</u>	1												<u>71</u>
Room 4 - Drinking Fountain				DW	9/21/2021	<u>6:15</u>	1												<u>72</u>
Room 4 - Sink				DW	9/21/2021	<u>6:16</u>	1												<u>73</u>
Room 6 - Drinking Fountain				DW	9/21/2021	<u>6:17</u>	1												<u>74</u>
Room 6 - Sink				DW	9/21/2021	<u>6:17</u>	1												<u>75</u>
Outside Room 6 Staff Unisex Restroom - Sink				DW	9/21/2021	<u>6:20</u>	1												<u>76</u>
Room 7 - Drinking Fountain				DW	9/21/2021	<u>6:21</u>	1												<u>77</u>
Room 7 - Sink				DW	9/21/2021	<u>6:22</u>	1												<u>78</u>

Chain of Custody Record

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Page 1 of 3

Section A Required Client Information	Section B Required Project Information	Section C Invoice Information	Section D Rush Status (Subject to Scheduling)
Company: MSD 549C	Project Name: 2021 Lead Testing	Attention: Accounting	☐ Standard 10-14 Days
Address: 815 South Oakdale Avenue	Project Number: 32 Jefferson 44 Oak Grove	Company Name: Medford School District	☐ 5 Business Days (50% surcharge)
Medford, OR 97501	Report <u>ron.havnear@medford.k12.or.</u>	Address: 815 South Oakdale Avenue	☐ 3 Business Days (75% surcharge)
Email: <u>ron.havnear@medford.k12.or.us</u>	Copy T <u>andy.chasteen@medford.k12.o</u>	Medford, OR 97501	☐ 24 - 48 hours (100% surcharge)
Phone: 541-840-4315 Fax:		P.O. # 61172	☐ Other
Collected By (Print):			Authorized ☐ Yes ☐ No

Collected By (Sign):

Email Report ☐ Yes ☐ No Mail Report ☐ Yes ☐ No

Fax Report ☐ Yes ☐ No

Section E Sample Information

Sample ID	Matrix*	Date Collected	Time Collect	No. of Containers	Analysis Requested										NRC Workorder # 2090922-00A	
															Remarks/Field Data	NRC Sample # (Lab Use Only)
North Side of Kitchen Men's Restroom - Sink (Left)	DW	9/21/2021	6:02	1												79
North Side of Kitchen Men's Restroom - Sink (Right)	DW	9/21/2021	6:07	1												80
North Side of Kitchen Women's Restroom - Sink (Left)	DW	9/21/2021	6:07	1												81
North Side of Kitchen Women's Restroom - Sink (Right)	DW	9/21/2021	6:07	1												82
North Side of Kitchen - Drinking Fountain (Outside)	DW	9/21/2021	6:07	1												83
~~East Side of Kitchen - Portable Drinking Fountain (Outside)~~	~~DW~~	~~9/21/2021~~	~~6:10~~	~~1~~	~~File error 9/21/21 no sample taken~~											84
Inside Kitchen Unisex Restroom (East) - Sink	DW	9/21/2021	6:25	1	Non Potable											85
Kitchen - Sink (Food Prep - Triple Sink)	DW	9/21/2021	6:14	1												86
Kitchen - Sink (Food Prep - Island)	DW	9/21/2021	6:14	1												87
Kitchen - Sink (Pre-rinse/Dishwasher)	DW	9/21/2021	6:14	1												88
Office C / Ram Store - Sink	DW	9/21/2021	6:15	1												89
Cafeteria - Drinking Fountain	DW	9/21/2021	6:16	1												90
Cafeteria - Bottle Filler	DW	9/21/2021	6:16	1												91
Health Room - Sink	DW	9/21/2021	6:31	1												92
Health Room - Unisex Restroom - Sink	DW	9/21/2021	6:31	1												93
Staff Work Room - Unisex Restroom - Sink	DW	9/21/2021	6:32	1												94
																95
Kitchen office hand sink		22	6:25													96
" unisex west			6:25													97

Chain of Custody Record

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Page 1 of 3

Section A Required Client Information	Section B Required Project Information	Section C Invoice Information	Section D Rush Status (Subject to Scheduling)
Company: MSD 549C	Project Name: 2021 Lead Testing	Attention: Accounting	☐ Standard 10-14 Days
Address: 815 South Oakdale Avenue	Project Number: 44 - Oak Grove	Company Name: Medford School District	☐ 5 Business Days (50% surcharge)
Medford, OR 97501	Report <u>ron.havnear@medford.k12.or.u</u>	Address: 815 South Oakdale Avenue	☐ 3 Business Days (75% surcharge)
Email: <u>ron.havnear@medford.k12.or.us</u>	Copy T <u>andy.chasteen@medford.k12.o</u>	Medford, OR 97501	☐ 24 - 48 hours (100% surcharge)
Phone: 541-840-4315 Fax:		P.O. # 61172	☐ Other _____
Collected By (Print): _____			Authorized ☐ Yes ☐ No

Collected By (Sign): _____

Email Report ☐ Yes ☐ No Mail Report ☐ Yes ☐ No

Fax Report ☐ Yes ☐ No

Section E Sample Information

Sample ID	Matrix*	Date Collected	Time Collect	No. o											Remarks/Field Data	NRC Sample # (Lab Use Only)
Outside Room 26 Boy's Restroom - Sink (1)	DW	9/21/2021	6:06	1												918 97
Outside Room 26 Boy's Restroom - Sink (2)	DW	9/21/2021	6:06	1												919 98
Outside Room 26 Boy's Restroom - Sink (3)	DW	9/21/2021	6:06	1												100 99
Outside Room 26 Boy's Restroom - Sink (4)	DW	9/21/2021	6:07	1												101 100
Outside Room 26 Boy's Restroom - Sink (5)	DW	9/21/2021	6:07	1												102 101
Outside Room 26 Boy's Restroom - Sink (6)	DW	9/21/2021	6:08	1												103 102
Outside Room 26 Boy's Restroom - Sink (7)	DW	9/21/2021	6:08	1												104 103
Outside Room 26 Boy's Restroom - Sink (8)	DW	9/21/2021	6:08	1												105 104
Outside Room 26 Boy's Restroom - Sink (9)	DW	9/21/2021	6:09	1												106 105
Outside Room 26 Women's Restroom - Sink (1)	DW	9/21/2021	6:09	1												107 106
Outside Room 26 Women's Restroom - Sink (2)	DW	9/21/2021	6:11	1												108 107
Outside Room 26 Women's Restroom - Sink (3)	DW	9/21/2021	6:11	1												109 108
Outside Room 26 Women's Restroom - Sink (4)	DW	9/21/2021	6:11	1												110 109
Outside Room 26 Women's Restroom - Sink (5)	DW	9/21/2021	6:12	1												111 110
Outside Room 26 Women's Restroom - Sink (6)	DW	9/21/2021	6:12	1												112 111
Outside Room 26 Women's Restroom - Sink (7)	DW	9/21/2021	6:13	1												113 112
Outside Room 26 Women's Restroom - Sink (8)	DW	9/21/2021	6:14	1												114 113
Outside Room 26 Women's Restroom - Sink (9)	DW	9/21/2021	6:14	1												115 114
		22														X

- hr/>
- B Analyte detected in the associated method blank.
- BA BOD Alternative Calculation: The initial results performed by Standard Methods did not fall within parameters of the Standard Methods calculation. An alternate approved calculation was performed using the HACH method and the value reported is an estimated concentration.
- C Sample(s) does not meet NELAP/ORELAP sample acceptance criteria. See Case Narrative.
- C1 Sample(s) does not meet NELAP/ORELAP sample acceptance criteria for temperature.
- CF Results confirmed by re-analysis.
- CU Cleanup performed as specified by method.
- D1 The diesel elution pattern for the sample is not typical.
- D2 The sample appears to be a heavier hydrocarbon range than diesel.
- D3 The sample appears to be a lighter hydrocarbon range than diesel.
- D4 Detected hydrocarbons do not have pattern and range consistent with typical petroleum products and may be due to biogenic interference.
- D5 Detected hydrocarbons in the diesel range appear to be weathered diesel.
- E Estimated value.
- ER Elevated reporting limit due to matrix. Report limits (MDLs, MRLs & PQLs) are adjusted based on variations in sample preparation amounts, analytical dilutions, and percent solids, where applicable.
- FC Fecal Coliforms: Sample(s) received past 40 CFR Part 136 specified holding time. Results reported as estimated values.
- G1 The gasoline elution pattern for the sample is not typical.
- G2 The sample appears to be a heavier hydrocarbon range than gasoline.
- G3 The sample appears to be a lighter hydrocarbon range than gasoline.
- G4 Detected hydrocarbons in the gasoline range appear to be weathered gasoline.
- HP Sample re-analysis performed outside of method specified holding time.
- HR Sample received outside of method specified holding time.
- HS Sample analyzed for volatile organics contained headspace.
- HT At the client's request, the sample was analyzed outside of method specified holding time.
- H Analysis performed outside of method specified holding time.
- J Analyte detected below the Minimum Reporting Limit (MRL) and above the Method Detection Limit (MDL). The J flag result is an estimated value and the user should be aware that this data is of limited reliability.
- L Dissolved metals were not filtered within 15 minutes of collection per 40 CFR Part 136.
- MI Surrogate, Duplicate Sample (DUP) or Matrix Spikes recoveries are out of control limits due to matrix interference. Sample results may be biased.
- N See Case Narrative on page 2 of report.
- NLR No Legionella Recovered.
- PLR Presence of Legionella Recovered.
- Q Initial calibration verification (ICV), continuing calibration verification (CCV) or laboratory control sample (LCS) exceeded high recovery limits, but associated samples are non-detect and the sample results are not affected. Data meets EPA/NELAP requirements.
- R Relative percent difference (RPD) is outside of the accepted recovery limits.
- R1 Relative percent difference (RPD) is outside of the accepted recovery limits. However, analyses are not controlled on RPD values for sample concentrations that are less than the reporting limit.
- R3 The relative percent difference (RPD) and/or percent recovery for the duplicate (DUP) or matrix spike (MS)/matrix spike duplicate (MSD) cannot be accurately calculated due to the concentration of analyte already present in the sample.
- R4 Duplicate analysis failed due to result being at or near the method reporting limit.
- S Surrogate and/or matrix spike recovery is outside of the accepted recovery limits. Sample results may be biased.
- S1 Surrogate or matrix spike recovery is outside of control limits due to dilution necessary for analysis.
- SC Sub-contracted to another laboratory for analysis.
- SP Sample(s) were not collected per EPA Method 5035A protocols. The results are considered minimum values.
- # Value exceeds regulatory level for TCLP contaminant.
- X1 The motor oil elution pattern for the sample is not typical.
- X2 The sample appears to be a heavier hydrocarbon range than motor oil.
- X3 The sample appears to be a lighter hydrocarbon range than motor oil.
- * Value exceeds Maximum Contaminant Level or is outside the acceptable range.