

Ruch Elementary School						
Lead Tests - Ruch Elementary School - Cafeteria/Gymnasium/Media Center/Rooms 5-6 - # 20481100						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481100-001DW	20481100-001DW21A	Media Center Work Room - Drinking Fountain	1/16/2020	Passed with 0.00331	None.
2	20481100-002SF	20481100-002SF21A	Media Center Work Room - Sink	1/16/2020	Passed with 0.00583	None.
3	20481100-003DW	20481100-003DW21A	Computer Room - Drinking Fountain	1/16/2020	Passed with 0.000414	This sink has a lead filter on it.
4	20481100-004CF	20481100-004CF21A	Computer Room - Sink	1/16/2020	Passed with 0.00158	This sink has a lead filter on it.
5	20481100-005DW	20481100-005DW21A	Gym - Drinking Fountain	1/16/2020	Passed with 0.00167	None.
6	20481100-006KF	20481100-006KF21A	Kitchen Food Prep - Sink (Left)	1/16/2020	Passed with 0.00324	None.
7	20481100-007KF	20481100-007KF21A	Kitchen Food Prep/Eyewash - Sink (Right)	1/16/2020	Passed with 0.000839	None.
8	20481100-008KF	20481100-008KF21A	Kitchen - Sink (Pre-rinse/Dishwasher)	1/16/2020	Failed with 0.0227	"Not For Consumption" tags installed 3/2/2020
9	20481100-009KF	20481100-009KF21A	Kitchen - Sink (Hand Wash)	1/16/2020	Passed with 0.00156	This sink has a lead filter on it.
10	20481100-010BF	20481100-010BF21A	Kitchen Unisex Restroom - Sink	3/18/2020	Passed with 0.00338	This sink has a lead filter on it.
11	20481100-011DW	20481100-011DW21A	Room 6 - Drinking Fountain	1/16/2020	Passed with 0.00560	None.
12	20481100-012CF	20481100-012CF21A	Room 6 - Sink	1/16/2020	Passed with 0.00156	This sink has a lead filter on it.
13	20481100-013DW	20481100-013DW21A	Outside Room 6 - Drinking Fountain	4/26/2021	Passed with None Detected	This sink has a lead filter on it.
N/A	N/A	N/A	Gym - Boy's Locker Room Right Side Of The Stage - Sink (L)	N/A	N/A	"Not For Consumption" tags installed 2/24/2020
N/A	N/A	N/A	Gym - Boy's Locker Room Right Side Of The Stage - Sink (R)	N/A	N/A	"Not For Consumption" tags installed 2/24/2020
N/A	N/A	N/A	Gym - Girl's Locker Room Left Side Of The Stage - Sink (L)	N/A	N/A	"Not For Consumption" tags installed 2/24/2020
N/A	N/A	N/A	Gym - Girl's Locker Room Left Side Of The Stage - Sink (R)	N/A	N/A	"Not For Consumption" tags installed 2/24/2020
Lead Tests - Ruch Elementary School - Rooms 10-13 Building - # 20481101						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481101-001DW	20481101-001DW21A	Room 10 - Drinking Fountain	1/16/2020	Passed with 0.00501	None.
2	20481101-002CF	20481101-002CF21A	Room 10 - Sink	1/16/2020	Passed with 0.00158	This sink has a lead filter on it.
3	20481101-003DW	20481101-003DW21A	Room 11 - Drinking Fountain	1/16/2020	Passed with 0.00339	None.
4	20481101-004CF	20481101-004CF21A	Room 11 - Sink	1/16/2020	Passed with 0.00109	None.
5	20481101-005DW	20481101-005DW21A	Room 12 - Drinking Fountain	1/16/2020	Passed with 0.00240	None.
6	20481101-006CF	20481101-006CF21A	Room 12 - Sink	1/16/2020	Passed with 0.00388	None.
7	20481101-007DW	20481101-007DW21A	Outside Room 13 - Drinking Fountain	4/26/2021	Passed with 0.325 (ppb)	None.
8	20481101-008DW	20481101-008DW21A	Room 13 - Drinking Fountain	1/16/2020	Passed with 0.00361	None.
9	20481101-009CF	20481101-009CF21A	Room 13 - Sink	1/16/2020	Passed with 0.00802	None.
Lead Tests - Ruch Elementary School - Rooms 7-9 Building - # 20481102						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481102-001DW	20481102-001DW21A	Room 7 - Drinking Fountain	1/16/2020	Passed with 0.00873	None.
2	20481102-002CF	20481102-002CF21A	Room 7 - Sink	1/16/2020	Passed with 0.00184	None.
3	20481102-003DW	20481102-003DW21A	Room 8 - Drinking Fountain	1/16/2020	Passed with 0.00477	None.
4	20481102-004CF	20481102-004CF21A	Room 8 - Sink	1/16/2020	Passed with 0.00769	None.
5	20481102-005DW	20481102-005DW21A	Room 9 - Drinking Fountain	1/27/2020	Passed with 0.00330	This sink has a lead filter on it.
6	20481102-006CF	20481102-006CF21A	Room 9 - Sink	1/16/2020	Passed with 0.00308	None.
7	20481102-007BF	20481102-007BF21A	Boy's Restroom Outside Room 9 - Sink	1/16/2020	Passed with 0.00267	None.
8	20481102-008BF	20481102-008BF21A	Girl's Restroom Outside Room 9 - Sink	1/16/2020	Passed with 0.00486	None.
Lead Tests - Ruch Elementary School - Rooms 2-4 Building - # 20481103						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481103-001BF	20481103-001BF21A	Staff Restroom Outside The Main Office - Sink	1/16/2020	Passed with 0.00165	None.
2	20481103-002DW	20481103-002DW21A	Room 2 - Drinking Fountain	1/16/2020	Passed with 0.00682	None.
3	20481103-003CF	20481103-003CF21A	Room 2 - Sink	1/27/2020	Passed with 0.00749	This sink has a lead filter on it.
4	20481103-004DW	20481103-004DW21A	Room 3 - Drinking Fountain	1/16/2020	Passed with 0.00777	None.
5	20481103-005CF	20481103-005CF21A	Room 3 - Sink	1/16/2020	Passed with 0.00499	None.
6	20481103-006DW	20481103-006DW21A	Room 4 - Drinking Fountain	1/16/2020	Passed with 0.00269	None.
7	20481103-007CF	20481103-007CF21A	Room 4 - Sink	1/27/2020	Passed with 0.00200	None.
Lead Tests - Ruch Elementary School - Main Office Building - # 20481104						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481104-001NS	20481104-001NS21A	Health Room - Sink	1/27/2020	Passed with 0.000941	None.
2	20481104-002BF	20481104-002BF21A	Health Room Restroom - Sink	1/16/2020	Passed with 0.00823	None.
3	20481104-003DW	20481104-003DW21A	Sports Field - Drinking Fountain (On Wellhouse)	4/26/2021	Passed with 2.43 (ppb)	None.
Lead Tests - Ruch Elementary School - Front Restrooms Building - # 20481105						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481105-001DW	20481105-001DW21A	Outside Main Office - Drinking Fountain (Left)	1/16/2020	Passed with 0.00768	None.
2	20481105-002DW	20481105-002DW21A	Outside Main Office - Drinking Fountain (Right)	1/16/2020	Passed with 0.00409	None.
3	20481105-003BF	20481105-003BF21A	Boy's Restroom Adjacent To Main Office - Sink (Left)	1/16/2020	Passed with 0.00911	None.
4	20481105-004BF	20481105-004BF21A	Boy's Restroom Adjacent To Main Office - Sink (Right)	1/16/2020	Passed with 0.00310	None.
5	20481105-005BF	20481105-005BF21A	Boy's Restroom Adjacent To Main Office - Sink (Center)	1/16/2020	Passed with 0.00283	None.
6	20481105-006BF	20481105-006BF21A	Boy's Restroom (Unisex Area) Adjacent To Main Office - Sink	8/26/2021	Passed with 1.95 ppb	None.

7	20481105-007BF	20481105-007BF21A	Girl's Restroom Adjacent To Main Office - Sink (Left)	1/16/2020	Passed with 0.00276	None.
8	20481105-008BF	20481105-008BF21A	Girl's Restroom Adjacent To Main Office - Sink (Right)	1/16/2020	Passed with 0.00709	None.
9	20481105-009BF	20481105-009BF21A	Girl's Restroom Adjacent To Main Office - Sink (Center)	1/16/2020	Passed with 0.00517	None.
10	20481105-010BF	20481105-010BF21A	Girl's Restroom (Unisex Area) Adjacent To Main Office - Sink	8/26/2021	Passed with 1.50 ppb	None.
Lead Tests - Ruch Elementary School - Staff Break Room Building - # 20481106						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481106-001SF	20481106-001SF21A	Staff Break Room - Sink	1/16/2020	Passed with 0.00192	None.
2	20481106-002SF	20481106-002SF21A	Room Adjacent To Staff Break Room - Sink	1/16/2020	Passed with 0.00291	This sink has a lead filter on it.
N/A	N/A	N/A	Staff Break Room - Drinking Fountain	6/30/2016	Passed with 0.00461	This drinking fountain was removed during the seismic uprade.
Lead Tests - Ruch Elementary School - Rooms 14-15 - # 20481107						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481107-001DW	20481107-001DW21A	Room 15 - Drinking Fountain	3/18/2020	Passed with 0.00663	This sink has a lead filter on it.
2	20481107-002CF	20481107-002CF21A	Room 15 - Sink	1/16/2020	Passed with 0.00155	This sink has a lead filter on it.
3	20481107-003DW	20481107-003DW21A	Room 14 - Drinking Fountain	3/18/2020	Passed with 0.00283	This sink has a lead filter on it.
4	20481107-004CF	20481107-004CF21A	Room 14 - Sink	3/18/2020	Passed with 0.00377	This sink has a lead filter on it.

*None Detected (ND) = .005 Or Less

 = Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

*ODE's required action level is 15 parts per billion (PPB)

*The E.P.A.'s recommended action level for lead in schools is 0.020. Oregon's action level for schools changed to 0.015 in 2019 in accordance with OAR 333-061-0400. In 2021, ODE changed the unit of measurement for reporting to parts per billion (PPB)

*The E.P.A. action level for copper is 1.30

*Lead test results will be posted on the MSD/Facilities website within 5 days minus the school map for security purposes.