



# Combined CTE @ Midland

## ➤ Completed Work:

- CMU work on all floors continued.
- Site and MEP concrete slab demolition continued
- Concrete slab work continued.
- Window sub sills continue on Levels 2, 3 and 4, and frames on Level 3.
- Ductwork installation continued on Levels 2, 3, and 4.
- Plumbing above ceiling continued on all floors.

## ➤ Upcoming Work / Look Ahead:

- Concrete slab on deck prep and pour on Level 2.
- CMU work to continue on all floors.
- Curtainwalls to start install.
- Ductwork installation to continue.
- Electrical and plumbing wall rough-ins to continue with masonry.
- **Continue concrete demolition, both interior and exterior (can be loud.)**



# Combined CTE @ Midland

Roof steel at Level 4 installed at Multipurpose



Week Ending September 15, 2023



# Combined CTE @ Midland

New door cut in a Level 1 Automotive



Week Ending September 15, 2023

# Combined CTE @ Midland

CMU at Diesel Lab progressing



Week Ending September 15, 2023

# Combined CTE @ Midland

Metal stud framing at main common space being installed



# Combined CTE @ Midland

Level 2 slab poured



Week Ending September 15, 2023

# Combined CTE @ Midland

Metal stud framing at main common space being installed



Week Ending September 15, 2023

# Combined CTE @ Midland

Dark gray acoustic spray being installed on Level 4



Week Ending September 15, 2023



# Combined CTE @ Midland

Accent color acoustic spray being installed on Level 4



Week Ending September 15, 2023