

Radon test result report for:

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7256091	206	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
7256092	206	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9176700	215	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9176745	215	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224293	220	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
7256061	223	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224276	225	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
7256084	233	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
7256067	233	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
7256083	233	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224288	241	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
7256095	305	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224289	A101	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224286	A102	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224296	A103	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224287	A104	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224292	A104	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224290	A105	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224284	A106	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9176695	A107	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224282	A108	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224281	B101	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9176692	B101	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224283	B102	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224291	B103	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224280	B104	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9176788	B105	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224299	B106	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224300	B106	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9176698	B107	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224297	B108	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224279	C101	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224278	C102	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224277	C102	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
7256062	C103	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224274	C104	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
7256096	C105	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16

December 16, 2019

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7256063	C107	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
7256094	C107	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
7256104	C108	2019-12-11 @ 6:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224298	CAFETERIA	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224295	CAFETERIA	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9176699	GYM	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224294	GYM	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
9224285	LIBRARY	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16
7256085	PRINCIPAL	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	11.0 ± 0.7	2019-12-16
9176696	STAGE	2019-12-11 @ 5:00 am	2019-12-13 @ 6:00 am	< 0.3	2019-12-16

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498