

POTABLE WATER SAMPLING FOR LEAD CONCENTRATION SAMPLE COLLECTION FORM

Appendix D

CLIENT INFORMATION

Name:	Lansingburgh Central School District
Address:	576 Fifth Ave Troy NY 12182
Client Rep:	Bob Schongar

Date of Sampling: 4/22/21	5/25/2021	7/9/2021	9/30/2021	12/29/2021
Samples Taken By: Tim LeVan	Jack Thomas	Ken Retell	Ken Retell	Ken Retell
Samples Taken By: Jack Thomas	Ken Retell	Jack Thomas		

SCHOOL/PROJECT INFORMATION

BLDG NO./NAME:	Knickerbacker middle school
BLDG ADDRESS:	320 Seventh Ave Troy NY 12182
CONTACT NAME & NUMBERS:	Bob Schongar 518-858-5580

(1) Yr. Built	(2) Yr 1st Add:	(3) Yr 2nd Add:	(4) Yr 1st Mod:	(5) Yr. 2nd Mod:
1935				

SAMPLE DATA

Sample Description ID (ID must match container label)				Outlet Information											
Lab Sample #	BOCES Sample #	Location	Outlet Description	Outlet Make & Model	Construct. Date	First Draw	Time of Collection (24hr)	Lead test Results ug/L from 4/22/2021	Lead test Results ug/L from 5/15/21	Lead test Results ug/L from 7/9/21	Lead test Results ug/L from 9/30/21	Lead test Results ug/L from 12/29/21	Remediation		
1	KMS-BM-BF1-P-01	Boys locker room	Sink faucet	Chicago		X	4:55	6.9							
2	KMS-BM-BF2-P-02	Boys locker room	Sink faucet	Chicago		X	4:56	8.1							
3	KMS-BM-LF1-P-03	Laundry Room	Sink Faucet			X	4:57	44.9	Hot water only, no test						
4	KMS-BM-LF2-P-04	Laundry room	Sink Faucet			X	4:58	6.1							
5	KMS-BM-IM-P-05	Track office	Ice machine	Manitowoc		X	7:56	4.8							
6	KMS-BM-BF-P-06	Track office	Sink Faucet			X	5:01	32.8	<1.0						
7	KMS-BM-BF-P-07	Men's room	Sink Faucet			X	5:02	348	45.6	18.6	8.0				
8	KMS-BM- BF1-P-08	Girls locker room	Sink faucet			X	5:07	134	8.4						
9	KMS-BM-BF2-P-09	Girls locker room	Sink faucet	Chicago		X	5:08	6.8							
10	KMS-BM-BF3-P-10	Girls locker room	Sink faucet	Chicago		X	5:08	8.2							
11	KMS-BM-BF-P-11	Women's room	Sink Faucet			X	5:09	32.1	13.4						
12	KMS-BM-SF-P-12	Maintenance shop	Sink faucet	Delta		X	5:11	3.0							
13	KMS-BM-FS-P-13	Faculty room	Sink faucet			X	5:13	9.1							
14	KMS-BM-BF-P-14	Faculty room bathroom	Sink faucet			X	5:17	7.3							
15	KMS-BM-COF-P-15	Custodian office	Sink faucet			X	5:19	3.7							
16	KMS-01-DW-P-16	Corridor outside 112	Water fountain	Elkay		X	5:20	<1.0							
17	KMS-01-DW-P-17	GYM south east side	Water fountain	Elkay		X	5:25	3.6							
18	KMS-01-BF-P-18	Coaches office bathroom	Sink faucet			X	5:24	16.3	16.8	18.1	4.8				
19	KMS-01-BF-P-19	Nurses office bathroom	Sink faucet	Chicago		X	5:27	1.5							
20	KMS-01-NF1-P-20	Nurses office	Sink faucet #1			X	5:28	6.7							
21	KMS-01-NF2-P-21	Nurses office	Sink faucet #2			X	5:28	6.0							
22	KMS-01-CF-P-22	Wood shop	Sink faucet	Central		X	5:29	21.6	31.2	47.1	3.0				
23	KMS-01-CF1-P-23	Metal shop 113	Sink Faucet #1			X	5:32	192	23.5	37.2	4.8				
24	KMS-01-CF2-P-24	Metal shop 113	Sink faucet #2	Speakman		X	5:33	125	46.9	17.5			Removed		

All containers are pre-cleaned/pre-certified 250ml plastic bottles and will be preserved w/HNO3@ pH by lab

CHAIN OF CUSTODY

Relinquished By:	Received By:	Time:	Date:

INSTRUCTIONS TO THE LABORATORY - Analyze all samples for lead and (Pb)

Lab:	PACE Analytical
Contact:	
Comments:	Provide Laboratory Data Report (LDR) and Chain of Custody

## CLIENT INFORMATION

Name:	Lansingburgh Central School District
Address:	576 Fifth Ave Troy Ny 12182
Client Rep:	Bob Schongar

Date of Sampling:	4/22/21	5/15/2021	7/9/2021	9/30/2021	12/29/2021
Samples Taken By:	Tim LeVan	Jack Thomas	Ken Retell	Ken Retell	Ken Retell
Samples Taken By:	Jack Thomas	Ken Retell	Jack Thomas		

## SCHOOL/PROJECT INFORMATION

BLDG NO./NAME:	Knickerbacker Middle School
BLDG ADDRESS:	320 Seventh Ave Troy NY 12182
CONTACT NAME & NUMBERS:	Bob Schongar 518-858-5580

(1) Yr. Built	(2) Yr 1st Add:	(3) Yr 2nd Add:	(4) Yr 1st Mod:	(5) Yr. 2nd Mod:
1935				

## SAMPLE DATA

Sample Description ID (ID must match container label)				Outlet Information									
Lab Sample #	BOCES Sample #	Location	Outlet Description	Outlet Make & Model	Construct. Date	First Draw	Time of Collection (24hr)	Lead test Results ug/L from 4/22/2021	Lead test Results ug/L from 5/15/21	Lead test Results ug/L from 7/9/2021	Results ug/L from 9/30/2021	Results ug/L from 12/29/2021	Remediation
25	KMS-01-HC-P-25	Court yard	Hose connection			X	5:36	33.1	15.4	16.9	16.3	16.2	Turned off for repair
26	KMS-01-CF-P-26	Rm 115	Sink faucet		2016	X	5:37	<1.0					
27	KMS-01-DW-P-27	1st floor Corridor outside boys room	Water fountain	Elkay		X	5:40	3.3					
28	KMS-01-DW-P-28	Corridor outside 112	Bottle filler	Elkay		X	5:39	<1.0					
29	KMS-01-DW-P-29	Northwest Stairwell off gym	Water fountain	Halsey Taylor		X	5:24	4.3					
30	KMS-01-BF1-P-30	Boys room	Sink faucet #1	Chicago		X	5:41	6.6					
31	KMS-01-BF2-P-31	Boys room	Sink faucet #2	Chicago		X	5:41	9.4					
32	KMS-01-BF3-P-32	Boys room	Sink faucet #3	Chicago		X	5:42	6.8					
33	KMS-01-BF-P-33	Principals bathroom	Sink faucet			X	5:44	24.5	18.9	20.3	53.0	1.6	
34	KMS-01-DW-P-34	1 <sup>st</sup> floor corridor outside girls room	Water fountain	Elkay		X	5:45	3.1					
35	KMS-01-BF1-P-35	1 <sup>ST</sup> Floor girls room	Sink faucet #1	Chicago		X	5:46	6.6					
36	KMS-01-BF2-P-36	1 <sup>ST</sup> Floor girls room	Sink faucet #2	Chicago		X	5:46	10.6					
37	KMS-01-CF-P-37	Rm 126	Sink faucet		2016	X	5:47	30.9	8.3				
38	KMS-01-CF-P-38	Rm 134, storage Rm	Sink faucet			X	5:49	12.3					
39A	KMS-02-CF-P-39A	Rm 210	Back sink			X	7:53	2.7					
39	KMS-02-CF-P-39	Rm 210	Sink faucet			X	5:56	3.2					
40	KMS-02-CF1-P-40	Rm 211	Sink faucet #1	Delta		X	5:56	1.5					
41	KMS-02-CF2-P-41	Rm 211	Sink faucet #2	Kohler		X	5:56	1.9					
42	KMS-02-DW-P-42	2 <sup>nd</sup> floor Corridor outside Rm 212	Water fountain	Elkay		X	5:58	8.2					
43	KMS-02-DW-P-43	2 <sup>nd</sup> floor corridor outside boys room	Water fountain	Elkay		X	5:59	<1.0					
44	KMS-02-DW-P-44	2 <sup>nd</sup> floor corridor outside boys room	Bottle filler	Elkay		X	6:00	<1.0					
45	KMS-02-BF1-P-45	2 <sup>ND</sup> floor boys room	Sink faucet #1	Chicago		X	6:00	15.4	11.3				
46	KMS-02-BF2-P-46	2 <sup>ND</sup> floor boys room	Sink faucet #2	Chicago		X	6:01	14.8					
47	KMS-02-CF2-P-47	Rm 224C	Sink faucet		2016	X	6:02	2.0					
48	KMS-02-DW-P-48	2 <sup>ND</sup> floor corridor outside girls room	Water fountain	Elkay		X	6:03	6.7					
49	KMS-02-BF1-P-49	2 <sup>nd</sup> floor girls room	Sink faucet #1	Chicago		X	6:05	9.4					
50	KMS-02-BF2-P-50	2 <sup>nd</sup> floor girls room	Sink faucet #2	Chicago		X	6:05	12.7					
51	KMS-02-BF3-P-51	2 <sup>nd</sup> floor girls room	Sink faucet #3	Chicago		X	6:06	13.6					

All containers are pre-cleaned/pre-certified 250ml plastic bottles and will be preserved w/HNO3@ pH by lab

## CHAIN OF CUSTODY

Relinquished By:	Received By:	Time:	Date:

## INSTRUCTIONS TO THE LABORATORY - Analyze all samples for lead (Pb)

Lab:	PACE Analytical
Contact:	
Comments:	Provide Laboratory Data Report (LDR) and Chain of Custody

## CLIENT INFORMATION

Name:	Lansingburgh Central School District
Address:	576 Fifth Ave Troy Ny 12182
Client Rep:	Bob Schongar

Date of Sampling: 4/22/21	5/15/2021	7/9/2021	9/30/2021	12/29/2021
Samples Taken By: Tim LeVan	Jack Thomas	Ken Retell	Ken Retell	Ken Retell
Samples Taken By: Jack Thomas	Ken Retell	Jack Thomas		

## SCHOOL/PROJECT INFORMATION

BLDG NO./NAME:	Knickerbacker middle school
BLDG ADDRESS:	320 Seventh Ave Troy NY 12182
CONTACT NAME & NUMBERS:	Bob Schongar 518-858-5580

(1) Yr. Built	(2) Yr 1st Add:	(3) Yr 2nd Add:	(4) Yr 1st Mod:	(5) Yr. 2nd Mod:

## SAMPLE DATA

Sample Description ID (ID must match container label)				Outlet Information									
Lab Sample #	BOCES Sample #	Location	Outlet Description	Outlet Make & Model	Construct. Date	First Draw	Time of Collection (24hr)	Lead test Results ug/L from 4/22/2021	Lead test Results ug/L from 5/15/21	Lead test Results ug/L from 7/9/2021	Lead test Results ug/L from	Lead test Results ug/L from	Remediation
52	KMS-02-BF-P-52	Rm 230 bathroom	Sink faucet			X	6:07	8.2					
53	KMS-02-BF-P-53	Rm 236 bathroom	Sink faucet			X	6:08	14.8					
54	KMS-03-CF1-P-54	Rm 334	Sink faucet	Chicago		X	6:12	26.2	17.7	35.9	8.6		
55	KMS-03-CF2-P-55	Rm 332	Sink faucet	Royal		X	6:14	167	28.2	42.8	52.1	Removed	Removed
56	KMS-03-DW-P-56	3 <sup>RD</sup> floor corridor outside girls room	Water fountain	Elkay		X	6:16	5.9					
57	KMS-03-BF1-P-57	3 <sup>rd</sup> floor girls room	Sink faucet #1	Chicago		X	6:17	20.3	15.3	18	3.3		
58	KMS-03-BF2-P-58	3 <sup>rd</sup> floor girls room	Sink faucet #2	Chicago		X	6:17	20.5	15.6	22.4	4.3		
59	KMS-03-BF3-P-59	3 <sup>rd</sup> floor girls room	Sink faucet #3	Chicago		X	6:18	21.3	21.1	36.1	4.7		
60	KMS-03-DW-P-60	3 <sup>RD</sup> floor corridor outside boys room	Water fountain	Elkay		X	6:19	<1.0					
61	KMS-03-DW-P-61	3 <sup>RD</sup> floor corridor outside boys room	Bottle filler	Elkay		X	6:19	<1.0					
62	KMS-03-BF1-P-62	3 <sup>RD</sup> floor boys room	Sink faucet #1	Chicago		X	6:20	11.8					
63	KMS-03-BF2-P-63	3 <sup>RD</sup> floor boys room	Sink faucet #2	Chicago		X	6:20	11.9					
64	KMS-03-DW-P-64	Cafeteria	Water fountain	Halsey Taylor		X	6:22	<1.0					
65	KMS-03-CF-P-65	Rm 317A	Sink faucet #1			X	6:21	12.0					
66	KMS-03-CF-P-66	Rm 317A	Sink faucet #2			X	6:23	17.5	36.8	67.5	13.4		
67	KMS-03-CF1-P-67	Rm 317A	Sink faucet #3			X	6:23	14.0					
68	KMS-03-CF2-P-68	Rm 317A	Sink faucet #4			X	6:24	22.0	197	93.9	4.7		
69	KMS-03-DW-P-69	3 <sup>rd</sup> floor corridor outside 312	Water fountain	Elkay		X	6:25	6.1					
70	KMS-03-CF-P-70	311	Sink faucet	Central		X	6:26	9.7					
71	KMS-03-BF-P-71	311B	Sink faucet			X	6:27	13.7					
72	KMS-03-CF-P-72	310	Sink faucet	Standard		X	6:27	35.4	26.9	25.8	3.7		
73	KMS-03-CF-P-73	310	Sink faucet	Standard		X	6:27	23.6	21	21.3	7.3		
74	KMS-03-BF-P-74	310A	Sink faucet	Standard		X	Not working No Sample				Removed	Removed	Removed
75	KMS-02-CF-P-75	Rm 217	Sink faucet			X	6:21				39.8	6	

All containers are pre-cleaned/pre-certified 250ml plastic bottles and will be preserved w/HNO3@ pH by lab

## CHAIN OF CUSTODY

Relinquished By:	Received By:	Time:	Date:

## INSTRUCTIONS TO THE LABORATORY - Analyze all samples for lead (Pb)

Lab:	PACE Analytical
Contact:	
Comments:	Provide Laboratory Data Report (LDR) and Chain of Custody