# Lead in School Drinking Water Report

## Sky Valley Education Center

Date(s) collected: 2023-09-30
Date(s) analyzed: 2023-10-12

| Sample ID | Building Name | Fixture Housing Type | Fixture Location | Fixture Location Details | Fixture Type | Lead Test Result (ppb) |
|---|---|---|---|---|---|---|
| 374150 | Building 2 - Annex | Sink | Annex A | Sink 3 of 3 sampled all except sink with hose | Tap | 125 |
| 374245 | Building 4 - Technology Education | Sink | Wood Shop | Emergency eye wash station starting on far left 1 of 5 | Tap | 50 |
| 374146 | Building 2 - Annex | Sink | Annex C | Sink 3 of 3 | Tap | 31 |
| 374252 | Building 4 - Technology Education | Sink | Kiln Room | Only sink sink 2 of 3 | Tap | 17 |
| 374243 | Building 5 - Pods/Library | Sink | Room 16a | Only sink | Tap | 16 |
| 374149 | Building 2 - | Sink | Annex A | Sink 2 of 3 | Tap | 11 |

| Sample ID | Building Name | Fixture Housing Type | Fixture Location | Fixture Location Details | Fixture Type | Lead Test Result (ppb) |
|---|---|---|---|---|---|---|
| | Annex | | | | | |
| 374259 | Building 2 - Annex | Sink | Room F | By emergency eyewash station | Tap | 11 |
| 374237 | Building 5 - Pods/Library | Sink | Pod | Between rooms 12 and 13 | Tap | 9 |
| 374239 | Building 5 - Pods/Library | Sink | Pod | Between rooms 8 and 9 | Tap | 6 |
| 374244 | Building 5 - Pods/Library | Sink | Room 16a | Only sink | Water Fountain | 6 |
| 374144 | Building 2 - Annex | Sink | Annex C | Sink 1 of 3 starting closest | Tap | 5 |
| 374147 | Building 2 - Annex | Sink | Room In Between Annex A And C | Only sink | Tap | 5 |
| 374242 | Building 5 - Pods/Library | Sink | Pod | Between rooms 19 and 20 | Water Fountain | 5 |
| 374142 | Building 2 - Annex | Sink | Room E | Next to windows | Water Fountain | 4 |
| 374148 | Building 2 - Annex | Sink | Annex A | Sink 1 of 3 starting by door | Tap | 4 |
| 374233 | Building 1 - Office | Sink | Nurses Office | Only sink | Tap | 4 |
| 374236 | Building 5 - Pods/Library | Sink | Pod | Between classrooms 1 and 2 | Water Fountain | 3 |
| 374238 | Building 5 - Pods/Library | Sink | Pod | Between rooms 12 and 13 | Water Fountain | 3 |
| 374246 | Building 4 - Technology | Sink | Wood Shop | Emergency eye wash | Tap | 3 |

| Sample ID | Building Name | Fixture Housing Type | Fixture Location | Fixture Location Details | Fixture Type | Lead Test Result (ppb) |
|---|---|---|---|---|---|---|
| | Education | | | station sink 2 of 5 | | |
| 374247 | Building 4 - Technology Education | Sink | Wood Shop | 3 of 5 | Tap | 3 |
| 374251 | Building 4 - Technology Education | Sink | Art Room/ Room 22 | Sink right outside kiln room sink 1 of 3 | Tap | 3 |
| 374253 | Building 4 - Technology Education | Sink | Art Room | Eye wash station sink 3 of 3 | Tap | 3 |
| 374254 | Building 3 - Gymnasium | Fountain | Outside Of Gymnasium | Right outside entry/exit | Water Fountain | 3 |
| 374140 | Building 2 - Annex | Sink | Room E | Next to windows | Tap | 2 |
| 374141 | Building 2 - Annex | Sink | Room E | Next to windows | Sprayer | 2 |
| 374241 | Building 5 - Pods/Library | Sink | Pod | Between rooms 19 and 20 | Tap | 2 |
| 374250 | Building 4 - Technology Education | Fountain | Hallway Outside Of Wood Shop | Across from restrooms | Water Fountain | 2 |
| 374143 | Building 2 - Annex | Sink | Cooking Room | Underneath windows | Tap | 1 |
| 374145 | Building 2 - Annex | Sink | Annex C | Sink 2 of 3 | Tap | 1 |
| 374151 | Building 2 - Annex | Fountain | Hallway | Next to annex A | Water Fountain | 1 |
| 374152 | Building 2 - Annex | Sink | Annex B | Only sink | Tap | 1 |
| 374240 | Building 5 - Pods/Library | Sink | Pod | Between rooms 8 and 9 | Water Fountain | 1 |
| 374248 | Building 4 - Technology Education | Sink | Wood Shop | 4 of 5 emergency eye wash | Tap | 1 |

| Sample ID | Building Name | Fixture Housing Type | Fixture Location | Fixture Location Details | Fixture Type | Lead Test Result (ppb) |
|---|---|---|---|---|---|---|
| | | | | station | | |
| 374255 | Building 3 - Gymnasium | Fountain | Gathering Room Attached To Gym | Right outside door to gym | Water Fountain | 1 |
| 374257 | Building 3 - Gymnasium | Sink | Gathering Room Cafe | Sink inside cafe | Sprayer | 1 |
| 374234 | Building 5 - Pods/Library | Sink | Pod | Between rooms 5 and 6 | Tap | <1 |
| 374235 | Building 5 - Pods/Library | Sink | Pod | Between classrooms 1 and 2 | Tap | <1 |
| 374249 | Building 4 - Technology Education | Sink | Wood Shop | 5 of 5 eye wash station | Tap | <1 |
| 374256 | Building 3 - Gymnasium | Sink | Gathering Room Attached To Gym | To the left of girls bathroom | Tap | <1 |
| 374258 | Portable 1 | Sink - Multi-Compartment | Transitions Room | To the right of fridge | Tap | <1 |

## EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: **leadfreekids@doh.wa.gov**